	Grounds											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU01548	Irrigation System	\$ 27750.00		20	01-01-1989	-15.3 years	0.0	0% Good	Retain	N/A
		IGILU1498	Distribution Board	\$ 1454.00		20	01-01-1992	-12.3 years	42.8	0% Good	Retain	N/A
		IGILU1500	Fencing	\$ 2553.00		20	01-01-1992	-12.3 years	6.3	1% Good	Retain	N/A
		IGILU1501	Gas Meter	\$ 1526.00		15	01-01-1992	-17.3 years	0.0	0% Good	Retain	N/A
		IGILU1503	Letterboxes	\$ 6660.00		30	01-01-1992	-2.3 years	12.7	5% Good	Repair	Missing unit numbers on
												the letterboxes, 42 and 9
		IGILU1504	Lighting Bollards	\$ 6593.00		15	01-01-1992			1% Good	Retain	N/A
		IGILU1506	Roads	\$ 404595.00		25	01-01-1992	•		1% Good	Retain	N/A
		IGILU1508	Signage	\$ 555.00		7	01-01-1992	-25.3 years	14.8	0% Fair	Repair	Units 21-26 sign
												damaged ; 1-8 sign
												damaged , 11-14 sign
												damaged , 15 km sign
		IGILU1509	Street Lighting	\$ 6143.00		15	01-01-1992	-17 3 years	19.7	5% Good	Retain	N/A
		IGILU1512	Hydrants	\$ 333.00		30				0% Good	Retain	N/A
C A F		IGILOTST2	пушансь	\$ 555.00		30	01-01-1992	-2.5 years	0.0	J76 G000	Retain	IN/A
Garage A-F	C A											
	Garage A				=** .1 .11 .00					A		
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1478	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	76.5	3% Good	Retain	N/A
	Garage B											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1479	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	81.0	3% Good	Retain	N/A
	Garage C											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1480	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	112.6	1% Good	Retain	N/A
	Garage D											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1481	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	54.0	5% Good	Retain	N/A
	Garage E											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1482	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	85.5	9% Good	Retain	N/A
	Garage F											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1483	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	135.1	4% Good	Retain	N/A
Garage G-M												
	Garage G											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	on Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1485	Electric Roller Door	\$ 3108.00		10	01-01-1992			3% Good	Retain	N/A
	Garage H	141441144		, , , , , , , , , , , , , , , , , , , ,					-		1.14.44	1.4
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	n Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1486	Electric Roller Door	\$ 3108.00		10	01-01-1992			3% Good	Retain	N/A
	Garage J	10,201,100	Electric Holler Book	\$ 5100.00		.0	01 01 1332	EL.J years	00	370 G00G	rictani	14/1
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	n Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1487	Electric Roller Door	\$ 3108.00		10	01-01-1992			1% Good	Retain	N/A
	Garage K	101201407	Electric Roller Bool	\$ 5100.00	1	10	01 01 1332	ZZ.J ycurs	155.1	470 GOOG	recuiii	IV/A
	Gurage K	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	n Data	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1488	Electric Roller Door	\$ 3108.00		10	01-01-1992			5% Good	Retain	N/A
	Garage L	IGILO 1400	Liectific Roller Door	\$ 3100.00		10	01-01-1332	-22.3 years	J 4 .0	376 G000	rctairi	IV/A
	Garage L	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio	D.4.	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
			_			10						
	C 14	IGILU1489	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	112.6	1% Good	Retain	N/A
	Garage M				=22 -1 -112					A		
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1490	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	135.1	4% Good	Retain	N/A
Garage N-S												
	Garage N											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1492	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	81.0	3% Good	Retain	N/A
	Garage O											
		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installatio		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1493	Electric Roller Door	\$ 3108.00		10	01-01-1992	-22.3 years	99.1	0% Good	Retain	N/A

Garage P										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1494	Electric Roller Door	\$ 3108.00		10 01-01-199	2 -22.3 years	99.10	% Good	Retain	N/A
Garage Q						<u> </u>	<u> </u>			
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1495	Electric Roller Door	\$ 3108.00		10 01-01-199	2 -22.3 years	96.09	% Good	Retain	N/A
Garage R						, ,				
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1496	Electric Roller Door	\$ 3108.00			2 -22.3 years		% Good	Retain	N/A
Garage S	TOICOT 150		\$ 5100.00		10 01 01 133	E ELIS Years		, o o o o o	recom	14//
Gurage 5	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1497	Electric Roller Door	\$ 3108.00			2 -22.3 years		% Good	Retain	N/A
	IGILU 1497	Electric Roller Door	\$ 5 100.00		10 01-01-199	2 -22.3 years	99.10	76 G000	Retain	IN/A
Pathua au										
Bathroom	A 1 NI I	A 1 N	A 1-111 C1 (A)	Effective Life (Y)	Land Harden Bart	B	A	A	DI	
	Asset Number	Asset Name	Acquisition Cost (\$)		Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1533	Interior Painting	\$ 1110.00			2 -22.3 years		% Good	Retain	N/A
	IGILU1534	Exhaust Fan	\$ 277.00			2 -22.3 years		% Good	Retain	N/A
	IGILU1535	Tapware	\$ 1304.00			2 -17.3 years		% Good	Retain	N/A
	IGILU1536	Tiles - Wall	\$ 3285.00			2 -12.3 years		% Good	Retain	N/A
	IGILU1537	Toilet & Cistern	\$ 1343.00		20 01-01-199	2 -12.3 years	0.00	% Good	Retain	N/A
Building Exte	rior									
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1556	Path	\$ 1509.00		30 01-01-199	2 -2.3 years	0.00	% Good	Retain	N/A
	IGILU1557	Exterior Painting	\$ 2086.00		10 01-01-199	2 -22.3 years	0.00	% Good	Retain	N/A
	IGILU1558	Doors	\$ 5605.00		30 01-01-199	2 -2.3 years	0.00	% Good	Retain	N/A
	IGILU1559	Porch	\$ 2908.00		30 01-01-199	2 -2.3 years	0.00	% Good	Retain	N/A
	IGILU1560	Downpipes	\$ 1742.00			2 -12.3 years	0.00	% Good	Retain	N/A
	IGILU1561	Fascias	\$ 2874.00		20 01-01-199	2 -12.3 years	0.00	% Good	Retain	N/A
	IGILU1562	Guttering	\$ 2819.00			2 -12.3 years		% Good	Retain	N/A
	IGILU1564	Electrical	\$ 1964.00			2 -12.3 years		% Good	Retain	N/A
		Switchboard	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			- 1-1- 7-1-1				,
	IGILU1565	Windows	\$ 3873.00		30 01-01-199	2 -2.3 years	0.00	% Good	Retain	N/A
Community H	-tall									
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1538	Air Conditioner -	\$ 2608.00		10 01-01-199	2 -22.3 years	0.00	% Good	Retain	N/A
		Split System								
	IGILU1540	Interior Painting	\$ 6438.00		10 01-01-199	2 -22.3 years	0.00	% Fair	Repair	There is a
										require, a
										linear me
	IGILU1541	Insulation	\$ 3069.00		20 01-01-199	2 -12.3 years				notice he
	IGILU1542				20 01-01-199	<u> </u>		O/ Cood	Datain	
					01 01 100			% Good	Retain	N/A
		Carpet	\$ 3174.00			2 -24.3 years	0.00	% Good	Retain	N/A
	IGILU1543	Carpet Smoke Alarms	\$ 3174.00 \$ 277.00		20 01-01-199	2 -12.3 years	0.00	% Good % Good	Retain Retain	N/A N/A
	IGILU1543 IGILU1544	Carpet Smoke Alarms Sarking	\$ 3174.00 \$ 277.00 \$ 2941.00		20 01-01-199 25 01-01-199	2 -12.3 years 2 -7.3 years	0.00 0.00 0.00	% Good % Good % Good	Retain Retain Retain	N/A N/A N/A
	IGILU1543 IGILU1544 IGILU1545	Carpet Smoke Alarms Sarking Lighting	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00		20 01-01-199 25 01-01-199 15 01-01-199	2 -12.3 years 2 -7.3 years 2 -17.3 years	0.00 0.00 0.00 0.00	% Good % Good % Good % Good	Retain Retain Retain Retain	N/A N/A
	IGILU1543 IGILU1544	Carpet Smoke Alarms Sarking Lighting Air Conditioner -	\$ 3174.00 \$ 277.00 \$ 2941.00		20 01-01-199 25 01-01-199 15 01-01-199	2 -12.3 years 2 -7.3 years	0.00 0.00 0.00 0.00	% Good % Good % Good	Retain Retain Retain	N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545	Carpet Smoke Alarms Sarking Lighting	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00		20 01-01-199 25 01-01-199 15 01-01-199	2 -12.3 years 2 -7.3 years 2 -17.3 years	0.00 0.00 0.00 0.00	% Good % Good % Good % Good	Retain Retain Retain Retain	N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00		20 01-01-199 25 01-01-199 15 01-01-199 10 01-01-199	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00	% Good % Good % Good % Good % Good % Good	Retain Retain Retain Retain Retain	N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good % Good % Good % Good % Good Good Asset Condition	Retain Retain Retain Retain Retain	N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$)	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good % Good % Good % Good % Good Asset Condition % Good	Retain Retain Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 1332.00 \$ 260.00	Effective Life (Y)	20 01-01-199 25 01-01-199 15 01-01-199 10 01-01-199 Installation Date 8 01-01-199 20 01-01-199	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good % Good % Good % Good % Good % Good ** **Good ** ** ** ** ** ** ** ** ** ** ** ** **	Retain Retain Retain Retain Retain Petain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 260.00 \$ 2342.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good Asset Condition % Good % Good % Good	Retain	N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 2342.00 \$ 710.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good % Good % Good % Good % Good % Good Asset Condition % Good % Good % Good % Good % Good	Retain Retain Retain Retain Retain Petain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 1332.00 \$ 2642.00 \$ 710.00 \$ 3818.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 2342.00 \$ 710.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good % Good % Good % Good % Good % Good Asset Condition % Good % Good % Good % Good % Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 1332.00 \$ 2642.00 \$ 710.00 \$ 3818.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00 Accumulated Repair Cost as % of Acquisition 0.00 0.00 0.00 0.00 0.000 0.000 0.000	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551 IGILU1552	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 1332.00 \$ 260.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 21 01-01-199. 22 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -20.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551 IGILU1552 IGILU1553	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 21 01-01-199. 22 01-01-199. 23 01-01-199. 24 01-01-199. 25 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years 2 -22.3 years 2 -12.4 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -13.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551 IGILU1552 IGILU1552 IGILU1553 IGILU1554	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 333.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 21 01-01-199. 22 01-01-199. 23 01-01-199. 24 01-01-199. 25 01-01-199. 26 01-01-199. 27 01-01-199. 28 01-01-199.	2 -12.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -20.3 years 2 -20.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1545 IGILU1545 IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551 IGILU1553 IGILU1553 IGILU1553 IGILU1555	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Vinyl	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 1563.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00 \$ 333.00 \$ 1665.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 16 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 10 01-01-199. 20 01-01-199. 11 01-01-199. 12 01-01-199. 15 01-01-199. 16 01-01-199. 17 01-01-199. 18 01-01-199. 19 01-01-199. 10 01-01-199. 10 01-01-199. 11 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -20.3 years 2 -20.3 years 2 -20.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1547 IGILU1549 IGILU1551 IGILU1552 IGILU1553 IGILU1553 IGILU1555 IGILU1555 IGILU1555	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Vinyl Cooktop	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 1332.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00 \$ 1355.00 \$ 1355.00 \$ 1355.00 \$ 1355.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 16 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 10 01-01-199. 20 01-01-199. 11 01-01-199. 12 01-01-199. 15 01-01-199. 16 01-01-199. 17 01-01-199. 18 01-01-199. 19 01-01-199. 10 01-01-199. 10 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -12.3 years 2 -12.3 years 2 -20.3 years 2 -17.3 years 2 -17.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1547 IGILU1549 IGILU1551 IGILU1552 IGILU1553 IGILU1553 IGILU1555 IGILU1555 IGILU1555	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Vinyl Cooktop	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 1332.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00 \$ 1355.00 \$ 1355.00 \$ 1355.00 \$ 1355.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 16 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 10 01-01-199. 20 01-01-199. 11 01-01-199. 12 01-01-199. 15 01-01-199. 16 01-01-199. 17 01-01-199. 18 01-01-199. 19 01-01-199. 10 01-01-199. 10 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -12.3 years 2 -12.3 years 2 -20.3 years 2 -17.3 years 2 -17.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1547 IGILU1549 IGILU1551 IGILU1552 IGILU1553 IGILU1553 IGILU1555 IGILU1555 IGILU1555	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Vinyl Cooktop	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 1332.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00 \$ 1355.00 \$ 1355.00 \$ 1355.00 \$ 1355.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 16 01-01-199. Installation Date 8 01-01-199. 20 01-01-199. 10 01-01-199. 20 01-01-199. 11 01-01-199. 12 01-01-199. 15 01-01-199. 16 01-01-199. 17 01-01-199. 18 01-01-199. 19 01-01-199. 10 01-01-199. 10 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -20.3 years 2 -17.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
Kitchen	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1548 IGILU1549 IGILU1551 IGILU1552 IGILU1552 IGILU1553 IGILU1555 IGILU1555 IGILU1846 IGILU1847	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Virnyl Cooktop Rangehood	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 2560.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1335.00 \$ 1354.00 \$ 1354.00 \$ 599.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 15 01-01-199. 10 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 21 01-01-199. 22 01-01-199. 23 01-01-199. 24 01-01-199. 25 01-01-199. 26 01-01-199. 27 01-01-199. 28 01-01-199. 29 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -20.3 years 2 -20.3 years 2 -22.3 years 2 -20.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A
	IGILU1543 IGILU1544 IGILU1545 IGILU1845 Asset Number IGILU1546 IGILU1547 IGILU1547 IGILU1549 IGILU1551 IGILU1552 IGILU1553 IGILU1553 IGILU1555 IGILU1555 IGILU1555	Carpet Smoke Alarms Sarking Lighting Air Conditioner - Split System Asset Name Dishwasher Smoke Alarms Benchtops Interior Painting Kitchen Cabinets Oven Sink & Fittings Blind Vinyl Cooktop	\$ 3174.00 \$ 277.00 \$ 2941.00 \$ 1665.00 \$ 1563.00 \$ 1332.00 \$ 2342.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1587.00 \$ 1355.00 \$ 1355.00 \$ 1355.00 \$ 1355.00	Effective Life (Y)	20 01-01-199. 25 01-01-199. 16 01-01-199. 17 Installation Date 8 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 20 01-01-199. 21 01-01-199. 22 01-01-199. 23 01-01-199. 24 01-01-199. 25 01-01-199. 26 01-01-199. 27 01-01-199. 28 01-01-199. 29 01-01-199. 20 01-01-199. 20 01-01-199.	2 -12.3 years 2 -7.3 years 2 -7.3 years 2 -17.3 years 2 -22.3 years Remaining Effective Life 2 -24.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -20.3 years 2 -17.3 years 2 -22.3 years	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	% Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A

Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

Unit 1-2

	IGILU0002	Insulation	\$ 3069.00	20	01-01-1992	· ·		00% Good	Retain	N/A
	IGILU0003	Lighting	\$ 1909.00	15	01-01-1992	-17.3 years		81% Good	Retain	N/A
	IGILU0004	Sarking	\$ 3174.00	25	01-01-1992	-7.3 years	0.0	00% Good	Retain	N/A
	IGILU0005	Hot Water System -	\$ 2386.00	12	01-01-1992	-20.3 years	30.0	04% Good	Retain	N/A
		Electric								
Unit 2										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)		Illation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0054	Insulation	\$ 3069.00	20	01-01-1992	· ·		00% Good	Retain	N/A
	IGILU0055	Lighting	\$ 1909.00	15	01-01-1992	-17.3 years	10.3	21% Good	Retain	N/A
	IGILU0056	Sarking	\$ 3174.00	25	01-01-1992	-7.3 years	0.0	00% Good	Retain	N/A
	IGILU0057	Hot Water System -	\$ 2386.00	12	01-01-1992	-20.3 years	28.1	53% Good	Retain	N/A
		Electric								
Bathroom										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)			Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0024	Exhaust Fan	\$ 255.00	10	01-04-2006	,		24% Excellent	Retain	N/A
	IGILU0025	Interior Painting	\$ 466.00	10	01-04-2006	-8.0 years	19.8	83% Good	Retain	N/A
	IGILU0026	Skylight	\$ 1010.00	10	01-04-2006	-8.0 years	16.2	22% Good	Retain	N/A
	IGILU0027	Tapware	\$ 1304.00	15	01-04-2006	-3.0 years	9.0	01% Excellent	Retain	N/A
Bed 1										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)	Insta	Illation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0016	Blind	\$ 333.00	10	01-04-2006	-8.0 years	4.	50% Good	Retain	N/A
	IGILU0017	Carpet	\$ 1032.00	8	01-01-2013	-3.3 years	0.0	00% Good	Retain	N/A
	IGILU0018	Interior Painting	\$ 888.00	10	01-04-2006	-8.0 years	0.9	90% Fair	Repair	Cornices
										spanning
										2 linear n
										necessita
	IGILU0019	Wardrobe	\$ 2053.00	10	01-04-2006	-8.0 years	16.2	22% Good	Retain	N/A
Bed 2										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)			Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0020	Blind	\$ 333.00	10	01-04-2006	· ·		04% Good	Retain	N/A
	IGILU0021	Carpet	\$ 688.00	8	01-01-2013			00% Good	Retain	N/A
	IGILU0022	Interior Painting	\$ 588.00	10	01-04-2006	-8.0 years	36.0	05% Good	Retain	N/A
Dining										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)	Insta	Illation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0038	Blind	\$ 388.00	10	01-04-2006	-8.0 years	18.0	04% Good	Retain	N/A
	IGILU0039	Carpet	\$ 910.00	8	01-01-2013	-3.3 years	0.0	00% Excellent	Retain	N/A
	IGILU0040	Interior Painting	\$ 832.00	10	01-04-2006	-8.0 years	0.9	90% Good	Retain	N/A
Kitchen										
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y)	Insta	Illation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU0006	Blind	\$ 333.00	10	01-04-2006	-8.0 years	0.0	00% Good	Retain	N/A
	IGILU0009	Interior Painting	\$ 710.00	10	01-04-2006	-8.0 years	16.3	23% Fair	Repair	Cornices
										spanning
										3 linear m
										indicating
										concerns
	1511110044) r 1	t 4040 00	40	04.04.000			250/ 5 1	B	
	IGILU0011	Vinyl	\$ 1010.00	10	01-04-2006	· ·		26% Good	Retain	N/A
								88% Good	Retain	N/A
	IGILU0013	Rangehood	\$ 599.00	12	01-04-2006	•				
		Rangehood Sink & Fittings	\$ 599.00 \$ 1587.00	12 15	01-04-2006	•		03% Good	Retain	N/A
Living	IGILU0013 IGILU0014	Sink & Fittings	\$ 1587.00	15	01-04-2006	-3.0 years	21.0	03% Good		'
Living	IGILU0013 IGILU0014 Asset Number	Sink & Fittings Asset Name	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y)	15 Insta	01-04-2006	-3.0 years Remaining Effective Life	21.0 Accumulated Repair Cost as % of Acquisition	O3% Good Asset Condition	Plan	Comme
Living	IGILU0013 IGILU0014 Asset Number IGILU0034	Sink & Fittings Asset Name Blind	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00	15 Insta	01-04-2006 allation Date 01-04-2006	-3.0 years Remaining Effective Life -8.0 years	Accumulated Repair Cost as % of Acquisition 16.	Asset Condition Good Good	Plan Retain	Comme N/A
Living	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035	Asset Name Blind Carpet	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00	15 Insta 10 8	01-04-2006 allation Date 01-04-2006 01-01-2013	-3.0 years Remaining Effective Life -8.0 years -3.3 years	Accumulated Repair Cost as % of Acquisition 16.0	Asset Condition 24% Good Good Good	Plan Retain Retain	Comme N/A N/A
Living	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036	Sink & Fittings Asset Name Blind	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00	15 Insta 10 8 15	01-04-2006 allation Date 01-04-2006	-3.0 years Remaining Effective Life -8.0 years -3.3 years	Accumulated Repair Cost as % of Acquisition 16.0	Asset Condition Good Good	Plan Retain	Comme N/A N/A N/A
Living	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035	Asset Name Blind Carpet	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00	15 Insta 10 8	01-04-2006 allation Date 01-04-2006 01-01-2013	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years	Accumulated Repair Cost as % of Acquisition 16 0.0	Asset Condition 24% Good Good Good	Plan Retain Retain	Comme N/A N/A
Living	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036	Sink & Fittings Asset Name Blind Carpet Heater	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00	15 Insta 10 8 15	01-04-2006 allation Date 01-04-2006 01-01-2013 01-04-2006	Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years	Accumulated Repair Cost as % of Acquisition 16. 0.0 19.4	Asset Condition 24% Good 00% Good 00% Good	Plan Retain Retain Retain	Comme N/A N/A N/A
	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623	Asset Name Blind Carpet Heater Interior Painting	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00 \$ 1176.00	15 Insta 10 8 15 10	01-04-2006 allation Date 01-04-2006 01-01-2013 01-04-2006 01-04-2006	Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years	Accumulated Repair Cost as % of Acquisition 16. 0.0 19.4	Asset Condition 24% Good 00% Good 00% Good 83% Good	Plan Retain Retain Retain Retain	N/A N/A N/A N/A
Living Toilet Room	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623	Sink & Fittings Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System	\$ 1587.00 Acquisition Cost (\$)	15 Insta 10 8 15 10 10	01-04-2006 01-04-2006 01-01-2013 01-04-2006 01-04-2006 06-07-2023	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years	21.0 Accumulated Repair Cost as % of Acquisition 16.3 0.0 19.1 281.0	Asset Condition 24% Good 00% Good 00% Good 00% Good Good Good Good Good Good	Plan Retain Retain Retain Retain	N/A N/A N/A N/A N/A
	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623 Asset Number	Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System Asset Name	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00 \$ 1176.00 \$ 1563.00 Acquisition Cost (\$) Effective Life (Y)	Insta 10 8 15 10 10 Insta	01-04-2006 01-04-2006 01-01-2013 01-04-2006 01-04-2006 06-07-2023	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 16. 0.0 19. 281.0 Accumulated Repair Cost as % of Acquisition	Asset Condition 24% Good 00% Good 00% Good 83% Good Asset Condition	Plan Retain Retain Retain Retain Retain	N/A N/A
Toilet Room	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623 Asset Number IGILU0032	Sink & Fittings Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System	\$ 1587.00 Acquisition Cost (\$)	15 Insta 10 8 15 10 10	01-04-2006 01-04-2006 01-01-2013 01-04-2006 01-04-2006 06-07-2023	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 16. 0.0 19. 281.0 Accumulated Repair Cost as % of Acquisition	Asset Condition 24% Good 00% Good 00% Good 00% Good Good Good Good Good Good	Plan Retain Retain Retain Retain	N/A N/A N/A N/A N/A
	IGILU0013 IGILU0014 Asset Number IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623 Asset Number IGILU0032	Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System Asset Name Interior Painting	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ \$ 865.00 \$ 1176.00 \$ 1563.00 Acquisition Cost (\$) Effective Life (Y)	Insta 10 8 15 10 10 10 10 10 Insta 10	01-04-2006 01-04-2006 01-01-2013 01-04-2006 01-04-2006 06-07-2023	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life -8.0 years	Accumulated Repair Cost as % of Acquisition 16. 0.0 19.1 281.0 Accumulated Repair Cost as % of Acquisition 22.1	Asset Condition 24% Good 00% Good 00% Good 00% Good Asset Condition Asset Condition 59% Good	Plan Retain Retain Retain Retain Retain Retain Retain	Comme N/A N/
Toilet Room	Asset Number IGILU0034 IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623 Asset Number IGILU0032	Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System Asset Name Interior Painting	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00 \$ 1176.00 \$ 1563.00 Acquisition Cost (\$) Effective Life (Y) \$ 166.00	Insta 10 8 15 10 10 Insta 10 Insta 10 Insta Inst	01-04-2006 allation Date 01-04-2006 01-01-2013 01-04-2006 06-07-2023 allation Date 01-04-2006	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life -8.0 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 16. 0.0 19. 281.0 Accumulated Repair Cost as % of Acquisition 22. Accumulated Repair Cost as % of Acquisition	Asset Condition 24% Good 00% Good 00% Good 00% Good Asset Condition Asset Condition Asset Condition	Plan Retain Retain Retain Retain Retain Retain Retain	Comme N/A Comme N/A
Toilet Room	Asset Number IGILU0034 IGILU0034 IGILU0036 IGILU0037 IGILU1623 Asset Number IGILU0032 IGILU0032 IGILU0032	Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System Asset Name Interior Painting Asset Name Courtyard	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00 \$ 1176.00 \$ 1563.00 Acquisition Cost (\$) Effective Life (Y) \$ 2486.00 \$ 2486.00	Insta 10 8 15 10 10 Insta 10 Insta 30	01-04-2006 01-04-2006 01-01-2013 01-04-2006 01-04-2006 06-07-2023 Illation Date 01-04-2006 01-04-2006	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life -8.0 years Remaining Effective Life -2.3 years	Accumulated Repair Cost as % of Acquisition 16.3 0.0 19.0 Accumulated Repair Cost as % of Acquisition 22.1 Accumulated Repair Cost as % of Acquisition 0.0	Asset Condition 24% Good 00% Good 00% Good 00% Good 00% Good Asset Condition 59% Good Asset Condition 00% Good	Plan Retain Retain Retain Retain Retain Retain Retain Plan Retain	Commer N/A N/A N/A N/A N/A N/A Commer N/A
Toilet Room	Asset Number IGILU0034 IGILU0034 IGILU0035 IGILU0036 IGILU0037 IGILU1623 Asset Number IGILU0032	Asset Name Blind Carpet Heater Interior Painting Air Conditioner - Solit System Asset Name Interior Painting	\$ 1587.00 Acquisition Cost (\$) Effective Life (Y) \$ 388.00 \$ 1165.00 \$ 865.00 \$ 1176.00 \$ 1563.00 Acquisition Cost (\$) Effective Life (Y) \$ 166.00	Insta 10 8 15 10 10 Insta 10 Insta 10 Insta Inst	01-04-2006 allation Date 01-04-2006 01-01-2013 01-04-2006 06-07-2023 allation Date 01-04-2006	-3.0 years Remaining Effective Life -8.0 years -3.3 years -3.0 years -8.0 years 9.3 years Remaining Effective Life -8.0 years Remaining Effective Life -2.3 years	Accumulated Repair Cost as % of Acquisition 16.3 0.0 19.0 Accumulated Repair Cost as % of Acquisition 22.1 Accumulated Repair Cost as % of Acquisition 0.0	Asset Condition 24% Good 00% Good 00% Good 00% Good Asset Condition Asset Condition Asset Condition	Plan Retain Retain Retain Retain Retain Retain Retain	Commer N/A N/A N/A N/A N/A N/A N/A

		Switchboard	\$ 130 1.00		0.0.1332	in it is a second of the secon		0000	rictani	'
	IGILU0046	Exterior painting	\$ 2086.00	10	01-01-1992	-22.3 years	0.009	6 Good	Retain	N/A
	IGILU0047	Fascias	\$ 2874.00					Good	Retain	N/A
	IGILU0048	Flyscreens	\$ 2186.00	10	01-01-1992	-22 3 years	86 519	Good	Retain	N/A
	IGILU0049	Guttering	\$ 2819.00					6 Good	Retain	N/A
	IGILU0050	Path	\$ 1509.00					Good	Retain	N/A
	IGILU0051	Porch	\$ 2908.00			•		6 Good	Retain	N/A
	IGILU0052		\$ 1098.00			•		6 Good	Retain	N/A
		Lattice Screening								
	IGILU0053	Windows	\$ 3873.00			•		Good	Retain	N/A
	IGILU1566	Awnings	\$ 9435.00	10	15-01-2010	-4.2 years	0.009	Good	Retain	N/A
Bathroom										
	Asset Number	Asset Name		Effective Life (Y)		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0075	Exhaust Fan	\$ 255.00				-	Good	Retain	N/A
	IGILU0076	Interior Painting	\$ 466.00				4.519	Good	Retain	N/A
	IGILU0077	Skylight	\$ 1010.00	10	01-01-1992	-22.3 years	30.63%	Good	Retain	N/A
	IGILU0078	Tapware	\$ 1304.00	15	01-01-1992	-17.3 years	144.179	Good	Retain	N/A
	IGILU0079	Tiles - Wall	\$ 3285.00	20	01-01-1992	-12.3 years	1.359	Good	Retain	N/A
	IGILU0080	Tiles - Floor	\$ 4884.00	20	01-01-1992	-12.3 years	1.359	Good	Retain	N/A
Bed 1						-				
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0067	Blind	\$ 333.00				·	6 Good	Retain	N/A
	IGILU0068	Carpet	\$ 1032.00					6 Good	Retain	N/A
	IGILU0069	Interior Painting	\$ 888.00					6 Good	Retain	N/A
	IGILU0070	Wardrobe	\$ 2053.00					6 Good	Retain	N/A
Bed 2	IGIEO0070	waitilobe	\$ 2033.00	10	01-01-1992	-22.3 years	0.007	GOOG	Retaili	IN/A
Beu Z	A 1 N 1	A 1 N	A1-111 C1 (f)	F((1'1'(-00	Land Harrison Bartis	D	A	Asset Condition	NI	<u></u>
	Asset Number	Asset Name		Effective Life (Y)		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition		Plan	Comments
	IGILU0071	Blind	\$ 333.00					Good	Retain	N/A
	IGILU0072	Carpet	\$ 688.00		01-01-1992			Good	Retain	N/A
	IGILU0073	Interior Painting	\$ 588.00					Good	Retain	N/A
	IGILU0074	Wardrobe	\$ 2053.00	10	01-01-1992	-22.3 years	22.539	Good	Retain	N/A
Dining										
	Asset Number	Asset Name		Effective Life (Y)		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0089	Asset Name Blind	\$ 388.00	10	01-01-1992	-22.3 years	18.049	Good	Plan Retain	N/A
				10	01-01-1992	-22.3 years	·	Good		N/A Carpet shows signs of
	IGILU0089	Blind	\$ 388.00	10	01-01-1992	-22.3 years	18.049	Good	Retain	N/A
	IGILU0089	Blind Carpet	\$ 388.00 \$ 910.00	10	01-01-1992 01-01-1992	-22.3 years -24.3 years	18.049 22.539	6 Good 6 Fair	Retain Replace	N/A Carpet shows signs of wear, indicating the need for replacement
	IGILU0089 IGILU0090	Blind Carpet Interior Painting	\$ 388.00 \$ 910.00 \$ 832.00	10	0 01-01-1992 01-01-1992 0 01-01-1992	-22.3 years -24.3 years -22.3 years	18.049 22.539 0.909	6 Good 6 Fair 6 Good	Retain Replace Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A
	IGILU0089	Blind Carpet Interior Painting Air Conditioner -	\$ 388.00 \$ 910.00	10	01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years	18.049 22.539 0.909	6 Good 6 Fair	Retain Replace	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old,
	IGILU0089 IGILU0090	Blind Carpet Interior Painting	\$ 388.00 \$ 910.00 \$ 832.00	10	0 01-01-1992 01-01-1992 0 01-01-1992	-22.3 years -24.3 years -22.3 years	18.049 22.539 0.909	6 Good 6 Fair 6 Good	Retain Replace Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years,
	IGILU0089 IGILU0090	Blind Carpet Interior Painting Air Conditioner -	\$ 388.00 \$ 910.00 \$ 832.00	10	0 01-01-1992 01-01-1992 0 01-01-1992	-22.3 years -24.3 years -22.3 years	18.049 22.539 0.909	6 Good 6 Fair 6 Good	Retain Replace Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a
Kitchen	IGILU0089 IGILU0090	Blind Carpet Interior Painting Air Conditioner -	\$ 388.00 \$ 910.00 \$ 832.00	10	0 01-01-1992 01-01-1992 0 01-01-1992	-22.3 years -24.3 years -22.3 years	18.049 22.539 0.909	6 Good 6 Fair 6 Good	Retain Replace Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years,
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814	Blind Carpet Interior Painting Air Conditioner - Split System	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00	10	01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years	18.049 22.539 0.909 0.009	Good 6 Fair 6 Good 6 Poor	Retain Replace Retain Replace	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$)	10 10 11 11 11 11 11 11 11 11 11 11 11 1	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition	Good Fair Good Poor Asset Condition	Retain Replace Retain Replace	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00	10 10 10 Effective Life (Y)	01-01-1992 01-01-1992 01-01-1992 01-01-1992 Installation Date	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years Remaining Effective Life -12.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839	Good 6 Fair 6 Good 6 Poor Asset Condition	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00	10 10 10 10 10 10 10 10 10 10 10 10 10 1	01-01-1992 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -22.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029	Good 6 Fair 6 Good 6 Poor Asset Condition 6 Good 6 Good	Retain Replace Retain Replace Plan Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age Comments N/A N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00	10 10 10 10 10 10 10 10 10 10 10 10 10 1	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069	Good Fair Good Foor Asset Condition Good Good Good	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age Comments N/A N/A N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0059 IGILU0059 IGILU0060 IGILU0061	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00	Effective Life (Y)	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119	Good Good Good Good Good Good Good Good	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age Comments N/A N/A N/A N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00	Effective Life (Y) 20 11 12 21 22	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069	Good Good Good Good Good Good Good Good	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A N/A N/A N/A Vinyl shows signs of
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0059 IGILU0059 IGILU0060 IGILU0061	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00	Effective Life (Y)	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119	Good Good Good Good Good Good Good Good	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0062	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00	Effective Life (Y) 20 11 20 11	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years -22.3 years -22.3 years -22.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0059 IGILU0059 IGILU0060 IGILU0061	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00	Effective Life (Y) 20 11 20 11	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -20.3 years -22.3 years -22.3 years -22.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Good Good Good Good Good Good Good	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A N/A N/A N/A Viryl shows signs of wear, indicating the
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0062 IGILU0063	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 770.00 \$ 3818.00 \$ 1010.00	Effective Life (Y) 20 10 11 11 11 11 11 11 11 11 11 11 11 11	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -23.3 years -20.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain Retain Replace Replace	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0063	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00	Effective Life (Y) 2(10 2(11 21 11 21 11 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -22.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain Replace	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment N/A N/A N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0064 IGILU0065	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00	Effective Life (Y) 20 11 10 21 11 11 11 11 11 11 11 11	01-01-1992 01-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -22.3 years -22.3 years -22.3 years -23 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain Retain Retain Replace	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable are Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment N/A N/A N/A N/A N/A N/A N/A N/A N/A
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0063	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00	Effective Life (Y) 2(11 10 20 11 11 11 11 11 11 11	Installation Date 0 10-01-1992 Installation Date 0 10-01-1992 Installation Date 0 10-01-1992 0 10-01-1992 0 10-01-1992 0 10-01-1992 0 10-01-1992	-22.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -22.3 years -22.3 years -22.3 years -23 years -20.3 years -20.3 years -20.3 years	18.049 22.539 0.909 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain Replace	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment N/A N/A N/A
Kitchen	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0062 IGILU0063 IGILU0064 IGILU0065 IGILU0066	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1409.00 \$ 1409.00 \$ 1587.00 \$ 260.00	Effective Life (Y) 20 11 11 12 11 12 12 12 12 12 12 13 14 15 16 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -23.3 years -23.3 years -24.3 years -25.3 years -26.3 years -27.3 years -27.3 years -27.3 years -27.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109 32.329 2.259 15.029 13.569	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment N/A
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0061 IGILU0063 IGILU0064 IGILU0066 IGILU0066 Asset Number	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 770.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00	Effective Life (Y) 2(01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -20.3 years -22.3 years -20.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109 32.329 2.259 15.029 13.569 Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain Retain Retain Retain Retain Retain Retain Replace Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age Comments N/A
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0064 IGILU0065 IGILU0066 Asset Number IGILU0085	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Blind	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$)	Effective Life (Y) 20 10 11 21 11 21 11 21 12 11 12 11 11 11 11	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.3 years -22.3 years -22.3 years -20.3 years -22.3 years -22.3 years -22.3 years -22.3 years -22.3 years -22.3 years -23 years -24.3 years -25.3 years -26.3 years -27.3 years -27.3 years -28.3 years -29.3 years -29.3 years -29.3 years -29.3 years -29.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109 32.329 2.259 15.029 13.569 Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0064 IGILU0065 IGILU0066 Asset Number IGILU0085 IGILU0085	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Blind Carpet	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00	Effective Life (Y) 2(11 10 22 11 11 12 12 15 16 17 18 18 19 19 10 10 10 10 10 10 10 10 10 10 10 10 10	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -23.9 years -24.3 years -25.3 years -26.3 years -27.3 years -28.3 years -29.3 years -29.3 years -29.3 years -29.3 years -29.3 years -29.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109 32.329 2.259 15.029 13.569 Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and considerable a
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0065 IGILU0066 IGILU0066 Asset Number IGILU0066 IGILU0066	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Bilind Carpet Heater	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 710.00 \$ 1409.00 \$ 1587.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00 \$ 1165.00	Effective Life (Y) 20 11 10 11 11 11 11 11 11 12 11 12 11 11 12 11 11	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.4 years -24.3 years -25.3 years -26.3 years -27.3 years -17.3 years -17.3 years -17.3 years -17.3 years -17.3 years -17.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 8.119 90.109 32.329 13.569 Accumulated Repair Cost as % of Acquisition 18.049 9.589 9.589	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for replacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A N/A N/A Vinyl shows signs of wear, indicating the need for refurbishment N/A
Living	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0064 IGILU0065 IGILU0066 Asset Number IGILU0085 IGILU0085	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Blind Carpet	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 Acquisition Cost (\$) \$ 2342.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00	Effective Life (Y) 20 11 10 21 11 11 21 11 21 Effective Life (Y)	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -22.3 years -22.4 years -24.3 years -25.3 years -26.3 years -27.3 years -17.3 years -17.3 years -17.3 years -17.3 years -17.3 years -17.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 8.119 90.109 32.329 13.569 Accumulated Repair Cost as % of Acquisition 18.049 9.589 9.589	Good Fair Good Good Good Good Good Good Good Goo	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and considerable a
	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0061 IGILU0061 IGILU0063 IGILU0064 IGILU0066 Asset Number IGILU0085 IGILU0086 IGILU0086	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Blind Carpet Heater Interior Painting	\$ 388.00 \$ 910.00 \$ 1563.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 770.00 \$ 3818.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00 \$ 865.00	Effective Life (Y) 20 11 12 11 12 12 11 12 12 11 12 11 12 11 12 11 12 11 12 11 12 11 12 11 12 12	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -24.3 years -22.3 years -23.9 years -24.3 years -25.3 years -27.3 years	18.049 22.539 0.909 0.009 0.009 Accumulated Repair Cost as % of Acquisition 3.839 15.029 36.069 8.119 90.109 32.329 2.259 15.029 13.569 Accumulated Repair Cost as % of Acquisition 18.049 9.589 0.009	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A
Living	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0060 IGILU0061 IGILU0063 IGILU0064 IGILU0065 IGILU0066 Asset Number IGILU0085 IGILU0088	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Bilind Carpet Heater	\$ 388.00 \$ 910.00 \$ 832.00 \$ 1563.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 710.00 \$ 3818.00 \$ 1010.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00 \$ 1176.00	Effective Life (Y) Effective Life (Y) 20 10 11 12 11 12 11 12 11 11 11 11 11 11 11	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -24.3 years -22.3 years -23 years -24.3 years -25.3 years -27.3 years	18.049 22.539 0.909 0.00	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable age. Comments N/A
Living	IGILU0089 IGILU0090 IGILU0091 IGILU1814 Asset Number IGILU0058 IGILU0059 IGILU0061 IGILU0061 IGILU0063 IGILU0064 IGILU0066 Asset Number IGILU0085 IGILU0086 IGILU0086	Blind Carpet Interior Painting Air Conditioner - Split System Asset Name Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl Electric Elevated Oven Rangehood Sink & Fittings Smoke Alarms Asset Name Blind Carpet Heater Interior Painting	\$ 388.00 \$ 910.00 \$ 1563.00 \$ 1563.00 \$ 1563.00 \$ 1354.00 \$ 770.00 \$ 3818.00 \$ 1409.00 \$ 599.00 \$ 1587.00 \$ 260.00 Acquisition Cost (\$) \$ 388.00 \$ 1165.00 \$ 865.00	Effective Life (Y) Effective Life (Y) 20 10 11 12 11 12 11 12 11 11 11 11 11 11 11	01-01-1992 01-01-1992	-22.3 years -24.3 years -24.3 years -24.3 years -22.3 years -23 years -24.3 years -25.3 years -27.3 years	18.049 22.539 0.909 0.00	Asset Condition Good Good Good Good Good Good Good Go	Retain Replace Retain Replace Plan Retain	N/A Carpet shows signs of wear, indicating the need for renlacement N/A Condition is very old, exceeding 15 years, suggesting a considerable and Comments N/A

Unit 2

IGILU0082

Toilet & Cistern

\$ 1343.00

20

01-01-1992 -12.3 years

Electrical

\$ 1964.00

20

01-01-1992 -12.3 years

N/A

Retain

92.16% Good

0.00% Good

Retain

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0092	Clothesline	\$ 499.00		10 01-01-1992	2 -22.3 years	0.00%	Good	Retain	N/A
	IGILU0093	Courtyard	\$ 2486.00		30 01-01-1992	2 -2.3 years	0.00%	Good	Retain	N/A
	IGILU0094	Doors	\$ 5605.00		30 01-01-1992	2 -2.3 years	1.80%	Good	Retain	N/A
	IGILU0095	Downpipes	\$ 1742.00		20 01-01-1992	2 -12.3 years	43.26%	Good	Retain	N/A
	IGILU0096	Electrical	\$ 1964.00		20 01-01-1992	2 -12.3 years	89.03%	Good	Retain	N/A
		Switchboard								
	IGILU0097	Exterior painting	\$ 2086.00		10 01-01-1992	2 -22.3 years	2.25%	Good	Retain	N/A
	IGILU0098	Fascias	\$ 2874.00		20 01-01-1992	2 -12.3 years	2.70%	Good	Retain	N/A
	IGILU0099	Flyscreens	\$ 2186.00		10 01-01-1992	2 -22.3 years	0.00%	Good	Retain	N/A
	IGILU0100	Guttering	\$ 2819.00			2 -12.3 years		Good	Retain	N/A
	IGILU0101	Path	\$ 1509.00		30 01-01-1992			Good	Retain	N/A
	IGILU0102	Porch	\$ 2908.00		30 01-01-1992	-		Good	Retain	N/A
						· ·				
	IGILU0103	Lattice Screening	\$ 1098.00			2 -12.3 years		Good	Retain	N/A
	IGILU0104	Windows	\$ 3873.00		30 01-01-1992	<u> </u>		Good	Retain	N/A
	IGILU1572	Awnings	\$ 9435.00		10 15-01-2010) -4.2 years	0.00%	Good	Retain	N/A
ommon										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0002b	Driveway	\$ 21978.00		25 01-01-1992	2 -7.3 years	0.00%	Good	Retain	N/A
nit 3										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0106	Insulation	\$ 3069.00			2 -12.3 years		Good	Retain	N/A
	IGILU0107		\$ 1909.00			· ·	18.02%		Retain	N/A
		Lighting				2 -17.3 years				
	IGILU0108	Sarking	\$ 3174.00		25 01-01-1992	-		Good	Retain	N/A
	IGILU0109	Hot Water System -	\$ 2386.00		12 01-01-1992	2 -20.3 years	18.77%	Excellent	Retain	N/A
		Electric								
nit 4										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0160	Insulation	\$ 3069.00		20 01-01-1992	-12.3 years	0.00%	Good	Retain	N/A
	IGILU0161	Lighting	\$ 1909.00		15 01-01-1992	2 -17.3 years	6.01%	Good	Retain	N/A
	IGILU0162	Sarking	\$ 3174.00		25 01-01-1992	2 -7.3 years	54.06%	Good	Retain	N/A
	IGILU0162 IGILU0163	Sarking Hot Water System -	\$ 3174.00 \$ 2386.00			2 -7.3 years 2 -20.3 years	54.06% 31.62%		Retain Retain	N/A N/A
		Hot Water System -								
tchen		Hot Water System -								
tchen		Hot Water System -					31.62%			
tchen	IGILU0163 Asset Number	Hot Water System - Electric	\$ 2386.00 Acquisition Cost (\$)	Effective Life (Y)	12 01-01-1992 Installation Date	2 -20.3 years Remaining Effective Life	31.62% Accumulated Repair Cost as % of Acquisition	Good Asset Condition	Retain	N/A Comments
	IGILU0163	Hot Water System - Electric	\$ 2386.00	Effective Life (Y)	12 01-01-1992	2 -20.3 years Remaining Effective Life	31.62%	Good Asset Condition	Retain	N/A
tchen	Asset Number	Hot Water System - Electric Asset Name Sink & Fittings	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00	Effective Life (Y)	12 01-01-1992 Installation Date 15 01-05-2019	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 90.11%	Asset Condition	Plan Retain	Comments N/A
	Asset Number	Asset Name Sink & Fittings Asset Name	Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	12	Remaining Effective Life 10.1 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition	Plan Retain	Comments N/A Comments
	Asset Number	Hot Water System - Electric Asset Name Sink & Fittings Asset Name Air Conditioner -	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00	Effective Life (Y) Effective Life (Y)	12 01-01-1992 Installation Date 15 01-05-2019	Remaining Effective Life 10.1 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 90.11%	Asset Condition Good Asset Condition	Plan Retain	Comments N/A
ving	Asset Number IGILU0117 Asset Number IGILU0138	Asset Name Sink & Fittings Asset Name	Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	12	Remaining Effective Life 10.1 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition	Plan Retain	Comments N/A Comments
ving	Asset Number IGILU0117 Asset Number IGILU0138	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00	Effective Life (Y) Effective Life (Y)	12 01-01-1992	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42%	Asset Condition Good Asset Condition	Plan Retain Plan Retain Retain	Comments N/A Comments N/A
ring	Asset Number IGILU0138 Asset Number	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name	Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	12	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Asset Condition	Plan Retain Plan Retain Plan Retain	Comments N/A Comments N/A Comments
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesline	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3296.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	12 01-01-1992	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life 2-22.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04%	Asset Condition Good Asset Condition Good Asset Condition Good	Plan Retain Plan Retain Plan Retain Plan Retain	Comments N/A Comments N/A Comments N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesline Courtyard	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 Acquisition Cost (\$) \$ 4499.00 \$ 2486.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	12 01-01-1992	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life 2.22.3 years 2.2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0148 IGILU0149	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors	Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 Acquisition Cost (\$) \$ 4490.00 \$ 2486.00 \$ 5605.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.22.3 years -2.3 years -2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesline Courtyard Doors Downpipes	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 4499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life 2-22.3 years 2-23 years -2.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0148 IGILU0149	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors	Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 Acquisition Cost (\$) \$ 4490.00 \$ 2486.00 \$ 5605.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.22.3 years -2.3 years -2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 2486.00 \$ 2486.00 \$ 1742.00 \$ 1964.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	12 01-01-1992	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life -22.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesian Courtyard Doors Downpipes Electrical	\$ 2386.00 Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 4499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life 2-22.3 years 2-23 years -2.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A
ing	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 2486.00 \$ 2486.00 \$ 1742.00 \$ 1964.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life -22.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good	Plan Retain Plan Retain Plan Retain Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A
ing	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0152	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3296.00 \$ 1742.00 \$ 1964.00 \$ 2086.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2. 22.3 years -2.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.2 years -2.2 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ing	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0152 IGILU0153	Asset Name Sink & Fittings Asset Name Air Conditioner - Split System Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 4499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	12	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 222.3 years 2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	Comments N/A Comments N/A Comments N/A
ring	Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0150 IGILU0151 IGILU0152 IGILU0152 IGILU0153 IGILU0154 IGILU0155	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 15.1 years Remaining Effective Life 2-22.3 years 2-2.3 years 2-12.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain	N/A
ring	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0152 IGILU0153 IGILU0154 IGILU0155 IGILU0156	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 2486.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 22874.00 \$ 22819.00 \$ 21819.00 \$ 15199.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A
ving	Asset Number IGILU0117 Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0155 IGILU0154 IGILU0155 IGILU0156 IGILU0157	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 296.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2186.00 \$ 22874.00 \$ 22874.00 \$ 22874.00 \$ 22874.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2. 22.3 years -2.3 years -12.3 years -2.3 years -2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 1.35% 27.03%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A
	Asset Number IGILU0117 Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0155 IGILU0155 IGILU0156 IGILU0157 IGILU0157	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 2908.00 \$ 15098.00 \$ 1098.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life 10.1 years Remaining Effective Life 10.1 years S.1 years Remaining Effective Life 2.22.3 years 2.23 years 2.23 years 2.12.3 years 2.12.3 years 2.22.3 years 2.12.3 years 2.12.3 years 2.12.3 years 2.23 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A
ving	Asset Number IGILU0117 Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0155 IGILU0154 IGILU0155 IGILU0156 IGILU0157	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 296.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2186.00 \$ 22874.00 \$ 22874.00 \$ 22874.00 \$ 22874.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 10.1 years S.1 years Remaining Effective Life 2.22.3 years 2.23 years 2.23 years 2.12.3 years 2.12.3 years 2.22.3 years 2.12.3 years 2.12.3 years 2.12.3 years 2.23 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 1.35% 27.03%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ving	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0152 IGILU0153 IGILU0154 IGILU0155 IGILU0156 IGILU0157 IGILU0157 IGILU0158 IGILU0159	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 299.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2181.00 \$ 2181.00 \$ 1509.00 \$ 3 2908.00 \$ 3 3873.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.2.3 years 2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0155 IGILU0155 IGILU0156 IGILU0157 IGILU0157	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 2908.00 \$ 15098.00 \$ 1098.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 10.1 years S.1 years Remaining Effective Life 2.22.3 years 2.23 years 2.23 years 2.12.3 years 2.12.3 years 2.22.3 years 2.12.3 years 2.12.3 years 2.12.3 years 2.23 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0152 IGILU0153 IGILU0154 IGILU0155 IGILU0156 IGILU0157 IGILU0157 IGILU0158 IGILU0159	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 299.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2181.00 \$ 2181.00 \$ 1509.00 \$ 3 2908.00 \$ 3 3873.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.2.3 years 2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ving	Asset Number IGILU0117 Asset Number IGILU0117 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0150 IGILU0150 IGILU0151 IGILU0151 IGILU0152 IGILU0153 IGILU0154 IGILU0155 IGILU0155 IGILU0156 IGILU0157 IGILU0157 IGILU0158 IGILU0159 IGILU0159	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 1998.00 \$ 3873.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2-22.3 years 2-2.3 years 2-12.3 years 2-12.3 years 2-12.3 years 2-12.3 years 2-12.3 years 2-2.3 years 2-2.3 years 2-2.3 years 2-2.3 years 2-3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11% 5.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A
ring	Asset Number IGILU0117 Asset Number IGILU0118 Asset Number IGILU0138 Asset Number IGILU0147 IGILU0148 IGILU0149 IGILU0150 IGILU0151 IGILU0151 IGILU0152 IGILU0153 IGILU0154 IGILU0155 IGILU0156 IGILU0157 IGILU0157 IGILU0158 IGILU0159	Asset Name Sink & Fittings Asset Name Air Conditioner - Solit System Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1587.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 299.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2181.00 \$ 2181.00 \$ 1509.00 \$ 3 2908.00 \$ 3 3873.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 15	Remaining Effective Life 10.1 years Remaining Effective Life 5.1 years Remaining Effective Life 2.2.3 years 2.3 years	Accumulated Repair Cost as % of Acquisition 90.11% Accumulated Repair Cost as % of Acquisition 178.42% Accumulated Repair Cost as % of Acquisition 18.04% 0.00% 4.82% 36.05% 129.20% 9.91% 9.91% 12.62% 104.20% 1.35% 27.03% 8.11%	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain Plan Retain Plan Retain	N/A Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A

Interior Painting

\$ 166.00

10

01-01-1992 -22.3 years

18.07% Good

Retain

N/A

IGILU0083

Unit 3-4

Unit 3

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation [Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0171	Sink & Fittings	\$ 1587.00		15 0	1-11-2021	12.6 years	120.149	Good	Retain	N/A
oilet Room											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation [Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0191	Toilet & Cistern	\$ 1343.00		20 0	1-11-2021	17.6 years	108.129	Good	Retain	N/A
it Exterior	A A No	Asset Name	A !:!!: C! (6)	F((1)1'(-00	Landa Hardana B		Description Effective 196	Assembled Breeds Controlly of Assembles	Asset Condition	DI	C
	Asset Number		Acquisition Cost (\$)	Effective Life (Y)	Installation [Remaining Effective Life -22.3 years	Accumulated Repair Cost as % of Acquisition		Plan	Comments
	IGILU0204	Clothesline	\$ 499.00 \$ 2486.00						Good	Retain	N/A N/A
	IGILU0205	Courtyard					-2.3 years			Retain	
	IGILU0206	Doors Downpipes	\$ 5605.00 \$ 1742.00				-2.3 years -12.3 years		Good	Retain Retain	N/A N/A
	IGILU0208		\$ 1742.00				-12.3 years		Good		N/A
	IGILUUZUB	Electrical Switchboard	\$ 1904.00		20 0	1-01-1992	- 12.5 years	15.90	5 G000	Retain	IN/A
	IGILU0209	Exterior painting	\$ 2086.00		10 0	1-01-1992	-22.3 years	18.029	Good	Retain	N/A
	IGILU0210	Fascias	\$ 2874.00			1-01-1992	-12.3 years		Good	Retain	N/A
	IGILU0211	Flyscreens	\$ 2186.00				-22.3 years	54.079		Repair	Entry door flyscreen is tight within the openin causing difficulty in pushing/pulling; repair required for smooth operation.
	IGILU0212	Guttering	\$ 2819.00		20 0	1-01-1992	-12.3 years	0.009	Good	Retain	N/A
	IGILU0212	Path	\$ 1509.00			1-01-1992			Good	Retain	N/A
	IGILU0214	Porch	\$ 2908.00			1-01-1992			Good	Retain	N/A
	IGILU0215	Lattice Screening	\$ 1098.00				-12.3 years		Good	Retain	N/A
	IGILU0216	Windows	\$ 3873.00			1-01-1992			Good	Retain	N/A
	IGILU1587	Awnings	\$ 9435.00			5-01-2010			Good	Retain	N/A
	IGIEO 1307	Awiiiigs	\$ 5455.00		10	3 01 2010	4.2 years	0.507	Good	retuiii	14/74
nit 5											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation [Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0218	Insulation	\$ 3069.00		20 0	1-01-1992	-12.3 years	0.009	Good	Retain	N/A
	IGILU0219	Lighting	\$ 1909.00		15 0	1-01-1992	-17.3 years	15.029	Good	Retain	N/A
	IGILU0220	Sarking	\$ 3174.00		25 0	1-01-1992	-7.3 years	32.449	Good	Retain	N/A
	IGILU0221	Hot Water System -	\$ 2386.00		12 0	1-01-1992	-20.3 years	1.509	Good	Retain	N/A
		Electric									
it 6											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation [Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0271	Insulation	\$ 3069.00				-12.3 years		Excellent	Retain	N/A
	IGILU0272	Lighting	\$ 1909.00				-17.3 years		Good	Retain	N/A
	IGILU0273	Sarking	\$ 3174.00			1-01-1992			Good	Retain	N/A
	IGILU0274	Hot Water System	\$ 2386.00		12 0	1-01-1992	-20.3 years	0.009	Good	Retain	N/A
		Electric									
throom											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation [Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0241	Exhaust Fan	\$ 255.00		10 0	1-05-2004	-9.9 years	43.299	Excellent	Retain	N/A
	IGILU0242	Interior Painting	\$ 466.00		10 0	1-05-2004	-9.9 years	14.429	Excellent	Retain	N/A
	IGILU0243	Toilet & Cistern	\$ 1343.00		20 0	1-05-2004	0.1 years	49.559	Excellent	Retain	N/A
	IGILU0244	Skylight	\$ 1010.00			1-05-2004			Excellent	Retain	N/A
	IGILU0245	Tapware	\$ 1304.00			1-05-2004	-		Excellent	Retain	N/A
						1-05-2004			Excellent	Retain	N/A
		Tiles - Wall	\$ 3285.00						Excellent	Repair	Visible grout marks
	IGILU0246 IGILU0247	Tiles - Wall Tiles - Floor	\$ 3285.00 \$ 4884.00		20 0	1-05-2004	o.i years	4.217		'	absorus di concessi.
	IGILU0246				20 0	1-05-2004	o.r. yeurs	4,277			observed; regrouting is needed to restore
d 1	IGILU0246 IGILU0247	Tiles - Floor	\$ 4884.00								needed to restore
ed 1	IGILU0246 IGILU0247 Asset Number	Tiles - Floor Asset Name	\$ 4884.00 Acquisition Cost (\$)	Effective Life (Y)	Installation [Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	needed to restore Comments
ed 1	IGILU0246 IGILU0247 Asset Number IGILU0232	Tiles - Floor Asset Name Blind	\$ 4884.00 Acquisition Cost (\$) \$ 333.00	Effective Life (Y)	Installation I	Date 1-05-2004	Remaining Effective Life -9.9 years	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan Retain	Comments N/A
ed 1	Asset Number IGILU0232 IGILU0233	Asset Name Blind Carpet	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00	Effective Life (Y)	Installation I 10 0 8 0	Date 1-05-2004 1-05-2004	Remaining Effective Life -9.9 years -11.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459	Asset Condition Good Good	Plan Retain Retain	Comments N/A N/A
ed 1	IGILU0246 IGILU0247 Asset Number IGILU0232 IGILU0233 IGILU0234	Asset Name Blind Carpet Ceiling Fan	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00	Effective Life (Y)	Installation 10	Date 1-05-2004 1-05-2004 1-05-2004	Remaining Effective Life -9.9 years -11.9 years -9.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259	Asset Condition Good Good Good	Plan Retain Retain Retain	Comments N/A N/A N/A
ed 1	Asset Number IGILU0232 IGILU0233 IGILU0234 IGILU0235	Asset Name Blind Carpet Ceiling Fan Interior Painting	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00 \$ 888.00	Effective Life (Y)	Installation 10	Date 1-05-2004 1-05-2004 1-05-2004 1-05-2004	Remaining Effective Life -9.9 years -11.9 years -9.9 years -9.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259 4.509	Asset Condition Good Good Good Good Good	Plan Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A
	IGILU0246 IGILU0247 Asset Number IGILU0232 IGILU0233 IGILU0234	Asset Name Blind Carpet Ceiling Fan	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00	Effective Life (Y)	Installation 10	Date 1-05-2004 1-05-2004 1-05-2004	Remaining Effective Life -9.9 years -11.9 years -9.9 years -9.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259 4.509	Asset Condition Good Good Good	Plan Retain Retain Retain	Comments N/A N/A N/A
	Asset Number IGILU0232 IGILU0233 IGILU0234 IGILU0235 IGILU0235	Asset Name Blind Carpet Ceiling Fan Interior Painting Wardrobe	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00 \$ 888.00 \$ 2053.00	Effective Life (Y)	Installation 10	Date 1-05-2004 1-05-2004 1-05-2004 1-05-2004 1-05-2004	Remaining Effective Life 9.9 years -11.9 years 9.9 years -9.9 years -9.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259 4.509 19.829	Asset Condition Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A
Ged 1	Asset Number IGILU0247 Asset Number IGILU0232 IGILU0233 IGILU0234 IGILU0235 IGILU0236 Asset Number	Asset Name Blind Carpet Ceiling Fan Interior Painting Wardrobe Asset Name	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Inst	Date 1-05-2004 1-05-2004 1-05-2004 1-05-2004 1-05-2004 Date	Remaining Effective Life 9.9 years -11.9 years -9.9 years -9.9 years -9.9 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259 4.509 19.829 Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Asset Condition	Plan Retain Retain Retain Retain Retain Retain Retain	N/A
	Asset Number IGILU0232 IGILU0233 IGILU0234 IGILU0235 IGILU0235	Asset Name Blind Carpet Ceiling Fan Interior Painting Wardrobe	\$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 588.00 \$ 888.00 \$ 2053.00	Effective Life (Y) Effective Life (Y)	Installation Inst	Date 1-05-2004 1-05-2004 1-05-2004 1-05-2004 1-05-2004 Date	Remaining Effective Life 9.9 years -11.9 years 9.9 years -9.9 years -9.9 years	Accumulated Repair Cost as % of Acquisition 16.229 8.459 34.259 4.509 19.829 Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A

Unit 5-6

	IGILU0238	Carpet	\$ 688.00		8 01-05-2004	-11.9 years	1.13%	Good	Retain	N/A
	IGILU0239	Interior Painting	\$ 588.00	1	01-05-2004	-9.9 years	9.01%	Good	Retain	N/A
	IGILU0240	Wardrobe	\$ 2053.00	1	01-05-2004	-9.9 years	4.51%	Good	Retain	N/A
Dining										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
,	IGILU0254	Blind	\$ 388.00		01-05-2004		36.08%		Retain	N/A
	IGILU0255	Carpet	\$ 910.00		8 01-05-2004		0.56%		Retain	N/A
	IGILU0256	Ceiling Fan	\$ 588.00		01-05-2004	•	34.25%		Retain	N/A
	IGILU0257	-	\$ 832.00			· ·				N/A
	IGILU0257	Interior Painting	\$ 052.00	'	01-05-2004	-9.9 years	5.41%	Good	Retain	IN/A
Kitchen	A 1 NI I	A A NI	A 1-111 C1 (A)	F((1'1'(-00	Land Harden Barta	D	A	A C 1717	NI	C
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	_	Remaining Effective Life		Asset Condition	Plan	Comments
	IGILU0222	Blind	\$ 333.00		01-05-2004	•	19.82%		Retain	N/A
	IGILU0223	Benchtops	\$ 2342.00		20 01-05-2004		8.56%		Retain	N/A
	IGILU0224	Cooktop	\$ 1354.00		2 01-05-2004	•	30.03%		Retain	N/A
	IGILU0225	Interior Painting	\$ 710.00		01-05-2004	•	34.25%		Retain	N/A
	IGILU0226	Kitchen Cabinets	\$ 3818.00		20 01-05-2004		2.25%		Retain	N/A
	IGILU0227	Vinyl	\$ 1010.00	1	01-05-2004	-9.9 years	56.31%	Good	Retain	N/A
	IGILU0228	Electric Elevated	\$ 1409.00	1	2 01-05-2004	-7.9 years	150.22%	Good	Retain	N/A
		Oven								
	IGILU0229	Rangehood	\$ 599.00		01-05-2004	-7.9 years	69.59%	Good	Retain	N/A
	IGILU0230	Sink & Fittings	\$ 1587.00		01-05-2004		120.14%		Retain	N/A
	IGILU0231	Smoke Alarms	\$ 260.00	2	20 01-05-2004	0.1 years	5.42%	Good	Retain	N/A
Living										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0249	Blind	\$ 388.00	1	01-05-2004	-9.9 years	16.24%	Good	Retain	N/A
	IGILU0250	Carpet	\$ 1165.00		8 01-05-2004	-11.9 years	10.14%	Good	Retain	N/A
	IGILU0251	Ceiling Fan	\$ 588.00	1	01-05-2004	-9.9 years	16.22%	Good	Retain	N/A
	IGILU0252	Heater	\$ 865.00	1	01-05-2004	-4.9 years	0.00%	Excellent	Retain	N/A
	IGILU0253	Interior Painting	\$ 1176.00	1	01-05-2004	-9.9 years	27.04%	Excellent	Retain	N/A
Unit Exterior						,				,
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
,	IGILU0258	Clothesline	\$ 499.00		01-01-1992		19.84%	Good	Retain	N/A
	IGILU0259	Courtyard	\$ 2486.00		01-01-1992		0.00%		Retain	N/A
	IGILU0260	Doors	\$ 5605.00		01-01-1992		7.51%		Retain	N/A
	IGILU0261	Downpipes	\$ 1742.00		20 01-01-1992		16.22%		Retain	N/A
		Downpipes	\$ 1742.00	-	.0 01 01 1332		10.2270	0000		14/7
		Electrical	\$ 1964.00	2	01 01 1002		66 62%	Good		NI/A
	IGILU0262	Electrical	\$ 1964.00	2	20 01-01-1992	-12.3 years	66.63%	Good	Retain	N/A
		Switchboard							Retain	
	IGILU0263	Switchboard Exterior painting	\$ 2086.00	1	0 01-01-1992	-22.3 years	4.06%	Good	Retain Retain	N/A
	IGILU0263 IGILU0264	Switchboard Exterior painting Fascias	\$ 2086.00 \$ 2874.00	1 2	0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years	4.06% 4.51%	Good	Retain Retain Retain	N/A N/A
	IGILU0263 IGILU0264 IGILU0265	Switchboard Exterior painting Fascias Flyscreens	\$ 2086.00 \$ 2874.00 \$ 2186.00	1 2	0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -22.3 years	4.06% 4.51% 7.21%	Good Good	Retain Retain Retain Retain	N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266	Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00	1 2 1 2	0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -22.3 years -12.3 years	4.06% 4.51% 7.21% 6.76%	Good Good Good	Retain Retain Retain Retain Retain	N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267	Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00	1 2 1 2 3	0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years	4.06% 4.51% 7.21% 6.76% 1.50%	Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00	1 2 1 2 3 3	0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00	1 2 1 2 3 3 3	0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -12.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00	1 2 1 2 1 2 2 3 3 3 3 2 2 3 3	0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86% 12.01%	Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00	1 2 1 2 1 2 2 3 3 3 3 2 2 3 3	0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992	-22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86%	Good Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00	1 2 1 2 1 2 2 3 3 3 3 2 2 3 3	0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86% 12.01%	Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A
	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU0591	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	1 2 1 2 3 3 3 2 2	0 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-1992 0 01-01-2010	-22.3 years -22.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years -2.4 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86% 12.01%	Good Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU01591	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	1 2 1 2 3 3 3 2 2 3 3 1 Effective Life (Y)	0 0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-22.3 years -22.3 years -12.3 years -12.3 years -2.3 years -1.2 years -1.2 years -1.2 years -1.2 years -2.3 years -2.4 years	4.06% 4.51% 7.21% 6.76% 1.50% 60.06% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU1591 Asset Number IGILU0293	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2196.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 3873.00 \$ 3473.00 \$ 4435.00	1 2 1 2 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.4 years -2.4 years -2.5 years -2.7 years -2.8 years -2.9 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0269 IGILU0270 IGILU0270 IGILU0270 IGILU0293 IGILU0293	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00	1 2 1 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-01-01 00 01-12-2010	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.4 years -2.4 years -2.5 years -2.7 years -2.8 years -2.9 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.6% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0270 IGILU0270 IGILU0271 IGILU0291 IGILU0294 IGILU0296	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00	1 2 1 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 1-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 15-01-2010 Installation Date 0 0 1-12-2005 0 0 1-12-2005	-22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -12.3 years -12.3 years -12.4 years -12.9 years -12.9 years -12.9 years -8.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 1.50% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0269 IGILU0270 IGILU0270 IGILU0270 IGILU0293 IGILU0293	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00	1 2 1 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-01-01 00 01-12-2010	-22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -12.3 years -12.3 years -12.4 years -12.9 years -12.9 years -12.9 years -8.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.6% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0270 IGILU0270 IGILU0271 IGILU0291 IGILU0294 IGILU0296	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00	1 2 1 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 1-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 15-01-2010	-22.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -2.3 years -2.4 years -2.8 years -2.9 years -2.9 years -2.9 years -2.9 years -2.9 years -3.9 years -3.9 years -3.9 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 1.50% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0270 IGILU0270 IGILU0271 IGILU0291 IGILU0294 IGILU0296	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00	1 2 1 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 1-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 15-01-2010	-22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -12.3 years -12.3 years -12.4 years -12.9 years -12.9 years -12.9 years -8.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 1.50% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0270 IGILU0270 IGILU0293 IGILU0294 IGILU0294 IGILU0297	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 255.00 \$ 1010.00 \$ 1304.00	1 2 2 3 3 3 2 2 3 3 1 1 Effective Life (Y)	0 0 1-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 01-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-1992 0 0 10-01-12-2005 0 0 11-12-2005 15 0 11-12-2005	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.4 years -2.5 years -2.5 years -2.6 years -2.7 years -2.8 years -2.9 ye	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.06% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU1591 Asset Number IGILU0294 IGILU0296 IGILU0297 IGILU0297	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$)	1 2 3 3 3 3 1 1 Effective Life (Y) Effective Life (Y) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -3.3 years -3.3 years -3.3 years -3.3 years -3.3 years -3.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.06% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0269 IGILU0270 IGILU0270 IGILU0293 IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0297	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1998.00 \$ 3873.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$)	1 2 1 2 3 3 3 3 2 3 3 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -12.3 years -12.3 years -12.3 years -12.4 years -12.3 years -12.3 years -12.3 years -12.3 years -13.3 years -13.3 years -13.3 years -10.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.6% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90%	Good Good Good Good Good Good Good Good	Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0270 IGILU0270 IGILU0270 IGILU0291 IGILU0293 IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0297	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet	\$ 2086.00 \$ 2874.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) 1 1 1 1 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -2.3 years -4.2 years -4.2 years -4.3 years -8.3 years -8.3 years -8.3 years -8.3 years -10.3 years -10.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 1.50% 6.00% 2.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90%	Good Good Good Good Good Good Good Good	Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU0270 IGILU0291 IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0296 IGILU0285 IGILU0285 IGILU0286	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Blind Carpet Interior Painting	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2196.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ \$ 3873.00 \$ \$ 3873.00 \$ \$ 486.00 \$ \$ 101.00 \$ \$ 1304.00	Effective Life (Y) Effective Life (Y) 1 1 1 1 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -2.3 years -4.2 years -4.2 years -4.3 years -8.3 years -8.3 years -8.3 years -8.3 years -10.3 years -10.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90%	Good Good Good Good Good Good Good Good	Retain Plan Retain	N/A
Bathroom Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0269 IGILU0270 IGILU0270 IGILU0293 IGILU0294 IGILU0296 IGILU0297 IGILU0297 Asset Number IGILU0286 IGILU0286 IGILU0286 IGILU0286	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Interior Painting Wardrobe	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1509.00 \$ 2988.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 265.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 888.00 \$ 2053.00	Effective Life (Y) Effective Life (Y) 1 1 1 1 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -3.4 years -8.3 years -8.3 years -8.3 years -3.3 years -3.3 years -3.3 years -8.3 years -8.3 years -8.3 years -8.3 years -8.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.06% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90% 22.53% 19.82% 1.80%	Good Good Good Good Good Good Good Good	Retain Plan Retain	N/A
Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU0270 IGILU0291 IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0296 IGILU0285 IGILU0285 IGILU0286	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Blind Carpet Interior Painting	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2196.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ \$ 3873.00 \$ \$ 3873.00 \$ \$ 486.00 \$ \$ 101.00 \$ \$ 1304.00	1 2 3 3 3 3 3 3 3 1 1 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -3.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.06% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90% Accumulated Repair Cost as % of Acquisition 1.80% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU1591 Asset Number IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0286 IGILU0286 IGILU0286 IGILU0287	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Interior Painting Wardrobe Asset Name Blind	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1908.00 \$ 3973.00 \$ 4466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00	Effective Life (Y) Effective Life (Y) 1 Effective Life (Y) 1 Effective Life (Y) 1 1 1 1 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -4.2 years -4.2 years -4.2 years -4.3 years -8.3 years -8.3 years -8.3 years -10.3 years -8.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.006% 1.50% 6.006% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90% 22.53% 19.82% 1.80% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain Retain	N/A
Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU0270 IGILU0293 IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0285 IGILU0286 IGILU0287	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Interior Painting Wardrobe Asset Name Blind Carpet Blind Carpet	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 3488.00 \$ 333.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	1 2 3 3 3 3 3 3 4 2 3 3 4 1 1 1 1 1 1 1 1 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -2.3 years -12.4 years -12.9 years -13.9 years -13.9 years -10.9 years -10.9 years -10.3 years -10.3 years -10.3 years -10.3 years -10.3 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.06% 5.86% 1.201% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90% 22.53% 19.82% 1.80% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
Bed 1	IGILU0263 IGILU0264 IGILU0265 IGILU0266 IGILU0267 IGILU0268 IGILU0269 IGILU0270 IGILU1591 Asset Number IGILU0294 IGILU0296 IGILU0297 Asset Number IGILU0286 IGILU0286 IGILU0286 IGILU0287	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Interior Painting Wardrobe Asset Name Blind	\$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2189.00 \$ 1509.00 \$ 1908.00 \$ 3973.00 \$ 4466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00 \$ 133.00	### 1	0	-22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.4 years -2.4 years -2.5 years -2.6 years -2.7 years -2.8 years -2.9 years -8.9 years	4.06% 4.51% 7.21% 6.76% 1.50% 6.0.06% 5.86% 12.01% 0.00% Accumulated Repair Cost as % of Acquisition 36.08% 36.05% 32.44% 54.06% Accumulated Repair Cost as % of Acquisition 0.90% 22.53% 19.82% 1.80% Accumulated Repair Cost as % of Acquisition 36.04% 10.14% 11.42%	Good Good Good Good Good Good Good Good	Retain Retain	N/A

Kitchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0276	Cooktop	\$ 1354.00		_	05 -6.3 years		Excellent	Retain	N/A
	IGILU0277	Interior Painting	\$ 710.00	-		05 -8.3 years		Excellent	Retain	N/A
	IGILU0279	Vinyl	\$ 1010.00			05 -8.3 years		Excellent	Retain	N/A
	IGILU0280	Oven	\$ 1409.00			05 -6.3 years		Excellent	Retain	N/A
	IGILU0281	Rangehood	\$ 599.00	-		05 -6.3 years		Excellent	Retain	N/A
	IGILU0282	Sink & Fittings	\$ 1587.00	-		05 -3.3 years	120.14%		Retain	N/A
Living	IGILOUZUZ	Sink & rittings	\$ 1307.00	1	3 01-12-200	-3.3 years	120.1476	Good	retairi	IV/A
Living	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0300	Air Conditioner -	\$ 3296.00			05 -8.3 years	145.98%		Retain	N/A
	IGIE00300	Split System	\$ 3230.00		01 12 200	o.s years	143.30%	dood	retain	IVA
	IGILU0301	Blind	\$ 388.00	1	0 01-12-200	05 -8.3 years	16.24%	Good	Retain	N/A
	IGILU0303	Heater	\$ 865.00			05 -3.3 years		Excellent	Retain	N/A
	IGILU0304	Interior Painting	\$ 1176.00			05 -8.3 years	14.42%		Retain	N/A
Unit Exterior			7					1	1.444	
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0308	Clothesline	\$ 499.00			92 -22.3 years		Good	Retain	N/A
	IGILU0309	Courtyard	\$ 2486.00			02 -2.3 years		Good	Retain	N/A
	IGILU0310	Doors	\$ 5605.00			92 -2.3 years	31.48%		Retain	N/A
	IGILU0311	Downpipes	\$ 1742.00			22 -12.3 years	16.22%		Retain	N/A
	IGILU0312	Electrical	\$ 1964.00	-		2 -12.3 years	95.14%		Retain	N/A
	. 3.2003.2	Switchboard	¥ 1504.00		01 01-199	,	55.14%			
	IGILU0313	Exterior painting	\$ 2086.00	1	0 01-01-199	2 -22.3 years	2.25%	Good	Retain	N/A
	IGILU0314	Fascias	\$ 2874.00	2	01-01-199	2 -12.3 years	17.12%	Good	Retain	N/A
	IGILU0315	Flyscreens	\$ 2186.00	1	0 01-01-199	2 -22.3 years	72.10%	Good	Retain	N/A
	IGILU0316	Guttering	\$ 2819.00			02 -12.3 years	16.89%		Retain	N/A
	IGILU0317	Path	\$ 1509.00			02 -2.3 years	16.37%	Good	Retain	N/A
	IGILU0318	Porch	\$ 2908.00			92 -2.3 years	15.02%		Retain	N/A
	IGILU0319	Lattice Screening	\$ 1098.00			92 -12.3 years		Good	Retain	N/A
	IGILU0320	Windows	\$ 3873.00			92 -2.3 years		Excellent	Retain	N/A
	IGILU1592	Awnings	\$ 9435.00			0 -4.2 years		Good	Retain	N/A
		9	7 0 100100						1.1010	
Common										
Common	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Common	Asset Number	Asset Name	Acquisition Cost (\$) \$ 21978.00	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan Retain	Comments N/A
Common Unit 7	Asset Number	Asset Name Driveway	Acquisition Cost (\$) \$ 21978.00			Remaining Effective Life		Asset Condition	Plan Retain	Comments N/A
	IGILU0002d	Driveway	\$ 21978.00	2	01-07-198	32 -16.8 years	0.00%	Good	Retain	N/A
	IGILU0002d Asset Number	Driveway Asset Name	\$ 21978.00 Acquisition Cost (\$)	Effective Life (Y)	01-07-198 Installation Date	Remaining Effective Life	0.00% Accumulated Repair Cost as % of Acquisition	Good Asset Condition	Retain	N/A Comments
	Asset Number	Asset Name Insulation	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00	Effective Life (Y)	01-07-198 Installation Date 0 01-01-199	Remaining Effective Life 12 -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Good Asset Condition Good	Plan Retain	N/A Comments N/A
	Asset Number IGILU0322 IGILU0323	Asset Name Insulation Lighting	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199	Remaining Effective Life 12 -12.3 years 12 -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00%	Asset Condition Good Good	Plan Retain Retain	N/A Comments N/A N/A
	Asset Number IGILU0322 IGILU0323 IGILU0324	Asset Name Insulation Lighting Sarking	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 22 -12.3 years 12 -17.3 years 12 -7.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60%	Asset Condition Good Good Excellent	Plan Retain Retain Retain Retain	Comments N/A N/A N/A N/A
	Asset Number IGILU0322 IGILU0323	Asset Name Insulation Lighting Sarking Hot Water System -	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 12 -12.3 years 12 -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00%	Asset Condition Good Good Excellent	Plan Retain Retain	N/A Comments N/A N/A
	Asset Number IGILU0322 IGILU0323 IGILU0324	Asset Name Insulation Lighting Sarking	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 22 -12.3 years 12 -17.3 years 12 -7.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60%	Asset Condition Good Good Excellent	Plan Retain Retain Retain Retain	Comments N/A N/A N/A N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324	Asset Name Insulation Lighting Sarking Hot Water System -	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 22 -12.3 years 12 -17.3 years 12 -7.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60%	Asset Condition Good Good Excellent	Plan Retain Retain Retain Retain	Comments N/A N/A N/A N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325	Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	Effective Life (Y) 2 1 2 1 Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 2 01-01-199 Installation Date	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Excellent Good	Plan Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) 2 1 2 1. Effective Life (Y)	Installation Date 10 01-01-199 5 01-01-199 5 01-01-199 2 01-01-199 Installation Date 0 01-01-199	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years 12 -Remaining Effective Life	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Good Good Excellent Good Asset Condition	Plan Retain Retain Retain Retain Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A Comments
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) 2 1 2 1 2 1 2 1 2 1	Installation Date 10	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years 12 -12.3 years 12 -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Good Good Excellent Good Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A Comments N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 1909.00	Effective Life (Y) 2 1 2 1 Effective Life (Y) 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	Installation Date 0 0 1-07-198 5 01-01-199 5 01-01-199 2 01-01-199 Installation Date 0 0 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 12 -12.3 years 2-17.3 years 12 -7.3 years 12 -20.3 years Remaining Effective Life 12 -12.3 years 12 -17.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 0.00%	Asset Condition Good Good Excellent Good Asset Condition Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Plan Retain Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Insulation Lighting Sarking	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 19709.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y) 2 1 2 1 Effective Life (Y) 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	Installation Date 10 01-07-198 15 01-01-199 15 01-01-199 2 01-01-199 Installation Date 0 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 12 -12.3 years 22 -17.3 years 12 -7.3 years 12 -20.3 years Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -17.3 years 12 -7.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09%	Asset Condition Good Good Excellent Good Asset Condition Good Good Good Good	Plan Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System -	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 19709.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y) 2 1 2 1 Effective Life (Y) 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	Installation Date 10 01-07-198 15 01-01-199 15 01-01-199 2 01-01-199 Installation Date 0 01-01-199 5 01-01-199 5 01-01-199	Remaining Effective Life 12 -12.3 years 22 -17.3 years 12 -7.3 years 12 -20.3 years Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -17.3 years 12 -7.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09%	Asset Condition Good Good Excellent Good Asset Condition Good Good Good Good	Plan Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Lighting Sarking Hot Water System - Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	Effective Life (Y) 2 1 2 1. Effective Life (Y) 2 1.	Installation Date 10 01-01-199 15 01-01-199 15 01-01-199 2 01-01-199 Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 2 01-01-199	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years 12 -20.3 years 12 -12.3 years 12 -7.3 years 12 -20.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01%	Asset Condition Good Good Excellent Good Asset Condition Good Good Good Good Good Good	Plan Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0381 IGILU0382 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 0 01-01-199 5 01-01-199 5 01-01-199 2 01-01-199 Installation Date 0 01-01-199 5 01-01-199 2 01-01-199 5 01-01-199 1 01-01-199	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years 12 -20.3 years 12 -20.3 years 12 -17.3 years 12 -17.3 years 12 -17.3 years 12 -17.3 years 12 -7.3 years 12 -7.3 years 12 -7.3 years 12 -8.3 years 13 -8.3 years 14 -8.3 years 15 -17.3 years 16 -17.3 years 17 -17.3 years 18 -17.3 years 19 -17.3 years 19 -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Excellent Good Asset Condition Good Good Good Good Good Good Good Asset Condition	Plan Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0347	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Electric Asset Name Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2386.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A
Unit 7 Unit 8	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0381 IGILU0382 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1	Installation Date	Remaining Effective Life 12 -12.3 years 12 -17.3 years 12 -7.3 years 12 -20.3 years 12 -20.3 years 12 -20.3 years 12 -17.3 years 12 -17.3 years 12 -17.3 years 12 -17.3 years 12 -7.3 years 12 -7.3 years 12 -7.3 years 12 -8.3 years 13 -8.3 years 14 -8.3 years 15 -17.3 years 16 -17.3 years 17 -17.3 years 18 -17.3 years 19 -17.3 years 19 -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A
Unit 8 Bathroom	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0349	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Figure 1 Asset Name Electric Asset Name Electric Eschaust Fan Skylight	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1010.00	Effective Life (Y) 21 22 1. Effective Life (Y) 21 1. Effective Life (Y) 1. Effective Life (Y)	Installation Date Installation Date Installation Date	Remaining Effective Life 12 - 12.3 years 12 - 17.3 years 12 - 7.3 years 12 - 20.3 years 12 - 12.3 years 12 - 12.3 years 12 - 12.3 years 12 - 12.3 years 12 - 17.3 years 12 - 17.3 years 12 - 2.3 years 12 - 2.3 years 12 - 2.3 years 12 - 2.2 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08%	Asset Condition Good Good Excellent Good Good Good Good Good Good Good Goo	Plan Retain	N/A
Unit 8 Bathroom	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0347	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Electric Asset Name Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2386.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A
Unit 8 Bathroom	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0381 IGILU0381 IGILU0382 Asset Number IGILU0347 IGILU0347 IGILU0349 Asset Number IGILU0337	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Figure 1 Asset Name Electric Asset Name Electric Eschaust Fan Skylight	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1010.00	Effective Life (Y)	Installation Date	Remaining Effective Life 12 - 12.3 years 12 - 17.3 years 12 - 7.3 years 12 - 20.3 years 12 - 12.3 years 12 - 12.3 years 12 - 12.3 years 12 - 12.3 years 12 - 17.3 years 12 - 17.3 years 12 - 2.3 years 12 - 2.3 years 12 - 2.3 years 12 - 2.2 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Excellent Good Good Good Good Good Good Good Goo	Plan Retain	N/A
Unit 7	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0380 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0347 IGILU0347 IGILU0347	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Exhaust Fan Skylight Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1 Effective Life (Y) 1 1 Effective Life (Y)	Installation Date	Remaining Effective Life 12 12.3 years 12 17.3 years 12 -7.3 years 12 -7.3 years 12 -20.3 years 12 -12.3 years 12 -2.3 years 12 -2.3 years 12 -2.3 years 12 -2.2 years 2 -2.2 years 13 -2.2 years 14 -2.2 years 15 -2.2 years 16.8 years 17 -2.2 years 18 -2.2 years 19 -2.2 years 19 -2.2 years 10 -2.2 years 10 -2.2 years 11 -2.2 years 12 -2.2 years 13 -2.2 years 14 -2.2 years 15 -2.2 years 16 -2.2 years 17 -2.2 years 18 -2.2 years 19 -2.2 years 19 -2.2 years 19 -2.2 years 10 -2.2 years	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 772.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Excellent Good Good Good Good Good Good Good Goo	Retain Plan Retain	N/A
Unit 7 Unit 8	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0381 IGILU0381 IGILU0382 Asset Number IGILU0347 IGILU0347 IGILU0349 Asset Number IGILU0337	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Electric Asset Name Exhaust Fan Skylight Asset Name Blind	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1010.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1 Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 772.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain	N/A
Unit 7 Unit 8	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0347 IGILU0349 Asset Number IGILU0347 IGILU0349	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Electric Asset Name Exhaust Fan Skylight Asset Name Blind Curtains	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 333.00 \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1 Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition 19.84% 3.75%	Asset Condition Good Good Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain	N/A
Unit 7 Unit 8 Bathroom	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0347 IGILU0349 Asset Number IGILU0347 IGILU0349	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Electric Asset Name Exhaust Fan Skylight Asset Name Blind Curtains	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 333.00 \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 1 Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition 19.84% 3.75%	Asset Condition Good Good Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Plan Retain	N/A
Unit 7 Unit 8 Bathroom	Asset Number IGILU0322 IGILU0323 IGILU0324 IGILU0325 Asset Number IGILU0379 IGILU0380 IGILU0381 IGILU0382 Asset Number IGILU0349 Asset Number IGILU0349 IGILU0337 IGILU0349	Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Insulation Lighting Sarking Hot Water System- Electric Asset Name Electric Asset Name Exhaust Fan Skylight Asset Name Blind Curtains Wardrobe	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 1010.00 Acquisition Cost (\$) \$ 333.00 \$ 1776.00 \$ 2053.00	Effective Life (Y) Effective Life (Y) 2 1 2 1 Effective Life (Y) Effective Life (Y) 1 Effective Life (Y) 1 Effective Life (Y)	Installation Date	Remaining Effective Life 12 12.3 years 12 17.3 years 12 -7.3 years 12 -7.3 years 12 -20.3 years 12 -12.3 years 12 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -2.3 years 2 -2.3 years 2 -2.2 years 3 -2.2 years 4 -2.2 years 5 -2.2 years 6 -2.2 years 7 -2.2 years 8 -2.2 years 9 -2.2 years 9 -2.2 years 10 -2.2 years 11 -2.2 years 12 -2.2 years 12 -2.2 years 13 -2.2 years 14 -2.2 years 15 -2.2 years 17 -2.2 years 18 -2.2 years 19 -2.2 years 19 -2.2 years 10 -2	Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 0.00% 3.60% 13.52% Accumulated Repair Cost as % of Acquisition 0.00% 0.00% 72.09% 12.01% Accumulated Repair Cost as % of Acquisition 19.84% 72.08% Accumulated Repair Cost as % of Acquisition 11.80% 3.75% 3.75% 34.24% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Excellent Good Good Good Good Good Good Good Goo	Plan Retain	N/A

Installation Date Remaining Effective Life

01-12-2005 -8.3 years

01-12-2005 -8.3 years

10

10

Accumulated Repair Cost as % of Acquisition

Asset Condition

22.55% Good

0.00% Good

Plan

Retain

Retain

Comments

N/A

N/A

Asset Number Asset Name

Blind

Interior Painting

IGILU0305

IGILU0307

Unit 7-8

Unit 7

Acquisition Cost (\$) Effective Life (Y)

\$ 388.00

\$ 832.00

	IGILU0344	Curtains	\$ 1776.00		6 01-02-2012	· ·		% Good	Retain	N/A
	IGILU0346	Wardrobe	\$ 2053.00)	10 01-02-2012	2 -2.2 years	9.01	% Good	Retain	N/A
Dining										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0363	Blind	\$ 388.00)	10 01-02-2012	2 -2.2 years	34.28	% Good	Retain	N/A
Kitchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0326	Blind	\$ 333.00)	10 01-02-2012	2 -2.2 years	15.32	% Good	Retain	N/A
Living										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0357	Blind	\$ 388.00		10 01-02-2012	· ·		% Good	Retain	N/A
	IGILU0359	Ceiling Fan	\$ 588.00			2 -2.2 years	36.05	% Good	Retain	N/A
	IGILU0360	Curtains	\$ 1776.00)	6 01-02-2012	2 -6.2 years	13.51	% Good	Retain	N/A
Unit Exterior										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0366	Clothesline	\$ 499.00			2 -22.3 years		% Good	Retain	N/A
	IGILU0367	Courtyard	\$ 2486.00		30 01-01-1992	· ·		% Excellent	Retain	N/A
	IGILU0368	Doors	\$ 5605.00		30 01-01-1992	- ·		% Good	Retain	N/A
	IGILU0369	Downpipes	\$ 1742.00			2 -12.3 years		% Good	Retain	N/A
	IGILU0370	Electrical	\$ 1964.00		20 01-01-1992	2 -12.3 years	0.00	% Good	Retain	N/A
	IGILU0371	Switchboard Exterior painting	\$ 2086.00	1	10 01-01-1992	2 -22.3 years	17.10	% Good	Retain	N/A
	IGILU0371	Fascias Fascias	\$ 2086.00			2 -22.3 years 2 -12.3 years		% Good % Good	Retain	N/A
	IGILU0373	Flyscreens	\$ 2186.00			2 -22.3 years		% Good	Retain	N/A
	IGILU0374	Guttering	\$ 2819.00			2 -12.3 years		% Good	Retain	N/A
	IGILU0375	Path	\$ 1509.00		30 01-01-1992			% Good	Retain	N/A
	IGILU0376	Porch	\$ 2908.00		30 01-01-1992	· ·		% Good	Retain	N/A
	IGILU0377	Lattice Screening	\$ 1098.00			2 -12.3 years		% Good	Retain	N/A
	IGILU0378	Windows	\$ 3873.00		30 01-01-1992	· ·		% Good	Retain	N/A
	IGILU1593	Awnings	\$ 9435.00		10 15-01-2010	· ·		% Good	Retain	N/A
	IGIEO 1555	Awilligs	\$ 5455.00	'	10 13-01-2010	7 -4.2 years	0.00	76 G000	Retaili	IN/A
Kitchen										
Riterien	A A M I									
			Acquisition Cost (\$)	Fttoctive Lite (V)	Installation Date	Romaining Effective Life	Accumulated Renair Cost as % of Acquisition	Asset Condition	Plan	Comments
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan Retain	Comments N/A
Unit Exterior	IGILU0390	Sink & Fittings	Acquisition Cost (\$) \$ 1587.00			Remaining Effective Life 1 11.8 years		Asset Condition % Good	Plan Retain	N/A
Unit Exterior	IGILU0390	Sink & Fittings	\$ 1587.00		15 01-02-2021	1 11.8 years	114.14	% Good	Retain	N/A
Unit Exterior	IGILU0390 Asset Number	Sink & Fittings Asset Name	\$ 1587.00 Acquisition Cost (\$)	Effective Life (Y)	15 01-02-2021 Installation Date	Remaining Effective Life	114.14 Accumulated Repair Cost as % of Acquisition	% Good Asset Condition	Retain	N/A Comments
Unit Exterior	IGILU0390	Sink & Fittings Asset Name Clothesline	\$ 1587.00 Acquisition Cost (\$) \$ 499.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992	Remaining Effective Life 2 -22.3 years	Accumulated Repair Cost as % of Acquisition 2.71	% Good	Retain	N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419	Sink & Fittings Asset Name Clothesline Courtyard	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1993	Remaining Effective Life 2 -22.3 years 2 -2.3 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00	M Good Asset Condition Excellent Excellent	Plan Retain Retain	N/A Comments N/A N/A
Unit Exterior	Asset Number	Sink & Fittings Asset Name Clothesline	\$ 1587.00 Acquisition Cost (\$) \$ 499.00	Effective Life (Y)	15 01-02-2021	Remaining Effective Life 2 -22.3 years 2 -2.3 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41	% Good Asset Condition Excellent	Retain Plan Retain	N/A Comments N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420	Asset Name Clothesline Courtyard Doors	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -2.3 years 2 -2.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41	Asset Condition Excellent Excellent Excellent	Plan Retain Retain Retain	N/A Comments N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421	Asset Name Clothesline Courtyard Doors Downpipes	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -2.3 years 2 -2.3 years 2 -12.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41	Asset Condition Excellent Excellent Excellent Excellent Excellent	Plan Retain Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421	Asset Name Clothesline Courtyard Doors Downpipes Electrical	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 10 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -2.3 years 2 -2.3 years 2 -12.3 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99	Asset Condition Excellent Excellent Excellent Excellent Excellent	Plan Retain Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 10 01-01-1992	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99	% Good Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Retain Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0422 IGILU0423 IGILU0424 IGILU0425	Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -23 years 2 -23 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44	M Good Asset Condition Excellent	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0418 IGILU0418 IGILU0420 IGILU0421 IGILU0422 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0426	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2286.00 \$ 22874.00 \$ 2186.00 \$ 22874.00 \$ 2186.00 \$ 22819.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44	Mood Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0424 IGILU0424 IGILU0425 IGILU0425 IGILU0425 IGILU0427	Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2286.00 \$ 22874.00 \$ 23819.00 \$ 3 2819.00 \$ 1509.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1993 30 01-01-1992	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.95 18.02 0.90 32.44 84.47	Asset Condition Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0425 IGILU0426 IGILU0427	Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2289.00 \$ 2299.00 \$ 2998.00	Effective Life (Y)	15 01-02-2021 Installation Date 10 01-01-1992 30 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1993 30 01-01-1992 30 01-01-1992	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 3.244 84.47 10.93 1.50	Asset Condition Asset Condition Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0390 Asset Number IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 289.00 \$ 1519.00 \$ 15199.00 \$ 1998.00 \$ 1998.00	Effective Life (Y)	15 01-02-2021 Installation Date 0 01-01-1992 30 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 17.13	Asset Condition Asset Condition Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0418 IGILU0418 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2819.00 \$ 1998.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	15	Remaining Effective Life 2 -22.3 years 2 -2.3 years -2.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years 2 -12.3 years 2 -2.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.44 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 1.7.12	M Good Asset Condition Excellent Good Excellent Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0390 Asset Number IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 289.00 \$ 1519.00 \$ 15199.00 \$ 1998.00 \$ 1998.00	Effective Life (Y)	15 01-02-2021 Installation Date 0 01-01-1992 30 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -2.3 years -2.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years 2 -12.3 years 2 -2.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.44 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 1.7.12	Asset Condition Asset Condition Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU0418 IGILU0418 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2819.00 \$ 1998.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	15	Remaining Effective Life 2 -22.3 years 2 -2.3 years -2.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years 2 -12.3 years 2 -2.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.44 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 1.7.12	M Good Asset Condition Excellent Good Excellent Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number IGILU0418 IGILU0418 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2819.00 \$ 1998.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	15	Remaining Effective Life 2 -22.3 years 2 -2.3 years -2.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -12.3 years 2 -22.3 years 2 -22.3 years 2 -22.3 years 2 -12.3 years 2 -2.3 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.44 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 1.7.12	M Good Asset Condition Excellent Good Excellent Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	IGILU0390 Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430	Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2899.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	15	11.8 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.95 18.02 0.90 32.44 84.47 10.93 1.50 17.13 0.00 0.00	## Asset Condition ## Asset Condition ## Excellent ## Good ## Good ## Excellent ## Good ## Good ## Excellent ## Excellent	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430 IGILU1594	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2819.00 \$ 1998.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	15	Remaining Effective Life 2 -22.3 years 2 -2.3 years 2 -2.3 years 2 -12.3 years 2 -2.3 years 2 -2.4 years 3 -4.2 years 4 -4.2 years	114.14 Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.44 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 1.7.12	M Good Asset Condition Excellent Good Excellent Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0422 IGILU0424 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0429 IGILU0430 IGILU0430 IGILU0430	Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 28819.00 \$ 38873.00 \$ 38873.00 \$ 38873.00 \$ 38873.00 Acquisition Cost (\$)	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.99 32.44 84.47 10.93 1.50 17.13 0.00 Accumulated Repair Cost as % of Acquisition	## Asset Condition ## Asset Condition ## Excellent ## Good ## Good ## Good ## Good ## Excellent ## Excellent ## Asset Condition ## Asset Condition	Plan Retain	N/A N/A
	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0430 IGILU0432 IGILU0432	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 28874.00 \$ 28873.00 \$ 3873.00 \$ 3495.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00 \$ 1999.00	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 84.47 10.93 1.50 17.12 0.00 0.00 Accumulated Repair Cost as % of Acquisition 0.00 22.83	Asset Condition Asset Condition Excellent	Plan Retain	N/A N/A N/
	IGILU0390 Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0427 IGILU0426 IGILU0427 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0431 IGILU0432 IGILU0433	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 1599.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1974.00	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 84.47 10.99 1.50 17.12 0.00 Accumulated Repair Cost as % of Acquisition 0.00 2.28 3.064	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Good ## Excellent ## Asset Condition ## Good ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Good ## Good ## Asset Condition ## Good	Plan Retain	N/A N/A N/
	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0425 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0430 IGILU0432 IGILU0432	Asset Name Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulating Lighting Sarking Hot Water System	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 28874.00 \$ 28873.00 \$ 3873.00 \$ 3495.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00 \$ 1999.00	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 84.47 10.99 1.50 17.12 0.00 Accumulated Repair Cost as % of Acquisition 0.00 2.28 3.064	Asset Condition Asset Condition Excellent	Retain Plan Retain	N/A N/A N/
Unit 11	IGILU0390 Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0427 IGILU0426 IGILU0427 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0431 IGILU0432 IGILU0433	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 1599.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1974.00	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 84.47 10.99 1.50 17.12 0.00 Accumulated Repair Cost as % of Acquisition 0.00 2.28 3.064	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Good ## Excellent ## Asset Condition ## Good ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Good ## Good ## Asset Condition ## Good	Plan Retain	N/A N/A N/
	Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0423 IGILU0423 IGILU0425 IGILU0425 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0430 IGILU0431 IGILU0433 IGILU0433 IGILU0434	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 28874.00 \$ 28873.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 \$ 2386.00	Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.99 32.44 84.47 10.93 1.50 17.12 0.00 Accumulated Repair Cost as % of Acquisition 0.00 22.83 30.64 28.53	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Excellent ## Excellent ## Good ## Excellent ## Good ## Excellent ## Good ## Good ## Excellent ## Good ## Good ## Excellent ## Good ## Good ## Good ## Good ## Excellent ## Asset Condition ## Good	Retain Plan Retain	N/A N/A
Unit 11	Asset Number IGILU0390 Asset Number IGILU0418 IGILU0419 IGILU0420 IGILU0421 IGILU0422 IGILU0423 IGILU0424 IGILU0425 IGILU0426 IGILU0426 IGILU0427 IGILU0428 IGILU0429 IGILU0430 IGILU0430 IGILU0430 IGILU0434 IGILU0433	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 1509.00 \$ 3873.00 \$ 3473.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.90 32.44 44.47 10.99 1.50 17.12 0.00 Accumulated Repair Cost as % of Acquisition 0.00 2.28 30.64 28.53 Accumulated Repair Cost as % of Acquisition	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Good ## Excellent ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Good ## Asset Condition ## Good	Retain Plan Retain	N/A N/A N/
Unit 11	IGILU0390	Asset Name Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2874.00 \$ 2874.00 \$ 2986.00 \$ 499.00 \$ 2875.00 \$ 2875.00 \$ 2875.00 \$ 2875.00 \$ 2986.00 \$ 1098.00 \$ 3873.00 \$ 3873.00 \$ 3475.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.95 18.02 0.90 32.44 84.47 10.93 1.50 1.7.13 0.00 Accumulated Repair Cost as % of Acquisition 0.00 Accumulated Repair Cost as % of Acquisition 0.00 Accumulated Repair Cost as % of Acquisition 0.00 Accumulated Repair Cost as % of Acquisition	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Cood ## Excellent ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Asset Condition ## Good ##	Retain Plan Retain	N/A N/A
Unit 11	IGILU0390	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 38873.00 \$ 38873.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.99 32.44 84.47 10.93 1.55 17.13 0.00 0.00 Accumulated Repair Cost as % of Acquisition 2.28: 30.64 28.53 Accumulated Repair Cost as % of Acquisition 0.00 18.02	Masset Condition Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Cood Cood Excellent Asset Condition Asset Condition Cood Cood Asset Condition	Retain Plan Retain Retain	N/A N/A
Unit 11	IGILU0390	Asset Name Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 1587.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2874.00 \$ 2874.00 \$ 2874.00 \$ 2986.00 \$ 499.00 \$ 2875.00 \$ 2875.00 \$ 2875.00 \$ 2875.00 \$ 2986.00 \$ 1098.00 \$ 3873.00 \$ 3873.00 \$ 3475.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	15	11.8 years	Accumulated Repair Cost as % of Acquisition 2.71 0.00 5.41 16.22 87.99 18.02 0.99 32.44 84.47 10.93 1.55 17.13 0.00 0.00 Accumulated Repair Cost as % of Acquisition 2.28: 30.64 28.53 Accumulated Repair Cost as % of Acquisition 0.00 18.02	## Asset Condition ## Asset Condition ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Excellent ## Good ## Good ## Good ## Cood ## Excellent ## Asset Condition ## Good ## Good ## Asset Condition ## Good ## Good ## Asset Condition ## Good ##	Retain Plan Retain	N/A N/A

Unit 11

Unit 11-12

	ν		

Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y)

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0464	Air Conditioner -	\$ 3296.00		10 01-11-2021	7.6 years	137.879	6 Good	Retain	N/A
		Split System								
Unit Exterior										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0474	Clothesline	\$ 499.00		10 01-01-1992	-22.3 years	6.319	6 Fair	Repair	Wires are drooping,
										indicating the need for
										adjustment
	IGILU0475	Courtyard	\$ 2486.00		30 01-01-1992	-2.3 years	0.009	6 Good	Retain	N/A
	IGILU0476	Doors	\$ 5605.00		30 01-01-1992	-2.3 years	0.609	6 Good	Retain	N/A
	IGILU0477	Downpipes	\$ 1742.00		20 01-01-1992	-12.3 years	15.329	6 Good	Retain	N/A
	IGILU0478	Electrical	\$ 1964.00		20 01-01-1992	-12.3 years	66.199	6 Good	Retain	N/A
		Switchboard				-				
	IGILU0479	Exterior painting	\$ 2086.00		10 01-01-1992	-22.3 years	8.119	6 Good	Retain	N/A
	IGILU0480	Fascias	\$ 2874.00		20 01-01-1992	-12.3 years	18.029	6 Good	Retain	N/A
	IGILU0481	Flyscreens	\$ 2186.00		10 01-01-1992	-22.3 years	68.499	6 Good	Retain	N/A
	IGILU0482	Guttering	\$ 2819.00		20 01-01-1992	-	84.479	6 Good	Retain	N/A
	IGILU0483	Path	\$ 1509.00		30 01-01-1992		16.619		Repair	Cracking observed on
	101200103	1 4411	\$ 1303.00		0.0.1332	Lis years	10.51	o i an	перип	the path spanning
										approximately 1 linear
										1
										meter, suggesting the
	IGILU0484	Porch	\$ 2908.00		30 01-01-1992	-2.3 years	57.069	6 Fair	Repair	Cracking on front porch
										brought to attention by
										resident ; also concrete
										cracking on back porch
										crucking on buck porch
	IGILU0486	Windows	\$ 3873.00		30 01-01-1992	-2.3 years	12.019	6 Good	Retain	N/A
	IGILU1568	Awnings	\$ 9435.00		10 15-01-2010	-4.2 years	0.009	6 Good	Retain	N/A
Bathroom										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0514	Exhaust Fan	\$ 255.00		10 01-07-2003	-10.8 years	0.009	6 Good	Retain	N/A
	IGILU0515	Interior Painting	\$ 466.00		10 01-07-2003	· ·		6 Good	Retain	N/A
	IGILU0516	Toilet & Cistern	\$ 1343.00		20 01-07-2003			6 Good	Retain	N/A
	IGILU0517	Skylight	\$ 1010.00		10 01-07-2003			6 Good	Retain	N/A
	IGILU0518		\$ 1304.00		15 01-07-2003	· ·		6 Excellent	Retain	N/A
	IGILU0518	Tapware	\$ 3285.00					6 Good	Retain	N/A
		Tiles - Wall				-				
	IGILU0520	Tiles - Floor	\$ 4884.00		20 01-07-2003	-0.8 years	19.669	6 Good	Retain	N/A
Bed 1										
	Asset Number	Asset Name		Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0501	Blind	\$ 333.00		10 01-07-2003	-10.8 years		6 Good	Retain	N/A
	IGILU0502	Carpet	\$ 1032.00		8 01-07-2003	-12.8 years	30.319	6 Good	Retain	N/A
	IGILU0503	Curtains	\$ 1776.00		6 01-07-2003	-14.8 years	30.039	6 Good	Retain	N/A
	IGILU0504	Interior Painting	\$ 888.00		10 01-07-2003	-10.8 years	34.239	6 Good	Retain	N/A
	IGILU0505	Wardrobe	\$ 2053.00		10 01-07-2003	-10.8 years	27.039	6 Good	Retain	N/A
Bed 2										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0506	Blind	\$ 333.00		10 01-07-2003			6 Good	Retain	N/A
	IGILU0507	Carpet	\$ 688.00		8 01-07-2003	· ·		6 Good	Retain	N/A
	IGILU0508	Curtains	\$ 1776.00		6 01-07-2003			6 Good	Retain	N/A
	IGILU0509	Interior Painting	\$ 588.00		10 01-07-2003			6 Good	Retain	N/A
	IGILU0510	Wardrobe	\$ 2053.00					6 Good	Retain	N/A
Dining	IGIEO0310	wardrobe	\$ 2055.00		10 01-07-2003	- 10.6 years	19.02	6 G000	Retain	IN/A
Dining				=## .1 11# an						
	Asset Number	Asset Name		Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0527	Blind	\$ 388.00		10 01-07-2003			6 Good	Retain	N/A
	IGILU0529	Curtains	\$ 1776.00		6 01-07-2003	-14.8 years	13.519	6 Good	Retain	N/A
	IGILU0530	Interior Painting	\$ 832.00		10 01-07-2003	-10.8 years	36.069	6 Good	Retain	N/A
Hallway										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0532	Interior Painting	\$ 333.00		10 01-07-2003	-10.8 years	0.009	6 Good	Retain	N/A
Kitchen							·			
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0491	Benchtops	\$ 2342.00		20 01-07-2003		·	6 Good	Retain	N/A
	IGILU0493	Curtains	\$ 444.00		6 01-07-2003			6 Good	Retain	N/A
	IGILU0494	Interior Painting	\$ 710.00		10 01-07-2003			6 Good	Retain	N/A
						· ·				
	IGILU0495	Kitchen Cabinets	\$ 3818.00		20 01-07-2003	-u.o years	11.269	6 Good	Retain	N/A

Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

	Acces November										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Instal	llation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0511	Interior Painting	\$ 166.00		10	01-07-2003	-10.8 years	91.72%	6 Good	Retain	N/A
	IGILU0512	Tiles - Wall	\$ 1076.00		20	01-07-2003	-0.8 years	18.03%	Good	Retain	N/A
	IGILU0513	Tiles - Floor	\$ 1076.00		20	01-07-2003	-0.8 years	29.09%	Good	Retain	N/A
.iving											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Instal	llation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0521	Air Conditioner -	\$ 3296.00		10	01-07-2003	-10.8 years	129.76%	Good	Retain	N/A
		Split System									
	IGILU0522	Blind	\$ 388.00		10	01-07-2003	-10.8 years	7.22%	Good	Retain	N/A
	IGILU0525	Heater	\$ 865.00		15	01-07-2003	-5.8 years	0.00%	Good	Retain	N/A
	IGILU0526	Interior Painting	\$ 1176.00		10	01-07-2003	-10.8 years	36.05%	Good	Retain	N/A
Jnit Exterior											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Instal	llation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0533	Clothesline	\$ 499.00		10	01-01-1992	-22.3 years	16.23%	6 Good	Retain	N/A
	IGILU0534	Courtyard	\$ 2486.00		30	01-01-1992	-2.3 years	0.00%	6 Good	Retain	N/A
	IGILU0535	Doors	\$ 5605.00		30	01-01-1992			Good	Retain	N/A
	IGILU0536	Downpipes	\$ 1742.00		20	01-01-1992		36.05%		Retain	N/A
	IGILU0537	Electrical	\$ 1964.00		20	01-01-1992			6 Good	Retain	N/A
	IGIEGOSSI	Switchboard	\$ 1304.00		20	01 01 1552	12.5 years	32.40%	Good	recuiii	14/7
	IGILU0538	Exterior painting	\$ 2086.00		10	01-01-1992	-22 3 years	9.01%	6 Good	Retain	N/A
	IGILU0539	Fascias	\$ 2874.00		20	01-01-1992			6 Good	Retain	N/A
	IGILU0540	Flyscreens	\$ 2186.00		10	01-01-1992	,	28.84%		Retain	N/A
	IGILU0541	Guttering	\$ 2819.00		20	01-01-1992		135.15%		Retain	N/A
	IGILU0542	Path	\$ 1509.00		30				6 Good		N/A
						01-01-1992				Retain	_
	IGILU0543	Porch	\$ 2908.00		30	01-01-1992			Good	Retain	N/A
	IGILU0545	Windows	\$ 3873.00		30	01-01-1992	,		Good	Retain	N/A
	IGILU1569	Awnings	\$ 9435.00		10	15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Common											
											_
	Asset Number	Asset Name		Effective Life (Y)		llation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	Asset Number	Asset Name Driveway	Acquisition Cost (\$) \$ 21978.00		Instal 25	Ilation Date 01-07-1982			Asset Condition Good	Plan Retain	N/A
	IGILU0002f	Driveway	\$ 21978.00		25	01-07-1982	-16.8 years	0.00%	Good	Retain	N/A
	IGILU0002f Asset Number	Driveway Asset Name	\$ 21978.00 Acquisition Cost (\$)		25 Instal	01-07-1982 Ilation Date	-16.8 years Remaining Effective Life	0.00% Accumulated Repair Cost as % of Acquisition	Asset Condition	Retain	N/A Comments
	Asset Number	Asset Name Insulation	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00		25 Instal 20	01-07-1982 Illation Date 01-01-1992	-16.8 years Remaining Effective Life -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Good	Plan Retain	N/A Comments N/A
	IGILU0002f Asset Number	Driveway Asset Name	\$ 21978.00 Acquisition Cost (\$)		25 Instal	01-07-1982 Ilation Date	-16.8 years Remaining Effective Life -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition	Asset Condition Good	Retain	N/A Comments
	Asset Number	Asset Name Insulation	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00		25 Instal 20	01-07-1982 Illation Date 01-01-1992	-16.8 years Remaining Effective Life -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Good	Plan Retain	N/A Comments N/A
	Asset Number IGILU0547 IGILU0548	Asset Name Insulation Lighting	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	25 Instal 20 15	01-07-1982 Ilation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Asset Condition Good Fair	Plan Retain Retain Repair	N/A Comments N/A Light globe in the living room is undone, requiring tightening
	Asset Number IGILU0547 IGILU0548	Asset Name Insulation Lighting Sarking	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	25 Instal 20 15 25	01-07-1982 Illation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Asset Condition Good Fair Good	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A
	Asset Number IGILU0547 IGILU0548	Asset Name Insulation Lighting Sarking Hot Water System -	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	25 Instal 20 15	01-07-1982 Ilation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Asset Condition Good Fair	Plan Retain Retain Repair	N/A Comments N/A Light globe in the living room is undone, requiring tightening
	Asset Number IGILU0547 IGILU0548	Asset Name Insulation Lighting Sarking	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	25 Instal 20 15 25	01-07-1982 Illation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Asset Condition Good Fair Good	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A
Jnit 13	Asset Number IGILU0547 IGILU0548	Asset Name Insulation Lighting Sarking Hot Water System -	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	25 Instal 20 15 25	01-07-1982 Illation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Asset Condition Good Fair Good	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A
Unit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550	Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	Effective Life (Y)	25 Instal 20 15 25 12	01-07-1982 Illation Date	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53%	Asset Condition Good Fair Good Good Good Good	Plan Retain Repair Retain Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y)	20 15 25 12 Instal	01-07-1982 Illation Date	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Asset Condition	Plan Retain Repair Retain Retain Retain Plan	N/A Comments N/A Light globe in the living room is undone, requiring trabtening N/A N/A Comments
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00	Effective Life (Y)	25 Instal 20 15 25 12 Instal 10	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Repair Retain Retain Retain Retain Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0550 Asset Number IGILU0570	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00	Effective Life (Y) Effective Life (Y)	25 Instal 20 25 25 12 Instal 10 10 10	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Repair Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0550 Asset Number IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00	Effective Life (Y) Effective Life (Y)	25 Instal 20 25 25 12 Instal 10 10 20	01-07-1982 Illation Date	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -22.3 years -12.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52%	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A N/A N/A N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life -12.3 years -17.3 years -20.3 years -20.3 years -22.3 years -12.3 years -12.3 years -22.3 years -22.3 years -12.3 years -22.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43%	Asset Condition Good Good Good Good Asset Condition Good Good Good Good Good Good	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575 IGILU0576	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1304.00 \$ 1304.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life -17.3 years -17.3 years -20.3 years -20.3 years -22.3 years -22.3 years -22.3 years -22.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Unit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -22.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14%	Asset Condition Good Good Good Good Asset Condition Good Good Good Good Good Good	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A
Unit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575 IGILU0576	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1304.00 \$ 1304.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -22.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0575 IGILU0575 IGILU0575 IGILU0576 IGILU0577	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -22.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11%	Asset Condition Good Good Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0575 IGILU0575 IGILU0575 IGILU0576 IGILU0577	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -22.3 years -12.3 years -12.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11%	Asset Condition Good Good Good Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0576 IGILU0577 IGILU0577 IGILU0577	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life -17.3 years -17.3 years -17.3 years -20.3 years -20.3 years -22.3 years -22.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Jnit 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0574 IGILU0574 IGILU0576 IGILU0577 IGILU0577 IGILU0577 IGILU0577 IGILU0577	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Instal 20	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years -20.3 years -22.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Jnit 13	Asset Number IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0574 IGILU0576 IGILU0577 IGILU0577 IGILU0578 Asset Number IGILU0578	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1304.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.4 years -12.4 years -12.5 years -12.4 years -12.5 years -12.6 years -12.7 years -12.8 years -12.9 years -12.9 years -12.9 years -12.9 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 22.52% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 8.11% 9.62%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Jnit 13	Asset Number IGILU0548 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0575 IGILU0576 IGILU0577 IGILU0578 Asset Number IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.4 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 6.63% 16.22%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0575 IGILU0576 IGILU0577 IGILU0577 IGILU0578 Asset Number IGILU0561 IGILU0562 IGILU0563	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet Interior Painting	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 288.00 \$ 388.00	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.4 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 6.63% 16.22%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/
Init 13	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575 IGILU0576 IGILU0577 IGILU0577 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU05661 IGILU05663 IGILU05663	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet Interior Painting Wardrobe	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 13143.00 \$ 1010.00 \$ 13285.00 \$ 4884.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 888.00 \$ 2053.00	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 Illation Date 01-01-1992 01-01-1992 01-01-1992 Illation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life -17.3 years -17.3 years -17.3 years -20.3 years -20.3 years -20.3 years -20.3 years -20.3 years -20.3 years -10.3 years	Accumulated Repair Cost as % of Acquisition 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 16.22%	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Retain Repair Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Juit 13 Bathroom	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0574 IGILU0576 IGILU0576 IGILU0577 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0561 IGILU0561 IGILU0564 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet Interior Painting Wardrobe Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1304.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	Remaining Effective Life 1-12.3 years -7.3 years -7.3 years -20.3 years -20.3 years -22.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 6.63% 16.22% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, equiting tightening N/A N/A N/A N/A N/A N/A N/A N/A
Juit 13 Bathroom	Asset Number IGILU0548 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0575 IGILU0575 IGILU0576 IGILU0577 IGILU0578 Asset Number IGILU0561 IGILU0562 IGILU0563 IGILU0564 Asset Number IGILU0565	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet Interior Painting Wardrobe Asset Name Blind	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1343.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years -20.3 years -22.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 16.22% Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 6.22% Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 6.22% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, requiring tightening N/A N/A N/A N/A N/A N/A N/A N/A
Juit 13 Bathroom Bed 1	Asset Number IGILU0547 IGILU0548 IGILU0549 IGILU0550 Asset Number IGILU0572 IGILU0573 IGILU0574 IGILU0574 IGILU0576 IGILU0576 IGILU0577 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0576 IGILU0561 IGILU0561 IGILU0564 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Carpet Interior Painting Wardrobe Asset Name	\$ 21978.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 466.00 \$ 1304.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Instal	01-07-1982 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-16.8 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 9.01% 22.53% Accumulated Repair Cost as % of Acquisition 34.27% 16.22% 22.52% 23.43% 120.14% 8.11% 9.62% Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 16.22% Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition 9.01% 5.63% 16.22% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A Light globe in the living room is undone, equiting tightening N/A N/A N/A N/A N/A N/A N/A N/A

IGILU0498

IGILU0499

IGILU0500

Laundry

Unit 13-14

Unit 13

Vinyl

Rangehood

Sink & Fittings

Smoke Alarms

\$ 1010.00

\$ 599.00

\$ 1587.00

\$ 260.00

10

12

15

20

01-07-2003 -10.8 years

01-07-2003 -8.8 years

01-07-2003 -5.8 years

01-07-2003 -0.8 years

11.26% Good

2.63% Good

90.11% Good

6.78% Good

Retain

Retain

Retain

Retain

N/A

N/A

N/A

							1			
	IGILU0568	Wardrobe	\$ 2053.00		10 01-01-199	92 -22.3 years	16.229	Excellent	Retain	N/A
ining										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0584	Blind	\$ 388.00		10 01-01-199	92 -22.3 years	36.089	Good	Retain	N/A
	IGILU0585	Carpet	\$ 910.00		8 01-01-199	92 -24.3 years	21.409	Good	Retain	N/A
	IGILU0586	Interior Painting	\$ 832.00			92 -22.3 years		6 Good	Retain	N/A
	IGILOUSOU	intenor rainting	\$ 052.00		10 01-01-13	22 -22.3 years	10.237	5 G000	Retairi	IN/A
lallway										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0587	Carpet	\$ 388.00		8 01-01-199	92 -24.3 years	22.559	6 Excellent	Retain	N/A
	IGILU0588	Interior Painting	\$ 333.00		10 01-01-199	2 -22.3 years	36.049	6 Good	Retain	N/A
itchen							<u> </u>			
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0551	Blind	\$ 333.00			92 -22.3 years	·	6 Good	Retain	N/A
	IGILU0552	Benchtops	\$ 2342.00			92 -12.3 years		Good	Retain	N/A
	IGILU0553	Cooktop	\$ 1354.00			92 -20.3 years		Good	Retain	N/A
	IGILU0554	Interior Painting	\$ 710.00		10 01-01-199	92 -22.3 years	18.039	Good	Retain	N/A
	IGILU0555	Kitchen Cabinets	\$ 3818.00		20 01-01-199	92 -12.3 years	9.019	6 Good	Retain	N/A
	IGILU0556	Vinyl	\$ 1010.00		10 01-01-199	92 -22.3 years	47.869	Good	Retain	N/A
	IGILU0557	Oven	\$ 1409.00			92 -20.3 years		Good	Retain	N/A
	IGILU0558	Rangehood	\$ 599.00			92 -20.3 years		6 Good	Retain	N/A
		-				· ·				
	IGILU0559	Sink & Fittings	\$ 1587.00		15 01-01-195	92 -17.3 years	0.009	Fair	Repair	The kitchen tap is
										leaking, indicating a
										need for repair to
	I CHILLIPS CT	- L .:			20 21 21 21	22 42 2				provent water wastage
	IGILU0560	Smoke Alarms	\$ 260.00		20 01-01-199	92 -12.3 years	18.089	Good	Retain	N/A
aundry										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0569	Interior Painting	\$ 166.00)	10 01-01-199	92 -22.3 years	67.109	Excellent	Retain	N/A
	IGILU0570	Tiles - Wall	\$ 1076.00		20 01-01-199	92 -12.3 years	9.929	Excellent	Retain	N/A
	IGILU0571	Tiles - Floor	\$ 1076.00		20 01-01-199	92 -12.3 years	14.989	Excellent	Retain	N/A
ving										,
villg	Asset Number	Asset Name	Association Cost (\$)	Effective Life (Y)	Installation Date	Damaining Effective Life	Assumulated Dansin Cost as 9/ of Assuisition	Asset Condition	Plan	Comments
			Acquisition Cost (\$)			Remaining Effective Life	Accumulated Repair Cost as % of Acquisition			
	IGILU0579	Air Conditioner -	\$ 3296.00		10 01-01-199	92 -22.3 years	145.989	Good	Retain	N/A
	ICH HOEGO	Split System	£ 200.00		10 01 01 100	22.2	0.130	(C 1	D-4-i-	NI/A
	IGILU0580	Blind	\$ 388.00			92 -22.3 years		6 Good	Retain	N/A
	IGILU0581	Carpet	\$ 1165.00			92 -24.3 years		Good	Retain	N/A
										N/A
	IGILU0582	Heater	\$ 865.00		15 01-01-199	32 - 17.3 years	0.009	Good	Retain	IN/A
	IGILU0582 IGILU0583	Interior Painting	\$ 865.00 \$ 1176.00			32 -17.3 years 32 -22.3 years		Good Good	Retain Retain	N/A
nit Exterior						· ·				
nit Exterior	IGILU0583	Interior Painting	\$ 1176.00		10 01-01-199	22 -22.3 years	36.059		Retain	N/A
nit Exterior	IGILU0583 Asset Number	Interior Painting Asset Name	\$ 1176.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-01-199	Remaining Effective Life	36.059 Accumulated Repair Cost as % of Acquisition	Good Asset Condition	Retain	N/A Comments
nit Exterior	Asset Number	Asset Name Clothesline	\$ 1176.00 Acquisition Cost (\$) \$ 499.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199	Remaining Effective Life 22 -22.3 years	Accumulated Repair Cost as % of Acquisition 75.429	Asset Condition Good	Retain Plan Retain	N/A Comments N/A
nit Exterior	Asset Number IGILU0589 IGILU0590	Asset Name Clothesline Courtyard	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199	Remaining Effective Life 22 - 22.3 years 22 - 22.3 years 22 - 2.3 years	Accumulated Repair Cost as % of Acquisition 75.429 0.009	Asset Condition Good Good	Plan Retain Retain	N/A Comments N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591	Asset Name Clothesline Courtyard Doors	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00	Effective Life (Y)	Installation Date 10 01-01-199 30 01-01-199 30 01-01-199	Remaining Effective Life 22-3 years 22-3 years 22-3 years 22-3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009	Asset Condition Good Good Good Good	Plan Retain Retain Retain	N/A Comments N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592	Asset Name Clothesline Courtyard Doors Downpipes	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y)	10	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 21.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259	Asset Condition Good Good Good Good Good	Plan Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591	Asset Name Clothesline Courtyard Doors	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00	Effective Life (Y)	10	Remaining Effective Life 22-3 years 22-3 years 22-3 years 22-3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009	Asset Condition Good Good Good Good Good	Plan Retain Retain Retain	N/A Comments N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593	Asset Name Clothesline Courtyard Doors Downpipes	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 21.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259	Asset Condition Good Good Good Good Good	Plan Retain Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592	Asset Name Clothesline Courtyard Doors Downpipes Electrical	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 21.3 years	Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259	Asset Condition Good Good Good Good Good	Plan Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 10 01-01-199	22 -22.3 years Remaining Effective Life 22 -22.3 years 22 -2.3 years 22 -2.3 years 23 -2.3 years 24 -2.3 years 25 -12.3 years 26 -12.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749	Asset Condition Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A N/A N/A N/A N/A
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 296.00 \$ 2086.00	Effective Life (Y)	10 01-01-195 Installation Date 10 01-01-195 30 01-01-195 30 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 21.2 2.3 years 22.12.3 years 23.2 12.3 years 24.2 12.3 years 25.2 12.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0593 IGILU0594 IGILU0595 IGILU0596	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 22874.00 \$ 2186.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199	Remaining Effective Life 22 -22.3 years 22 -2.3 years 22 -2.3 years 22 -2.3 years 23 -2.3 years 24 -12.3 years 25 -12.3 years 26 -12.3 years 27 -22.3 years 28 -22.3 years 29 -22.3 years 20 -22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609	Asset Condition Good Good Good Good Good Good Good G	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0589 IGILU0599 IGILU0591 IGILU0593 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0597	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 28874.00 \$ 2186.00 \$ 2819.00	Effective Life (Y)	10 01-01-195 Installation Date 10 01-01-195 30 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195 20 01-01-195	Remaining Effective Life 22 -22.3 years 22 -22.3 years 22 -23.9 years 23 -23.9 years 24 -12.3 years 25 -12.3 years 26 -12.3 years 27 -22.3 years 28 -22.3 years 29 -22.3 years 20 -22.3 years 20 -22.3 years 21 -23.3 years 22 -23.3 years 23 -23.3 years 24 -12.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0597 IGILU0598	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00	Effective Life (Y)	10 01-01-198 Installation Date 10 01-01-198 30 01-01-198 20 01-01-198 20 01-01-198 20 01-01-198 20 01-01-198 20 01-01-198 20 01-01-198 30 01-01-198 30 01-01-198	Remaining Effective Life 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 21.2.3 years 21.2.3 years 21.2.3 years 22.3 years 22.3 years 22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 21874.00 \$ 2180.00 \$ 2180.00 \$ 290.00 \$ 290.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0598 IGILU0599 IGILU0599	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2899.00 \$ 15109.00 \$ 1509.00 \$ 1998.00 \$ 1098.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199	Remaining Effective Life 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 21.2.3 years 21.2.3 years 21.2.3 years 22.3 years 22.3 years 22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 21874.00 \$ 2180.00 \$ 2180.00 \$ 290.00 \$ 290.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0598 IGILU0599 IGILU0599	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2899.00 \$ 15109.00 \$ 1509.00 \$ 1998.00 \$ 1098.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 22.3 years 22.3 years 22.3 years 22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.349 0.009 5.419	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
nit Exterior	Asset Number IGILU0583 IGILU0589 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0599 IGILU0600 IGILU0601	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Parch Lattice Screening Windows	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2819.00 \$ 12908.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199	Remaining Effective Life 2	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.349 0.009 5.419	Asset Condition Good Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number IGILU0583 IGILU0589 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0599 IGILU0600 IGILU0601	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Parch Lattice Screening Windows	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2819.00 \$ 12908.00 \$ 1998.00 \$ 3873.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199	Remaining Effective Life 2	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.349 0.009 5.419	Asset Condition Good Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2180.00 \$ 1981.00 \$ 1983.00 \$ 1098.00 \$ 9435.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 10 01-01-199 10 01-01-199 10 01-01-199 10 01-01-199 10 01-01-199	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.500 33.049 0.009 5.419 0.009	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0600 IGILU0601 IGILU0570	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 10 15-01-209	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.23 years 23.24 years 24.25 years 25.25 years 26.26 years 27.27 years 28.28 years 29.29 years 29.29 years 20.29 years 20.29 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 5.419 0.009	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 21874.00 \$ 2180.00 \$ 2180.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 10 15-01-209	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 22.3 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.500 33.049 0.009 5.419 0.009	Asset Condition Good Good Good Good Good Good Good Go	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0600 IGILU0601 IGILU0570	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 10 15-01-209	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.23 years 23.24 years 24.25 years 25.25 years 26.26 years 27.27 years 28.28 years 29.29 years 29.29 years 20.29 years 20.29 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 5.419 0.009	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0600 IGILU0601 IGILU0570	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-01-199 Installation Date 10 01-01-199 30 01-01-199 30 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 20 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 30 01-01-199 10 15-01-209	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.23 years 23.24 years 24.25 years 25.25 years 26.26 years 27.27 years 28.28 years 29.29 years 29.29 years 20.29 years 20.29 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 5.419 0.009	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0590 IGI	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 198.00 \$ 198.00 \$ 3873.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22 - 22.3 years 22 - 22.3 years 23 - 2.3 years 24 - 2.3 years 25 - 12.3 years 26 - 12.3 years 27 - 12.3 years 28 - 12.3 years 29 - 12.3 years 20 - 12.3 years 20 - 12.3 years 21 - 12.3 years 22 - 12.3 years 23 - 12.3 years 24 - 12.3 years 25 - 12.3 years 26 - 12.3 years 27 - 12.3 years 28 - 12.3 years 29 - 12.3 years 20 - 12.3 years 21 - 12.3 years 22 - 12.3 years 23 - 12.3 years 24 - 12.3 years 25 - 12.3 years 26 - 12.3 years 27 - 12.3 years 28 - 12.3 years 29 - 12.3 years 20 - 12.9 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.003 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.003 Accumulated Repair Cost as % of Acquisition 120.149 Accumulated Repair Cost as % of Acquisition	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	IGILU0583 Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0597 IGILU0599 IGILU0600 IGILU0601 IGILU0601 IGILU0630 Asset Number IGILU0630 Asset Number IGILU0610 IGILU06	Asset Name Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware Asset Name Vinyl	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2190.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.10 years 22.9 years 23.10 years Remaining Effective Life 20.10.9 years Remaining Effective Life 20.5.9 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 54.119 0.009 Accumulated Repair Cost as % of Acquisition 120.149 Accumulated Repair Cost as % of Acquisition 90.109	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain Retain	N/A N/A
athroom	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0600 IGILU0601 IGILU0630 Asset Number IGILU0610 IGILU0611	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware Asset Name Vinyl Oven	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2286.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2988.00 \$ 1098.00 \$ 3873.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1049.00 \$ 1090.00 \$	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.2.3 years 22.3 years 22.3 years 22.12.3 years 22.3 years 22.0 years 23.0 years 24.0 years 25.0 years Remaining Effective Life 26.0 1.5 years 27.9 years	Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 8.119 3.609 57.449 1.509 1.509 33.049 0.009 Accumulated Repair Cost as % of Acquisition 120.149 Accumulated Repair Cost as % of Acquisition 90.109 142.719	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A N/A
athroom	IGILU0583 Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0597 IGILU0599 IGILU0600 IGILU0601 IGILU0601 IGILU0630 Asset Number IGILU0630 Asset Number IGILU0610 IGILU06	Asset Name Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware Asset Name Vinyl	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2190.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.12.3 years 22.2.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.10 years 22.9 years 23.10 years Remaining Effective Life 20.10.9 years Remaining Effective Life 20.5.9 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 54.119 0.009 Accumulated Repair Cost as % of Acquisition 120.149 Accumulated Repair Cost as % of Acquisition 90.109	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain Retain	N/A N/A
athroom	Asset Number	Interior Painting Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware Asset Name Vinyl Oven Sink & Fittings	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 2988.00 \$ 38373.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1409.00 \$ 1587.00	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22 - 22.3 years 22 - 22.3 years 22 - 2.3 years 23 - 2.3 years 24 - 12.3 years 25 - 12.3 years 26 - 12.3 years 27 - 12.3 years 28 - 12.3 years 29 - 12.3 years 20 - 12.3 years 20 - 12.3 years 21 - 12.3 years 22 - 22.3 years 23 - 12.3 years 24 - 12.3 years 25 - 12.3 years 26 - 12.3 years 27 - 12.3 years 28 - 12.3 years 29 - 12.3 years 20 - 12.9 years 20 - 12.9 years 21 - 12.9 years 22 - 12.9 years 23 - 12.9 years 24 - 12.9 years 25 - 12.9 years 26 - 12.9 years 27 - 12.9 years 28 - 12.9 years 29 - 12.9 years 20 - 12.9 years	36.059 Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.255 121.749 9.919 8.119 3.609 57.449 1.509 33.049 0.009 Accumulated Repair Cost as % of Acquisition 4.20149 Accumulated Repair Cost as % of Acquisition 90.109 142.719 114.149	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
athroom	Asset Number IGILU0589 IGILU0590 IGILU0591 IGILU0592 IGILU0593 IGILU0594 IGILU0595 IGILU0596 IGILU0596 IGILU0597 IGILU0598 IGILU0599 IGILU0600 IGILU0601 IGILU0630 Asset Number IGILU0610 IGILU0611	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Tapware Asset Name Vinyl Oven	\$ 1176.00 Acquisition Cost (\$) \$ 499.00 \$ 2286.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2874.00 \$ 2988.00 \$ 1098.00 \$ 3873.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1049.00 \$ 1090.00 \$	Effective Life (Y) Effective Life (Y)	10	Remaining Effective Life 22.3 years 22.3 years 22.3 years 22.3 years 22.3 years 22.12.3 years 22.2.3 years 22.3 years 22.3 years 22.12.3 years 22.3 years 22.0 years 23.0 years 24.0 years 25.0 years Remaining Effective Life 26.0 1.5 years 27.9 years	Accumulated Repair Cost as % of Acquisition 75.429 0.009 0.009 34.259 121.749 8.119 3.609 57.449 1.509 1.509 33.049 0.009 Accumulated Repair Cost as % of Acquisition 120.149 Accumulated Repair Cost as % of Acquisition 90.109 142.719	Asset Condition Good Good Good Good Good Good Good Go	Retain Plan Retain	N/A N/A

	IGILU0645		\$ 2486.00	,	01-01-1992	2.5 years	0.0	U% G000	Ketain	N/A
		Doors	\$ 5605.00	30	01-01-1992	-2.3 years	13.6	2% Good	Retain	N/A
	IGILU0646	Downpipes	\$ 1742.00	20	01-01-1992	2 -12.3 years	34.2	5% Good	Retain	N/A
	IGILU0648	Exterior painting	\$ 2086.00	10	0 01-01-1992	2 -22.3 years	13.5	2% Good	Retain	N/A
	IGILU0649	Fascias	\$ 2874.00	21	01-01-1992	-12.3 years	11.2	6% Good	Retain	N/A
	IGILU0650	Flyscreens	\$ 2186.00	10	0 01-01-1992	-22.3 years	32.4	4% Good	Retain	N/A
	IGILU0651	Guttering	\$ 2819.00	20	01-01-1992	-12.3 years	60.8	2% Good	Retain	N/A
	IGILU0652	Path	\$ 1509.00					5% Good	Retain	N/A
	IGILU0653	Porch	\$ 2908.00	30			0.0	10% Good	Retain	N/A
	IGILU0654	Lattice Screening	\$ 1098.00					1% Good	Retain	N/A
	IGILU0655	Windows	\$ 3873.00			· ·		1% Good	Retain	N/A
	IGILU1571	Awnings	\$ 9435.00			· ·		10% Good	Retain	N/A
Unit 14	IGIEO 137 I	Awilligs	\$ 5455.00	, ,	13-01-2010	-4.2 years	0.0	076 0000	Retain	IVA
Jilit 14	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0602	Insulation	\$ 3069.00			2 -12.3 years		10% Good	Retain	N/A
	IGILU0603	Lighting	\$ 1909.00			· ·		13% Good	Retain	N/A
	IGILU0604		\$ 3174.00					11% Good		N/A
		Sarking							Retain	
	IGILU0605	Hot Water System -	\$ 2386.00	1:	2 01-01-1992	-20.3 years	4.5	1% Good	Retain	N/A
	IGILU0647	Electric Electrical	\$ 1387.00	21	01 01 1002	2 -12.3 years	66.7	6% Good	Retain	N/A
	101200047	Switchboard	ş 1367.00	-	.0 01-01-1992	12.5 years	66.7	570 GOOG	INCIAIT	11/0
		SWITCHDOME	1		1		'	'		
Common										
-	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0002g	Driveway	\$ 21978.00			2 -16.8 years		10% Good	Retain	N/A
Unit 21	loizooozg	Direction	\$2,370.00		.5 01 01 1302	10.0 years	0.0	070 0000	recum	14/1
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0657	Insulation	\$ 3069.00			2 -12.3 years	· · · · · · · · · · · · · · · · · · ·	10% Good	Retain	N/A
	IGILU0658	Lighting	\$ 1909.00			2 -17.3 years		1% Good	Retain	N/A
	IGILU0659		\$ 3174.00					14% Good	Retain	N/A
		Sarking		-					Retain	
	IGILU0660	Hot Water System -	\$ 2386.00	1.	2 01-01-1992	2 -20.3 years	13.5	2% Good	Retain	N/A
Unit 22		Electric				1				
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0710	Insulation	\$ 3069.00			2 -12.3 years	· · · · · · · · · · · · · · · · · · ·	10% Good	Retain	N/A
	IGILU0711	Lighting	\$ 1909.00		5 01-01-1992	· ·		1% Good	Retain	N/A
	IGILU0712	Sarking	\$ 3174.00	-				4% Good	Retain	N/A
	IGILU0713	-	\$ 2386.00			,		2% Good	Retain	N/A
	IGILUU/ 13	Hot Water System -	\$ 2500.00	"	2 01-01-1992	-20.5 years	15.3	276 0000	Retain	IN/A
		Electric				1				
Bathroom										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0683	Skylight	\$ 1010.00			2 -22.3 years	· · · · · · · · · · · · · · · · · · ·	4% Good	Retain	N/A
										1.4
Bed 1	IGIEO0003				0, 0, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	,	39.0	476 0000	Retaili	
Bed 1			'	'		,				Comments
Bed 1	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bed 1	Asset Number	Asset Name	Acquisition Cost (\$) \$ 333.00	Effective Life (Y)	Installation Date 0 01-01-1992	Remaining Effective Life 2 -22.3 years	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan Retain	N/A
Bed 1	Asset Number IGILU0671 IGILU0672	Asset Name Blind Carpet	Acquisition Cost (\$) \$ 333.00 \$ 1032.00	Effective Life (Y)	Installation Date 0 01-01-1992 8 01-01-1992	Remaining Effective Life 2 -22.3 years 2 -24.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5	Asset Condition 2% Good 7% Good	Plan Retain Retain	N/A N/A
Bed 1	Asset Number IGILU0671 IGILU0672 IGILU0673	Asset Name Blind Carpet Curtains	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	Installation Date 0 01-01-1992 8 01-01-1992 6 01-01-1992	Remaining Effective Life 2-22.3 years 2-24.3 years 2-26.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5	Asset Condition 2% Good 7% Good 2% Good	Plan Retain Retain Retain	N/A N/A N/A
Bed 1	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674	Asset Name Blind Carpet Curtains Interior Painting	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00	Effective Life (V)	Installation Date 0 01-01-1992 8 01-01-1992 6 01-01-1992 0 01-01-1992	Remaining Effective Life 2-22.3 years 2-24.3 years 2-26.3 years 2-22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 10.5	Asset Condition 2% Good 7% Good 2% Good 11% Good	Plan Retain Retain Retain Retain	N/A N/A N/A N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673	Asset Name Blind Carpet Curtains	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (V)	Installation Date 0 01-01-1992 8 01-01-1992 6 01-01-1992 0 01-01-1992	Remaining Effective Life 2-22.3 years 2-24.3 years 2-26.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 10.5	Asset Condition 2% Good 7% Good 2% Good	Plan Retain Retain Retain	N/A N/A N/A
Bed 1	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674 IGILU0675	Asset Name Blind Carpet Curtains Interior Painting Wardrobe	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00	Effective Life (Y)	Installation Date 0 01-01-1992 8 01-01-1992 6 01-01-1992 0 01-01-1992	Remaining Effective Life 22.3 years 24.3 years 26.3 years 2.22.3 years 2.22.3 years 2.22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4	Asset Condition 2% Good 7% Good 2% Good 11% Good 0% Good	Plan Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674 IGILU0675 Asset Number	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life 2-2.3 years 2-2.3 years 2-2.3 years 2-2.3 years 2-2.3 years 2-2.3 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition	Asset Condition 2% Good 7% Good 2% Good 1% Good Good Asset Condition	Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674 IGILU0675 Asset Number IGILU0676	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life -22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2	Asset Condition 2% Good 7% Good 2% Good 11% Good 00% Good Asset Condition 2% Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A Comments
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674 IGILU0675 Asset Number IGILU0676 IGILU0677	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ 688.00	Effective Life (Y)	Installation Date	Remaining Effective Life - 22.3 years - 26.3 years - 26.3 years - 22.3 years - 22.3 years Remaining Effective Life - 22.3 years - 24.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 10.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1	Asset Condition 2% Good 7% Good 2% Good 11% Good 0% Good Asset Condition 2% Good 3% Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0673 IGILU0675 Asset Number IGILU0676 IGILU0677 IGILU0677	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet Interior Painting	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ \$ 888.00 \$ \$ 288.00 \$ \$ 288.00 \$ \$ 588.00 \$ \$ 588.00	Effective Life (Y) 11 11 Effective Life (Y) 11 11 11	Installation Date	Remaining Effective Life - 22.3 years - 24.3 years - 22.3 years - 24.3 years - 24.3 years - 24.3 years - 24.3 years - 22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1	Asset Condition 2% Good 7% Good 2% Good 2% Good 1% Good 3% Good Asset Condition 2% Good 3% Good	Plan Retain	N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0674 IGILU0675 Asset Number IGILU0676 IGILU0677	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ 688.00	Effective Life (Y) 11 11 Effective Life (Y) 11 11 11	Installation Date	Remaining Effective Life - 22.3 years - 26.3 years - 26.3 years - 22.3 years - 22.3 years Remaining Effective Life - 22.3 years - 24.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1	Asset Condition 2% Good 7% Good 2% Good 11% Good 0% Good Asset Condition 2% Good 3% Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A
	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0673 IGILU0675 Asset Number IGILU0676 IGILU0677 IGILU0677	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet Interior Painting	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ \$ 888.00 \$ \$ 288.00 \$ \$ 288.00 \$ \$ 588.00 \$ \$ 588.00	Effective Life (Y) 11 11 Effective Life (Y) 11 11 11	Installation Date	Remaining Effective Life - 22.3 years - 24.3 years - 22.3 years - 24.3 years - 24.3 years - 24.3 years - 24.3 years - 22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1	Asset Condition 2% Good 7% Good 2% Good 1% Good 3% Good Asset Condition 2% Good Asset Condition 2% Good 4% Good	Plan Retain	N/A
Bed 2	Asset Number IGILU0671 IGILU0672 IGILU0673 IGILU0673 IGILU0675 Asset Number IGILU0676 IGILU0677 IGILU0677	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet Interior Painting	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ \$ 888.00 \$ \$ 288.00 \$ \$ 288.00 \$ \$ 588.00 \$ \$ 588.00	Effective Life (Y) 11 11 Effective Life (Y) 11 11 11	Installation Date	Remaining Effective Life - 22.3 years - 24.3 years - 22.3 years - 24.3 years - 24.3 years - 24.3 years - 24.3 years - 22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1	Asset Condition 2% Good 7% Good 2% Good 2% Good 1% Good 3% Good Asset Condition 2% Good 3% Good	Plan Retain	N/A
Bed 2	Asset Number IIGILU0671 IIGILU0672 IIGILU0673 IIGILU0673 IIGILU0675 Asset Number IIGILU0676 IIGILU0677 IIGILU0677 IIGILU0678 IIGILU0679	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet Interior Painting Wardrobe	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) \$ 333.00 \$ 688.00 \$ 588.00 \$ 588.00 \$ 2053.00	Effective Life (Y) 11 10 Effective Life (Y) 11 Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life 22.3 years 24.3 years 26.3 years 22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5 16.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1 3.6 36.0 Accumulated Repair Cost as % of Acquisition	Asset Condition 2% Good 7% Good 2% Good 1% Good 3% Good Asset Condition 2% Good Asset Condition 2% Good 4% Good	Plan Retain	N/A N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A
Bed 2	Asset Number IGILU0672 IGILU0672 IGILU0673 IGILU0674 IGILU0675 Asset Number IGILU0676 IGILU0677 IGILU0677 IGILU0679 Asset Number	Asset Name Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind Carpet Interior Painting Wardrobe	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -22.3 years -24.3 years -26.3 years -22.3 years -22.3 years Remaining Effective Life -22.3 years	Accumulated Repair Cost as % of Acquisition 16.2 9.5. 10.5 5.4 2.7 Accumulated Repair Cost as % of Acquisition 16.2 1.1 3.6 3.6 Accumulated Repair Cost as % of Acquisition	Asset Condition 2% Good 7% Good 2% Good 1% Good 0% Good Asset Condition 2% Good 4% Good Asset Condition 4% Good Asset Condition	Plan Retain	N/A

01-03-2020 5.9 years

Installation Date Remaining Effective Life

01-01-1992 -22.3 years

01-01-1992 -2.3 years

30

308.17% Good

5.41% Good

0.00% Good

Asset Condition

Accumulated Repair Cost as % of Acquisition

Retain

Plan

Retain

Retain

N/A

N/A

N/A

Comments

IGILU0633

IGILU0643

IGILU0644

Asset Number

Unit Exterior

Unit 21-22

Unit 21

Air Conditioner -

Split System

Asset Name

Clothesline

Courtyard

\$ 3296.00

Acquisition Cost (\$) Effective Life (Y)

\$ 499.00

\$ 2486.00

	IGILU0696	Interior Painting	\$ 832.00		10 01-01-1	992 -22.3 years	16.2	3% Good	Retain	N/A
hen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0661	Blind	\$ 333.00			992 -22.3 years		2% Good	Retain	N/A
	IGILU0662	Benchtops	\$ 2342.00			992 -12.3 years		1% Good	Retain	N/A
	IGILU0663	Cooktop	\$ 1354.00			992 -20.3 years		2% Good	Retain	N/A
	IGILU0664	Interior Painting	\$ 710.00			992 -22.3 years		1% Good	Retain	N/A
	IGILU0665	Kitchen Cabinets	\$ 3818.00			992 -12.3 years		0% Good	Retain	N/A
	IGILU0666	Vinyl	\$ 1010.00			992 -22.3 years		9% Good	Retain	N/A
	IGILU0667	Electric Elevated	\$ 1409.00		12 01-01-1	992 -20.3 years	67.6	0% Good	Retain	N/A
	IGILU0669	Oven Sink & Fittings	\$ 1587.00		15 01-01-1	992 -17.3 years	120.1	4% Good	Retain	N/A
	IGILU0670	Smoke Alarms	\$ 260.00			992 -17.3 years 992 -12.3 years		0% Good	Retain	N/A
ving	IGIEO0070	SHICKE Alainis	\$ 200.00		20 01-01-1	332 -12.3 years	0.0	0 /8 G000	rictairi	N/A
····g	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0688	Blind	\$ 388.00			992 -22.3 years		0% Good	Retain	N/A
	IGILU0689	Carpet	\$ 1165.00			992 -24.3 years		9% Good	Retain	N/A
	IGILU0690	Curtains	\$ 1776.00			992 -26.3 years		2% Good	Retain	N/A
	IGILU0691	Heater	\$ 865.00			992 -17.3 years		0% Good	Retain	N/A
	IGILU0692	Interior Painting	\$ 1176.00			992 -22.3 years		3% Good	Retain	N/A
nit Exterior	IGILOUGE	interior Fainting	\$ 1170.00		10 01-01-1	552 -22.5 years	13.0.	376 0000	Retain	N/A
III EXCEITOI	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0697	Clothesline	\$ 499.00			992 -22.3 years	· · · · · · · · · · · · · · · · · · ·	1% Good	Retain	N/A
	IGILU0698	Courtyard	\$ 2486.00			992 -2.3 years		0% Good	Retain	N/A
	IGILU0699	Doors	\$ 5605.00			992 -2.3 years		2% Good	Retain	N/A
	IGILU0700	Downpipes	\$ 1742.00			992 -12.3 years		3% Good	Retain	N/A
	IGILU0701	Electrical	\$ 1964.00			992 -12.3 years		5% Good	Retain	N/A
	IGILO0701	Switchboard	\$ 1504.00		20 01-01-1	552 - 12.5 years	40.5	376 G000	Retain	N/A
	IGILU0702	Exterior painting	\$ 2086.00		10 01-01-1	992 -22.3 years	8.1	1% Good	Retain	N/A
	IGILU0703	Fascias	\$ 2874.00			992 -12.3 years		5% Good	Retain	N/A
	IGILU0704	Flyscreens	\$ 2186.00		10 01-01-1	992 -22.3 years	32.4	4% Good	Retain	N/A
	IGILU0705	Guttering	\$ 2819.00		20 01-01-1	992 -12.3 years	135.1	5% Good	Retain	N/A
	IGILU0706	Path	\$ 1509.00		30 01-01-1	992 -2.3 years	0.0	0% Good	Retain	N/A
	IGILU0707	Porch	\$ 2908.00		30 01-01-1	992 -2.3 years	33.0	4% Good	Retain	N/A
	IGILU0708	Lattice Screening	\$ 1098.00			992 -12.3 years		7% Good	Retain	N/A
	IGILU0709	Windows	\$ 3873.00			992 -2.3 years	7.5	1% Good	Retain	N/A
	IGILU1573	Awnings	\$ 9435.00			010 -4.2 years		0% Good	Retain	N/A
		, ,				,				
throom										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0731	Exhaust Fan	\$ 255.00			012 -2.1 years		0% Good	Retain	N/A
	IGILU0732	Interior Painting	\$ 466.00			012 -2.1 years		0% Good	Retain	N/A
	IGILU0734	Skylight	\$ 1010.00		10 01-03-2	012 -2.1 years	58.7	7% Good	Retain	N/A
ed 1										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0723	Blind	\$ 333.00			012 -2.1 years		2% Good	Retain	N/A
	IGILU0724	Carpet	\$ 1032.00			012 -4.1 years		8% Good	Retain	N/A
	IGILU0725	Interior Painting	\$ 888.00			012 -2.1 years		2% Good	Retain	N/A
	IGILU0726	Wardrobe	\$ 2053.00		10 01-03-2	012 -2.1 years	36.0	4% Fair	Repair	The wardrobe door is off
										its tracks, necessitating
										realignment.
12										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0727	Blind	\$ 333.00		10 01-03-2	012 -2.1 years	9.0	1% Good	Retain	N/A
	IGILU0728	Carpet	\$ 688.00		8 01-03-2	012 -4.1 years	9.5	8% Good	Retain	N/A
	IGILU0729	Interior Painting	\$ 588.00		10 01-03-2	012 -2.1 years	34.2	5% Good	Retain	N/A
	IGILU0730	Wardrobe	\$ 2053.00			012 -2.1 years		0% Good	Retain	N/A
ning	-						· · · · · · · · · · · · · · · · · · ·		1	1.7
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0743	Blind	\$ 388.00			012 -2.1 years		1% Good	Retain	N/A
	IGILU0744	Carpet	\$ 910.00			012 -4.1 years		0% Good	Retain	N/A
	IGILU0745	Interior Painting	\$ 832.00			012 -2.1 years		0% Good	Retain	N/A
chen	.31200743		\$ 032.00	1	.0 01-03-2	one en years	1.0	3000	ctairi	//
ien	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0715	Cooktop	\$ 1354.00				· · · · · · · · · · · · · · · · · · ·	Asset Condition 5% Good	Retain	N/A
	IGILUU/ 15	Сооктор	\$ 1354.00		12 01-03-2	012 -0.1 years	2.2	o % G000	retain	IN/A

01-03-2012 -2.1 years

36.06% Good

Retain

N/A

Unit 22

Interior Painting

\$ 710.00

IGILU0716

	IGILU0718	Vinyl	\$ 1010.00	10	01-03-2012	-2.1 years	40.54%	Good	Retain	N/A
	IGILU0719	Electric Elevated	\$ 1409.00	12	2 01-03-2012	-0.1 years	150.22%	Good	Retain	N/A
		Oven				,				
	IGILU0720	Rangehood	\$ 599.00	12	2 01-03-2012	-0.1 years	6.39%	Good	Retain	N/A
Living						,				
Living	A Al I	A NI	A (A)	Fff1' 1'f- 00	Land Harden Bart	P	A	Asset Condition	DI	c
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life				Comments
	IGILU0738	Air Conditioner -	\$ 3296.00	10	01-03-2012	-2.1 years	308.17%	Good	Retain	N/A
		Split System								
	IGILU0739	Blind	\$ 388.00				22.55%	Good	Retain	N/A
	IGILU0740	Carpet	\$ 1165.00	3	8 01-03-2012	-4.1 years	1.13%	Good	Retain	N/A
	IGILU0742	Interior Painting	\$ 1176.00	10	01-03-2012	-2.1 years	36.05%	Good	Retain	N/A
Unit Exterior		-								
Olite Exterior	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
						· · · · · · · · · · · · · · · · · · ·				
	IGILU0746	Clothesline	\$ 499.00				2.71%			N/A
	IGILU0747	Courtyard	\$ 2486.00	30	01-01-1992	-2.3 years	0.00%	Good	Retain	N/A
	IGILU0748	Doors	\$ 5605.00	30	01-01-1992	-2.3 years	2.85%	Good	Retain	N/A
	IGILU0749	Downpipes	\$ 1742.00	20	01-01-1992	-12.3 years	14.42%	Good	Retain	N/A
	IGILU0750	Electrical	\$ 1964.00	-			66.12%			N/A
	10.200730		¥ 150 1.00		01 01 1332	12.5 years	00.1270	0000	Treatment of the second	,,,
	IGILU0751	Switchboard Exterior painting	\$ 2086.00	10	0 01-01-1992	-22.3 years	0.45%	Good	Retain	N/A
	IGILU0752	Fascias	\$ 2874.00				8.11%			N/A
	IGILU0753	Flyscreens	\$ 2186.00	-		-22.3 years	36.05%	Good	Retain	N/A
	IGILU0754	Guttering	\$ 2819.00	20	01-01-1992	-12.3 years	74.33%	Good	Retain	N/A
	IGILU0755	Path	\$ 1509.00	30	01-01-1992	-2.3 years	3.76%	Good	Retain	N/A
	IGILU0756	Porch	\$ 2908.00	30	01-01-1992	-2.3 years	57.06%	Good	Retain	N/A
	IGILU0757	Lattice Screening	\$ 1098.00				7.21%			N/A
	IGILU0758	Windows	\$ 3873.00	-			12.01%			N/A
	IGILU1574	Awnings	\$ 9435.00	10	0 15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Unit 23										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
					ilistaliation Date	Remaining Effective Life	Accumulated Repair Cost as 76 of Acquisition	Asset Condition	riali	
					04 04 4000	42.2	0.000	6 1	B	
	IGILU0760	Insulation	\$ 3069.00	-			0.00%			N/A
	IGILU0761	Insulation Lighting	\$ 1909.00	15	5 01-01-1992		0.00% 28.83%	Good	Retain	N/A
				15	5 01-01-1992	-17.3 years		Good	Retain	
	IGILU0761	Lighting	\$ 1909.00	15 25	5 01-01-1992 5 01-01-1992	-17.3 years -7.3 years	28.83% 23.43%	Good	Retain Retain	N/A
	IGILU0761 IGILU0762	Lighting Sarking Hot Water System -	\$ 1909.00 \$ 3174.00	15 25	5 01-01-1992 5 01-01-1992	-17.3 years -7.3 years	28.83% 23.43%	Good Good	Retain Retain	N/A N/A
Unit 24	IGILU0761 IGILU0762	Lighting Sarking	\$ 1909.00 \$ 3174.00	15 25	5 01-01-1992 5 01-01-1992	-17.3 years -7.3 years	28.83% 23.43%	Good Good	Retain Retain	N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763	Lighting Sarking Hot Water System - Electric	\$ 1909.00 \$ 3174.00 \$ 2386.00	15 25 12	5 01-01-1992 5 01-01-1992 2 01-01-1992	-17.3 years -7.3 years -20.3 years	28.83% 23.43% 0.00%	Good Good Excellent	Retain Retain Retain	N/A N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763	Lighting Sarking Hot Water System- Electric Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	15 25 12 Effective Life (Y)	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition	Retain Retain Retain	N/A N/A N/A Comments
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806	Lighting Sarking Hot Water System - Electric Asset Name Insulation	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00	15 25 12 Effective Life (Y)	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Excellent Asset Condition Good	Retain Retain Retain Plan Retain	N/A N/A N/A N/A Comments N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	15 25 12 Effective Life (Y)	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81%	Good Good Excellent Asset Condition Good Good	Retain Retain Retain Plan Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806	Lighting Sarking Hot Water System - Electric Asset Name Insulation	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00	15 25 12 Effective Life (Y) Effective Life (Y) 20 25 25 25 25 25 25 25 25 25 25 25 25 25	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Excellent Asset Condition Good Good	Retain Retain Retain Plan Retain Retain Retain	N/A N/A N/A N/A Comments N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	15 25 12 Effective Life (Y)	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81%	Good Good Excellent Asset Condition Good Good Good	Retain Retain Retain Plan Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	15 25 12 Effective Life (Y) Effective Life (Y) 20 25 25 25 25 25 25 25 25 25 25 25 25 25	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65%	Good Good Excellent Asset Condition Good Good Good	Retain Retain Retain Plan Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	15 25 12 Effective Life (Y) Effective Life (Y) 20 25 25 25 25 25 25 25 25 25 25 25 25 25	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65%	Good Good Excellent Asset Condition Good Good Good	Retain Retain Retain Plan Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A N/A N/A
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	15 25 12 Effective Life (Y) Effective Life (Y) 20 25 25 25 25 25 25 25 25 25 25 25 25 25	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65%	Good Good Excellent Asset Condition Good Good Good	Retain Retain Retain Plan Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A N/A N/A
Unit 24	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	15 25 12 Effective Life (Y) Effective Life (Y) 20 15 25 12	5 01-01-1992 5 01-01-1992 2 01-01-1992 Installation Date 0 01-01-1992 5 01-01-1992 2 01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27%	Good Good Excellent Asset Condition Good Good Good Good Good	Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0807 IGILU0808 IGILU0809 Asset Number	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00	Effective Life (Y) 20 11 20 11 20 11 20 12 Effective Life (Y)	01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Good Asset Condition	Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A Comments
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	10-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14%	Good Good Excellent Asset Condition Good Good Good Good Good Good Excellent	Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A Comments N/A
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0778	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 12 Effective Life (Y)	1.01-01-1992 1.01-01-01-1992 1.01-01-01-1992 1.01-01-1992 1.01-01-1992 1.01-01-1992 1.01-01-1992	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55%	Good Good Excellent Asset Condition Good Good Good Good Asset Condition Excellent Excellent	Retain Retain Retain Plan Retain	N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A N/A
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 12 Effective Life (Y)	1.01-01-1992 1.01	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55%	Good Good Excellent Asset Condition Good Good Good Good Good Good Excellent	Retain Retain Retain Plan Retain	N/A N/A N/A N/A Comments N/A
	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0778	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 12 Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55%	Good Good Excellent Asset Condition Good Good Good Good Asset Condition Excellent Excellent Excellent	Retain	N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A N/A
	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0809 IGILU0781	Lighting Sarking Hot Water System -Electric Asset Name Insulation Lighting Sarking Hot Water System -Electric Asset Name Exhaust Fan Toilet & Cistern Skylight	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 12 Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61%	Good Good Excellent Asset Condition Good Good Good Good Asset Condition Excellent Excellent Excellent	Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A
	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0809 IGILU0781	Lighting Sarking Hot Water System -Electric Asset Name Insulation Lighting Sarking Hot Water System -Electric Asset Name Exhaust Fan Toilet & Cistern Skylight	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 12 Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61%	Good Good Excellent Asset Condition Good Good Good Good Asset Condition Excellent Excellent Excellent	Retain Retain Retain Plan Retain	N/A N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A Old Condition, a little tilted, and has some
	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0781 IGILU0782	Lighting Sarking Hot Water System -Electric Asset Name Insulation Lighting Sarking Hot Water System -Electric Asset Name Exhaust Fan Toilet & Cistern Skylight	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00	Effective Life (Y) Effective Life (Y) 20 12 21 25 12 12 16 17 18 19 10 10 10 10 10 10 10 10 10	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years -17.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61%	Good Good Excellent Asset Condition Good Good Good Good Asset Condition Excellent Excellent Excellent Excellent Excellent	Retain	N/A N/A N/A N/A Comments N/A
	Asset Number IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0780 IGILU0780 IGILU0780 IGILU0780 IGILU0781 IGILU0782	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00	Effective Life (Y) Effective Life (Y) 20 112 Effective Life (Y) 10 10 115	S	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years -17.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66%	Good Good Excellent Asset Condition Good Good Good Good Fasset Condition Excellent Excellent Excellent Excellent Excellent Excellent Good	Retain Retain Retain Retain Plan Retain	N/A
Bathroom	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0781 IGILU0782	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00	Effective Life (Y) Effective Life (Y) 20 112 Effective Life (Y) 10 10 115	S	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -12.3 years -17.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00%	Good Good Excellent Asset Condition Good Good Good Good Fasset Condition Excellent Excellent Excellent Excellent Excellent Excellent Good	Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A Comments N/A
Bathroom	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0780 IGILU0781 IGILU0782 IGILU0783 IGILU0784	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	Effective Life (Y) Effective Life (Y) 20 11 22 12 Effective Life (Y) 10 20 10 10 20 20 20 20	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02%	Good Good Excellent Asset Condition Good Good Good Good Facellent Excellent Excellent Excellent Excellent Excellent Fair Good Good Good	Retain	N/A
	Asset Number IGILU0782 IGILU0806 IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0788 IGILU0780 IGILU0781 IGILU0782 IGILU0783 IGILU0784 Asset Number	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 22 20 20 Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Fasset Condition Excellent Excellent Excellent Excellent Fair Good Good Good Asset Condition	Retain	N/A
Bathroom	Asset Number IGILU0761 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0780 IGILU0781 IGILU0782 IGILU0783 IGILU0784	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 22 20 20 Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02%	Good Good Excellent Asset Condition Good Good Good Good Fasset Condition Excellent Excellent Excellent Excellent Fair Good Good Good Asset Condition	Retain	N/A
Bathroom	Asset Number IGILU0782 IGILU0806 IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0788 IGILU0780 IGILU0781 IGILU0782 IGILU0783 IGILU0784 Asset Number	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 11 21 21 22 20 21 21 21 21 21 21 21 21 21 21 21 21 21	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Facellent Excellent Excellent Excellent Excellent Excellent Asset Condition Asset Condition Good Good	Retain Retain Retain Retain Plan Retain	N/A
Bathroom Bed 1	Asset Number IGILU0783 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0781 IGILU0782 IGILU0783 IGILU0784 Asset Number IGILU0784	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 3374.00 \$ 3374.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 22 20 20 21 21 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 21 22 22	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Facellent Excellent Excellent Excellent Excellent Excellent Asset Condition Asset Condition Good Good	Retain Retain Retain Retain Plan Retain	N/A
Bathroom Bed 1	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0778 IGILU0778 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0778 IGILU0778 IGILU0778 IGILU0778 IGILU0778 IGILU0778	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 Acquisition Cost (\$) \$ 3285.00 \$ 34884.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 10 20 11 20 11 15 20 16 17 17 18 20 20 20 20 20 20 20 20 20 2	Installation Date	-17.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -17.3 years -12.3 years -17.3 years -18.3 years -19.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04%	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1	Asset Number IGILU0782 IGILU0806 IGILU0807 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0780 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0774 IGILU0774 IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 22 20 20 Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -20.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1 Dining	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0807 IGILU0809 Asset Number IGILU0778 IGILU0778 IGILU0778 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0778 IGILU0778 IGILU0778 IGILU0778 IGILU0778 IGILU0778	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 Acquisition Cost (\$) \$ 3285.00 \$ 34884.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 10 21 22 25 10 10 10 10 Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	-17.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -17.3 years -12.3 years -17.3 years -18.3 years -19.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04%	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1 Dining	Asset Number IGILU0782 IGILU0806 IGILU0807 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0780 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0774 IGILU0774 IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 10 21 22 25 10 10 10 10 Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years -12.3 years -17.3 years -17.3 years -7.3 years -7.3 years -20.3 years -20.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom	Asset Number IGILU0782 IGILU0806 IGILU0807 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0780 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0774 IGILU0774 IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe Asset Name	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 10 21 22 25 10 10 10 10 Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -20.3 years -20.3 years -20.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04% Accumulated Repair Cost as % of Acquisition	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1 Dining	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0780 IGILU0781 IGILU0781 IGILU0784 Asset Number IGILU0774 IGILU0777	Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 3286.00 Acquisition Cost (\$) \$ 225.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 22 20 Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	-17.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years -12.3 years -17.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% 36.04% Accumulated Repair Cost as % of Acquisition 34.23% 36.04%	Good Good Excellent Asset Condition Good Good Good Good Good Good Asset Condition Excellent Excellent Excellent Fair Good Good Good Asset Condition	Retain	N/A
Bathroom Bed 1 Dining	Asset Number IGILU0781 IGILU0763 Asset Number IGILU0806 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0778 IGILU0781 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0777 Asset Number IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Asset Name Blind	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 2053.00 Acquisition Cost (\$) \$ 338.00 \$ 333.00 \$ 333.00 \$ 2053.00	Effective Life (Y)	Installation Date	-17.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years Remaining Effective Life -22.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% Accumulated Repair Cost as % of Acquisition 19.85% Accumulated Repair Cost as % of Acquisition 19.85%	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1 Dining	IGILU0761 IGILU0762 IGILU0763 Asset Number IGILU0806 IGILU0807 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0781 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0777 IGILU0777 IGILU0777 IGILU0777 IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Wardrobe Asset Name Blind Asset Name Blind Benchtops	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) 20 21 22 25 26 27 27 27 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	Installation Date	-17.3 years -7.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% Accumulated Repair Cost as % of Acquisition 19.85% Accumulated Repair Cost as % of Acquisition 19.85% Accumulated Repair Cost as % of Acquisition 19.85%	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Bathroom Bed 1 Dining	Asset Number IGILU0781 IGILU0763 Asset Number IGILU0806 IGILU0808 IGILU0809 Asset Number IGILU0778 IGILU0778 IGILU0781 IGILU0781 IGILU0782 IGILU0784 Asset Number IGILU0777 Asset Number IGILU0777	Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Exhaust Fan Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Asset Name Blind	\$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 1343.00 \$ 1304.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 333.00 \$ 2053.00 Acquisition Cost (\$) \$ 338.00 \$ 333.00 \$ 333.00 \$ 2053.00	Effective Life (Y) 20 21 22 25 26 27 27 27 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	Installation Date	-17.3 years -7.3 years -7.3 years -20.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -20.3 years -12.3 years	28.83% 23.43% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 10.81% 39.65% 14.27% Accumulated Repair Cost as % of Acquisition 17.14% 49.55% 12.61% 0.00% 7.66% 18.02% Accumulated Repair Cost as % of Acquisition 34.23% Accumulated Repair Cost as % of Acquisition 19.85% Accumulated Repair Cost as % of Acquisition 19.85%	Good Good Excellent Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A

Unit 23-24

Unit 23

Vinyl

\$ 1010.00

10

01-03-2012 -2.1 years

40.54% Good

Retain

	IGILU0768	Kitchen Cabinets	\$ 3818.00	20	01-01-1992	- 12.3 years	11.26%	Fair	Repair	Cabinet doors next to
										the oven are slightly
										worn and stained, with
										hinges showing signs of
										failure; inspection and
										hinge replacement are
	IGILU0770	Oven	\$ 1409.00	12	01-01-1992	-20.3 years	82.62%	Good	Retain	N/A
	IGILU0771	Rangehood	\$ 599.00	12	01-01-1992	-20.3 years	2.25%	Good	Retain	N/A
	IGILU0772	Sink & Fittings	\$ 1587.00				114.14%		Retain	N/A
I facilities as	IGIEOUTTE	Sink & rittings	\$ 1507.00	1-	01 01 1332	17.5 years	113.13%	Good	rectain	IV/A
Living										
	Asset Number	Asset Name		Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0785	Air Conditioner -	\$ 3296.00	10	01-01-1992	-22.3 years	137.87%	Excellent	Retain	N/A
		Split System								
	IGILU0786	Blind	\$ 388.00				11.73%	Excellent	Retain	N/A
	IGILU0788	Heater	\$ 865.00	15	01-01-1992	-17.3 years	0.00%	Excellent	Retain	N/A
Unit Exterior										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0793	Clothesline	\$ 499.00				19.84%		Retain	N/A
	IGILU0794		\$ 2486.00				0.00%		Retain	N/A
		Courtyard								
	IGILU0795	Doors	\$ 5605.00					Good	Retain	N/A
	IGILU0796	Downpipes	\$ 1742.00	20	01-01-1992	-12.3 years	24.30%	Good	Retain	N/A
	IGILU0797	Electrical	\$ 1964.00	20	01-01-1992	-12.3 years	61.99%	Good	Retain	N/A
		Switchboard								
	IGILU0798	Exterior painting	\$ 2086.00	10	01-01-1992	-22.3 years	6.76%	Good	Retain	N/A
	IGILU0799	Fascias	\$ 2874.00	20	01-01-1992	-12.3 years	8.11%	Good	Retain	N/A
	IGILU0800	Flyscreens	\$ 2186.00	10	01-01-1992	-22.3 years	30.64%	Good	Retain	N/A
	IGILU0801	Guttering	\$ 2819.00				6.76%	Good	Retain	N/A
	IGILU0802	Path	\$ 1509.00					Good	Retain	N/A
	IGILU0803	Porch	\$ 2908.00					Good	Retain	N/A
	IGILU0804	Lattice Screening	\$ 1098.00	20	01-01-1992	-12.3 years	2.25%	Good	Retain	N/A
	IGILU0805	Windows	\$ 3873.00	30	01-01-1992	-2.3 years	11.71%	Good	Retain	N/A
	IGILU1575	Awnings	\$ 9435.00	10	15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Bathroom										
Bathroom	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (V)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bathroom	Asset Number	Asset Name		Effective Life (Y)		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bathroom	IGILU0824	Exhaust Fan	\$ 255.00	10	01-01-1992	-22.3 years	16.24%	Good	Retain	N/A
Bathroom				10	01-01-1992	-22.3 years		Good		N/A The cornices have cracks,
Bathroom	IGILU0824	Exhaust Fan	\$ 255.00	10	01-01-1992	-22.3 years	16.24%	Good	Retain	N/A The cornices have cracks, spanning approximately
Bathroom	IGILU0824	Exhaust Fan	\$ 255.00	10	01-01-1992	-22.3 years	16.24%	Good	Retain	N/A The cornices have cracks,
Bathroom	IGILU0824 IGILU0825	Exhaust Fan Interior Painting	\$ 255.00 \$ 466.00	10	01-01-1992 01-08-2019	-22.3 years 5.3 years	16.24% 264.69%	Good Fair	Retain Repair	N/A The cornices have cracks, spanning approximately 2 linear meters.
Bathroom	IGILU0824 IGILU0825	Exhaust Fan Interior Painting Toilet & Cistern	\$ 255.00 \$ 466.00 \$ 1343.00	10	01-01-1992 01-08-2019 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29%	Good Fair Good	Retain Repair Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A
Bathroom	IGILU0824 IGILU0825 IGILU0826 IGILU0827	Exhaust Fan Interior Painting Toilet & Cistern Skylight	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00	10 10 20 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -22.3 years	16.24% 264.69% 38.29% 32.44%	Good Fair Good Good	Retain Repair Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A
Bathroom	IGILU0824 IGILU0825	Exhaust Fan Interior Painting Toilet & Cistern	\$ 255.00 \$ 466.00 \$ 1343.00	10 10 20 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -22.3 years	16.24% 264.69% 38.29%	Good Fair Good Good	Retain Repair Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A
Bathroom	IGILU0824 IGILU0825 IGILU0826 IGILU0827	Exhaust Fan Interior Painting Toilet & Cistern Skylight	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00	20 10 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -22.3 years -17.3 years	16.24% 264.69% 38.29% 32.44%	Good Fair Good Good Good	Retain Repair Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A
Bathroom	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00	20 10 11 11 12 20	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08%	Good Fair Good Good Good Good	Retain Repair Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00	20 10 11 11 12 20	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11%	Good Fair Good Good Good Good	Retain Repair Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	20 10 20 10 20 20	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.24% 66.08% 8.11% 18.02%	Good Fair Good Good Good Good Good	Retain Repair Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	20 10 11 15 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -17.3 years -12.3 years -12.3 years -12.4 years -12.5 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A N/A N/A Comments
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	20 10 11 15 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -17.3 years -12.3 years -12.3 years -12.4 years -12.5 years	16.24% 264.69% 38.29% 32.24% 66.08% 8.11% 18.02%	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	20 10 11 15 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -17.3 years -12.3 years -12.3 years -12.4 years -12.5 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A The wire handle is cracked, and the blind
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00	20 10 11 15 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -17.3 years -12.3 years -12.3 years -12.4 years -12.5 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$)	20 10 11 11 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.119 18.02% Accumulated Repair Cost as % of Acquisition 16.22%	Good Fair Good Good Good Good Good Fair Asset Condition Fair	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the need for renait.
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00	20 10 11 15 20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22%	Good Fair Good Good Good Good Good Fair Asset Condition Fair	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the neart for renail N/A
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$)	20 10 11 15 20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.119 18.02% Accumulated Repair Cost as % of Acquisition 16.22%	Good Fair Good Good Good Good Good Fair Asset Condition Fair	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nead for renait.
	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1776.00 \$ 2053.00	20 10 10 10 10 10 10 10 10 10 10 10 10 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -2.3 years -2.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82%	Good Fair Good Good Good Good Good Fair Asset Condition Fair Good Good Good	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Repair	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the pead for repair N/A N/A N/A
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1776.00 \$ 2053.00	20 10 11 15 20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22%	Good Fair Good Good Good Good Good Fair Asset Condition Fair	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the neart for renais N/A
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1776.00 \$ 2053.00	20 10 10 10 10 10 10 10 10 10 10 10 10 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82%	Good Fair Good Good Good Good Good Fair Good Good Good Good Good Asset Condition Fair Good Good	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Repair	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the paed for renail N/A N/A N/A
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00	20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nead for cenair N/A N/A Comments
Bed 1	IGILU0824 IGILU0825 IGILU0825 IGILU0827 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823 Asset Number IGILU0823	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 Acquisition Cost (\$) \$ 2053.00	20 10 11 15 20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11%	Good Fair Good Good Good Good Good Good Good Asset Condition Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nearlier cranais N/A N/A N/A Comments N/A N/A N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0823 Asset Number IGILU0823	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$)	20 10 11 15 20 20 20 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -12.3 years -17.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nearl for renail N/A N/A N/A N/A Comments N/A Comments
Bed 1	IGILU0824 IGILU0825 IGILU0826 IGILU0827 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823 Asset Number IGILU0838 IGILU0838 IGILU0838	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 333.00 \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00	20 20 20 20 20 20 20 20 20 20 20 20 20 2	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A Comments The wire handle is cracked, and the blind has fallen off, indicating the need for renair N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0827 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00	20 10 11 11 12 20 20 Effective Life (Y) 10 Effective Life (Y) 10 Effective Life (Y)	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 Installation Date 01-01-1992 Installation Date 01-01-1992 Installation Date 01-01-1992 Installation Date	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.119 18.02% Accumulated Repair Cost as % of Acquisition 15.02% 15.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Asset Condition Good Good Good Asset Condition Good Asset Condition Good Good Asset Condition Good Good Good Asset Condition	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nead for renail N/A N/A N/A Comments N/A N/A N/A N/A Comments N/A N/A N/A N/A Comments
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0827 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0821 IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number IGILU0839	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00 \$ 2342.00	## 100	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.119 18.02% Accumulated Repair Cost as % of Acquisition 15.02% 15.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Plan Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nearl for renail N/A N/A N/A N/A N/A Comments N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0823 Asset Number IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number IGILU0831	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 2777.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3777.00 \$ 2164.00 \$ 1776.00 \$ 1776.00 \$ 1776.00 \$ 1776.00 \$ 1776.00	20 20 10 10 10 10 10 10 10 10 10 10 10 10 10	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the need for renail N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0827 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0821 IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number IGILU0839	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop Kitchen Cabinets	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00 \$ 2342.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 Effective Life (Y) 21 22 22	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76%	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Retain Plan Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nearl for renail N/A N/A N/A N/A N/A Comments N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0823 Asset Number IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number IGILU0831	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 2777.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3777.00 \$ 2164.00 \$ 1776.00 \$ 1776.00 \$ 1776.00 \$ 1776.00 \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 Effective Life (Y) 20 21 22 22 22 23	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -12.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -22.3 years -26.3 years -26.3 years -26.3 years -26.3 years -27.3 years -28.3 years -29.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Retain Retain Retain Plan Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the need for renail N/A N/A N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0823 Asset Number IGILU0838 IGILU0838 IGILU0839 Asset Number IGILU0838 IGILU0839	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop Kitchen Cabinets	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 2777.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00 \$ 2342.00 \$ 1354.00 \$ 3818.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 Effective Life (Y) 21 22 22	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years -12.3 years -12.3 years -12.3 years -17.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -22.3 years -26.3 years -26.3 years -26.3 years -26.3 years -27.3 years -28.3 years -29.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 15.02% 17.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76% 8.11%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Repair Plan Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A Comments The wire handle is cracked, and the blind has fallen off, indicating the nead for renait N/A N/A N/A Comments N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0821 IGILU0823 Asset Number IGILU0838 IGILU0838 IGILU0839 Asset Number IGILU0838 IGILU0839	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop Kitchen Cabinets Electric Elevated	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 2777.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 777.00 \$ 2164.00 \$ 1776.00 \$ 2342.00 \$ 1354.00 \$ 3818.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 Effective Life (Y) 21 22 21 21 21 22 22	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years -22.3 years -22.3 years -22.3 years -23 years -24.3 years -25.3 years -26.3 years -27.3 years -28.3 years -29.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.11% 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 15.02% 17.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76% 8.11%	Good Fair Good Good Good Good Good Good Good Go	Retain Repair Retain Retain Retain Retain Retain Retain Retain Repair Plan Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A Comments The wire handle is cracked, and the blind has fallen off, indicating the nead for renait N/A N/A N/A Comments N/A
Bed 1 Dining	IGILU0824 IGILU0825 IGILU0825 IGILU0826 IGILU0827 IGILU0828 IGILU0829 IGILU0830 Asset Number IGILU0819 IGILU0821 IGILU0823 Asset Number IGILU0837 IGILU0838 IGILU0839 Asset Number IGILU0831 IGILU0831 IGILU0811	Exhaust Fan Interior Painting Toilet & Cistern Skylight Tapware Tiles - Wall Tiles - Floor Asset Name Blind Curtains Wardrobe Asset Name Blind Vinyl Curtains Asset Name Benchtops Cooktop Kitchen Cabinets Electric Elevated Oven	\$ 255.00 \$ 466.00 \$ 1343.00 \$ 1010.00 \$ 1304.00 \$ 3285.00 \$ 4884.00 Acquisition Cost (\$) \$ 2777.00 \$ 2164.00 \$ 1776.00 \$ 2342.00 \$ 1354.00 \$ 3818.00 \$ 1409.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) 20 21 21 21 21	01-01-1992 01-08-2019 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-22.3 years 5.3 years -12.3 years	16.24% 264.69% 38.29% 32.44% 66.08% 8.119 18.02% Accumulated Repair Cost as % of Acquisition 16.22% 15.02% 19.82% Accumulated Repair Cost as % of Acquisition 11.71% 90.11% 1.50% Accumulated Repair Cost as % of Acquisition 2.25% 12.76% 8.11% 50.73%	Good Fair Good Good Good Good Good Good Good Goo	Retain Repair Retain Retain Retain Retain Retain Retain Retain Plan Repair Plan Retain	N/A The cornices have cracks, spanning approximately 2 linear meters. N/A N/A N/A N/A N/A N/A N/A The wire handle is cracked, and the blind has fallen off, indicating the nearly for renail N/A

Unit 24

Kitchen Cabinets

\$ 3818.00

20

01-01-1992 -12.3 years

11.26% Fair

Repair

Cabinet doors next to

Living	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y	Incts	allation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Com
	IGILU0831	Asset Name Air Conditioner -	\$ 3296.00	10	01-01-1992		Accumulated Repair Cost as % of Acquisition 324.39%		Retain	N/A
	IGIEU005 I	Split System	\$ 5290.00	10	01-01-1992	-22.3 years	324.39%	GOOG	Retain	IN/A
	IGILU0832	Blind	\$ 388.00	10	01-01-1992	-22.3 years	36.08%	Good	Retain	N/A
	IGILU0834	Curtains	\$ 1776.00	6	01-01-1992	,	14.26%		Retain	N/A
Unit Exterior				-		,		1		
	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y	Insta	allation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Cor
	IGILU0841	Clothesline	\$ 499.00	10	01-01-1992			Good	Retain	N/A
	IGILU0842	Courtyard	\$ 2486.00	30	01-01-1992		0.00%	Good	Retain	N/A
	IGILU0843	Doors	\$ 5605.00	30	01-01-1992		5.41%	Good	Retain	N/A
	IGILU0844	Downpipes	\$ 1742.00	20	01-01-1992	•	16.22%	Good	Retain	N/A
	IGILU0845	Electrical	\$ 1964.00	20	01-01-1992	· ·	40.55%		Retain	N/A
		Switchboard				,				
	IGILU0846	Electrical	\$ 1964.00	20	01-01-1992	-12.3 years	127.73%	Good	Retain	N/A
		Switchboard								
	IGILU0847	Exterior painting	\$ 2086.00	10	01-01-1992	· ·		Good	Retain	N/A
	IGILU0848	Fascias	\$ 2874.00	20	01-01-1992			Good	Retain	N/A
	IGILU0849	Flyscreens	\$ 2186.00	10	01-01-1992	-22.3 years	32.44%	Fair	Repair	Back
										locki
										off t
										a ne
	IGILU0850	Guttering	\$ 2819.00	20	01-01-1992	-12 3 years	33.79%	Good	Retain	N/A
	IGILU0851	Path	\$ 1509.00	30	01-01-1992			Good	Retain	N/A
	IGILU0852	Porch	\$ 2908.00	30	01-01-1992	•		Good	Retain	N/A
										N/A
	IGILU0853	Lattice Screening Windows	\$ 1098.00	20	01-01-1992			Good	Retain	
	IGILU0854 IGILU1576		\$ 3873.00	30	01-01-1992	•		Good		N/A
		Awnings	\$ 9435.00	10	15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Unit 25	Asset Number	Asset Name	Acquisition Cost (\$) Effective Life (Y			Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	
Unit 25	Asset Number	Insulation	\$ 3069.00	20	01-01-1992	-12.3 years	0.00%	Good	Retain	N/A
Unit 25	Asset Number IGILU0856 IGILU0857	Insulation Lighting	\$ 3069.00 \$ 1909.00	20 15	01-01-1992 01-01-1992	-12.3 years -17.3 years	0.00%	Good Excellent	Retain Retain	N/A N/A
Unit 25	Asset Number IGILU0856 IGILU0857 IGILU0858	Insulation Lighting Sarking	\$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25	01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years	0.00% 13.21% 18.02%	Good Excellent Excellent	Retain Retain Retain	N/A N/A N/A
Unit 25	Asset Number IGILU0856 IGILU0857	Insulation Lighting Sarking Hot Water System	\$ 3069.00 \$ 1909.00 \$ 3174.00	20 15	01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years	0.00%	Good Excellent Excellent	Retain Retain	N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858	Insulation Lighting Sarking	\$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25	01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years	0.00% 13.21% 18.02%	Good Excellent Excellent	Retain Retain Retain	N/A N/A N/A
Unit 25 Unit 26	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859	Insulation Lighting Sarking Hot Water System Electric	\$ 3069 00 \$ 1909.00 \$ 3174.00 \$ 2386 00	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years -20.3 years	0.00% 13.21% 18.02% 28.53%	Good Excellent Excellent Good	Retain Retain Retain Retain	N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859	Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition	Good Excellent Excellent Good Asset Condition	Retain Retain Retain Retain Plan	N/A N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y	20 15 25 12 Insta	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00%	Good Excellent Excellent Good Asset Condition Good	Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00	20 15 25 12 Insta 20	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Good Excellent Excellent Good Asset Condition Good Good	Retain Retain Retain Retain Retain Plan Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910 IGILU0911	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25 12 Insta 20 15 25	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Good Excellent Excellent Good Asset Condition Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A Com N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25 12 Insta 20	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03%	Good Excellent Excellent Good Asset Condition Good Good Good Good	Retain Retain Retain Retain Retain Plan Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910 IGILU0911	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25 12 Insta 20 15 25	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Good Excellent Excellent Good Asset Condition Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A Com N/A N/A N/A
	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910 IGILU0911	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25 12 Insta 20 15 25	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Good Excellent Excellent Good Asset Condition Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A Com N/A N/A N/A
Unit 26	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0910 IGILU0911	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00	20 15 25 12 20 15 25 15 25 12 20 15 25 12 20 15 25 12 20 20 20 20 20 20 20	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Good Excellent Excellent Good Asset Condition Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A
Unit 26	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0911 IGILU0912	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	20 15 25 12 20 15 25 15 25 12 20 15 25 12 20 15 25 12 20 20 20 20 20 20 20	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition	Good Excellent Excellent Good Asset Condition Good Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A
Unit 26	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Asset Condition	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A Com N/A N/A N/A
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Asset Condition	Retain	N/A N/A N/A N/A N/A N/A N/A N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 1587.00)	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Food Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 01-01-2992 01-01-2992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33%	Good Excellent Excellent Good Asset Condition Good Good Good Good Asset Condition Excellent Asset Condition	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A Con N/A Con N/A Con
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0868 IGILU0896 IGILU0897	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 499.00 \$ 2486.00	20 15 25 12 15 25 15 25 12 15 15	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A N/A Con N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0868	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y	20 15 25 12	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 allation Date 01-05-2019 allation Date 01-01-1992 01-01-1992	12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -2.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10%	Good Excellent Excellent Good Asset Condition Good Good Good Good Fixed Condition Cood Good Good Good Good Good Good Good	Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Plan Retain Retain Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0897 IGILU0898 IGILU0899	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 1587.00 Acquisition Cost (\$) Effective Life (Y. \$ 499.00 \$ 2486.00 \$ 2486.00 \$ 5505.00 \$ 1742.00	20 15 25 12 20 15 25 15 25 12 25 15 15	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 allation Date 01-05-2019 allation Date 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain Retain Retain Retain Plan Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0896 IGILU0897 IGILU0898	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Downpipes Electrical	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 499.00 \$ 2486.00 \$ 5605.00	20 15 25 12 20 15 25 12 20 15 25 12 25 15 25 15 25 15 26 26 26 26 26 26 26 2	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 allation Date 01-05-2019 allation Date 01-01-1992 01-01-1992	12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0897 IGILU0898 IGILU0899	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 1587.00 Acquisition Cost (\$) Effective Life (Y. \$ 499.00 \$ 2486.00 \$ 2486.00 \$ 5505.00 \$ 1742.00	20 15 25 12 20 15 25 15 25 12 25 15 15	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 allation Date 01-05-2019 allation Date 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -12.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain Retain Retain Retain Plan Retain	N/A
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0896 IGILU0897 IGILU0898 IGILU0899 IGILU0900	Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 1499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00	20 15 25 12 15 25 15 25 12 15 15	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	-12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.4 years -20.5 years -20.6 years -20.7 years -20.8 years -20.8 years -20.9 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80% 61.99%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A N/A N/A N/A N/A Con N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 F	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 \$ 2486.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00	20 15 25 12 20 15 25 12 20 15 25 12 20 15 25 15 20 20 20 20 20 10 10	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 allation Date 01-05-2019 allation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80% 61.99%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0857 IGILU0858 IGILU0859 IGILU0910 IGILU0911 IGILU0911 IGILU0912 Asset Number IGILU0898 IGILU0898 IGILU0899 IGILU0899 IGILU0900 IGILU0901 IGILU0901	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 499.00 \$ 2486.00 \$ 55605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00	20 15 25 12 20 15 25 15 25 12 20 16 16 16 16 16 16 16 1	01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years -22.3 years -22.3 years	0.00% 13.21% 18.02% 28.53% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.04% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80% 61.99% 18.02% 21.63% 72.10%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 r Asset Number IGILU0896 IGILU0897 IGILU0897 IGILU0899 IGILU0900 IGILU0900 IGILU0901 IGILU0901 IGILU0902 IGILU0903 IGILU0904	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 3069.00 \$ 1909.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 \$ 2496.00 \$ 5 2486.00 \$ 5 605.00 \$ 1742.00 \$ 1964.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00 \$ 22874.00 \$ 2286.00	20 15 25 12 15 25 15 25 15 25 15 1	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 61.99% 18.00% 61.99% 18.02% 21.63% 72.10% 74.33%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0909 IGILU0911 IGILU0912 Asset Number IGILU0986 IGILU0897 IGILU0898 IGILU0899 IGILU0900 IGILU0900 IGILU0901 IGILU0903 IGILU0904 IGILU0905	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2816.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 3190.00 \$ 1599.00	20 15 25 12 20 15 25 12 25 12 25 15 25 15 25 15 26 20 20 20 20 20 20 20	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years	Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 61.99% 18.02% 21.63% 72.10% 74.33% 6.01%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 F	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 3069.00 \$ 1909.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 3069.00) \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 1587.00 Acquisition Cost (\$) Effective Life (Y. \$ 499.00) \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 22874.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2196.00 \$ 22819.00 \$ 3190.00 \$ 3190.00	20 15 25 12 20 15 25 12 25 12 20 20 20 20 20 20 20	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years -20.3 years -17.3 years -17.3 years -17.3 years -17.3 years -17.3 years -20.3 years -10.3 years	0.00% 13.21% 18.02% 28.53%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	Com N/A
Unit 26 Kitchen	Asset Number IGILU0856 IGILU0857 IGILU0857 IGILU0858 IGILU0859 IGILU0910 IGILU0911 IGILU0911 IGILU0912 Asset Number IGILU0991 IGILU0896 IGILU0896 IGILU0899 IGILU0899 IGILU0890 IGILU0900 IGILU0901 IGILU0901 IGILU0901 IGILU0906 IGILU0906 IGILU0906 IGILU0907	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y \$ 1587.00 Acquisition Cost (\$) Effective Life (Y \$ 499.00 \$ 2486.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 22874.00 \$ 2186.00 \$ 2186.00 \$ 2180.00 \$ 1290.00 \$ 1290.00 \$ 1909.00 \$ 1909.00	20 15 25 12 20 15 25 15 25 12 20 10 20 20 10 20 30 30 20 20 20 20 30 20 2	01-01-1992 01-01-1992 allation Date 01-01-1992 01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years -13.3 years -13.3 years -13.3 years -13.3 years	Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition Accumulated Repair Cost as % of Acquisition 120.14% Accumulated Repair Cost as % of Acquisition 15.33% 0.00% 2.10% 1.80% 61.99% 18.02% 21.63% 72.10% 74.33% 6.011%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N/A N/A
Unit 26 Kitchen	Asset Number GILU0856 IGILU0857 IGILU0858 IGILU0859 Asset Number IGILU0910 IGILU0911 IGILU0912 Asset Number IGILU0868 F	Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Sarking Hot Water System Electric Sink & Fittings Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 3069.00 \$ 1909.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Effective Life (Y. \$ 3069.00) \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 1587.00 Acquisition Cost (\$) Effective Life (Y. \$ 499.00) \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 22874.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2196.00 \$ 22819.00 \$ 3190.00 \$ 3190.00	20 15 25 12 20 15 25 12 25 12 20 20 20 20 20 20 20	01-01-1992 01-01-1992 01-01-1992 allation Date 01-01-1992	12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -17.3 years -17.3 years -20.3 years Remaining Effective Life 10.1 years Remaining Effective Life -22.3 years -2.3 years -12.3 years -13.3 years -13.3 years -13.3 years -13.3 years	0.00% 13.21% 18.02% 28.53%	Good Excellent Excellent Good Asset Condition Good Good Good Good Good Good Good Go	Retain	N// N//

Unit 25-26

Bathroom

IGILU1577

Awnings

\$ 9435.00

10

15-01-2010 -4.2 years

0.00% Good

Retain

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0932	Exhaust Fan	\$ 255.00	2	10 01-10-2014		19.84%		Retain	N/A
	IGILU0933	Interior Painting	\$ 466.00		10 01-10-2014			Good	Retain	N/A
						•				
	IGILU0935	Skylight	\$ 1010.00		10 01-10-2014	U.5 years	3.60%	Excellent	Retain	N/A
ed 1										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0923	Blind	\$ 333.00		10 01-10-2014	0.5 years	16.22%	Good	Retain	N/A
	IGILU0924	Carpet	\$ 1032.00		8 01-10-2014	-1.5 years	27.03%	Good	Retain	N/A
	IGILU0925	Curtains	\$ 1776.00		6 01-10-2014	-3.5 years	16.52%	Good	Retain	N/A
	IGILU0926	Interior Painting	\$ 888.00		10 01-10-2014	0.5 years	18.02%	Good	Retain	N/A
	IGILU0927	Wardrobe	\$ 2053.00		10 01-10-2014		19.82%	Good	Retain	N/A
ed 2		11111111111	7			100 700.0		1	1.000	1.4
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0928	Blind	\$ 333.00	Lifective Life (1)	10 01-10-2014			Excellent	Retain	N/A
	IGILU0929		\$ 688.00				10.14%		Retain	N/A
		Carpet								- '
	IGILU0930	Interior Painting	\$ 588.00		10 01-10-2014		16.22%		Retain	N/A
	IGILU0931	Wardrobe	\$ 2053.00		10 01-10-2014	0.5 years	6.31%	Good	Retain	N/A
ning										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0940	Air Conditioner -	\$ 3296.00		10 01-10-2014	0.5 years	145.98%	Excellent	Retain	N/A
		Split System								
	IGILU0946	Blind	\$ 388.00		10 01-10-2014	0.5 years	0.00%	Excellent	Retain	N/A
	IGILU0949	Interior Painting	\$ 832.00		10 01-10-2014	0.5 years	36.06%	Good	Retain	N/A
chen						1 - 1				
_	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0915	Curtains	\$ 444.00	Lifective Life (1)	6 01-10-2014			Good	Retain	N/A
	IGILU0916	Interior Painting	\$ 710.00					Good	Retain	N/A
	IGILU0918	Vinyl	\$ 1010.00		10 01-10-2014	0.5 years	18.02%	Excellent	Retain	N/A
ring										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0941	Blind	\$ 388.00		10 01-10-2014	0.5 years	7.22%	Good	Retain	N/A
	IGILU0943	Curtains	\$ 1776.00		6 01-10-2014	-3.5 years	3.75%	Good	Retain	N/A
	IGILU0945	Interior Painting	\$ 1176.00		10 01-10-2014	0.5 years	36.05%	Good	Retain	N/A
nit Exterior						,				
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0950	Clothesline	\$ 499.00		10 01-01-1992		19.84%		Retain	N/A
	IGILU0951	Courtyard	\$ 2486.00		30 01-01-1992			Good	Retain	N/A
	IGILU0952	Doors	\$ 5605.00					Good	Retain	N/A
		Doors	\$ 5005.00		30 01-01-1992			G000	Retain	N/A
		l = .								
	IGILU0953	Downpipes	\$ 1742.00		20 01-01-1992			Excellent	Retain	
	IGILU0953	Electrical	\$ 1742.00 \$ 1964.00		20 01-01-1992 20 01-01-1992			Excellent Excellent	Retain Retain	N/A
	IGILU0954	Electrical Switchboard	\$ 1964.00		20 01-01-1992	2 -12.3 years	93.15%	Excellent	Retain	N/A
		Electrical			20 01-01-1992 10 01-01-1992	2 -12.3 years		Excellent		
	IGILU0954	Electrical Switchboard	\$ 1964.00		20 01-01-1992 10 01-01-1992	2 -12.3 years	93.15% 17.12%	Excellent	Retain	N/A
	IGILU0954 IGILU0955	Electrical Switchboard Exterior painting	\$ 1964.00 \$ 2086.00		20 01-01-1992 10 01-01-1992	-12.3 years -22.3 years -12.3 years	93.15% 17.12%	Excellent Good Good	Retain Retain	N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956	Electrical Switchboard Exterior painting Fascias	\$ 1964.00 \$ 2086.00 \$ 2874.00		20 01-01-1992 10 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years	93.15% 17.12% 9.91%	Excellent Good Good Fair	Retain Retain Retain	N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957	Electrical Switchboard Exterior painting Fascias Flyscreens	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -12.3 years	93.15% 17.12% 9.91% 54.07% 27.03%	Excellent Good Good Fair	Retain Retain Retain Repair	N/A N/A N/A Lock is not worl
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76%	Excellent Good Good Fair Good Good	Retain Retain Retain Repair Retain Retain	N/A N/A N/A Lock is not worl N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02%	Excellent Good Good Fair Good Good Good	Retain Retain Retain Repair Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00		20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -1.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25%	Excellent Good Good Fair Good Good Good Good Good	Retain Retain Retain Repair Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not worl N/A N/A N/A N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00		20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71%	Excellent Good Good Fair Good Good Good Good Good	Retain Retain Retain Repair Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 1509.00 \$ 1998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -2.4 years -2.5 years -2.7 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A
t 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962 IGILU1578 Asset Number	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 1998.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 10 15-01-2010	-12.3 years -22.3 years -12.3 years -22.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.4 years -4.2 years -4.5 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition	Excellent Good Good Fair Good Good Good Good Good Good Good Excellent Asset Condition	Retain Retain Retain Repair Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A Lock is not wor N/A N/A N/A N/A N/A N/A N/A N/A Comments
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0960 IGILU0960 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$)	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992	-12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not wor N/A
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00 \$ 3475.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 50 01-01-1992 50 01-01-2010	-12.3 years -17.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.7.1% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Excellent Good Good Fair Good Good Good Good Good Excellent Asset Condition Good Good	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not wor N/A
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0960 IGILU0961 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0966	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1308.00 \$ 34873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 1709.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -17.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not wor N/A
it 27	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0959 IGILU0960 IGILU0961 IGILU0962 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System -	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00 \$ 3475.00 Acquisition Cost (\$) \$ 3069.00 \$ 1999.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 50 01-01-1992 50 01-01-2010	-12.3 years -17.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.7.1% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not wor N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0960 IGILU0961 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0966	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1308.00 \$ 34873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 1709.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -17.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05%	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not wor N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0960 IGILU0961 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0966 IGILU0966 IGILU0967	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00		20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 50 01-01-1992 50 01-01-1992 50 01-01-1992 51 01-01-1992	-12.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05% 12.77%	Excellent Good Good Fair Good Good Good Good Excellent Asset Condition Good Good Good Excellent	Retain Retain Retain Repair Retain Retain	N/A N/A N/A Lock is not wor N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0959 IGILU0959 IGILU0960 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0965 IGILU0967	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 5 01-01-1992 10 01-01-1992 11 01-01-1992	-12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -4.2 years -12.3 years -4.7 years -17.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05% 12.77% Accumulated Repair Cost as % of Acquisition	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not worl N/A
	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0958 IGILU0960 IGILU0961 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0966 IGILU0966 IGILU0967	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00		20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 5 01-01-1992 10 01-01-1992 11 01-01-1992	-12.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05% 12.77% Accumulated Repair Cost as % of Acquisition	Excellent Good Good Fair Good Good Good Good Excellent Asset Condition Good Good Good Excellent	Retain Retain Retain Repair Retain Retain	N/A N/A N/A Lock is not work N/A
nit 27 nit 28	IGILU0954 IGILU0955 IGILU0956 IGILU0957 IGILU0959 IGILU0959 IGILU0960 IGILU0961 IGILU0962 IGILU1578 Asset Number IGILU0964 IGILU0965 IGILU0965 IGILU0967	Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 3435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00		20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 5 01-01-1992 10 01-01-1992 11 01-01-1992	-12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -12.3 years	93.15% 17.12% 9.91% 54.07% 27.03% 3.76% 15.02% 2.25% 11.71% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 45.05% 12.77% Accumulated Repair Cost as % of Acquisition	Excellent Good Good Fair Good Good Good Good Good Good Good Goo	Retain Retain Retain Repair Retain	N/A N/A N/A Lock is not work N/A

IGILU1019

Sarking

Electric

Hot Water System -

\$ 3174.00

\$ 2386.00

25

12

01-01-1992 -7.3 years

01-01-1992 -20.3 years

30.64% Good

4.22% Excellent

Retain

Retain

N/A

N/A

Unit 27-28

ed 1	Asset Number GILU0988 GILU0989 GILU0991 GILU0992 Asset Number GILU0978 GILU0979 IGILU0980 IGILU0981 IGILU0982	Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Curtains Interior Painting Wardrobe	Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	Installation Date 10	-6.4 years	15.32%	Asset Condition Excellent Excellent Excellent	Retain Retain Retain	N/A N/A N/A N/A
	IGILU0988 IGILU0989 IGILU0991 IGILU0992 Asset Number IGILU0978 IGILU0979 IGILU0980 IGILU0981 IGILU0982	Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind Carpet Curtains Interior Painting	\$ 255.00 \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	10 01-11-2007 10 01-11-2007 10 01-11-2007 15 01-11-2007	-6.4 years -6.4 years -6.4 years	4.51% 15.32% 72.08%	Excellent Excellent Excellent	Retain Retain Retain	N/A N/A N/A
	IGILU0989 IGILU0991 IGILU0992 Asset Number IGILU0978 IGILU0979 IGILU0980 IGILU0981 IGILU0982	Interior Painting Skylight Tapware Asset Name Blind Carpet Curtains Interior Painting	\$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	10 01-11-2007 10 01-11-2007 15 01-11-2007	-6.4 years	15.32% 72.08%	Excellent Excellent	Retain Retain	N/A N/A
	IGILU0991 IGILU0992 Asset Number IGILU0978 IGILU0978 IGILU0980 IGILU0981 IGILU0982	Skylight Tapware Asset Name Blind Carpet Curtains Interior Painting	\$ 1010.00 \$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	01-11-2007 01-11-2007	-6.4 years	72.08%	Excellent	Retain	N/A
	Asset Number IGILU0978 IGILU0978 IGILU0980 IGILU0981 IGILU0982	Asset Name Blind Carpet Curtains Interior Painting	\$ 1304.00 Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)	01-11-2007	-				
	Asset Number IGILU0978 IGILU0979 IGILU0980 IGILU0981 IGILU0982	Asset Name Blind Carpet Curtains Interior Painting	Acquisition Cost (\$) \$ 333.00 \$ 1032.00 \$ 1776.00	Effective Life (Y)		1)			Retain	
	IGILU0978 IGILU0979 IGILU0980 IGILU0981 IGILU0982	Blind Carpet Curtains Interior Painting	\$ 333.00 \$ 1032.00 \$ 1776.00	1	Installation Date					
ed 2	IGILU0978 IGILU0979 IGILU0980 IGILU0981 IGILU0982	Blind Carpet Curtains Interior Painting	\$ 333.00 \$ 1032.00 \$ 1776.00	1		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
ed 2	IGILU0980 IGILU0981 IGILU0982	Curtains Interior Painting	\$ 1032.00 \$ 1776.00		10 01-11-2007			Excellent		N/A
ed 2	IGILU0980 IGILU0981 IGILU0982	Curtains Interior Painting	\$ 1776.00		8 01-11-2007	-8.4 years	16.90%	Good	Retain	N/A
ed 2	IGILU0981 IGILU0982	Interior Painting			6 01-11-2007		30.03%			N/A
ed 2		Wardrobe	\$ 888.00		10 01-11-2007	•	19.82%		Retain	N/A
ed 2			\$ 2053.00	1	10 01-11-2007	-6.4 years	36.04%	Excellent	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0983	Blind	\$ 333.00	1	10 01-11-2007	-6.4 years	7.21%	Excellent	Retain	N/A
	IGILU0984	Carpet	\$ 688.00		8 01-11-2007	-8.4 years	3.94%	Good	Retain	N/A
	IGILU0985	Curtains	\$ 1776.00		6 01-11-2007	-10.4 years	30.03%	Good	Retain	N/A
	IGILU0986	Interior Painting	\$ 588.00	1	10 01-11-2007		4.51%	Good	Retain	N/A
	IGILU0987	Wardrobe	\$ 2053.00	1	10 01-11-2007			Excellent	Retain	N/A
ining										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1000	Blind	\$ 388.00	1	10 01-11-2007	-6.4 years	27.06%	Excellent	Retain	N/A
	IGILU1001	Carpet	\$ 910.00		8 01-11-2007	-8.4 years	1.69%	Excellent	Retain	N/A
	IGILU1002	Interior Painting	\$ 832.00	1	10 01-11-2007	-6.4 years	8.11%	Excellent	Retain	N/A
tchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU0968	Blind	\$ 333.00	1	10 01-11-2007	-6.4 years	16.22%	Excellent	Retain	N/A
	IGILU0970	Cooktop	\$ 1354.00	1	12 01-11-2007	-4.4 years	13.52%	Good	Retain	N/A
	IGILU0971	Interior Painting	\$ 710.00	1	10 01-11-2007	-6.4 years	19.83%	Good	Retain	N/A
	IGILU0974	Electric Elevated	\$ 1409.00	1	12 01-11-2007	-4.4 years	67.60%	Good	Retain	N/A
		Oven								
	IGILU0975	Rangehood	\$ 599.00		12 01-11-2007	-	15.03%			N/A
	IGILU0976	Sink & Fittings	\$ 1587.00	1	15 01-11-2007	-1.4 years	114.14%	Good	Retain	N/A
ving				-44						_
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition		Comments
	IGILU0995	Blind	\$ 388.00		01-11-2007			Excellent		N/A
	IGILU0996 IGILU0997	Carpet	\$ 1165.00		8 01-11-2007 6 01-11-2007			Excellent Excellent		N/A
	IGILU0997	Curtains	\$ 1776.00 \$ 865.00		6 01-11-2007 15 01-11-2007			Excellent		N/A N/A
			\$ 1176.00			,		Excellent		N/A
nit Exterior	IGILU0999	Interior Painting	\$ 1176.00		10 01-11-2007	-6.4 years	27.04%	Excellent	Retain	IN/A
nit Exterior	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1003	Clothesline	\$ 499.00		10 01-01-1992		Accumulated Repair Cost as % of Acquisition 36.07%			N/A
		Ciotnesiine	\$ 499.00		30 01-01-1992					IN/A
		Courtward	¢ 2496 00							NI/A
	IGILU1004	Courtyard	\$ 2486.00				0.00%			N/A
	IGILU1004 IGILU1005	Doors	\$ 5605.00	3	30 01-01-1992	-2.3 years	7.51%	Good	Retain	N/A
	IGILU1004 IGILU1005 IGILU1006	Doors Downpipes	\$ 5605.00 \$ 1742.00	2	01-01-1992 0 01-01-1992	-2.3 years -12.3 years	7.51% 9.01%	Good	Retain Retain	N/A N/A
	IGILU1004 IGILU1005	Doors Downpipes Electrical	\$ 5605.00	2	30 01-01-1992	-2.3 years -12.3 years	7.51%	Good	Retain Retain	N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007	Doors Downpipes Electrical Switchboard	\$ 5605.00 \$ 1742.00 \$ 1964.00	2	30 01-01-1992 20 01-01-1992 20 01-01-1992	-2.3 years -12.3 years -12.3 years	7.51% 9.01% 68.37%	Good Good Good	Retain Retain Retain	N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007	Doors Downpipes Electrical Switchboard Exterior painting	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00	2	30 01-01-1992 20 01-01-1992 20 01-01-1992 10 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years	7.51% 9.01% 68.37% 18.02%	Good Good Good	Retain Retain Retain Retain	N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007	Doors Downpipes Electrical Switchboard	\$ 5605.00 \$ 1742.00 \$ 1964.00	2 2	30 01-01-1992 20 01-01-1992 20 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years	7.51% 9.01% 68.37% 18.02%	Good Good Good Good	Retain Retain Retain Retain Retain	N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009	Doors Downpipes Electrical Switchboard Exterior painting Fascias	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00	1 2 2 1	00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -22.3 years -12.3 years -22.3 years	7.51% 9.01% 68.37% 18.02% 9.91%	Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00	2 2 2 1 1 2 2	00 01-01-1992 20 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -12.3 years -12.3 years -12.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10%	Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010 IGILU1011	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00	2 2 2 3 1 1 2 2	00 01-01-1992 20 01-01-1992 20 01-01-1992 10 01-01-1992 20 01-01-1992 10 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79%	Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1009 IGILU1009 IGILU1011 IGILU1011	Doors Downpipes Electrical Switchboard Exercior painting Fascias Flyscreens Guttering Path	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00	2 2 1 2 2 3 3 3	00 01-01-1992 20 01-01-1992 20 01-01-1992 00 01-01-1992 20 01-01-1992 20 01-01-1992 20 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79% 0.45%	Good Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010 IGILU1011 IGILU1011 IGILU1012 IGILU1013 IGILU1014	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00	2 2 1 2 2 3 3 3 3 3 3	00 01-01-1992 00 01-01-1992 01 01-01-1992 10 01-01-1992 10 01-01-1992 10 01-01-1992 10 01-01-1992 10 01-01-1992 10 01-01-1992 10 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -12.3 years -12.3 years -2.3 years -2.3 years -2.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79% 0.45% 0.00%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010 IGILU1011 IGILU1011 IGILU1012 IGILU1013	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00	2 2 3 1 2 3 3 3 3	00 01-01-1992 00 01-01-1992 01 01-01-1992 01 01-01-1992 02 01-01-1992 03 01-01-1992 04 01-01-1992 05 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79% 0.45% 0.00% 4.51% 6.61%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010 IGILU1011 IGILU1011 IGILU1012 IGILU1013 IGILU1014 IGILU1015	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Patch Porch Lattice Screening Windows	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00	2 2 3 1 2 3 3 3 3	00 01-01-1992 00 01-01-1992 01 01-01-1992 01 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79% 0.45% 0.00% 4.51% 6.61%	Good Good Good Good Good Good Good Good	Retain	N/A
athroom	IGILU1004 IGILU1005 IGILU1006 IGILU1007 IGILU1008 IGILU1009 IGILU1010 IGILU1011 IGILU1011 IGILU1012 IGILU1013 IGILU1014 IGILU1015	Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Patch Porch Lattice Screening Windows	\$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00	2 2 3 1 2 3 3 3 3	00 01-01-1992 00 01-01-1992 01 01-01-1992 01 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992 00 01-01-1992	-2.3 years -12.3 years -12.3 years -22.3 years -12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years	7.51% 9.01% 68.37% 18.02% 9.91% 72.10% 33.79% 0.45% 0.00% 4.51% 6.61%	Good Good Good Good Good Good Good Good	Retain	N/A

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Li
	IGILU1040	Skylight	\$ 1010.00	

Installation Date Remaining Effective Life
0 01-07-2005 -8.8 years N/A 10 30.63% Excellent Retain Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
IGILU1028	Blind	\$ 333.00	10	01-07-2005	-8.8 years	15.32%	6 Excellent	Retain	N/A
IGILU1030	Curtains	\$ 1776.00	6	01-07-2005	-12.8 years	13.51%	6 Excellent	Retain	N/A

d 2										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1033	Blind	\$ 333.00		10 01-07-2005			Excellent	Retain	N/A
	IGILU1036	Wardrobe	\$ 2053.00		10 01-07-2005		16.22%		Retain	N/A
ning										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1050	Blind	\$ 388.00		10 01-07-2005	-8.8 years	4.51%	Good	Retain	N/A
tchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1023	Vinyl	\$ 1010.00		10 01-07-2005	-8.8 years	90.10%	Excellent	Retain	N/A
	IGILU1024	Oven	\$ 1409.00		12 01-07-2005	-6.8 years	18.78%	Excellent	Retain	N/A
	IGILU1025	Rangehood	\$ 599.00		12 01-07-2005	-6.8 years	1.88%	Excellent	Retain	N/A
	IGILU1026	Sink & Fittings	\$ 1587.00		15 01-07-2005	-3.8 years	120.14%	Excellent	Retain	N/A
ring										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1044	Air Conditioner -	\$ 3296.00		10 01-07-2005	-8.8 years	308.17%	Excellent	Retain	N/A
	IGILU1045	Split System Blind	\$ 388.00		10 01-07-2005	9.9 years	22 550	Excellent	Retain	N/A
	IGILU1047	Curtains	\$ 1776.00		6 01-07-2005		12.01%		Retain	N/A
	IGILU1048	Heater	\$ 865.00		15 01-07-2005			Excellent	Retain	N/A
nit Exterior	IGIE01040	rieatei	\$ 003.00		15 01-07-2003	-3.0 years	0.00%	LACEIIEIIC	Retaili	IN/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1054	Clothesline	\$ 499.00			2 -22.3 years	18.04%		Retain	N/A
	IGILU1055	Courtyard	\$ 2486.00		30 01-01-1992			Good	Retain	N/A
	IGILU1056	Doors	\$ 5605.00		30 01-01-1992	-		Good	Retain	N/A
	IGILU1057	Downpipes	\$ 1742.00		20 01-01-1992		22.53%	Good	Retain	N/A
	IGILU1058	Electrical	\$ 1964.00			-12.3 years	87.87%	Good	Retain	N/A
		Switchboard								
	IGILU1059	Exterior painting	\$ 2086.00		10 01-01-1992	2 -22.3 years	25.43%	Good	Retain	N/A
	IGILU1060	Fascias	\$ 2874.00		20 01-01-1992	-12.3 years	11.26%	Good	Retain	N/A
	IGILU1061	Flyscreens	\$ 2186.00			2 -22.3 years	32.44%	Good	Retain	N/A
	IGILU1062	Guttering	\$ 2819.00			-12.3 years	135.15%	Good	Retain	N/A
	IGILU1063	Path	\$ 1509.00		30 01-01-1992		6.01%	Excellent	Retain	N/A
	IGILU1064	Porch	\$ 2908.00		30 01-01-1992	2 -2.3 years	0.00%	Excellent	Retain	N/A
	IGILU1065	Lattice Screening	\$ 1098.00		20 01-01-1992	2 -12.3 years	7.21%	Excellent	Retain	N/A
	IGILU1066	Windows	\$ 3873.00		30 01-01-1992			Excellent	Retain	N/A
	IGILU1066 IGILU1580	-	\$ 3873.00 \$ 9435.00		30 01-01-1992 10 15-01-2010			Excellent Excellent	Retain Retain	
		Windows								N/A
.i+ 20		Windows								N/A
it 29	IGILU1580	Windows Awnings	\$ 9435.00		10 15-01-2010	-4.2 years	0.00%	Excellent	Retain	N/A N/A
it 29	IGILU1580 Asset Number	Windows Awnings Asset Name	\$ 9435.00 Acquisition Cost (\$)	Effective Life (Y)	10 15-01-2010	4.2 years Remaining Effective Life	0.00% Accumulated Repair Cost as % of Acquisition	Excellent Asset Condition	Retain	N/A N/A
nit 29	Asset Number	Windows Awnings Asset Name Insulation	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00	Effective Life (Y)	10 15-01-2010 Installation Date 20 01-01-1992	-4.2 years Remaining Effective Life -12.3 years	Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent	Retain Plan Retain	N/A N/A Comments N/A
it 29	Asset Number IGILU1068 IGILU1069	Windows Awnings Asset Name Insulation Lighting	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00	Effective Life (Y)	Installation Date 20 01-01-1992 15 01-01-1992	-4.2 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Excellent Excellent	Plan Retain Retain Retain	N/A N/A Comments N/A N/A
nit 29	Asset Number	Asset Name Insulation Lighting Sarking	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00	Effective Life (Y)	10 15-01-2010 Installation Date 20 01-01-1992 15 01-01-1992 25 01-01-1992	-4.2 years Remaining Effective Life -12.3 years -17.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Asset Condition Excellent Excellent	Retain Plan Retain	N/A N/A Comments N/A
it 29	Asset Number IGILU1068 IGILU1069 IGILU1070	Windows Awnings Asset Name Insulation Lighting	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	Installation Date 20 01-01-1992 15 01-01-1992 25 01-01-1992	Remaining Effective Life 12.3 years -17.3 years -7.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Asset Condition Excellent Excellent Excellent Good	Plan Retain Retain Retain Retain	N/A N/A Comments N/A N/A N/A
	Asset Number IGILU1068 IGILU1070 IGILU1071	Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00	Effective Life (Y)	Installation Date 20 01-01-1992 15 01-01-1992 25 01-01-1992	Remaining Effective Life -12.3 years -17.3 years -20.3 years	0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64%	Asset Condition Excellent Excellent Good Excellent	Plan Retain Retain Retain Retain Retain	N/A N/A Comments N/A N/A N/A N/A N/A N/A
	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	10 15-01-2010 Installation Date 20 01-01-1992 15 01-01-1992 25 01-01-1992 12 Installation Date	Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent Excellent Excellent Good Excellent Excellent	Plan Retain Retain Retain Retain Retain	N/A N/A Comments N/A N/A N/A N/A N/A Comments
	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1071	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00	Effective Life (Y) Effective Life (Y)	Installation Date 20	Remaining Effective Life 12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good	Plan Retain Retain Retain Retain Retain Retain Retain	Comments N/A
	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1117	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Sarking	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A Comments N/A
nit 29	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1071	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Asset Name Insulation Asset Name Hot Water System -	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00	Effective Life (Y) Effective Life (Y)	15-01-2010 15-01-2010 15-01-2010 15-01-2010 15-01-1992 15-01-01-01-1992 15-01-01-01-01-01-01-01-01-01-01-01-01-01-	Remaining Effective Life 12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% Accumulated Repair Cost as % of Acquisition 0.00%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A
	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1117	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Sarking	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A Comments N/A
nit 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1117	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Asset Name Insulation Asset Name Hot Water System -	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A
it 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3174.00 \$ 3369.00 \$ 3174.00 \$ 2386.00	Effective Life (Y) Effective Life (Y)	Installation Date 20 01-01-1992 15 01-01-1992 25 01-01-1992 26 01-01-1992 27 01-01-1992 28 01-01-1992	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -7.3 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77%	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good Good Good	Plan Retain	Comments N/A
it 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Sarking Hot Water System - Electric Asset Name Asset Name Asset Name	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years -20.3 years -12.3 years -20.3 years -20.3 years -20.3 years -20.3 years -7.3 years -7.3 years -7.4 years -7.5 years -7.6 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Plan Retain Retain Retain	N/A N/A
it 30	Asset Number IGILU1068 IGILU1070 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1089	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Sarking Hot Water System-Electric Asset Name Hot Water System-Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 2386.00	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years -12.3 years -12.9 years -12.9 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent Excellent Good Excellent Good Good Good Good Good Good Good Goo	Plan Retain	N/A
	Asset Number IGILU1088 IGILU1069 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1120	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Hot Water System - Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2366.00 \$ 466.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	15-01-2010 15-01-2010 15-01-2010 15-01-2010 15-01-2010 15-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-01-01-01-01-01-01-01-01-01-01-01-	Remaining Effective Life -12.3 years -17.3 years -20.3 years -12.3 years -12.9 years -12.9 years -20.9 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51%	Asset Condition Excellent Excellent Excellent Excellent Good Excellent Good Good Good Good Asset Condition Excellent	Plan Retain	N/A
iit 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1120	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Sarking Hot Water System-Electric Asset Name Electric Asset Name Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 \$ 466.00 \$ 466.00 \$ 1010.00	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -7.3 years -7.9 years -9.0 years -9.0 years -9.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06%	Asset Condition Excellent	Plan Retain	N/A N/A
it 30	Asset Number IGILU1088 IGILU1069 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1120	Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Insulation Lighting Sarking Hot Water System - Electric Asset Name Hot Water System - Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2366.00 \$ 466.00	Effective Life (Y) Effective Life (Y)	15-01-2010 15-01-2010 15-01-2010 15-01-2010 15-01-2010 15-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-1992 15-01-01-01-01-01-01-01-01-01-01-01-01-01-	Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -7.3 years -7.9 years -9.0 years -9.0 years -9.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06%	Asset Condition Excellent Excellent Excellent Excellent Good Excellent Good Good Good Good Asset Condition Excellent	Plan Retain	N/A
it 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1120	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Sarking Hot Water System-Electric Asset Name Electric Asset Name Electric	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 \$ 466.00 \$ 466.00 \$ 1010.00	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -7.3 years -20.3 years Remaining Effective Life -12.3 years -7.3 years -7.3 years -7.3 years -7.9 years -9.0 years -9.0 years -9.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06%	Asset Condition Excellent	Plan Retain	N/A N/A
it 30	Asset Number IGILU1068 IGILU1069 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU11090 IGILU1090 IGILU1090 IGILU1093	Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Sarking Hot Water System Electric Asset Name Exhaust Ian Interior Painting Skylight Tapware	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00 \$ 1304.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years Remaining Effective Life -9.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06% 120.14% Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent Excellent Good Excellent Asset Condition Good Good Good Good Excellent	Plan Retain	N/A N/A
iit 30	Asset Number IGILU1068 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1090 IGILU1092 IGILU1093 Asset Number	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Sarking Hot Water System-Electric Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1101.00 \$ 1304.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 20	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years Remaining Effective Life -9.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06% 120.14% Accumulated Repair Cost as % of Acquisition	Asset Condition Excellent Excellent Good Excellent Good Good Good Good Good Good Good Goo	Plan Retain	N/A N/A
iit 30	Asset Number IGILU1088 IGILU1069 IGILU1070 IGILU1071 Asset Number IGILU1117 IGILU1119 IGILU1120 Asset Number IGILU1089 IGILU1090 IGILU1092 IGILU1093 Asset Number IGILU1082	Asset Name Insulation Lighting Sarking Hot Water System-Electric Asset Name Insulation Insulation Sarking Hot Water System-Electric Asset Name Insulation Sarking Hot Water System-Electric Asset Name Exhaust Fan Interior Painting Skylight Tapware Asset Name Blind	\$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00 \$ 3369.00 \$ 3174.00 \$ 2386.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 255.00 \$ 466.00 \$ 1010.00 \$ 1304.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 20	Remaining Effective Life -12.3 years -17.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years Remaining Effective Life -12.3 years -20.3 years -20.9 years -9.0 years -9.0 years -9.0 years -4.0 years -4.0 years -11.0 years -11.0 years	Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 30.64% 30.04% Accumulated Repair Cost as % of Acquisition 0.00% 39.65% 18.77% Accumulated Repair Cost as % of Acquisition 2.71% 4.51% 54.06% 120.14% Accumulated Repair Cost as % of Acquisition 19.82% 12.39%	Asset Condition Excellent Excellent Excellent Good Excellent Good Good Good Good Asset Condition Excellent	Plan Retain	N/A N/A

Unit 29-30

Unit 29

Dining

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1101	Blind	\$ 388.00		10 01-04-2005	-9.0 years	7.22%	Good	Retain	N/A
	IGILU1103	Interior Painting	\$ 832.00		10 01-04-2005		A 51%	Excellent	Retain	N/A
IC . I.	131201103	interior rainting	ş 032.00	1	.0 01-04-2003	5.0 years	4.31%	Executions	rectain	1.40
Kitchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1072	Blind	\$ 333.00	,	10 01-04-2005	-9 O years		Excellent	Retain	N/A
		-								-
	IGILU1074	Cooktop	\$ 1354.00		12 01-04-2005	-7.0 years		Excellent	Retain	N/A
	IGILU1075	Interior Painting	\$ 710.00		10 01-04-2005	-9.0 years	19.83%	Excellent	Retain	N/A
	IGILU1077	Vinyl	\$ 1010.00		10 01-04-2005	-9 O years	85.59%	Good	Retain	N/A
	IGILU1078	Oven	\$ 1409.00		12 01-04-2005	-7.0 years	93.89%	Excellent	Retain	N/A
	IGILU1079	Rangehood	\$ 599.00		12 01-04-2005	-7.0 years	8.26%	Excellent	Retain	N/A
	IGILU1080	Sink & Fittings	\$ 1587.00		15 01-04-2005		90.11%	Excellent	Retain	N/A
	101201000	Sink & Fittings	\$ 1507.00		15 01 04 2003	4.0 years	50.11%	Excellent	rectain	14/15
Living										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1096	Air Conditioner -	\$ 3296.00		10 01-04-2005	-9.0 years	324 39%	Excellent	Retain	N/A
			, , , , , , , , , , , , , , , , , , , ,			,				
	1011111007	Split System	£ 300.00		10 01 04 2005	0.0	24.2007	Cd	Date!	NI/A
	IGILU1097	Blind	\$ 388.00		10 01-04-2005		34.28%			N/A
	IGILU1099	Heater	\$ 865.00	'	15 01-04-2005	-4.0 years	0.00%	Excellent	Retain	N/A
	IGILU1100	Interior Painting	\$ 1176.00		10 01-04-2005	-9.0 years	22 53%	Excellent	Retain	N/A
Half Francisco						1 ,			1.00	
Unit Exterior										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1104	Clothesline	\$ 499.00		10 01-01-1992	-22.3 years	22.55%	Good	Retain	N/A
	IGILU1105	Courtyard	\$ 2486.00				0.00%			N/A
	IGILU1106	Doors	\$ 5605.00		30 01-01-1992	-2.3 years	3.90%	Good	Retain	N/A
	IGILU1107	Downpipes	\$ 1742.00		20 01-01-1992	-12.3 years	19.83%	Good	Retain	N/A
	IGILU1108	Electrical	\$ 1964.00		20 01-01-1992		73.89%		Retain	N/A
	IGILOTTOO		\$ 1904.00	1	20 01-01-1992	- 12.3 years	13.03%	Good	Retaili	IN/A
		Switchboard								
	IGILU1109	Exterior painting	\$ 2086.00		10 01-01-1992	-22.3 years	2.25%	Good	Retain	N/A
	IGILU1110	Fascias	\$ 2874.00	:	20 01-01-1992	-12.3 years	9.91%	Good	Retain	N/A
	IGILU1111	Flyscreens	\$ 2186.00		10 01-01-1992	-22.3 years	72.10%	Good	Retain	N/A
										-
	IGILU1112	Guttering	\$ 2819.00		20 01-01-1992	-12.3 years	135.15%	Good	Retain	N/A
	IGILU1113	Path	\$ 1509.00	:	30 01-01-1992	-2.3 years	2.85%	Good	Retain	N/A
	IGILU1114	Porch	\$ 2908.00		30 01-01-1992	-2 3 years	37 5/1%	Excellent	Retain	N/A
						-				-
	IGILU1115	Lattice Screening	\$ 1098.00		20 01-01-1992	-12.3 years	7.66%	Good	Retain	N/A
	IGILU1116	Windows	\$ 3873.00	:	30 01-01-1992	-2.3 years	5.71%	Excellent	Retain	N/A
	IGII U1581	Awnings	\$ 9435.00		10 15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
	IGILU1581	Awnings	\$ 9435.00		10 15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
	IGILU1581	Awnings	\$ 9435.00	•	10 15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Bathroom	IGILU1581	Awnings	\$ 9435.00		10 15-01-2010	-4.2 years	0.00%	Good	Retain	N/A
Bathroom									'	
Bathroom	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
				Effective Life (Y)		Remaining Effective Life		Asset Condition	Plan	
Bathroom Bed 1	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	Asset Number	Asset Name	Acquisition Cost (\$) \$ 1010.00	Effective Life (Y)	Installation Date 10 01-10-2010	Remaining Effective Life -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04%	Asset Condition	Plan	Comments N/A
	Asset Number IGILU1142 Asset Number	Asset Name Skylight Asset Name	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date	Remaining Effective Life -3.5 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition	Plan Retain	Comments N/A Comments
	Asset Number IGILU1142 Asset Number IGILU1132	Asset Name Skylight Asset Name Curtains	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52%	Asset Condition Good Asset Condition Good	Plan Retain Plan Retain	Comments N/A Comments N/A
	Asset Number IGILU1142 Asset Number	Asset Name Skylight Asset Name	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52%	Asset Condition Good Asset Condition	Plan Retain Plan Retain	Comments N/A Comments
	Asset Number IGILU1142 Asset Number IGILU1132	Asset Name Skylight Asset Name Curtains	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00	Effective Life (Y) Effective Life (Y)	Installation Date	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52%	Asset Condition Good Asset Condition Good	Plan Retain Plan Retain	Comments N/A Comments N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134	Asset Name Skylight Asset Name Curtains Wardrobe	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00	Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43%	Asset Condition Good Asset Condition Good Excellent	Plan Retain Plan Retain Retain Retain	Comments N/A Comments N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition	Plan Retain Plan Retain Retain Retain	Comments N/A Comments N/A N/A Comments
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 10 10 10 10 10 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent	Plan Retain Plan Retain Retain Retain Plan Retain	Comments N/A Comments N/A N/A Comments N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51%	Asset Condition Good Asset Condition Good Excellent Asset Condition	Plan Retain Plan Retain Retain Retain	Comments N/A Comments N/A N/A Comments
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 10 10 10 10 10 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent	Plan Retain Plan Retain Retain Retain Plan Retain	Comments N/A Comments N/A N/A Comments N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 0	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent	Plan Retain Plan Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years Remaining Effective Life Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Asset Condition	Plan Retain Plan Retain Retain Retain Retain Plan Retain Retain Retain	Comments N/A Comments N/A N/A N/A N/A Comments N/A N/A Comments
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00	Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 0	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years Remaining Effective Life Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent	Plan Retain Plan Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A N/A N/A N/A N/A N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Courtains Courtains Courtains Countains Countains Countains	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 10 10 10 10 10 10 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Asset Condition	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Plan Retain	Comments N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Courtains Curtains Curtains Electric Elevated	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Asset Condition Excellent	Plan Retain Plan Retain Retain Retain Retain Plan Retain Retain Retain	Comments N/A Comments N/A N/A N/A N/A Comments N/A N/A Comments
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1138 Asset Number IGILU1122 IGILU1126	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Contains Contains Cooktop Electric Elevated Oven	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2053.00 \$ 2053.00 \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 1776.00 \$ 1000 \$	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 13 01-10-2010 14 01-10-2010 15 01-10-2010 15 01-10-2010 15 01-10-2010 15 01-10-2010 16 01-10-2010 17	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -7.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1138 Asset Number IGILU1122 IGILU1126	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Contains Contains Cooktop Electric Elevated Oven	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 2053.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 \$ 1409.00 \$ 1409.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -7.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A Comments N/A N/A
Bed 1	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 1776.00 \$ 1000 \$	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 12 01-10-2010 13 01-10-2010 14 01-10-2010 15 01-10-2010 15 01-10-2010 15 01-10-2010 15 01-10-2010 16 01-10-2010 17	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -7.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1409.00 \$ 1587.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 15 01-10-2010 15 01-10-2010 16 01-10-2010 17 01-10-2010 18 01-10-2010 19	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1127 IGILU1128 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Courtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner -	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1409.00 \$ 1587.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 15 01-10-2010 15 01-10-2010 16 01-10-2010 17 01-10-2010 18 01-10-2010 19	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System	Acquisition Cost (\$) \$ 1010.00 Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 3296.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 6 01-10-2010 10 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 15 01-10-2010 Installation Date Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 10 01-10-201	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years 1.5 years Remaining Effective Life -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent	Plan Retain Plan Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Courtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner -	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years 1.5 years Remaining Effective Life -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1146 IGILU1147	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 388.00 \$ 388.00 \$ 388.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% 17.14%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent	Plan Retain Plan Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain Retain	Comments N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 388.00 \$ 588.00 \$ 588.00 \$ 588.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% 17.14% 15.32%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain	Comments N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1146 IGILU1147	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 388.00 \$ 388.00 \$ 388.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% 17.14%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain	Comments N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 3296.00 \$ 388.00 \$ 588.00 \$ 588.00 \$ 588.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% 17.14% 15.32%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1122 IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1147 IGILU1149 IGILU1149 IGILU1150	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1010.00 \$ 1776.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 1587.00 \$ 3296.00 \$ 588.00 \$ 1776.00	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 81.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% 17.14% 15.32% 16.52%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain Plan Retain	Comments N/A N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149 IGILU1150 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan Curtains Asset Name	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1076.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years -1.5 years -3.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years -7.5 years -7.5 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 15.52% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Asset Condition Excellent Excellent Excellent Excellent Asset Condition Excellent Asset Condition	Plan Retain Plan Retain	Comments N/A N/A N/A Comments
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1127 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149 IGILU1150 Asset Number IGILU1150	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan Curtains Asset Name Clothesline	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 388.00 \$ 588.00 \$ 1776.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date Installation Date Installation Date 6 01-10-2010 Installation Date 6 01-10-2010 Installation Date 6 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 15 01-10-2010 Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 Installation Date Install	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years -1.5 years -3.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -7.5 years Remaining Effective Life -22.3 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% Accumulated Repair Cost as % of Acquisition 4.15.03% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 13.54% Accumulated Repair Cost as % of Acquisition 35.17% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Good Good Asset Condition Good	Plan Retain Plan Retain Retain Plan Retain	Comments N/A
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1126 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149 IGILU1150 Asset Number	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan Curtains Asset Name	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 1076.00 \$ 2053.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date 10	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years -1.5 years -3.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -7.5 years Remaining Effective Life -22.3 years	Accumulated Repair Cost as % of Acquisition 36.04% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% Accumulated Repair Cost as % of Acquisition 4.15.03% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 13.54% Accumulated Repair Cost as % of Acquisition 35.17% Accumulated Repair Cost as % of Acquisition	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Asset Condition Excellent Excellent Excellent Excellent Asset Condition Excellent Asset Condition	Plan Retain Plan Retain	Comments N/A N/A N/A Comments
Bed 2 Kitchen	Asset Number IGILU1142 Asset Number IGILU1132 IGILU1134 Asset Number IGILU1136 IGILU1138 Asset Number IGILU1127 IGILU1127 IGILU1128 Asset Number IGILU1146 IGILU1147 IGILU1149 IGILU1150 Asset Number IGILU1150	Asset Name Skylight Asset Name Curtains Wardrobe Asset Name Curtains Wardrobe Asset Name Cooktop Electric Elevated Oven Rangehood Sink & Fittings Asset Name Air Conditioner - Solit System Blind Ceiling Fan Curtains Asset Name Clothesline	Acquisition Cost (\$) Acquisition Cost (\$) \$ 1010.00 \$ 2053.00 Acquisition Cost (\$) \$ 1354.00 \$ 1409.00 \$ 1587.00 Acquisition Cost (\$) \$ 388.00 \$ 588.00 \$ 1776.00 Acquisition Cost (\$)	Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y) Effective Life (Y)	Installation Date Installation Date Installation Date 6 01-10-2010 Installation Date 6 01-10-2010 Installation Date 6 01-10-2010 Installation Date 12 01-10-2010 12 01-10-2010 12 01-10-2010 15 01-10-2010 Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 Installation Date 10 01-10-2010 Installation Date Install	Remaining Effective Life -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -7.5 years -3.5 years Remaining Effective Life -1.5 years -1.5 years -1.5 years -1.5 years Remaining Effective Life -3.5 years -3.5 years -3.5 years -3.5 years -3.5 years -7.5 years -3.2 years -3.3 years -3.3 years -3.3 years -3.3 years -3.3 years -3.3 years	Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 22.52% 45.43% Accumulated Repair Cost as % of Acquisition 13.51% 10.81% Accumulated Repair Cost as % of Acquisition 18.77% 67.60% 15.03% 120.14% Accumulated Repair Cost as % of Acquisition 113.54% Accumulated Repair Cost as % of Acquisition 113.54% 17.14% 15.32% 16.52% Accumulated Repair Cost as % of Acquisition 35.17% 0.00%	Asset Condition Good Asset Condition Good Excellent Asset Condition Excellent Asset Condition Excellent Excellent Excellent Excellent Excellent Excellent Good Good Asset Condition Good	Plan Retain Plan Retain Retain Plan Retain	Comments N/A

Installation Date Remaining Effective Life

Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

Asset Number Asset Name

Unit 30

Acquisition Cost (\$) Effective Life (Y)

Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217 IGILU1218 IGILU1219 IGILU1220 IGILU1221 IGILU1222 IGILU1222 IGILU1223 IGILU1224 IGILU1584 IGILU1584 Asset Number	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2286.00 \$ 2819.00 \$ 1998.00 \$ 1998.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$)	Effective Life (V)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1 20 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1	992 -26.3 years 992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.42 43.99 110.55 27.06 3.14	% Good **Asset Condition** Good Good Good Good Good Good Good Good ** Good ** **Excellent Excellent Excellent Excellent Excellent Excellent Excellent August Excellent Excellent August Excellent Excellent August Excellent Excellent Excellent August Excellent Excellent Excellent Excellent Excellent August Excellent Excellent Excellent Excellent Excellent August Excellent Excellent Excellent Excellent	Retain Retain Plan Retain	N/A
	Asset Number GILU1212 GILU1213 GILU1214 GILU1215 GILU1216 GILU1217 GILU1218 GILU1219 GILU1220 GILU1221 GILU1221 GILU1222 GILU1223 GILU1224	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2819.00 \$ 2819.00 \$ 1998.00 \$ 3873.00	Effective Life (V)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1	P92 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.42 43.99 110.55 27.06 3.14	Masset Condition Asset Condition Good Good Good Good Good Good Good Sood Good Sood Sexellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number GILU1212 GILU1213 GILU1214 GILU1215 GILU1216 GILU1217 GILU1218 GILU1219 GILU1220 GILU1221 GILU1221 GILU1222 GILU1223 GILU1224	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2819.00 \$ 2819.00 \$ 1998.00 \$ 3873.00	Effective Life (V)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1	P92 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.42 43.99 110.55 27.06 3.14	Masset Condition Asset Condition Good Good Good Good Good Good Good Sood Good Sood Sexellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number GILU1212 GILU1213 GILU1214 GILU1215 GILU1216 GILU1217 GILU1218 GILU1219 GILU1220 GILU1221 GILU1221 GILU1222 GILU1223 GILU1224	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2819.00 \$ 2819.00 \$ 1998.00 \$ 3873.00	Effective Life (V)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1	P92 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.42 43.99 110.55 27.06 3.14	Masset Condition Asset Condition Good Good Good Good Good Good Good Sood Good Sood Sexellent Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number GILU1212 GILU1213 GILU1214 GILU1215 GILU1216 GILU1217 GILU1218 GILU1219 GILU1220 GILU1220 GILU1221 GILU1222 GILU1223	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Parth Porch Lattice Screening	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2899.00 \$ 15199.00 \$ 1998.00 \$ 1998.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1 20 01-01-1 20 01-01-1 30 01-01-1 20 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -2.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -12.3 years 992 -12.3 years 992 -2.3 years 992 -2.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.44 43.93 110.55 27.00 3.16	Asset Condition Asset Condition Good Good Good Good Good Good Cood Good Excellent Excellent Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217 IGILU1217 IGILU1218 IGILU1219 IGILU1220 IGILU1220 IGILU1221	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 219.00 \$ 299.00 \$ 299.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1 30 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -12.3 years 992 -12.3 years 992 -2.3 years 992 -2.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.44 6.3° 90.12 18.00 7.66 14.44 43.99 110.55 27.00	Asset Condition Asset Condition Good Good Good Good Good Good Cood Good Excellent Excellent Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number GILU1212 GILU1213 GILU1214 GILU1215 GILU1215 GILU1216 GILU1217 GILU1218 GILU1219 GILU1220 GILU1221	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2874.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00 \$ 2186.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 30 01-01-1 30 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -2.3 years 992 -2.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3° 0.00 2.40 6.3° 90.12 18.02 7.66 14.42 43.99 110.58	Asset Condition Asset Condition Good Good Good Good Good Good Cood Good Cood Good Excellent Excellent	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217 IGILU1217 IGILU1218 IGILU1219 IGILU1220	Asset Name Clothesline Courtyard Doors Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2286.00 \$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 2819.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 20 01-01-1 20 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -23.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -12.3 years 992 -12.3 years 992 -12.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.44 6.3' 90.12 18.03 7.66 14.44 43.93	Asset Condition Asset Condition Good Good Good Good Good Good Good Cood Good Cood Co	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217 IGILU1218 IGILU1219	Asset Name Clothesline Courtyard Doors Doors Downpipes Electrical Switchboard Exterior painting Fascias Flyscreens	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 22874.00 \$ 2186.00 \$ 2186.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1 10 01-01-1 20 01-01-1 10 01-01-1 10 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years 992 -22.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.44 6.3' 90.12 18.00 7.66 14.44	Sood Asset Condition Good Good Good Good Good Good Good Good Cood Good Cood Good Good Good Good Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217 IGILU1218	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting Fascias	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 1742.00 \$ 1964.00 \$ 2086.00 \$ 2486.00 \$ 2486.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-2 20 01-01-1 10 01-01-1 20 01-01-2	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -2.3 years 992 -12.3 years 992 -2.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.4(6.3' 90.12 18.00 7.66	Sood Asset Condition Good	Plan Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216 IGILU1217	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard Exterior painting	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00 \$ 2086.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1 10 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years 992 -2.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.44 6.3' 90.12	Asset Condition Asset Condition Good Good Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A N/A N/A N/
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215 IGILU1216	Asset Name Clothesline Courtyard Doors Downpipes Electrical Switchboard	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00 \$ 1964.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 20 01-01-1 20 01-01-1	17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -2.3 years 992 -12.3 years 992 -12.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.40 6.3' 90.12	% Good Asset Condition Good Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215	Asset Name Clothesline Courtyard Doors Downpipes Electrical	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 30 01-01-1 20 01-01-1	992 -17.3 years Remaining Effective Life 992 -2.3 years 992 -2.3 years 992 -2.3 years 992 -12.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.4(6.3'	Asset Condition Good Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214 IGILU1215	Asset Name Clothesline Courtyard Doors Downpipes	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00 \$ 1742.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1 30 01-01-1 20 01-01-1	992 -17.3 years Remaining Effective Life 992 -2.3 years 992 -2.3 years 992 -2.3 years 992 -12.3 years	0.00 Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.4(6.3'	Asset Condition Good Good Good Good Good Good Good	Plan Retain Retain Retain Retain Retain Retain	N/A Comments N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU1212 IGILU1213 IGILU1214	Asset Name Clothesline Courtyard Doors	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00 \$ 5605.00	Effective Life (Y)	Installation Date 10 01-01-1 30 01-01-1 30 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years 992 -2.3 years	Accumulated Repair Cost as % of Acquisition 6.3' 0.00 2.40	Asset Condition Good Good Good Good	Plan Retain Retain Retain Retain	Comments N/A N/A N/A N/A
Unit Exterior	Asset Number IGILU1212 IGILU1213	Asset Name Clothesline Courtyard	\$ 865.00 Acquisition Cost (\$) \$ 499.00 \$ 2486.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1 30 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years 992 -2.3 years	Accumulated Repair Cost as % of Acquisition 6.3	% Good Asset Condition % Good Good	Plan Retain Retain	N/A Comments N/A N/A
Unit Exterior	Asset Number	Asset Name Clothesline	\$ 865.00 Acquisition Cost (\$) \$ 499.00	Effective Life (Y)	15 01-01-1 Installation Date 10 01-01-1	992 -17.3 years Remaining Effective Life 992 -22.3 years	Accumulated Repair Cost as % of Acquisition 6.3	% Good Asset Condition % Good	Retain Plan Retain	N/A Comments N/A
Unit Exterior	Asset Number	Asset Name	\$ 865.00 Acquisition Cost (\$)	Effective Life (Y)	15 01-01-1 Installation Date	992 -17.3 years Remaining Effective Life	0.00 Accumulated Repair Cost as % of Acquisition	% Good Asset Condition	Retain	N/A Comments
Unit Exterior			\$ 865.00		15 01-01-1	992 -17.3 years	0.00	% Good	Retain	N/A
II. to France		Heater				•				
	IGILU1206					•				
	IGILU1205	Curtains	€ 1776 OC			000 000		0/ 5 1		21/4
	1011111205	Split System	\$ 1776.00							
	IGILU1201	Air Conditioner -	\$ 3296.00	, <u> </u>	10 01-01-1	992 -22.3 years	56.77	% Excellent	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Living										
	IGILU1183	Smoke Alarms	\$ 260.00	j .	20 01-01-1	992 -12.3 years	18.08	% Excellent	Retain	N/A
<u>-</u>	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Kitchen										
	IGILU1191	Curtains	\$ 1776.00		6 01-01-1	992 -26.3 years		% Good	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bed 2										
	IGILU1186	Curtains	\$ 1776.00			992 -26.3 years		% Good	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bed 1		1 6 6	¥ 15 10.00	1	3.011	··)	1330.			· · · ·
	IGILU1197	Skylight	\$ 1010.00			992 -22.3 years		% Excellent	Retain	N/A
Datinooni	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Bathroom										
		Electric	1							
	IGILU1228	Hot Water System -	\$ 2386.00	1	12 01-01-1	992 -20.3 years	28.53	% Good	Retain	N/A
	IGILU1227	Sarking	\$ 3174.00			992 -7.3 years		% Good	Retain	N/A
	IGILU1225	Insulation	\$ 3069.00			992 -12.3 years		% Good	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Unit 32										
		Electric								
	IGILU1173	Hot Water System -	\$ 2386.00	1		992 -20.3 years	22.53	% Good	Retain	N/A
	IGILU1172	Sarking	\$ 3174.00)	25 01-01-1	992 -7.3 years	70.28	% Good	Retain	N/A
	IGILU1170	Insulation	\$ 3069.00			992 -12.3 years		% Good	Retain	N/A
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Unit 31										
		· ······g-	, , , , , , , , , , , , , , , , , , , ,			,,				
	IGILU1583	Awnings	\$ 9435.00			010 -4.2 years		% Good	Retain	N/A
	IGILU1168	Windows	\$ 3873.00			992 -2.3 years		% Good	Retain	N/A
	IGILU1167	Lattice Screening	\$ 1098.00			992 -12.3 years		% Good % Good	Retain	N/A
	IGILU1165 IGILU1166	Path Porch	\$ 1509.00 \$ 2908.00			992 -2.3 years 992 -2.3 years		% Good % Good	Retain Retain	N/A N/A
	IGILU1164	Guttering	\$ 2819.00 \$ 1509.00			992 -12.3 years		% Good % Good	Retain	N/A
	IGILU1163	Flyscreens	\$ 2186.00			992 -22.3 years		% Good	Retain	N/A
	IGILU1162	Fascias	\$ 2874.00			992 -12.3 years		% Good	Retain	N/A

IGILU1160

IGILU1161

Unit 31-32

Unit 31

Unit 32

Bed 1

Downpipes

Switchboard Exterior painting

Electrical

\$ 1742.00

\$ 1964.00

\$ 2086.00

20

20

10

01-01-1992 -12.3 years

01-01-1992 -12.3 years

01-01-1992 -22.3 years

22.53% Good

6.76% Good

0.00% Good

Retain

Retain

Retain

N/A

N/A

		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
March Marc							•				
Accordance Acc	Livina	IGIEG 1241	Curtains	\$ 1770.00		0 010420	11.0 years	30.	0370 G000	rectairi	IV/A
March Marc	Living	A 1 M I	A M	A (A)	F(f - 1 - 1 - 1 - 00	Land Harden Barta	B	A	Accet Condition	DI	
March											
Mark Hamber											
Accordance Acc		IGILU1260	Heater	\$ 865.00		15 01-04-20	07 -2.0 years	0.	00% Good	Retain	N/A
Part 1985 Controlled 14890 15 10 10 12 23 years 14800 10 10 10 10 10 10 10	Unit Exterior										
CALUSSIS Color SAME		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
		IGILU1265	Clothesline	\$ 499.00		10 01-01-19	92 -22.3 years	4.	51% Good	Retain	N/A
Descriptor Descriptor Statistical Descriptor Descr		IGILU1266	Courtyard	\$ 2486.00		30 01-01-19	92 -2.3 years	0.	00% Good	Retain	N/A
Descriptor Descriptor Statistical Descriptor Descr		IGILU1267	Doors	\$ 5605.00		30 01-01-19	92 -2.3 years	7.	51% Good	Retain	N/A
							· ·				
Column C		101201203		¥ 150 1.00		20 01 01 13	sz izis yeurs		5770 COOG	riciani	147.1
		IGILU1270		\$ 2086.00		10 01-01-19	92 -22.3 years	7.	66% Good	Retain	N/A
			-								
GUL1774 Delta 1.00 1.0											
GULT/12 Part 1 1980 20 01 1978 2 2 years 6.001 Cool Recan MA MA MA MA MA MA MA M							· ·				
Figure F			-								
							· ·				
Part											
Asset Number Asse		IGILU1585	Awnings	\$ 9435.00		10 15-01-20	110 -4.2 years	0.	00% Good	Retain	N/A
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accommunated Repair Cost as % of Acquisition Asset Condition Plan Comments											
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accommunated Repair Cost as % of Acquisition Asset Condition Plan Comments											
Columbia	Unit 39										
CRILLIP29		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Fig. Fig. Fig. Fig. Fig. Fig. Fig. Fi									00% Good		
Comments											
Dectric Comments											
Mase Number		IGILO 1202		\$ 2300.00		12 01-01-13	132 -20.3 years	13.	52 /8 G000	Retaili	IV/A
Asset Number Asset Name Acquisition Cost (5) Effective Life (7) Installation Date Remaining Effective Life (7) Installation Date Remaining Effective Life (8) Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments	Unit 40		Electric				1				
		Accet Number	Accet Name	Acquisition Cost (\$)	Effective Life (V)	Installation Date	Pamaining Effective Life	Accumulated Popair Cost as % of Acquisition	Asset Condition	Dlan	Comments
					Lifective Life (1)						
GILU1327 Sarking Sar											
Sathwork											
Bathroom See Number Asset Name Collul 300 Slykight S 1010.00 10 01-06-2004 -88 years 14.42% Good Retain N/A			-				· ·				
Rase Number		IGILU1328		\$ 2386.00		12 01-01-19	192 -20.3 years	2.	25% Good	Retain	N/A
Asset Number Asset Name Acquisition Cost (S) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Asset Condition N/A			Electric								
Asset Number Asset Name Acquisition Cost (S) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Asset Condition N/A	D. (1										
	Bathroom										
Asset Number Asset Number Asset Number Asset Number GIULU922 Smoke Alarms S 260,00 20 O1-06-2004 O2 years 9.94% Good Retain N/A		IGILU1300	Skylight	\$ 1010.00		10 01-06-20	04 -9.8 years	14.	42% Good	Retain	N/A
	Kitchen										
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments		IGILU1292	Smoke Alarms	\$ 260.00		20 01-06-20	0.2 years	9.	94% Good	Retain	N/A
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments	Living										
GILUT304		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
Solit System Face									88% Good		
GILU1307 Heater \$865.00 15 01-06-2004 4.8 years 0.00% Good Retain N/A				, , , , , , , , , , , , , , , , , , , ,							'
Name Asset Number Asset Number Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments		IGILU1307		\$ 865.00		15 01-06-20	04 -4.8 years	0.	00% Good	Retain	N/A
Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments	Unit Exterior										
IGILU1312 Clothesline \$ 499.00 10 01-01-1992 -22.3 years 1623% Good Retain N/A IGILU1313 Courtyard \$ 2486.00 30 01-01-1992 -2.3 years 0.00% Good Retain N/A IGILU1314 Doors \$ 5605.00 30 01-01-1992 -2.3 years 7.51% Good Retain N/A IGILU1315 Downpipes \$ 1742.00 20 01-01-1992 -12.3 years 36.05% Good Retain N/A IGILU1316 Electrical \$ 1964.00 20 01-01-1992 -12.3 years 56.33% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -22.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -12.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -22.3 years 18.02% Good Retain N/A IGILU1321 Path \$ 5000 30 01-01-1992 -23.3 years 128.40% Good Retain N/A IGILU1322 Porch \$ 298.00 30 01-01-1992 -23.3 years 23.9 years 3.00% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 3.00%		Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (V)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
IGILU1313 Courtyard \$ 2486.00 30 01-01-1992 -2.3 years 0.00% Good Retain N/A IGILU1314 Doors \$ 5605.00 30 01-01-1992 -2.3 years 7.51% Good Retain N/A IGILU1315 Downpipes \$ 1742.00 20 01-01-1992 -12.3 years 36.05% Good Retain N/A IGILU1316 Electrical \$ 1964.00 20 01-01-1992 -12.3 years 56.33% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -22.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -22.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -22.3 years 18.02% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -23.3 years 128.0% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -23.3 years 128.0% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 18.02% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -											
IGILU1314 Doors \$ 5605.00 30 01-01-1992 2.3 years 7.51% Good Retain N/A IGILU1315 Downpipes \$ 1742.00 20 01-01-1992 -12.3 years 36.05% Good Retain N/A IGILU1316 Electrical \$ 1964.00 20 01-01-1992 -12.3 years 56.33% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -22.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -22.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -22.3 years 18.02% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -12.3 years 12.840% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 12.840% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A											
IGILU1315 Downpipes \$ 1742.00 20 01-01-1992 -12.3 years 36.05% Good Retain N/A IGILU1316 Electrical \$ 1964.00 20 01-01-1992 -12.3 years 56.33% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -22.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -22.3 years 18.00% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -22.3 years 18.00% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -23.3 years 128.40% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -23.3 years 128.00% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -23.3 years 60.06% Good Retain N/A											
IGILU1316 Electrical \$ 1964.00 20 01-01-1992 -12.3 years 56.33% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -22.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -12.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -12.3 years 18.02% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -12.3 years 128.40% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 128.40% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1325 Retain Retai							· ·				
Switchboard Switchboard Center or painting \$ 2086.00 10 01-01-1992 -2.3 years 11.27% Good Retain N/A IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -12.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -22.3 years 4486 Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -12.3 years 128.04% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 270% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A							· ·				
IGILU1317 Exterior painting \$ 2086.00 10 01-01-1992 -2.3 years 11.27% Good Retain N/A IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -1.2 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -2.3 years 44.86% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -2.3 years 128.40% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 2.70% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1325 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1328 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1328 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1328 Windows Win		IGILU1316		\$ 1964.00		20 01-01-19	92 -12.3 years	56.	33% Good	Retain	N/A
IGILU1318 Fascias \$ 2874.00 20 01-01-1992 -12.3 years 18.02% Good Retain N/A IGILU1319 Flyscreens \$ 2186.00 10 01-01-1992 -2.3 years 44.86% Good Retain N/A IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -12.3 years 128.40% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 2.70% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1325 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1326 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1327 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1328 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1328 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1329 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A IGILU1329 Windows Wi											
Flyscreens \$2186.00 10 01-01-1992 -2.3 years 44.86% Good Retain N/A GILU1320 Guttering \$2819.00 20 01-01-1992 -12.3 years 128.40% Good Retain N/A GILU1321 Path \$1509.00 30 01-01-1992 -2.3 years 2.70% Good Retain N/A GILU1322 Porch \$2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1324 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1325 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows \$3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A GILU1326 Windows Windows Windows Windows Wind											
IGILU1320 Guttering \$ 2819.00 20 01-01-1992 -12.3 years 128.40% Good Retain N/A IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 2.70% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A											
IGILU1321 Path \$ 1509.00 30 01-01-1992 -2.3 years 2.70% Good Retain N/A IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A											
IGILU1322 Porch \$ 2908.00 30 01-01-1992 -2.3 years 60.06% Good Retain N/A IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A		IGILU1320	Guttering	\$ 2819.00		20 01-01-19	92 -12.3 years	128.	40% Good	Retain	N/A
IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A		IGILU1321	Path	\$ 1509.00		30 01-01-19	92 -2.3 years	2.	70% Good	Retain	N/A
IGILU1324 Windows \$ 3873.00 30 01-01-1992 -2.3 years 4.81% Good Retain N/A		IGILU1322	Porch	\$ 2908.00		30 01-01-19	92 -2.3 years	60.	06% Good	Retain	N/A
			Windows				· ·			Retain	N/A
1000 0000 1000 1000											
			J 3"		1		1 7		1,111	1	

Unit 39-40

Unit 39

	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Commen
	IGILU1343	Exhaust Fan	\$ 255.00		10 01-12-2012		Accumulated Repair Cost as % of Acquisition 6.31%		Retain	N/A
	IGILU1344	Interior Painting	\$ 466.00		10 01-12-2012		10.82%		Retain	N/A
	IGILU1346	-					3.60%			
	IGILU 1346	Skylight	\$ 1010.00		10 01-12-2012	-1.3 years	3.60%	Good	Retain	N/A
ed 1	Accet Name has	Acces Name	Association Cost (6)	reference Life (M)	Installation Date	Damaining Effective Life	Assumulated Banair Cost on 9/ of Assuriation	Asset Condition	Plan	Commen
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition			
	IGILU1338 IGILU1339	Blind	\$ 333.00		10 01-12-2012		36.04%		Retain	N/A
		Carpet	\$ 1032.00		8 01-12-2012 6 01-12-2012	-	7.32%		Retain	N/A
	IGILU1340	Curtains	\$ 1776.00				6.01%		Retain	N/A
	IGILU1341	Interior Painting	\$ 888.00		10 01-12-2012		9.01%		Retain	N/A
	IGILU1342	Wardrobe	\$ 2053.00		10 01-12-2012	-1.3 years	15.32%	Good	Retain	N/A
ning										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Commer
	IGILU1356	Blind	\$ 388.00		10 01-12-2012		36.08%		Retain	N/A
	IGILU1358	Interior Painting	\$ 832.00		10 01-12-2012	-1.3 years	16.23%	Good	Retain	N/A
chen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Commer
	IGILU1330	Cooktop	\$ 1354.00		12 01-12-2012	0.7 years	18.77%	Good	Retain	N/A
	IGILU1331	Interior Painting	\$ 710.00		10 01-12-2012	-1.3 years	36.06%	Good	Retain	N/A
	IGILU1333	Vinyl	\$ 1010.00		10 01-12-2012		85.59%		Retain	N/A
	IGILU1334	Oven	\$ 1409.00		12 01-12-2012		150.22%		Retain	N/A
	IGILU1335	Rangehood	\$ 599.00		12 01-12-2012		9.39%		Retain	N/A
ng	101201333	rangenood	\$ 333.00		01 12 2012	o.i years	3.3370	0000	riccani	1.477
ng .	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comme
	IGILU1350	Air Conditioner -	\$ 3296.00		10 01-12-2012		178.42%		Retain	N/A
	IGILO 1330	Split System	\$ 3250.00		01-12-2012	- 1.5 years	170.42.6	Good	Retaili	IN/A
	IGILU1351	Blind	\$ 388.00		10 01-12-2012	-1.3 years	1.80%	Good	Retain	N/A
	IGILU1353	Curtains	\$ 1776.00		6 01-12-2012	-	13.51%		Retain	N/A
	IGILU1355	Interior Painting	\$ 1176.00		10 01-12-2012		0.00%		Retain	N/A
it Exterior	101201333	interior rainting	\$ 1170.00		01 12 2012	1.5 years	0.0070	GOOG	recuiii	14/75
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Commer
	IGILU1359	Clothesline	\$ 499.00		10 01-01-1992		4.51%		Retain	N/A
	IGILU1360	Courtyard	\$ 2486.00		30 01-01-1992		0.00%		Retain	N/A
	IGILU1361	Doors	\$ 5605.00		30 01-01-1992		0.90%		Retain	N/A
	IGILU1362	Downpipes	\$ 1742.00		20 01-01-1992		9.01%		Retain	N/A
	IGILU1363	Electrical					72.31%		Retain	N/A
	IGILU 1363	Electrical	\$ 1964.00		20 01-01-1992	-12.3 years	72.31%	Good	Ketain	IN/A
	IGII I 1364	Switchboard	\$ 2086.00		10 01-01-1992	-22 3 years	9.56%	Good	Retain	NI/A
	IGILU1364	Switchboard Exterior painting	\$ 2086.00		10 01-01-1992		8.56%		Retain	N/A
	IGILU1365	Switchboard Exterior painting Fascias	\$ 2874.00		20 01-01-1992	-12.3 years	0.00%	Good	Retain	N/A
	IGILU1365 IGILU1366	Switchboard Exterior painting Fascias Flyscreens	\$ 2874.00 \$ 2186.00		20 01-01-1992 10 01-01-1992	-12.3 years -22.3 years	0.00% 72.10%	Good Good	Retain Retain	N/A N/A
	IGILU1365 IGILU1366 IGILU1367	Switchboard Exterior painting Fascias Flyscreens Guttering	\$ 2874.00 \$ 2186.00 \$ 2819.00		20 01-01-1992 10 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years	0.00% 72.10% 47.30%	Good Good Good	Retain Retain Retain	N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368	Switchboard Exterior painting Fascias Flyscreens Guttering Path	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20%	Good Good Good	Retain Retain Retain Retain	N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51%	Good Good Good Good	Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66%	Good Good Good Good Good	Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A
: 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A
: 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00		20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A
: 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370 IGILU1371 IGILU1588	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 10 15-01-2010	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -12.3 years -2.4 years -2.5 years -2.9 years -2.9 years -2.9 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00%	Good Good Good Good Good Good Good Good	Retain Retain Retain Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A N/A N/A
ŧ 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1399 IGILU1370 IGILU1371 IGILU1588	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1998.00 \$ 3873.00 \$ 9435.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 10 15-01-2010	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.4 years -2.9 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A N/A N/A N/A N/A N/A N/A N/A N/A Comme
t 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$)	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 5 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Good Good Good Good Good Good	Retain Petain Retain Retain	N/A
t 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1373 IGILU1374 IGILU1375	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 25 01-01-1992 26 01-01-1992 27 01-01-1992 28 01-01-1992 29 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -12.3 years -12.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
t 41	IGILU1365 IGILU1366 IGILU1367 IGILU1367 IGILU1369 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1373	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 5 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -12.3 years -12.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1373 IGILU1374 IGILU1375	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 25 01-01-1992 26 01-01-1992 27 01-01-1992 28 01-01-1992 29 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -12.3 years -12.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1369 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1373 IGILU1374 IGILU1375	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2998.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 1909.00 \$ 3174.00	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 25 01-01-1992 26 01-01-1992 27 01-01-1992 28 01-01-1992 29 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -12.3 years -12.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% 32.44%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1370 IGILU1371 IGILU1371 IGILU13731 IGILU1373 IGILU1373 IGILU1373 IGILU1374 IGILU1375 IGILU1376	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 2908.00 \$ 1098.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3174.00 \$ 2386.00 Acquisition Cost (\$)	Effective Life (Y)	20 01-01-1992 10 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 10 15-01-2010 Installation Date 20 01-01-1992 25 01-01-1992 26 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -2.4 years -2.4 years -12.5 years -12.7 years -17.3 years -17.4 years -17.5 years -17.6 years -17.7 years -17.8 years -17.9 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 24.03% 32.44% 30.04% Accumulated Repair Cost as % of Acquisition	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1374 IGILU1375 IGILU1376 Asset Number IGILU1376	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$)	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 50 01-01-1992 51 01-01-1992 52 01-01-1992 52 01-01-1992 53 01-01-1992 54 01-01-1992 55 01-01-1992 56 01-01-1992 57 01-01-1992 58 01-01-1992 59 01-01-1992 50 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -12.3 years -12.4 years -12.9 years -12.9 years -12.9 years -12.9 years -12.9 years -12.9 years -12.3 years -13.3 years -13.3 years -14.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 24.03% 32.44% 30.04% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Good Good Good Good Good Good	Retain	N/A
t 41	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1370 IGILU1371 IGILU1371 IGILU1373 IGILU1373 IGILU1373 IGILU1374 IGILU1375 IGILU1376 Asset Number IGILU1376 IGILU1423 IGILU1423	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name Insulation Lighting Lighting	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1930.00 \$ 1998.00 \$ 1998.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) Acquisition Cost (\$) Acquisition Cost (\$) \$ 3069.00 \$ 199.00 \$ 3174.00 \$ 2386.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1999.00 \$ 1999.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -2.3 years -2.3 years -2.4 years -2.5 years -2.5 years -2.6 years -2.7 years -2.8 years -2.9 years -2.9 years -2.9 years -2.9 years -2.1 years -1.7 years -1.7 years -2.9 years -1.7 years -1.7 years -1.7 years -1.7 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 0.00% 24.03% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Good Good Good Good Good Good	Retain	N/A
	IGILU1365 IGILU1366 IGILU1367 IGILU1368 IGILU1370 IGILU1371 IGILU1588 Asset Number IGILU1373 IGILU1374 IGILU1375 IGILU1376 Asset Number IGILU1376	Switchboard Exterior painting Fascias Flyscreens Guttering Path Porch Lattice Screening Windows Awnings Asset Name Insulation Lighting Sarking Hot Water System Electric Asset Name	\$ 2874.00 \$ 2186.00 \$ 2819.00 \$ 1509.00 \$ 1509.00 \$ 1908.00 \$ 3873.00 \$ 9435.00 Acquisition Cost (\$) \$ 3069.00 \$ 3174.00 \$ 2386.00 \$ 1909.00 \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 3174.00 \$ 3174.00	Effective Life (Y)	20 01-01-1992 20 01-01-1992 20 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 30 01-01-1992 50 01-01-1992 51 01-01-1992 52 01-01-1992 52 01-01-1992 53 01-01-1992 54 01-01-1992 55 01-01-1992 56 01-01-1992 57 01-01-1992 58 01-01-1992 59 01-01-1992 50 01-01-1992	-12.3 years -22.3 years -12.3 years -2.3 years -2.3 years -12.3 years -17.3 years	0.00% 72.10% 47.30% 1.20% 7.51% 7.66% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 24.03% 32.44% 30.04% Accumulated Repair Cost as % of Acquisition 0.00%	Good Good Good Good Good Good Good Good	Retain	N/A

Bathroom

Accat Number Accat Name Acquisition Cost (\$) Effective Life (V) Installation D

Unit 41-42

Unit 41

Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Comments

| GILU1395 | Exhaust Fan | \$255.00 | 10 | 01-01-1992 | -2.3 years | 36.08% | Good | Retain | N/A

	IGILU1397	Toilet & Cistern	\$ 1343.00		20 01-01-	1992 -12.3 years		% Good	Retain	N/A
	IGILU1398	Skylight	\$ 1010.00		10 01-01-	1992 -22.3 years	14.429	% Good	Retain	N/A
	IGILU1399	Tapware	\$ 1304.00		15 01-01-	1992 -17.3 years	66.08	% Good	Retain	N/A
	IGILU1400	Tiles - Wall	\$ 3285.00			1992 -12.3 years		% Good	Retain	N/A
	IGILU1401	Tiles - Floor	\$ 4884.00			1992 -12.3 years		% Good	Retain	N/A
Bed 1	101201401	.1103 11001	ş 4004.00	1	20 01-01-	1552 12.5 years	0.90		rectum	1.4/15
Deu i	A 1 NI I	A 1 M	A 1-111 C1 (A)	F((- 1' 1' (- 00	Land Harton Barto	D	A	Asset Condition	pl	C
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition		Plan	Comments
	IGILU1387	Blind	\$ 333.00			1992 -22.3 years		% Good	Retain	N/A
	IGILU1390	Wardrobe	\$ 2053.00)	10 01-01-	1992 -22.3 years	9.919	% Good	Retain	N/A
Bed 2										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1391	Blind	\$ 333.00		10 01-01-	1992 -22.3 years	36.04	% Good	Retain	N/A
	IGILU1394	Wardrobe	\$ 2053.00			1992 -22.3 years	27.03	% Good	Retain	N/A
Dining						,,		1		'
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1407	Blind	\$ 388.00			1992 -22.3 years	·	% Good	Retain	N/A
V:4.ala.a.a	IGILU 1407	BIIIIU	\$ 500.00	'	10 01-01-	1992 -22.3 years	11./3	76 G000	Retairi	IN/A
Kitchen										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1377	Blind	\$ 333.00)	10 01-01-	1992 -22.3 years	9.91	% Good	Retain	N/A
	IGILU1378	Benchtops	\$ 2342.00			1992 -12.3 years	4.96	% Good	Retain	N/A
	IGILU1379	Cooktop	\$ 1354.00		12 01-01-	1992 -20.3 years	12.01	% Good	Retain	N/A
	IGILU1381	Kitchen Cabinets	\$ 3818.00		20 01-01-	1992 -12.3 years	18.029	% Good	Retain	N/A
	IGILU1383	Electric Elevated	\$ 1409.00		12 01-01-	1992 -20.3 years	11.279	% Good	Retain	N/A
		Oven								
	IGILU1384	Rangehood	\$ 599.00		12 01-01-	1992 -20.3 years	14.65	% Good	Retain	N/A
	IGILU1385	Sink & Fittings	\$ 1587.00		15 01-01-	1992 -17.3 years	33.04	% Good	Retain	N/A
	IGILU1386	Smoke Alarms	\$ 260.00		20 01-01-	1992 -12.3 years	18.08	% Good	Retain	N/A
Living	1414444		, , , , , , , , , , , , , , , , , , , ,			,			1.444	1.4
Living	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1403	Blind	\$ 388.00			1992 -22.3 years		% Good	Retain	N/A
Hara Francis		BIIIIU	\$ 500.00	'	10 01-01-	1992 -22.5 years	3.02	76 G000	Retairi	IN/A
Unit Exterio										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1410	Clothesline	\$ 499.00			1992 -22.3 years		% Good	Retain	N/A
	IGILU1411	Courtyard	\$ 2486.00)	30 01-01-	1992 -2.3 years	0.009	% Good	Retain	N/A
	IGILU1412	Doors	\$ 5605.00)	30 01-01-	1992 -2.3 years	6.619	% Good	Retain	N/A
	IGILU1413	Downpipes	\$ 1742.00)	20 01-01-	1992 -12.3 years	36.05	% Good	Retain	N/A
	IGILU1414	Electrical	\$ 1964.00		20 01-01-	1992 -12.3 years	93.15	% Good	Retain	N/A
		Switchboard								
	IGILU1415	Exterior painting	\$ 2086.00		10 01-01-	1992 -22.3 years	3.60	% Good	Retain	N/A
	IGILU1416	Fascias	\$ 2874.00		20 01-01-	1992 -12.3 years	17.57	% Good	Retain	N/A
	IGILU1417	Flyscreens	\$ 2186.00		10 01-01-	1992 -22.3 years	70.29	% Good	Retain	N/A
	IGILU1418	Guttering	\$ 2819.00			1992 -12.3 years	74.339	% Good	Retain	N/A
	IGILU1419	Path	\$ 1509.00			1992 -2.3 years		% Good	Retain	N/A
	IGILU1420	Porch	\$ 2908.00			1992 -2.3 years		% Good	Retain	N/A
	IGILU1421	Lattice Screening	\$ 1098.00			1992 -12.3 years		% Good	Retain	N/A
	IGILU1422	Windows	\$ 3873.00			1992 -2.3 years		% Good	Retain	N/A
	IGILU1589	Awnings	\$ 9435.00		10 15-01-	2010 -4.2 years	0.009	% Good	Retain	N/A
Bathroom										
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1447	Exhaust Fan	\$ 255.00		10 01-09-	2013 -0.6 years	36.08	% Good	Retain	N/A
	IGILU1448	Interior Painting	\$ 466.00			2013 -0.6 years	19.83	% Good	Retain	N/A
	IGILU1450	Skylight	\$ 1010.00			2013 -0.6 years		% Good	Retain	N/A
Bed 1		l 3 3	\$ 1010.00	1		/	45.05	.,	1	1 4
				Effective Life (Y)	Installation Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Commonts
	Accet Number	Accet Name				Remaining Effective Life				Comments
	Asset Number	Asset Name	Acquisition Cost (\$)			0012 0.6		V CI		
	IGILU1437	Blind	\$ 333.00)	10 01-09-	2013 -0.6 years		% Good	Retain	N/A
	IGILU1437 IGILU1438	Blind Carpet	\$ 333.00 \$ 1032.00		10 01-09- 8 01-09-	2013 -2.6 years	16.90	% Good	Retain	N/A
	IGILU1437 IGILU1438 IGILU1439	Blind Carpet Curtains	\$ 333.00 \$ 1032.00 \$ 1776.00		10 01-09- 8 01-09- 6 01-09-	2013 -2.6 years 2013 -4.6 years	16.90 ⁴ 18.77 ⁴	% Good % Good		N/A N/A
	IGILU1437 IGILU1438	Blind Carpet	\$ 333.00 \$ 1032.00		10 01-09- 8 01-09- 6 01-09- 10 01-09-	2013 -2.6 years	16.90 ⁴ 18.77 ⁴	% Good	Retain	N/A N/A N/A
	IGILU1437 IGILU1438 IGILU1439	Blind Carpet Curtains	\$ 333.00 \$ 1032.00 \$ 1776.00		10 01-09- 8 01-09- 6 01-09- 10 01-09-	2013 -2.6 years 2013 -4.6 years	16.90' 18.77' 36.04'	% Good % Good	Retain Retain	N/A N/A
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440	Blind Carpet Curtains Interior Painting	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00		10 01-09- 8 01-09- 6 01-09- 10 01-09-	2013 -2.6 years 2013 -4.6 years 2013 -0.6 years	16.90' 18.77' 36.04'	% Good % Good % Good	Retain Retain Retain	N/A N/A N/A
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440	Blind Carpet Curtains Interior Painting	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00		10 01-09- 8 01-09- 6 01-09- 10 01-09-	2013 -2.6 years 2013 -4.6 years 2013 -0.6 years	16.90' 18.77' 36.04'	% Good % Good % Good	Retain Retain Retain	N/A N/A N/A
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440 IGILU1441	Blind Carpet Curtains Interior Painting Wardrobe	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00	Effective Life (Y)	10 01-09- 8 01-09- 6 01-09- 10 01-09- 10 01-09- Installation Date	2013 - 2.6 years 2013 - 4.6 years 2013 - 0.6 years 2013 - 0.6 years	16.90' 18.77' 36.04' 36.04' Accumulated Repair Cost as % of Acquisition	% Good % Good % Good % Good	Retain Retain Retain Retain	N/A N/A N/A N/A
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440 IGILU1441 Asset Number IGILU1442	Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-09- 8 01-09- 6 01-09- 10 01-09- 10 01-09- Installation Date 10 01-09-	2013 - 2.6 years 2013 - 4.6 years 2013 - 0.6 years 2013 - 0.6 years Remaining Effective Life 2013 - 0.6 years	16.90 18.77 36.04 36.04 Accumulated Repair Cost as % of Acquisition 36.04	% Good % Good % Good % Good Masset Condition % Good	Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A N/A N/A N/A
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440 IGILU1441	Blind Carpet Curtains Interior Painting Wardrobe Asset Name	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00	Effective Life (Y)	10 01-09- 8 01-09- 6 01-09- 10 01-09- 10 01-09- Installation Date 10 01-09-	2013 - 2.6 years 2013 - 4.6 years 2013 - 0.6 years 2013 - 0.6 years Remaining Effective Life	16.90 18.77 36.04 36.04 Accumulated Repair Cost as % of Acquisition 36.04	% Good % Good % Good % Good Asset Condition	Retain Retain Retain Retain	N/A N/A N/A N/A N/A N/A There are scuff and di
Bed 2	IGILU1437 IGILU1438 IGILU1439 IGILU1440 IGILU1441 Asset Number IGILU1442	Blind Carpet Curtains Interior Painting Wardrobe Asset Name Blind	\$ 333.00 \$ 1032.00 \$ 1776.00 \$ 888.00 \$ 2053.00 Acquisition Cost (\$)	Effective Life (Y)	10 01-09- 8 01-09- 6 01-09- 10 01-09- 10 01-09- Installation Date 10 01-09-	2013 - 2.6 years 2013 - 4.6 years 2013 - 0.6 years 2013 - 0.6 years Remaining Effective Life 2013 - 0.6 years	16.90 18.77 36.04 36.04 Accumulated Repair Cost as % of Acquisition 36.04	% Good % Good % Good % Good Masset Condition % Good	Retain Retain Retain Retain Plan Retain	N/A N/A N/A N/A Comments

	IGILU1444	Curtains	\$ 1776.00		6	01-09-2013	-4.6 years	9.0	1% Good	Retain	N/A
	IGILU1445	Interior Painting	\$ 588.00		10	01-09-2013	-0.6 years	34.2	5% Good	Retain	N/A
	IGILU1446	Wardrobe	\$ 2053.00		10	01-09-2013	-0.6 years	2.7	0% Good	Retain	N/A
Dining							'	<u>'</u>			
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation	Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1460	Blind	\$ 388.00		10	01-09-2013	-0.6 years	27.0	5% Good	Retain	N/A
	IGILU1461	Carpet	\$ 910.00		8	01-09-2013	-2.6 years	22.5	3% Good	Retain	N/A
	IGILU1462	Curtains	\$ 1776.00		6	01-09-2013	-4.6 years	2.2	5% Good	Retain	N/A
	IGILU1463	Interior Painting	\$ 832.00		10	01-09-2013	-0.6 years	10.8	2% Good	Retain	N/A
Kitchen											
	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation	Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1429	Curtains	\$ 444.00		6	01-09-2013	-4.6 years	0.0	0% Good	Retain	N/A
	IGILU1430	Interior Painting	\$ 710.00		10	01-09-2013	-0.6 years	17.1	3% Good	Retain	N/A
	IGILU1432	Vinyl	\$ 1010.00		10	01-09-2013	-0.6 years	24.7	3% Good	Retain	N/A
	IGILU1433	Electric Elevated	\$ 1409.00		12	01-09-2013	1.4 years	112.6	7% Good	Retain	N/A
		Oven									
Living											
	Asset Number	Asset Name		Effective Life (Y)	Installation		Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1454	Air Conditioner -	\$ 3296.00		10	01-09-2013	-0.6 years	105.4	3% Good	Retain	N/A
	IGILU1455	Split System Blind	\$ 388.00		10	01-09-2013	0.6 years	24.2	3% Good	Retain	N/A
	IGILU1456	Carpet	\$ 1165.00			01-09-2013	,		3% Good	Retain	N/A
	IGILU1457	Curtains	\$ 1776.00		-	01-09-2013	,		3% Good	Retain	N/A
	IGILU1459	Interior Painting	\$ 1176.00			01-09-2013			5% Good	Retain	N/A
Unit Exterior	IGIEO 1433	interior rainting	\$1170.00		10	01 03 2013	o.o years	J-1.2	370 G000	rectain	IV/A
Ome Exterior	Asset Number	Asset Name	Acquisition Cost (\$)	Effective Life (Y)	Installation	Date	Remaining Effective Life	Accumulated Repair Cost as % of Acquisition	Asset Condition	Plan	Comments
	IGILU1464	Clothesline	\$ 499.00			01-01-1992		··	1% Good	Retain	N/A
	IGILU1465	Courtyard	\$ 2486.00			01-01-1992	,		0% Good	Retain	N/A
	IGILU1466	Doors	\$ 5605.00			01-01-1992	,		1% Good	Retain	N/A
	IGILU1467	Downpipes	\$ 1742.00			01-01-1992	,		1% Good	Retain	N/A
	IGILU1468	Electrical	\$ 1964.00			01-01-1992			9% Good	Retain	N/A
		Switchboard	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							1.00	.,,
	IGILU1469	Exterior painting	\$ 2086.00		10	01-01-1992	-22.3 years	5.4	1% Good	Retain	N/A
	IGILU1470	Fascias	\$ 2874.00		20	01-01-1992	-12.3 years	7.6	5% Good	Retain	N/A
	IGILU1471	Flyscreens	\$ 2186.00		10	01-01-1992	-22.3 years	21.6	3% Fair	Repair	The back flyscreen door
											is not closina properly
	IGILU1472	Guttering	\$ 2819.00			01-01-1992			5% Good	Retain	N/A
	IGILU1473	Path	\$ 1509.00			01-01-1992	,		5% Good	Retain	N/A
	IGILU1474	Porch	\$ 2908.00			01-01-1992	,		1% Good	Retain	N/A
	IGILU1475	Lattice Screening	\$ 1098.00		20	01-01-1992	-12.3 years	18.0	3% Good	Retain	N/A

IGILU1590

Windows

Awnings

\$ 3873.00

\$ 9435.00

30

10

01-01-1992 -2.3 years

15-01-2010 -4.2 years

N/A

N/A

Retain

Retain

1.50% Good

0.00% Good