

Assets Register - Kelso

Common

Garage A-F

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1477	Roof	Good				15984		50/01/01/1992	100	
IGILU1624	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Garage G-M

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1484	Roof	Good				15984		50/01/01/1992	100	

Grounds

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01548	Irrigation System	Good				27750		20/01/01/1989		
IGILU1498	Distribution Board	Good				1454		20/01/01/1992	100	
IGILU1499	Drainage	Good				0		50/01/01/1992	20	Aged Care
IGILU1500	Fencing	Good				2553		20/01/01/1992	20	Aged Care
IGILU1501	Gas Meter	Good				1526		15/01/01/1992	20	Aged Care
IGILU1502	Kerb & Gutter	Good				105450		50/01/01/1992	20	Aged Care
IGILU1503	Letterboxes	Good				6660		30/01/01/1992	100	
IGILU1504	Lighting Bollards	Good				6593		15/01/01/1992	100	
IGILU1505	Power Supply	Good				2308		40/01/01/1992	20	Aged Care
IGILU1506	Roads	Good				404595		25/01/01/1992	20	Aged Care
IGILU1507	Sewer	Good				0		80/01/01/1992	20	Aged Care
IGILU1508	Signage	Fair				555		7/01/01/1992	20	Aged Care
IGILU1509	Street Lighting	Good				6143		15/01/01/1992	20	Aged Care
IGILU1510	Telephone/Comms Services	Good				0		40/01/01/1992	20	Aged Care
IGILU1511	Water Mains	Good				0		80/01/01/1992	20	Aged Care
IGILU1512	Hydrants	Good				333		30/01/01/1992	20	Aged Care

Community Hall

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1533	Interior Painting	Good				1110		10/01/01/1992		
IGILU1534	Exhaust Fan	Good				277		10/01/01/1992		
IGILU1535	Tapware	Good				1304		15/01/01/1992		
IGILU1536	Tiles - Wall	Good				3285		20/01/01/1992		
IGILU1537	Toilet & Cistern	Good				1343		20/01/01/1992		
IGILU1844	Vinyl	Good				1010		10/13/12/2023		

Building Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1556	Path	Good				1509		30/01/01/1992		
IGILU1557	Exterior Painting	Good				2086		10/01/01/1992		
IGILU1558	Doors	Good				5605		30/01/01/1992		
IGILU1559	Porch	Good				2908		30/01/01/1992		
IGILU1560	Downpipes	Good				1742		20/01/01/1992		
IGILU1561	Fascias	Good				2874		20/01/01/1992		
IGILU1562	Guttering	Good				2819		20/01/01/1992		
IGILU1564	Electrical Switchboard	Good				1964		20/01/01/1992		
IGILU1565	Windows	Good				3873		30/01/01/1992		

Community Hall

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1538	Air Conditioner - Split System	Good	Daikin			2608		10/01/01/1992		
IGILU1539	Roof	Good				13320		50/01/01/1992		
IGILU1540	Interior Painting	Fair				6438		10/01/01/1992		
IGILU1541	Insulation	Good				3069		20/01/01/1992		
IGILU1542	Carpet	Good				3174		8/01/01/1992		
IGILU1543	Smoke Alarms	Good				277		20/01/01/1992		

IGILU1544	Sarking	Good					2941		25/01/1992		
IGILU1545	Lighting	Good					1665		15/01/1992		
IGILU1845	Air Conditioner - Split System	Good					1563		10/01/1992		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1546	Dishwasher	Good	Dishlex			1332		8/01/1992		
IGILU1547	Smoke Alarms	Good				260		20/01/1992		
IGILU1548	Benchtops	Good				2342		20/01/1992		
IGILU1549	Interior Painting	Good				710		10/01/1992		
IGILU1551	Kitchen Cabinets	Good				3818		20/01/1992		
IGILU1552	Oven	Good	Westinghouse			1409		12/01/1992		
IGILU1553	Sink & Fittings	Good				1587		15/01/1992		
IGILU1554	Blind	Good				333		10/01/1992		
IGILU1555	Vinyl	Good				1665		10/01/1992		
IGILU1846	Cooktop	Good				1354		12/01/1992		
IGILU1847	Rangehood	Good				599		12/01/1992		

Garage A-F

Garage A

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1478	Electric Roller Door	Good				3108		10/01/1992	100	

Garage B

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1479	Electric Roller Door	Good				3108		10/01/1992	100	

Garage C

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1480	Electric Roller Door	Good				3108		10/01/1992	100	

Garage D

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1481	Electric Roller Door	Good				3108		10/01/1992	100	

Garage E

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1482	Electric Roller Door	Good				3108		10/01/1992	100	

Garage F

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1483	Electric Roller Door	Good				3108		10/01/1992	100	

Garage G-M

Garage G

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1485	Electric Roller Door	Good				3108		10/01/1992	100	

Garage H

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1486	Electric Roller Door	Good				3108		10/01/1992	100	

Garage J

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1487	Electric Roller Door	Good				3108		10/01/1992	100	

Garage K

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1488	Electric Roller Door	Good				3108		10/01/1992	100	

Garage L

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1489	Electric Roller Door	Good				3108		10/01/1992	100	

Garage M

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1490	Electric Roller Door	Good				3108		10/01/1992	100	

Garage N-5

Garage N

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1492	Electric Roller Door	Good				3108		10/01/1992	100	

Garage N-5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1491	Roof	Good				15984		50/01/01/1992	100	
Garage O										
Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1493	Electric Roller Door	Good				3108		10/01/01/1992	100	
Garage P										
Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1494	Electric Roller Door	Good				3108		10/01/01/1992	100	
Garage Q										
Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1495	Electric Roller Door	Good				3108		10/01/01/1992	100	
Garage R										
Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1496	Electric Roller Door	Good				3108		10/01/01/1992	100	
Garage S										
Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1497	Electric Roller Door	Good				3108		10/01/01/1992	100	

Unit 1-2

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0001	Roof	Good				13320		50/01/01/1992	100	
IGILU0002a	Driveway	Good				21978		25/01/07/1982	100	

Unit 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002	Insulation	Good				3069		20/01/01/1992	100	
IGILU0003	Lighting	Good				1909		15/01/01/1992	100	
IGILU0004	Sarking	Good				3174		25/01/01/1992	100	
IGILU0005	Hot Water System - Electric	Good	Dux Proflo	160F1-36	6300993561	2386		12/01/01/1992	100	

Unit 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0054	Insulation	Good				3069		20/01/01/1992	100	
IGILU0055	Lighting	Good				1909		15/01/01/1992	100	
IGILU0056	Sarking	Good				3174		25/01/01/1992	100	
IGILU0057	Hot Water System - Electric	Good	Thermann	160THM136	15090930091H	2386		12/01/01/1992	100	

Unit 1

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0024	Exhaust Fan	Excellent				255		10/01/04/2006	100	
IGILU0025	Interior Painting	Good				466		10/01/04/2006	100	
IGILU0026	Skylight	Good				1010		10/01/04/2006	100	
IGILU0027	Tapware	Excellent				1304		15/01/04/2006	100	
IGILU0028	Tiles - Wall	Excellent				3285		20/01/04/2006	100	
IGILU0029	Tiles - Floor	Excellent				4884		20/01/04/2006	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0016	Blind	Good				333		10/01/04/2006	100	
IGILU0017	Carpet	Good				1032		8/01/01/2013	100	
IGILU0018	Interior Painting	Fair				888		10/01/04/2006	100	
IGILU0019	Wardrobe	Good				2053		10/01/04/2006	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0020	Blind	Good				333		10/01/04/2006	100	
IGILU0021	Carpet	Good				688		8/01/01/2013	100	
IGILU0022	Interior Painting	Good				588		10/01/04/2006	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0038	Blind	Good				388		10/01/04/2006	100	
IGILU0039	Carpet	Excellent				910		8/01/01/2013	100	

IGILU0040	Interior Painting	Good					832	10/01/04/2006	100	
-----------	-------------------	------	--	--	--	--	-----	---------------	-----	--

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0006	Blind	Good				333		10/01/04/2006	100	
IGILU0007	Benchtops	Good				2342		20/01/04/2006	100	
IGILU0009	Interior Painting	Fair				710		10/01/04/2006	100	
IGILU0010	Kitchen Cabinets	Good				3818		20/01/04/2006	100	
IGILU0011	Vinyl	Good				1010		10/01/04/2006	100	
IGILU0013	Rangehood	Good	Westinghouse			599		12/01/04/2006	100	
IGILU0014	Sink & Fittings	Good				1587		15/01/04/2006	100	
IGILU1595	Dishwasher	Good	Bosch	SMS46KI01A/69	260110299190006800	1332		8/20/10/2022	100	
IGILU1813	Electric Elevated Oven	Good	Westinghouse			1409		12/12/12/2023		
IGILU1848	Cooktop	Good	Westinghouse			1409		12/12/12/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0034	Blind	Good				388		10/01/04/2006	100	
IGILU0035	Carpet	Good				1165		8/01/01/2013	100	
IGILU0036	Heater	Good	IXL			865		15/01/04/2006	100	
IGILU0037	Interior Painting	Good				1176		10/01/04/2006	100	
IGILU01565	Smoke Alarms	Good				260		20/01/11/2012		
IGILU1623	Air Conditioner - Split System	Good				1563		10/06/07/2023	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0030	Tiles - Floor	Good				1076		20/01/04/2006	100	
IGILU0031	Toilet & Cistern	Good				1343		20/01/04/2006	100	
IGILU0032	Interior Painting	Good				166		10/01/04/2006	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0042	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0043	Doors	Good				5605		30/01/01/1992	100	
IGILU0044	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0045	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0046	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0047	Fascias	Good				2874		20/01/01/1992	100	
IGILU0048	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0049	Guttering	Good				2819		20/01/01/1992	100	
IGILU0050	Path	Good				1509		30/01/01/1992	100	
IGILU0051	Porch	Good				2908		30/01/01/1992	100	
IGILU0052	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0053	Windows	Good				3873		30/01/01/1992	100	
IGILU1566	Awnings	Good				9435		10/15/01/2010		

Unit 2

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0075	Exhaust Fan	Good				255		10/01/01/1992	100	
IGILU0076	Interior Painting	Good				466		10/01/01/1992	100	
IGILU0077	Skylight	Good				1010		10/01/01/1992	100	
IGILU0078	Tapware	Good				1304		15/01/01/1992	100	
IGILU0079	Tiles - Wall	Good				3285		20/01/01/1992	100	
IGILU0080	Tiles - Floor	Good				4884		20/01/01/1992	100	
IGILU01540	Sink & Fittings	Good				1587		15/01/05/2015		

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0067	Blind	Good				333		10/01/01/1992	100	
IGILU0068	Carpet	Good				1032		8/01/01/1992	100	
IGILU0069	Interior Painting	Good				888		10/01/01/1992	100	
IGILU0070	Wardrobe	Good				2053		10/01/01/1992	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0071	Blind	Good				333		10/01/1992	100	
IGILU0072	Carpet	Good				688		8/01/1992	100	
IGILU0073	Interior Painting	Good				588		10/01/1992	100	
IGILU0074	Wardrobe	Good				2053		10/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0089	Blind	Good				388		10/01/1992	100	
IGILU0090	Carpet	Fair				910		8/01/1992	100	
IGILU0091	Interior Painting	Good				832		10/01/1992	100	
IGILU1814	Air Conditioner - Split System	Poor				1563		10/01/1992		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0058	Benchtops	Good				2342		20/01/1992	100	
IGILU0059	Cooktop	Good	Westinghouse			1354		12/01/1992	100	
IGILU0060	Interior Painting	Good				710		10/01/1992	100	
IGILU0061	Kitchen Cabinets	Good				3818		20/01/1992	100	
IGILU0062	Vinyl	Fair				1010		10/01/1992	100	
IGILU0063	Electric Elevated Oven	Good	Westinghouse	PEK1370W-R	23680050	1409		12/01/1992	100	
IGILU0064	Rangehood	Good	Westinghouse			599		12/01/1992	100	
IGILU0065	Sink & Fittings	Good				1587		15/01/1992	100	
IGILU0066	Smoke Alarms	Good				260		20/01/1992	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0085	Blind	Good				388		10/01/1992	100	
IGILU0086	Carpet	Good				1165		8/01/1992	100	
IGILU0087	Heater	Good	IXL	03G2AJ		865		15/01/1992	100	
IGILU0088	Interior Painting	Good				1176		10/01/1992	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0081	Tiles - Floor	Good				1076		20/01/1992	100	
IGILU0082	Toilet & Cistern	Good				1343		20/01/1992	100	
IGILU0083	Interior Painting	Good				166		10/01/1992	100	
IGILU01551	Exhaust Fan	Good				255		10/11/2017		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0092	Clothesline	Good				499		10/01/1992	100	
IGILU0093	Courtyard	Good				2486		30/01/1992	100	
IGILU0094	Doors	Good				5605		30/01/1992	100	
IGILU0095	Downpipes	Good				1742		20/01/1992	100	
IGILU0096	Electrical Switchboard	Good				1964		20/01/1992	100	
IGILU0097	Exterior painting	Good				2086		10/01/1992	100	
IGILU0098	Fascias	Good				2874		20/01/1992	100	
IGILU0099	Flyscreens	Good				2186		10/01/1992	100	
IGILU0100	Guttering	Good				2819		20/01/1992	100	
IGILU0101	Path	Good				1509		30/01/1992	100	
IGILU0102	Porch	Good				2908		30/01/1992	100	
IGILU0103	Lattice Screening	Good				1098		20/01/1992	100	
IGILU0104	Windows	Good				3873		30/01/1992	100	
IGILU1572	Awnings	Good				9435		10/15/2010		

Unit 3-4

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002b	Driveway	Good				21978		25/01/1992	100	
IGILU0105	Roof	Good				13320		50/01/1992	100	

Unit 3

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0106	Insulation	Good				3069		20/01/1992	100	
IGILU0107	Lighting	Good				1909		15/01/1992	100	
IGILU0108	Sarking	Good				3174		25/01/1992	100	
IGILU0109	Hot Water System - Electric	Excellent	Vulcan	66108007	4956391	2386		12/01/1992	100	

Unit 4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0160	Insulation	Good				3069		20/01/1992	100	
IGILU0161	Lighting	Good				1909		15/01/1992	100	
IGILU0162	Sarking	Good				3174		25/01/1992	100	
IGILU0163	Hot Water System - Electric	Good	Dux Proflo			2386		12/01/1992	100	

Unit 3

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0129	Exhaust Fan	Good				255		10/01/05/2019	100	
IGILU0130	Interior Painting	Good				466		10/01/05/2019	100	
IGILU0131	Skylight	Good				1010		10/01/05/2019	100	
IGILU0132	Tapware	Good				1304		15/01/05/2019	100	
IGILU0133	Tiles - Wall	Good				3285		20/01/05/2019	100	
IGILU0134	Tiles - Floor	Good				4884		20/01/05/2019	100	
IGILU1815	Washing Machine	Good	Electrolux	Ultimatecare 500		1332		12/01/05/2019		

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0119	Blind	Good				333		10/01/05/2019	100	
IGILU0120	Carpet	Good				1032		8/01/05/2019	100	
IGILU0121	Curtains	Good				1776		6/01/05/2019	100	
IGILU0122	Interior Painting	Good				888		10/01/05/2019	100	
IGILU0123	Wardrobe	Good				2053		10/01/05/2019	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0124	Blind	Good				333		10/01/05/2019	100	
IGILU0125	Carpet	Excellent				688		8/01/05/2019	100	
IGILU0126	Curtains	Excellent				1776		6/01/05/2019	100	
IGILU0127	Interior Painting	Good				588		10/01/05/2019	100	
IGILU0128	Wardrobe	Good				2053		10/01/05/2019	100	
IGILU1816	Ceiling Fan	Good				588		10/01/05/2019		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0144	Blind	Fair				388		10/01/05/2019	100	
IGILU0146	Interior Painting	Good				832		10/01/05/2019	100	
IGILU1817	Vinyl	Good				1010		10/12/2023		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0110	Blind	Good				333		10/01/05/2019	100	
IGILU0111	Benchtops	Good				2342		20/01/05/2019	100	
IGILU0112	Interior Painting	Good				710		10/01/05/2019	100	
IGILU0113	Kitchen Cabinets	Good				3818		20/01/05/2019	100	
IGILU0114	Vinyl	Good				1010		10/01/05/2019	100	
IGILU0116	Rangehood	Good	Fisher and Paykel			599		12/01/05/2019	100	
IGILU0117	Sink & Fittings	Good				1587		15/01/05/2019	100	
IGILU0118	Smoke Alarms	Good				260		20/01/05/2019	100	
IGILU1818	Oven	Good	Fisher and Paykel			1409		12/12/2023		
IGILU1819	Cooktop	Good	Fisher and Paykel			1354		12/01/05/2019		
IGILU1820	Dishwasher	Good				1332		8/01/05/2019		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0138	Air Conditioner - Split System	Good	Actron Air			3296		10/01/05/2019	100	
IGILU0139	Blind	Good				388		10/01/05/2019	100	
IGILU0140	Carpet	Good				1165		8/01/05/2019	100	

IGILU0141	Curtains	Good	Vulcan			1776		6/01/05/2019	100	
IGILU0142	Heater	Good	Odyssey			865		15/01/05/2019	100	
IGILU0143	Interior Painting	Good				1176		10/01/05/2019	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0135	Tiles - Floor	Excellent				1076		20/01/05/2019	100	
IGILU0136	Toilet & Cistern	Good				1343		20/01/05/2019	100	
IGILU0137	Interior Painting	Good				166		10/01/05/2019	100	
IGILU1821	Basin	Good				1206		15/01/05/2019		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0147	Clothesline	Good				499		10/01/01/1992	100	
IGILU0148	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0149	Doors	Good				5605		30/01/01/1992	100	
IGILU0150	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0151	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0152	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0153	Fascias	Good				2874		20/01/01/1992	100	
IGILU0154	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0155	Guttering	Good				2819		20/01/01/1992	100	
IGILU0156	Path	Good				1509		30/01/01/1992	100	
IGILU0157	Porch	Good				2908		30/01/01/1992	100	
IGILU0158	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0159	Windows	Fair				3873		30/01/01/1992	100	
IGILU1582	Awnings	Good				9435		10/15/01/2010		

Unit 4

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0184	Exhaust Fan	Good				255		10/01/11/2021	100	
IGILU0185	Interior Painting	Good				466		10/01/11/2021	100	
IGILU0186	Skylight	Good				1010		10/01/11/2021	100	
IGILU0187	Tapware	Good				1304		15/01/11/2021	100	
IGILU0188	Tiles - Wall	Good				3285		20/01/11/2021	100	
IGILU0189	Tiles - Floor	Good				4884		20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0173	Blind	Good				333		10/01/11/2021	100	
IGILU0174	Carpet	Good				1032		8/01/11/2021	100	
IGILU0175	Ceiling Fan	Good				588		10/01/11/2021	100	
IGILU0176	Curtains	Good				1776		6/01/11/2021	100	
IGILU0177	Interior Painting	Good				888		10/01/11/2021	100	
IGILU0178	Wardrobe	Good				2053		10/01/11/2021	100	
IGILU1601	Ceiling Fan	Good				588		10/20/10/2022	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0179	Blind	Good				333		10/01/11/2021	100	
IGILU0180	Carpet	Good				688		8/01/11/2021	100	
IGILU0181	Curtains	Good				1776		6/01/11/2021	100	
IGILU0182	Interior Painting	Good				588		10/01/11/2021	100	
IGILU0183	Wardrobe	Good				2053		10/01/11/2021	100	
IGILU1603	Ceiling Fan	Good				588		10/20/10/2022	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0200	Blind	Good				388		10/01/11/2021	100	
IGILU0201	Carpet	Good				910		8/01/11/2021	100	
IGILU0202	Ceiling Fan	Good				588		10/01/11/2021	100	
IGILU0203	Interior Painting	Good				832		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0164	Benchtops	Good					2342	20/01/11/2021	100	
IGILU0165	Cooktop	Excellent	Fisher & Paykel				1354	12/01/11/2021	100	
IGILU0166	Interior Painting	Good					710	10/01/11/2021	100	
IGILU0167	Kitchen Cabinets	Good					3818	20/01/11/2021	100	
IGILU0168	Vinyl	Excellent					1010	10/01/11/2021	100	
IGILU0169	Oven	Good	Fisher & Paykel	0B60SC7CEX2	CPV287657		1409	12/01/11/2021	100	
IGILU0170	Rangehood	Good	Fisher & Paykel				599	12/01/11/2021	100	
IGILU0171	Sink & Fittings	Good					1587	15/01/11/2021	100	
IGILU0172	Smoke Alarms	Good					260	20/01/11/2021	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0193	Air Conditioner - Split System	Good	Mitsubishi Electric	DXK18ZSA-W	143803734CF	3296		10/01/11/2021	100	
IGILU0195	Carpet	Good				1165		8/01/11/2021	100	
IGILU0197	Curtains	Good				1776		6/01/11/2021	100	
IGILU0199	Interior Painting	Good				1176		10/01/11/2021	100	
IGILU1596	Blind	Good				388		10/20/10/2022	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0190	Tiles - Floor	Good				1076		20/01/11/2021	100	
IGILU0191	Toilet & Cistern	Good				1343		20/01/11/2021	100	
IGILU0192	Interior Painting	Good				166		10/01/11/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0204	Clothesline	Good				499		10/01/01/1992	100	
IGILU0205	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0206	Doors	Good				5605		30/01/01/1992	100	
IGILU0207	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0208	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0209	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0210	Fascias	Good				2874		20/01/01/1992	100	
IGILU0211	Flyscreens	Fair				2186		10/01/01/1992	100	
IGILU0212	Guttering	Good				2819		20/01/01/1992	100	
IGILU0213	Path	Good				1509		30/01/01/1992	100	
IGILU0214	Porch	Good				2908		30/01/01/1992	100	
IGILU0215	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0216	Windows	Good				3873		30/01/01/1992	100	
IGILU1587	Awnings	Good				9435		10/15/01/2010		

Unit 5-6

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002c	Driveway	Good				21978		25/01/01/2004	100	
IGILU0217	Roof	Good				13320		50/01/01/1992	100	

Unit 5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0218	Insulation	Good				3069		20/01/01/1992	100	
IGILU0219	Lighting	Good				1909		15/01/01/1992	100	
IGILU0220	Sarking	Good				3174		25/01/01/1992	100	
IGILU0221	Hot Water System - Electric	Good	Thermann	125THM136	14082530091H	2386		12/01/01/1992	100	

Unit 6

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0271	Insulation	Excellent				3069		20/01/01/1992	100	
IGILU0272	Lighting	Good				1909		15/01/01/1992	100	
IGILU0273	Sarking	Good				3174		25/01/01/1992	100	
IGILU0274	Hot Water System - Electric	Good	Dux Proflo	160F1-36	2844299674	2386		12/01/01/1992	100	

Unit 5

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0241	Exhaust Fan	Excellent				255		10/01/05/2004	100	
IGILU0242	Interior Painting	Excellent				466		10/01/05/2004	100	
IGILU0243	Toilet & Cistern	Excellent				1343		20/01/05/2004	100	
IGILU0244	Skylight	Excellent				1010		10/01/05/2004	100	
IGILU0245	Tapware	Excellent				1304		15/01/05/2004	100	
IGILU0246	Tiles - Wall	Excellent				3285		20/01/05/2004	100	
IGILU0247	Tiles - Floor	Excellent				4884		20/01/05/2004	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0232	Blind	Good				333		10/01/05/2004	100	
IGILU0233	Carpet	Good				1032		8/01/05/2004	100	
IGILU0234	Ceiling Fan	Good				588		10/01/05/2004	100	
IGILU0235	Interior Painting	Good				888		10/01/05/2004	100	
IGILU0236	Wardrobe	Good				2053		10/01/05/2004	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0237	Blind	Excellent				333		10/01/05/2004	100	
IGILU0238	Carpet	Good				688		8/01/05/2004	100	
IGILU0239	Interior Painting	Good				588		10/01/05/2004	100	
IGILU0240	Wardrobe	Good				2053		10/01/05/2004	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0248_	Air Conditioner - Split System	Good	Daikin	FTXV50WVMA	E006452	2440		10/28/04/2022		
IGILU0254	Blind	Good				388		10/01/05/2004	100	
IGILU0255	Carpet	Good				910		8/01/05/2004	100	
IGILU0256	Ceiling Fan	Good				588		10/01/05/2004	100	
IGILU0257	Interior Painting	Good				832		10/01/05/2004	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0222	Blind	Good				333		10/01/05/2004	100	
IGILU0223	Benchtops	Good				2342		20/01/05/2004	100	
IGILU0224	Cooktop	Good	Westinghouse			1354		12/01/05/2004	100	
IGILU0225	Interior Painting	Good				710		10/01/05/2004	100	
IGILU0226	Kitchen Cabinets	Good				3818		20/01/05/2004	100	
IGILU0227	Vinyl	Good				1010		10/01/05/2004	100	
IGILU0228	Electric Elevated Oven	Good	Westinghouse	WDE135WA-L	60280002	1409		12/01/05/2004	100	
IGILU0229	Rangehood	Good	Torin			599		12/01/05/2004	100	
IGILU0230	Sink & Fittings	Good				1587		15/01/05/2004	100	
IGILU0231	Smoke Alarms	Good				260		20/01/05/2004	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0249	Blind	Good				388		10/01/05/2004	100	
IGILU0250	Carpet	Good				1165		8/01/05/2004	100	
IGILU0251	Ceiling Fan	Good				588		10/01/05/2004	100	
IGILU0252	Heater	Excellent	IXL			865		15/01/05/2004	100	
IGILU0253	Interior Painting	Excellent				1176		10/01/05/2004	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0258	Clothesline	Good				499		10/01/01/1992	100	
IGILU0259	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0260	Doors	Good				5605		30/01/01/1992	100	
IGILU0261	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0262	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0263	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0264	Fascias	Good				2874		20/01/01/1992	100	
IGILU0265	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0266	Guttering	Good				2819		20/01/01/1992	100	

IGILU0267	Path	Good					1509	30/01/1992	100	
IGILU0268	Porch	Good					2908	30/01/1992	100	
IGILU0269	Lattice Screening	Good					1098	20/01/1992	100	
IGILU0270	Windows	Good					3873	30/01/1992	100	
IGILU1591	Awnings	Good					9435	10/15/01/2010		

Unit 6

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0293	Exhaust Fan	Good				255		10/01/12/2005	100	
IGILU0294	Interior Painting	Good				466		10/01/12/2005	100	
IGILU0295	Toilet & Cistern	Good				1343		20/01/12/2005	100	
IGILU0296	Skylight	Good				1010		10/01/12/2005	100	
IGILU0297	Tapware	Good				1304		15/01/12/2005	100	
IGILU0298	Tiles - Wall	Good				3285		20/01/12/2005	100	
IGILU0299	Tiles - Floor	Excellent				4884		20/01/12/2005	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0284	Blind	Excellent				333		10/01/12/2005	100	
IGILU0285	Carpet	Good				1032		8/01/12/2005	100	
IGILU0286	Interior Painting	Good				888		10/01/12/2005	100	
IGILU0287	Wardrobe	Good				2053		10/01/12/2005	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0288	Blind	Excellent				333		10/01/12/2005	100	
IGILU0289	Carpet	Good				688		8/01/12/2005	100	
IGILU0291	Interior Painting	Good				588		10/01/12/2005	100	
IGILU0292	Wardrobe	Excellent				2053		10/01/12/2005	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0305	Blind	Good				388		10/01/12/2005	100	
IGILU0307	Interior Painting	Good				832		10/01/12/2005	100	
IGILU1823	Vinyl	Excellent				1010		10/13/12/2023		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0275	Benchtops	Excellent				2342		20/01/12/2005	100	
IGILU0276	Cooktop	Excellent	Fisher & Paykel			1354		12/01/12/2005	100	
IGILU0277	Interior Painting	Excellent				710		10/01/12/2005	100	
IGILU0278	Kitchen Cabinets	Excellent				3818		20/01/12/2005	100	
IGILU0279	Vinyl	Excellent				1010		10/01/12/2005	100	
IGILU0280	Oven	Excellent	Fisher & Paykel	OB60SC7CEX2	CAV291895	1409		12/01/12/2005	100	
IGILU0281	Rangehood	Excellent	Fisher & Paykel			599		12/01/12/2005	100	
IGILU0282	Sink & Fittings	Good				1587		15/01/12/2005	100	
IGILU0283	Smoke Alarms	Good				260		20/01/12/2005	100	
IGILU1598	Dishwasher	Excellent	Fisher & Paykel	DW60FC1X1	FAN330143	1332		8/20/10/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0300	Air Conditioner - Split System	Good	Daikin	FTXD508VMA8	E005057	3296		10/01/12/2005	100	
IGILU0301	Blind	Good				388		10/01/12/2005	100	
IGILU0303	Heater	Excellent	IXL			865		15/01/12/2005	100	
IGILU0304	Interior Painting	Good				1176		10/01/12/2005	100	
IGILU1824	Vinyl	Excellent				1010		10/13/12/2023		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0308	Clothesline	Good				499		10/01/01/1992	100	
IGILU0309	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0310	Doors	Good				5605		30/01/01/1992	100	
IGILU0311	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0312	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0313	Exterior painting	Good				2086		10/01/01/1992	100	

IGILU0314	Fascias	Good				2874	20/01/1992	100	
IGILU0315	Flyscreens	Good				2186	10/01/1992	100	
IGILU0316	Guttering	Good				2819	20/01/1992	100	
IGILU0317	Path	Good				1509	30/01/1992	100	
IGILU0318	Porch	Good				2908	30/01/1992	100	
IGILU0319	Lattice Screening	Good				1098	20/01/1992	100	
IGILU0320	Windows	Excellent				3873	30/01/1992	100	
IGILU1592	Awnings	Good				9435	10/15/01/2010		

Unit 7-8

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002d	Driveway	Good				21978		25/01/07/1982	100	
IGILU0321	Roof	Good				13320		50/01/01/1992	100	

Unit 7

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0322	Insulation	Good				3069		20/01/01/1992	100	
IGILU0323	Lighting	Good				1909		15/01/01/1992	100	
IGILU0324	Sarking	Excellent				3174		25/01/01/1992	100	
IGILU0325	Hot Water System - Electric	Good	Dux Proflo	160S124	90612103960	2386		12/01/01/1992	100	
IGILU1637	Curtains	Excellent				1129		6/11/08/2023	100	

Unit 8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0379	Insulation	Good				3069		20/01/01/1992	100	
IGILU0380	Lighting	Good				1909		15/01/01/1992	100	
IGILU0381	Sarking	Good				3174		25/01/01/1992	100	
IGILU0382	Hot Water System - Electric	Good	Dux Proflo	160F136G	60120103860	2386		12/01/01/1992	100	

Unit 7

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0347	Exhaust Fan	Good				255		10/01/02/2012	100	
IGILU0349	Skylight	Good				1010		10/01/02/2012	100	
IGILU0350	Tapware	Good				1304		15/01/02/2012	100	
IGILU0351	Tiles - Wall	Good				3285		20/01/02/2012	100	
IGILU0352	Tiles - Floor	Good				4884		20/01/02/2012	100	
IGILU1628	Interior Painting	Good				499		10/11/08/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01553	Ceiling Fan	Good				588		10/01/11/2017		
IGILU0337	Blind	Good				333		10/01/02/2012	100	
IGILU0339	Curtains	Good				1776		6/01/02/2012	100	
IGILU0341	Wardrobe	Good				2053		10/01/02/2012	100	
IGILU1625	Carpet	Good				499		8/11/08/2023	100	
IGILU1630	Interior Painting	Fair				499		10/11/08/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0342	Blind	Good				333		10/01/02/2012	100	
IGILU0344	Curtains	Good				1776		6/01/02/2012	100	
IGILU0346	Wardrobe	Good				2053		10/01/02/2012	100	
IGILU1629	Interior Painting	Good				499		10/11/08/2023	100	
IGILU1812	Carpet	Good				499		8/11/08/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01552	Curtains	Good				1776		6/01/11/2019		
IGILU0363	Blind	Good				388		10/01/02/2012	100	
IGILU1626	Carpet	Good				499		8/11/08/2023	100	
IGILU1632	Interior Painting	Good				499		10/11/08/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0326	Blind	Good				333		10/01/02/2012	100	
IGILU1631	Interior Painting	Good				499		10/11/08/2023	100	
IGILU1635	Benchtops	Good				11912		20/11/08/2023	100	
IGILU1636	Cooktop	Good	Fisher and Paykel			2171		12/11/08/2023	100	
IGILU1638	Dishwasher	Good	Di Lusso			2171		8/11/08/2023	100	
IGILU1639	Kitchen Cabinets	Good				7990		20/11/08/2023	100	
IGILU1640	Oven	Good	Di Lusso	OV608SDS	TN2021060219	2171		12/11/08/2023	100	
IGILU1641	Rangehood	Good	Westinghouse	WRF910WA		2171		12/11/08/2023	100	
IGILU1642	Sink & Fittings	Good				666		15/11/08/2023	100	
IGILU1643	Vinyl	Good				1498		10/11/08/2023	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01560	Smoke Alarms	Good				260		20/01/11/2012		
IGILU0357	Blind	Good				388		10/01/02/2012	100	
IGILU0359	Ceiling Fan	Good				588		10/01/02/2012	100	
IGILU0360	Curtains	Good				1776		6/01/02/2012	100	
IGILU0361	Heater	Good	IXL			865		15/01/02/2012	100	
IGILU1627	Carpet	Good				499		8/11/08/2023	100	
IGILU1633	Interior Painting	Good				499		10/11/08/2023	100	
IGILU1825	Air Conditioner - Ducted System	Good				1332		10/11/08/2023		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0353	Tiles - Floor	Good				1076		20/01/02/2012	100	
IGILU0354	Toilet & Cistern	Good				1343		20/01/02/2012	100	
IGILU1634	Interior Painting	Good				557		10/11/08/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0366	Clothesline	Good				499		10/01/01/1992	100	
IGILU0367	Courtyard	Excellent				2486		30/01/01/1992	100	
IGILU0368	Doors	Good				5605		30/01/01/1992	100	
IGILU0369	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0370	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0371	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0372	Fascias	Good				2874		20/01/01/1992	100	
IGILU0373	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0374	Guttering	Good				2819		20/01/01/1992	100	
IGILU0375	Path	Good				1509		30/01/01/1992	100	
IGILU0376	Porch	Good				2908		30/01/01/1992	100	
IGILU0377	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0378	Windows	Good				3873		30/01/01/1992	100	
IGILU1593	Awnings	Good				9435		10/15/01/2010		

Unit 8

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0400	Exhaust Fan	Good				255		10/01/02/2021	100	
IGILU0401	Interior Painting	Good				466		10/01/02/2021	100	
IGILU0402	Toilet & Cistern	Good				1343		20/01/02/2021	100	
IGILU0403	Skylight	Fair				1010		10/01/02/2021	100	
IGILU0404	Tapware	Good				1304		15/01/02/2021	100	
IGILU0405	Tiles - Wall	Fair				3285		20/01/02/2021	100	
IGILU0406	Tiles - Floor	Fair				4884		20/01/02/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0392	Blind	Good				333		10/01/02/2021	100	
IGILU0393	Carpet	Good				1032		8/01/02/2021	100	
IGILU0394	Interior Painting	Good				888		10/01/02/2021	100	
IGILU0395	Wardrobe	Good				2053		10/01/02/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0396	Blind	Good				333		10/01/02/2021	100	
IGILU0397	Carpet	Good				688		8/01/02/2021	100	
IGILU0398	Interior Painting	Good				588		10/01/02/2021	100	
IGILU0399	Wardrobe	Good				2053		10/01/02/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0410	Air Conditioner - Split System	Good	Actron Air	WRE-035AS		3296		10/15/09/2023		
IGILU0415	Blind	Good				388		10/01/02/2021	100	
IGILU0416	Carpet	Good				910		8/01/02/2021	100	
IGILU0417	Interior Painting	Good				832		10/01/02/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0383	Benchtops	Good				2342		20/01/02/2021	100	
IGILU0385	Interior Painting	Good				710		10/01/02/2021	100	
IGILU0386	Kitchen Cabinets	Excellent				3818		20/01/02/2021	100	
IGILU0387	Vinyl	Good				1010		10/01/02/2021	100	
IGILU0389	Rangehood	Good				599		12/01/02/2021	100	
IGILU0390	Sink & Fittings	Good				1587		15/01/02/2021	100	
IGILU0391	Smoke Alarms	Good	Clipsal			260		20/01/02/2021	100	
IGILU1826	Cooktop	Excellent	Di Lusso			1354		12/12/12/2023		
IGILU1827	Oven	Good	Westinghouse			1409		12/12/12/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0411	Blind	Good				388		10/01/02/2021	100	
IGILU0412	Carpet	Good				1165		8/01/02/2021	100	
IGILU0413	Heater	Good	IXL	23E3AU		865		15/01/02/2021	100	
IGILU0414	Interior Painting	Good				1176		10/01/02/2021	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0407	Tiles - Floor	Good				1076		20/01/02/2021	100	
IGILU0408	Toilet & Cistern	Good				1343		20/01/02/2021	100	
IGILU0409	Interior Painting	Good				166		10/01/02/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0418	Clothesline	Excellent				499		10/01/01/1992	100	
IGILU0419	Courtyard	Excellent				2486		30/01/01/1992	100	
IGILU0420	Doors	Excellent				5605		30/01/01/1992	100	
IGILU0421	Downpipes	Excellent				1742		20/01/01/1992	100	
IGILU0422	Electrical Switchboard	Excellent				1964		20/01/01/1992	100	
IGILU0423	Exterior painting	Excellent				2086		10/01/01/1992	100	
IGILU0424	Fascias	Excellent				2874		20/01/01/1992	100	
IGILU0425	Flyscreens	Excellent				2186		10/01/01/1992	100	
IGILU0426	Guttering	Good				2819		20/01/01/1992	100	
IGILU0427	Path	Good				1509		30/01/01/1992	100	
IGILU0428	Porch	Excellent				2908		30/01/01/1992	100	
IGILU0429	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0430	Windows	Good				3873		30/01/01/1992	100	
IGILU1594	Awnings	Excellent				9435		10/15/01/2010		

Unit 11-12

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002e	Driveway	Good				21978		25/01/06/2016	100	
IGILU0431	Roof	Good				13320		50/01/01/1992	100	

Unit 11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0432	Insulation	Good				3069		20/01/01/1992	100	
IGILU0433	Lighting	Good				1909		15/01/01/1992	100	
IGILU0434	Sarking	Good				3174		25/01/01/1992	100	

IGILU0435	Hot Water System - Electric	Good	Thermann	250THM136	15091420253H		2386		12/01/01/1992	100	
-----------	-----------------------------	------	----------	-----------	--------------	--	------	--	---------------	-----	--

Unit 12

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0487	Insulation	Good				3069		20/01/01/1992	100	
IGILU0488	Lighting	Good				1909		15/01/01/1992	100	
IGILU0489	Sarking	Good				3174		25/01/01/1992	100	
IGILU0490	Hot Water System - Electric	Good	Dux Proflo	250THMB136	20022420041H	2386		12/01/06/2022	100	

Unit 11

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0457	Exhaust Fan	Good				255		10/01/11/2021	100	
IGILU0458	Interior Painting	Good				466		10/01/11/2021	100	
IGILU0459	Toilet & Cistern	Fair				1343		20/01/11/2021	100	
IGILU0460	Skylight	Good				1010		10/01/11/2021	100	
IGILU0461	Tapware	Good				1304		15/01/11/2021	100	
IGILU0462	Tiles - Wall	Good				3285		20/01/11/2021	100	
IGILU0463	Tiles - Floor	Good				4884		20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0446	Blind	Good				333		10/01/11/2021	100	
IGILU0447	Carpet	Good				1032		8/01/11/2021	100	
IGILU0448	Interior Painting	Good				888		10/01/11/2021	100	
IGILU0449	Wardrobe	Good				2053		10/01/11/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0450	Blind	Good				333		10/01/11/2021	100	
IGILU0451	Carpet	Good				688		8/01/11/2021	100	
IGILU0452	Interior Painting	Good				588		10/01/11/2021	100	
IGILU0453	Wardrobe	Good				2053		10/01/11/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0469	Blind	Good				388		10/01/11/2021	100	
IGILU0471	Interior Painting	Good				832		10/01/11/2021	100	
IGILU1599	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1606	Vinyl	Good				1665		10/20/10/2022	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0472	Carpet	Good				388		8/01/11/2021	100	
IGILU0473	Interior Painting	Good				333		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0436	Blind	Good				333		10/01/11/2021	100	
IGILU0437	Benchtops	Good				2342		20/01/11/2021	100	
IGILU0438	Cooktop	Good	Fisher & Paykel			1354		12/01/11/2021	100	
IGILU0439	Interior Painting	Good				710		10/01/11/2021	100	
IGILU0440	Kitchen Cabinets	Good				3818		20/01/11/2021	100	
IGILU0441	Vinyl	Good				1010		10/01/11/2021	100	
IGILU0442	Oven	Good	Fisher & Paykel	OB60SC7CEX2	CPV287640	1409		12/01/11/2021	100	
IGILU0443	Rangehood	Good	Fisher & Paykel			599		12/01/11/2021	100	
IGILU0444	Sink & Fittings	Good				1587		15/01/11/2021	100	
IGILU0445	Smoke Alarms	Good	Clipsal			260		20/01/11/2021	100	
IGILU1604	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAM830535	1332		8/20/10/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0454	Interior Painting	Good				166		10/01/11/2021	100	
IGILU0455	Tiles - Wall	Good				1076		20/01/11/2021	100	
IGILU0456	Tiles - Floor	Good				1076		20/01/11/2021	100	
IGILU1602	Dryer	Good	Stirling			777		12/20/10/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0464	Air Conditioner - Split System	Good	Mitsubishi	DXK18ZSA-W		3296		10/01/11/2021	100	
IGILU0465	Blind	Good				388		10/01/11/2021	100	
IGILU0467	Heater	Good	IXL			865	15	01/11/2021	100	
IGILU0468	Interior Painting	Good				1176		10/01/11/2021	100	
IGILU1600	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1605	Vinyl	Good				1665		10/20/10/2022	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0474	Clothesline	Fair				499		10/01/01/1992	100	
IGILU0475	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0476	Doors	Good				5605		30/01/01/1992	100	
IGILU0477	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0478	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0479	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0480	Fascias	Good				2874		20/01/01/1992	100	
IGILU0481	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0482	Guttering	Good				2819		20/01/01/1992	100	
IGILU0483	Path	Fair				1509		30/01/01/1992	100	
IGILU0484	Porch	Fair				2908		30/01/01/1992	100	
IGILU0486	Windows	Good				3873		30/01/01/1992	100	
IGILU1568	Awnings	Good				9435		10/15/01/2010		

Unit 12

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0514	Exhaust Fan	Good				255		10/01/07/2003	100	
IGILU0515	Interior Painting	Good				466		10/01/07/2003	100	
IGILU0516	Toilet & Cistern	Good				1343		20/01/07/2003	100	
IGILU0517	Skylight	Good				1010		10/01/07/2003	100	
IGILU0518	Tapware	Excellent				1304	15	01/07/2003	100	
IGILU0519	Tiles - Wall	Good				3285		20/01/07/2003	100	
IGILU0520	Tiles - Floor	Good				4884		20/01/07/2003	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0501	Blind	Good				333		10/01/07/2003	100	
IGILU0502	Carpet	Good				1032		8/01/07/2003	100	
IGILU0503	Curtains	Good				1776		6/01/07/2003	100	
IGILU0504	Interior Painting	Good				888		10/01/07/2003	100	
IGILU0505	Wardrobe	Good				2053		10/01/07/2003	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0506	Blind	Good				333		10/01/07/2003	100	
IGILU0507	Carpet	Good				688		8/01/07/2003	100	
IGILU0508	Curtains	Good				1776		6/01/07/2003	100	
IGILU0509	Interior Painting	Good				588		10/01/07/2003	100	
IGILU0510	Wardrobe	Good				2053		10/01/07/2003	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0527	Blind	Good				388		10/01/07/2003	100	
IGILU0529	Curtains	Good				1776		6/01/07/2003	100	
IGILU0530	Interior Painting	Good				832		10/01/07/2003	100	
IGILU1828	Vinyl	Excellent				1010		10/13/12/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0532	Interior Painting	Good				333		10/01/07/2003	100	
IGILU1829	Vinyl	Excellent				1010		10/13/12/2023		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0491	Benchtops	Good				2342		20/01/07/2003	100	

IGILU0493	Curtains	Good				444		6/01/07/2003	100	
IGILU0494	Interior Painting	Good				710		10/01/07/2003	100	
IGILU0495	Kitchen Cabinets	Good				3818		20/01/07/2003	100	
IGILU0496	Vinyl	Good				1010		10/01/07/2003	100	
IGILU0498	Rangehood	Good	Fisher and Paykel			599		12/01/07/2003	100	
IGILU0499	Sink & Fittings	Good				1587		15/01/07/2003	100	
IGILU0500	Smoke Alarms	Good				260		20/01/07/2003	100	
IGILU1830	Cooktop	Good	Fisher and Paykel			1354		12/13/12/2023		
IGILU1831	Oven	Good	Fisher and Paykel			1409		12/13/12/2023		
IGILU1832	Dishwasher	Excellent				1332		8/13/12/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0511	Interior Painting	Good				166		10/01/07/2003	100	
IGILU0512	Tiles - Wall	Good				1076		20/01/07/2003	100	
IGILU0513	Tiles - Floor	Good				1076		20/01/07/2003	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0521	Air Conditioner - Split System	Good	Daikin	FTXD718VMA	3919723	3296		10/01/07/2003	100	
IGILU0522	Blind	Good				388		10/01/07/2003	100	
IGILU0525	Heater	Good	IXL			865		15/01/07/2003	100	
IGILU0526	Interior Painting	Good				1176		10/01/07/2003	100	
IGILU1833	Vinyl	Excellent				1010		10/13/12/2023		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0533	Clothesline	Good				499		10/01/01/1992	100	
IGILU0534	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0535	Doors	Good				5605		30/01/01/1992	100	
IGILU0536	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0537	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0538	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0539	Fascias	Good				2874		20/01/01/1992	100	
IGILU0540	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0541	Guttering	Good				2819		20/01/01/1992	100	
IGILU0542	Path	Good				1509		30/01/01/1992	100	
IGILU0543	Porch	Good				2908		30/01/01/1992	100	
IGILU0545	Windows	Good				3873		30/01/01/1992	100	
IGILU1569	Awnings	Good				9435		10/15/01/2010		

Unit 13-14

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002f	Driveway	Good				21978		25/01/07/1982	100	
IGILU0546	Roof	Good				13320		50/01/01/1992	100	

Unit 13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0547	Insulation	Good				3069		20/01/01/1992	100	
IGILU0548	Lighting	Fair				1909		15/01/01/1992	100	
IGILU0549	Sarking	Good				3174		25/01/01/1992	100	
IGILU0550	Hot Water System - Electric	Good	Rheem	491250R7	5744853	2386		12/01/01/1992	100	

Unit 13

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0572	Exhaust Fan	Good				255		10/01/01/1992	100	
IGILU0573	Interior Painting	Good				466		10/01/01/1992	100	
IGILU0574	Toilet & Cistern	Good				1343		20/01/01/1992	100	
IGILU0575	Skylight	Good				1010		10/01/01/1992	100	
IGILU0576	Tapware	Good				1304		15/01/01/1992	100	
IGILU0577	Tiles - Wall	Good				3285		20/01/01/1992	100	

IGILU0578	Tiles - Floor	Good					4884	20/01/1992	100	
-----------	---------------	------	--	--	--	--	------	------------	-----	--

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0561	Blind	Excellent				333		10/01/1992	100	
IGILU0562	Carpet	Excellent				1032		8/01/1992	100	
IGILU0563	Interior Painting	Excellent				888		10/01/1992	100	
IGILU0564	Wardrobe	Excellent				2053		10/01/1992	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0565	Blind	Excellent				333		10/01/1992	100	
IGILU0566	Carpet	Excellent				688		8/01/1992	100	
IGILU0567	Interior Painting	Excellent				588		10/01/1992	100	
IGILU0568	Wardrobe	Excellent				2053		10/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0584	Blind	Good				388		10/01/1992	100	
IGILU0585	Carpet	Good				910		8/01/1992	100	
IGILU0586	Interior Painting	Good				832		10/01/1992	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0587	Carpet	Excellent				388		8/01/1992	100	
IGILU0588	Interior Painting	Good				333		10/01/1992	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0551	Blind	Good				333		10/01/1992	100	
IGILU0552	Benchtops	Good				2342		20/01/1992	100	
IGILU0553	Cooktop	Good	Electrolux Chef			1354		12/01/1992	100	
IGILU0554	Interior Painting	Good				710		10/01/1992	100	
IGILU0555	Kitchen Cabinets	Good				3818		20/01/1992	100	
IGILU0556	Vinyl	Good				1010		10/01/1992	100	
IGILU0557	Oven	Good	Electrolux Chef			1409		12/01/1992	100	
IGILU0558	Rangehood	Good	Westinghouse			599		12/01/1992	100	
IGILU0559	Sink & Fittings	Fair				1587		15/01/1992	100	
IGILU0560	Smoke Alarms	Good	Clipsal			260		20/01/1992	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0569	Interior Painting	Excellent				166		10/01/1992	100	
IGILU0570	Tiles - Wall	Excellent				1076		20/01/1992	100	
IGILU0571	Tiles - Floor	Excellent				1076		20/01/1992	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0579	Air Conditioner - Split System	Good	Daikin	FTXS50FVMA	E002613	3296		10/01/1992	100	
IGILU0580	Blind	Good				388		10/01/1992	100	
IGILU0581	Carpet	Good				1165		8/01/1992	100	
IGILU0582	Heater	Good	IXL			865		15/01/1992	100	
IGILU0583	Interior Painting	Good				1176		10/01/1992	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0589	Clothesline	Good				499		10/01/1992	100	
IGILU0590	Courtyard	Good				2486		30/01/1992	100	
IGILU0591	Doors	Good				5605		30/01/1992	100	
IGILU0592	Downpipes	Good				1742		20/01/1992	100	
IGILU0593	Electrical Switchboard	Good				1964		20/01/1992	100	
IGILU0594	Exterior painting	Good				2086		10/01/1992	100	
IGILU0595	Fascias	Good				2874		20/01/1992	100	
IGILU0596	Flyscreens	Good				2186		10/01/1992	100	
IGILU0597	Guttering	Good				2819		20/01/1992	100	
IGILU0598	Path	Excellent				1509		30/01/1992	100	
IGILU0599	Porch	Good				2908		30/01/1992	100	

IGILU0600	Lattice Screening	Good					1098	20/01/1992	100	
IGILU0601	Windows	Good					3873	30/01/1992	100	
IGILU1570	Awnings	Good					9435	10/15/01/2010		

Unit 14

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0626	Exhaust Fan	Good				255		10/01/03/2020	100	
IGILU0627	Interior Painting	Good				466		10/01/03/2020	100	
IGILU0628	Toilet & Cistern	Good				1343		20/01/03/2020	100	
IGILU0629	Skylight	Good				1010		10/01/03/2020	100	
IGILU0630	Tapware	Good				1304		15/01/03/2020	100	
IGILU0631	Tiles - Wall	Good				3285		20/01/03/2020	100	
IGILU0632	Tiles - Floor	Good				4884		20/01/03/2020	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0615	Blind	Good				333		10/01/03/2020	100	
IGILU0616	Carpet	Good				1032		8/01/03/2020	100	
IGILU0617	Interior Painting	Good				888		10/01/03/2020	100	
IGILU0618	Wardrobe	Good				2053		10/01/03/2020	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0619	Blind	Good				333		10/01/03/2020	100	
IGILU0620	Carpet	Good				688		8/01/03/2020	100	
IGILU0621	Interior Painting	Good				588		10/01/03/2020	100	
IGILU0622	Wardrobe	Good				2053		10/01/03/2020	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0638	Blind	Good				388		10/01/03/2020	100	
IGILU0640	Interior Painting	Good				832		10/01/03/2020	100	
IGILU1834	Vinyl	Good				1010		10/13/12/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0642	Interior Painting	Good				333		10/01/03/2020	100	
IGILU1835	Vinyl	Good				1010		10/13/12/2023		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0606	Benchtops	Good				2342		20/01/03/2020	100	
IGILU0607	Cooktop	Good	Westinghouse			1354		12/01/03/2020	100	
IGILU0608	Interior Painting	Good				710		10/01/03/2020	100	
IGILU0609	Kitchen Cabinets	Good				3818		20/01/03/2020	100	
IGILU0610	Vinyl	Good				1010		10/01/03/2020	100	
IGILU0611	Oven	Good	Westinghouse	WVES613WC-L	1350792	1409		12/01/03/2020	100	
IGILU0612	Rangehood	Good	Westinghouse			599		12/01/03/2020	100	
IGILU0613	Sink & Fittings	Good				1587		15/01/03/2020	100	
IGILU0614	Smoke Alarms	Good				260		20/01/03/2020	100	
IGILU1607	Dishwasher	Good	Fisher & Paykel	DD60SCW9	DSG278498	1332		8/20/10/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0623	Interior Painting	Good				166		10/01/03/2020	100	
IGILU0624	Tiles - Wall	Good				1076		20/01/03/2020	100	
IGILU0625	Tiles - Floor	Good				1076		20/01/03/2020	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0633	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	SRK80ZEA-S1	916001042 RE	3296		10/01/03/2020	100	
IGILU0634	Blind	Good				388		10/01/03/2020	100	
IGILU0636	Heater	Good	IXL			865		15/01/03/2020	100	
IGILU0637	Interior Painting	Good				1176		10/01/03/2020	100	
IGILU1836	Vinyl	Good				1010		10/13/12/2023		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0643	Clothesline	Good				499		10/01/1992	100	
IGILU0644	Courtyard	Good				2486		30/01/1992	100	
IGILU0645	Doors	Good				5605		30/01/1992	100	
IGILU0646	Downpipes	Good				1742		20/01/1992	100	
IGILU0648	Exterior painting	Good				2086		10/01/1992	100	
IGILU0649	Fascias	Good				2874		20/01/1992	100	
IGILU0650	Flyscreens	Good				2186		10/01/1992	100	
IGILU0651	Guttering	Good				2819		20/01/1992	100	
IGILU0652	Path	Good				1509		30/01/1992	100	
IGILU0653	Porch	Good				2908		30/01/1992	100	
IGILU0654	Lattice Screening	Good				1098		20/01/1992	100	
IGILU0655	Windows	Good				3873		30/01/1992	100	
IGILU1571	Awnings	Good				9435		10/15/01/2010		

Unit 14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0602	Insulation	Good				3069		20/01/1992	100	
IGILU0603	Lighting	Good				1909		15/01/1992	100	
IGILU0604	Sarking	Good				3174		25/01/1992	100	
IGILU0605	Hot Water System - Electric	Good	Thermann	250THM136	16010720239H	2386		12/01/1992	100	
IGILU0647	Electrical Switchboard	Good				1387		20/01/1992	100	

Unit 21-22

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002g	Driveway	Good				21978		25/01/07/1982	100	
IGILU0656	Roof	Good				13320		50/01/1992	100	

Unit 21

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0657	Insulation	Good				3069		20/01/1992	100	
IGILU0658	Lighting	Good				1909		15/01/1992	100	
IGILU0659	Sarking	Good				3174		25/01/1992	100	
IGILU0660	Hot Water System - Electric	Good	Thermann	250THM136	16010720239H	2386		12/01/1992	100	

Unit 22

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0710	Insulation	Good				3069		20/01/1992	100	
IGILU0711	Lighting	Good				1909		15/01/1992	100	
IGILU0712	Sarking	Good				3174		25/01/1992	100	
IGILU0713	Hot Water System - Electric	Good	Dux Proflo	160F136G	80526102100	2386		12/01/1992	100	

Unit 21

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0683	Skylight	Good				1010		10/01/01/1992	100	
IGILU1644	Exhaust Fan	Good				4660		10/20/06/2023	100	
IGILU1645	Interior Painting	Good				2501		10/20/06/2023	100	
IGILU1646	Tapware	Good	Eurosmart			1206		15/20/06/2023	100	
IGILU1647	Tiles - Floor	Good				6819		20/20/06/2023	100	
IGILU1648	Tiles - Wall	Good				6819		20/20/06/2023	100	
IGILU1649	Toilet & Cistern	Good	Caroma			2501		20/20/06/2023	100	
IGILU1650	Laundry Cabinets	Good				4660		20/20/06/2023	100	
IGILU1651	Laundry Benchtop	Good				11138		20/20/06/2023	100	
IGILU1652	Sink & Fittings	Good	Posh Solus			1206		15/20/06/2023	100	
IGILU1653	Vanity	Good				1206		20/20/06/2023	100	
IGILU1654	Basin	Good				1206		15/20/06/2023	100	
IGILU1655	Shower Screen	Good				3365		20/20/06/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0671	Blind	Good					333	10/01/1992	100	
IGILU0672	Carpet	Good					1032	8/01/1992	100	
IGILU0673	Curtains	Good					1776	6/01/1992	100	
IGILU0674	Interior Painting	Good					888	10/01/1992	100	
IGILU0675	Wardrobe	Good					2053	10/01/1992	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0676	Blind	Good					333	10/01/1992	100	
IGILU0677	Carpet	Good					688	8/01/1992	100	
IGILU0678	Interior Painting	Good					588	10/01/1992	100	
IGILU0679	Wardrobe	Good					2053	10/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0687	Air Conditioner - Split System	Good	Daikin	FTXV71WVMA	E014118		3296	10/28/07/2022		
IGILU0693	Blind	Good					388	10/01/1992	100	
IGILU0694	Carpet	Good					910	8/01/1992	100	
IGILU0695	Curtains	Good					1776	6/01/1992	100	
IGILU0696	Interior Painting	Good					832	10/01/1992	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0661	Blind	Good					333	10/01/1992	100	
IGILU0662	Benchtops	Good					2342	20/01/1992	100	
IGILU0663	Cooktop	Good	Westinghouse				1354	12/01/1992	100	
IGILU0664	Interior Painting	Good					710	10/01/1992	100	
IGILU0665	Kitchen Cabinets	Good					3818	20/01/1992	100	
IGILU0666	Vinyl	Good					1010	10/01/1992	100	
IGILU0667	Electric Elevated Oven	Good	Westinghouse	WDE135WA-R	62880021		1409	12/01/1992	100	
IGILU0669	Sink & Fittings	Good					1587	15/01/1992	100	
IGILU0670	Smoke Alarms	Good	Clipsal				260	20/01/1992	100	
IGILU1837	Rangehood	Good	Westinghouse				1211	12/13/12/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0688	Blind	Good					388	10/01/1992	100	
IGILU0689	Carpet	Good					1165	8/01/1992	100	
IGILU0690	Curtains	Good					1776	6/01/1992	100	
IGILU0691	Heater	Good	IXL				865	15/01/1992	100	
IGILU0692	Interior Painting	Good					1176	10/01/1992	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0697	Clothesline	Good					499	10/01/1992	100	
IGILU0698	Courtyard	Good					2486	30/01/1992	100	
IGILU0699	Doors	Good					5605	30/01/1992	100	
IGILU0700	Downpipes	Good					1742	20/01/1992	100	
IGILU0701	Electrical Switchboard	Good					1964	20/01/1992	100	
IGILU0702	Exterior painting	Good					2086	10/01/1992	100	
IGILU0703	Fascias	Good					2874	20/01/1992	100	
IGILU0704	Flyscreens	Good					2186	10/01/1992	100	
IGILU0705	Guttering	Good					2819	20/01/1992	100	
IGILU0706	Path	Good					1509	30/01/1992	100	
IGILU0707	Porch	Good					2908	30/01/1992	100	
IGILU0708	Lattice Screening	Good					1098	20/01/1992	100	
IGILU0709	Windows	Good					3873	30/01/1992	100	
IGILU1573	Awnings	Good					9435	10/15/01/2010		

Unit 22

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0731	Exhaust Fan	Good					255	10/01/03/2012	100	
IGILU0732	Interior Painting	Good					466	10/01/03/2012	100	

IGILU0733	Toilet & Cistern	Fair					1343	20/01/03/2012	100	
IGILU0734	Skylight	Good					1010	10/01/03/2012	100	
IGILU0735	Tapware	Good					1304	15/01/03/2012	100	
IGILU0736	Tiles - Wall	Good					3285	20/01/03/2012	100	
IGILU0737	Tiles - Floor	Good					4884	20/01/03/2012	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0723	Blind	Good				333	10	01/03/2012	100	
IGILU0724	Carpet	Good				1032	8	01/03/2012	100	
IGILU0725	Interior Painting	Good				888	10	01/03/2012	100	
IGILU0726	Wardrobe	Fair				2053	10	01/03/2012	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0727	Blind	Good				333	10	01/03/2012	100	
IGILU0728	Carpet	Good				688	8	01/03/2012	100	
IGILU0729	Interior Painting	Good				588	10	01/03/2012	100	
IGILU0730	Wardrobe	Good				2053	10	01/03/2012	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0743	Blind	Good				388	10	01/03/2012	100	
IGILU0744	Carpet	Good				910	8	01/03/2012	100	
IGILU0745	Interior Painting	Good				832	10	01/03/2012	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0714	Benchtops	Good				2342	20	01/03/2012	100	
IGILU0715	Cooktop	Good	Westinghouse			1354	12	01/03/2012	100	
IGILU0716	Interior Painting	Good				710	10	01/03/2012	100	
IGILU0717	Kitchen Cabinets	Good				3818	20	01/03/2012	100	
IGILU0718	Vinyl	Good				1010	10	01/03/2012	100	
IGILU0719	Electric Elevated Oven	Good	Westinghouse	PEK1350W-R	20380004	1409	12	01/03/2012	100	
IGILU0720	Rangehood	Good	Westinghouse			599	12	01/03/2012	100	
IGILU0721	Sink & Fittings	Good				1587	15	01/03/2012	100	
IGILU0722	Smoke Alarms	Good	Clipsal			260	20	01/03/2012	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0738	Air Conditioner - Split System	Good	Daikin	FTXD50CV48	E011540	3296	10	01/03/2012	100	
IGILU0739	Blind	Good				388	10	01/03/2012	100	
IGILU0740	Carpet	Good				1165	8	01/03/2012	100	
IGILU0741	Heater	Good	IXL			865	15	01/03/2012	100	
IGILU0742	Interior Painting	Good				1176	10	01/03/2012	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0746	Clothesline	Good				499	10	01/01/1992	100	
IGILU0747	Courtyard	Good				2486	30	01/01/1992	100	
IGILU0748	Doors	Good				5605	30	01/01/1992	100	
IGILU0749	Downpipes	Good				1742	20	01/01/1992	100	
IGILU0750	Electrical Switchboard	Good				1964	20	01/01/1992	100	
IGILU0751	Exterior painting	Good				2086	10	01/01/1992	100	
IGILU0752	Fascias	Good				2874	20	01/01/1992	100	
IGILU0753	Flyscreens	Good				2186	10	01/01/1992	100	
IGILU0754	Guttering	Good				2819	20	01/01/1992	100	
IGILU0755	Path	Good				1509	30	01/01/1992	100	
IGILU0756	Porch	Good				2908	30	01/01/1992	100	
IGILU0757	Lattice Screening	Good				1098	20	01/01/1992	100	
IGILU0758	Windows	Good				3873	30	01/01/1992	100	
IGILU1574	Awnings	Good				9435	10	15/01/2010		

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002h	Driveway	Good				21978		25/01/12/2017	100	
IGILU0759	Roof	Good				13320		50/01/01/1992	100	

Unit 23

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0760	Insulation	Good				3069		20/01/01/1992	100	
IGILU0761	Lighting	Good				1909		15/01/01/1992	100	
IGILU0762	Sarking	Good				3174		25/01/01/1992	100	
IGILU0763	Hot Water System - Electric	Excellent	Rinnai	RIN125E36	12021020020H	2386		12/01/01/1992	100	

Unit 24

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0806	Insulation	Good				3069		20/01/01/1992	100	
IGILU0807	Lighting	Good				1909		15/01/01/1992	100	
IGILU0808	Sarking	Good				3174		25/01/01/1992	100	
IGILU0809	Hot Water System - Electric	Good	Dux Proflo	160S136	1.10926E+11	2386		12/01/01/1992	100	

Unit 23

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0778	Exhaust Fan	Excellent				255		10/01/01/1992	100	
IGILU0779	Interior Painting	Excellent				466		10/01/05/2021	100	
IGILU0780	Toilet & Cistern	Excellent				1343		20/01/01/1992	100	
IGILU0781	Skylight	Excellent				1010		10/01/01/1992	100	
IGILU0782	Tapware	Fair				1304		15/01/01/1992	100	
IGILU0783	Tiles - Wall	Good				3285		20/01/01/1992	100	
IGILU0784	Tiles - Floor	Good				4884		20/01/01/1992	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0774	Blind	Good				333		10/01/01/1992	100	
IGILU0775	Carpet	Good				1032		8/01/05/2021	100	
IGILU0776	Interior Painting	Fair				888		10/01/05/2021	100	
IGILU0777	Wardrobe	Good				2053		10/01/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0790	Blind	Good				388		10/01/01/1992	100	
IGILU0791	Carpet	Good				910		8/01/05/2021	100	
IGILU0792	Interior Painting	Excellent				832		10/01/05/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0764	Blind	Good				333		10/01/01/1992	100	
IGILU0765	Benchtops	Good				2342		20/01/01/1992	100	
IGILU0766	Cooktop	Good	Simpson			1354		12/01/01/1992	100	
IGILU0767	Interior Painting	Good				710		10/01/05/2021	100	
IGILU0768	Kitchen Cabinets	Fair				3818		20/01/01/1992	100	
IGILU0769	Vinyl	Good				1010		10/01/05/2021	100	
IGILU0770	Oven	Good	Simpson	61D931W*04	23281721	1409		12/01/01/1992	100	
IGILU0771	Rangehood	Good	Simpson			599		12/01/01/1992	100	
IGILU0772	Sink & Fittings	Good				1587		15/01/01/1992	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01545	Smoke Alarms	Excellent				260		20/01/11/2012		
IGILU0785	Air Conditioner - Split System	Excellent	Daikin	FTXD718VMA8	E011041	3296		10/01/01/1992	100	
IGILU0786	Blind	Excellent				388		10/01/01/1992	100	
IGILU0787	Carpet	Fair				1376		8/01/05/2021	100	
IGILU0788	Heater	Excellent	IXL	09H1AF		865		15/01/01/1992	100	
IGILU0789	Interior Painting	Fair				1176		10/01/05/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

IGILU0793	Clothesline	Good				499		10/01/1992	100	
IGILU0794	Courtyard	Good				2486		30/01/1992	100	
IGILU0795	Doors	Good				5605		30/01/1992	100	
IGILU0796	Downpipes	Good				1742		20/01/1992	100	
IGILU0797	Electrical Switchboard	Good				1964		20/01/1992	100	
IGILU0798	Exterior painting	Good				2086		10/01/1992	100	
IGILU0799	Fascias	Good				2874		20/01/1992	100	
IGILU0800	Flyscreens	Good				2186		10/01/1992	100	
IGILU0801	Guttering	Good				2819		20/01/1992	100	
IGILU0802	Path	Good				1509		30/01/1992	100	
IGILU0803	Porch	Good				2908		30/01/1992	100	
IGILU0804	Lattice Screening	Good				1098		20/01/1992	100	
IGILU0805	Windows	Good				3873		30/01/1992	100	
IGILU1575	Awnings	Good				9435		10/15/2010		

Unit 24

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0824	Exhaust Fan	Good				255		10/01/1992	100	
IGILU0825	Interior Painting	Fair				466		10/01/08/2019	100	
IGILU0826	Toilet & Cistern	Good				1343		20/01/1992	100	
IGILU0827	Skylight	Good				1010		10/01/1992	100	
IGILU0828	Tapware	Good				1304		15/01/1992	100	
IGILU0829	Tiles - Wall	Good				3285		20/01/1992	100	
IGILU0830	Tiles - Floor	Good				4884		20/01/1992	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0819	Blind	Fair				333		10/01/1992	100	
IGILU0820	Carpet	Good				1032		8/01/08/2019	100	
IGILU0821	Curtains	Good				1776		6/01/1992	100	
IGILU0822	Interior Painting	Fair				888		10/01/08/2019	100	
IGILU0823	Wardrobe	Good				2053		10/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0837	Blind	Good				777		10/01/1992	100	
IGILU0838	Vinyl	Good				2164		10/01/08/2019	100	
IGILU0839	Curtains	Good				1776		6/01/1992	100	
IGILU0840	Interior Painting	Good				832		10/01/08/2019	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0810	Benchtops	Good				2342		20/01/1992	100	
IGILU0811	Cooktop	Good	Westinghouse			1354		12/01/1992	100	
IGILU0812	Interior Painting	Good				710		10/01/08/2019	100	
IGILU0813	Kitchen Cabinets	Good				3818		20/01/1992	100	
IGILU0814	Vinyl	Good				1010		10/01/08/2019	100	
IGILU0815	Electric Elevated Oven	Good	Westinghouse	PEK1350W-R*53	11380009	1409		12/01/1992	100	
IGILU0816	Rangehood	Good	Westinghouse			599		12/01/1992	100	
IGILU0817	Sink & Fittings	Good				1587		15/01/1992	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01555	Smoke Alarms	Good				260		20/01/11/2012		
IGILU0831	Air Conditioner - Split System	Good	Daikin	FTXD80CV46	E009431	3296		10/01/1992	100	
IGILU0832	Blind	Good				388		10/01/1992	100	
IGILU0833	Vinyl	Good				3330		10/01/08/2019	100	
IGILU0834	Curtains	Good				1776		6/01/1992	100	
IGILU0836	Interior Painting	Fair				1176		10/01/08/2019	100	
IGILU1851	Heater	Excellent	Pureheat Odyssey Heater			1270		15/08/03/2024		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0841	Clothesline	Good				499		10/01/1992	100	
IGILU0842	Courtyard	Good				2486		30/01/1992	100	
IGILU0843	Doors	Good				5605		30/01/1992	100	
IGILU0844	Downpipes	Good				1742		20/01/1992	100	
IGILU0845	Electrical Switchboard	Good				1964		20/01/1992	100	
IGILU0846	Electrical Switchboard	Good				1964		20/01/1992	100	
IGILU0847	Exterior painting	Good				2086		10/01/1992	100	
IGILU0848	Fascias	Good				2874		20/01/1992	100	
IGILU0849	Flyscreens	Fair				2186		10/01/1992	100	
IGILU0850	Guttering	Good				2819		20/01/1992	100	
IGILU0851	Path	Good				1509		30/01/1992	100	
IGILU0852	Porch	Good				2908		30/01/1992	100	
IGILU0853	Lattice Screening	Good				1098		20/01/1992	100	
IGILU0854	Windows	Good				3873		30/01/1992	100	
IGILU1576	Awnings	Good				9435		10/15/2010		

Unit 25-26

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002i	Driveway	Good				21978		25/01/2004	100	
IGILU0855	Roof	Good				13320		50/01/1992	100	

Unit 25

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0856	Insulation	Good				3069		20/01/1992	100	
IGILU0857	Lighting	Excellent				1909		15/01/1992	100	
IGILU0858	Sarking	Excellent				3174		25/01/1992	100	
IGILU0859	Hot Water System - Electric	Good	Thermann	125THM136	16021730079TH	2386		12/01/1992	100	

Unit 26

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0909	Insulation	Good				3069		20/01/1992	100	
IGILU0910	Lighting	Good				1909		15/01/1992	100	
IGILU0911	Sarking	Good				3174		25/01/1992	100	
IGILU0912	Hot Water System - Electric	Good	Dux Proflo	160S136	1.00208E+11	2386		12/01/1992	100	

Unit 25

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0879	Exhaust Fan	Good				255		10/01/05/2019	100	
IGILU0880	Interior Painting	Good				466		10/01/05/2019	100	
IGILU0881	Toilet & Cistern	Excellent				1343		20/01/05/2019	100	
IGILU0882	Skylight	Good				1010		10/01/05/2019	100	
IGILU0883	Tapware	Excellent				1304		15/01/05/2019	100	
IGILU0884	Tiles - Wall	Good				3285		20/01/05/2019	100	
IGILU0885	Tiles - Floor	Good				4884		20/01/05/2019	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0870	Blind	Excellent				333		10/01/05/2019	100	
IGILU0871	Carpet	Excellent				1032		8/01/05/2019	100	
IGILU0872	Curtains	Excellent				1776		6/01/05/2019	100	
IGILU0873	Interior Painting	Fair				888		10/01/05/2019	100	
IGILU0874	Wardrobe	Excellent				2053		10/01/05/2019	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0875	Blind	Excellent				333		10/01/05/2019	100	
IGILU0876	Curtains	Excellent				1776		6/01/05/2019	100	
IGILU0877	Interior Painting	Excellent				588		10/01/05/2019	100	
IGILU0878	Wardrobe	Excellent				2053		10/01/05/2019	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0892	Blind	Good				388		10/01/05/2019	100	
IGILU0893	Carpet	Good				910		8/01/05/2019	100	
IGILU0894	Curtains	Excellent				1776		6/01/05/2019	100	
IGILU0895	Interior Painting	Good				832		10/01/05/2019	100	
IGILU1838	Air Conditioner - Split System	Good				1563		10/01/05/2019		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0860	Blind	Good				333		10/01/05/2019	100	
IGILU0861	Benchtops	Good				2342		20/01/05/2019	100	
IGILU0862	Curtains	Good				444		6/01/05/2019	100	
IGILU0863	Interior Painting	Good				710		10/01/05/2019	100	
IGILU0864	Kitchen Cabinets	Good				3818		20/01/05/2019	100	
IGILU0865	Vinyl	Good				1010		10/01/05/2019	100	
IGILU0866	Oven	Good	Omega	OB0654GG	708019007552380000	1409		12/01/05/2019	100	
IGILU0867	Rangehood	Good	Fisher and Paykel			599		12/01/05/2019	100	
IGILU0868	Sink & Fittings	Excellent				1587		15/01/05/2019	100	
IGILU1839	Cooktop	Good	Omega			1354		12/01/05/2019		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01550	Smoke Alarms	Excellent				260		20/01/11/2012		
IGILU0886	Air Conditioner - Split System	Good	Daikin	FTXD508VMA	4994121	3296		10/01/05/2019	100	
IGILU0887	Blind	Good				388		10/01/05/2019	100	
IGILU0888	Carpet	Fair				1165		8/01/05/2019	100	
IGILU0889	Curtains	Excellent				1776		6/01/05/2019	100	
IGILU0890	Heater	Good	IXL	18G1AF		865		15/01/05/2019	100	
IGILU0891	Interior Painting	Good				1176		10/01/05/2019	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0896	Clothesline	Good				499		10/01/01/1992	100	
IGILU0897	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0898	Doors	Good				5605		30/01/01/1992	100	
IGILU0899	Downpipes	Good				1742		20/01/01/1992	100	
IGILU0900	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU0901	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0902	Fascias	Good				2874		20/01/01/1992	100	
IGILU0903	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU0904	Guttering	Good				2819		20/01/01/1992	100	
IGILU0905	Path	Good				1509		30/01/01/1992	100	
IGILU0906	Porch	Good				2908		30/01/01/1992	100	
IGILU0907	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0908	Windows	Good				3873		30/01/01/1992	100	
IGILU1577	Awnings	Good				9435		10/15/01/2010		

Unit 26

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0932	Exhaust Fan	Good				255		10/01/10/2014	100	
IGILU0933	Interior Painting	Good				466		10/01/10/2014	100	
IGILU0934	Toilet & Cistern	Good				1343		20/01/10/2014	100	
IGILU0935	Skylight	Excellent				1010		10/01/10/2014	100	
IGILU0936	Tapware	Good				1304		15/01/10/2014	100	
IGILU0937	Tiles - Wall	Good				3285		20/01/10/2014	100	
IGILU0938	Tiles - Floor	Good				4884		20/01/10/2014	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0923	Blind	Good				333		10/01/10/2014	100	
IGILU0924	Carpet	Good				1032		8/01/10/2014	100	

IGILU0925	Curtains	Good					1776	6/01/10/2014	100	
IGILU0926	Interior Painting	Good					888	10/01/10/2014	100	
IGILU0927	Wardrobe	Good					2053	10/01/10/2014	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0928	Blind	Excellent				333		10/01/10/2014	100	
IGILU0929	Carpet	Good				688		8/01/10/2014	100	
IGILU0930	Interior Painting	Good				588		10/01/10/2014	100	
IGILU0931	Wardrobe	Good				2053		10/01/10/2014	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0940	Air Conditioner - Split System	Excellent	Fujitsu	AST14RVACW	E002897	3296		10/01/10/2014	100	
IGILU0946	Blind	Excellent				388		10/01/10/2014	100	
IGILU0949	Interior Painting	Good				832		10/01/10/2014	100	
IGILU1608	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1612	Vinyl	Excellent				1665		10/21/10/2022	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0913	Benchtops	Good				2342		20/01/10/2014	100	
IGILU0914	Cooktop	Good	Fisher & Paykel			1354		12/01/10/2014	100	
IGILU0915	Curtains	Good				444		6/01/10/2014	100	
IGILU0916	Interior Painting	Good				710		10/01/10/2014	100	
IGILU0917	Kitchen Cabinets	Good				3818		20/01/10/2014	100	
IGILU0918	Vinyl	Excellent				1010		10/01/10/2014	100	
IGILU0919	Oven	Good	Fisher & Paykel	OB60SC7CEX2	UFV263091	1409		12/01/10/2014	100	
IGILU0920	Rangehood	Good	Fisher & Paykel			599		12/01/10/2014	100	
IGILU0921	Sink & Fittings	Good				1587		15/01/10/2014	100	
IGILU0922	Smoke Alarms	Good				260		20/01/10/2014	100	
IGILU1610	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAN330164	1332		8/20/10/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0941	Blind	Good				388		10/01/10/2014	100	
IGILU0943	Curtains	Good				1776		6/01/10/2014	100	
IGILU0945	Interior Painting	Good				1176		10/01/10/2014	100	
IGILU1609	Vinyl	Excellent				1665		10/20/10/2022	100	
IGILU1611	Vinyl	Good				1665		10/21/10/2022	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0950	Clothesline	Good				499		10/01/01/1992	100	
IGILU0951	Courtyard	Good				2486		30/01/01/1992	100	
IGILU0952	Doors	Good				5605		30/01/01/1992	100	
IGILU0953	Downpipes	Excellent				1742		20/01/01/1992	100	
IGILU0954	Electrical Switchboard	Excellent				1964		20/01/01/1992	100	
IGILU0955	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU0956	Fascias	Good				2874		20/01/01/1992	100	
IGILU0957	Flyscreens	Fair				2186		10/01/01/1992	100	
IGILU0958	Guttering	Good				2819		20/01/01/1992	100	
IGILU0959	Path	Good				1509		30/01/01/1992	100	
IGILU0960	Porch	Good				2908		30/01/01/1992	100	
IGILU0961	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU0962	Windows	Good				3873		30/01/01/1992	100	
IGILU1578	Awnings	Excellent				9435		10/15/01/2010		

Unit 27-28

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002]	Driveway	Good				21978		25/01/04/2015	100	
IGILU0963	Roof	Good				13320		50/01/01/1992	100	

Unit 27

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0964	Insulation	Good				3069		20/01/1992	100	
IGILU0965	Lighting	Good				1909		15/01/1992	100	
IGILU0966	Sarking	Good				3174		25/01/1992	100	
IGILU0967	Hot Water System - Electric	Good	Dux Proflo	160F136G	80526102070	2386		12/01/1992	100	

Unit 28

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1016	Insulation	Good				3069		20/01/1992	100	
IGILU1017	Lighting	Good				1909		15/01/1992	100	
IGILU1018	Sarking	Good				3174		25/01/1992	100	
IGILU1019	Hot Water System - Electric	Excellent	Dux Proflo	125S136	12090720192H	2386		12/01/1992	100	

Unit 27

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0988	Exhaust Fan	Excellent				255		10/01/11/2007	100	
IGILU0989	Interior Painting	Excellent				466		10/01/11/2007	100	
IGILU0990	Toilet & Cistern	Excellent				1343		20/01/11/2007	100	
IGILU0991	Skylight	Excellent				1010		10/01/11/2007	100	
IGILU0992	Tapware	Good				1304		15/01/11/2007	100	
IGILU0993	Tiles - Wall	Good				3285		20/01/11/2007	100	
IGILU0994	Tiles - Floor	Good				4884		20/01/11/2007	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0978	Blind	Excellent				333		10/01/11/2007	100	
IGILU0979	Carpet	Good				1032		8/01/11/2007	100	
IGILU0980	Curtains	Good				1776		6/01/11/2007	100	
IGILU0981	Interior Painting	Good				888		10/01/11/2007	100	
IGILU0982	Wardrobe	Excellent				2053		10/01/11/2007	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0983	Blind	Excellent				333		10/01/11/2007	100	
IGILU0984	Carpet	Good				688		8/01/11/2007	100	
IGILU0985	Curtains	Good				1776		6/01/11/2007	100	
IGILU0986	Interior Painting	Good				588		10/01/11/2007	100	
IGILU0987	Wardrobe	Excellent				2053		10/01/11/2007	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1000	Blind	Excellent				388		10/01/11/2007	100	
IGILU1001	Carpet	Excellent				910		8/01/11/2007	100	
IGILU1002	Interior Painting	Excellent				832		10/01/11/2007	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0968	Blind	Excellent				333		10/01/11/2007	100	
IGILU0969	Benchtops	Good				2342		20/01/11/2007	100	
IGILU0970	Cooktop	Good	Chef Premier			1354		12/01/11/2007	100	
IGILU0971	Interior Painting	Good				710		10/01/11/2007	100	
IGILU0972	Kitchen Cabinets	Good				3818		20/01/11/2007	100	
IGILU0974	Electric Elevated Oven	Good	Chef	EECL031W	10860103	1409		12/01/11/2007	100	
IGILU0975	Rangehood	Good	Robin Hood			599		12/01/11/2007	100	
IGILU0976	Sink & Fittings	Good				1587		15/01/11/2007	100	
IGILU0977	Smoke Alarms	Excellent				260		20/01/11/2007	100	
IGILU1840	Carpet	Good				910		8/13/12/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU01554	Air Conditioner - Split System	Excellent	Fujitsu	ASTA18LCC	E029866	3296		10/01/11/2017		
IGILU0995	Blind	Excellent				388		10/01/11/2007	100	
IGILU0996	Carpet	Excellent				1165		8/01/11/2007	100	

IGILU0997	Curtains	Excellent				1776	6/01/11/2007	100	
IGILU0998	Heater	Excellent	IXL	20L7AR		865	15/01/11/2007	100	
IGILU0999	Interior Painting	Excellent				1176	10/01/11/2007	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1003	Clothesline	Good				499		10/01/01/1992	100	
IGILU1004	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1005	Doors	Good				5605		30/01/01/1992	100	
IGILU1006	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1007	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1008	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1009	Fascias	Good				2874		20/01/01/1992	100	
IGILU1010	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU1011	Guttering	Good				2819		20/01/01/1992	100	
IGILU1012	Path	Good				1509		30/01/01/1992	100	
IGILU1013	Porch	Excellent				2908		30/01/01/1992	100	
IGILU1014	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU1015	Windows	Excellent				3873		30/01/01/1992	100	
IGILU1579	Awnings	Good				9435		10/15/01/2010		

Unit 28

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1040	Skylight	Excellent				1010		10/01/07/2005	100	
IGILU1662	Interior Painting	Excellent				973		10/26/06/2023	100	
IGILU1663	Tiles - Wall	Excellent				4777		20/26/06/2023	100	
IGILU1664	Tiles - Floor	Good				4597		20/26/06/2023	100	
IGILU1669	Exhaust Fan	Excellent				2030		10/26/06/2023	100	
IGILU1670	Toilet & Cistern	Excellent				1815		20/26/06/2023	100	
IGILU1671	Tapware	Excellent				1388		15/26/06/2023	100	
IGILU1674	Laundry Benchtop	Excellent				4597		20/26/06/2023	100	
IGILU1675	Laundry Cabinets	Excellent				2457		20/26/06/2023	100	
IGILU1676	Sink & Fittings	Excellent				1388		15/26/06/2023	100	
IGILU1677	Vanity	Excellent				1388		20/26/06/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1028	Blind	Excellent				333		10/01/07/2005	100	
IGILU1030	Curtains	Excellent				1776		6/01/07/2005	100	
IGILU1032	Wardrobe	Good				2053		10/01/07/2005	100	
IGILU1658	Carpet	Good				2138		8/26/06/2023	100	
IGILU1659	Interior Painting	Good				973		10/26/06/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1033	Blind	Excellent				333		10/01/07/2005	100	
IGILU1036	Wardrobe	Good				2053		10/01/07/2005	100	
IGILU1660	Carpet	Excellent				2138		8/26/06/2023	100	
IGILU1661	Interior Painting	Excellent				973		10/26/06/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1050	Blind	Good				388		10/01/07/2005	100	
IGILU1668	Interior Painting	Excellent				984		10/26/06/2023	100	
IGILU1672	Vinyl	Excellent				2138		10/26/06/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1020	Benchtops	Excellent				2342		20/01/07/2005	100	
IGILU1022	Kitchen Cabinets	Excellent				3818		20/01/07/2005	100	
IGILU1023	Vinyl	Excellent				1010		10/01/07/2005	100	
IGILU1024	Oven	Excellent	Omega	OBO654GG	724635007831740000	1409		12/01/07/2005	100	
IGILU1025	Rangehood	Excellent				599		12/01/07/2005	100	
IGILU1026	Sink & Fittings	Excellent				1587		15/01/07/2005	100	

IGILU1027	Smoke Alarms	Excellent					260		20/01/07/2005	100	
IGILU1657	Interior Painting	Good					973		10/26/06/2023	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1044	Air Conditioner - Split System	Excellent	Fujitsu	ASTA12LCC	E003367	3296		10/01/07/2005	100	
IGILU1045	Blind	Excellent				388		10/01/07/2005	100	
IGILU1047	Curtains	Good				1776		6/01/07/2005	100	
IGILU1048	Heater	Excellent	IXL			865		15/01/07/2005	100	
IGILU1666	Interior Painting	Excellent				973		10/26/06/2023	100	
IGILU1673	Vinyl	Excellent				2138		10/26/06/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1054	Clothesline	Good				499		10/01/01/1992	100	
IGILU1055	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1056	Doors	Good				5605		30/01/01/1992	100	
IGILU1057	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1058	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1059	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1060	Fascias	Good				2874		20/01/01/1992	100	
IGILU1061	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU1062	Guttering	Good				2819		20/01/01/1992	100	
IGILU1063	Path	Excellent				1509		30/01/01/1992	100	
IGILU1064	Porch	Excellent				2908		30/01/01/1992	100	
IGILU1065	Lattice Screening	Excellent				1098		20/01/01/1992	100	
IGILU1066	Windows	Excellent				3873		30/01/01/1992	100	
IGILU1580	Awnings	Excellent				9435		10/15/01/2010		

Unit 29-30

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002k	Driveway	Good				21978		25/01/01/2017	100	
IGILU1067	Roof	Good				13320		50/01/01/1992	100	

Unit 29

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1068	Insulation	Excellent				3069		20/01/01/1992	100	
IGILU1069	Lighting	Excellent				1909		15/01/01/1992	100	
IGILU1070	Sarking	Good				3174		25/01/01/1992	100	
IGILU1071	Hot Water System - Electric	Excellent	Dux Proflo	160S124	90904110450	2386		12/01/01/1992	100	

Unit 30

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1117	Insulation	Good				3069		20/01/01/1992	100	
IGILU1119	Sarking	Good				3174		25/01/01/1992	100	
IGILU1120	Hot Water System - Electric	Good	Dux Proflo	125S136	12020720132H	2386		12/01/01/1992	100	
IGILU1700	Lighting	Good				1916		15/03/07/2023	100	

Unit 29

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1089	Exhaust Fan	Excellent				255		10/01/04/2005	100	
IGILU1090	Interior Painting	Excellent				466		10/01/04/2005	100	
IGILU1091	Toilet & Cistern	Excellent				1343		20/01/04/2005	100	
IGILU1092	Skylight	Excellent				1010		10/01/04/2005	100	
IGILU1093	Tapware	Excellent				1304		15/01/04/2005	100	
IGILU1094	Tiles - Wall	Excellent				3285		20/01/04/2005	100	
IGILU1095	Tiles - Floor	Excellent				4884		20/01/04/2005	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1082	Blind	Excellent				333		10/01/04/2005	100	

IGILU1083	Carpet	Good					1032	8/01/04/2005	100	
IGILU1084	Interior Painting	Excellent					888	10/01/04/2005	100	
IGILU1085	Wardrobe	Excellent					2053	10/01/04/2005	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1101	Blind	Good				388		10/01/04/2005	100	
IGILU1103	Interior Painting	Excellent				832		10/01/04/2005	100	
IGILU1613	Vinyl	Excellent				1665		10/20/10/2022	100	
IGILU1616	Vinyl	Excellent				1665		10/20/10/2022	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1072	Blind	Excellent				333		10/01/04/2005	100	
IGILU1073	Benchtops	Excellent				2342		20/01/04/2005	100	
IGILU1074	Cooktop	Excellent	Fisher & Paykel	EEC1230W-L*20	50900116	1354		12/01/04/2005	100	
IGILU1075	Interior Painting	Excellent				710		10/01/04/2005	100	
IGILU1076	Kitchen Cabinets	Excellent				3818		20/01/04/2005	100	
IGILU1077	Vinyl	Good				1010		10/01/04/2005	100	
IGILU1078	Oven	Excellent	Fisher & Paykel	OB60SC7CEX2	UFV264272	1409		12/01/04/2005	100	
IGILU1079	Rangehood	Excellent	Fisher & Paykel			599		12/01/04/2005	100	
IGILU1080	Sink & Fittings	Excellent				1587		15/01/04/2005	100	
IGILU1081	Smoke Alarms	Excellent	Clipsal			260		20/01/04/2005	100	
IGILU1617	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAN330122	1332		8/20/10/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1096	Air Conditioner - Split System	Excellent	Mitsubishi Electric	MSZ-GE50VA2	2004442	3296		10/01/04/2005	100	
IGILU1097	Blind	Good				388		10/01/04/2005	100	
IGILU1099	Heater	Excellent	IXL	22E0AB		865		15/01/04/2005	100	
IGILU1100	Interior Painting	Excellent				1176		10/01/04/2005	100	
IGILU1615	Vinyl	Excellent				1665		10/20/10/2022	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1104	Clothesline	Good				499		10/01/01/1992	100	
IGILU1105	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1106	Doors	Good				5605		30/01/01/1992	100	
IGILU1107	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1108	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1109	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1110	Fascias	Good				2874		20/01/01/1992	100	
IGILU1111	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU1112	Guttering	Good				2819		20/01/01/1992	100	
IGILU1113	Path	Good				1509		30/01/01/1992	100	
IGILU1114	Porch	Excellent				2908		30/01/01/1992	100	
IGILU1115	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU1116	Windows	Excellent				3873		30/01/01/1992	100	
IGILU1581	Awnings	Good				9435		10/15/01/2010		

Unit 30

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1142	Skylight	Good				1010		10/01/10/2010	100	
IGILU1678	Exhaust Fan	Excellent				3588		10/03/07/2023	100	
IGILU1679	Interior Painting	Excellent				2446		10/03/07/2023	100	
IGILU1680	Tapware	Excellent	Eurosmart			1761		15/03/07/2023	100	
IGILU1681	Tiles - Floor	Excellent				5839		20/03/07/2023	100	
IGILU1682	Tiles - Wall	Excellent				5839		20/03/07/2023	100	
IGILU1683	Toilet & Cistern	Excellent	Caroma			2446		20/03/07/2023	100	
IGILU1689	Laundry Cabinets	Excellent				5309		20/03/07/2023	100	
IGILU1690	Laundry Benchtop	Excellent				7623		20/03/07/2023	100	
IGILU1691	Sink & Fittings	Excellent	Posh Solus			2372		15/03/07/2023	100	
IGILU1692	Vanity	Excellent				2372		20/03/07/2023	100	

IGILU1693	Basin	Excellent					2372	15/03/07/2023	100	
IGILU1694	Shower Screen	Excellent					3514	20/03/07/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1130	Blind	Good				333	10	10/10/2023		
IGILU1132	Curtains	Good				1776	6	01/10/2010	100	
IGILU1134	Wardrobe	Excellent				2053	10	01/10/2010	100	
IGILU1686	Carpet	Good				3536	8	03/07/2023	100	
IGILU1699	Interior Painting	Good				1720	10	03/07/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1135	Blind	Excellent				333	10	10/10/2023		
IGILU1136	Curtains	Excellent				1776	6	01/10/2010	100	
IGILU1138	Wardrobe	Excellent				2053	10	01/10/2010	100	
IGILU1687	Carpet	Excellent				3536	8	03/07/2023	100	
IGILU1697	Interior Painting	Good				1720	10	03/07/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1153	Blind	Excellent				388	10	10/10/2023		
IGILU1684	Carpet	Excellent				3536	8	03/07/2023	100	
IGILU1695	Interior Painting	Excellent				1720	10	03/07/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1121	Benchtops	Good				2342	20	01/10/2010	100	
IGILU1122	Cooktop	Excellent	Westinghouse			1354	12	01/10/2010	100	
IGILU1124	Kitchen Cabinets	Fair				3818	20	01/10/2010	100	
IGILU1126	Electric Elevated Oven	Excellent	Westinghouse	PEK1350W-R*57	3280067	1409	12	01/10/2010	100	
IGILU1127	Rangehood	Excellent	Westinghouse			599	12	01/10/2010	100	
IGILU1128	Sink & Fittings	Excellent				1587	15	01/10/2010	100	
IGILU1129	Smoke Alarms	Excellent				260	20	01/10/2010	100	
IGILU1688	Vinyl	Excellent				3536	10	03/07/2023	100	
IGILU1698	Interior Painting	Excellent				1720	10	03/07/2023	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1146	Air Conditioner - Split System	Excellent	Mitsubishi Heavy Industries	SRK71ZMA-S	638405173BE	3296	10	01/10/2010	100	
IGILU1147	Blind	Excellent				388	10	01/10/2010	100	
IGILU1149	Ceiling Fan	Good				588	10	01/10/2010	100	
IGILU1150	Curtains	Good				1776	6	01/10/2010	100	
IGILU1151	Heater	Excellent	IXL	09L0AC		865	15	01/10/2010	100	
IGILU1685	Carpet	Excellent				3536	8	03/07/2023	100	
IGILU1696	Interior Painting	Fair				1720	10	03/07/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1156	Clothesline	Good				499	10	01/01/1992	100	
IGILU1157	Courtyard	Excellent				2486	30	01/01/1992	100	
IGILU1158	Doors	Good				5605	30	01/01/1992	100	
IGILU1159	Downpipes	Good				1742	20	01/01/1992	100	
IGILU1160	Electrical Switchboard	Good				1964	20	01/01/1992	100	
IGILU1161	Exterior painting	Good				2086	10	01/01/1992	100	
IGILU1162	Fascias	Good				2874	20	01/01/1992	100	
IGILU1163	Flyscreens	Good				2186	10	01/01/1992	100	
IGILU1164	Guttering	Good				2819	20	01/01/1992	100	
IGILU1165	Path	Good				1509	30	01/01/1992	100	
IGILU1166	Porch	Good				2908	30	01/01/1992	100	
IGILU1167	Lattice Screening	Good				1098	20	01/01/1992	100	
IGILU1168	Windows	Good				3873	30	01/01/1992	100	
IGILU1583	Awnings	Good				9435	10	15/01/2010		

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU00021	Driveway	Good				21978		25/01/01/2004	100	
IGILU1169	Roof	Good				13320		50/01/01/1992	100	

Unit 31

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1170	Insulation	Good				3069		20/01/01/1992	100	
IGILU1172	Sarking	Good				3174		25/01/01/1992	100	
IGILU1173	Hot Water System - Electric	Good	Dux Proflo	160F148G	51026102800	2386		12/01/01/1992	100	
IGILU1731	Lighting	Good				2025		15/03/07/2023	100	

Unit 32

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1225	Insulation	Good				3069		20/01/01/1992	100	
IGILU1227	Sarking	Good				3174		25/01/01/1992	100	
IGILU1228	Hot Water System - Electric	Good	Thermann	160THM136	17051630061H	2386		12/01/01/1992	100	
IGILU1769	Lighting	Good				1989		15/14/07/2023	100	

Unit 31**Bathroom**

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1197	Skylight	Excellent				1010		10/01/01/1992	100	
IGILU1704	Tiles - Floor	Good				2025		20/03/07/2023	100	
IGILU1708	Exhaust Fan	Good				2025		10/03/07/2023	100	
IGILU1709	Interior Painting	Good				2083		10/03/07/2023	100	
IGILU1710	Tapware	Good	Eurosmart			2025		15/03/07/2023	100	
IGILU1711	Tiles - Wall	Good				2025		20/03/07/2023	100	
IGILU1712	Toilet & Cistern	Good	Caroma			2612		20/03/07/2023	100	
IGILU1732	Laundry Cabinets	Good				4514		20/03/07/2023	100	
IGILU1733	Laundry Benchtop	Good				4514		20/03/07/2023	100	
IGILU1734	Sink & Fittings	Good	Posh Solus			2025		15/03/07/2023	100	
IGILU1735	Vanity	Good				2025		20/03/07/2023	100	
IGILU1736	Basin	Good				2025		15/03/07/2023	100	
IGILU1737	Shower Screen	Good				2891		20/03/07/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1186	Curtains	Good				1776		6/01/01/1992	100	
IGILU1702	Carpet	Good				3626		8/03/07/2023	100	
IGILU1713	Blind	Good	Vibe			2025		10/03/07/2023	100	
IGILU1714	Interior Painting	Good				2083		10/03/07/2023	100	
IGILU1715	Wardrobe	Good				2025		10/03/07/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1191	Curtains	Good				1776		6/01/01/1992	100	
IGILU1703	Carpet	Good				3626		8/03/07/2023	100	
IGILU1716	Blind	Good	Vibe			2025		10/03/07/2023	100	
IGILU1717	Interior Painting	Good				2083		10/03/07/2023	100	
IGILU1718	Wardrobe	Good				4514		10/03/07/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1707	Carpet	Good				3626		8/03/07/2023	100	
IGILU1719	Blind	Good	Vibe			2025		10/03/07/2023	100	
IGILU1720	Interior Painting	Good				2083		10/03/07/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1183	Smoke Alarms	Excellent				260		20/01/01/1992	100	
IGILU1701	Kitchen Cabinets	Good				12395		20/03/07/2023	100	
IGILU1721	Benchtops	Fair				19230		20/03/07/2023	100	
IGILU1722	Blind	Good	Vibe			2025		10/03/07/2023	100	
IGILU1723	Cooktop	Good	Fisher & Paykel			2025		12/03/07/2023	100	

IGILU1724	Interior Painting	Good					2083	10/03/07/2023	100	
IGILU1725	Oven	Excellent	Fisher & Paykel				2025	12/03/07/2023	100	
IGILU1726	Rangehood	Excellent	Fisher & Paykel				2025	12/03/07/2023	100	
IGILU1727	Sink & Fittings	Good	Posh Solus				2025	15/03/07/2023	100	
IGILU1728	Vinyl	Excellent					3626	10/03/07/2023	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1201	Air Conditioner - Split System	Excellent	Mitsubishi Heavy Industries	SRK60ZJX-S	117800018 RE		3296	10/01/01/1992	100	
IGILU1205	Curtains	Good					1776	6/01/01/1992	100	
IGILU1206	Heater	Good	Odyssey				865	15/01/01/1992	100	
IGILU1705	Carpet	Good					3626	8/03/07/2023	100	
IGILU1706	Interior Painting	Excellent					2083	10/03/07/2023	100	
IGILU1729	Blind	Good	Vibe				2025	10/03/07/2023	100	
IGILU1730	Ceiling Fan	Excellent	Ventair Spinika				2025	10/03/07/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1212	Clothesline	Good					499	10/01/01/1992	100	
IGILU1213	Courtyard	Good					2486	30/01/01/1992	100	
IGILU1214	Doors	Good					5605	30/01/01/1992	100	
IGILU1215	Downpipes	Good					1742	20/01/01/1992	100	
IGILU1216	Electrical Switchboard	Good					1964	20/01/01/1992	100	
IGILU1217	Exterior painting	Good					2086	10/01/01/1992	100	
IGILU1218	Fascias	Good					2874	20/01/01/1992	100	
IGILU1219	Flyscreens	Excellent					2186	10/01/01/1992	100	
IGILU1220	Guttering	Excellent					2819	20/01/01/1992	100	
IGILU1221	Path	Excellent					1509	30/01/01/1992	100	
IGILU1222	Porch	Excellent					2908	30/01/01/1992	100	
IGILU1223	Lattice Screening	Excellent					1098	20/01/01/1992	100	
IGILU1224	Windows	Excellent					3873	30/01/01/1992	100	
IGILU1584	Awnings	Good					9435	10/15/01/2010		

Unit 32

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1251	Skylight	Good					1010	10/01/04/2007	100	
IGILU1739	Tiles - Floor	Good					1989	20/14/07/2023	100	
IGILU1741	Exhaust Fan	Good					1989	10/14/07/2023	100	
IGILU1742	Interior Painting	Good					2074	10/14/07/2023	100	
IGILU1743	Tapware	Good	Eurosmart				1989	15/14/07/2023	100	
IGILU1744	Tiles - Wall	Good					1989	20/14/07/2023	100	
IGILU1745	Toilet & Cistern	Good	Caroma				2576	20/14/07/2023	100	
IGILU1770	Laundry Cabinets	Good					4505	20/14/07/2023	100	
IGILU1771	Laundry Benchtop	Good					4505	20/14/07/2023	100	
IGILU1772	Sink & Fittings	Good	Posh Solus				1989	15/14/07/2023	100	
IGILU1773	Vanity	Good					1989	20/14/07/2023	100	
IGILU1774	Basin	Good					1989	15/14/07/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1241	Curtains	Good					1776	6/01/04/2007	100	
IGILU1746	Blind	Good	Vibe				1989	10/14/07/2023	100	
IGILU1747	Carpet	Good					3617	8/14/07/2023	100	
IGILU1748	Ceiling Fan	Good	Ventair Spinika				1989	10/14/07/2023	100	
IGILU1749	Interior Painting	Good					2074	10/14/07/2023	100	
IGILU1750	Wardrobe	Good					4505	10/14/07/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1751	Blind	Good	Vibe				1989	10/14/07/2023	100	
IGILU1752	Carpet	Good					3617	8/14/07/2023	100	
IGILU1753	Interior Painting	Good					2074	10/14/07/2023	100	
IGILU1754	Wardrobe	Good					3665	10/14/07/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1755	Blind	Good	Vibe			1989	10	14/07/2023	100	
IGILU1757	Interior Painting	Good				2074	10	14/07/2023	100	
IGILU1777	Vinyl	Good				3617	10	14/07/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1237	Smoke Alarms	Good				260	20	01/04/2007	100	
IGILU1758	Benchtops	Good				17492	20	14/07/2023	100	
IGILU1759	Cooktop	Good	Fisher & Paykel			1989	12	14/07/2023	100	
IGILU1760	Interior Painting	Good				2074	10	14/07/2023	100	
IGILU1761	Kitchen Cabinets	Good				13197	20	14/07/2023	100	
IGILU1762	Oven	Good	Fisher & Paykel			1989	12	14/07/2023	100	
IGILU1763	Rangehood	Good	Fisher & Paykel			1989	12	14/07/2023	100	
IGILU1764	Sink & Fittings	Good	Posh Solus			1989	15	14/07/2023	100	
IGILU1765	Vinyl	Good				3617	10	14/07/2023	100	
IGILU1841	Dishwasher	Excellent				1332	8	14/07/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1255	Air Conditioner - Split System	Good	Daikin	ATXD80CV4	Daikin FTXV71W	3296		10/03/10/2023		
IGILU1259	Curtains	Good				1776		6/01/04/2007	100	
IGILU1260	Heater	Good	IXL	28G9AA		865	15	01/04/2007	100	
IGILU1740	Interior Painting	Good				2074	10	14/07/2023	100	
IGILU1766	Blind	Good	Vibe			1989	10	14/07/2023	100	
IGILU1768	Ceiling Fan	Good	Ventair Spinika			1989	10	14/07/2023	100	
IGILU1776	Vinyl	Good				3617	10	14/07/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1265	Clothesline	Good				499		10/01/01/1992	100	
IGILU1266	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1267	Doors	Good				5605		30/01/01/1992	100	
IGILU1268	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1269	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1270	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1271	Fascias	Good				2874		20/01/01/1992	100	
IGILU1272	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU1273	Guttering	Good				2819		20/01/01/1992	100	
IGILU1274	Path	Good				1509		30/01/01/1992	100	
IGILU1275	Porch	Good				2908		30/01/01/1992	100	
IGILU1276	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU1277	Windows	Good				3873		30/01/01/1992	100	
IGILU1585	Awnings	Good				9435		10/15/01/2010		

Unit 39-40

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002m	Driveway	Good				21978		25/01/04/2021	100	
IGILU1278	Roof	Good				13320		50/01/01/1992	100	

Unit 39

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1279	Insulation	Good				3069		20/01/01/1992	100	
IGILU1281	Sarking	Good				3174		25/01/01/1992	100	
IGILU1282	Hot Water System - Electric	Good	Dux Proflo	160F148G	70115100790	2386		12/01/01/1992	100	
IGILU1803	Lighting	Good				5830		15/08/09/2023	100	

Unit 40

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1325	Insulation	Good				3069		20/01/01/1992	100	
IGILU1326	Lighting	Good				1909		15/01/01/1992	100	

IGILU1327	Sarking	Good				3174	25/01/1992	100	
IGILU1328	Hot Water System - Electric	Good	Dux Proflo	160S136	1.11114E+11	2386	12/01/1992	100	

Unit 39

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1300	Skylight	Good				1010		10/01/06/2004	100	
IGILU1778	Exhaust Fan	Good				2112		10/08/09/2023	100	
IGILU1779	Interior Painting	Good				2112		10/08/09/2023	100	
IGILU1780	Tapware	Good	Eurosmart			2112		15/08/09/2023	100	
IGILU1781	Tiles - Floor	Good				2112		20/08/09/2023	100	
IGILU1782	Tiles - Wall	Good				2112		20/08/09/2023	100	
IGILU1783	Toilet & Cistern	Good	Caroma			2833		20/08/09/2023	100	
IGILU1806	Laundry Cabinets	Good				4387		20/08/09/2023	100	
IGILU1807	Laundry Benchtop	Good				5053		20/08/09/2023	100	
IGILU1808	Sink & Fittings	Good	Posh Solus			2112		15/08/09/2023	100	
IGILU1809	Vanity	Good				2112		20/08/09/2023	100	
IGILU1810	Basin	Good				2315		15/08/09/2023	100	
IGILU1811	Shower Screen	Good				3055		20/08/09/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1784	Blind	Good	Vibe			2112		10/08/09/2023	100	
IGILU1785	Carpet	Good				2112		8/08/09/2023	100	
IGILU1786	Interior Painting	Good				2112		10/08/09/2023	100	
IGILU1787	Wardrobe	Good				2112		10/08/09/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1788	Blind	Good	Vibe			2112		10/08/09/2023	100	
IGILU1790	Interior Painting	Good				2949		10/08/09/2023	100	
IGILU1804	Vinyl	Good				2112		10/08/09/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1292	Smoke Alarms	Good				260		20/01/06/2004	100	
IGILU1791	Benchtops	Good				20038		20/08/09/2023	100	
IGILU1792	Blind	Good	Vibe			2112		10/08/09/2023	100	
IGILU1793	Cooktop	Good	Fisher & Paykel			2112		12/08/09/2023	100	
IGILU1794	Interior Painting	Good				2112		10/08/09/2023	100	
IGILU1795	Kitchen Cabinets	Good				13082		20/08/09/2023	100	
IGILU1796	Oven	Good	Fisher & Paykel			2112		12/08/09/2023	100	
IGILU1797	Rangehood	Good	Fisher & Paykel			2112		12/08/09/2023	100	
IGILU1798	Sink & Fittings	Good	Posh Solus			2112		15/08/09/2023	100	
IGILU1799	Vinyl	Good				2112		10/08/09/2023	100	
IGILU1842	Dishwasher	Excellent				1332		8/08/09/2023		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1304	Air Conditioner - Split System	Good	Daikin			3296		10/01/06/2004	100	
IGILU1307	Heater	Good	IXL	11A1AD		865		15/01/06/2004	100	
IGILU1800	Blind	Good	Vibe			2112		10/08/09/2023	100	
IGILU1802	Interior Painting	Good				2949		10/08/09/2023	100	
IGILU1805	Vinyl	Good				2112		10/08/09/2023	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1312	Clothesline	Good				499		10/01/01/1992	100	
IGILU1313	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1314	Doors	Good				5605		30/01/01/1992	100	
IGILU1315	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1316	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1317	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1318	Fascias	Good				2874		20/01/01/1992	100	

IGILU1319	Flyscreens	Good					2186	10/01/1992	100	
IGILU1320	Guttering	Good					2819	20/01/1992	100	
IGILU1321	Path	Good					1509	30/01/1992	100	
IGILU1322	Porch	Good					2908	30/01/1992	100	
IGILU1324	Windows	Good					3873	30/01/1992	100	
IGILU1586	Awnings	Good					9435	10/15/01/2010		

Unit 40

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1343	Exhaust Fan	Good				255		10/01/12/2012	100	
IGILU1344	Interior Painting	Good				466		10/01/12/2012	100	
IGILU1345	Toilet & Cistern	Good				1343		20/01/12/2012	100	
IGILU1346	Skylight	Good				1010		10/01/12/2012	100	
IGILU1347	Tapware	Good				1304		15/01/12/2012	100	
IGILU1348	Tiles - Wall	Good				3285		20/01/12/2012	100	
IGILU1349	Tiles - Floor	Good				4884		20/01/12/2012	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1338	Blind	Good				333		10/01/12/2012	100	
IGILU1339	Carpet	Good				1032		8/01/12/2012	100	
IGILU1340	Curtains	Good				1776		6/01/12/2012	100	
IGILU1341	Interior Painting	Good				888		10/01/12/2012	100	
IGILU1342	Wardrobe	Good				2053		10/01/12/2012	100	
IGILU1849	Ceiling Fan	Excellent	Spinka			100		10/04/03/2024		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1356	Blind	Good				388		10/01/12/2012	100	
IGILU1358	Interior Painting	Good				832		10/01/12/2012	100	
IGILU1618	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1621	Vinyl	Good				1665		10/20/10/2022	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1329	Benchtops	Good				2342		20/01/12/2012	100	
IGILU1330	Cooktop	Good	Fisher & Paykel			1354		12/01/12/2012	100	
IGILU1331	Interior Painting	Good				710		10/01/12/2012	100	
IGILU1332	Kitchen Cabinets	Good				3818		20/01/12/2012	100	
IGILU1333	Vinyl	Good				1010		10/01/12/2012	100	
IGILU1334	Oven	Good	Fisher & Paykel	OB60SC7CEX2	CRV284313	1409		12/01/12/2012	100	
IGILU1335	Rangehood	Good	Fisher & Paykel			599		12/01/12/2012	100	
IGILU1336	Sink & Fittings	Good				1587		15/01/12/2012	100	
IGILU1337	Smoke Alarms	Good				260		20/01/12/2012	100	
IGILU1620	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAN330120	1332		8/20/10/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1350	Air Conditioner - Split System	Good	Daikin	FTYN50DV1A	E002334	3296		10/01/12/2012	100	
IGILU1351	Blind	Good				388		10/01/12/2012	100	
IGILU1353	Curtains	Good				1776		6/01/12/2012	100	
IGILU1354	Heater	Good	IXL			865		15/01/12/2012	100	
IGILU1355	Interior Painting	Good				1176		10/01/12/2012	100	
IGILU1619	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1622	Vinyl	Good				1665		10/20/10/2022	100	
IGILU1850	Ceiling Fan	Excellent	Spinka			100		10/04/03/2024		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1359	Clothesline	Good				499		10/01/01/1992	100	
IGILU1360	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1361	Doors	Good				5605		30/01/01/1992	100	
IGILU1362	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1363	Electrical Switchboard	Good				1964		20/01/01/1992	100	

IGILU1364	Exterior painting	Good				2086		10/01/1992	100	
IGILU1365	Fascias	Good				2874		20/01/1992	100	
IGILU1366	Flyscreens	Good				2186		10/01/1992	100	
IGILU1367	Guttering	Good				2819		20/01/1992	100	
IGILU1368	Path	Good				1509		30/01/1992	100	
IGILU1369	Porch	Good				2908		30/01/1992	100	
IGILU1370	Lattice Screening	Good				1098		20/01/1992	100	
IGILU1371	Windows	Good				3873		30/01/1992	100	
IGILU1588	Awnings	Good				9435		10/15/2010		

Unit 41-42

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU0002n	Driveway	Good				21978		25/01/2004	100	
IGILU1372	Roof	Good				13320		50/01/1992	100	

Unit 41

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1373	Insulation	Good				3069		20/01/1992	100	
IGILU1374	Lighting	Good				1909		15/01/1992	100	
IGILU1375	Sarking	Good				3174		25/01/1992	100	
IGILU1376	Hot Water System - Electric	Good	Thermann			2386		12/01/1992	100	

Unit 42

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1423	Insulation	Good				3069		20/01/1992	100	
IGILU1424	Lighting	Good				1909		15/01/1992	100	
IGILU1425	Sarking	Good				3174		25/01/1992	100	
IGILU1426	Hot Water System - Electric	Good	Dux Proflo	160S136	13051420171H	2386		12/01/1992	100	

Unit 41

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1395	Exhaust Fan	Good				255		10/01/1992	100	
IGILU1396	Interior Painting	Good				466		10/01/03/2021	100	
IGILU1397	Toilet & Cistern	Good				1343		20/01/1992	100	
IGILU1398	Skylight	Good				1010		10/01/1992	100	
IGILU1399	Tapware	Good				1304		15/01/1992	100	
IGILU1400	Tiles - Wall	Good				3285		20/01/1992	100	
IGILU1401	Tiles - Floor	Good				4884		20/01/1992	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1387	Blind	Good				333		10/01/1992	100	
IGILU1388	Carpet	Good				1032		8/01/03/2021	100	
IGILU1389	Interior Painting	Good				888		10/01/03/2021	100	
IGILU1390	Wardrobe	Good				2053		10/01/1992	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1391	Blind	Good				333		10/01/1992	100	
IGILU1392	Carpet	Good				688		8/01/03/2021	100	
IGILU1393	Interior Painting	Good				588		10/01/03/2021	100	
IGILU1394	Wardrobe	Good				2053		10/01/1992	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1407	Blind	Good				388		10/01/1992	100	
IGILU1408	Carpet	Good				910		8/01/03/2021	100	
IGILU1409	Interior Painting	Good				832		10/01/03/2021	100	
IGILU1843	Air Conditioner - Split System	Good	Daikin	FTXS71LMVA		1563		10/12/2023		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1377	Blind	Good				333		10/01/1992	100	

IGILU1378	Benchtops	Good				2342		20/01/1992	100	
IGILU1379	Cooktop	Good	Chef Premier			1354		12/01/1992	100	
IGILU1380	Interior Painting	Good				710		10/01/03/2021	100	
IGILU1381	Kitchen Cabinets	Good				3818		20/01/01/1992	100	
IGILU1382	Vinyl	Good				1010		10/01/03/2021	100	
IGILU1383	Electric Elevated Oven	Good	Chef	EECRO31W	10360157	1409		12/01/01/1992	100	
IGILU1384	Rangehood	Good	Everdure			599		12/01/01/1992	100	
IGILU1385	Sink & Fittings	Good				1587		15/01/01/1992	100	
IGILU1386	Smoke Alarms	Good	Clipsal			260		20/01/01/1992	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1403	Blind	Good				388		10/01/01/1992	100	
IGILU1404	Carpet	Good				1165		8/01/03/2021	100	
IGILU1405	Heater	Good	IXL	11A1AD		865		15/05/09/2023		
IGILU1406	Interior Painting	Good				1176		10/01/03/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1410	Clothesline	Good				499		10/01/01/1992	100	
IGILU1411	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1412	Doors	Good				5605		30/01/01/1992	100	
IGILU1413	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1414	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1415	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1416	Fascias	Good				2874		20/01/01/1992	100	
IGILU1417	Flyscreens	Good				2186		10/01/01/1992	100	
IGILU1418	Guttering	Good				2819		20/01/01/1992	100	
IGILU1419	Path	Good				1509		30/01/01/1992	100	
IGILU1420	Porch	Good				2908		30/01/01/1992	100	
IGILU1421	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU1422	Windows	Good				3873		30/01/01/1992	100	
IGILU1589	Awnings	Good				9435		10/15/01/2010		

Unit 42

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1447	Exhaust Fan	Good				255		10/01/09/2013	100	
IGILU1448	Interior Painting	Good				466		10/01/09/2013	100	
IGILU1449	Toilet & Cistern	Good				1343		20/01/09/2013	100	
IGILU1450	Skylight	Good				1010		10/01/09/2013	100	
IGILU1451	Tapware	Good				1304		15/01/09/2013	100	
IGILU1452	Tiles - Wall	Good				3285		20/01/09/2013	100	
IGILU1453	Tiles - Floor	Good				4884		20/01/09/2013	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1437	Blind	Good				333		10/01/09/2013	100	
IGILU1438	Carpet	Good				1032		8/01/09/2013	100	
IGILU1439	Curtains	Good				1776		6/01/09/2013	100	
IGILU1440	Interior Painting	Good				888		10/01/09/2013	100	
IGILU1441	Wardrobe	Good				2053		10/01/09/2013	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1442	Blind	Good				333		10/01/09/2013	100	
IGILU1443	Carpet	Fair				688		8/01/09/2013	100	
IGILU1444	Curtains	Good				1776		6/01/09/2013	100	
IGILU1445	Interior Painting	Good				588		10/01/09/2013	100	
IGILU1446	Wardrobe	Good				2053		10/01/09/2013	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1460	Blind	Good				388		10/01/09/2013	100	
IGILU1461	Carpet	Good				910		8/01/09/2013	100	

IGILU1462	Curtains	Good				1776		6/01/09/2013	100	
IGILU1463	Interior Painting	Good				832		10/01/09/2013	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1427	Benchtops	Good				2342		20/01/09/2013	100	
IGILU1428	Cooktop	Good	Chef Premier			1354		12/01/09/2013	100	
IGILU1429	Curtains	Good				444		6/01/09/2013	100	
IGILU1430	Interior Painting	Good				710		10/01/09/2013	100	
IGILU1431	Kitchen Cabinets	Good				3818		20/01/09/2013	100	
IGILU1432	Vinyl	Good				1010		10/01/09/2013	100	
IGILU1433	Electric Elevated Oven	Good	Chef	EECL031W	11760059	1409		12/01/09/2013	100	
IGILU1434	Rangehood	Good				599		12/01/09/2013	100	
IGILU1435	Sink & Fittings	Good				1587		15/01/09/2013	100	
IGILU1436	Smoke Alarms	Good				260		20/01/09/2013	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1454	Air Conditioner - Split System	Good	Panasonic	CS-A248KP	335638562	3296		10/01/09/2013	100	
IGILU1455	Blind	Good				388		10/01/09/2013	100	
IGILU1456	Carpet	Good				1165		8/01/09/2013	100	
IGILU1457	Curtains	Good				1776		6/01/09/2013	100	
IGILU1458	Heater	Good	IXL	27D1AE		865		15/01/09/2013	100	
IGILU1459	Interior Painting	Good				1176		10/01/09/2013	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
IGILU1464	Clothesline	Good				499		10/01/01/1992	100	
IGILU1465	Courtyard	Good				2486		30/01/01/1992	100	
IGILU1466	Doors	Good				5605		30/01/01/1992	100	
IGILU1467	Downpipes	Good				1742		20/01/01/1992	100	
IGILU1468	Electrical Switchboard	Good				1964		20/01/01/1992	100	
IGILU1469	Exterior painting	Good				2086		10/01/01/1992	100	
IGILU1470	Fascias	Good				2874		20/01/01/1992	100	
IGILU1471	Flyscreens	Fair				2186		10/01/01/1992	100	
IGILU1472	Guttering	Good				2819		20/01/01/1992	100	
IGILU1473	Path	Good				1509		30/01/01/1992	100	
IGILU1474	Porch	Good				2908		30/01/01/1992	100	
IGILU1475	Lattice Screening	Good				1098		20/01/01/1992	100	
IGILU1476	Windows	Good				3873		30/01/01/1992	100	
IGILU1590	Awnings	Good				9435		10/15/01/2010		