| Sarage 1-14 | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|-----------------------|
| | | | • | `, | | | | | | |
| | LNILU4083 | Roof | \$ 38414.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| | LNILU4084 | Fascias | \$ 11844.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Repair | Fascia needs painting |
| Garage 15-21 | <u></u> | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4099 | Roof | \$ 19207.00 | 50 | 01-07-1982 | 7.3 years | 33.24% | Good | Retain | N/A |
| | LNILU4100 | Fascias | \$ 5922.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Fair | Retain | N/A |
| Garage 22-28 | 3 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4108 | Roof | \$ 19207.00 | 50 | 01-07-1982 | 7.3 years | 33.24% | Good | Retain | N/A |
| | LNILU4109 | Fascias | \$ 5922.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Fair | Retain | N/A |
| Sarage 29-37 | 7 | | | | | , | <u>'</u> | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4117 | Roof | \$ 21951.00 | 50 | 01-07-1982 | 7.3 years | 0.87% | Fair | Repair | N/A |
| | LNILU4118 | Fascias | \$ 7402.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| Garage 38-41 | 1 | | | | | | <u>'</u> | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4128 | Roof | \$ 12347.00 | 50 | 01-07-1982 | 7.3 years | 10.50% | Good | Retain | N/A |
| | LNILU4129 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 14.43% | Good | Retain | N/A |
| Sarage 42-48 | 3 | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4134 | Roof | \$ 19207.00 | 50 | 01-07-1982 | 7.3 years | 33.24% | Good | Retain | N/A |
| | LNILU4135 | Fascias | \$ 5922.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| Sarage 50-52 | 2 | | ' | | | | 1 | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4143 | Roof | \$ 8917.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |

| LNILU4144 Fascias \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Fair | Retain | N/A |
|------------------------------|----|------------|-------------|--------|------|--------|-----|
|------------------------------|----|------------|-------------|--------|------|--------|-----|

Garage 53-55

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU4148 | Roof | \$ 8917.00 | 50 | 01-07-1982 | 7.3 years | 2.62% | Good | Retain | N/A |
| LNILU4149 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |

Grounds

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------------------------------------------------------------------------------|
| LNILU4153 | Distribution Board | \$ 1497.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | N/A |
| LNILU4154 | Drainage | \$ 1063.00 | 50 | 01-07-1982 | 7.3 years | 139.46% | Good | Retain | N/A |
| LNILU4155 | Fencing | \$ 25724.00 | 20 | 01-07-1982 | -22.7 years | 29.95% | Good | Retain | N/A |
| LNILU4156 | Gas Meter | \$ 1063.00 | 15 | 01-07-1982 | -27.7 years | 0.00% | Good | Retain | N/A |
| LNILU4157 | Handrails | \$ 4801.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4158 | Kerb & Gutter | \$ 130336.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| LNILU4159 | Letterboxes | \$ 14176.00 | 30 | 01-07-1982 | -12.7 years | 3.79% | Good | Retain | N/A |
| LNILU4160 | Power Supply | \$ 1063.00 | 40 | 01-07-1982 | -2.7 years | 0.00% | Good | Retain | N/A |
| LNILU4161 | Roads | \$ 720279.00 | 25 | 01-07-1982 | -17.7 years | 33.24% | Good | Retain | Storage bay adjacent to garage 28 in disrepair - cracking to pathway adjacent to Unit 27Have been resurfaced |
| LNILU4162 | Sewer | \$ 1063.00 | 80 | 01-07-1982 | 37.3 years | 0.00% | Good | Retain | N/A |
| LNILU4163 | Signage | \$ 2286.00 | 7 | 01-07-1982 | -35.7 years | 63.02% | Good | Retain | N/A |
| LNILU4164 | Street Lighting | \$ 1063.00 | 15 | 01-07-1982 | -27.7 years | 0.00% | Good | Retain | N/A |
| LNILU4165 | Telephone/Com ms services | \$ 1063.00 | 40 | 01-07-1982 | -2.7 years | 0.00% | Good | Retain | N/A |
| LNILU4166 | Water Mains | \$ 1063.00 | 80 | 01-07-1982 | 37.3 years | 0.00% | Fair | Repair | Cover missing from water meter |
| LNILU4167 | Hydrants | \$ 1063.00 | 30 | 01-07-1982 | -12.7 years | 0.00% | Good | Repair | N/A |

Community Hall

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|-----------------------------------|
| LNILU4048 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 28.86% | Good | Retain | N/A |
| LNILU4050 | Interior Painting | \$ 15434.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU4051 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU4052 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 5.67% | Fair | Retain | N/A |
| LNILU4053 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| LNILU4054 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| LNILU4057 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU4058 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | These A/Cs are in Recreation Room |
| LNILU4629 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4630 | Ceiling Fan | \$ 605.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Fair | Retain | N/A |
| LNILU4631 | Ceiling Fan | \$ 605.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4632 | Vinyl | \$ 1011.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4633 | Interior Painting | \$ 971.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4634 | Tapware | \$ 251.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4636 | Toilet & Cistern | \$ 1383.00 | 20 | 16-11-2022 | 17.7 years | 0.00% | Good | Retain | N/A |
| LNILU4637 | Interior Painting | \$ 971.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4638 | Tapware | \$ 251.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4640 | Toilet & Cistern | \$ 1383.00 | 20 | 16-11-2022 | 17.7 years | 0.00% | Good | Retain | N/A |
| LNILU4957 | Tiles - Floor | \$ 4058.00 | 20 | 15-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4958 | Tiles - Floor | \$ 4058.00 | 20 | 15-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4959 | Carpet | \$ 891.00 | 8 | 10-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |

Community Hall

Kitchen

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU4060 | Blind | \$ 277.00 | 10 | 01-07-1982 | -32.7 years | 3.61% | Good | Retain | N/A |
| LNILU4061 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |

| LNILU4063 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 27.03% | Fair | Repair | Lamination on kitchen cabinet is lifting |
|-----------|---------------------|------------|----|------------|-------------|---------|------|--------|------------------------------------------|
| LNILU4064 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 28.45% | Poor | Repair | Lifting vinyl poses as a trip hazard |
| LNILU4067 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| LNILU4068 | Fridge | \$ 1143.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU4070 | Microwave | \$ 342.00 | 8 | 01-07-1982 | -34.7 years | 0.00% | Good | Retain | N/A |
| LNILU4071 | Kettle | \$ 114.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU4072 | Fridge | \$ 1143.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU4623 | Ceiling Fan | \$ 605.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Fair | Retain | N/A |
| LNILU4624 | Cooktop | \$ 1394.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4625 | Cooktop | \$ 1394.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4626 | Dishwasher | \$ 800.00 | 8 | 16-11-2022 | 5.7 years | 0.00% | Good | Retain | N/A |
| LNILU4627 | Oven | \$ 958.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4628 | Oven | \$ 958.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|----------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|------------------------------|
| LNILU4074 | BBQ | \$ 571.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU4075 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 12.76% | Good | Retain | N/A |
| LNILU4076 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 33.26% | Poor | Retain | N/A |
| LNILU4077 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU4078 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | Some areas have been painted |
| LNILU4079 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU4080 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 108.28% | Good | Retain | N/A |
| LNILU4081 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU4082 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU4960 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 0.00% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------|--------------|-------------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| | LNILU4085 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| arage 2 | | , | | , | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4086 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 17.49% | Good | Retain | N/A |
| arage 3 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4087 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 61.23% | Good | Retain | N/A |
| arage 4 | | | | | | | _ | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4088 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 63.15% | Good | Retain | N/A |
| rage 5 | | | | | | | | , | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4089 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| rage 6 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4090 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 4.37% | Fair | Repair | N/A |
| arage 7 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4091 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| arage 8 | | | , | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | | |
| | LNILU4092 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 56.86% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|---------------------|-------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| | LNILU4093 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 52.48% | Good | Retain | N/A |
| Gara | ge 10 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4094 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| Gara | ge 11 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4095 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| Gara | ge 12 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4096 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 56.86% | Good | Retain | N/A |
| Gara | ge 13 | | | | | | | | - | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4097 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 83.10% | Good | Retain | N/A |
| Gara | ge 14 | | | | | | | | - | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4098 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| 5-21 | | | | | | | | | | |
| | | | | | | | | | | |
| Gara | ge 15 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4101 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| Gara | ge 16 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4102 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| | | | | | | | | | | |

Garage 9

| | LNILU410 | 3 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 175.82% | Good | Retain | N/A |
|------------|----------------------------------------------|------|------------------------------------------------------------------|-----------------------------------------------|--------------------|-------------------------------------------|---------------------------------------------------|-----------------------------------------------------|------------------------|-----------------------|---------------|
| Gar | age 18 | | 2001 | | | | | | | | |
| | Asset Nu | mber | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU410 | ı | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 61.23% | Good | Retain | N/A |
| Gar | age 19 | | | | | | | | | | |
| | Asset Nu | mber | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU410 | 5 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| Gar | age 20 | | | | | | | | | | |
| | Asset Nu | mber | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU410 | 5 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| Gar | age 21 | | | | | | | | | | |
| | Asset Nu | mber | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU410 | , | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | | | Door | | | | | | | | |
| 8 | | | Door | | | | | | | | |
| | age 22 | | Door | | | | | | | | |
| | age 22 Asset Nu | mber | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | | | | Acquisition Cost (\$) \$ 5716.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 78.73% | Asset Condition Good | Plan Retain | Commen N/A |
| Gar | Asset Nu | | Asset Name Electric Roller | | | | | i i | | | |
| Gar | Asset Nu LNILU411 | | Asset Name Electric Roller | | | | | i i | | | N/A |
| Gar | Asset Nu LNILU411 | mber | Asset Name Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 78.73% | Good | Retain | N/A |
| Gar Gar | Asset Nu LNILU411 rage 23 Asset Nu | mber | Asset Name Electric Roller Door Asset Name Electric Roller | \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -32.7 years Remaining Effective Life | 78.73% Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain | Comment |
| Gar Gar | Asset Nu LNILU411 Fage 23 Asset Nu LNILU411 | mber | Asset Name Electric Roller Door Asset Name Electric Roller | \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -32.7 years Remaining Effective Life | 78.73% Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain | N/A Comment |
| Gar Gar | Asset Nu LNILU411 rage 23 Asset Nu LNILU411 | mber | Asset Name Electric Roller Door Asset Name Electric Roller Door | \$ 5716.00 Acquisition Cost (\$) \$ 5716.00 | Effective Life (Y) | 01-07-1982 Installation Date 01-07-1982 | -32.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 174.95% | Asset Condition Good | Plan Retain | Commer N/A |

Remaining Effective Life

Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

Installation Date

Acquisition Cost (\$) Effective Life (Y)

Garage 17

Asset Number

Asset Name

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commer |
|------------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|--------------------------------------------------------------------|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|--------------------------|---------------------|
| | LNILU4113 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 83.10% | Good | Retain | N/A |
| Garage 26 | | D001 | | | | | | | | |
| Garage 20 | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commer |
| | LNILU4114 | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 43.74% | Good | Retain | N/A |
| | LIVILOTTIT | Door | \$ 37 10.00 | | 01 07 1302 | 32.7 years | 13.7170 | Good | Retuin | 14// |
| Garage 27 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme |
| | LNILU4115 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 17.49% | Good | Retain | N/A |
| Garage 28 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme |
| | 15111114446 | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | LNILU4116 | Door Door | \$ 37 10.00 | | | , | | | | |
| | LNILU4116 | | ¥ 37 10.00 | | | , | | | | |
| | LNILU4116 | | \$ 37 TO.00 | | | , | | | | |
| Garage 29 | LNILU4116 | | \$3710.00 | | | | | | | |
| Garage 29 | Asset Number | | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| Garage 29 | | Door | | | | | | | | |
| Garage 29 Garage 30 | Asset Number | Asset Name Electric Roller | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme |
| | Asset Number | Asset Name Electric Roller | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme N/A |
| | Asset Number LNILU4119 | Asset Name Electric Roller Door | Acquisition Cost (\$) \$ 5716.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 174.95% | Asset Condition Fair | Plan Retain | Comme |
| | Asset Number LNILU4119 Asset Number | Asset Name Electric Roller Door Asset Name Electric Roller | Acquisition Cost (\$) \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) 10 Effective Life (Y) | Installation Date 01-07-1982 Installation Date | Remaining Effective Life -32.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition 174.95% Accumulated Repair Cost as % of Acquisition | Asset Condition Fair Asset Condition | Plan Retain | Comme N/A |
| Garage 30 | Asset Number LNILU4119 Asset Number | Asset Name Electric Roller Door Asset Name Electric Roller | Acquisition Cost (\$) \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) 10 Effective Life (Y) | Installation Date 01-07-1982 Installation Date | Remaining Effective Life -32.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition 174.95% Accumulated Repair Cost as % of Acquisition | Asset Condition Fair Asset Condition | Plan Retain | Comme N/A |
| Garage 30 | Asset Number LNILU4119 Asset Number LNILU4120 | Asset Name Electric Roller Door Asset Name Electric Roller | Acquisition Cost (\$) \$ 5716.00 Acquisition Cost (\$) \$ 5716.00 | Effective Life (Y) 10 Effective Life (Y) 10 | Installation Date 01-07-1982 Installation Date 01-07-1982 | Remaining Effective Life -32.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 174.95% Accumulated Repair Cost as % of Acquisition 174.95% | Asset Condition Fair Asset Condition Good | Plan Retain Plan Retain | Comme N/A |
| Garage 30 | Asset Number LNILU4119 Asset Number LNILU4120 Asset Number | Asset Name Electric Roller Door Asset Name Electric Roller Door Asset Name Electric Roller | Acquisition Cost (\$) \$ 5716.00 Acquisition Cost (\$) \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) 10 Effective Life (Y) 10 Effective Life (Y) | Installation Date 01-07-1982 Installation Date 01-07-1982 Installation Date | Remaining Effective Life -32.7 years Remaining Effective Life -32.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition 174.95% Accumulated Repair Cost as % of Acquisition 174.95% Accumulated Repair Cost as % of Acquisition | Asset Condition Fair Asset Condition Good Asset Condition | Plan Retain Plan Retain | Comme N/A Comme |

01-07-1982 -32.7 years

174.95% Good

Retain

N/A

Garage 25

LNILU4122

Electric Roller

Door

\$ 5716.00

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------------|------------------------------------------------|--------------------------------------------------|-------------------------------------|--------------------|---------------------------------|---------------------------------------|-----------------------------------------------------|------------------------|-----------------------|-----------------|
| | LNILU4123 | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | LIVILOTIZS | Door | \$ 37 TO.00 | 10 | 01-07-1302 | 32.1 years | 174.55% | 3000 | Retain | IN/A |
| Garage : | 34 | | · | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4124 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| _ Garage : | 35 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4125 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Fair | Repair | N/A |
| Garage : | 36 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4126 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 17.49% | Good | Retain | N/A |
| Garage : | 37 | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4127 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Garage : | 38 | | | | | | | | | |
| Garage | 38 Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| Garage | | Asset Name Electric Roller Door | Acquisition Cost (\$) \$ 5716.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 174.95% | Asset Condition Poor | Plan Retain | Comments N/A |
| Garage | Asset Number LNILU4130 | Electric Roller | • | | | | · | | | |
| | Asset Number LNILU4130 | Electric Roller | • | | | | · | | | N/A |
| | Asset Number LNILU4130 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Poor | Retain | N/A |
| | Asset Number LNILU4130 Asset Number LNILU4131 | Electric Roller Door Asset Name Electric Roller | \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -32.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Poor Asset Condition | Retain | Comments |
| Garage : | Asset Number LNILU4130 Asset Number LNILU4131 | Electric Roller Door Asset Name Electric Roller | \$ 5716.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -32.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Poor Asset Condition | Retain | N/A Comments |

Garage 33

Door

| Garage | 41 |
|--------|----|
|--------|----|

Garage 42-48

Asset Number

Asset Name

| | LNILU4133 | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
|-----------|--------------|-------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|----------|------------|
| | | Door | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Garage 42 | | | | | | | | | | , |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4136 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 144.33% | Fair | Retain | Paint Door |
| Garage 43 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4137 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| Garage 44 | | | <u>'</u> | | | , | | | ' | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4138 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| Garage 45 | | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4139 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| Garage 46 | | | · | | | , | | | <u>'</u> | |
| _ | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4140 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 166.20% | Good | Retain | N/A |
| Garage 47 | | | | | | | | | <u>'</u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4141 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| Garage 48 | | | | | | | | | - | |
| _ | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4142 | Electric Roller | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Fair | Repair | N/A |

Remaining Effective Life

Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

Installation Date

Acquisition Cost (\$) Effective Life (Y)

| | Garage 50 | | | | | | | | | | |
|--------------|-----------|--------------|-------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4145 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | Garage 51 | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4146 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | Garage 52 | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4147 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 74.35% | Fair | Retain | N/A |
| Garage 53-55 | | | | | | | | | | | |
| | | | | | | | | | | | |
| | Garage 53 | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4150 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 174.95% | Good | Retain | N/A |
| | Garage 54 | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4151 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 61.23% | Good | Retain | N/A |
| | Garage 55 | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | LNILU4152 | Electric Roller Door | \$ 5716.00 | 10 | 01-07-1982 | -32.7 years | 78.73% | Good | Retain | N/A |
| Unit 1-2 | | | | | | | | | | | |
| | Common | | | | | | | | | | |
| | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | | | |

| | | • - | |
|----|----|------|--|
| L. | In | IIT. | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0199 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU0200 | Lighting | \$ 1966.00 | 15 | 01-10-2019 | 9.5 years | 23.33% | Good | Retain | N/A |
| LNILU0201 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 29.74% | Good | Retain | N/A |
| LNILU0202 | Smoke Alarms | \$ 268.00 | 20 | 01-10-2019 | 14.5 years | 17.54% | Good | Retain | N/A |

Unit 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0263 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU0264 | Lighting | \$ 1966.00 | 15 | 01-06-2014 | 4.2 years | 10.50% | Good | Retain | N/A |
| LNILU0265 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 12.25% | Good | Retain | N/A |
| LNILU0266 | Smoke Alarms | \$ 268.00 | 20 | 01-06-2014 | 9.2 years | 17.54% | Good | Retain | N/A |

Unit 1

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------|
| LNILU0224 | Exhaust Fan | \$ 262.00 | 10 | 01-10-2019 | 4.5 years | 12.29% | Good | Retain | N/A |
| LNILU0225 | Interior Painting | \$ 228.00 | 10 | 01-10-2019 | 4.5 years | 4.39% | Good | Retain | N/A |
| LNILU0226 | Shower Screen | \$ 1200.00 | 20 | 01-10-2019 | 14.5 years | 7.44% | Good | Retain | N/A |
| LNILU0227 | Skylight | \$ 1040.00 | 10 | 01-10-2019 | 4.5 years | 70.00% | Good | Retain | N/A |
| LNILU0228 | Tapware | \$ 1343.00 | 15 | 01-10-2019 | 9.5 years | 116.65% | Good | Retain | N/A |
| LNILU0229 | Tiles - Wall | \$ 3384.00 | 20 | 01-10-2019 | 14.5 years | 7.87% | Good | Retain | N/A |
| LNILU0230 | Tiles - Floor | \$ 4058.00 | 20 | 01-10-2019 | 14.5 years | 17.06% | Good | Retain | N/A |
| LNILU4961 | Vanity | \$ 1829.00 | 20 | 01-07-2024 | 19.3 years | 0.00% | Good | Retain | Glossy white vanity and basin |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-----------------------------|
| LNILU0212 | Blind | \$ 342.00 | 10 | 01-10-2019 | 4.5 years | 14.91% | Good | Retain | N/A |
| LNILU0213 | Carpet | \$ 891.00 | 8 | 01-10-2019 | 2.5 years | 21.34% | Good | Retain | N/A |
| LNILU0214 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2019 | 4.5 years | 35.04% | Good | Retain | N/A |
| LNILU0215 | Interior Painting | \$ 726.00 | 10 | 01-10-2019 | 4.5 years | 13.99% | Good | Retain | N/A |
| LNILU0216 | Wardrobe | \$ 2115.00 | 10 | 01-10-2019 | 4.5 years | 34.11% | Fair | Retain | General usage wear and tear |

| Red | 2 |
|-----|---|
| | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------|---------------------|---------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|---------------------------------------------|
| | LNILU0217 | Blind | \$ 342.00 | 10 | 01-10-2019 | 4.5 years | 0.88% | Good | Retain | N/A |
| | LNILU0218 | Carpet | \$ 743.00 | 8 | 01-10-2019 | 2.5 years | 21.87% | Good | Retain | N/A |
| | LNILU0219 | Interior Painting | \$ 605.00 | 10 | 01-10-2019 | 4.5 years | 35.04% | Good | Retain | N/A |
| | LNILU0220 | Wardrobe | \$ 2115.00 | 10 | 01-10-2019 | 4.5 years | 14.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0241 | Blind | \$ 400.00 | 10 | 01-10-2019 | 4.5 years | 15.75% | Good | Retain | N/A |
| | LNILU0242 | Carpet | \$ 640.00 | 8 | 01-10-2019 | 2.5 years | 9.30% | Good | Retain | N/A |
| | LNILU0243 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2019 | 4.5 years | 33.29% | Good | Retain | N/A |
| | LNILU0244 | Interior Painting | \$ 514.00 | 10 | 01-10-2019 | 4.5 years | 1.75% | Good | Retain | N/A |
| Hallway | | | | | | | 1 | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0245 | Carpet | \$ 354.00 | 8 | 01-10-2019 | 2.5 years | 6.02% | Good | Retain | N/A |
| | LNILU0246 | Interior Painting | \$ 285.00 | 10 | 01-10-2019 | 4.5 years | 1.75% | Good | Retain | N/A |
| Kitchen | | | | | | | 1 | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0203 | Blind | \$ 285.00 | 10 | 01-10-2019 | 4.5 years | 1.75% | Good | Retain | N/A |
| | LNILU0204 | Benchtops | \$ 2414.00 | 20 | 01-10-2019 | 14.5 years | 8.53% | Good | Retain | N/A |
| | LNILU0205 | Cooktop | \$ 1394.00 | 12 | 01-10-2019 | 6.5 years | 28.44% | Fair | Retain | Corrosion around hobs, continue to monitor. |
| | LNILU0206 | Interior Painting | \$ 434.00 | 10 | 01-10-2019 | 4.5 years | 4.38% | Good | Retain | N/A |
| | LNILU0207 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-10-2019 | 14.5 years | 2.62% | Good | Retain | N/A |
| | LNILU0208 | Vinyl | \$ 1011.00 | 10 | 01-10-2019 | 4.5 years | 39.39% | Good | Retain | N/A |
| | LNILU0209 | Oven | \$ 1451.00 | 12 | 01-10-2019 | 6.5 years | 58.35% | Good | Retain | N/A |
| | LNILU0210 | Rangehood | \$ 617.00 | 12 | 01-10-2019 | 6.5 years | 6.56% | Fair | Retain | N/A |
| | LNILU0211 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2019 | 9.5 years | 116.69% | Good | Retain | N/A |

| Laundry |
|---------|
|---------|

| Laundry | | | | | | | | | | |
|---------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0221 | Interior Painting | \$ 257.00 | 10 | 01-10-2019 | 4.5 years | 35.02% | Good | Retain | N/A |
| | LNILU0222 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2019 | 14.5 years | 7.87% | Good | Retain | N/A |
| | LNILU0223 | Tiles - Floor | \$ 2086.00 | 20 | 01-10-2019 | 14.5 years | 17.50% | Fair | Retain | Regrouting will have to take place soon. |
| | LNILU4753 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4754 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4755 | Washing Machine | \$ 1371.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0236 | Air Conditioner - Split System | \$ 2369.00 | 10 | 03-07-2024 | 9.3 years | 0.00% | Good | Retain | |
| | LNILU0237 | Blind | \$ 400.00 | 10 | 01-10-2019 | 4.5 years | 0.88% | Good | Retain | N/A |

01-10-2019 2.5 years

01-10-2019 4.5 years

01-10-2019 4.5 years

8

10

10

Toilet room

LNILU0238

LNILU0239

LNILU0240

Carpet

Ceiling Fan

Interior Painting

\$ 1371.00

\$ 605.00

\$ 1097.00

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------------------------|
| LNILU0231 | Skylight | \$ 1040.00 | 10 | 01-10-2019 | 4.5 years | 70.00% | Good | Retain | N/A |
| LNILU0232 | Toilet & Cistern | \$ 1383.00 | 20 | 01-10-2019 | 14.5 years | 85.30% | Good | Repair | Resident advised the flushing buttons stick |
| LNILU0233 | Tiles - Wall | \$ 926.00 | 20 | 01-10-2019 | 14.5 years | 0.44% | Good | Retain | N/A |
| LNILU0234 | Tiles - Floor | \$ 1429.00 | 20 | 01-10-2019 | 14.5 years | 17.06% | Good | Retain | N/A |
| LNILU0235 | Tapware | \$ 251.00 | 15 | 01-10-2019 | 9.5 years | 49.67% | Good | Retain | N/A |
| LNILU4756 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

20.79% Good

35.04% Good

33.25% Good

N/A

N/A

N/A

Retain

Retain

Retain

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|------------------------|
| LNILU0247 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 273.64% | Good | Retain | N/A |
| LNILU0248 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Good | Retain | No key for screen door |

| | | | | | | | | | damaged awning |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|---------|-----------------------------------------------------------|
| LNILU4168 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 16.48% | Poor | Replace | Holes present in the awning; Replacement required for the |
| LNILU0262 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Repair | N/A |
| LNILU0261 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.22% | Good | Retain | N/A |
| LNILU0260 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0259 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU0258 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 16.04% | Good | Retain | N/A |
| LNILU0257 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 0.73% | Fair | Repair | Path crack opposite kitchen window |
| LNILU0256 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU0255 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 4.08% | Good | Retain | N/A |
| LNILU0254 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Fair | Retain | Requires cleaning |
| LNILU0253 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 8.75% | Good | Retain | N/A |
| LNILU0252 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU0251 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU0250 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 13.12% | Good | Retain | Shared between uni 1/2 |
| LNILU0249 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 35.01% | Good | Retain | N/A |

Unit 2

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0288 | Exhaust Fan | \$ 262.00 | 10 | 01-06-2014 | -0.8 years | 33.36% | Good | Retain | N/A |
| LNILU0289 | Interior Painting | \$ 228.00 | 10 | 01-06-2014 | -0.8 years | 34.21% | Good | Retain | N/A |
| LNILU0290 | Shower Screen | \$ 1200.00 | 20 | 01-06-2014 | 9.2 years | 1.31% | Good | Retain | N/A |
| LNILU0291 | Skylight | \$ 1040.00 | 10 | 01-06-2014 | -0.8 years | 66.50% | Good | Retain | N/A |
| LNILU0292 | Tapware | \$ 1343.00 | 15 | 01-06-2014 | 4.2 years | 49.58% | Good | Retain | N/A |
| LNILU0293 | Tiles - Wall | \$ 3384.00 | 20 | 01-06-2014 | 9.2 years | 17.06% | Good | Retain | N/A |
| LNILU0294 | Tiles - Floor | \$ 4058.00 | 20 | 01-06-2014 | 9.2 years | 17.50% | Good | Retain | N/A |

| _ | | |
|----|---|--|
| ĸД | ~ | |
| uc | u | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|---------|-------------------------------|
| | LNILU0276 | Blind | \$ 342.00 | 10 | 01-06-2014 | -0.8 years | 35.09% | Poor | Replace | Roller blind |
| | LNILU0277 | Carpet | \$ 891.00 | 8 | 01-06-2014 | -2.8 years | 21.89% | Good | Retain | N/A |
| | LNILU0278 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2014 | -0.8 years | 35.04% | Good | Retain | N/A |
| | LNILU0279 | Interior Painting | \$ 726.00 | 10 | 01-06-2014 | -0.8 years | 14.87% | Good | Retain | N/A |
| | LNILU0280 | Wardrobe | \$ 2115.00 | 10 | 01-06-2014 | -0.8 years | 34.99% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0281 | Blind | \$ 342.00 | 10 | 01-06-2014 | -0.8 years | 1.75% | Good | Retain | N/A |
| | LNILU0282 | Carpet | \$ 743.00 | 8 | 01-06-2014 | -2.8 years | 3.83% | Good | Retain | N/A |
| | LNILU0283 | Interior Painting | \$ 605.00 | 10 | 01-06-2014 | -0.8 years | 14.89% | Good | Retain | N/A |
| | LNILU0284 | Wardrobe | \$ 2115.00 | 10 | 01-06-2014 | -0.8 years | 14.87% | Good | Retain | N/A |
| | LNILU4962 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Good | Retain | |
| Dining | | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0305 | Blind | \$ 400.00 | 10 | 01-06-2014 | -0.8 years | 35.00% | Good | Retain | N/A |
| | LNILU0306 | Carpet | \$ 640.00 | 8 | 01-06-2014 | -2.8 years | 7.11% | Good | Retain | N/A |
| | LNILU0307 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2014 | -0.8 years | 33.29% | Good | Retain | N/A |
| | LNILU0308 | Interior Painting | \$ 514.00 | 10 | 01-06-2014 | -0.8 years | 33.27% | Good | Retain | N/A |
| Hallway | | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0309 | Carpet | \$ 354.00 | 8 | 01-06-2014 | -2.8 years | 26.27% | Good | Retain | N/A |
| | LNILU0310 | Interior Painting | \$ 285.00 | 10 | 01-06-2014 | -0.8 years | 6.14% | Good | Retain | N/A |
| | LNILU4963 | Wardrobe | \$ 2115.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Good | Retain | Double door built ir wardrobe |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0267 | Blind | \$ 285.00 | 10 | 01-06-2014 | -0.8 years | 11.40% | Good | Retain | N/A |
| | LNILU0268 | Benchtops | \$ 2414.00 | 20 | 01-06-2014 | 9.2 years | 8.75% | Good | Retain | N/A |
| | LNILU0269 | Cooktop | \$ 1394.00 | 12 | 01-06-2014 | 1.2 years | 3.65% | Good | Retain | N/A |

| LNILU0270 | Interior Painting | \$ 434.00 | 10 | 01-06-2014 | -0.8 years | 14.88% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|------------|---------|------|--------|------------|
| LNILU0271 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-06-2014 | 9.2 years | 7.44% | Good | Retain | N/A |
| LNILU0272 | Vinyl | \$ 1011.00 | 10 | 01-06-2014 | -0.8 years | 26.26% | Good | Retain | N/A |
| LNILU0273 | Oven | \$ 1451.00 | 12 | 01-06-2014 | 1.2 years | 145.88% | Good | Retain | N/A |
| LNILU0274 | Rangehood | \$ 617.00 | 12 | 01-06-2014 | 1.2 years | 6.93% | Good | Retain | N/A |
| LNILU0275 | Sink & Fittings | \$ 1634.00 | 15 | 01-06-2014 | 4.2 years | 17.50% | Good | Retain | N/A |
| LNILU4964 | Tiles - Wall | \$ 834.00 | 20 | 01-07-2024 | 19.3 years | 0.00% | Good | Retain | Splashback |
| LNILU4965 | Fridge | \$ 1143.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Good | Retain | |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0285 | Interior Painting | \$ 257.00 | 10 | 01-06-2014 | -0.8 years | 14.88% | Good | Retain | N/A |
| LNILU0286 | Tiles - Wall | \$ 1246.00 | 20 | 01-06-2014 | 9.2 years | 17.06% | Good | Retain | N/A |
| LNILU0287 | Tiles - Floor | \$ 2086.00 | 20 | 01-06-2014 | 9.2 years | 17.50% | Good | Retain | N/A |
| LNILU4757 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4758 | Washing Machine | \$ 1371.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0300 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-06-2014 | -0.8 years | 314.93% | Good | Retain | N/A |
| LNILU0301 | Blind | \$ 400.00 | 10 | 01-06-2014 | -0.8 years | 4.38% | Good | Retain | N/A |
| LNILU0302 | Carpet | \$ 1371.00 | 8 | 01-06-2014 | -2.8 years | 21.88% | Good | Retain | N/A |
| LNILU0303 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2014 | -0.8 years | 35.04% | Good | Retain | N/A |
| LNILU0304 | Interior Painting | \$ 1097.00 | 10 | 01-06-2014 | -0.8 years | 35.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0295 | Skylight | \$ 1040.00 | 10 | 01-06-2014 | -0.8 years | 8.75% | Good | Retain | N/A |
| LNILU0296 | Toilet & Cistern | \$ 1383.00 | 20 | 01-06-2014 | 9.2 years | 87.49% | Good | Retain | N/A |
| LNILU0297 | Tiles - Wall | \$ 926.00 | 20 | 01-06-2014 | 9.2 years | 17.06% | Good | Retain | N/A |
| LNILU0298 | Tiles - Floor | \$ 1429.00 | 20 | 01-06-2014 | 9.2 years | 16.62% | Good | Retain | N/A |
| LNILU0299 | Tapware | \$ 251.00 | 15 | 01-06-2014 | 4.2 years | 116.86% | Good | Retain | N/A |

| | LNILU4759 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|-----------|--------------|-------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| Unit Exte | ior | | | | | | | | | |
| <u>—</u> | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------|
| LNILU0312 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0313 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 34.13% | Good | Retain | N/A |
| LNILU0315 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU0316 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU0317 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU0318 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 157.49% | Good | Retain | To be cleaned |
| LNILU0319 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |
| LNILU0320 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU0321 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 7.00% | Fair | Repair | Concrete is cracking |
| LNILU0322 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 17.49% | Good | Retain | N/A |
| LNILU0323 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU0324 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 4.96% | Good | Retain | N/A |
| LNILU0325 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 3.94% | Good | Retain | N/A |
| LNILU0326 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.72% | Good | Retain | N/A |
| LNILU4179 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Repair | N/A |

Unit 3-4

| Common | | | | | | | | | | |
|--------|------------------------|-----------------------|-------------------------------------|--------------------|------------------------------|---------------------------------|----------------------------------------------------|------------------------|-----------------------|-----------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0327 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 7.87% | Good | Retain | N/A |
| Unit 3 | | | | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number LNILU0328 | Asset Name Insulation | Acquisition Cost (\$) \$ 3224.00 | Effective Life (Y) | Installation Date 01-07-1982 | | Accumulated Repair Cost as % of Acquisition 0.00% | Asset Condition Good | Plan Retain | Comments N/A |
| | | | 1 | | 01-07-1982 | -22.7 years | • | | | |

| | LNILU0331 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 4.38% | Good | Retain | N/A |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Unit 4 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0392 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 16.31% | Good | Retain | N/A |
| | LNILU0393 | Lighting | \$ 1966.00 | 15 | 01-05-2013 | 3.1 years | 22.75% | Good | Retain | N/A |
| | LNILU0394 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU0395 | Smoke Alarms | \$ 268.00 | 20 | 01-05-2013 | 8.1 years | 7.46% | Good | Retain | N/A |
| | | ' | | | | | | | | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0353 | Exhaust fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 11.41% | Good | Retain | N/A |
| | LNILU0354 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 9.65% | Good | Retain | N/A |
| | LNILU0355 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU0356 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU0357 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 139.99% | Good | Retain | N/A |
| | LNILU0358 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 20.99% | Good | Retain | N/A |
| | LNILU0359 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| | LNILU4966 | Vanity | \$ 1829.00 | 20 | 01-07-2024 | 19.3 years | 0.00% | Good | Retain | Glossy white value of the control of |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0341 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0342 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU0343 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU0344 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU0345 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 33.24% | Good | Retain | N/A |
| | LNILU4762 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Bed 2 | | <u>'</u> | | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0346 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 14.91% | Good | Retain | N/A |
| | LIVILOUS40 | Dillia | 7 | | | | | | | |

| | LNILU0348 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 15.77% | Good | Retain | N/A |
|---------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU0349 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 33.24% | Good | Retain | N/A |
| | LNILU4763 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0370 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0372 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 14.89% | Good | Retain | N/A |
| | LNILU0373 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 42.02% | Good | Retain | N/A |
| | LNILU4771 | Vinyl | \$ 1011.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0375 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 10.53% | Good | Retain | N/A |
| | LNILU4772 | Vinyl | \$ 1011.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0332 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0333 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 2.62% | Good | Retain | N/A |
| | LNILU0334 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 27.71% | Good | Retain | N/A |
| | LNILU0335 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU0336 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU0337 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 28.45% | Good | Retain | N/A |
| | LNILU0338 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 100.17% | Good | Retain | N/A |
| | LNILU0339 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 14.59% | Fair | Retain | N/A |
| | LNILU0340 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| | LNILU4760 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4761 | Dishwasher | \$ 1486.00 | 8 | 14-11-2022 | 5.7 years | 0.00% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0350 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Repair | N/A |
| | | | | | | | | | | |

01-07-1982 -22.7 years

N/A

Retain

7.44% Good

20

\$ 1246.00

LNILU0351

Tiles - Wall

| LNILU0352 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
|-----------|--------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU4764 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4765 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4766 | Washing Machine | \$ 1371.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0366 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU0368 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 42.05% | Good | Retain | N/A |
| LNILU0369 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU4769 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| LNILU4770 | Vinyl | \$ 1011.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4795 | Air Conditioner - Split System | \$ 3395.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------------------------------------------------------------------------------------------------------------------|
| LNILU0361 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 84.00% | Good | Retain | N/A |
| LNILU0362 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 37.18% | Good | Retain | N/A |
| LNILU0363 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU0364 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU4767 | Exhaust fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4768 | Interior Painting | \$ 971.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Fair | Repair | Basin has been removed for better access and holes present next to the Cistern; Holes requires patching and painting |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0376 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 14.88% | Good | Retain | N/A |
| LNILU0377 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 4.96% | Good | Retain | N/A |
| LNILU0378 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |

| LNILU0379 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 13.12% | Good | Retain | Shared between unit 3/4 |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|--------------------------|
| LNILU0380 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 0.44% | Good | Retain | N/A |
| LNILU0381 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 5.69% | Good | Retain | N/A |
| LNILU0382 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Fair | Retain | Refit flyscreen securely |
| LNILU0383 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU0384 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 27.99% | Good | Retain | N/A |
| LNILU0385 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 4.37% | Fair | Retain | N/A |
| LNILU0386 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU0387 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU0388 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 14.00% | Good | Retain | N/A |
| LNILU0389 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 2.04% | Good | Retain | N/A |
| LNILU0390 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU0391 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 10.50% | Good | Retain | N/A |
| LNILU4190 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 4

| Bathroom |
|----------|
| |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0419 | Exhaust Fan | \$ 262.00 | 10 | 01-05-2013 | -1.9 years | 34.24% | Good | Retain | N/A |
| LNILU0421 | Shower Screen | \$ 1200.00 | 20 | 01-05-2013 | 8.1 years | 7.44% | Good | Retain | N/A |
| LNILU0422 | Skylight | \$ 1040.00 | 10 | 01-05-2013 | -1.9 years | 68.25% | Good | Retain | N/A |
| LNILU0423 | Tapware | \$ 1343.00 | 15 | 01-05-2013 | 3.1 years | 14.58% | Good | Retain | N/A |
| LNILU0424 | Tiles - Wall | \$ 3384.00 | 20 | 01-05-2013 | 8.1 years | 6.12% | Good | Retain | N/A |
| LNILU0425 | Tiles - Floor | \$ 4058.00 | 20 | 01-05-2013 | 8.1 years | 21.00% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0405 | Blind | \$ 342.00 | 10 | 01-05-2013 | -1.9 years | 0.00% | Good | Retain | N/A |
| LNILU0406 | Carpet | \$ 891.00 | 8 | 01-05-2013 | -3.9 years | 21.89% | Good | Retain | N/A |

| | LNILU0407 | Ceiling Fan | \$ 605.00 | 10 | 01-05-2013 | -1.9 years | 4.38% | Good | Retain | N/A |
|---------|------------------------|---------------------|--------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|-----------------|---------|------------|
| | LNILU0409 | Interior Painting | \$ 726.00 | 10 | 01-05-2013 | -1.9 years | 34.99% | Good | Retain | N/A |
| | LNILU0410 | Wardrobe | \$ 2115.00 | 10 | 01-05-2013 | -1.9 years | 14.87% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0411 | Blind | \$ 342.00 | 10 | 01-05-2013 | -1.9 years | 0.00% | Good | Retain | N/A |
| | LNILU0412 | Carpet | \$ 743.00 | 8 | 01-05-2013 | -3.9 years | 26.24% | Good | Retain | N/A |
| | LNILU0414 | Interior Painting | \$ 605.00 | 10 | 01-05-2013 | -1.9 years | 12.26% | Good | Retain | N/A |
| | LNILU0415 | Wardrobe | \$ 2115.00 | 10 | 01-05-2013 | -1.9 years | 15.74% | Good | Retain | N/A |
| | LNILU4775 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0436 | Blind | \$ 400.00 | 10 | 01-05-2013 | -1.9 years | 0.00% | Good | Retain | N/A |
| | LNILU0438 | Ceiling Fan | \$ 605.00 | 10 | 01-05-2013 | -1.9 years | 34.17% | Good | Retain | N/A |
| | LNILU0439 | Interior Painting | \$ 514.00 | 10 | 01-05-2013 | -1.9 years | 33.27% | Good | Retain | N/A |
| | LNILU4781 | Vinyl | \$ 1011.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0441 | Interior Painting | \$ 285.00 | 10 | 01-05-2013 | -1.9 years | 35.09% | Good | Retain | N/A |
| | LNILU4782 | Vinyl | \$ 1011.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0397 | Benchtops | \$ 2414.00 | 20 | 01-05-2013 | 8.1 years | 8.53% | Good | Retain | N/A |
| | LNILU0398 | Cooktop | \$ 1394.00 | 12 | 01-05-2013 | 0.1 years | 13.13% | Good | Retain | N/A |
| | LNILU0399 | Interior Painting | \$ 434.00 | 10 | 01-05-2013 | -1.9 years | 1.75% | Good | Retain | N/A |
| | LINILOUS99 | | | | | | 16 620/ | 6 1 | Retain | N/A |
| | LNILU0400 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-05-2013 | 8.1 years | 16.62% | Good | Retaili | |
| | | | \$ 3932.00 \$ 1011.00 | 20 | 01-05-2013 01-05-2013 | -1.9 years | 2.19% | Good | Retain | N/A |
| | LNILU0400 | Cabinets | | | | · | | | | N/A N/A |
| | LNILU0400 LNILU0401 | Cabinets Vinyl | \$ 1011.00 | 10 | 01-05-2013 | -1.9 years | 2.19% | Good | Retain | |

| | LNILU4773 | Blind | \$ 285.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|-------------|---------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------------------------------------|----------------------------------------------------------------------|---------------------------------------|
| | LNILU4774 | Dishwasher | \$ 1486.00 | 8 | 14-11-2022 | 5.7 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4968 | Fridge | \$ 1143.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Good | Retain | Bottom mount stainless steel |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0416 | Interior Painting | \$ 257.00 | 10 | 01-05-2013 | -1.9 years | 7.88% | Good | Retain | N/A |
| | LNILU0417 | Tiles - Wall | \$ 1246.00 | 20 | 01-05-2013 | 8.1 years | 17.06% | Good | Retain | N/A |
| | LNILU0418 | Tiles - Floor | \$ 2086.00 | 20 | 01-05-2013 | 8.1 years | 17.50% | Good | Retain | N/A |
| | LNILU4776 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4777 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | Water marking to be monitored |
| | LNILU4778 | Washing Machine | \$ 971.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4967 | Dryer | \$ 628.00 | 12 | 01-07-2024 | 11.3 years | 0.00% | Good | Retain | |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0431 | Air Conditioner | \$ 3395.00 | 10 | 01-05-2013 | -1.9 years | 299.19% | Good | Retain | N/A |
| | | - Split System | | | | | | | | |
| | LNILU0432 | - Split System Blind | \$ 400.00 | 10 | 01-05-2013 | -1.9 years | 0.00% | Good | Retain | N/A |
| | LNILU0432 LNILU0434 | | | | | -1.9 years -1.9 years | | | | N/A N/A |
| | | Blind | \$ 400.00 | 10 | 01-05-2013 | , | 0.00% | Good | Retain | |
| | LNILU0434 | Blind Ceiling Fan | \$ 400.00 \$ 605.00 | 10 10 | 01-05-2013 01-05-2013 | -1.9 years | 0.00% 1.75% | Good Good | Retain Retain | N/A |
| Toilet room | LNILU0434 LNILU0435 LNILU4780 | Blind Ceiling Fan Interior Painting | \$ 400.00 \$ 605.00 \$ 1097.00 | 10 10 10 | 01-05-2013 01-05-2013 01-05-2013 | -1.9 years -1.9 years | 0.00% 1.75% 12.25% | Good Good | Retain Retain Retain | N/A N/A |
| Toilet room | LNILU0434 LNILU0435 LNILU4780 | Blind Ceiling Fan Interior Painting | \$ 400.00 \$ 605.00 \$ 1097.00 | 10 10 10 | 01-05-2013 01-05-2013 01-05-2013 | -1.9 years -1.9 years | 0.00% 1.75% 12.25% | Good Good | Retain Retain Retain | N/A N/A |
| Foilet room | LNILU0434 LNILU0435 LNILU4780 | Blind Ceiling Fan Interior Painting Vinyl | \$ 400.00 \$ 605.00 \$ 1097.00 \$ 1011.00 | 10 10 10 10 | 01-05-2013 01-05-2013 01-05-2013 14-11-2022 | -1.9 years -1.9 years 7.7 years | 0.00% 1.75% 12.25% 0.00% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A |
| oilet room | LNILU0434 LNILU0435 LNILU4780 Asset Number | Blind Ceiling Fan Interior Painting Vinyl Asset Name | \$ 400.00 \$ 605.00 \$ 1097.00 \$ 1011.00 Acquisition Cost (\$) | 10 10 10 10 10 Effective Life (Y) | 01-05-2013 01-05-2013 01-05-2013 14-11-2022 Installation Date | -1.9 years -1.9 years 7.7 years Remaining Effective Life | 0.00% 1.75% 12.25% 0.00% Accumulated Repair Cost as % of Acquisition | Good Good Good Asset Condition | Retain Retain Retain Retain | N/A N/A N/A Comments |
| oilet room | LNILU0434 LNILU0435 LNILU4780 Asset Number LNILU0426 | Blind Ceiling Fan Interior Painting Vinyl Asset Name Skylight | \$ 400.00 \$ 605.00 \$ 1097.00 \$ 1011.00 Acquisition Cost (\$) \$ 1040.00 | 10 10 10 10 10 Effective Life (Y) | 01-05-2013 01-05-2013 01-05-2013 14-11-2022 Installation Date 01-05-2013 | -1.9 years -1.9 years 7.7 years Remaining Effective Life -1.9 years | 0.00% 1.75% 12.25% 0.00% Accumulated Repair Cost as % of Acquisition 70.00% | Good Good Good Good Asset Condition Good | Retain Retain Retain Retain Plan Retain | N/A N/A N/A Comments N/A |
| oilet room | LNILU0434 LNILU0435 LNILU4780 Asset Number LNILU0426 LNILU0427 | Blind Ceiling Fan Interior Painting Vinyl Asset Name Skylight Toilet & Cistern | \$ 400.00 \$ 605.00 \$ 1097.00 \$ 1011.00 Acquisition Cost (\$) \$ 1040.00 \$ 1383.00 | 10 10 10 10 10 Effective Life (Y) | 01-05-2013 01-05-2013 01-05-2013 14-11-2022 Installation Date 01-05-2013 01-05-2013 | -1.9 years -1.9 years 7.7 years Remaining Effective Life -1.9 years 8.1 years | 0.00% 1.75% 12.25% 0.00% Accumulated Repair Cost as % of Acquisition 70.00% 85.30% | Good Good Good Good Asset Condition Good Good | Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A Comments N/A N/A |
| Toilet room | LNILU0434 LNILU0435 LNILU4780 Asset Number LNILU0426 LNILU0427 LNILU0428 | Blind Ceiling Fan Interior Painting Vinyl Asset Name Skylight Toilet & Cistern Tiles - Wall | \$ 400.00 \$ 605.00 \$ 1097.00 \$ 1011.00 Acquisition Cost (\$) \$ 1040.00 \$ 1383.00 \$ 926.00 | 10 10 10 10 10 Effective Life (Y) | 01-05-2013 01-05-2013 01-05-2013 14-11-2022 Installation Date 01-05-2013 01-05-2013 01-05-2013 | -1.9 years -1.9 years 7.7 years Remaining Effective Life -1.9 years 8.1 years 8.1 years | 0.00% 1.75% 12.25% 0.00% Accumulated Repair Cost as % of Acquisition 70.00% 85.30% 4.81% | Good Good Good Asset Condition Good Good Good | Retain Retain Retain Retain Plan Retain Retain Retain Retain Retain | N/A N/A N/A Comments N/A N/A N/A N/A |

0.00% Good

Retain

N/A

14-11-2022 7.7 years

\$ 262.00

LNILU4779

Exhaust Fan

10

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0443 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 13.99% | Good | Retain | N/A |
| LNILU0444 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 87.72% | Good | Retain | N/A |
| LNILU0445 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 13.12% | Good | Retain | N/A |
| LNILU0446 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.87% | Good | Retain | N/A |
| LNILU0447 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 20.99% | Good | Retain | N/A |
| LNILU0448 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 10.50% | Good | Retain | N/A |
| LNILU0449 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU0450 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU0451 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU0452 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 0.15% | Good | Retain | N/A |
| LNILU0453 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 69.98% | Good | Retain | N/A |
| LNILU0454 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 9.62% | Good | Retain | N/A |
| LNILU0455 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0456 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 3.94% | Good | Retain | N/A |
| LNILU0457 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 1.09% | Good | Retain | N/A |
| LNILU4201 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 5-6

| Common | | | | | | | | | | |
|--------|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0458 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.11% | Good | Retain | N/A |
| Unit 5 | | | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0459 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 20.89% | Good | Retain | N/A |
| LNILU0460 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| LNILU0461 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |

| | LNILU0462 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 7.89% | Good | Retain | N/A |
|----------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|----------|--------|
| Unit 6 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU0524 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 25.48% | Good | Retain | N/A |
| | LNILU0525 | Lighting | \$ 1966.00 | 15 | 01-05-2021 | 11.1 years | 23.33% | Good | Retain | N/A |
| | LNILU0526 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 1.75% | Good | Retain | N/A |
| | LNILU0527 | Smoke Alarms | \$ 268.00 | 20 | 01-05-2021 | 16.1 years | 17.10% | Good | Retain | N/A |
| | | | | | | | | | <u>'</u> | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU0485 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 15.80% | Good | Retain | N/A |
| | LNILU0486 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 34.21% | Good | Retain | N/A |
| | LNILU0487 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | N/A |
| | LNILU0488 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 68.25% | Good | Retain | N/A |
| | LNILU0489 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 49.58% | Good | Retain | N/A |
| | LNILU0490 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 7.43% | Good | Retain | N/A |
| | LNILU0491 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.06% | Good | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU0472 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 94.48% | Good | Retain | N/A |
| | LNILU0473 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 10.53% | Good | Retain | N/A |
| | LNILU0474 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 1.09% | Good | Retain | N/A |
| | LNILU0475 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 13.14% | Good | Retain | N/A |
| | LNILU0476 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 17.49% | Good | Retain | N/A |
| | LNILU0477 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 10.50% | Good | Retain | N/A |
| Bed 2 | | | | | · | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU0478 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 34.21% | Good | Retain | N/A |
| | LNILU0479 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 26.24% | Good | Retain | N/A |
| | LNILU0480 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 34.17% | Good | Retain | N/A |

| | LNILU0481 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 41.99% | Fair | Repair | Patch paint do handles |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|------------------------|
| ining | | | | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0502 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 13.13% | Good | Retain | N/A |
| | LNILU0503 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| | LNILU0504 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 16.64% | Good | Retain | N/A |
| | LNILU0505 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 34.14% | Good | Retain | N/A |
| llway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0506 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU0507 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 14.91% | Good | Retain | N/A |
| chen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0463 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 14.91% | Good | Retain | N/A |
| | LNILU0464 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.53% | Good | Retain | N/A |
| | LNILU0465 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 13.86% | Good | Retain | N/A |
| | LNILU0466 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 11.38% | Good | Retain | N/A |
| | LNILU0467 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 7.44% | Good | Retain | N/A |
| | LNILU0468 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 39.39% | Fair | Retain | N/A |
| | LNILU0469 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 175.05% | Good | Retain | N/A |
| | LNILU0470 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 13.86% | Good | Retain | N/A |
| | LNILU0471 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| undry | | | | | | | | , | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0482 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Good | Retain | N/A |
| | LNILU0483 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.06% | Good | Retain | N/A |
| | LNILU0484 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU4783 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4784 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |

| | LNILU4785 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
|---------------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------|
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0497 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 47.24% | Good | Retain | N/A |
| | LNILU0498 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 14.88% | Good | Retain | N/A |
| | LNILU0499 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 26.26% | Good | Retain | N/A |
| | LNILU0500 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 34.17% | Good | Retain | N/A |
| | LNILU0501 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 34.13% | Good | Retain | N/A |
| Toilet room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0492 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 68.25% | Good | Retain | N/A |
| | LNILU0493 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 85.30% | Good | Retain | N/A |
| | LNILU0494 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.06% | Good | Retain | N/A |
| | LNILU0495 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| | LNILU0496 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 37.98% | Good | Retain | N/A |
| | LNILU4786 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Unit Exterior | | | | | | | | | | |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0508 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 15.76% | Good | Retain | N/A |
| | LNILU0509 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 3.79% | Good | Retain | N/A |
| | LNILU0510 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 88.96% | Good | Retain | N/A |
| | LNILU0511 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 26.25% | Good | Retain | Shared between unit 5/6 |
| | LNILU0512 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.06% | Fair | Retain | N/A |
| | LNILU0513 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 5.69% | Fair | Retain | N/A |
| | LNILU0514 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 68.25% | Good | Retain | N/A |
| | LNILU0515 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 42.65% | Good | Retain | N/A |
| | LNILU0516 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |

| LNILU0517 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
|-----------|----------------------|------------|----|------------|-------------|--------|------|--------|-----------------------------------|
| LNILU0518 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | Cracked pathway has been repaired |
| LNILU0519 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU0520 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 17.50% | Good | Retain | N/A |
| LNILU0521 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 2.04% | Good | Retain | N/A |
| LNILU0522 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 10.50% | Good | Retain | N/A |
| LNILU0523 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4212 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 6

| Bathroom |
|----------|
|----------|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0549 | Exhaust Fan | \$ 262.00 | 10 | 01-05-2021 | 6.1 years | 42.14% | Good | Retain | N/A |
| LNILU0550 | Interior Painting | \$ 228.00 | 10 | 01-05-2021 | 6.1 years | 10.53% | Good | Retain | N/A |
| LNILU0551 | Shower Screen | \$ 1200.00 | 20 | 01-05-2021 | 16.1 years | 17.06% | Good | Retain | N/A |
| LNILU0552 | Skylight | \$ 1040.00 | 10 | 01-05-2021 | 6.1 years | 19.25% | Good | Retain | N/A |
| LNILU0553 | Tapware | \$ 1343.00 | 15 | 01-05-2021 | 11.1 years | 37.91% | Good | Retain | N/A |
| LNILU0554 | Tiles - Wall | \$ 3384.00 | 20 | 01-05-2021 | 16.1 years | 1.31% | Good | Retain | N/A |
| LNILU0555 | Tiles - Floor | \$ 4058.00 | 20 | 01-05-2021 | 16.1 years | 17.06% | Fair | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0537 | Blind | \$ 342.00 | 10 | 01-05-2021 | 6.1 years | 35.09% | Good | Retain | N/A |
| LNILU0538 | Carpet | \$ 891.00 | 8 | 01-05-2021 | 4.1 years | 9.85% | Good | Retain | N/A |
| LNILU0539 | Ceiling Fan | \$ 605.00 | 10 | 01-05-2021 | 6.1 years | 35.04% | Good | Retain | N/A |
| LNILU0540 | Interior Painting | \$ 726.00 | 10 | 01-05-2021 | 6.1 years | 34.11% | Good | Retain | N/A |
| LNILU0541 | Wardrobe | \$ 2115.00 | 10 | 01-05-2021 | 6.1 years | 9.62% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0542 | Blind | \$ 342.00 | 10 | 01-05-2021 | 6.1 years | 34.21% | Good | Retain | N/A |

| | LNILU0543 | Carpet | \$ 743.00 | 8 | 01-05-2021 | 4.1 years | 7.66% | Good | Retain | N/A |
|-------------|-----------------------------------------------------|--------------------------------------------|----------------------------------------------------------------|--------------------------------------|-------------------------------------------------------------|----------------------------------------------------------|-------------------------------------------------------------------|---------------------------|----------------------------|----------------------|
| | LNILU0544 | Interior Painting | \$ 605.00 | 10 | 01-05-2021 | 6.1 years | 9.64% | Good | Retain | N/A |
| | LNILU0545 | Wardrobe | \$ 2115.00 | 10 | 01-05-2021 | 6.1 years | 15.74% | Fair | Retain | N/A |
| | LNILU4787 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ng | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0566 | Blind | \$ 400.00 | 10 | 01-05-2021 | 6.1 years | 2.63% | Good | Retain | N/A |
| | LNILU0567 | Carpet | \$ 640.00 | 8 | 01-05-2021 | 4.1 years | 7.66% | Good | Retain | N/A |
| | LNILU0568 | Ceiling Fan | \$ 605.00 | 10 | 01-05-2021 | 6.1 years | 33.29% | Good | Retain | N/A |
| | LNILU0569 | Interior Painting | \$ 514.00 | 10 | 01-05-2021 | 6.1 years | 34.14% | Good | Retain | N/A |
| <i>ı</i> ay | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0570 | Carpet | \$ 354.00 | 8 | 01-05-2021 | 4.1 years | 21.34% | Good | Retain | N/A |
| | LNILU0571 | Interior Painting | \$ 285.00 | 10 | 01-05-2021 | 6.1 years | 33.33% | Good | Retain | N/A |
| en | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0528 | Blind | \$ 285.00 | 10 | 01-05-2021 | 6.1 years | 33.33% | Good | Retain | N/A |
| | LNILU0529 | Benchtops | \$ 2414.00 | 20 | 01-05-2021 | 16.1 years | 1.53% | Good | Retain | N/A |
| | LNILU0530 | Cooktop | \$ 1394.00 | 12 | 01-05-2021 | 8.1 years | 28.44% | Good | Retain | N/A |
| | LNILU0531 | Interior Painting | \$ 434.00 | 10 | 01-05-2021 | 6.1 years | 35.02% | Good | Retain | N/A |
| | LNILU0532 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-05-2021 | 16.1 years | 6.56% | Good | Retain | N/A |
| | | | | | | | | | | |
| | LNILU0533 | Vinyl | \$ 1011.00 | 10 | 01-05-2021 | 6.1 years | 41.58% | Good | Retain | N/A |
| | LNILU0533 LNILU0534 | Vinyl Oven | \$ 1011.00 \$ 1451.00 | 10 | 01-05-2021 01-05-2021 | 6.1 years 8.1 years | 41.58% 10.94% | Good | Retain Retain | N/A N/A |
| | | - | | | | - | | | | |
| | LNILU0534 | Oven | \$ 1451.00 | 12 | 01-05-2021 | 8.1 years | 10.94% | Good | Retain | N/A |
| dry | LNILU0534 LNILU0535 | Oven Rangehood | \$ 1451.00 \$ 617.00 | 12 12 | 01-05-2021 01-05-2021 | 8.1 years 8.1 years | 10.94% 0.73% | Good Good | Retain Retain | N/A N/A |
| dry | LNILU0534 LNILU0535 | Oven Rangehood | \$ 1451.00 \$ 617.00 | 12 12 | 01-05-2021 01-05-2021 | 8.1 years 8.1 years | 10.94% 0.73% | Good Good | Retain Retain | N/A N/A |
| dry | LNILU0534 LNILU0535 LNILU0536 | Oven Rangehood Sink & Fittings | \$ 1451.00 \$ 617.00 \$ 1634.00 | 12 12 15 | 01-05-2021 01-05-2021 01-05-2021 | 8.1 years 8.1 years 11.1 years | 10.94% 0.73% 113.77% | Good Good | Retain Retain Retain | N/A N/A N/A |
| dry | LNILU0534 LNILU0535 LNILU0536 Asset Number | Oven Rangehood Sink & Fittings Asset Name | \$ 1451.00 \$ 617.00 \$ 1634.00 Acquisition Cost (\$) | 12 12 15 Effective Life (Y) | 01-05-2021 01-05-2021 01-05-2021 Installation Date | 8.1 years 8.1 years 11.1 years Remaining Effective Life | 10.94% 0.73% 113.77% Accumulated Repair Cost as % of Acquisition | Good Good Asset Condition | Retain Retain Retain | N/A N/A N/A Comments |

8.75% Good

Retain

N/A

20

01-05-2021 16.1 years

\$ 2086.00

LNILU0548

Tiles - Floor

| 1.001.14270 | Ciple Or Fittings | ¢ 1634.00 | 15 | 14 11 2022 | 12.7 | 0.000/ | Card | Datain. | NI/A |
|------------------------|-----------------------------------|-------------------------|--------------------|--------------------------|--------------------------|----------------------------------------------|-----------------|------------------|------------|
| LNILU4279 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4788 | Dryer | \$ 628.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4789 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | | | | | | | | - | |
| Asset Numb | er Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | motumation bate | Remaining Effective Life | Accumulated Repair Cost as 70 of Acquisition | Asset Condition | riaii | Comments |
| LNILU0561 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-05-2021 | 6.1 years | 55.11% | Good | Retain | N/A |
| LNILU0561 LNILU0562 | | | | | | · · · · · · · · · · · · · · · · · · · | | | |
| | - Split System | \$ 3395.00 | 10 | 01-05-2021 | 6.1 years | 55.11% | Good | Retain | N/A |
| LNILU0562 | - Split System Blind | \$ 3395.00 \$ 400.00 | 10 | 01-05-2021 01-05-2021 | 6.1 years 6.1 years | 55.11% 16.63% | Good | Retain Retain | N/A N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0556 | Skylight | \$ 1040.00 | 10 | 01-05-2021 | 6.1 years | 66.50% | Good | Retain | N/A |
| LNILU0557 | Toilet & Cistern | \$ 1383.00 | 20 | 01-05-2021 | 16.1 years | 85.30% | Good | Retain | N/A |
| LNILU0558 | Tiles - Wall | \$ 926.00 | 20 | 01-05-2021 | 16.1 years | 20.99% | Good | Retain | N/A |
| LNILU0559 | Tiles - Floor | \$ 1429.00 | 20 | 01-05-2021 | 16.1 years | 7.44% | Good | Retain | N/A |
| LNILU0560 | Tapware | \$ 251.00 | 15 | 01-05-2021 | 11.1 years | 113.94% | Good | Retain | N/A |
| LNILU4790 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4791 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|-------------------------|
| LNILU0572 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 34.14% | Good | Retain | N/A |
| LNILU0573 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0574 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 6.13% | Good | Retain | N/A |
| LNILU0575 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 85.31% | Good | Retain | Shared between unit 5/6 |
| LNILU0576 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 21.00% | Good | Retain | N/A |
| LNILU0577 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU0578 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 22.75% | Good | Retain | N/A |

| LNILU0579 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 127.96% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|---------|-----|
| LNILU0580 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU0581 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.06% | Good | Retain | N/A |
| LNILU0582 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.75% | Good | Retain | N/A |
| LNILU0583 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU0584 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 34.12% | Fair | Retain | N/A |
| LNILU0585 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.37% | Good | Retain | N/A |
| LNILU0586 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.53% | Good | Retain | N/A |
| LNILU0587 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 10.50% | Poor | Replace | N/A |
| LNILU4223 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 7-8

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|------------------------|
| | LNILU0588 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 33.24% | Good | Retain | N/A |
| Unit 7 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0589 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 24.75% | Good | Retain | N/A |
| | LNILU0590 | Lighting | \$ 1966.00 | 15 | 01-04-2012 | 2.0 years | 22.75% | Fair | Retain | Update lighting LED |
| | LNILU0591 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 22.74% | Good | Retain | N/A |
| | LNILU0592 | Smoke Alarms | \$ 268.00 | 20 | 01-04-2012 | 7.0 years | 5.26% | Good | Retain | N/A |
| Unit 8 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0653 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0654 | Lighting | \$ 1966.00 | 15 | 01-04-2005 | -5.0 years | 8.17% | Good | Retain | N/A |
| | LNILU0655 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 20.99% | Good | Retain | N/A |
| | LNILU0656 | Smoke Alarms | \$ 268.00 | 20 | 01-04-2005 | 0.0 years | 17.10% | Good | Retain | N/A |

| R | at | h | ro | O | m |
|---|----|---|----|---|---|
| | | | | | |

| Bathroom | | | | | | | | | | |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0614 | Exhaust Fan | \$ 262.00 | 10 | 01-04-2012 | -3.0 years | 11.41% | Good | Retain | N/A |
| | LNILU0615 | Interior Painting | \$ 228.00 | 10 | 01-04-2012 | -3.0 years | 34.21% | Good | Retain | N/A |
| | LNILU0616 | Shower Screen | \$ 1200.00 | 20 | 01-04-2012 | 7.0 years | 17.50% | Good | Retain | N/A |
| | LNILU0617 | Skylight | \$ 1040.00 | 10 | 01-04-2012 | -3.0 years | 21.00% | Good | Retain | N/A |
| | LNILU0618 | Tapware | \$ 1343.00 | 15 | 01-04-2012 | 2.0 years | 116.65% | Fair | Retain | Renew missing cold tap top - waste plug rusty |
| | LNILU0619 | Tiles - Wall | \$ 3384.00 | 20 | 01-04-2012 | 7.0 years | 3.06% | Good | Retain | N/A |
| | LNILU0620 | Tiles - Floor | \$ 4058.00 | 20 | 10-11-2018 | 13.6 years | 0.00% | Good | Retain | |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0602 | Blind | \$ 342.00 | 10 | 01-04-2012 | -3.0 years | 35.09% | Good | Retain | N/A |
| | LNILU0603 | Carpet | \$ 891.00 | 8 | 01-04-2012 | -5.0 years | 21.89% | Good | Retain | N/A |

01-04-2012 -3.0 years

01-04-2012 -3.0 years

01-04-2012 -3.0 years

10

10

10

Bed 2

LNILU0604

LNILU0605

LNILU0606

Ceiling Fan

Wardrobe

Interior Painting

\$ 605.00

\$ 726.00

\$ 2115.00

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0607 | Blind | \$ 342.00 | 10 | 01-04-2012 | -3.0 years | 2.63% | Good | Retain | N/A |
| LNILU0608 | Carpet | \$ 743.00 | 8 | 01-04-2012 | -5.0 years | 8.20% | Good | Retain | N/A |
| LNILU0609 | Interior Painting | \$ 605.00 | 10 | 01-04-2012 | -3.0 years | 11.39% | Good | Retain | N/A |
| LNILU0610 | Wardrobe | \$ 2115.00 | 10 | 01-04-2012 | -3.0 years | 34.99% | Good | Retain | N/A |
| LNILU4792 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

35.04% Good

34.99% Good

12.25% Good

Retain

Retain

Retain

N/A

N/A

N/A

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0631 | Blind | \$ 400.00 | 10 | 01-04-2012 | -3.0 years | 34.13% | Good | Retain | N/A |
| LNILU0632 | Carpet | \$ 640.00 | 8 | 01-04-2012 | -5.0 years | 20.78% | Good | Retain | N/A |
| LNILU0633 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2012 | -3.0 years | 11.39% | Good | Retain | N/A |
| LNILU0634 | Interior Painting | \$ 514.00 | 10 | 01-04-2012 | -3.0 years | 16.63% | Good | Retain | N/A |

| панмау | | | | | | | | | | |
|---------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0635 | Carpet | \$ 354.00 | 8 | 01-04-2012 | -5.0 years | 20.80% | Good | Retain | N/A |
| | LNILU0636 | Interior Painting | \$ 285.00 | 10 | 01-04-2012 | -3.0 years | 34.21% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0593 | Blind | \$ 285.00 | 10 | 01-04-2012 | -3.0 years | 34.21% | Good | Retain | N/A |
| | LNILU0594 | Benchtops | \$ 2414.00 | 20 | 01-04-2012 | 7.0 years | 3.28% | Fair | Retain | N/A |
| | LNILU0595 | Cooktop | \$ 1394.00 | 12 | 01-04-2012 | -1.0 years | 28.44% | Good | Retain | N/A |
| | LNILU0596 | Interior Painting | \$ 434.00 | 10 | 01-04-2012 | -3.0 years | 16.64% | Good | Retain | N/A |
| | LNILU0597 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-04-2012 | 7.0 years | 17.06% | Good | Retain | N/A |
| | LNILU0598 | Vinyl | \$ 1011.00 | 10 | 01-04-2012 | -3.0 years | 83.16% | Fair | Retain | N/A |
| | LNILU0599 | Oven | \$ 1451.00 | 12 | 01-04-2012 | -1.0 years | 145.88% | Good | Retain | N/A |
| | LNILU0600 | Rangehood | \$ 617.00 | 12 | 01-04-2012 | -1.0 years | 4.74% | Good | Retain | N/A |
| | LNILU0601 | Sink & Fittings | \$ 1634.00 | 15 | 01-04-2012 | 2.0 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0611 | Interior Painting | \$ 257.00 | 10 | 01-04-2012 | -3.0 years | 33.27% | Good | Retain | N/A |
| | LNILU0612 | Tiles - Wall | \$ 1246.00 | 20 | 01-04-2012 | 7.0 years | 17.50% | Good | Retain | N/A |
| | LNILU0613 | Tiles - Floor | \$ 2086.00 | 20 | 01-04-2012 | 7.0 years | 17.50% | Good | Retain | N/A |
| | LNILU4286 | Washing Machine | \$ 1371.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4793 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4794 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgraded to 1/4 turn |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0626 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-04-2012 | -3.0 years | 307.06% | Good | Retain | N/A |
| | LNILU0627 | Blind | \$ 400.00 | 10 | 01-04-2012 | -3.0 years | 16.63% | Good | Retain | N/A |
| | LNILU0628 | Carpet | \$ 1371.00 | 8 | 01-04-2012 | -5.0 years | | Good | | N/A |

| LNILU0629 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2012 | -3.0 years | 10.51% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|------------|--------|------|--------|-----|
| LNILU0630 | Interior Painting | \$ 1097.00 | 10 | 01-04-2012 | -3.0 years | 6.13% | Good | Retain | N/A |

Toilet room

| Asset Num | ber Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-----------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0621 | Skylight | \$ 1040.00 | 10 | 01-04-2012 | -3.0 years | 5.25% | Good | Retain | N/A |
| LNILU0622 | Toilet & Cistern | \$ 1383.00 | 20 | 01-04-2012 | 7.0 years | 85.30% | Good | Retain | N/A |
| LNILU0623 | Tiles - Wall | \$ 926.00 | 20 | 01-04-2012 | 7.0 years | 16.62% | Good | Retain | N/A |
| LNILU0624 | Tiles - Floor | \$ 1429.00 | 20 | 01-04-2012 | 7.0 years | 2.19% | Good | Retain | N/A |
| LNILU0625 | Tapware | \$ 251.00 | 15 | 01-04-2012 | 2.0 years | 55.51% | Good | Retain | N/A |
| LNILU4287 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------|
| LNILU0637 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 9.63% | Good | Retain | N/A |
| LNILU0638 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 4.08% | Good | Retain | N/A |
| LNILU0639 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 57.61% | Good | Retain | N/A |
| LNILU0640 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 7/8 |
| LNILU0641 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Fair | Retain | N/A |
| LNILU0642 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 20.99% | Fair | Repair | N/A |
| LNILU0643 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 22.75% | Good | Retain | N/A |
| LNILU0644 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 105.08% | Good | Retain | N/A |
| LNILU0646 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 0.87% | Good | Retain | N/A |
| LNILU0647 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.92% | Good | Retain | N/A |
| LNILU0648 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 16.04% | Good | Retain | N/A |
| LNILU0650 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 3.21% | Good | Retain | N/A |
| LNILU0651 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU0652 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Retain | N/A |
| LNILU0709 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU4736 | Awnings | \$ 13029.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Excellent | Retain | N/A |

| | LNILU4796 | Water Tank | \$ 1063.00 | 25 | 08-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------|
| | | | | | | | | | | |
| Bathroom | | | | | | , | | , | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU0678 | Exhaust Fan | \$ 262.00 | 10 | 01-04-2005 | -10.0 years | 2.63% | Good | Retain | N/A |
| | LNILU0680 | Shower Screen | \$ 1200.00 | 20 | 01-04-2005 | 0.0 years | 0.88% | Good | Retain | N/A |
| | LNILU0681 | Skylight | \$ 1040.00 | 10 | 01-04-2005 | -10.0 years | 70.00% | Good | Retain | N/A |
| | LNILU0682 | Tapware | \$ 1343.00 | 15 | 01-04-2005 | -5.0 years | 8.75% | Good | Retain | N/A |
| | LNILU0683 | Tiles - Wall | \$ 3384.00 | 20 | 01-04-2005 | 0.0 years | 0.87% | Good | Retain | N/A |
| | LNILU0684 | Tiles - Floor | \$ 4058.00 | 20 | 01-04-2005 | 0.0 years | 17.50% | Fair | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU0666 | Blind | \$ 342.00 | 10 | 01-04-2005 | -10.0 years | 35.09% | Good | Retain | N/A |
| | LNILU0667 | Carpet | \$ 891.00 | 8 | 01-04-2005 | -12.0 years | 21.89% | Good | Retain | N/A |
| | LNILU0668 | Ceiling Fan | \$ 605.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| | LNILU0669 | Interior Painting | \$ 726.00 | 10 | 01-04-2005 | -10.0 years | 34.99% | Good | Retain | N/A |
| | LNILU0670 | Wardrobe | \$ 2115.00 | 10 | 01-04-2005 | -10.0 years | 34.11% | Fair | Repair | Repaint |
| Bed 2 | | | | | | | | | · | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU0671 | Blind | \$ 342.00 | 10 | 01-04-2005 | -10.0 years | 17.54% | Poor | Repair | Blind adjus broken |
| | LNILU0672 | Carpet | \$ 743.00 | 8 | 01-04-2005 | -12.0 years | 21.32% | Good | Retain | N/A |
| | LNILU0673 | Interior Painting | \$ 605.00 | 10 | 01-04-2005 | -10.0 years | 10.51% | Good | Retain | N/A |
| | LNILU0674 | Wardrobe | \$ 2115.00 | 10 | 01-04-2005 | -10.0 years | 13.12% | Good | Retain | N/A |
| Dining | | | | | | | | | · | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU0695 | Blind | \$ 400.00 | 10 | 01-04-2005 | -10.0 years | 35.00% | Good | Retain | N/A |
| | LNILU0697 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2005 | -10.0 years | 35.04% | Good | Retain | N/A |
| | LNILU0698 | Interior Painting | \$ 514.00 | 10 | 01-04-2005 | -10.0 years | 33.27% | Good | Retain | N/A |
| | LNILU4292 | Tiles - Floor | \$ 1011.00 | 20 | 14-11-2022 | 17.7 years | 0.00% | Good | Retain | N/A |

LNILU0692

Carpet

| Hallway | | | | | | | | | | |
|---------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0699 | Carpet | \$ 354.00 | 8 | 01-04-2005 | -12.0 years | 1.64% | Good | Retain | N/A |
| | LNILU0700 | Interior Painting | \$ 285.00 | 10 | 01-04-2005 | -10.0 years | 34.21% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0657 | Blind | \$ 285.00 | 10 | 01-04-2005 | -10.0 years | 35.09% | Good | Retain | N/A |
| | LNILU0658 | Benchtops | \$ 2414.00 | 20 | 01-04-2005 | 0.0 years | 8.75% | Good | Retain | N/A |
| | LNILU0659 | Cooktop | \$ 1394.00 | 12 | 01-04-2005 | -8.0 years | 29.17% | Good | Retain | N/A |
| | LNILU0660 | Interior Painting | \$ 434.00 | 10 | 01-04-2005 | -10.0 years | 35.02% | Good | Retain | N/A |
| | LNILU0661 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-04-2005 | 0.0 years | 0.87% | Good | Retain | N/A |
| | LNILU0662 | Vinyl | \$ 1011.00 | 10 | 01-04-2005 | -10.0 years | 87.54% | Good | Retain | N/A |
| | LNILU0663 | Oven | \$ 1451.00 | 12 | 01-04-2005 | -8.0 years | 145.88% | Good | Retain | N/A |
| | LNILU0664 | Rangehood | \$ 617.00 | 12 | 01-04-2005 | -8.0 years | 14.22% | Good | Retain | N/A |
| | LNILU0665 | Sink & Fittings | \$ 1634.00 | 15 | 01-04-2005 | -5.0 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0675 | Interior Painting | \$ 257.00 | 10 | 01-04-2005 | -10.0 years | 33.27% | Good | Retain | N/A |
| | LNILU0676 | Tiles - Wall | \$ 1246.00 | 20 | 01-04-2005 | 0.0 years | 17.50% | Fair | Repair | Re grout wall tiles |
| | LNILU0677 | Tiles - Floor | \$ 2086.00 | 20 | 01-04-2005 | 0.0 years | 17.50% | Fair | Retain | N/A |
| | LNILU4288 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4289 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgraded to 1/4 turn |
| | LNILU4290 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0690 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-04-2005 | -10.0 years | 307.06% | Good | Retain | N/A |
| | LNILU0691 | Blind | \$ 400.00 | 10 | 01-04-2005 | -10.0 years | 34.13% | Good | Retain | N/A |
| | | | | | | | | | | |

20.79% Good

Retain

N/A

01-04-2005 -12.0 years

8

\$ 1371.00

| LNILU0693 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2005 | -10.0 years | 12.26% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU0694 | Interior Painting | \$ 1097.00 | 10 | 01-04-2005 | -10.0 years | 10.50% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0685 | Skylight | \$ 1040.00 | 10 | 01-04-2005 | -10.0 years | 68.25% | Good | Retain | N/A |
| LNILU0686 | Toilet & Cistern | \$ 1383.00 | 20 | 01-04-2005 | 0.0 years | 98.30% | Good | Retain | N/A |
| LNILU0687 | Tiles - Wall | \$ 926.00 | 20 | 01-04-2005 | 0.0 years | 17.49% | Good | Retain | N/A |
| LNILU0688 | Tiles - Floor | \$ 1429.00 | 20 | 01-04-2005 | 0.0 years | 17.06% | Fair | Repair | N/A |
| LNILU0689 | Tapware | \$ 251.00 | 15 | 01-04-2005 | -5.0 years | 116.86% | Good | Retain | N/A |
| LNILU4291 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------------------------------------------------|
| LNILU0701 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Repair | Re-tensioning required |
| LNILU0702 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.37% | Good | Retain | Key to front door does not unlock door - replace lock urgently |
| LNILU0703 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 72.62% | Good | Retain | N/A |
| LNILU0704 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 15.31% | Good | Retain | Shared between unit 7/8 |
| LNILU0705 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.12% | Good | Retain | N/A |
| LNILU0706 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 20.99% | Good | Retain | N/A |
| LNILU0707 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU0708 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 39.37% | Good | Retain | N/A |
| LNILU0711 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 7.00% | Good | Retain | N/A |
| LNILU0712 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 20.41% | Good | Retain | N/A |
| LNILU0713 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 34.12% | Good | Retain | N/A |
| LNILU0714 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | N/A |
| LNILU0715 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU0716 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Retain | N/A |

| | LNILU4737 | Awnings | \$ 7075.00 | 10 | 26-06-2023 | 8.3 years | 0.009 | Good | Retain | N/A | |
|-----------|-----------|---------|------------|----|------------|-----------|-------|------|--------|-----|--|
| Unit 9-10 | | | | | | | | | | | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Con |
|-----------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|------------------------------------------------|------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-------------------------------------------------------|---------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | LNILU0717 | Insulation | \$ 3130.00 | 20 | 01-07-1982 | -22.7 years | 23.07% | Good | Retain | N/A |
| | LNILU0718 | Lighting | \$ 1909.00 | 15 | 01-04-2006 | -4.0 years | 1.80% | Good | Retain | N/A |
| | LNILU0719 | Sarking | \$ 285.00 | 25 | 01-07-1982 | -17.7 years | 249.26% | Good | Retain | 0 |
| | LNILU0720 | Smoke Alarms | \$ 260.00 | 20 | 01-04-2006 | 1.0 years | 1.36% | Good | Retain | N/A |
| Unit 10 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com |
| | LNILU0781 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0782 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 20.77% | Good | Retain | New too s origir repla |
| | LNILU0783 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 5.25% | Good | Retain | N/A |
| | LNILU0784 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 1.32% | Good | Retain | N/A |
| Dathyaaya | EINIE00704 | SHOKE Alams | \$ 200.00 | | 01 07 1302 | ZZ.i ycuis | 1.5270 | Good | Retaill | IV/A |
| Bathroom | Asset Number | Asset Name | | | Installation Date | | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com |
| Bathroom | | | Acquisition Cost (\$) \$ 222.00 | Effective Life (Y) | | Remaining Effective Life | | | | Com |
| Bathroom | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| Bathroom | Asset Number | Asset Name Interior Painting | Acquisition Cost (\$) \$ 222.00 | Effective Life (Y) | Installation Date 01-04-2006 | Remaining Effective Life -9.0 years | Accumulated Repair Cost as % of Acquisition 36.04% | Asset Condition Good | Plan Retain | Com N/A |
| Bathroom | Asset Number LNILU0679 LNILU0742 | Asset Name Interior Painting Exhaust Fan | Acquisition Cost (\$) \$ 222.00 \$ 255.00 | Effective Life (Y) 10 10 | Installation Date 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% | Asset Condition Good Good | Plan Retain Retain | Com N/A N/A |
| Bathroom | Asset Number LNILU0679 LNILU0742 LNILU0743 | Asset Name Interior Painting Exhaust Fan Interior Painting | Acquisition Cost (\$) \$ 222.00 \$ 255.00 \$ 228.00 | Effective Life (Y) 10 10 10 | 1nstallation Date 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% | Asset Condition Good Good Good | Plan Retain Retain Retain | Com N/A N/A N/A |
| Bathroom | Asset Number LNILU0679 LNILU0742 LNILU0743 LNILU0744 | Asset Name Interior Painting Exhaust Fan Interior Painting Shower Screen | \$ 222.00 \$ 255.00 \$ 228.00 \$ 1165.00 | Effective Life (Y) 10 10 10 20 | 01-04-2006 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years 1.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% 18.03% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | Com N/A N/A N/A N/A |
| Bathroom | Asset Number LNILU0679 LNILU0742 LNILU0743 LNILU0744 LNILU0745 | Asset Name Interior Painting Exhaust Fan Interior Painting Shower Screen Skylight | \$ 222.00 \$ 255.00 \$ 228.00 \$ 1165.00 \$ 1010.00 | Effective Life (Y) 10 10 10 20 10 | 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years 1.0 years -9.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% 18.03% 72.08% | Asset Condition Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain | Com N/A N/A N/A N/A |
| Bathroom | Asset Number LNILU0679 LNILU0742 LNILU0743 LNILU0744 LNILU0745 LNILU0746 | Asset Name Interior Painting Exhaust Fan Interior Painting Shower Screen Skylight Tapware | \$ 222.00 \$ 255.00 \$ 228.00 \$ 1165.00 \$ 1010.00 \$ 1304.00 | Effective Life (Y) 10 10 10 20 10 15 | 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years 1.0 years -9.0 years -4.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% 18.03% 72.08% 30.04% | Asset Condition Good Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A |
| Bathroom Bed 1 | Asset Number LNILU0679 LNILU0742 LNILU0743 LNILU0744 LNILU0745 LNILU0746 LNILU0747 | Asset Name Interior Painting Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 222.00 \$ 255.00 \$ 228.00 \$ 1165.00 \$ 1010.00 \$ 1304.00 \$ 3384.00 | Effective Life (Y) 10 10 10 20 10 15 20 | 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years 1.0 years -4.0 years 1.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% 18.03% 72.08% 30.04% 17.49% | Asset Condition Good Good Good Good Good Good Good Go | Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A |
| | Asset Number LNILU0679 LNILU0742 LNILU0743 LNILU0744 LNILU0745 LNILU0746 LNILU0747 | Asset Name Interior Painting Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 222.00 \$ 255.00 \$ 228.00 \$ 1165.00 \$ 1010.00 \$ 1304.00 \$ 3384.00 | Effective Life (Y) 10 10 10 20 10 15 20 | 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 01-04-2006 | Remaining Effective Life -9.0 years -9.0 years -9.0 years 1.0 years -4.0 years 1.0 years | Accumulated Repair Cost as % of Acquisition 36.04% 34.27% 35.09% 18.03% 72.08% 30.04% 17.49% | Asset Condition Good Good Good Good Good Good Good Go | Plan Retain Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A |

| | LNILU0731 | Carpet | \$ 865.00 | 8 | 01-04-2006 | -11.0 years | 22.54% | Good | Retain | N/A |
|--------|------------------------|----------------------------|-------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|-----------------|---------|------------|
| | LNILU0732 | Ceiling Fan | \$ 588.00 | 10 | 01-04-2006 | -9.0 years | 43.27% | Good | Retain | N/A |
| | LNILU0733 | Interior Painting | \$ 704.00 | 10 | 01-04-2006 | -9.0 years | 34.28% | Good | Retain | N/A |
| | LNILU0734 | Wardrobe | \$ 2053.00 | 10 | 01-04-2006 | -9.0 years | 15.32% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0735 | Blind | \$ 333.00 | 10 | 01-04-2006 | -9.0 years | 6.31% | Good | Retain | N/A |
| | LNILU0736 | Carpet | \$ 721.00 | 8 | 01-04-2006 | -11.0 years | 3.94% | Good | Retain | N/A |
| | LNILU0737 | Interior Painting | \$ 588.00 | 10 | 01-04-2006 | -9.0 years | 2.70% | Good | Retain | N/A |
| | LNILU0738 | Wardrobe | \$ 2115.00 | 10 | 01-04-2006 | -9.0 years | 34.99% | Good | Retain | N/A |
| | LNILU4293 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ning | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0759 | Blind | \$ 400.00 | 10 | 01-04-2006 | -9.0 years | 35.00% | Good | Retain | N/A |
| | LNILU0760 | Carpet | \$ 621.00 | 8 | 01-04-2006 | -11.0 years | 10.71% | Good | Retain | N/A |
| | LNILU0761 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2006 | -9.0 years | 2.63% | Good | Retain | N/A |
| | LNILU0762 | Interior Painting | \$ 514.00 | 10 | 01-04-2006 | -9.0 years | 11.38% | Good | Retain | N/A |
| allway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0763 | Carpet | \$ 344.00 | 8 | 01-04-2006 | -11.0 years | 22.53% | Good | Retain | N/A |
| | LNILU0764 | Interior Painting | \$ 277.00 | 10 | 01-04-2006 | -9.0 years | 17.15% | Good | Retain | N/A |
| tchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0721 | Blind | \$ 277.00 | 10 | 01-04-2006 | -9.0 years | 18.05% | Good | Retain | N/A |
| | LNILU0722 | Benchtops | \$ 2344.00 | 20 | 01-04-2006 | 1.0 years | 9.01% | Good | Retain | N/A |
| | LIVILOUTZZ | | | | | | 20 520/ | C 1 | Retain | N/A |
| | LNILU0723 | Cooktop | \$ 1354.00 | 12 | 01-04-2006 | -7.0 years | 28.53% | Good | Retairi | |
| | | Cooktop Interior Painting | \$ 1354.00 \$ 434.00 | 12 10 | 01-04-2006 01-04-2006 | -7.0 years -9.0 years | 9.63% | Good | Retain | N/A |
| | LNILU0723 | · · | | | | | | | | N/A N/A |
| | LNILU0723 LNILU0724 | Interior Painting Kitchen | \$ 434.00 | 10 | 01-04-2006 | -9.0 years | 9.63% | Good | Retain | |

| | LNILU0728 | Rangehood | \$ 599.00 | 12 | 01-04-2006 | -7.0 years | 15.03% | Good | Retain | N/A |
|----------------------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU0729 | Sink & Fittings | \$ 1587.00 | 15 | 01-04-2006 | -4.0 years | 15.02% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0739 | Interior Painting | \$ 257.00 | 10 | 01-04-2006 | -9.0 years | 35.02% | Good | Retain | N/A |
| | LNILU0740 | Tiles - Wall | \$ 1209.00 | 20 | 01-04-2006 | 1.0 years | 5.86% | Good | Retain | N/A |
| | LNILU0741 | Tiles - Floor | \$ 2025.00 | 20 | 01-04-2006 | 1.0 years | 4.96% | Good | Retain | N/A |
| | LNILU4294 | Dryer | \$ 609.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4295 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4296 | Washing Machine | \$ 999.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| Living | | | ' | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0754 | Air Conditioner - Split System | \$ 3296.00 | 10 | 01-04-2006 | -9.0 years | 324.39% | Good | Retain | N/A |
| | LNILU0755 | Blind | \$ 388.00 | 10 | 01-04-2006 | -9.0 years | 17.14% | Good | Retain | N/A |
| | LNILU0756 | Carpet | \$ 1371.00 | 8 | 01-04-2006 | -11.0 years | 7.66% | Good | Retain | N/A |
| | LNILU0757 | Ceiling Fan | \$ 588.00 | 10 | 01-04-2006 | -9.0 years | 36.05% | Good | Retain | N/A |
| | LNILU0758 | Interior Painting | \$ 1065.00 | 10 | 01-04-2006 | -9.0 years | 36.06% | Good | Retain | N/A |
| Toilet room | | | ' | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0749 | Skylight | \$ 1040.00 | 10 | 01-04-2006 | -9.0 years | 24.50% | Good | Retain | N/A |
| | LNILU0750 | Toilet & Cistern | \$ 1343.00 | 20 | 01-04-2006 | 1.0 years | 90.10% | Good | Retain | N/A |
| | LNILU0751 | Tiles - Wall | \$ 899.00 | 20 | 01-04-2006 | 1.0 years | 18.02% | Good | Retain | N/A |
| | LNILU0752 | Tiles - Floor | \$ 1387.00 | 20 | 01-04-2006 | 1.0 years | 18.02% | Good | Retain | N/A |
| | LNILU0753 | Tapware | \$ 244.00 | 15 | 01-04-2006 | -4.0 years | 114.21% | Good | Retain | N/A |
| | LNILU4297 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Unit Exterior | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0765 | Clothesline | \$ 499.00 | 10 | 01-07-1982 | -32.7 years | 2.71% | Good | Retain | N/A |
| | LNILU0766 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 5.25% | Good | Retain | N/A |
| | LNILU0767 | Downpipes | \$ 1742.00 | 20 | 01-07-1982 | -22.7 years | 75.47% | Good | Retain | N/A |
| | | | | | | | I . | | | · |

| LNILU0768 | Electrical Switchboard | \$ 1964.00 | 20 | 01-07-1982 | -22.7 years | 93.18% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|-----------|--------|--------------------------------------------|
| LNILU0769 | Exterior Painting | \$ 2086.00 | 10 | 01-07-1982 | -32.7 years | 18.02% | Good | Retain | N/A |
| LNILU0770 | Fascias | \$ 2874.00 | 20 | 01-07-1982 | -22.7 years | 8.11% | Good | Retain | N/A |
| LNILU0771 | Flyscreens | \$ 1864.00 | 10 | 01-07-1982 | -32.7 years | 68.50% | Good | Retain | N/A |
| LNILU0772 | Guttering | \$ 2819.00 | 20 | 01-07-1982 | -22.7 years | 60.82% | Good | Retain | N/A |
| LNILU0773 | Hot Water System - Solar | \$ 4384.00 | 15 | 01-07-1982 | -27.7 years | 11.41% | Good | Retain | N/A |
| LNILU0774 | Lattice Screening | \$ 2142.00 | 20 | 01-07-1982 | -22.7 years | 1.35% | Good | Retain | N/A |
| LNILU0775 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.19% | Poor | Repair | Repair cracked pathway leading to entrance |
| LNILU0776 | Porch | \$ 3207.00 | 30 | 01-07-1982 | -12.7 years | 60.08% | Good | Retain | N/A |
| LNILU0777 | Water Tank | \$ 1032.00 | 25 | 01-07-1982 | -17.7 years | 36.05% | Good | Retain | N/A |
| LNILU0778 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Fair | Retain | N/A |
| LNILU0779 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU0780 | Balcony Flooring | \$ 3574.00 | 20 | 01-07-1982 | -22.7 years | 9.01% | Good | Retain | N/A |
| LNILU4738 | Awnings | \$ 8718.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Excellent | Retain | N/A |

Unit 10

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0806 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 16.68% | Good | Retain | N/A |
| LNILU0807 | Interior Painting | \$ 228.00 | 10 | 01-10-2020 | 5.5 years | 33.33% | Good | Retain | N/A |
| LNILU0808 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU0809 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU0810 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 32.08% | Good | Retain | N/A |
| LNILU0811 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU0812 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0794 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 11.40% | Good | Retain | N/A |

| | LNILU0795 | Carpet | \$ 891.00 | 8 | 01-10-2020 | 3.5 years | 10.40% | Good | Retain | N/A |
|-------|----------------------------------------------------------------|------------------------------------------------------------|------------------------------------------------------------------|----------------------------|----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------|------------------------------------------------|--------------------------|
| | LNILU0796 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 13.14% | Good | Retain | N/A |
| | LNILU0797 | Interior Painting | \$ 726.00 | 10 | 01-10-2020 | 5.5 years | 34.99% | Good | Retain | N/A |
| | LNILU0798 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| 2 | | | | | | | | | - | - |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0799 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU0800 | Carpet | \$ 743.00 | 8 | 01-10-2020 | 3.5 years | 8.20% | Good | Retain | N/A |
| | LNILU0801 | Interior Painting | \$ 605.00 | 10 | 01-10-2020 | 5.5 years | 35.04% | Good | Retain | N/A |
| | LNILU0802 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| ing | | | | | | | | | - | - |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0823 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU0824 | Carpet | \$ 640.00 | 8 | 01-10-2020 | 3.5 years | 21.88% | Good | Retain | N/A |
| | LNILU0825 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU0826 | Interior Painting | \$ 514.00 | 10 | 01-10-2020 | 5.5 years | 35.02% | Good | Retain | N/A |
| llway | | | | | , | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | Carpet | \$ 354.00 | 8 | 01-10-2020 | 3.5 years | 21.89% | Good | Retain | N/A |
| | LNILU0827 | Interior Painting | \$ 285.00 | 10 | 01-10-2020 | 5.5 years | 0.650/ | <u> </u> | D. L. C. | N/A |
| | LNILU0827 LNILU0828 | | | | | J.J years | 9.65% | Good | Retain | IN/A |
| hen | | | | | | J.J years | 9.05% | Good | Ketain | IV/A |
| hen | | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| hen | LNILU0828 | Asset Name Blind | Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | | | | | | |
| hen | LNILU0828 Asset Number | | • | | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| hen | Asset Number LNILU0785 | Blind | \$ 285.00 | 10 | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 12.28% | Asset Condition Good | Plan Retain | Comments N/A |
| hen | Asset Number LNILU0785 LNILU0786 | Blind Benchtops | \$ 285.00 \$ 2414.00 | 10 20 | 1nstallation Date 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years | Accumulated Repair Cost as % of Acquisition 12.28% 4.16% | Asset Condition Good Good | Plan Retain Retain | Comments N/A N/A |
| hen | Asset Number LNILU0785 LNILU0786 LNILU0787 | Blind Benchtops Cooktop | \$ 285.00 \$ 2414.00 \$ 1394.00 | 10 20 12 | 1nstallation Date 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years | Accumulated Repair Cost as % of Acquisition 12.28% 4.16% 29.17% | Asset Condition Good Good Good | Plan Retain Retain Retain | Comments N/A N/A N/A |
| hen | Asset Number LNILU0785 LNILU0786 LNILU0787 LNILU0788 | Blind Benchtops Cooktop Interior Painting Kitchen | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 | 10 20 12 10 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-10-2020 | Remaining Effective Life -32.7 years -22.7 years -30.7 years 5.5 years | Accumulated Repair Cost as % of Acquisition 12.28% 4.16% 29.17% 13.13% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | Comments N/A N/A N/A N/A |
| hen | Asset Number LNILU0785 LNILU0786 LNILU0787 LNILU0788 LNILU0789 | Blind Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | 10 20 12 10 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-10-2020 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years 5.5 years -22.7 years | Accumulated Repair Cost as % of Acquisition 12.28% 4.16% 29.17% 13.13% 16.62% | Asset Condition Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A |

| | LNILU0793 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 113.77% | Good | Retain | N/A |
|----------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------|
| ndry | | ' | ' | , | , | , | · | , | ' | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0803 | Interior Painting | \$ 257.00 | 10 | 01-10-2020 | 5.5 years | 15.76% | Good | Retain | N/A |
| | LNILU0804 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU0805 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU4298 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4299 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4300 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | Recommend 1 turn tapware |
| | LNILU4301 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ng | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0818 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| | LNILU0819 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU0820 | Carpet | \$ 1371.00 | 8 | 01-10-2020 | 3.5 years | 7.66% | Good | Retain | N/A |
| | LNILU0821 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU0822 | Interior Painting | \$ 1097.00 | 10 | 01-10-2020 | 5.5 years | 11.38% | Good | Retain | N/A |
| et room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0813 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU0814 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | N/A |
| | LNILU0815 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| | LNILU0816 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 9.18% | Good | Retain | N/A |
| | LNILU0817 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| | LNILU4302 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Exterior | | | | | | | · | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0829 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | | Doors | \$ 9215.00 | 30 | i | i e | 11.08% | Good | Retain | N/A |

| LNILU0831 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 35.01% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|--------|--------------------------|
| LNILU0832 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 9/10 |
| LNILU0833 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 8.31% | Good | Retain | N/A |
| LNILU0834 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU0835 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 21.00% | Good | Retain | N/A |
| LNILU0836 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 55.78% | Fair | Repair | Gutters require painting |
| LNILU0837 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU0838 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU0839 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.04% | Fair | Retain | Repair trip hazard |
| LNILU0840 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU0841 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 182.55% | Good | Retain | N/A |
| LNILU0842 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0843 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU0844 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 4.16% | Fair | Retain | N/A |
| LNILU4169 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 11-12

| common | | | | | | | | | | |
|--------|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0845 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |

Unit 11

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0846 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU0847 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 7.00% | Good | Retain | N/A |
| LNILU0848 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| LNILU0849 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

| - 11 | :- | 1 | |
|------|-----|---|---|
| U | nit | | 4 |

| LNILU0910 Insulation \$ 3224.00 20 01-07-1982 -22.7 years 0.00% Good Retain N/A LNILU0911 Lighting \$ 1966.00 15 01-03-2009 -1.1 years 1.75% Good Retain N/A LNILU0912 Sarking \$ 3384.00 25 01-07-1982 -17.7 years 5.25% Good Retain N/A | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0912 Sarking \$3384.00 25 01-07-1982 -17.7 years 5.25% Good Retain N/A | LNILU0910 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0911 | Lighting | \$ 1966.00 | 15 | 01-03-2009 | -1.1 years | 1.75% | Good | Retain | N/A |
| 17510/ 6 1 1 | LNILU0912 | Sarking | \$ 3384.00 | | 01-07-1982 | -17.7 years | 5.25% | Good | Retain | N/A |
| LNILU0913 Smoke Alarms \$ 268.00 20 01-03-2009 3.9 years 17.54% Good Retain N/A | LNILU0913 | Smoke Alarms | \$ 268.00 | 20 | 01-03-2009 | 3.9 years | 17.54% | Good | Retain | N/A |

Unit 11

Bathroom

| Asse | et Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|-----------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------|
| LNIL | .U0871 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNIL | .U0872 | Interior Painting | \$ 228.00 | 10 | 01-12-2013 | -1.3 years | 35.09% | Good | Retain | N/A |
| LNIL | .U0873 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNIL | .U0874 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNIL | .U0875 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 55.41% | Good | Retain | N/A |
| LNIL | .U0876 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Poor | Repair | Cracks on wall tile |
| LNIL | .U0877 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0859 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 16.67% | Good | Retain | N/A |
| LNILU0860 | Carpet | \$ 891.00 | 8 | 01-12-2013 | -3.3 years | 21.89% | Good | Retain | N/A |
| LNILU0861 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU0862 | Interior Painting | \$ 726.00 | 10 | 01-12-2013 | -1.3 years | 16.62% | Good | Retain | N/A |
| LNILU0863 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 16.62% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0864 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU0865 | Carpet | \$ 743.00 | 8 | 01-12-2013 | -3.3 years | 8.20% | Good | Retain | N/A |
| LNILU0866 | Interior Painting | \$ 605.00 | 10 | 01-12-2013 | -1.3 years | 33.29% | Good | Retain | N/A |
| LNILU0867 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU4303 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|---------------------|---------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| | LNILU0888 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU0889 | Carpet | \$ 640.00 | 8 | 01-12-2013 | -3.3 years | 20.78% | Good | Retain | N/A |
| | LNILU0890 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| | LNILU0891 | Interior Painting | \$ 514.00 | 10 | 01-12-2013 | -1.3 years | 35.02% | Good | Retain | N/A |
| lway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0892 | Carpet | \$ 354.00 | 8 | 01-12-2013 | -3.3 years | 20.80% | Good | Retain | N/A |
| | LNILU0893 | Interior Painting | \$ 285.00 | 10 | 01-12-2013 | -1.3 years | 33.33% | Good | Retain | N/A |
| hen | | | · | , | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0850 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU0851 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| | LNILU0852 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 29.17% | Good | Retain | N/A |
| | LNILU0853 | Interior Painting | \$ 434.00 | 10 | 01-12-2013 | -1.3 years | 15.76% | Good | Retain | N/A |
| | LNILU0854 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| | LNILU0855 | Vinyl | \$ 1011.00 | 10 | 01-12-2013 | -1.3 years | 39.39% | Good | Retain | N/A |
| | LNILU0856 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 69.29% | Good | Retain | N/A |
| | LNILU0857 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 6.93% | Good | Retain | N/A |
| | LNILU0858 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| ndry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0868 | Interior Painting | \$ 257.00 | 10 | 01-12-2013 | -1.3 years | 35.02% | Good | Retain | N/A |
| | LNILU0869 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Fair | Retain | N/A |

| Asset Numbe | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------------|--------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0868 | Interior Painting | \$ 257.00 | 10 | 01-12-2013 | -1.3 years | 35.02% | Good | Retain | N/A |
| LNILU0869 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Fair | Retain | N/A |
| LNILU0870 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | N/A |
| LNILU4304 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4305 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4306 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| L۱ | VI | n | C |
|----|----|---|---|
| | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0883 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU0884 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| LNILU0885 | Carpet | \$ 1371.00 | 8 | 01-12-2013 | -3.3 years | 21.88% | Good | Retain | N/A |
| LNILU0886 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| LNILU0887 | Interior Painting | \$ 1097.00 | 10 | 01-12-2013 | -1.3 years | 33.25% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0878 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU0879 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 83.12% | Good | Retain | N/A |
| LNILU0880 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU0881 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU0882 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| LNILU4307 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------------|
| LNILU0894 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 17.51% | Good | Retain | N/A |
| LNILU0895 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 4.08% | Good | Retain | N/A |
| LNILU0896 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 42.44% | Good | Retain | N/A |
| LNILU0897 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 21.87% | Good | Retain | Shared between unit 11/12 |
| LNILU0898 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.56% | Fair | Retain | N/A |
| LNILU0899 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 14.43% | Good | Retain | N/A |
| LNILU0900 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| LNILU0901 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 124.68% | Good | Retain | N/A |
| LNILU0902 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU0903 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

| LNILU0904 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | Pathway cracks between U11 & 18 |
|-----------|---------------------|------------|----|------------|-------------|--------|------|--------|------------------------------------|
| LNILU0905 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 4.37% | Fair | Retain | N/A |
| LNILU0906 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 15.75% | Good | Retain | N/A |
| LNILU0907 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU0908 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU0909 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Retain | N/A |
| LNILU4170 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 12

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------|
| LNILU0938 | Exhaust Fan | \$ 262.00 | 10 | 01-03-2009 | -6.1 years | 12.29% | Good | Retain | N/A |
| LNILU0939 | Interior Painting | \$ 228.00 | 10 | 01-03-2009 | -6.1 years | 12.28% | Good | Retain | N/A |
| LNILU0940 | Shower Screen | \$ 1200.00 | 20 | 01-03-2009 | 3.9 years | 17.50% | Good | Retain | N/A |
| LNILU0941 | Skylight | \$ 1040.00 | 10 | 01-03-2009 | -6.1 years | 70.00% | Good | Retain | N/A |
| LNILU0942 | Tapware | \$ 1343.00 | 15 | 01-03-2009 | -1.1 years | 116.65% | Good | Retain | N/A |
| LNILU0943 | Tiles - Wall | \$ 3384.00 | 20 | 01-03-2009 | 3.9 years | 17.49% | Fair | Repair | Cracks on wall tile |
| LNILU0944 | Tiles - Floor | \$ 4058.00 | 20 | 01-03-2009 | 3.9 years | 17.50% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------|
| LNILU0924 | Blind | \$ 342.00 | 10 | 01-03-2009 | -6.1 years | 35.09% | Good | Retain | N/A |
| LNILU0925 | Carpet | \$ 891.00 | 8 | 01-03-2009 | -8.1 years | 21.89% | Good | Retain | N/A |
| LNILU0926 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2009 | -6.1 years | 159.01% | Poor | Repair | Ceiling fan is noisy |
| LNILU0927 | Curtains | \$ 914.00 | 6 | 01-03-2009 | -10.1 years | 0.00% | Good | Retain | N/A |
| LNILU0928 | Interior Painting | \$ 726.00 | 10 | 01-03-2009 | -6.1 years | 34.99% | Good | Retain | N/A |
| LNILU0929 | Wardrobe | \$ 2115.00 | 10 | 01-03-2009 | -6.1 years | 28.87% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0930 | Blind | \$ 342.00 | 10 | 01-03-2009 | -6.1 years | 16.67% | Good | Retain | N/A |
| LNILU0931 | Carpet | \$ 743.00 | 8 | 01-03-2009 | -8.1 years | 20.78% | Good | Retain | N/A |
| LNILU0932 | Curtains | \$ 914.00 | 6 | 01-03-2009 | -10.1 years | 0.00% | Good | Retain | N/A |

| | LNILU0933 | Interior Painting | \$ 605.00 | 10 | 01-03-2009 | -6.1 years | 35.04% | Good | Retain | N/A |
|---------|------------------------|--------------------------------|-------------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|----------|----------|
| | LNILU0934 | Wardrobe | \$ 2115.00 | 10 | 01-03-2009 | -6.1 years | 13.12% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0955 | Blind | \$ 400.00 | 10 | 01-03-2009 | -6.1 years | 12.25% | Good | Retain | N/A |
| | LNILU0956 | Carpet | \$ 640.00 | 8 | 01-03-2009 | -8.1 years | 21.88% | Good | Retain | N/A |
| | LNILU0957 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2009 | -6.1 years | 35.04% | Good | Retain | N/A |
| | LNILU0958 | Interior Painting | \$ 514.00 | 10 | 01-03-2009 | -6.1 years | 33.27% | Good | Retain | N/A |
| | LNILU4314 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0959 | Carpet | \$ 354.00 | 8 | 01-03-2009 | -8.1 years | 6.02% | Good | Retain | N/A |
| | LNILU0960 | Interior Painting | \$ 285.00 | 10 | 01-03-2009 | -6.1 years | 16.67% | Good | Retain | N/A |
| Kitchen | | <u>'</u> | | | | | | | <u>'</u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0914 | Blind | \$ 285.00 | 10 | 01-03-2009 | -6.1 years | 35.09% | Good | Retain | N/A |
| | LNILU0915 | Benchtops | \$ 2414.00 | 20 | 01-03-2009 | 3.9 years | 8.75% | Good | Retain | N/A |
| | LNILU0916 | Cooktop | \$ 1394.00 | 12 | 01-03-2009 | -4.1 years | 29.17% | Good | Retain | N/A |
| | LNILU0917 | Curtains | \$ 342.00 | 6 | 01-03-2009 | -10.1 years | 0.00% | Good | Retain | N/A |
| | LNILU0918 | Interior Painting | \$ 434.00 | 10 | 01-03-2009 | -6.1 years | 33.27% | Good | Retain | N/A |
| | LNILU0919 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-03-2009 | 3.9 years | 17.50% | Good | Retain | N/A |
| | LNILU0920 | Vinyl | \$ 1011.00 | 10 | 01-03-2009 | -6.1 years | 21.88% | Good | Retain | N/A |
| | LNILU0921 | Oven | \$ 1451.00 | 12 | 01-03-2009 | -4.1 years | 138.58% | Good | Retain | N/A |
| | LNILU0922 | Rangehood | \$ 617.00 | 12 | 01-03-2009 | -4.1 years | 13.86% | Good | Retain | N/A |
| | LNILU0923 | Sink & Fittings | \$ 1634.00 | 15 | 01-03-2009 | -1.1 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | 01 02 2000 | -6.1 years | 33.27% | Good | Retain | N/A |
| | LNILU0935 | Interior Painting | \$ 257.00 | 10 | 01-03-2009 | o.i years | 33.2770 | 0000 | recuiii | , |
| | LNILU0935 LNILU0936 | Interior Painting Tiles - Wall | \$ 257.00 \$ 1246.00 | 20 | 01-03-2009 | 3.9 years | 7.87% | Fair | Repair | N/A |

| LNILU4308 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|-----------|--------------------|------------|----|------------|------------|-------|------|--------|-----|
| LNILU4309 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4310 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4311 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Numbe | r Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0950 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-03-2009 | -6.1 years | 133.85% | Good | Retain | N/A |
| LNILU0951 | Blind | \$ 400.00 | 10 | 01-03-2009 | -6.1 years | 14.88% | Good | Retain | N/A |
| LNILU0952 | Carpet | \$ 1371.00 | 8 | 01-03-2009 | -8.1 years | 9.85% | Good | Retain | N/A |
| LNILU0953 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2009 | -6.1 years | 35.04% | Good | Retain | N/A |
| LNILU0954 | Interior Painting | \$ 1097.00 | 10 | 01-03-2009 | -6.1 years | 33.25% | Fair | Retain | N/A |
| LNILU4313 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------|
| LNILU0945 | Skylight | \$ 1040.00 | 10 | 01-03-2009 | -6.1 years | 26.25% | Good | Retain | N/A |
| LNILU0946 | Toilet & Cistern | \$ 1383.00 | 20 | 01-03-2009 | 3.9 years | 24.06% | Good | Retain | N/A |
| LNILU0947 | Tiles - Wall | \$ 926.00 | 20 | 01-03-2009 | 3.9 years | 8.31% | Fair | Repair | Crack on wall tiles |
| LNILU0948 | Tiles - Floor | \$ 1429.00 | 20 | 01-03-2009 | 3.9 years | 17.49% | Good | Retain | N/A |
| LNILU0949 | Tapware | \$ 251.00 | 15 | 01-03-2009 | -1.1 years | 43.82% | Good | Retain | N/A |
| LNILU4312 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|-------------------------|
| LNILU0961 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU0962 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 3.50% | Good | Retain | N/A |
| LNILU0963 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 13.13% | Good | Retain | N/A |
| LNILU0964 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared with unit 11 |
| LNILU0965 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.12% | Fair | Repair | Repaint balcony ceiling |
| LNILU0966 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |

| LNILU0967 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 24.50% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|--------|-------------------------------|
| LNILU0968 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 124.68% | Good | Retain | N/A |
| LNILU0969 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU0970 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU0971 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | Path crack near water tank |
| LNILU0972 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU0973 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU0974 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU0975 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| LNILU0976 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 2.62% | Fair | Retain | N/A |
| LNILU4171 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 13-14

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU0977 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 12.25% | Good | Retain | N/A |
| t 13 | | | | <u> </u> | | , | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0978 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 12.93% | Good | Retain | N/A |
| | LNILU0979 | Lighting | \$ 1966.00 | 15 | 01-10-2004 | -5.5 years | 24.20% | Fair | Retain | N/A |
| | LNILU0980 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 83.20% | Good | Retain | N/A |
| | LNILU0981 | Smoke Alarms | \$ 268.00 | 20 | 01-10-2004 | -0.5 years | 16.66% | Good | Retain | N/A |
| it 14 | | ' | ' | | | | | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1043 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1044 | Lighting | \$ 1966.00 | 15 | 01-06-2006 | -3.8 years | 25.44% | Fair | Retain | N/A |
| | LNILU1045 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU1046 | Smoke Alarms | \$ 268.00 | 20 | 01-06-2006 | 1.2 years | 8.33% | Good | Retain | N/A |

| Bathroom | | A N | A | | Installation Date | Damaining Effective 116 | Accomplated Densin Cost == 0/ = £ A ==== !!! | A | Dlan | Commercial |
|----------|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|------------------------------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1005 | Exhaust Fan | \$ 262.00 | 10 | 01-10-2004 | -10.5 years | 16.68% | Fair | Retain | N/A |
| | LNILU1006 | Interior Painting | \$ 228.00 | 10 | 01-10-2004 | -10.5 years | 33.33% | Good | Retain | N/A |
| | LNILU1007 | Shower Screen | \$ 1200.00 | 20 | 01-10-2004 | -0.5 years | 17.50% | Good | Retain | Screen door doesn't close properly has been reported by resident |
| | LNILU1008 | Skylight | \$ 1040.00 | 10 | 01-10-2004 | -10.5 years | 31.50% | Good | Retain | N/A |
| | LNILU1009 | Tapware | \$ 1343.00 | 15 | 01-10-2004 | -5.5 years | 116.65% | Good | Retain | N/A |
| | LNILU1010 | Tiles - Wall | \$ 3384.00 | 20 | 01-10-2004 | -0.5 years | 7.87% | Good | Retain | N/A |
| | LNILU1011 | Tiles - Floor | \$ 4058.00 | 20 | 01-10-2004 | -0.5 years | 4.81% | Fair | Repair | Requires cleaning and regrouting |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0991 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-10-2004 | -10.5 years | 299.19% | Good | Retain | N/A |
| | LNILU0992 | Blind | \$ 342.00 | 10 | 01-10-2004 | -10.5 years | 33.33% | Good | Retain | N/A |
| | LNILU0993 | Carpet | \$ 891.00 | 8 | 01-10-2004 | -12.5 years | 21.89% | Fair | Retain | N/A |
| | LNILU0994 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2004 | -10.5 years | 33.29% | Good | Retain | N/A |
| | LNILU0995 | Interior Painting | \$ 726.00 | 10 | 01-10-2004 | -10.5 years | 34.99% | Good | Retain | N/A |
| | LNILU0996 | Wardrobe | \$ 2115.00 | 10 | 01-10-2004 | -10.5 years | 1.75% | Good | Retain | N/A |
| | LNILU4797 | Lighting | \$ 1966.00 | 15 | 01-10-2004 | -5.5 years | 0.00% | Poor | Repair | 2 lamps not operating |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0997 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-10-2004 | -10.5 years | 149.59% | Good | Retain | N/A |
| | LNILU0998 | Blind | \$ 342.00 | 10 | 01-10-2004 | -10.5 years | 35.09% | Good | Retain | N/A |
| | LNILU0999 | Carpet | \$ 743.00 | 8 | 01-10-2004 | -12.5 years | 1.64% | Good | Retain | N/A |
| | LNILU1000 | Interior Painting | \$ 605.00 | 10 | 01-10-2004 | -10.5 years | 33.29% | Good | Retain | N/A |
| | LNILU1001 | Wardrobe | \$ 2115.00 | 10 | 01-10-2004 | -10.5 years | 34.99% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|----------|----------|
| | LNILU1022 | Blind | \$ 400.00 | 10 | 01-10-2004 | -10.5 years | 35.00% | Good | Retain | N/A |
| | LNILU1023 | Carpet | \$ 640.00 | 8 | 01-10-2004 | -12.5 years | 1.64% | Good | Retain | N/A |
| | LNILU1024 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2004 | -10.5 years | 33.29% | Good | Retain | N/A |
| | LNILU1025 | Interior Painting | \$ 514.00 | 10 | 01-10-2004 | -10.5 years | 35.02% | Good | Retain | N/A |
| llway | | | | | | | | | <u>'</u> | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1026 | Carpet | \$ 354.00 | 8 | 01-10-2004 | -12.5 years | 6.57% | Good | Retain | N/A |
| | LNILU1027 | Interior Painting | \$ 285.00 | 10 | 01-10-2004 | -10.5 years | 12.28% | Good | Retain | N/A |
| chen | | | | | | , | | | <u> </u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0982 | Blind | \$ 285.00 | 10 | 01-10-2004 | -10.5 years | 35.09% | Good | Retain | N/A |
| | LNILU0983 | Benchtops | \$ 2414.00 | 20 | 01-10-2004 | -0.5 years | 4.16% | Good | Retain | N/A |
| | LNILU0984 | Cooktop | \$ 1394.00 | 12 | 01-10-2004 | -8.5 years | 29.17% | Good | Retain | N/A |
| | LNILU0985 | Interior Painting | \$ 434.00 | 10 | 01-10-2004 | -10.5 years | 35.02% | Good | Retain | N/A |
| | LNILU0986 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-10-2004 | -0.5 years | 6.12% | Good | Retain | N/A |
| | LNILU0987 | Vinyl | \$ 1011.00 | 10 | 01-10-2004 | -10.5 years | 87.54% | Good | Retain | N/A |
| | LNILU0988 | Oven | \$ 1451.00 | 12 | 01-10-2004 | -8.5 years | 145.88% | Good | Retain | N/A |
| | LNILU0989 | Rangehood | \$ 617.00 | 12 | 01-10-2004 | -8.5 years | 7.66% | Good | Retain | N/A |
| | LNILU0990 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2004 | -5.5 years | 55.43% | Good | Retain | N/A |
| ındry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1002 | Interior Painting | \$ 257.00 | 10 | 01-10-2004 | -10.5 years | 35.02% | Good | Retain | N/A |
| | LNILU1003 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2004 | -0.5 years | 17.50% | Good | Retain | N/A |

| Ass | set Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-----|------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNI | ILU1002 | Interior Painting | \$ 257.00 | 10 | 01-10-2004 | -10.5 years | 35.02% | Good | Retain | N/A |
| LNI | ILU1003 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2004 | -0.5 years | 17.50% | Good | Retain | N/A |
| LNI | ILU1004 | Tiles - Floor | \$ 2086.00 | 20 | 01-10-2004 | -0.5 years | 17.50% | Good | Retain | N/A |
| LNI | ILU4315 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNI | ILU4316 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNI | ILU4317 | Washing Machine | \$ 1028.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| | | ~ |
|-----|-----|----|
| _11 | /11 | HL |
| | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1017 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-10-2004 | -10.5 years | 314.93% | Good | Retain | N/A |
| LNILU1018 | Blind | \$ 400.00 | 10 | 01-10-2004 | -10.5 years | 35.00% | Good | Retain | N/A |
| LNILU1019 | Carpet | \$ 1371.00 | 8 | 01-10-2004 | -12.5 years | 21.88% | Good | Retain | N/A |
| LNILU1020 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2004 | -10.5 years | 35.04% | Good | Retain | N/A |
| LNILU1021 | Interior Painting | \$ 1097.00 | 10 | 01-10-2004 | -10.5 years | 15.75% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1012 | Skylight | \$ 1040.00 | 10 | 01-10-2004 | -10.5 years | 57.75% | Good | Retain | N/A |
| LNILU1013 | Toilet & Cistern | \$ 1383.00 | 20 | 01-10-2004 | -0.5 years | 87.49% | Good | Retain | N/A |
| LNILU1014 | Tiles - Wall | \$ 926.00 | 20 | 01-10-2004 | -0.5 years | 17.49% | Good | Retain | N/A |
| LNILU1015 | Tiles - Floor | \$ 1429.00 | 20 | 01-10-2004 | -0.5 years | 17.49% | Good | Retain | N/A |
| LNILU1016 | Tapware | \$ 251.00 | 15 | 01-10-2004 | -5.5 years | 61.35% | Good | Retain | N/A |
| LNILU4318 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------------|
| LNILU1028 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1029 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1030 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 78.27% | Good | Retain | N/A |
| LNILU1031 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 112.43% | Good | Retain | Shared between unit 13/14 |
| LNILU1032 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.44% | Good | Retain | N/A |
| LNILU1033 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1034 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1035 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 124.68% | Good | Retain | N/A |
| LNILU1036 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1037 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.60% | Good | Retain | N/A |
| LNILU1038 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |

| LNILU1039 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 33.25% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU1040 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1041 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| LNILU1042 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU4172 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 14

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1071 | Exhaust Fan | \$ 262.00 | 10 | 01-06-2006 | -8.8 years | 33.36% | Good | Retain | N/A |
| LNILU1072 | Interior Painting | \$ 228.00 | 10 | 01-06-2006 | -8.8 years | 15.79% | Good | Retain | N/A |
| LNILU1073 | Shower Screen | \$ 1200.00 | 20 | 01-06-2006 | 1.2 years | 16.63% | Good | Retain | N/A |
| LNILU1074 | Skylight | \$ 1040.00 | 10 | 01-06-2006 | -8.8 years | 70.00% | Good | Retain | N/A |
| LNILU1075 | Tapware | \$ 1343.00 | 15 | 01-06-2006 | -3.8 years | 116.65% | Good | Retain | N/A |
| LNILU1076 | Tiles - Wall | \$ 3384.00 | 20 | 01-06-2006 | 1.2 years | 17.49% | Good | Retain | N/A |
| LNILU1077 | Tiles - Floor | \$ 4058.00 | 20 | 01-06-2006 | 1.2 years | 17.50% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1056 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-06-2006 | -8.8 years | 314.93% | Good | Retain | N/A |
| LNILU1057 | Blind | \$ 342.00 | 10 | 01-06-2006 | -8.8 years | 12.28% | Good | Retain | N/A |
| LNILU1058 | Carpet | \$ 891.00 | 8 | 01-06-2006 | -10.8 years | 18.06% | Good | Retain | N/A |
| LNILU1059 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2006 | -8.8 years | 33.29% | Good | Retain | N/A |
| LNILU1060 | Curtains | \$ 914.00 | 6 | 01-06-2006 | -12.8 years | 0.00% | Good | Retain | N/A |
| LNILU1061 | Interior Painting | \$ 726.00 | 10 | 01-06-2006 | -8.8 years | 34.99% | Good | Retain | N/A |
| LNILU1062 | Wardrobe | \$ 2115.00 | 10 | 01-06-2006 | -8.8 years | 33.24% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1063 | Blind | \$ 342.00 | 10 | 01-06-2006 | -8.8 years | 15.79% | Good | Retain | N/A |
| LNILU1064 | Carpet | \$ 743.00 | 8 | 01-06-2006 | -10.8 years | 21.87% | Good | Retain | N/A |
| LNILU1065 | Curtains | \$ 914.00 | 6 | 01-06-2006 | -12.8 years | 0.00% | Good | Retain | N/A |
| LNILU1066 | Interior Painting | \$ 605.00 | 10 | 01-06-2006 | -8.8 years | 35.04% | Good | Retain | N/A |

| | LNILU1067 | Wardrobe | \$ 2115.00 | 10 | 01-06-2006 | -8.8 years | 15.74% | Good | Retain | N/A |
|--------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| Dining | | , | ' | , | | | | , | ' | , |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1088 | Blind | \$ 400.00 | 10 | 01-06-2006 | -8.8 years | 33.25% | Good | Retain | N/A |
| | LNILU1089 | Carpet | \$ 640.00 | 8 | 01-06-2006 | -10.8 years | 21.88% | Good | Retain | N/A |
| | LNILU1090 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2006 | -8.8 years | 0.00% | Fair | Retain | N/A |
| | LNILU1091 | Curtains | \$ 914.00 | 6 | 01-06-2006 | -12.8 years | 0.00% | Good | Retain | N/A |
| | LNILU1092 | Interior Painting | \$ 514.00 | 10 | 01-06-2006 | -8.8 years | 35.02% | Fair | Retain | N/A |
| allway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1093 | Carpet | \$ 354.00 | 8 | 01-06-2006 | -10.8 years | 20.80% | Good | Retain | N/A |
| | LNILU1094 | Interior Painting | \$ 285.00 | 10 | 01-06-2006 | -8.8 years | 33.33% | Good | Retain | N/A |
| itchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1047 | Blind | \$ 285.00 | 10 | 01-06-2006 | -8.8 years | 14.91% | Good | Retain | N/A |
| | LNILU1048 | Benchtops | \$ 2414.00 | 20 | 01-06-2006 | 1.2 years | 8.75% | Good | Retain | N/A |
| | LNILU1049 | Cooktop | \$ 1394.00 | 12 | 01-06-2006 | -6.8 years | 10.21% | Good | Retain | N/A |
| | LNILU1050 | Interior Painting | \$ 434.00 | 10 | 01-06-2006 | -8.8 years | 12.26% | Good | Retain | N/A |
| | LNILU1051 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-06-2006 | 1.2 years | 14.44% | Good | Retain | N/A |
| | LNILU1052 | Vinyl | \$ 1011.00 | 10 | 01-06-2006 | -8.8 years | 26.26% | Good | Retain | N/A |
| | LNILU1053 | Oven | \$ 1451.00 | 12 | 01-06-2006 | -6.8 years | 145.88% | Good | Retain | N/A |
| | LNILU1054 | Rangehood | \$ 617.00 | 12 | 01-06-2006 | -6.8 years | 5.11% | Good | Retain | N/A |
| | LNILU1055 | Sink & Fittings | \$ 1634.00 | 15 | 01-06-2006 | -3.8 years | 40.84% | Good | Retain | N/A |
| undry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1068 | Interior Painting | \$ 257.00 | 10 | 01-06-2006 | -8.8 years | 12.26% | Good | Retain | N/A |
| | LNILU1069 | Tiles - Wall | \$ 1246.00 | 20 | 01-06-2006 | 1.2 years | 16.62% | Good | Retain | N/A |
| | LNILU1070 | Tiles - Floor | \$ 2086.00 | 20 | 01-06-2006 | 1.2 years | 17.50% | Good | Retain | N/A |
| | LNILU4319 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4320 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Fair | Repair | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|----------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|----------|----------|
| | LNILU1084 | Blind | \$ 400.00 | 10 | 01-06-2006 | -8.8 years | 15.75% | Good | Retain | N/A |
| | LNILU1085 | Carpet | \$ 1371.00 | 8 | 01-06-2006 | -10.8 years | 10.39% | Good | Retain | N/A |
| | LNILU1086 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2006 | -8.8 years | 33.29% | Good | Retain | N/A |
| | | | | | | | | | | |
| | LNILU1087 | Interior Painting | \$ 1097.00 | 10 | 01-06-2006 | -8.8 years | 35.00% | Fair | Retain | N/A |
| | LNILU4323 | Air Conditioner - Split System | \$ 3395.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4324 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1078 | Skylight | \$ 1040.00 | 10 | 01-06-2006 | -8.8 years | 70.00% | Good | Retain | N/A |
| | LNILU1079 | Toilet & Cistern | \$ 1383.00 | 20 | 01-06-2006 | 1.2 years | 87.49% | Good | Retain | N/A |
| | LNILU1080 | Tiles - Wall | \$ 926.00 | 20 | 01-06-2006 | 1.2 years | 17.49% | Good | Retain | N/A |
| | LNILU1081 | Tiles - Floor | \$ 1429.00 | 20 | 01-06-2006 | 1.2 years | 17.49% | Good | Retain | N/A |
| | LNILU1082 | Tapware | \$ 251.00 | 15 | 01-06-2006 | -3.8 years | 32.14% | Good | Retain | N/A |
| | LNILU4322 | Exhaust Fan | \$ 262.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Exterior | | | | | | | | | <u>'</u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1095 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1096 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| | LNILU1097 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 35.01% | Good | Retain | N/A |
| | LNILU1098 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 116.80% | Good | Retain | N/A |
| | LNILU1099 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 16.62% | Good | Retain | N/A |
| | LNILU1100 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| | LNILU1101 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| | LNILU1102 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 39.37% | Fair | Retain | N/A |
| | | | - | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |

0.00% Good

N/A

Retain

12

\$ 1028.00

LNILU4321

Washing

Machine

14-11-2022 9.7 years

| LNILU1104 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 25.06% | Good | Retain | N/A |
|-----------|----------------------|------------|----|------------|-------------|--------|------|--------|----------------------------------------|
| LNILU1105 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU1106 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1107 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 9.62% | Good | Retain | N/A |
| LNILU1108 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1109 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1110 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 19.47% | Fair | Repair | Clean/regrout or replace damaged tiles |
| LNILU4173 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 15-16

Unit 15

Bathroom

Asset Number

LNILU1137

Asset Name

Exhaust Fan

Acquisition Cost (\$)

\$ 262.00

Effective Life (Y)

10

Installation Date

01-10-2007 -7.5 years

| Common | | | | | | | | | | |
|---------|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|----------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1111 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Jnit 15 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1112 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1113 | Lighting | \$ 1966.00 | 15 | 01-10-2007 | -2.5 years | 8.17% | Good | Retain | N/A |
| | LNILU1114 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 24.49% | Good | Retain | N/A |
| | LNILU1115 | Smoke Alarms | \$ 268.00 | 20 | 01-10-2007 | 2.5 years | 17.54% | Good | Retain | N/A |
| Jnit 16 | | ' | | , | | | | | <u>'</u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1175 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1176 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Fair | Retain | N/A |
| | LNILU1177 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU1178 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 8.33% | Good | Retain | N/A |

Remaining Effective Life

Accumulated Repair Cost as % of Acquisition

Asset Condition

12.29% Fair

Plan

Retain

Comments

N/A

| LNILU1126 LNILU1127 | Carpet Ceiling Fan | \$ 891.00 \$ 605.00 | 8 10 | 01-10-2007 01-10-2007 | -9.5 years -7.5 years | 10.40% 35.04% | Good | Retain Retain | N/A N/A |
|------------------------|--------------------|------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|-----------------|------------------|-------------------------------------------------------|
| LNILU1125 | Blind | \$ 342.00 | 10 | 01-10-2007 | -7.5 years | 35.09% | Good | Retain | N/A |
| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | |
| | | | | | | | | | regroutingFlooring has been re- grouted/cleaned |
| LNILU1143 | Tiles - Floor | \$ 4058.00 | 20 | 01-10-2007 | 2.5 years | 8.31% | Good | Retain | Requires cleaning and |
| LNILU1142 | Tiles - Wall | \$ 3384.00 | 20 | 01-10-2007 | 2.5 years | 7.87% | Good | Retain | N/A |
| LNILU1141 | Tapware | \$ 1343.00 | 15 | 01-10-2007 | -2.5 years | 116.65% | Good | Retain | N/A |
| LNILU1140 | Skylight | \$ 1040.00 | 10 | 01-10-2007 | -7.5 years | 66.50% | Good | Retain | N/A |
| LNILU1139 | Shower Screen | \$ 1200.00 | 20 | 01-10-2007 | 2.5 years | 4.81% | Good | Retain | N/A |
| LNILU1138 | Interior Painting | \$ 228.00 | 10 | 01-10-2007 | -7.5 years | 16.67% | Good | Retain | N/A |

Bed 2

Bed 1

LNILU1128

LNILU1129

LNILU4325

Interior Painting

Wardrobe

Curtains

\$ 726.00

\$ 2115.00

\$ 914.00

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1130 | Blind | \$ 342.00 | 10 | 01-10-2007 | -7.5 years | 16.67% | Good | Retain | N/A |
| LNILU1131 | Carpet | \$ 743.00 | 8 | 01-10-2007 | -9.5 years | 21.87% | Good | Retain | N/A |
| LNILU1132 | Interior Painting | \$ 605.00 | 10 | 01-10-2007 | -7.5 years | 35.04% | Good | Retain | N/A |
| LNILU1133 | Wardrobe | \$ 2115.00 | 10 | 01-10-2007 | -7.5 years | 13.12% | Good | Retain | N/A |
| LNILU4326 | Ceiling Fan | \$ 605.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

34.99% Good

9.62% Good

0.00% Good

N/A

N/A

N/A

Retain

Retain

Retain

01-10-2007 -7.5 years

01-10-2007 -7.5 years

14-11-2022 3.7 years

10

10

6

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1154 | Blind | \$ 400.00 | 10 | 01-10-2007 | -7.5 years | 35.00% | Good | Retain | N/A |
| LNILU1155 | Carpet | \$ 640.00 | 8 | 01-10-2007 | -9.5 years | 21.88% | Good | Retain | N/A |
| LNILU1156 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2007 | -7.5 years | 35.04% | Good | Retain | N/A |
| LNILU1157 | Interior Painting | \$ 514.00 | 10 | 01-10-2007 | -7.5 years | 9.63% | Good | Retain | N/A |
| LNILU4331 | Curtains | \$ 914.00 | 6 | 14-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

| Hall | way |
|------|-----|
|------|-----|

LNILU1150

Blind

| univuy | | | | | | | | | | |
|--------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1158 | Carpet | \$ 354.00 | 8 | 01-10-2007 | -9.5 years | 21.89% | Good | Retain | N/A |
| | LNILU1159 | Interior Painting | \$ 285.00 | 10 | 01-10-2007 | -7.5 years | 12.28% | Good | Retain | N/A |
| itchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1116 | Blind | \$ 285.00 | 10 | 01-10-2007 | -7.5 years | 33.33% | Good | Retain | N/A |
| | LNILU1117 | Benchtops | \$ 2414.00 | 20 | 01-10-2007 | 2.5 years | 8.31% | Good | Retain | N/A |
| | LNILU1119 | Interior Painting | \$ 434.00 | 10 | 01-10-2007 | -7.5 years | 33.27% | Fair | Retain | Re grouting requires at front of the sink. |
| | LNILU1120 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-10-2007 | 2.5 years | 17.50% | Good | Retain | N/A |
| | LNILU1121 | Vinyl | \$ 1011.00 | 10 | 01-10-2007 | -7.5 years | 87.54% | Fair | Retain | N/A |
| | LNILU1122 | Oven | \$ 1451.00 | 12 | 01-10-2007 | -5.5 years | 145.88% | Good | Retain | N/A |
| | LNILU1123 | Rangehood | \$ 617.00 | 12 | 01-10-2007 | -5.5 years | 13.86% | Good | Retain | N/A |
| | LNILU1124 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2007 | -2.5 years | 55.43% | Good | Retain | N/A |
| | LNILU4645 | Cooktop | \$ 4063.00 | 12 | 21-08-2023 | 10.4 years | 0.00% | Excellent | Retain | N/A |
| ndry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1134 | Interior Painting | \$ 257.00 | 10 | 01-10-2007 | -7.5 years | 9.63% | Good | Retain | N/A |
| | LNILU1135 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2007 | 2.5 years | 1.31% | Good | Retain | N/A |
| | LNILU1136 | Tiles - Floor | \$ 2086.00 | 20 | 01-10-2007 | 2.5 years | 16.62% | Fair | Retain | N/A |
| | LNILU4327 | Blind | \$ 400.00 | 10 | 14-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4328 | Dryer | \$ 627.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4329 | Sink & Fittings | \$ 1634.00 | 15 | 14-11-2022 | 12.7 years | 0.00% | Fair | Retain | Upgrade to 1/4 turn |
| | LNILU4330 | Washing Machine | \$ 1371.00 | 12 | 14-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1149 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-10-2007 | -7.5 years | 391.96% | Good | Retain | New A/c unit (no asset No.) |
| | | | | | | | | | | |

35.00% Good

Retain

N/A

10

01-10-2007 -7.5 years

\$ 400.00

| LNILU1151 | Carpet | \$ 1371.00 | 8 | 01-10-2007 | -9.5 years | 10.39% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|------------|--------|------|--------|-----|
| LNILU1152 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2007 | -7.5 years | 33.29% | Good | Retain | N/A |
| LNILU1153 | Interior Painting | \$ 1097.00 | 10 | 01-10-2007 | -7.5 years | 12.25% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1144 | Skylight | \$ 1040.00 | 10 | 01-10-2007 | -7.5 years | 70.00% | Fair | Repair | N/A |
| LNILU1145 | Toilet & Cistern | \$ 1383.00 | 20 | 01-10-2007 | 2.5 years | 87.49% | Good | Retain | N/A |
| LNILU1146 | Tiles - Wall | \$ 926.00 | 20 | 01-10-2007 | 2.5 years | 17.49% | Good | Retain | N/A |
| LNILU1147 | Tiles - Floor | \$ 1429.00 | 20 | 01-10-2007 | 2.5 years | 17.49% | Fair | Retain | N/A |
| LNILU1148 | Tapware | \$ 251.00 | 15 | 01-10-2007 | -2.5 years | 116.86% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------------------------------------------|
| LNILU1160 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1161 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1162 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 121.25% | Good | Retain | N/A |
| LNILU1163 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 155.32% | Good | Retain | Shared between unit 15/16 |
| LNILU1164 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Fair | Repair | Marks present on the balcony soffit, requires re-painting |
| LNILU1166 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 21.00% | Good | Retain | N/A |
| LNILU1168 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1169 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.63% | Good | Retain | Path crack opposite water tank & AC unit ot be monitored |
| LNILU1170 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1172 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1173 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1174 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4174 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Good | Retain | N/A |
| LNILU4647 | Guttering | \$ 1432.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

| | LNILU4648 | Fascias | \$ 1432.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
|----------|-----------|------------|------------|----|------------|------------|-------|-----------|--------|-----|
| | LNILU4798 | Water Tank | \$ 1063.00 | 25 | 09-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |
| 11.14.46 | | | | | | | | | | |

| | • . | -4 | |
|-------|-----|----|---|
| m | | -1 | h |
| | | | v |

| | Trate: raint | 4 .005.00 | | 05 0. 202. | 2010) 00.10 | 0.007.5 | 0000 | | , |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | | | | | | | |
| | | | | | | | | | |
| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU1200 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 12.29% | Good | Retain | N/A |
| LNILU1201 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU1202 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 4.81% | Good | Retain | N/A |
| LNILU1203 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU1204 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 37.91% | Good | Retain | N/A |
| LNILU1205 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU1206 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Retain | N/A |
| | | | | | | | | | |
| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU1188 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 33.33% | Good | Retain | N/A |
| LNILU1189 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Fair | Retain | N/A |
| LNILU1190 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 13.14% | Good | Retain | N/A |
| LNILU1191 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU1192 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 33.24% | Good | Retain | N/A |
| LNILU4333 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1200 LNILU1201 LNILU1202 LNILU1203 LNILU1204 LNILU1205 LNILU1206 Asset Number LNILU1188 LNILU1189 LNILU1190 LNILU1191 LNILU1192 | LNILU1200 Exhaust Fan LNILU1201 Interior Painting LNILU1202 Shower Screen LNILU1203 Skylight LNILU1204 Tapware LNILU1205 Tiles - Wall LNILU1206 Tiles - Floor Asset Number Asset Name LNILU1188 Blind LNILU1189 Carpet LNILU1190 Ceiling Fan LNILU1191 Interior Painting LNILU1192 Wardrobe | Asset Number Asset Name Acquisition Cost (\$) LNILU1200 Exhaust Fan \$ 262.00 LNILU1201 Interior Painting \$ 228.00 LNILU1202 Shower Screen \$ 1200.00 LNILU1203 Skylight \$ 1040.00 LNILU1204 Tapware \$ 1343.00 LNILU1205 Tiles - Wall \$ 3384.00 LNILU1206 Tiles - Floor \$ 4058.00 Asset Number Asset Name Acquisition Cost (\$) LNILU1188 Blind \$ 342.00 LNILU1189 Carpet \$ 891.00 LNILU1190 Ceiling Fan \$ 605.00 LNILU1191 Interior Painting \$ 726.00 LNILU1192 Wardrobe \$ 2115.00 | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) LNILU1200 Exhaust Fan \$ 262.00 10 LNILU1201 Interior Painting \$ 228.00 10 LNILU1202 Shower Screen \$ 1200.00 20 LNILU1203 Skylight \$ 1040.00 10 LNILU1204 Tapware \$ 1343.00 15 LNILU1205 Tiles - Wall \$ 3384.00 20 LNILU1206 Tiles - Floor \$ 4058.00 20 Asset Number LNILU1188 Blind \$ 342.00 10 LNILU1189 Carpet \$ 891.00 8 LNILU1190 Ceiling Fan \$ 605.00 10 LNILU1191 Interior Painting \$ 726.00 10 LNILU1192 Wardrobe \$ 2115.00 10 | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 LNILU1203 Skylight \$ 1040.00 10 01-07-1982 LNILU1204 Tapware \$ 1343.00 15 01-07-1982 LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 LNILU1188 Blind \$ 342.00 10 01-07-1982 LNILU1189 Carpet \$ 891.00 8 01-07-1982 LNILU1190 Ceiling Fan \$ 605.00 10 01-07-1982 LNILU1191 Interior Painting \$ 726.00 10 01-07-1982 LNILU1192 Wardrobe \$ 2115.00 10 01-07-1982 | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 -32.7 years LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years LNILU1203 Skylight \$ 1040.00 10 01-07-1982 -32.7 years LNILU1204 Tapware \$ 1343.00 15 01-07-1982 -27.7 years LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life LNILU1188 Blind \$ 342.00 10 01-07-1982 -32.7 years LNILU1190 Ceiling Fan \$ 605.00 10 01-07-1982 <t< td=""><td>Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 12.29% LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 -32.7 years 35.09% LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 481% LNILU1203 Skylight \$ 1040.00 10 01-07-1982 -32.7 years 66.50% LNILU1204 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 37.91% LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 7.87% LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years 7.87% LNILU1180 Blind \$ 342.00 10 01-07-1982 -32.7 years 28.00 17.50% LNILU1189 Carpet \$ 891.00 8</td><td>Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 12.29% Good LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 -32.7 years 35.09% Good LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 4.81% Good LNILU1203 Skylight \$ 1040.00 10 01-07-1982 -22.7 years 66.50% Good LNILU1204 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 37.91% Good LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 7.87% Good LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years 17.50% Fair Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y)</td><td> Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan </td></t<> | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 12.29% LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 -32.7 years 35.09% LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 481% LNILU1203 Skylight \$ 1040.00 10 01-07-1982 -32.7 years 66.50% LNILU1204 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 37.91% LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 7.87% LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years 7.87% LNILU1180 Blind \$ 342.00 10 01-07-1982 -32.7 years 28.00 17.50% LNILU1189 Carpet \$ 891.00 8 | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition LNILU1200 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 12.29% Good LNILU1201 Interior Painting \$ 228.00 10 01-07-1982 -32.7 years 35.09% Good LNILU1202 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 4.81% Good LNILU1203 Skylight \$ 1040.00 10 01-07-1982 -22.7 years 66.50% Good LNILU1204 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 37.91% Good LNILU1205 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 7.87% Good LNILU1206 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years 17.50% Fair Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) | Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1193 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU1194 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 20.78% | Fair | Retain | N/A |
| LNILU1195 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 164.79% | Good | Retain | N/A |
| LNILU1196 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 12.25% | Good | Retain | N/A |

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1217 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 12.25% | Good | Retain | N/A |
| LNILU1218 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 1.64% | Fair | Retain | N/A |
| LNILU1219 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |

| | LNILU1220 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Good | Retain | N/A |
|---------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------|
| | LNILU4340 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1221 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 9.85% | Good | Retain | N/A |
| | LNILU1222 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Fair | Retain | N/A |
| Kitchen | | | | | | | | | | |
| ` | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1180 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Retain | Requires upgrade soon. |
| | LNILU1181 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 13.13% | Good | Retain | N/A |
| | LNILU1182 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1183 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| | LNILU1184 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 41.58% | Fair | Retain | N/A |
| | LNILU1185 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| | LNILU1186 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 4.01% | Fair | Retain | N/A |
| | LNILU1187 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 43.76% | Fair | Repair | Re grout tiles behind sink |
| | LNILU4332 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Laundry | | | | | | | _ | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1197 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Good | Retain | N/A |
| | LNILU1198 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 7.44% | Good | Retain | N/A |
| | LNILU1199 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Fair | Retain | N/A |
| | LNILU4334 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4335 | Dryer | \$ 627.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4336 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgraded to 1/4 turn |
| | LNILU4337 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| | • | | |
|-----|----|---|---|
| L۱۱ | VI | n | C |
| | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1212 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 149.59% | Good | Retain | N/A |
| LNILU1213 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| LNILU1214 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 10.39% | Fair | Retain | N/A |
| LNILU1215 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU1216 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU4339 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1207 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 31.50% | Good | Retain | N/A |
| LNILU1208 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU1209 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1210 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1211 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 111.02% | Good | Retain | N/A |
| LNILU4338 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU1223 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1224 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1225 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 128.85% | Good | Retain | N/A |
| LNILU1226 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 106.61% | Good | Retain | Shared between unit 15/16 |
| LNILU1227 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Fair | Retain | N/A |
| LNILU1229 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU1231 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1232 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 4.81% | Good | Retain | N/A |
| LNILU1233 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1235 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |

| LNILU1236 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|-------|-----------|--------|-----|
| LNILU1237 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4646 | Awnings | \$ 9176.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4649 | Guttering | \$ 1624.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4650 | Fascias | \$ 1624.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4799 | Water Tank | \$ 1063.00 | 25 | 09-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |

Unit 17-18

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|----------|----------|
| | LNILU1238 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| nit 17 | | | | | | | | | · | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1239 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1240 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU1241 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 81.61% | Fair | Retain | N/A |
| | LNILU1242 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| nit 18 | | ' | | | | | | | <u>'</u> | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1303 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1304 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU1305 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 1.75% | Good | Retain | N/A |
| | LNILU1306 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 16.66% | Good | Retain | N/A |

Unit 17

| Bathroon | ſ |
|----------|---|
|----------|---|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1264 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 16.68% | Good | Retain | N/A |
| LNILU1265 | Interior Painting | \$ 228.00 | 10 | 01-08-2020 | 5.4 years | 33.33% | Good | Retain | N/A |
| LNILU1266 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1267 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 24.50% | Good | Retain | N/A |

| | LNILU1268 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 8.75% | Good | Retain | N/A |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|---------|------------------------------------------------|
| | LNILU1269 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| | LNILU1270 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Fair | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1252 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1253 | Carpet | \$ 891.00 | 8 | 01-08-2020 | 3.4 years | 6.02% | Poor | Replace | Carpet is very old; Recommend new carpet |
| | LNILU1254 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Poor | Repair | Re-adjust fan capping back in place |
| | LNILU1255 | Interior Painting | \$ 726.00 | 10 | 01-08-2020 | 5.4 years | 33.24% | Good | Retain | N/A |
| | LNILU1256 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 33.24% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1257 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1258 | Carpet | \$ 743.00 | 8 | 01-08-2020 | 3.4 years | 20.78% | Good | Retain | N/A |
| | LNILU1259 | Interior Painting | \$ 605.00 | 10 | 01-08-2020 | 5.4 years | 35.04% | Good | Retain | N/A |
| | LNILU1260 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 18.37% | Good | Retain | N/A |
| | LNILU4341 | Ceiling Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1281 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU1282 | Carpet | \$ 640.00 | 8 | 01-08-2020 | 3.4 years | 20.78% | Fair | Retain | N/A |
| | LNILU1283 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU1284 | Interior Painting | \$ 514.00 | 10 | 01-08-2020 | 5.4 years | 16.63% | Good | Retain | N/A |
| lallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1285 | Carpet | \$ 354.00 | 8 | 01-08-2020 | 3.4 years | 21.89% | Poor | Replace | Carpet is very old; Recommend new carpet |
| | LNILU1286 | Interior Painting | \$ 285.00 | 10 | 01-08-2020 | 5.4 years | 35.09% | Good | Retain | N/A |
| | | | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|---------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1243 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 9.65% | Good | Retain | N/A |
| LNILU1244 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1245 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 10.21% | Fair | Retain | N/A |
| LNILU1246 | Interior Painting | \$ 434.00 | 10 | 01-08-2020 | 5.4 years | 15.76% | Good | Retain | N/A |
| LNILU1247 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1248 | Vinyl | \$ 1011.00 | 10 | 01-08-2020 | 5.4 years | 87.54% | Good | Retain | N/A |
| LNILU1249 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 69.29% | Good | Retain | N/A |
| LNILU1250 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 6.56% | Good | Retain | N/A |
| LNILU1251 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1261 | Interior Painting | \$ 257.00 | 10 | 01-08-2020 | 5.4 years | 33.27% | Good | Retain | N/A |
| LNILU1262 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU1263 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 5.25% | Good | Retain | N/A |
| LNILU4342 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4343 | Dryer | \$ 937.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4344 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4345 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|---------|------------------------------------------------|
| LNILU1276 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU1277 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU1278 | Carpet | \$ 1371.00 | 8 | 01-08-2020 | 3.4 years | 6.02% | Poor | Replace | Carpet is very old; Recommend new carpet |
| LNILU1279 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| LNILU1280 | Interior Painting | \$ 1097.00 | 10 | 01-08-2020 | 5.4 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1271 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| LNILU1272 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 83.12% | Good | Retain | N/A |
| LNILU1273 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1274 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1275 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 2.92% | Good | Retain | N/A |
| LNILU4346 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU1287 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 15.76% | Good | Retain | N/A |
| LNILU1288 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1289 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 80.57% | Good | Retain | N/A |
| LNILU1290 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 111.25% | Good | Retain | Shared between unit 17/18 |
| LNILU1291 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Fair | Retain | N/A |
| LNILU1292 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1293 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU1294 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU1295 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1296 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1297 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 0.44% | Good | Retain | N/A |
| LNILU1298 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1299 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 209.03% | Fair | Retain | N/A |
| LNILU1300 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 4.08% | Good | Retain | N/A |
| LNILU1301 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 2.41% | Good | Retain | N/A |
| LNILU1302 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.06% | Good | Retain | N/A |
| LNILU4176 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Fair | Retain | N/A |

| throom | | | | | | | | | | |
|--------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1334 | Interior Painting | \$ 228.00 | 10 | 01-05-2015 | 0.1 years | 35.09% | Excellent | Retain | N/A |
| | LNILU4800 | Exhaust Fan | \$ 262.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4801 | Shower Screen | \$ 1200.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4802 | Skylight | \$ 1040.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4803 | Tapware | \$ 1343.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4804 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4805 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| I | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1317 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 299.19% | Good | Retain | N/A |
| | LNILU4806 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4807 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4808 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | | _ | | | | | | | | |
| | LNILU4809 | Interior Painting | \$ 228.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

Bed 2

LNILU4810

Wardrobe

\$ 2115.00

10

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1328 | Interior Painting | \$ 605.00 | 10 | 01-05-2015 | 0.1 years | 33.29% | Excellent | Retain | N/A |
| LNILU4811 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4812 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4813 | Wardrobe | \$ 2115.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

09-01-2024 8.8 years

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1354 | Interior Painting | \$ 514.00 | 10 | 01-05-2015 | 0.1 years | 16.63% | Excellent | Retain | N/A |
| LNILU4814 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4815 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4816 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

0.00% Excellent

Retain

N/A

| Hal | lway |
|-----|------|
| | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| | LNILU1356 | Interior Painting | \$ 285.00 | 10 | 01-05-2015 | 0.1 years | 35.09% | Excellent | Retain | N/A |
| | LNILU4817 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| chen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1311 | Interior Painting | \$ 434.00 | 10 | 01-05-2015 | 0.1 years | 35.02% | Excellent | Retain | N/A |
| | LNILU4818 | Cooktop | \$ 1394.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4819 | Oven | \$ 1451.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4820 | Rangehood | \$ 617.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4821 | Benchtops | \$ 2414.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4822 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4823 | Kitchen Cabinets | \$ 3932.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4824 | Sink & Fittings | \$ 1634.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4825 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| undry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1330 | Interior Painting | \$ 257.00 | 10 | 01-05-2015 | 0.1 years | 35.02% | Excellent | Retain | N/A |
| | LNILU4826 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4827 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4828 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4829 | Sink & Fittings | \$ 1634.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |
| ing | | - | | | | | | | | - |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1345 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 299.19% | Good | Retain | N/A |
| | LNILU1350 | Interior Painting | \$ 1097.00 | 10 | 01-05-2015 | 0.1 years | 35.00% | Excellent | Retain | N/A |
| | LNILU4830 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4831 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | 2.1.20 .00 . | | | | | - | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1340 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU4833 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4834 | Toilet & Cistern | \$ 1383.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4835 | Exhaust Fan | \$ 262.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1357 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 14.88% | Good | Retain | N/A |
| LNILU1358 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Good | Retain | N/A |
| LNILU1359 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 117.73% | Good | Retain | N/A |
| LNILU1360 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 51.93% | Good | Retain | N/A |
| LNILU1361 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.87% | Good | Retain | N/A |
| LNILU1363 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 29.75% | Good | Retain | N/A |
| LNILU1365 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1366 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1367 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1368 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1369 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 173.81% | Good | Retain | N/A |
| LNILU1370 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Good | Retain | N/A |
| LNILU1371 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1372 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU4177 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.12% | Fair | Retain | N/A |
| LNILU4651 | Fascias | \$ 1395.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4652 | Guttering | \$ 1395.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
|-----------------|--------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|---------------------------------------------|--------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|--------------------------------------------------------------|--|
| | LNILU1373 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 11.37% | Good | Retain | |
| Unit 19 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| | LNILU1374 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | |
| | LNILU1375 | Lighting | \$ 1966.00 | 15 | 01-12-2018 | 8.7 years | 6.36% | Good | Retain | |
| | LNILU1376 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | |
| | LNILU1377 | Smoke Alarms | \$ 268.00 | 20 | 01-12-2018 | 13.7 years | 8.33% | Good | Retain | |
| Unit 20 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| | LNILU1438 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 21.16% | Excellent | Retain | |
| | LNILU1439 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 4.67% | Good | Retain | |
| | LNILU1440 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | |
| | | | | | | | | | | |
| | LNILU1441 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | |
| | LNILU1441 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | |
| Bathroom | LNILU1441 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | |
| Bathroom | Asset Number | Smoke Alarms Asset Name | \$ 268.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -22.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain | |
| Bathroom | | | | | | | | | | |
| Bathroom | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| Bathroom | Asset Number LNILU1399 | Asset Name Exhaust Fan | Acquisition Cost (\$) \$ 262.00 | Effective Life (Y) | Installation Date 01-12-2018 | Remaining Effective Life 3.7 years | Accumulated Repair Cost as % of Acquisition 15.80% | Asset Condition Good | Plan Retain | |
| Bathroom | Asset Number LNILU1399 LNILU1400 | Asset Name Exhaust Fan Interior Painting | Acquisition Cost (\$) \$ 262.00 \$ 228.00 | Effective Life (Y) 10 10 | Installation Date 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% | Asset Condition Good Good | Plan Retain Retain | |
| Bathroom | Asset Number LNILU1399 LNILU1400 LNILU1401 | Asset Name Exhaust Fan Interior Painting Shower Screen | Acquisition Cost (\$) \$ 262.00 \$ 228.00 \$ 1200.00 | Effective Life (Y) 10 10 20 | Installation Date 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% | Asset Condition Good Good Good | Plan Retain Retain Retain | |
| Bathroom | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 | Effective Life (Y) 10 10 20 10 | 01-12-2018 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% | Asset Condition Good Good Good Fair | Plan Retain Retain Retain Repair | |
| Bathroom | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 LNILU1403 | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight Tapware | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 | Effective Life (Y) 10 10 20 10 15 | 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years 8.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% 37.91% | Asset Condition Good Good Good Fair Good | Plan Retain Retain Retain Retain Repair Retain | |
| Bathroom Bed 1 | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 LNILU1403 LNILU1404 | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | Effective Life (Y) 10 10 20 10 15 20 | 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years 8.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% 37.91% 4.81% | Asset Condition Good Good Good Fair Good Good | Plan Retain Retain Retain Repair Retain Retain Retain | |
| | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 LNILU1403 LNILU1404 | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | Effective Life (Y) 10 10 20 10 15 20 | 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years 8.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% 37.91% 4.81% | Asset Condition Good Good Good Fair Good Good | Plan Retain Retain Retain Repair Retain Retain Retain | |
| | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 LNILU1403 LNILU1404 LNILU1405 | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall Tiles - Floor | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 \$ 4058.00 | Effective Life (Y) 10 10 20 10 15 20 20 | 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years 8.7 years 13.7 years 13.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% 37.91% 4.81% 14.43% | Asset Condition Good Good Fair Good Good Fair | Plan Retain Retain Retain Repair Retain Retain Retain Retain | |
| | Asset Number LNILU1399 LNILU1400 LNILU1401 LNILU1402 LNILU1403 LNILU1404 LNILU1405 Asset Number | Asset Name Exhaust Fan Interior Painting Shower Screen Skylight Tapware Tiles - Wall Tiles - Floor Asset Name | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 \$ 4058.00 | Effective Life (Y) 10 10 20 10 15 20 20 20 | Installation Date 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 01-12-2018 Installation Date | Remaining Effective Life 3.7 years 3.7 years 13.7 years 3.7 years 8.7 years 13.7 years 13.7 years 13.7 years 13.7 years | Accumulated Repair Cost as % of Acquisition 15.80% 35.09% 17.50% 5.25% 37.91% 4.81% 14.43% Accumulated Repair Cost as % of Acquisition | Asset Condition Good Good Fair Good Good Fair Asset Condition | Plan Retain Retain Retain Repair Retain Retain Retain Retain | |

| | LNILU4354 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
|---------|------------------------|---------------------|--------------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------------------------------------------------|
| | LNILU4642 | Blind | \$ 342.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1392 | Blind | \$ 342.00 | 10 | 01-12-2018 | 3.7 years | 0.88% | Good | Retain | N/A |
| | LNILU1393 | Carpet | \$ 743.00 | 8 | 01-12-2018 | 1.7 years | 20.78% | Good | Retain | N/A |
| | LNILU1394 | Interior Painting | \$ 605.00 | 10 | 01-12-2018 | 3.7 years | 9.64% | Fair | Repair | Water leak marks on the ceiling; requires investigation |
| | LNILU1395 | Wardrobe | \$ 2115.00 | 10 | 01-12-2018 | 3.7 years | 11.37% | Good | Retain | N/A |
| | LNILU4355 | Ceiling Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4356 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1416 | Blind | \$ 400.00 | 10 | 01-12-2018 | 3.7 years | 2.63% | Good | Retain | N/A |
| | LNILU1417 | Carpet | \$ 640.00 | 8 | 01-12-2018 | 1.7 years | 21.88% | Good | Retain | N/A |
| | LNILU1418 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2018 | 3.7 years | 16.64% | Good | Retain | N/A |
| | LNILU1419 | Interior Painting | \$ 514.00 | 10 | 01-12-2018 | 3.7 years | 35.02% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1420 | Carpet | \$ 354.00 | 8 | 01-12-2018 | 1.7 years | 2.19% | Good | Retain | N/A |
| | LNILU1421 | Interior Painting | \$ 285.00 | 10 | 01-12-2018 | 3.7 years | 35.09% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1379 | Benchtops | \$ 2414.00 | 20 | 01-12-2018 | 13.7 years | 8.75% | Good | Retain | N/A |
| | LNILU1380 | Cooktop | \$ 1394.00 | 12 | 01-12-2018 | 5.7 years | 2.19% | Good | Retain | N/A |
| | LNILU1381 | Interior Painting | \$ 434.00 | 10 | 01-12-2018 | 3.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1382 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-12-2018 | 13.7 years | 17.50% | Good | Retain | N/A |
| | | | £ 1011 00 | 10 | 01-12-2018 | 3.7 years | 39.39% | Good | Retain | N/A |
| | LNILU1383 | Vinyl | \$ 1011.00 | 10 | 01-12-2018 | 7 7 | | | | |
| | LNILU1383 LNILU1384 | Vinyl Oven | \$ 1011.00 \$ 1451.00 | 12 | 01-12-2018 | • | 138.58% | Good | Retain | N/A |

| | LNILU1407 | Toilet & Cistern | \$ 1383.00 | 20 | 01-12-2018 | 13.7 years | 87.49% | Good | Retain | N/A |
|------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU1406 | Skylight | \$ 1040.00 | 10 | 01-12-2018 | 3.7 years | 70.00% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| room | | | | | | | | | | |
| | LNILU4643 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4360 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1415 | Interior Painting | \$ 1097.00 | 10 | 01-12-2018 | 3.7 years | 10.50% | Good | Retain | N/A |
| | LNILU1414 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2018 | 3.7 years | 33.29% | Good | Retain | N/A |
| | LNILU1413 | Carpet | \$ 1371.00 | 8 | 01-12-2018 | 1.7 years | 21.88% | Good | Retain | N/A |
| | LNILU1411 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-12-2018 | 3.7 years | 86.61% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | ' | | | | | | | | |
| | LNILU4359 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4358 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4357 | Dryer | \$ 994.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1398 | Tiles - Floor | \$ 2086.00 | 20 | 01-12-2018 | 13.7 years | 16.62% | Good | Retain | N/A |
| | LNILU1397 | Tiles - Wall | \$ 1246.00 | 20 | 01-12-2018 | 13.7 years | 17.50% | Good | Retain | N/A |
| | LNILU1396 | Interior Painting | \$ 257.00 | 10 | 01-12-2018 | 3.7 years | 35.02% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| y | | | | | | | | , | | ' |
| | LNILU4641 | Blind | \$ 285.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4353 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1386 | Sink & Fittings | \$ 1634.00 | 15 | 01-12-2018 | 8.7 years | 116.69% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1406 | Skylight | \$ 1040.00 | 10 | 01-12-2018 | 3.7 years | 70.00% | Good | Retain | N/A |
| LNILU1407 | Toilet & Cistern | \$ 1383.00 | 20 | 01-12-2018 | 13.7 years | 87.49% | Good | Retain | N/A |
| LNILU1408 | Tiles - Wall | \$ 926.00 | 20 | 01-12-2018 | 13.7 years | 4.81% | Good | Retain | N/A |
| LNILU1409 | Tiles - Floor | \$ 1429.00 | 20 | 01-12-2018 | 13.7 years | 0.44% | Good | Retain | N/A |
| LNILU1410 | Tapware | \$ 251.00 | 15 | 01-12-2018 | 8.7 years | 116.86% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1422 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1423 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |

| LNILU1424 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 93.25% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|--------|------------------------------|
| LNILU1425 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 110.99% | Good | Retain | Shared between unit 18/19 |
| LNILU1426 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 1.31% | Good | Retain | N/A |
| LNILU1428 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 24.50% | Good | Retain | N/A |
| LNILU1430 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1431 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1432 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1433 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 4.37% | Good | Retain | N/A |
| LNILU1434 | Water Tank | \$ 1063.00 | 25 | 07-11-2023 | 23.6 years | 0.00% | Good | Retain | N/A |
| LNILU1435 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU1436 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1437 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4178 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Good | Retain | N/A |
| LNILU4654 | Fascias | \$ 1432.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4655 | Guttering | \$ 1432.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

Unit 20

| Bathroom |
|----------|
| |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------|
| LNILU1469 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNILU1470 | Interior Painting | \$ 228.00 | 10 | 01-09-2016 | 1.4 years | 35.09% | Good | Retain | N/A |
| LNILU1471 | Shower Screen | \$ 1200.00 | 20 | 11-11-2022 | 17.6 years | 0.00% | Excellent | Retain | |
| LNILU1472 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1473 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 110.82% | Good | Retain | N/A |
| LNILU1474 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1475 | Tiles - Floor | \$ 4058.00 | 20 | 11-11-2022 | 17.6 years | 0.00% | Excellent | Retain | Refurbished |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1451 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 15.79% | Good | Retain | N/A |

| | LNILU1452 | Carpet | \$ 891.00 | 8 | 11-02-2024 | 6.9 years | 0.00% | Excellent | Retain | |
|-------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU1453 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 14.89% | Good | Retain | N/A |
| | LNILU1454 | Interior Painting | \$ 726.00 | 10 | 01-09-2016 | 1.4 years | 16.62% | Good | Retain | N/A |
| | LNILU1455 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4361 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| d 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1456 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 33.33% | Good | Retain | N/A |
| | LNILU1457 | Carpet | \$ 743.00 | 8 | 01-09-2016 | -0.6 years | 21.87% | Good | Retain | N/A |
| | LNILU1458 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| | LNILU1459 | Interior Painting | \$ 605.00 | 10 | 01-09-2016 | 1.4 years | 0.88% | Good | Retain | N/A |
| | LNILU1460 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4362 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ning | | ' | | | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1485 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 28.88% | Good | Retain | N/A |
| | LNILU1486 | Carpet | \$ 640.00 | 8 | 01-09-2016 | -0.6 years | 1.64% | Good | Retain | N/A |
| | LNILU1487 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 15.77% | Good | Retain | N/A |
| | LNILU1488 | Interior Painting | \$ 514.00 | 10 | 01-09-2016 | 1.4 years | 2.63% | Good | Retain | N/A |
| | LNILU4369 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| llway | | | | | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1489 | Carpet | \$ 354.00 | 8 | 11-02-2024 | 6.9 years | 0.00% | Excellent | Retain | |
| | LNILU1490 | Interior Painting | \$ 285.00 | 10 | 01-09-2016 | 1.4 years | 28.95% | Good | Retain | N/A |
| chen | | ' | ' | | | | | | ' | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1442 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1443 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 3.06% | Good | Retain | N/A |
| | | 1 | | | 0.4 0= 4000 | 20.7 | 20.170/ | Caral | Datain | N/A |
| | LNILU1444 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 29.17% | Good | Retain | IN/A |

| l | LNILU1446 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
|--------|------------------------|--------------------------------|------------------------------------|--------------------|------------------------------|------------------------------------|-----------------------------------------------------|------------------------|-----------------------|-----------------|
| L | LNILU1447 | Vinyl | \$ 1011.00 | 10 | 01-09-2016 | 1.4 years | 24.07% | Good | Retain | N/A |
| l | LNILU1448 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| L | LNILU1449 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 14.59% | Good | Retain | N/A |
| L | LNILU1450 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| | | | | | | | | | | · |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number LNILU1461 | Asset Name Interior Painting | Acquisition Cost (\$) \$ 257.00 | Effective Life (Y) | Installation Date 01-09-2016 | Remaining Effective Life 1.4 years | Accumulated Repair Cost as % of Acquisition 33.27% | Asset Condition Good | Plan Retain | Comments N/A |
| L | | | | | | | · | | | |
| l l | LNILU1461 | Interior Painting | \$ 257.00 | 10 | 01-09-2016 | 1.4 years | 33.27% | Good | Retain | N/A |
| l l | LNILU1461 LNILU1462 | Interior Painting Tiles - Wall | \$ 257.00 \$ 1246.00 | 10 20 | 01-09-2016 01-07-1982 | 1.4 years -22.7 years | 33.27% 5.69% | Good Good | Retain Retain | N/A N/A |

15-11-2022 9.7 years

15-11-2022 12.7 years

15-11-2022 9.7 years

Living

LNILU4364

LNILU4365

LNILU4366

Dryer

Washing

Machine

Sink & Fittings

\$ 628.00

\$ 1634.00

\$ 1371.00

12

15

12

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1480 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 259.82% | Good | Retain | N/A |
| LNILU1481 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU1482 | Carpet | \$ 1371.00 | 8 | 01-09-2016 | -0.6 years | 10.39% | Good | Retain | N/A |
| LNILU1483 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU1484 | Interior Painting | \$ 1097.00 | 10 | 01-09-2016 | 1.4 years | 9.63% | Good | Retain | N/A |
| LNILU4368 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

N/A

N/A

N/A

Retain

Retain

Retain

0.00% Good

0.00% Good

0.00% Good

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|--------------------------------------------|
| LNILU1464 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU1467 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU1468 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| LNILU1476 | Toilet & Cistern | \$ 1383.00 | 20 | 11-11-2022 | 17.6 years | 0.00% | Excellent | Retain | Toilet now in bathroom - fully refurbished |

|--|

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------|
| LNILU1491 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1492 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 4.08% | Good | Retain | N/A |
| LNILU1493 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 92.41% | Good | Retain | N/A |
| LNILU1494 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 60.68% | Good | Retain | Shared between unit 19/20 |
| LNILU1495 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU1497 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1499 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1500 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| LNILU1501 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1502 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 17.49% | Good | Retain | N/A |
| LNILU1503 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 14.87% | Good | Retain | N/A |
| LNILU1504 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU1505 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1506 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4180 | Awnings | \$ 9718.00 | 10 | 11-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| LNILU4661 | Fascias | \$ 1558.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4662 | Guttering | \$ 1558.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

Unit 21-22

| Common | | | | | | | | | | |
|---------|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1507 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Unit 21 | | | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1508 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |

| | 181111111111111111111111111111111111111 | L'alaria | # 40CC 00 | 4.5 | 04.07.4000 | 27.7 | 22.222/ | F.*. | D.I'. | T NI /A |
|---------|-----------------------------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU1509 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Fair | Retain | N/A |
| | LNILU1510 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 29.74% | Good | Retain | N/A |
| | LNILU1511 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 7.46% | Good | Retain | N/A |
| Jnit 22 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1572 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1573 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 25.21% | Good | Retain | N/A |
| | LNILU1574 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU1575 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 8.33% | Good | Retain | N/A |
| | | | | | | | | | | |
| athroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1533 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 11.41% | Good | Retain | N/A |
| | LNILU1534 | Interior Painting | \$ 228.00 | 10 | 01-08-2017 | 2.4 years | 35.09% | Good | Retain | N/A |
| | LNILU1535 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU1536 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| | LNILU1537 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 110.82% | Good | Retain | N/A |
| | LNILU1538 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| | LNILU1539 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| ed 1 | | | ' | | | | ' | ' | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1521 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1522 | Carpet | \$ 891.00 | 8 | 01-08-2017 | 0.4 years | 21.89% | Good | Retain | N/A |
| | LNILU1523 | Ceiling Fan | \$ 605.00 | 10 | 28-10-2023 | 8.6 years | 0.00% | Good | Retain | N/A |
| | LNILU1524 | Interior Painting | \$ 726.00 | 10 | 01-08-2017 | 2.4 years | 33.24% | Fair | Retain | N/A |
| | LNILU1525 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| Bed 2 | | | <u> </u> | 1 | 1 | | 1 | ! | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1526 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | | - | | - | | · · | - | + | + | + |

20.78% Good

12.26% Good

Retain

Retain

N/A

N/A

01-08-2017 0.4 years

01-08-2017 2.4 years

8

10

LNILU1527

LNILU1528

Carpet

Interior Painting

\$ 743.00

\$ 605.00

Unit 21

| | LNILU1529 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 9.62% | Good | Retain | N/A |
|---------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU4370 | Ceiling Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1550 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| | LNILU1551 | Carpet | \$ 640.00 | 8 | 01-08-2017 | 0.4 years | 20.78% | Good | Retain | N/A |
| | LNILU1552 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 16.64% | Good | Retain | N/A |
| | LNILU1553 | Interior Painting | \$ 514.00 | 10 | 01-08-2017 | 2.4 years | 7.00% | Good | Retain | N/A |
| Hallway | | | | | | | 1 | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1554 | Carpet | \$ 354.00 | 8 | 01-08-2017 | 0.4 years | 18.06% | Good | Retain | N/A |
| | LNILU1555 | Interior Painting | \$ 285.00 | 10 | 01-08-2017 | 2.4 years | 35.09% | Good | Retain | N/A |
| Kitchen | | | | | | | 1 | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1512 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1513 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| | LNILU1514 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 0.73% | Fair | Retain | N/A |
| | LNILU1515 | Interior Painting | \$ 434.00 | 10 | 01-08-2017 | 2.4 years | 10.51% | Good | Retain | N/A |
| | LNILU1516 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| | LNILU1517 | Vinyl | \$ 1011.00 | 10 | 01-08-2017 | 2.4 years | 87.54% | Good | Retain | N/A |
| | LNILU1518 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 120.35% | Good | Retain | N/A |
| | LNILU1519 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 5.11% | Fair | Retain | N/A |
| | LNILU1520 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1530 | Interior Painting | \$ 257.00 | 10 | 01-08-2017 | 2.4 years | 35.02% | Fair | Repair | N/A |
| | LNILU1531 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| | LNILU1532 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| | LNILU4371 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4372 | Dryer | \$ 627.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| L | LNILU4373 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
|----------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|---------|-----------------------------------------------------------|
| L | LNILU4374 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ng | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU1545 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| L | LNILU1546 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 7.00% | Good | Retain | N/A |
| L | LNILU1547 | Carpet | \$ 1371.00 | 8 | 01-08-2017 | 0.4 years | 18.05% | Good | Retain | N/A |
| L | LNILU1548 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| L | LNILU1549 | Interior Painting | \$ 1097.00 | 10 | 01-08-2017 | 2.4 years | 35.00% | Good | Retain | N/A |
| et room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU1540 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| L | LNILU1541 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 83.12% | Good | Retain | Replace toilet seatSeat has be replaced |
| L | LNILU1542 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| L | LNILU1543 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| L | LNILU1544 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 55.51% | Good | Retain | N/A |
| L | LNILU4375 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Exterior | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU1556 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| L | LNILU1557 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Poor | Replace | Bathroom door frame is water damaged and rotting |
| L | LNILU1558 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 115.09% | Good | Retain | N/A |
| L | LNILU1559 | Electrical | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 24.42% | Good | Retain | N/A |

16.62% Fair

57.75% Fair

Retain

Retain

N/A

N/A

01-07-1982 -32.7 years

01-07-1982 -32.7 years

Switchboard

Exterior Painting

Flyscreens

\$ 2149.00

\$ 1920.00

10

10

LNILU1560

LNILU1562

| LNILU1564 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|-----------|--------|-----|
| LNILU1565 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1566 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.77% | Good | Retain | N/A |
| LNILU1567 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1568 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU1569 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU1570 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1571 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4653 | Awnings | \$ 8404.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4663 | Fascias | \$ 1642.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4664 | Guttering | \$ 1642.00 | 20 | 03-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

Unit 22

| _ | | | | | | | |
|---|---|---|----|---|---|---|---|
| D | _ | 4 | Ь. | - | _ | _ | m |
| D | a | ш | п | п | u | u | ш |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1599 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 33.36% | Good | Retain | N/A |
| LNILU1600 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| LNILU1601 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 7.44% | Good | Retain | N/A |
| LNILU1602 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 26.25% | Good | Retain | N/A |
| LNILU1603 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 55.41% | Good | Retain | N/A |
| LNILU1604 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1605 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1585 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU1586 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 16.67% | Good | Retain | N/A |
| LNILU1587 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| LNILU1588 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 109.42% | Good | Retain | N/A |
| LNILU1589 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU1590 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |

| R | 6 | Ы | 2 |
|---|---|---|---|
| u | c | u | _ |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|----------------|--------------------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|----------------------------------------|----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------------------------------------------------|-------------------------------------------------------|-------------------------|
| | LNILU1591 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 33.33% | Good | Retain | N/A |
| | LNILU1592 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 20.78% | Good | Retain | N/A |
| | LNILU1593 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| | LNILU1594 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU1595 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| Dining | | | ' | , | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1616 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| | LNILU1617 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 9.30% | Good | Retain | N/A |
| | LNILU1618 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| | LNILU1619 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| Hallway | | | | | | | 1 | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1620 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU1621 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LINILOTOZI | intendi Familing | \$ 205.00 | 10 | 01 07 1302 | JEN Years | 33.0370 | 0000 | rtetani | |
| (itchen | LIVILO 1021 | interior Fainting | \$ 203.00 | 10 | 01 07 1302 | SEN years | 55.0570 | | ream | |
| itchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| itchen | | | | | | | | | | Comments N/A |
| itchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| itchen | Asset Number LNILU1576 | Asset Name Blind | Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% | Asset Condition Good | Plan Retain | N/A |
| Citchen | Asset Number LNILU1576 LNILU1577 | Asset Name Blind Benchtops | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 | Effective Life (Y) 10 20 | 1nstallation Date 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% | Asset Condition Good Good | Plan Retain Retain | N/A N/A |
| itchen | Asset Number LNILU1576 LNILU1577 LNILU1578 | Asset Name Blind Benchtops Cooktop | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 | Effective Life (Y) 10 20 12 | 1nstallation Date 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 29.17% | Asset Condition Good Good Good | Plan Retain Retain Retain | N/A N/A N/A |
| itchen | Asset Number LNILU1576 LNILU1577 LNILU1578 LNILU1579 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 | Effective Life (Y) 10 20 12 10 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 29.17% 2.63% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | N/A N/A N/A |
| itchen | Asset Number LNILU1576 LNILU1577 LNILU1578 LNILU1579 LNILU1580 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | Effective Life (Y) 10 20 12 10 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years -32.7 years -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 29.17% 2.63% 7.87% | Asset Condition Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| litchen | Asset Number LNILU1576 LNILU1577 LNILU1578 LNILU1579 LNILU1580 LNILU1581 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 | 10 20 12 10 20 12 10 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years -32.7 years -22.7 years -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 29.17% 2.63% 7.87% | Asset Condition Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A |

| Laundry |
|---------|
|---------|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|--------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1596 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1597 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 5.25% | Good | Retain | N/A |
| LNILU1598 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4376 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4377 | Dryer | \$ 627.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4378 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4379 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|-------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1611 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 23.62% | Fair | Retain | N/A |
| LNILU1612 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 16.63% | Good | Retain | N/A |
| LNILU1613 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 1.64% | Good | Retain | N/A |
| LNILU1614 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| LNILU1615 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1606 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 1.75% | Good | Retain | N/A |
| LNILU1607 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU1608 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1609 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1610 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 8.76% | Fair | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|---------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU1622 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1623 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1624 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 130.65% | Good | Retain | N/A |
| LNILU1625 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 51.93% | Good | Retain | Shared between unit 21/22 |

| LNILU1626 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|-----------|--------|-----|
| LNILU1628 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1630 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1631 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1632 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1633 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1634 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 2.62% | Good | Retain | N/A |
| LNILU1635 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| LNILU1636 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1637 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4656 | Awnings | \$ 8388.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4657 | Fascias | \$ 1625.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Excellent | Retain | N/A |
| LNILU4658 | Guttering | \$ 1625.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Excellent | Retain | N/A |

Unit 23-24

| Common | | | | | | | | | | |
|---------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1638 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 16.62% | Good | Retain | N/A |
| Unit 23 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1639 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 3.31% | Good | Retain | N/A |
| | LNILU1640 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 1.75% | Good | Retain | N/A |
| | LNILU1641 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 7.00% | Good | Retain | N/A |
| | LNILU1642 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| Unit 24 | | - | | | | | | 2 | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1703 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 15.19% | Good | Retain | N/A |
| | LNILU1704 | Lighting | \$ 1966.00 | 15 | 01-11-2005 | -4.4 years | 4.67% | Good | Retain | N/A |

LNILU1705

LNILU1706

Sarking

Smoke Alarms

| | | | · · | | | , | | | | · · |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | | | | | | | | | | |
| athroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1664 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| | LNILU1665 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1666 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU1667 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU1668 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 116.65% | Good | Retain | N/A |
| | LNILU1669 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| | LNILU1670 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| ed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1652 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1653 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU1654 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU1655 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU1656 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Fair | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1657 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1658 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU1659 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 164.79% | Good | Retain | N/A |
| | LNILU1660 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4380 | Ceiling Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1681 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 12.25% | Good | Retain | N/A |
| | LNILU1682 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| | LNILU1683 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 3.50% | Good | Retain | N/A |

01-07-1982 -17.7 years

01-11-2005 0.6 years

25

20

5.25% Good

17.54% Good

Retain

Retain

N/A

N/A

\$ 3384.00

\$ 268.00

| | LNILU1684 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
|--------|--------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|----------------------------------------------------------------------------|------------------------------------------------------------|
| allway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1685 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU1686 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| itchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1643 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 7.02% | Good | Retain | N/A |
| | LNILU1644 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| | LNILU1645 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 29.17% | Good | Retain | N/A |
| | LNILU1646 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1647 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 1.75% | Good | Retain | N/A |
| | LNILU1648 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 26.26% | Good | Retain | N/A |
| | LNILU1649 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 3.65% | Good | Retain | N/A |
| | LNILU1650 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 0.36% | Good | Retain | N/A |
| | LIVILO 1030 | Rangenood | \$ 617.00 | 12 | 01-07-1902 | -30.7 years | 0.50% | Good | Retaili | 11/7 |
| | LNILU1651 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 32.09% | Good | Retain | N/A |
| undry | | | | | | , | | | | |
| undry | | | | | | , | | | | |
| undry | LNILU1651 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 32.09% | Good | Retain | N/A |
| ındry | Asset Number | Sink & Fittings Asset Name | \$ 1634.00 Acquisition Cost (\$) | Effective Life (Y) | 01-07-1982 Installation Date | -27.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain Plan | N/A Comments |
| ındry | Asset Number LNILU1661 | Sink & Fittings Asset Name Interior Painting | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 | Effective Life (Y) | 01-07-1982 Installation Date 01-07-1982 | -27.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% | Asset Condition Good | Plan Retain | Comments N/A |
| undry | Asset Number LNILU1661 LNILU1662 | Sink & Fittings Asset Name Interior Painting Tiles - Wall | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 | Effective Life (Y) 10 20 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 | -27.7 years Remaining Effective Life -32.7 years -22.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 17.50% | Asset Condition Good Good | Plan Retain Retain | Comments N/A N/A |
| indry | Asset Number LNILU1661 LNILU1662 LNILU1663 | Sink & Fittings Asset Name Interior Painting Tiles - Wall Tiles - Floor | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 | 15 Effective Life (Y) 10 20 20 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% | Asset Condition Good Good Good | Plan Retain Retain Retain | Comments N/A N/A N/A |
| undry | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 | Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 | 15 Effective Life (Y) 10 20 20 10 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years | 32.09% Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% | Good Asset Condition Good Good Good Good Good | Plan Retain Retain Retain Retain Retain | N/A Comments N/A N/A N/A N/A N/A |
| undry | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 LNILU4382 | Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind Sink & Fittings Washing | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 \$ 1634.00 | 15 Effective Life (Y) 10 20 20 10 15 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years 12.7 years | 32.09% Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% 0.00% | Good Asset Condition Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain Retain | N/A Comments N/A N/A N/A N/A N/A N/A |
| | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 LNILU4382 | Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind Sink & Fittings Washing | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 \$ 1634.00 | 15 Effective Life (Y) 10 20 20 10 15 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years 12.7 years | 32.09% Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% 0.00% | Good Asset Condition Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain Retain | N/A Comments N/A N/A N/A N/A N/A N/A |
| | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 LNILU4382 LNILU4383 | Sink & Fittings Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind Sink & Fittings Washing Machine | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 \$ 1634.00 \$ 1371.00 | 15 Effective Life (Y) 10 20 20 10 15 12 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 15-11-2022 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years 12.7 years 9.7 years | 32.09% Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% 0.00% 0.00% | Good Asset Condition Good Good Good Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain Retain Retain | N/A Comments N/A N/A N/A N/A N/A N/A N/A |
| | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 LNILU4382 LNILU4383 Asset Number | Sink & Fittings Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind Sink & Fittings Washing Machine Asset Name | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 \$ 1634.00 \$ 1371.00 Acquisition Cost (\$) | 15 Effective Life (Y) 10 20 20 10 15 12 Effective Life (Y) | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 15-11-2022 Installation Date | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years 12.7 years 9.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition | Asset Condition Good Good Good Good Good Good Good Asset Condition | Plan Retain Retain Retain Retain Retain Retain Retain Retain | N/A Comments N/A N/A N/A N/A N/A N/A N/A Comments |
| | Asset Number LNILU1661 LNILU1662 LNILU1663 LNILU4381 LNILU4382 LNILU4383 Asset Number LNILU1677 | Sink & Fittings Asset Name Interior Painting Tiles - Wall Tiles - Floor Blind Sink & Fittings Washing Machine Asset Name Blind | \$ 1634.00 Acquisition Cost (\$) \$ 257.00 \$ 1246.00 \$ 2086.00 \$ 400.00 \$ 1634.00 \$ 1371.00 Acquisition Cost (\$) \$ 400.00 | 15 Effective Life (Y) 10 20 20 10 15 12 Effective Life (Y) 10 | 01-07-1982 Installation Date 01-07-1982 01-07-1982 01-07-1982 15-11-2022 15-11-2022 Installation Date 01-07-1982 | -27.7 years Remaining Effective Life -32.7 years -22.7 years -22.7 years 7.7 years 12.7 years 9.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% 17.50% 4.81% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 35.00% | Good Asset Condition Good Good Good Good Good Good Good Go | Plan Retain | N/A Comments N/A N/A N/A N/A N/A N/A N/A N/ |

| | LNILU4384 | Air Conditioner - Split System | \$ 3395.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|----------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|---------|----------------------------------------------------------|
| let room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1671 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU1672 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| | LNILU1673 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 14.43% | Good | Retain | N/A |
| | LNILU1674 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| | LNILU1675 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| Exterior | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1687 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1688 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 2.33% | Good | Retain | N/A |
| | LNILU1689 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 115.80% | Good | Retain | N/A |
| | LNILU1690 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 110.99% | Good | Retain | Shared between un 23/24 |
| | LNILU1691 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 16.62% | Good | Retain | N/A |
| | LNILU1693 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| | LNILU1695 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |
| | LNILU1697 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | Cracked pathway adjacent to park bench outside U23 |
| | LNILU1698 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| | LNILU1699 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 33.25% | Good | Retain | N/A |
| | LNILU1700 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| | LINILO 1700 | VVIIIdovis | Ψ 1 300.00 | 50 | 01 07 1302 | 12.7 years | 0.0176 | Cood | recuiii | 14//1 |

01-07-1982 -22.7 years

01-07-1982 -22.7 years

15-01-2010 -5.2 years

19-06-2023 18.2 years

19-06-2023 18.2 years

\$ 1943.00

\$ 3681.00

\$ 9718.00

\$ 1446.00

\$ 1446.00

20

20

10

20

20

LNILU1701

LNILU1702

LNILU4183

LNILU4659

LNILU4660

Balustrade

Balcony

Flooring

Awnings

Fascias

Guttering

0.66% Good

0.22% Good

3.27% Good

0.00% Excellent

0.00% Excellent

N/A

N/A

N/A

N/A

Still waiting for awning upgrade

Retain

Retain

Retain

Retain

Retain

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | LNILU1729 | Interior Painting | \$ 228.00 | 10 | 01-11-2005 | -9.4 years | 35.09% | Good | Retain | N/A |
| | LNILU1730 | Shower Screen | \$ 1200.00 | 20 | 01-11-2005 | 0.6 years | 0.44% | Good | Retain | N/A |
| | LNILU1731 | Skylight | \$ 1040.00 | 10 | 21-09-2023 | 8.5 years | 0.00% | Good | Retain | N/A |
| | LNILU1732 | Tapware | \$ 1343.00 | 15 | 01-11-2005 | -4.4 years | 110.82% | Good | Retain | N/A |
| | LNILU1733 | Tiles - Wall | \$ 3384.00 | 20 | 01-11-2005 | 0.6 years | 1.31% | Good | Retain | N/A |
| | LNILU1734 | Tiles - Floor | \$ 4058.00 | 20 | 01-11-2005 | 0.6 years | 17.50% | Fair | Retain | N/A |
| ed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1716 | Blind | \$ 342.00 | 10 | 01-11-2005 | -9.4 years | 35.09% | Good | Retain | N/A |
| | LNILU1717 | Carpet | \$ 891.00 | 8 | 01-11-2005 | -11.4 years | 21.89% | Good | Retain | N/A |
| | LNILU1718 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2005 | -9.4 years | 35.04% | Good | Retain | N/A |
| | LNILU1719 | Interior Painting | \$ 726.00 | 10 | 01-11-2005 | -9.4 years | 34.99% | Good | Retain | N/A |
| | LNILU1720 | Wardrobe | \$ 2115.00 | 10 | 01-11-2005 | -9.4 years | 34.99% | Good | Retain | N/A |
| | LNILU4386 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1721 | Blind | \$ 342.00 | 10 | 01-11-2005 | -9.4 years | 35.09% | Good | Retain | N/A |
| | LNILU1722 | Carpet | \$ 743.00 | 8 | 01-11-2005 | -11.4 years | 21.87% | Good | Retain | N/A |
| | LNILU1723 | Interior Painting | \$ 605.00 | 10 | 01-11-2005 | -9.4 years | 35.04% | Fair | Retain | N/A |
| | LNILU1724 | Wardrobe | \$ 2115.00 | 10 | 01-11-2005 | -9.4 years | 34.99% | Good | Retain | N/A |
| | LNILU4387 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ning | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1745 | Blind | \$ 400.00 | 10 | 01-11-2005 | -9.4 years | 2.63% | Good | Retain | N/A |
| | LNILU1746 | Carpet | \$ 640.00 | 8 | 01-11-2005 | -11.4 years | 18.05% | Good | Retain | N/A |
| | LNILU1747 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2005 | -9.4 years | 35.04% | Good | Retain | N/A |
| | LNILU1748 | Interior Painting | \$ 514.00 | 10 | 01-11-2005 | -9.4 years | 35.02% | Good | Retain | N/A |

| Hall | way |
|------|-----|
|------|-----|

Blind

Carpet

\$ 400.00

\$ 1371.00

10

8

01-11-2005 -9.4 years

01-11-2005 -11.4 years

LNILU1741

LNILU1742

| aniway | | | | | | | | | | |
|--------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1749 | Carpet | \$ 354.00 | 8 | 01-11-2005 | -11.4 years | 0.55% | Good | Retain | N/A |
| | LNILU1750 | Interior Painting | \$ 285.00 | 10 | 01-11-2005 | -9.4 years | 28.95% | Good | Retain | N/A |
| tchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1707 | Blind | \$ 285.00 | 10 | 01-11-2005 | -9.4 years | 35.09% | Good | Retain | N/A |
| | LNILU1708 | Benchtops | \$ 2414.00 | 20 | 01-11-2005 | 0.6 years | 8.75% | Good | Retain | N/A |
| | LNILU1709 | Cooktop | \$ 1394.00 | 12 | 01-11-2005 | -7.4 years | 29.17% | Fair | Retain | N/A |
| | LNILU1710 | Interior Painting | \$ 434.00 | 10 | 01-11-2005 | -9.4 years | 7.00% | Good | Retain | N/A |
| | LNILU1711 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-11-2005 | 0.6 years | 1.31% | Good | Retain | N/A |
| | LNILU1712 | Vinyl | \$ 1011.00 | 10 | 01-11-2005 | -9.4 years | 72.22% | Good | Retain | N/A |
| | LNILU1713 | Oven | \$ 1451.00 | 12 | 01-11-2005 | -7.4 years | 145.88% | Good | Retain | N/A |
| | LNILU1714 | Rangehood | \$ 617.00 | 12 | 01-11-2005 | -7.4 years | 12.03% | Fair | Retain | N/A |
| | LNILU1715 | Sink & Fittings | \$ 1634.00 | 15 | 01-11-2005 | -4.4 years | 116.69% | Good | Retain | N/A |
| | LNILU4385 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ındry | | | ' | ' | , | , | | | ' | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1725 | Interior Painting | \$ 257.00 | 10 | 01-11-2005 | -9.4 years | 33.27% | Good | Retain | N/A |
| | LNILU1726 | Tiles - Wall | \$ 1246.00 | 20 | 01-11-2005 | 0.6 years | 16.62% | Good | Retain | N/A |
| | LNILU1727 | Tiles - Floor | \$ 2086.00 | 20 | 01-11-2005 | 0.6 years | 17.50% | Good | Retain | N/A |
| | LNILU4388 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4389 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4390 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ving | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU1740 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-11-2005 | -9.4 years | 94.48% | Good | Retain | N/A |
| | | | | | | | | | | |

2.63% Good

1.64% Good

Retain

Retain

N/A

N/A

| LNILU1743 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2005 | -9.4 years | 0.88% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|------------|--------|------|--------|-----|
| LNILU1744 | Interior Painting | \$ 1097.00 | 10 | 01-11-2005 | -9.4 years | 33.25% | Fair | Retain | N/A |
| LNILU4391 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1735 | Skylight | \$ 1040.00 | 10 | 01-11-2005 | -9.4 years | 70.00% | Good | Retain | N/A |
| LNILU1736 | Toilet & Cistern | \$ 1383.00 | 20 | 01-11-2005 | 0.6 years | 87.49% | Good | Retain | N/A |
| LNILU1737 | Tiles - Wall | \$ 926.00 | 20 | 01-11-2005 | 0.6 years | 16.62% | Good | Retain | N/A |
| LNILU1738 | Tiles - Floor | \$ 1429.00 | 20 | 01-11-2005 | 0.6 years | 17.49% | Fair | Retain | N/A |
| LNILU1739 | Tapware | \$ 251.00 | 15 | 01-11-2005 | -4.4 years | 116.86% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU1751 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1752 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Good | Retain | N/A |
| LNILU1753 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 127.41% | Good | Retain | N/A |
| LNILU1754 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 25.68% | Good | Retain | Shared 23/24 |
| LNILU1755 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 3.50% | Good | Retain | N/A |
| LNILU1757 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU1759 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1760 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| LNILU1761 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.60% | Fair | Repair | Path crack outside U24 |
| LNILU1762 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 53.52% | Fair | Retain | N/A |
| LNILU1763 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 2.62% | Good | Retain | N/A |
| LNILU1764 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 1.17% | Good | Retain | N/A |
| LNILU1765 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1766 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4184 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Fair | Retain | N/A |

| U | nit | 25 | -26 |
|---|-----|----|-----|
| | | | |

Unit 25

LNILU4669

LNILU4672

Fascias

Guttering

| ommon | | | | | | | | | | |
|----------|---------------------------------------------------------------|---------------------------------------------------------------|-------------------------------------------------------------------|----------------------------|------------------------------------------------------|-------------------------------------------------------------------------|---------------------------------------------------|------------------------------|-------------------------------------------|--------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1767 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| nit 25 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1768 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1769 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU1770 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU1771 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| nit 26 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1832 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1833 | Lighting | \$ 1966.00 | 15 | 01-07-2011 | 1.3 years | 6.42% | Good | Retain | N/A |
| | LNILU1834 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 87.41% | Good | Retain | N/A |
| | LNILU1835 | Smoke Alarms | \$ 268.00 | 20 | 01-07-2011 | 6.3 years | 16.66% | Good | Retain | N/A |
| | | | | | | | | | | |
| | | | | | | | | | | |
| nthroom | | | | | | | | | | |
| throom | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| throom | Asset Number | Asset Name Interior Painting | Acquisition Cost (\$) \$ 228.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 2.63% | Asset Condition Good | Plan Retain | Comments N/A |
| throom | | | | | | | · · · · · · · · · · · · · · · · · · · | | | |
| athroom | LNILU1794 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| athroom | LNILU1794 LNILU1795 | Interior Painting Shower Screen | \$ 228.00 \$ 1200.00 | 10 20 | 01-07-1982 01-07-1982 | -32.7 years -22.7 years | 2.63% 17.50% | Good Good | Retain Retain | N/A N/A |
| athroom | LNILU1794 LNILU1795 LNILU1796 | Interior Painting Shower Screen Skylight | \$ 228.00 \$ 1200.00 \$ 1040.00 | 10 20 10 | 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -22.7 years -32.7 years | 2.63% 17.50% 70.00% | Good Good | Retain Retain Retain | N/A N/A N/A |
| athroom | LNILU1794 LNILU1795 LNILU1796 LNILU1797 | Interior Painting Shower Screen Skylight Tapware | \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 | 10 20 10 15 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -22.7 years -32.7 years -27.7 years | 2.63% 17.50% 70.00% 116.65% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A N/A |
| | LNILU1794 LNILU1795 LNILU1796 LNILU1797 LNILU1798 | Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | 10 20 10 15 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -22.7 years -32.7 years -32.7 years -27.7 years -22.7 years | 2.63% 17.50% 70.00% 116.65% 16.62% | Good Good Good Good | Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A |
| Bathroom | LNILU1794 LNILU1795 LNILU1796 LNILU1797 LNILU1798 | Interior Painting Shower Screen Skylight Tapware Tiles - Wall | \$ 228.00 \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | 10 20 10 15 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -22.7 years -32.7 years -32.7 years -27.7 years -22.7 years | 2.63% 17.50% 70.00% 116.65% 16.62% | Good Good Good Good | Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A |

27-07-2023 18.3 years

27-07-2023 18.3 years

N/A

N/A

Retain

Retain

0.00% Excellent

0.00% Excellent

\$ 1558.00

\$ 1558.00

20

20

| | LNILU1782 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
|---------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------|
| | LNILU1783 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU1784 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU1785 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4393 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1786 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 12.28% | Good | Retain | N/A |
| | LNILU1787 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU1788 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 28.91% | Good | Retain | N/A |
| | LNILU1789 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 33.24% | Good | Retain | N/A |
| | LNILU4394 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1810 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU1811 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| | LNILU1812 | Ceiling Fan | \$ 605.00 | 10 | 12-11-2023 | 8.6 years | 0.00% | Excellent | Retain | |
| | LNILU1813 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU4399 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1814 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 10.95% | Good | Retain | N/A |
| | LNILU1815 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Fair | Retain | N/A |
| Kitchen | | - | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1772 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1773 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 3.72% | Good | Retain | Cracked tiles near sink and fittings |
| | LNILU1774 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 8.75% | Good | Retain | N/A |
| | LNILU1775 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU1776 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

| | LNILU1777 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 72.22% | Good | Retain | N/A |
|-------|-------------------------------------|----------------------------------------------|---------------------------------------|--------------------|----------------------------------------|-------------------------------------------|----------------------------------------------------|----------------------|----------------------------|------------------------------------|
| | LNILU1778 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 65.64% | Good | Retain | N/A |
| | LNILU1779 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 14.59% | Good | Retain | N/A |
| | LNILU1780 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 8.75% | Good | Retain | Sink spout very stiff hard to move |
| | LNILU4392 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ındry | | | | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number LNILU1790 | Asset Name Interior Painting | Acquisition Cost (\$) \$ 257.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 35.02% | Asset Condition Poor | Plan Retain | Comments N/A |
| | | | • | | | | · | | | |
| | LNILU1790 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Poor | Retain | N/A |
| | LNILU1790 LNILU1791 | Interior Painting Tiles - Wall | \$ 257.00 \$ 1246.00 | 10 20 | 01-07-1982 01-07-1982 | -32.7 years -22.7 years | 35.02% 17.50% | Poor Good | Retain Retain | N/A N/A |
| | LNILU1790 LNILU1791 LNILU1792 | Interior Painting Tiles - Wall Tiles - Floor | \$ 257.00 \$ 1246.00 \$ 2086.00 | 10 20 20 | 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -22.7 years -22.7 years | 35.02% 17.50% 0.44% | Poor Good Good | Retain Retain Retain | N/A N/A N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1805 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU1806 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU1807 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| LNILU1808 | Ceiling Fan | \$ 605.00 | 10 | 12-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| LNILU1809 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Fair | Retain | N/A |
| LNILU4398 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU1800 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1801 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU1802 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU1803 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU1804 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 55.51% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|---------|---------------------------|
| LNILU1816 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Poor | Replace | Replace rusty clothesline |
| LNILU1817 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 4.08% | Good | Retain | N/A |
| LNILU1818 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 120.41% | Good | Retain | N/A |
| LNILU1819 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 95.68% | Good | Retain | Shared between unit 25/26 |
| LNILU1820 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.12% | Fair | Retain | N/A |
| LNILU1822 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1824 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU1825 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU1826 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1827 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1828 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU1829 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1830 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 2.84% | Good | Retain | N/A |
| LNILU1831 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 247.10% | Good | Retain | N/A |
| LNILU4185 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Fair | Retain | N/A |
| LNILU4665 | Fascias | \$ 1415.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Excellent | Retain | N/A |
| LNILU4666 | Guttering | \$ 1415.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Excellent | Retain | N/A |

Unit 26

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1858 | Exhaust Fan | \$ 236.00 | 10 | 01-07-2011 | -3.7 years | 38.98% | Good | Retain | |
| LNILU1859 | Interior Painting | \$ 206.00 | 10 | 01-07-2011 | -3.7 years | 38.83% | Good | Retain | |
| LNILU1860 | Shower Screen | \$ 1081.00 | 20 | 01-07-2011 | 6.3 years | 9.23% | Good | Retain | |
| LNILU1861 | Skylight | \$ 937.00 | 10 | 01-07-2011 | -3.7 years | 19.42% | Good | Retain | |
| LNILU1862 | Tapware | \$ 1210.00 | 15 | 01-07-2011 | 1.3 years | 129.48% | Good | Retain | |

| | LNILU1863 | Tiles - Wall | \$ 3048.00 | 20 | 01-07-2011 | 6.3 years | 19.42% | Fair | Retain | 200 x 300, mould, needs cleaning |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------------|
| | LNILU1864 | Tiles - Floor | \$ 3656.00 | 20 | 01-07-2011 | 6.3 years | 19.42% | Fair | Retain | 200 x 200, mould, needs cleaning |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1845 | Blind | \$ 309.00 | 10 | 01-07-2011 | -3.7 years | 38.83% | Good | Retain | 1. Vertical |
| | LNILU1846 | Carpet | \$ 803.00 | 8 | 01-07-2011 | -5.7 years | 24.28% | Good | Retain | |
| | LNILU1847 | Ceiling Fan | \$ 545.00 | 10 | 01-07-2011 | -3.7 years | 38.90% | Good | Retain | |
| | LNILU1848 | Interior Painting | \$ 654.00 | 10 | 01-07-2011 | -3.7 years | 38.84% | Good | Retain | |
| | LNILU1849 | Wardrobe | \$ 1905.00 | 10 | 01-07-2011 | -3.7 years | 38.85% | Good | Retain | |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1850 | Blind | \$ 309.00 | 10 | 01-07-2011 | -3.7 years | 38.83% | Good | Retain | 1. Vertical |
| | LNILU1851 | Carpet | \$ 669.00 | 8 | 01-07-2011 | -5.7 years | 0.61% | Good | Retain | |
| | LNILU1852 | Ceiling Fan | \$ 545.00 | 10 | 01-07-2011 | -3.7 years | 38.90% | Good | Retain | With light |
| | LNILU1853 | Interior Painting | \$ 545.00 | 10 | 01-07-2011 | -3.7 years | 36.95% | Good | Retain | |
| | LNILU1854 | Wardrobe | \$ 1905.00 | 10 | 01-07-2011 | -3.7 years | 38.85% | Good | Retain | |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1875 | Blind | \$ 360.00 | 10 | 01-07-2011 | -3.7 years | 38.89% | Good | Retain | 1. Vertical |
| | LNILU1876 | Carpet | \$ 576.00 | 8 | 01-07-2011 | -5.7 years | 23.09% | Good | Retain | |
| | LNILU1877 | Ceiling Fan | \$ 545.00 | 10 | 01-07-2011 | -3.7 years | 36.95% | Good | Retain | |
| | LNILU1878 | Interior Painting | \$ 463.00 | 10 | 01-07-2011 | -3.7 years | 9.72% | Good | Retain | |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1879 | Carpet | \$ 319.00 | 8 | 01-07-2011 | -5.7 years | 24.29% | Good | Retain | |
| | LNILU1880 | Interior Painting | \$ 257.00 | 10 | 01-07-2011 | -3.7 years | 7.78% | Good | Retain | |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1836 | Blind | \$ 257.00 | 10 | 01-07-2011 | -3.7 years | 38.91% | Good | Retain | 1. Vertical |
| | LNILU1837 | Benchtops | \$ 2175.00 | 20 | 01-07-2011 | 6.3 years | 9.71% | Good | Retain | Laminate |

| LNILU1838 | Cooktop | \$ 1256.00 | 12 | 01-07-2011 | -1.7 years | 2.43% | Good | Retain | Ceramic, 4 plate |
|-----------|---------------------|------------|----|------------|------------|---------|------|--------|---------------------|
| LNILU1839 | Interior Painting | \$ 391.00 | 10 | 01-07-2011 | -3.7 years | 2.92% | Good | Retain | |
| LNILU1840 | Kitchen Cabinets | \$ 3543.00 | 20 | 01-07-2011 | 6.3 years | 19.42% | Good | Retain | |
| LNILU1841 | Vinyl Flooring | \$ 911.00 | 10 | 01-07-2011 | -3.7 years | 97.15% | Good | Retain | |
| LNILU1842 | Oven | \$ 1308.00 | 12 | 01-07-2011 | -1.7 years | 161.82% | Good | Retain | |
| LNILU1843 | Rangehood | \$ 556.00 | 12 | 01-07-2011 | -1.7 years | 1.21% | Good | Retain | |
| LNILU1844 | Sink & Fittings | \$ 1472.00 | 15 | 01-07-2011 | 1.3 years | 3.24% | Good | Retain | 1.5 Bowl with mixer |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------------------------------------------------------|
| LNILU1855 | Interior Painting | \$ 231.00 | 10 | 01-07-2011 | -3.7 years | 10.71% | Good | Retain | |
| LNILU1856 | Tiles - Wall | \$ 1122.00 | 20 | 01-07-2011 | 6.3 years | 1.46% | Good | Retain | |
| LNILU1857 | Tiles - Floor | \$ 1879.00 | 20 | 01-07-2011 | 6.3 years | 9.23% | Good | Retain | 200 x 200 |
| LNILU4400 | Blind | \$ 360.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | 1 Vertical blind; Unknown installation date, assessment date used for installation date |
| LNILU4401 | Sink & Fittings | \$ 1472.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | Unknown installation date, assessment date used for installation date |
| LNILU4402 | Washing Machine | \$ 1236.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | Unknown installation date, assessment date used for installation date |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------|
| LNILU1870 | Air Conditioner - Split System | \$ 3059.00 | 10 | 01-07-2011 | -3.7 years | 332.05% | Good | Retain | Outdoor unit model: ESE18HRB Serial No.: E012319 |
| LNILU1871 | Blind | \$ 360.00 | 10 | 01-07-2011 | -3.7 years | 38.89% | Good | Retain | 2. Vertical |
| LNILU1872 | Carpet | \$ 1236.00 | 8 | 01-07-2011 | -5.7 years | 24.27% | Good | Retain | |

| LNILU1873 | Ceiling Fan | \$ 545.00 | 10 | 01-07-2011 | -3.7 years | 13.61% | Good | Retain | |
|-----------|-------------------|-----------|----|------------|------------|--------|------|--------|---------------|
| LNILU1874 | Interior Painting | \$ 988.00 | 10 | 01-07-2011 | -3.7 years | 10.69% | Fair | Retain | Cracks on the |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-----------|
| LNILU1865 | Skylight | \$ 937.00 | 10 | 01-07-2011 | -3.7 years | 27.19% | Good | Retain | |
| LNILU1866 | Toilet & Cistern | \$ 1246.00 | 20 | 01-07-2011 | 6.3 years | 97.11% | Good | Retain | |
| LNILU1867 | Tiles - Wall | \$ 834.00 | 20 | 01-07-2011 | 6.3 years | 8.26% | Good | Retain | 200 x 300 |
| LNILU1868 | Tiles - Floor | \$ 1287.00 | 20 | 01-07-2011 | 6.3 years | 19.43% | Good | Retain | 200 x 200 |
| LNILU1869 | Tapware | \$ 226.00 | 15 | 01-07-2011 | 1.3 years | 129.79% | Good | Retain | |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------------------------------------------|
| LNILU1881 | Clothesline | \$ 463.00 | 10 | 01-07-1982 | -32.7 years | 38.88% | Good | Retain | |
| LNILU1882 | Doors | \$ 8301.00 | 30 | 01-07-1982 | -12.7 years | 4.85% | Good | Retain | |
| LNILU1883 | Downpipes | \$ 1617.00 | 20 | 01-07-1982 | -22.7 years | 131.97% | Good | Retain | Repair (19/06/2023) |
| LNILU1884 | Electrical Switchboard | \$ 1823.00 | 20 | 01-07-1982 | -22.7 years | 55.20% | Good | Retain | Upgrade (20/07/2023) |
| LNILU1885 | Exterior Painting | \$ 1936.00 | 10 | 01-07-1982 | -32.7 years | 19.42% | Good | Retain | |
| LNILU1887 | Flyscreens | \$ 1730.00 | 10 | 01-07-1982 | -32.7 years | 23.31% | Good | Retain | |
| LNILU1889 | Hot Water System - Solar | \$ 4068.00 | 15 | 01-07-1982 | -27.7 years | 125.61% | Good | Retain | |
| LNILU1890 | Lattice Screening | \$ 1987.00 | 20 | 01-07-1982 | -22.7 years | 19.43% | Good | Retain | Painted |
| LNILU1891 | Path | \$ 1400.00 | 30 | 01-07-1982 | -12.7 years | 6.48% | Good | Retain | Concrete |
| LNILU1892 | Porch | \$ 2976.00 | 30 | 01-07-1982 | -12.7 years | 0.00% | Good | Retain | |
| LNILU1893 | Water Tank | \$ 957.00 | 25 | 01-07-1982 | -17.7 years | 38.87% | Good | Retain | C/bond. Steel |
| LNILU1894 | Windows | \$ 7189.00 | 30 | 01-07-1982 | -12.7 years | 12.95% | Good | Retain | Aluminium Framed |
| LNILU1895 | Balcony Balustrade | \$ 1751.00 | 20 | 01-07-1982 | -22.7 years | 9.71% | Good | Retain | Powder coated alum. |
| LNILU1896 | Balcony Flooring | \$ 3316.00 | 20 | 01-07-1982 | -22.7 years | 4.37% | Good | Retain | Tiled |
| LNILU4186 | Awnings | \$ 8755.00 | 10 | 15-01-2010 | -5.2 years | 5.91% | Fair | Retain | One missing . Installed on all windows |

| U | nit | 27- | 28 |
|---|------|-------|----|
| • | 1111 | ~ / - | 20 |

Unit 27

LNILU4667

LNILU4668

LNILU1927

LNILU1928

LNILU1929

Tapware

Tiles - Wall

Tiles - Floor

Fascias

Guttering

\$ 1361.00

\$ 1361.00

\$ 1343.00

\$ 3384.00

\$ 4058.00

20

20

15

20

20

| Common | | | | | | | | | | |
|----------|------------------------|-------------------------------|---------------------------------|--------------------|------------------------------|-------------------------------------|-----------------------------------------------------|----------------------|-----------------------|----------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1897 | Roof | \$ 24720.00 | 50 | 01-07-1982 | 7.3 years | 36.89% | Good | Retain | Tiled Roof |
| Unit 27 | | | | | | | | | · | |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1898 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1899 | Lighting | \$ 1966.00 | 15 | 01-07-2010 | 0.3 years | 23.33% | Good | Retain | N/A |
| | LNILU1900 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU1901 | Smoke Alarms | \$ 268.00 | 20 | 01-07-2010 | 5.3 years | 1.32% | Good | Retain | N/A |
| Unit 28 | | | | | | | | | | |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1961 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1962 | Lighting | \$ 1966.00 | 15 | 01-10-2003 | -6.5 years | 11.08% | Good | Retain | N/A |
| | LNILU1963 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU1964 | Smoke Alarms | \$ 268.00 | 20 | 01-10-2003 | -1.5 years | 17.54% | Good | Retain | N/A |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Bathroom | | | | | | | | | | |
| Bathroom | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Bathroom | Asset Number LNILU1923 | Asset Name Exhaust Fan | Acquisition Cost (\$) \$ 262.00 | Effective Life (Y) | Installation Date 01-07-2010 | Remaining Effective Life -4.7 years | Accumulated Repair Cost as % of Acquisition 120.31% | Asset Condition Poor | Plan Repair | Comments Exhaust fan filter is broken |
| Bathroom | | | • | | | | | | | Exhaust fan filter is |
| Bathroom | LNILU1923 | Exhaust Fan | \$ 262.00 | 10 | 01-07-2010 | -4.7 years | 120.31% | Poor | Repair | Exhaust fan filter is broken |
| Bathroom | LNILU1923 LNILU1924 | Exhaust Fan Interior Painting | \$ 262.00 \$ 228.00 | 10 | 01-07-2010 01-07-2010 | -4.7 years | 120.31% 33.33% | Poor | Repair Retain | Exhaust fan filter broken N/A |

01-07-2010 0.3 years

01-07-2010 5.3 years

01-07-2010 5.3 years

19-06-2023 18.2 years

19-06-2023 18.2 years

0.00% Excellent

0.00% Excellent

0.00% Good

7.87% Good

17.50% Good

Retain

Retain

Retain

Retain

Retain

N/A

N/A

N/A

Replace asset LNILU1888

| Bed 1 |
|-------|
|-------|

LNILU1903

Benchtops

\$ 2414.00

20

01-07-2010 5.3 years

| JCu i | | | | | | | | | | |
|-------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1911 | Blind | \$ 342.00 | 10 | 01-07-2010 | -4.7 years | 33.33% | Good | Retain | N/A |
| | LNILU1912 | Carpet | \$ 891.00 | 8 | 01-07-2010 | -6.7 years | 6.57% | Good | Retain | N/A |
| | LNILU1913 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 28.91% | Good | Retain | N/A |
| | LNILU1914 | Interior Painting | \$ 726.00 | 10 | 01-07-2010 | -4.7 years | 34.99% | Good | Retain | N/A |
| | LNILU1915 | Wardrobe | \$ 2115.00 | 10 | 01-07-2010 | -4.7 years | 28.87% | Good | Retain | N/A |
| | LNILU4405 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ed 2 | | ' | | ' | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1916 | Blind | \$ 342.00 | 10 | 01-07-2010 | -4.7 years | 35.09% | Good | Retain | N/A |
| | LNILU1917 | Carpet | \$ 743.00 | 8 | 01-07-2010 | -6.7 years | 21.87% | Good | Retain | N/A |
| | LNILU1918 | Interior Painting | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 35.04% | Good | Retain | N/A |
| | LNILU1919 | Wardrobe | \$ 2115.00 | 10 | 01-07-2010 | -4.7 years | 9.62% | Good | Retain | N/A |
| | LNILU4406 | Ceiling Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4407 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ning | | ' | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1940 | Blind | \$ 400.00 | 10 | 01-07-2010 | -4.7 years | 35.00% | Good | Retain | N/A |
| | LNILU1941 | Carpet | \$ 640.00 | 8 | 12-07-2022 | 5.3 years | 0.00% | Good | Retain | |
| | LNILU1942 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 35.04% | Good | Retain | N/A |
| | LNILU1943 | Interior Painting | \$ 514.00 | 10 | 01-07-2010 | -4.7 years | 33.27% | Good | Retain | N/A |
| | LNILU4413 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| llway | | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1944 | Carpet | \$ 354.00 | 8 | 01-07-2010 | -6.7 years | 76.18% | Good | Retain | N/A |
| | LNILU1945 | Interior Painting | \$ 285.00 | 10 | 01-07-2010 | -4.7 years | 0.88% | Good | Retain | N/A |
| tchen | | | ' | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU1902 | Blind | \$ 285.00 | 10 | 01-07-2010 | -4.7 years | 12.28% | Good | Retain | N/A |
| | | - | + | | | | | | + | + |

0.22% Good

Retain

N/A

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (V) | Installation Date | Remaining Effective Life | Accumulated Renair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | | | | 1 | | 1 | 1 | | · |
| NILU4404 | Oven | \$ 958.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| NILU4403 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| LNILU1910 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-2010 | 0.3 years | 40.84% | Good | Retain | N/A |
| LNILU1909 | Rangehood | \$ 617.00 | 12 | 01-07-2010 | -2.7 years | 14.59% | Good | Retain | N/A |
| NILU1907 | Vinyl | \$ 1011.00 | 10 | 01-07-2010 | -4.7 years | 87.54% | Good | Retain | N/A |
| NILU1906 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-2010 | 5.3 years | 8.75% | Good | Retain | N/A |
| LNILU1905 | Interior Painting | \$ 434.00 | 10 | 01-07-2010 | -4.7 years | 7.00% | Good | Retain | N/A |
| NILU1904 | Cooktop | \$ 1394.00 | 12 | 01-07-2010 | -2.7 years | 8.02% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------|
| LNILU1920 | Interior Painting | \$ 257.00 | 10 | 01-07-2010 | -4.7 years | 35.02% | Good | Retain | N/A |
| LNILU1921 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-2010 | 5.3 years | 17.50% | Good | Retain | N/A |
| LNILU1922 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-2010 | 5.3 years | 5.25% | Good | Retain | N/A |
| LNILU4408 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| LNILU4409 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Fair | Retain | Upgrade tapware to 1/4 turn |
| LNILU4410 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Ass | set Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-----|------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNI | ILU1935 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-2010 | -4.7 years | 94.48% | Good | Retain | N/A |
| LNI | ILU1936 | Blind | \$ 400.00 | 10 | 01-07-2010 | -4.7 years | 16.63% | Good | Retain | N/A |
| LNI | ILU1937 | Carpet | \$ 1371.00 | 8 | 01-07-2010 | -6.7 years | 0.55% | Good | Retain | N/A |
| LNI | ILU1938 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 28.91% | Good | Retain | N/A |
| LNI | ILU1939 | Interior Painting | \$ 1097.00 | 10 | 01-07-2010 | -4.7 years | 33.25% | Good | Retain | N/A |
| LNI | ILU4412 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1930 | Skylight | \$ 1040.00 | 10 | 01-07-2010 | -4.7 years | 57.75% | Good | Retain | N/A |
| LNILU1931 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-2010 | 5.3 years | 83.12% | Good | Retain | N/A |

| LNILU1932 | Tiles - Wall | \$ 926.00 | 20 | 01-07-2010 | 5.3 years | 0.44% | Good | Retain | N/A |
|-----------|---------------|------------|----|------------|-----------|---------|------|--------|-----|
| LNILU1933 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-2010 | 5.3 years | 14.43% | Good | Retain | N/A |
| LNILU1934 | Tapware | \$ 251.00 | 15 | 01-07-2010 | 0.3 years | 116.86% | Good | Retain | N/A |
| LNILU4411 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------------------------|
| LNILU1946 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU1947 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.08% | Good | Retain | Maintenance to secure front door weather strip |
| LNILU1948 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 120.41% | Good | Retain | N/A |
| LNILU1949 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 106.61% | Good | Retain | Shared between unit 27/28 |
| LNILU1950 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU1952 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU1954 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 11.08% | Good | Retain | N/A |
| LNILU1955 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU1956 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU1957 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 33.25% | Good | Retain | N/A |
| LNILU1958 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU1959 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU1960 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 2.62% | Good | Retain | N/A |
| LNILU4187 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.29% | Fair | Retain | General usage wear and tear |
| LNILU4670 | Fascias | \$ 1415.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Good | Retain | N/A |
| LNILU4671 | Guttering | \$ 1415.00 | 20 | 19-06-2023 | 18.2 years | 0.00% | Excellent | Retain | N/A |

Unit 28

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU1988 | Exhaust Fan | \$ 262.00 | 10 | 01-10-2003 | -11.5 years | 35.11% | Good | Retain | N/A |
| LNILU1989 | Interior Painting | \$ 228.00 | 10 | 01-10-2003 | -11.5 years | 16.67% | Good | Retain | N/A |

| | LNILU2006 | Blind | \$ 400.00 | 10 | 01-10-2003 | -11.5 years | 28.88% | Good | Retain | N/A |
|----|------------------------|----------------------|--------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|-----------------|------------------|------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| ng | | | | | | | | | | |
| | LNILU4414 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU1983 | Interior Painting | \$ 605.00 | 10 | 01-10-2003 | -11.5 years | 35.04% | Good | Retain | N/A |
| | LNILU1982 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2003 | -11.5 years | 28.91% | Good | Retain | N/A |
| | LNILU1981 | Carpet | \$ 743.00 | 8 | 01-10-2003 | -13.5 years | 18.04% | Good | Retain | N/A |
| | LNILU1980 | Blind | \$ 342.00 | 10 | 01-10-2003 | -11.5 years | 35.09% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| 2 | | | | | | | | | ' | ' |
| | LNILU1979 | Wardrobe | \$ 2115.00 | 10 | 01-10-2003 | -11.5 years | 33.24% | Good | Retain | N/A |
| | LNILU1978 | Interior Painting | \$ 726.00 | 10 | 01-10-2003 | -11.5 years | 34.99% | Good | Retain | N/A |
| | LNILU1977 | Curtains | \$ 914.00 | 6 | 01-10-2003 | -15.5 years | 0.00% | Good | Retain | N/A |
| | LNILU1976 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2003 | -11.5 years | 35.04% | Good | Retain | N/A |
| | LNILU1975 | Carpet | \$ 891.00 | 8 | 01-10-2003 | -13.5 years | 21.89% | Good | Retain | N/A |
| | LNILU1974 | Blind | \$ 342.00 | 10 | 01-10-2003 | -11.5 years | 35.09% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LIVIEO 1994 | 11103 | ψ 4030.00 | 20 | 01 10 2003 | 1.5 years | 0.5170 | Tuil | recuiii | TV/A |
| | LNILU1994 | Tiles - Floor | \$ 4058.00 | 20 | 01-10-2003 | -1.5 years | 8.31% | Fair | Retain | N/A |
| | LNILU1993 | Tapware Tiles - Wall | \$ 1343.00 | 15 20 | 01-10-2003 | -6.5 years -1.5 years | 16.62% | Fair | Retain | N/A |
| | LNILU1991 LNILU1992 | Skylight | \$ 1040.00 \$ 1343.00 | 10 | 01-10-2003 01-10-2003 | -11.5 years | 5.25% 116.65% | Good | Retain Retain | N/A N/A |
| | 1 NUL 1 1 1 0 0 1 | Shower Screen | \$ 1200.00 | 20 | 12-11-2018 | 13.6 years | 0.00% | Good | Retain | New screen |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2006 | Blind | \$ 400.00 | 10 | 01-10-2003 | -11.5 years | 28.88% | Good | Retain | N/A |
| LNILU2007 | Carpet | \$ 640.00 | 8 | 01-10-2003 | -13.5 years | 20.78% | Good | Retain | N/A |
| LNILU2008 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2003 | -11.5 years | 35.04% | Good | Retain | N/A |
| LNILU2009 | Curtains | \$ 914.00 | 6 | 01-10-2003 | -15.5 years | 0.00% | Good | Retain | N/A |
| LNILU2010 | Interior Painting | \$ 514.00 | 10 | 01-10-2003 | -11.5 years | 28.89% | Good | Retain | N/A |

Hallway

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2011 | Carpet | \$ 354.00 | 8 | 01-10-2003 | -13.5 years | 18.06% | Good | Retain | N/A |
| LNILU2012 | Interior Painting | \$ 285.00 | 10 | 01-10-2003 | -11.5 years | 35.09% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1965 | Blind | \$ 285.00 | 10 | 01-10-2003 | -11.5 years | 35.09% | Good | Retain | N/A |
| LNILU1966 | Benchtops | \$ 2414.00 | 20 | 01-10-2003 | -1.5 years | 2.62% | Good | Retain | N/A |
| LNILU1967 | Cooktop | \$ 1394.00 | 12 | 01-10-2003 | -9.5 years | 29.17% | Good | Retain | N/A |
| LNILU1968 | Interior Painting | \$ 434.00 | 10 | 01-10-2003 | -11.5 years | 10.51% | Good | Retain | N/A |
| LNILU1969 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-10-2003 | -1.5 years | 17.50% | Good | Retain | N/A |
| LNILU1970 | Vinyl | \$ 1011.00 | 10 | 01-10-2003 | -11.5 years | 87.54% | Good | Retain | N/A |
| LNILU1971 | Oven | \$ 1451.00 | 12 | 01-10-2003 | -9.5 years | 69.29% | Good | Retain | N/A |
| LNILU1972 | Rangehood | \$ 617.00 | 12 | 01-10-2003 | -9.5 years | 12.03% | Good | Retain | N/A |
| LNILU1973 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2003 | -6.5 years | 110.85% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------|
| LNILU1985 | Interior Painting | \$ 257.00 | 10 | 01-10-2003 | -11.5 years | 35.02% | Good | Retain | N/A |
| LNILU1986 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2003 | -1.5 years | 17.50% | Good | Retain | N/A |
| LNILU1987 | Tiles - Floor | \$ 2086.00 | 20 | 01-10-2003 | -1.5 years | 17.50% | Good | Retain | N/A |
| LNILU4415 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4416 | Dryer | \$ 628.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4417 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | Upgrade to 1/4 turn |
| LNILU4418 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2001 | Blind | \$ 400.00 | 10 | 01-10-2003 | -11.5 years | 35.00% | Good | Retain | N/A |
| LNILU2002 | Carpet | \$ 1371.00 | 8 | 01-10-2003 | -13.5 years | 21.88% | Good | Retain | N/A |
| LNILU2003 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2003 | -11.5 years | 35.04% | Good | Retain | N/A |
| LNILU2004 | Curtains | \$ 914.00 | 6 | 01-10-2003 | -15.5 years | 0.00% | Good | Retain | N/A |
| LNILU2005 | Interior Painting | \$ 1097.00 | 10 | 01-10-2003 | -11.5 years | 33.25% | Good | Retain | N/A |
| LNILU4420 | Air Conditioner - Split System | \$ 3395.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU1995 | Skylight | \$ 1040.00 | 10 | 01-10-2003 | -11.5 years | 70.00% | Good | Retain | N/A |
| LNILU1996 | Toilet & Cistern | \$ 1383.00 | 20 | 01-10-2003 | -1.5 years | 87.49% | Good | Retain | N/A |
| LNILU1997 | Tiles - Wall | \$ 926.00 | 20 | 01-10-2003 | -1.5 years | 4.37% | Good | Retain | N/A |
| LNILU1998 | Tiles - Floor | \$ 1429.00 | 20 | 01-10-2003 | -1.5 years | 16.62% | Good | Retain | N/A |
| LNILU1999 | Tapware | \$ 251.00 | 15 | 01-10-2003 | -6.5 years | 116.86% | Good | Retain | N/A |
| LNILU4419 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------------------------------------|
| LNILU2013 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU2014 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2015 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 40.90% | Fair | Repair | N/A |
| LNILU2016 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 27/28 |
| LNILU2017 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2019 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2021 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 19.24% | Good | Retain | N/A |
| LNILU2022 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2023 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 4.81% | Good | Repair | Path cracks adjacent U28 water tank |
| LNILU2024 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2025 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2026 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2027 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 2.41% | Good | Retain | N/A |
| LNILU2028 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 235.34% | Good | Retain | N/A |
| LNILU4188 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.17% | Fair | Retain | N/A |
| LNILU4673 | Fascias | \$ 2295.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4674 | Guttering | \$ 2295.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme |
|----------|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------|------------------------|--------|----------------------|
| | LNILU2029 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 28.86% | Good | Retain | N/A |
| Unit 29 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comme |
| | LNILU2030 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2031 | Lighting | \$ 1966.00 | 15 | 01-04-2013 | 3.0 years | 8.17% | Good | Retain | N/A |
| | LNILU2032 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 72.21% | Good | Retain | N/A |
| | LNILU2033 | Smoke Alarms | \$ 268.00 | 20 | 01-04-2013 | 8.0 years | 17.54% | Good | Retain | N/A |
| Unit 30 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comm |
| | LNILU2096 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 22.39% | Good | Retain | N/A |
| | LNILU2097 | Lighting | \$ 1966.00 | 15 | 01-12-2020 | 10.7 years | 7.00% | Good | Retain | N/A |
| | LNILU2098 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 29.74% | Good | Retain | N/A |
| | LNILU2099 | Smoke Alarms | \$ 268.00 | 20 | 01-12-2020 | 15.7 years | 17.54% | Good | Retain | N/A |
| | | | <u> </u> | | | , | | | · | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comm |
| | LNILU2057 | Exhaust Fan | \$ 262.00 | 10 | 01-04-2013 | -2.0 years | 28.97% | Good | Retain | N/A |
| | LNILU2058 | Interior Painting | \$ 228.00 | 10 | 01-04-2013 | -2.0 years | 2.63% | Good | Retain | N/A |
| | LNILU2059 | Shower Screen | \$ 1200.00 | 20 | 12-11-2022 | 17.6 years | 0.00% | Excellent | Retain | Bathroo refurbisl |
| | LNILU2060 | Skylight | \$ 1040.00 | 10 | 01-04-2013 | -2.0 years | 5.25% | Good | Retain | N/A |
| | LNILU2061 | Tapware | \$ 1343.00 | 15 | 01-04-2013 | 3.0 years | 8.75% | Good | Retain | N/A |
| | LNILU2062 | Tiles - Wall | \$ 3384.00 | 20 | 01-04-2013 | 8.0 years | 1.75% | Excellent | Retain | N/A |
| | LNILU2063 | Tiles - Floor | \$ 4058.00 | 20 | 12-11-2022 | 17.6 years | 0.00% | Excellent | Retain | |
| | | | | | | | | | | |
| Bed 1 | | | A | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commo |
| Bed 1 | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (1) | mstanation bate | Kemaning Effective Effe | Accumulated Repair cost as 70 of Acquisition | / isset condition | 1 1411 | CO |

| r Painting | \$ 514.00 | 10 | 01-04-2013 | -2.0 years | 10.51% | Good | Retain | N/A |
|---------------------|----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|---------|------------|
| g Fan | \$ 605.00 | 10 | 01-04-2013 | -2.0 years | 10.51% | Good | Retain | N/A |
| i | \$ 640.00 | 8 | 01-04-2013 | -4.0 years | 21.88% | Good | Retain | N/A |
| | \$ 400.00 | 10 | 01-04-2013 | -2.0 years | 35.00% | Good | Retain | N/A |
| Name Acq | quisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| - | | | | | | | | · |
| ns | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| g Fan | \$ 605.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| obe | \$ 2115.00 | 10 | 01-04-2013 | -2.0 years | 11.37% | Good | Retain | N/A |
| r Painting | \$ 605.00 | 10 | 01-04-2013 | -2.0 years | 35.04% | Good | Retain | N/A |
| t | \$ 743.00 | 8 | 01-04-2013 | -4.0 years | 7.66% | Good | Retain | N/A |
| | \$ 342.00 | 10 | 01-04-2013 | -2.0 years | 33.33% | Good | Retain | N/A |
| nditioner System | \$ 3395.00 | 10 | 01-04-2013 | -2.0 years | 299.19% | Good | Retain | N/A |
| Name Acq | equisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | φ 31 1.00 | | 13 11 2022 | 3.7 yeurs | 0.0070 | 2000 | rtetain | 14// |
| ns | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| obe | \$ 2115.00 | 10 | 01-04-2013 | -2.0 years | 0.87% | Good | Retain | N/A |
| r Painting | \$ 726.00 | 10 | 01-04-2013 | -2.0 years | 14.87% | Good | Retain | N/A |
| t g Fan | \$ 605.00 | 10 | 01-04-2013 | -4.0 years | 13.14% | Good | Retain | N/A |
| | \$ 342.00 | 8 | 01-04-2013 | , | 21.89% | Good | Retain | N/A N/A |
| | | \$ 342.00 | · . | · | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2078 | Carpet | \$ 354.00 | 8 | 01-04-2013 | -4.0 years | 21.89% | Good | Retain | N/A |
| LNILU2079 | Interior Painting | \$ 285.00 | 10 | 01-04-2013 | -2.0 years | 16.67% | Good | Retain | N/A |

Kitchen

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2034 | Blind | \$ 285.00 | 10 | 01-04-2013 | -2.0 years | 35.09% | Good | Retain | N/A |
| LNILU2035 | Benchtops | \$ 2414.00 | 20 | 01-04-2013 | 8.0 years | 8.75% | Good | Retain | N/A |
| LNILU2036 | Cooktop | \$ 1394.00 | 12 | 01-04-2013 | 0.0 years | 29.17% | Good | Retain | N/A |

| LNILU2037 | Interior Painting | \$ 434.00 | 10 | 01-04-2013 | -2.0 years | 35.02% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|------------|---------|------|--------|-----|
| LNILU2038 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-04-2013 | 8.0 years | 17.50% | Good | Retain | N/A |
| LNILU2039 | Vinyl | \$ 1011.00 | 10 | 01-04-2013 | -2.0 years | 87.54% | Good | Retain | N/A |
| LNILU2040 | Oven | \$ 1451.00 | 12 | 01-04-2013 | 0.0 years | 145.88% | Good | Retain | N/A |
| LNILU2041 | Rangehood | \$ 617.00 | 12 | 01-04-2013 | 0.0 years | 14.59% | Good | Retain | N/A |
| LNILU2042 | Sink & Fittings | \$ 1634.00 | 15 | 01-04-2013 | 3.0 years | 55.43% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2054 | Interior Painting | \$ 257.00 | 10 | 01-04-2013 | -2.0 years | 35.02% | Good | Retain | N/A |
| LNILU2055 | Tiles - Wall | \$ 1246.00 | 20 | 01-04-2013 | 8.0 years | 17.50% | Good | Retain | N/A |
| LNILU2056 | Tiles - Floor | \$ 2086.00 | 20 | 01-04-2013 | 8.0 years | 17.50% | Good | Retain | N/A |
| LNILU4424 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4425 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4426 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2069 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-04-2013 | -2.0 years | 299.19% | Good | Retain | N/A |
| LNILU2070 | Blind | \$ 400.00 | 10 | 01-04-2013 | -2.0 years | 35.00% | Good | Retain | N/A |
| LNILU2071 | Carpet | \$ 1371.00 | 8 | 01-04-2013 | -4.0 years | 21.88% | Good | Retain | N/A |
| LNILU2072 | Ceiling Fan | \$ 605.00 | 10 | 01-04-2013 | -2.0 years | 35.04% | Good | Retain | N/A |
| LNILU2073 | Interior Painting | \$ 1097.00 | 10 | 01-04-2013 | -2.0 years | 35.00% | Good | Retain | N/A |
| LNILU4428 | Curtains | \$ 914.00 | 6 | 15-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2064 | Skylight | \$ 1040.00 | 10 | 01-04-2013 | -2.0 years | 21.00% | Good | Retain | N/A |
| LNILU2065 | Toilet & Cistern | \$ 1383.00 | 20 | 01-04-2013 | 8.0 years | 87.49% | Good | Retain | N/A |
| LNILU2066 | Tiles - Wall | \$ 926.00 | 20 | 01-04-2013 | 8.0 years | 0.44% | Good | Retain | N/A |
| LNILU2067 | Tiles - Floor | \$ 1429.00 | 20 | 01-04-2013 | 8.0 years | 14.43% | Good | Retain | N/A |
| LNILU2068 | Tapware | \$ 251.00 | 15 | 01-04-2013 | 3.0 years | 40.90% | Good | Retain | N/A |

| LNILU4427 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|-----------|-------------|-----------|----|------------|-----------|-------|------|--------|-----|
|-----------|-------------|-----------|----|------------|-----------|-------|------|--------|-----|

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------------|
| LNILU2080 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 7.00% | Good | Retain | N/A |
| LNILU2081 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2082 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 127.41% | Good | Retain | N/A |
| LNILU2083 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 37.18% | Good | Retain | Shared between units 29/30 |
| LNILU2084 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2086 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2088 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2089 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2090 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU2091 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2092 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2093 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 3.50% | Good | Retain | N/A |
| LNILU2094 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU2095 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.72% | Good | Retain | N/A |
| LNILU4189 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Poor | Repair | Replace awning at kitchen window |
| LNILU4675 | Fascias | \$ 1558.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4676 | Guttering | \$ 1558.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

Unit 30

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2121 | Exhaust Fan | \$ 262.00 | 10 | 01-12-2020 | 5.7 years | 35.11% | Good | Retain | N/A |
| LNILU2122 | Interior Painting | \$ 228.00 | 10 | 01-12-2020 | 5.7 years | 13.16% | Good | Retain | N/A |
| LNILU2123 | Shower Screen | \$ 1200.00 | 20 | 01-12-2020 | 15.7 years | 17.50% | Good | Retain | N/A |
| LNILU2124 | Skylight | \$ 1040.00 | 10 | 01-12-2020 | 5.7 years | 70.00% | Good | Retain | N/A |

| | LNILU2125 | Tapware | \$ 1343.00 | 15 | 01-12-2020 | 10.7 years | 116.65% | Good | Repair | N/A |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU2126 | Tiles - Wall | \$ 3384.00 | 20 | 01-12-2020 | 15.7 years | 17.49% | Good | Retain | N/A |
| | LNILU2127 | Tiles - Floor | \$ 4058.00 | 20 | 01-12-2020 | 15.7 years | 1.31% | Fair | Retain | N/A |
| Bed 1 | | | | , | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2109 | Blind | \$ 342.00 | 10 | 01-12-2020 | 5.7 years | 28.95% | Good | Retain | N/A |
| | LNILU2110 | Carpet | \$ 891.00 | 8 | 01-12-2020 | 3.7 years | 21.89% | Good | Retain | N/A |
| | LNILU2111 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2020 | 5.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2112 | Interior Painting | \$ 726.00 | 10 | 01-12-2020 | 5.7 years | 34.99% | Good | Retain | N/A |
| | LNILU2113 | Wardrobe | \$ 2115.00 | 10 | 01-12-2020 | 5.7 years | 13.12% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2114 | Blind | \$ 342.00 | 10 | 01-12-2020 | 5.7 years | 2.63% | Good | Retain | N/A |
| | LNILU2115 | Carpet | \$ 743.00 | 8 | 01-12-2020 | 3.7 years | 0.55% | Good | Retain | N/A |
| | LNILU2116 | Interior Painting | \$ 605.00 | 10 | 01-12-2020 | 5.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2117 | Wardrobe | \$ 2115.00 | 10 | 01-12-2020 | 5.7 years | 33.24% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2138 | Blind | \$ 400.00 | 10 | 01-12-2020 | 5.7 years | 12.25% | Good | Retain | N/A |
| | LNILU2139 | Carpet | \$ 640.00 | 8 | 01-12-2020 | 3.7 years | 20.78% | Good | Retain | N/A |
| | LNILU2140 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2020 | 5.7 years | 33.29% | Good | Retain | N/A |
| | LNILU2141 | Interior Painting | \$ 514.00 | 10 | 01-12-2020 | 5.7 years | 35.02% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2142 | Carpet | \$ 354.00 | 8 | 01-12-2020 | 3.7 years | 21.89% | Fair | Retain | N/A |
| | LNILU2143 | Interior Painting | \$ 285.00 | 10 | 01-12-2020 | 5.7 years | 13.16% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2100 | Blind | \$ 285.00 | 10 | 01-12-2020 | 5.7 years | 3.51% | Good | Retain | N/A |
| | | | | | | | | | | |
| | LNILU2101 | Benchtops | \$ 2414.00 | 20 | 01-12-2020 | 15.7 years | 8.75% | Good | Retain | N/A |

| LNILU2118 | Interior Painting | Acquisition Cost (\$) \$ 257.00 | 10 | 01-12-2020 | 5.7 years | 35.02% | Good | Retain | N/A |
|--------------|---------------------|------------------------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU2108 | Sink & Fittings | \$ 1634.00 | 15 | 01-12-2020 | 10.7 years | 116.69% | Good | Retain | N/A |
| LNILU2107 | Rangehood | \$ 617.00 | 12 | 01-12-2020 | 7.7 years | 5.47% | Good | Retain | N/A |
| LNILU2106 | Oven | \$ 1451.00 | 12 | 01-12-2020 | 7.7 years | 145.88% | Good | Retain | N/A |
| LNILU2105 | Vinyl | \$ 1011.00 | 10 | 01-12-2020 | 5.7 years | 87.54% | Good | Retain | N/A |
| LNILU2104 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-12-2020 | 15.7 years | 17.50% | Good | Retain | N/A |
| LNILU2103 | Interior Painting | \$ 434.00 | 10 | 01-12-2020 | 5.7 years | 16.64% | Good | Retain | N/A |

0.00% Good

0.00% Good

0.00% Good

Retain

Retain

Retain

N/A

N/A

N/A

Blind

Washing

Machine

Sink & Fittings

LNILU4429

LNILU4430

LNILU4431

\$ 400.00

\$ 1634.00

\$ 1371.00

10

15

12

15-11-2022 7.7 years

15-11-2022 12.7 years

15-11-2022 9.7 years

Laundry

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|-------------------------------------|
| LNILU2133 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-12-2020 | 5.7 years | 314.93% | Good | Retain | N/A |
| LNILU2134 | Blind | \$ 400.00 | 10 | 01-12-2020 | 5.7 years | 33.25% | Good | Retain | Securely fit blind adjustment cords |
| LNILU2135 | Carpet | \$ 1371.00 | 8 | 01-12-2020 | 3.7 years | 6.56% | Good | Retain | N/A |
| LNILU2136 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2020 | 5.7 years | 33.29% | Good | Retain | N/A |
| LNILU2137 | Interior Painting | \$ 1097.00 | 10 | 01-12-2020 | 5.7 years | 35.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2128 | Skylight | \$ 1040.00 | 10 | 01-12-2020 | 5.7 years | 26.25% | Good | Retain | N/A |
| LNILU2129 | Toilet & Cistern | \$ 1383.00 | 20 | 01-12-2020 | 15.7 years | 87.49% | Good | Retain | N/A |
| LNILU2130 | Tiles - Wall | \$ 926.00 | 20 | 01-12-2020 | 15.7 years | 14.43% | Good | Retain | N/A |
| LNILU2131 | Tiles - Floor | \$ 1429.00 | 20 | 01-12-2020 | 15.7 years | 16.62% | Good | Retain | N/A |
| LNILU2132 | Tapware | \$ 251.00 | 15 | 01-12-2020 | 10.7 years | 116.86% | Good | Retain | N/A |

| LNILU4432 Exhaust Fan \$ 262.00 10 | 15-11-2022 7.7 years 0.0 | Good | Retain N/A |
|------------------------------------|--------------------------|------|------------|
|------------------------------------|--------------------------|------|------------|

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------------|
| LNILU2144 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU2145 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2146 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 68.03% | Good | Retain | N/A |
| LNILU2147 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 83.12% | Good | Retain | Shared between unit 29/30 |
| LNILU2148 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.12% | Good | Retain | N/A |
| LNILU2149 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 26.58% | Good | Retain | N/A |
| LNILU2150 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Poor | Repair | Properly secure dining room screen |
| LNILU2151 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU2152 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 8.16% | Good | Retain | N/A |
| LNILU2153 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU2154 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.19% | Good | Retain | N/A |
| LNILU2155 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2156 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 28.87% | Good | Retain | N/A |
| LNILU2157 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2158 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU2159 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.06% | Good | Retain | N/A |
| LNILU4677 | Awnings | \$ 3637.00 | 10 | 26-06-2023 | 8.3 years | 0.00% | Good | Retain | N/A |

Unit 31-32

| Commor | ì |
|--------|---|
|--------|---|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2160 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |

| Unit | : 31 |
|------|------|
|------|------|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2161 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU2162 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| LNILU2163 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 66.48% | Good | Retain | N/A |
| LNILU2164 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| | | | | | | | | | |

Unit 32

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------------|
| LNILU2228 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU2229 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 25.36% | Good | Retain | Light switch not working properly |
| LNILU2230 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 39.61% | Good | Retain | N/A |
| LNILU2231 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

Unit 31

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2188 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 13.17% | Good | Retain | N/A |
| LNILU2189 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 28.95% | Good | Retain | N/A |
| LNILU2190 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2191 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2192 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 52.49% | Good | Retain | N/A |
| LNILU2193 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2194 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2175 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| LNILU2176 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU2178 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU2179 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU4434 | Blind | \$ 342.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Red | 2 |
|-----|---|
| | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------|-----------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------|------------------------------------|----------------------------------------------------------------|---------------------------------|
| | LNILU2181 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU2183 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2184 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4435 | Blind | \$ 342.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2207 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2208 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 12.26% | Good | Retain | N/A |
| | LNILU2210 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU4441 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2211 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 18.06% | Good | Retain | N/A |
| | LNILU2212 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 28.95% | Good | Retain | N/A |
| Kitchen | | | ' | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | 15111110466 | | | | | | | | | |
| | LNILU2166 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| | LNILU2166 LNILU2167 | Benchtops Cooktop | \$ 2414.00 \$ 1394.00 | 20 | 01-07-1982 01-07-1982 | -22.7 years -30.7 years | 7.22% 12.40% | Good Good | Retain Retain | N/A N/A |
| | | · | · · | | | • | | | | |
| | LNILU2167 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 12.40% | Good | Retain | N/A |
| | LNILU2167 LNILU2168 | Cooktop Interior Painting Kitchen | \$ 1394.00 \$ 434.00 | 12 10 | 01-07-1982 01-07-1982 | -30.7 years -32.7 years | 12.40% 2.63% | Good Good | Retain Retain | N/A N/A |
| | LNILU2167 LNILU2168 LNILU2169 | Cooktop Interior Painting Kitchen Cabinets | \$ 1394.00 \$ 434.00 \$ 3932.00 | 12 10 20 | 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years | 12.40% 2.63% 8.75% | Good Good | Retain Retain Retain | N/A N/A N/A |
| | LNILU2167 LNILU2168 LNILU2169 LNILU2170 | Cooktop Interior Painting Kitchen Cabinets Vinyl | \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 | 12 10 20 | 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years -32.7 years | 12.40% 2.63% 8.75% 30.64% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A |
| | LNILU2167 LNILU2168 LNILU2169 LNILU2170 LNILU2171 | Cooktop Interior Painting Kitchen Cabinets Vinyl Oven | \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 \$ 1451.00 | 12 10 20 10 12 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years -32.7 years -30.7 years | 12.40% 2.63% 8.75% 30.64% 36.47% | Good Good Good Good | Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| | LNILU2167 LNILU2168 LNILU2169 LNILU2170 LNILU2171 LNILU2172 | Cooktop Interior Painting Kitchen Cabinets Vinyl Oven Rangehood | \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 \$ 1451.00 \$ 617.00 | 12 10 20 10 12 12 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years -32.7 years -30.7 years -30.7 years | 12.40% 2.63% 8.75% 30.64% 36.47% 14.59% | Good Good Good Good Good Good | Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A N/A |
| Laundry | LNILU2167 LNILU2168 LNILU2169 LNILU2170 LNILU2171 LNILU2172 LNILU2173 | Cooktop Interior Painting Kitchen Cabinets Vinyl Oven Rangehood Sink & Fittings | \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 \$ 1451.00 \$ 617.00 \$ 1634.00 | 12 10 20 10 12 12 12 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years -32.7 years -30.7 years -30.7 years -30.7 years | 12.40% 2.63% 8.75% 30.64% 36.47% 14.59% 110.85% | Good Good Good Good Good Good Good | Retain Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A N/A N/A |
| Laundry | LNILU2167 LNILU2168 LNILU2169 LNILU2170 LNILU2171 LNILU2172 LNILU2173 | Cooktop Interior Painting Kitchen Cabinets Vinyl Oven Rangehood Sink & Fittings | \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 \$ 1451.00 \$ 617.00 \$ 1634.00 | 12 10 20 10 12 12 12 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | -30.7 years -32.7 years -22.7 years -32.7 years -30.7 years -30.7 years -30.7 years | 12.40% 2.63% 8.75% 30.64% 36.47% 14.59% 110.85% | Good Good Good Good Good Good Good | Retain Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A N/A N/A |

| LNILU2186 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
|-----------|--------------------|------------|----|------------|-------------|--------|------|--------|----------------------------|
| LNILU2187 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4436 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4437 | Dryer | \$ 685.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4438 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | Mixer upgraded to 1/4 turn |
| LNILU4439 | Washing Machine | \$ 1371.00 | 12 | 15-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2200 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU2202 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| LNILU2203 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU2205 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU4644 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|------------------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2195 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU2196 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 21.87% | Good | Retain | N/A |
| LNILU2197 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU2198 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2199 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| LNILU4440 | Exhaust Fan | \$ 262.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU2213 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU2214 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2215 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 140.94% | Good | Retain | N/A |
| LNILU2216 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 24.06% | Good | Retain | Shared between unit 31/32 |
| LNILU2217 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 1.31% | Good | Retain | N/A |

| LNILU2219 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU2221 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 1.75% | Good | Retain | N/A |
| LNILU2222 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.63% | Good | Retain | N/A |
| LNILU2223 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | N/A |
| LNILU2224 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2225 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2226 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU2227 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4678 | Awnings | \$ 2104.00 | 10 | 22-08-2023 | 8.4 years | 0.00% | Good | Retain | N/A |
| LNILU4679 | Fascias | \$ 1836.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4680 | Guttering | \$ 1836.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 32

| Bathroom |
|-----------------|
|-----------------|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2256 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNILU2257 | Interior Painting | \$ 228.00 | 10 | 01-04-2012 | -3.0 years | 11.40% | Good | Retain | N/A |
| LNILU2258 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 14.44% | Fair | Retain | N/A |
| LNILU2259 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2260 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 116.65% | Good | Retain | N/A |
| LNILU2261 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU2262 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 5.25% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2241 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU2242 | Carpet | \$ 891.00 | 8 | 01-04-2012 | -5.0 years | 7.11% | Good | Retain | N/A |
| LNILU2243 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| LNILU2244 | Curtains | \$ 914.00 | 6 | 01-07-1982 | -36.7 years | 0.00% | Good | Retain | N/A |
| LNILU2245 | Interior Painting | \$ 726.00 | 10 | 01-04-2012 | -3.0 years | 28.86% | Good | Retain | N/A |
| LNILU2246 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |

| Bed 2 | | | • | | • | | | , | | |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2247 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU2248 | Carpet | \$ 743.00 | 8 | 01-04-2012 | -5.0 years | 21.87% | Good | Retain | N/A |
| | LNILU2249 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2250 | Curtains | \$ 914.00 | 6 | 01-07-1982 | -36.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2251 | Interior Painting | \$ 605.00 | 10 | 01-04-2012 | -3.0 years | 35.04% | Good | Retain | N/A |
| | LNILU2252 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 16.62% | Good | Retain | N/A |
| ning | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2273 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| | LNILU2274 | Carpet | \$ 640.00 | 8 | 01-04-2012 | -5.0 years | 7.66% | Good | Retain | N/A |
| | LNILU2275 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 28.91% | Good | Retain | N/A |
| | LNILU2276 | Curtains | \$ 914.00 | 6 | 01-07-1982 | -36.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2277 | Interior Painting | \$ 514.00 | 10 | 01-04-2012 | -3.0 years | 11.38% | Good | Retain | N/A |
| llway | | | | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2278 | Carpet | \$ 354.00 | 8 | 01-04-2012 | -5.0 years | 21.89% | Good | Retain | N/A |
| | LNILU2279 | Interior Painting | \$ 285.00 | 10 | 01-04-2012 | -3.0 years | 35.09% | Good | Retain | N/A |
| chen | | ' | | | | , | | ' | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2232 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | Refit blind in mounting |
| | LNILU2233 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 0.22% | Good | Retain | N/A |
| | LNILU2234 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 8.75% | Good | Retain | N/A |
| | LNILU2235 | Interior Painting | \$ 434.00 | 10 | 01-04-2012 | -3.0 years | 35.02% | Good | Retain | N/A |
| | LNILU2236 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |

72.22% Good

145.88% Good

14.59% Good

96.27% Good

N/A

N/A

N/A

N/A

Retain

Retain

Retain

Retain

01-04-2012 -3.0 years

01-07-1982 -30.7 years

01-07-1982 -30.7 years

01-07-1982 -27.7 years

10

12

12

15

\$ 1011.00

\$ 1451.00

\$ 617.00

\$ 1634.00

LNILU2237

LNILU2238

LNILU2239

LNILU2240

Vinyl

Oven

Rangehood

Sink & Fittings

| Laundry |
|---------|
|---------|

| unary | A4 NII | Assat Nassas | Λ - · · · · · · · · · · · · · · · · · · | Effection Life (A) | In stallation Data | Daniel - Effective Life | A | A 4 C 1'4' | DI | |
|-------|--------------|-------------------|-----------------------------------------|--------------------|--------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2253 | Interior Painting | \$ 257.00 | 10 | 01-04-2012 | -3.0 years | 35.02% | Good | Retain | N/A |
| | LNILU2254 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| | LNILU2255 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU4442 | Blind | \$ 400.00 | 10 | 15-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4443 | Sink & Fittings | \$ 1634.00 | 15 | 15-11-2022 | 12.7 years | 0.00% | Good | Retain | Mixer upgraded t |
| | | | | | | | | | | 1/4 turn |
| ving | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2268 | Air Conditioner | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| | | - Split System | | | | | | | | |

01-07-1982 -32.7 years

01-04-2012 -5.0 years

01-07-1982 -32.7 years

01-04-2012 -3.0 years

15-11-2022 3.7 years

Toilet room

LNILU2269

LNILU2270

LNILU2271

LNILU2272

LNILU4445

Blind

Carpet

Ceiling Fan

Curtains

Interior Painting

\$ 400.00

\$ 1371.00

\$ 605.00

\$ 1097.00

\$ 914.00

10

8

10

10

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2263 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU2264 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU2265 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2266 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2267 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |

28.88% Good

18.05% Good

28.91% Good

18.38% Good

0.00% Good

Retain

Retain

Retain

Retain

Retain

N/A

N/A

N/A

N/A

N/A

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU2280 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU2281 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2282 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 108.15% | Good | Retain | N/A |
| LNILU2283 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 30.62% | Good | Retain | Shared between unit 31/32 |

| LNILU2284 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.44% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|-----------|--------|-------------------------------------------------|
| LNILU2286 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2288 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 1.75% | Good | Retain | N/A |
| LNILU2289 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Fair | Repair | Path cracks front and side U32 |
| LNILU2290 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 48.11% | Good | Retain | N/A |
| LNILU2291 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 7.00% | Poor | Repair | Empty and flush water tank and check seal |
| LNILU2292 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2293 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 21.58% | Good | Retain | N/A |
| LNILU2294 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| LNILU4681 | Awnings | \$ 5192.00 | 10 | 22-08-2023 | 8.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4682 | Fascias | \$ 1748.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4683 | Guttering | \$ 1748.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 33-34

| Common | | | | | | | | | | |
|---------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2295 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Unit 33 | | | | | | | | | | |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2296 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 17.24% | Good | Retain | N/A |
| | LNILU2297 | Lighting | \$ 1966.00 | 15 | 01-09-2006 | -3.6 years | 23.33% | Good | Retain | N/A |
| | LNILU2298 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU2299 | Smoke Alarms | \$ 268.00 | 20 | 01-09-2006 | 1.4 years | 6.14% | Good | Retain | N/A |
| Unit 34 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2359 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 23.20% | Excellent | Retain | N/A |
| | LNILU2360 | Lighting | \$ 1966.00 | 15 | 01-10-2005 | -4.5 years | 1.75% | Fair | Retain | N/A |

|--|

LNILU2361

LNILU2362

Sarking

Smoke Alarms

\$ 3384.00

\$ 268.00

25

20

| Bathroom | | | | | | | | | | |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2322 | Exhaust Fan | \$ 262.00 | 10 | 01-09-2006 | -8.6 years | 2.63% | Good | Retain | N/A |
| | LNILU2323 | Interior Painting | \$ 228.00 | 10 | 01-09-2006 | -8.6 years | 35.09% | Good | Retain | N/A |
| | LNILU2324 | Shower Screen | \$ 1200.00 | 20 | 01-09-2006 | 1.4 years | 17.50% | Good | Retain | N/A |
| | LNILU2325 | Skylight | \$ 1040.00 | 10 | 01-09-2006 | -8.6 years | 70.00% | Good | Retain | N/A |
| | LNILU2326 | Tapware | \$ 1343.00 | 15 | 01-09-2006 | -3.6 years | 23.33% | Good | Retain | N/A |
| | LNILU2327 | Tiles - Wall | \$ 3384.00 | 20 | 01-09-2006 | 1.4 years | 3.50% | Good | Retain | N/A |
| | LNILU2328 | Tiles - Floor | \$ 4058.00 | 20 | 01-09-2006 | 1.4 years | 14.43% | Good | Retain | Requires cleaning and regrouting |
| Bed 1 | | | , | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2310 | Carpet | \$ 891.00 | 8 | 01-09-2006 | -10.6 years | 21.89% | Good | Retain | N/A |
| | LNILU2311 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2006 | -8.6 years | 35.04% | Good | Retain | N/A |
| | LNILU2312 | Curtains | \$ 1829.00 | 6 | 01-09-2006 | -12.6 years | 29.16% | Good | Retain | N/A |
| | LNILU2313 | Interior Painting | \$ 726.00 | 10 | 01-09-2006 | -8.6 years | 12.25% | Good | Retain | N/A |
| | LNILU2314 | Wardrobe | \$ 2115.00 | 10 | 01-09-2006 | -8.6 years | 34.99% | Good | Retain | N/A |
| | LNILU4836 | Blind | \$ 342.00 | 10 | 01-09-2006 | -8.6 years | 0.00% | Excellent | Retain | N/A |
| Bed 2 | | | | ı | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2315 | Carpet | \$ 743.00 | 8 | 01-09-2006 | -10.6 years | 20.78% | Good | Retain | N/A |
| | LNILU2316 | Curtains | \$ 1829.00 | 6 | 01-09-2006 | -12.6 years | 13.85% | Good | Retain | N/A |
| | LNILU2317 | Interior Painting | \$ 605.00 | 10 | 01-09-2006 | -8.6 years | 35.04% | Good | Retain | N/A |
| | LNILU2318 | Wardrobe | \$ 2115.00 | 10 | 01-09-2006 | -8.6 years | 34.99% | Good | Retain | N/A |
| | LNILU4447 | Ceiling Fan | \$ 605.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4837 | Blind | \$ 342.00 | 10 | 01-09-2006 | -8.6 years | 0.00% | Excellent | Retain | N/A |

01-07-1982 -17.7 years

01-10-2005 0.5 years

69.98% Good

17.54% Good

N/A

N/A

Retain

Retain

| ning | | | | | | | | | | |
|-------|----------------------------------|-------------------------------|---------------------------------------------------------------|----------------------------|-------------------------------------------------------|-----------------------------------------------------------|------------------------------------------------------------|-----------------------------|--------------------|------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2339 | Carpet | \$ 640.00 | 8 | 01-09-2006 | -10.6 years | 10.39% | Good | Retain | N/A |
| | LNILU2340 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2006 | -8.6 years | 35.04% | Good | Retain | N/A |
| | LNILU2341 | Interior Painting | \$ 514.00 | 10 | 01-09-2006 | -8.6 years | 35.02% | Good | Retain | N/A |
| | LNILU4452 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4838 | Blind | \$ 342.00 | 10 | 01-09-2006 | -8.6 years | 0.00% | Excellent | Retain | N/A |
| llway | | | | | | | | | | <u> </u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2342 | Carnot | ¢ 254.00 | 8 | 01 00 2000 | 10.0 | 24 000/ | 6 1 | Б | 31/4 |
| | 11E0E0 1E | Carpet | \$ 354.00 | 0 | 01-09-2006 | -10.6 years | 21.89% | Good | Retain | N/A |
| | LNILU2343 | Interior Painting | \$ 285.00 | 10 | 01-09-2006 | -8.6 years | 35.09% | Good | Retain | N/A N/A |
| chen | | · | | - | | | | | | |
| chen | | · | | - | | | | | | |
| chen | LNILU2343 | Interior Painting | \$ 285.00 | 10 | 01-09-2006 | -8.6 years | 35.09% | Good | Retain | N/A |
| chen | LNILU2343 Asset Number | Interior Painting Asset Name | \$ 285.00 Acquisition Cost (\$) | 10 Effective Life (Y) | 01-09-2006 Installation Date | -8.6 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain | N/A Comments |
| chen | Asset Number LNILU2300 | Asset Name Blind | \$ 285.00 Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | 01-09-2006 Installation Date 01-09-2006 | -8.6 years Remaining Effective Life -8.6 years | Accumulated Repair Cost as % of Acquisition 35.09% | Good Asset Condition Good | Plan Retain | Comments N/A |
| chen | Asset Number LNILU2300 LNILU2301 | Asset Name Blind Benchtops | \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 | Effective Life (Y) 10 20 | 01-09-2006 Installation Date 01-09-2006 01-09-2006 | -8.6 years Remaining Effective Life -8.6 years 1.4 years | Accumulated Repair Cost as % of Acquisition 35.09% 8.75% | Asset Condition Good Good | Plan Retain Retain | Comments N/A N/A |

01-09-2006 1.4 years

01-09-2006 -8.6 years

01-09-2006 -6.6 years

01-09-2006 -6.6 years

01-09-2006 -3.6 years

16-11-2022 5.7 years

20

10

12

12

15

8

LNILU2309 Sink & Fittings
LNILU4446 Dishwasher

Laundry

LNILU2305

LNILU2306

LNILU2307

LNILU2308

Kitchen

Cabinets Vinyl

Rangehood

Oven

\$ 3932.00

\$ 1011.00

\$ 1451.00

\$ 617.00

\$ 1634.00

\$ 2685.00

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2319 | Interior Painting | \$ 257.00 | 10 | 01-09-2006 | -8.6 years | 35.02% | Good | Retain | N/A |
| LNILU2320 | Tiles - Wall | \$ 1246.00 | 20 | 01-09-2006 | 1.4 years | 17.50% | Good | Retain | N/A |
| LNILU2321 | Tiles - Floor | \$ 2086.00 | 20 | 01-09-2006 | 1.4 years | 17.50% | Good | Retain | N/A |
| LNILU4448 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

17.50% Good

87.54% Good

145.88% Good

14.59% Good

116.69% Good

0.00% Good

Retain

Retain

Retain

Retain

Retain

Retain

N/A

N/A

N/A

N/A

N/A

N/A

| LNILU44 | 449 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
|------------|--------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------------------|
| LNILU44 | 450 | Washing Machine | \$ 1004.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| Asset N | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU23 | 334 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-09-2006 | -8.6 years | 314.93% | Good | Retain | N/A |
| LNILU23 | 335 | Carpet | \$ 1371.00 | 8 | 01-09-2006 | -10.6 years | 4.38% | Good | Retain | N/A |
| LNILU23 | 336 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2006 | -8.6 years | 35.04% | Good | Retain | N/A |
| LNILU23 | 337 | Curtains | \$ 1829.00 | 6 | 01-09-2006 | -12.6 years | 27.70% | Good | Retain | N/A |
| LNILU23 | 338 | Interior Painting | \$ 1097.00 | 10 | 01-09-2006 | -8.6 years | 35.00% | Good | Retain | N/A |
| et room | | | | | | | | | | |
| Asset N | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU23 | 329 | Skylight | \$ 1040.00 | 10 | 01-09-2006 | -8.6 years | 70.00% | Good | Retain | N/A |
| LNILU23 | 330 | Toilet & Cistern | \$ 1383.00 | 20 | 01-09-2006 | 1.4 years | 87.49% | Good | Retain | N/A |
| LNILU23 | 331 | Tiles - Wall | \$ 926.00 | 20 | 01-09-2006 | 1.4 years | 3.50% | Good | Retain | N/A |
| LNILU23 | 332 | Tiles - Floor | \$ 1429.00 | 20 | 01-09-2006 | 1.4 years | 17.49% | Good | Retain | Requires cleaning and regrouting |
| LNILU23 | :333 | Tapware | \$ 251.00 | 15 | 01-09-2006 | -3.6 years | 116.86% | Good | Retain | N/A |
| LNILU44 | 451 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| t Exterior | | | | | | | | | | |
| Asset N | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU23 | 344 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU23 | 345 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 3.50% | Good | Retain | N/A |
| LNILU23 | 346 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 71.33% | Good | Retain | N/A |
| LNILU23 | 347 | Electrical | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between |

Retain

Repair

Retain

Retain

16.62% Good

66.50% Good

23.32% Good

2.63% Good

33/34

N/A

N/A

N/A

N/A

01-07-1982 -32.7 years

01-07-1982 -32.7 years

01-07-1982 -27.7 years

01-07-1982 -12.7 years

LNILU2348

LNILU2350

LNILU2352

LNILU2353

Exterior

Painting

Flyscreens

Hot Water

Path

System - Solar

Switchboard

\$ 2149.00

\$ 1920.00

\$ 4516.00

\$ 1554.00

10

10

15

30

| LNILU2354 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|--------|-----------|--------|-------------------|
| LNILU2355 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2356 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2357 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU2358 | Balcony Flooring | \$ 3681.00 | 20 | 12-11-2018 | 13.6 years | 0.00% | Good | Retain | New balcony tiles |
| LNILU4684 | Awnings | \$ 4832.00 | 10 | 22-08-2023 | 8.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4685 | Fascias | \$ 488.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4686 | Guttering | \$ 488.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

Unit 34

| Ba | +h | | _ | m |
|----|-----|----|---|---|
| Da | ıuı | ľU | u | ш |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2385 | Interior Painting | \$ 228.00 | 10 | 01-10-2005 | -9.5 years | 10.53% | Good | Retain | N/A |
| LNILU2386 | Shower Screen | \$ 1200.00 | 20 | 01-10-2005 | 0.5 years | 1.31% | Good | Retain | N/A |
| LNILU2387 | Skylight | \$ 1040.00 | 10 | 01-10-2005 | -9.5 years | 70.00% | Good | Retain | N/A |
| LNILU2388 | Tapware | \$ 1343.00 | 15 | 01-10-2005 | -4.5 years | 116.65% | Good | Retain | N/A |
| LNILU2389 | Tiles - Wall | \$ 3384.00 | 20 | 01-10-2005 | 0.5 years | 5.69% | Good | Retain | N/A |
| LNILU2390 | Tiles - Floor | \$ 4058.00 | 20 | 01-10-2005 | 0.5 years | 1.31% | Fair | Repair | Regrout |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------------------|
| LNILU2372 | Blind | \$ 342.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| LNILU2373 | Carpet | \$ 891.00 | 8 | 01-10-2005 | -11.5 years | 7.66% | Good | Retain | N/A |
| LNILU2374 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2005 | -9.5 years | 35.04% | Good | Retain | N/A |
| LNILU2375 | Interior Painting | \$ 726.00 | 10 | 01-10-2005 | -9.5 years | 34.99% | Good | Retain | N/A |
| LNILU2376 | Wardrobe | \$ 2115.00 | 10 | 01-10-2005 | -9.5 years | 10.50% | Good | Retain | Minor scratches visible; re- paintDoors have been painted |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2377 | Blind | \$ 342.00 | 10 | 01-10-2005 | -9.5 years | 35.09% | Good | Retain | N/A |
| LNILU2378 | Carpet | \$ 743.00 | 8 | 01-10-2005 | -11.5 years | 21.87% | Good | Retain | N/A |

| | LNILU2379 | Interior Painting | \$ 605.00 | 10 | 01-10-2005 | -9.5 years | 7.01% | Good | Retain | N/A |
|---------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------|
| Dining | | _ | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2401 | Blind | \$ 400.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| | LNILU2402 | Carpet | \$ 640.00 | 8 | 01-10-2005 | -11.5 years | 21.88% | Good | Retain | N/A |
| | LNILU2403 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2005 | -9.5 years | 35.04% | Good | Retain | N/A |
| | LNILU2404 | Interior Painting | \$ 514.00 | 10 | 01-10-2005 | -9.5 years | 2.63% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2405 | Carpet | \$ 354.00 | 8 | 01-10-2005 | -11.5 years | 20.80% | Good | Retain | N/A |
| | LNILU2406 | Interior Painting | \$ 285.00 | 10 | 01-10-2005 | -9.5 years | 15.79% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2363 | Blind | \$ 285.00 | 10 | 01-10-2005 | -9.5 years | 28.95% | Good | Retain | N/A |
| | LNILU2364 | Benchtops | \$ 2414.00 | 20 | 01-10-2005 | 0.5 years | 0.66% | Fair | Retain | N/A |
| | LNILU2365 | Cooktop | \$ 1394.00 | 12 | 01-10-2005 | -7.5 years | 9.48% | Good | Retain | N/A |
| | LNILU2366 | Interior Painting | \$ 434.00 | 10 | 01-10-2005 | -9.5 years | 35.02% | Good | Retain | N/A |
| | LNILU2367 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-10-2005 | 0.5 years | 14.44% | Good | Retain | N/A |
| | LNILU2368 | Vinyl | \$ 1011.00 | 10 | 01-10-2005 | -9.5 years | 87.54% | Good | Retain | N/A |
| | LNILU2369 | Oven | \$ 1451.00 | 12 | 01-10-2005 | -7.5 years | 29.18% | Good | Retain | N/A |
| | LNILU2370 | Rangehood | \$ 617.00 | 12 | 01-10-2005 | -7.5 years | 14.59% | Good | Retain | N/A |
| | LNILU2371 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2005 | -4.5 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2381 | Interior Painting | \$ 257.00 | 10 | 01-10-2005 | -9.5 years | 28.89% | Good | Retain | N/A |
| | LNILU2382 | Tiles - Wall | \$ 1246.00 | 20 | 01-10-2005 | 0.5 years | 14.43% | Good | Retain | N/A |
| | LNILU2383 | Tiles - Floor | \$ 2086.00 | 20 | 01-10-2005 | 0.5 years | 17.50% | Fair | Retain | N/A |
| | LNILU4453 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4454 | Dryer | \$ 931.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4455 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgraded to 1/4 turn |

| | LNILU4456 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
|---------------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------------------------------------------------------------------------------|
| Living | | , | ' | | | | | ' | ' | ' |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2396 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-10-2005 | -9.5 years | 94.48% | Fair | Retain | N/A |
| | LNILU2397 | Blind | \$ 400.00 | 10 | 01-10-2005 | -9.5 years | 33.25% | Good | Retain | N/A |
| | LNILU2398 | Carpet | \$ 1371.00 | 8 | 01-10-2005 | -11.5 years | 21.88% | Good | Retain | N/A |
| | LNILU2399 | Ceiling Fan | \$ 605.00 | 10 | 01-10-2005 | -9.5 years | 35.04% | Good | Retain | N/A |
| | LNILU2400 | Interior Painting | \$ 1097.00 | 10 | 01-10-2005 | -9.5 years | 35.00% | Good | Retain | N/A |
| Toilet room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2391 | Skylight | \$ 1040.00 | 10 | 01-10-2005 | -9.5 years | 57.75% | Good | Retain | N/A |
| | LNILU2392 | Toilet & Cistern | \$ 1383.00 | 20 | 01-10-2005 | 0.5 years | 86.37% | Good | Retain | N/A |
| | LNILU2393 | Tiles - Wall | \$ 926.00 | 20 | 01-10-2005 | 0.5 years | 17.49% | Good | Retain | N/A |
| | LNILU2394 | Tiles - Floor | \$ 1429.00 | 20 | 01-10-2005 | 0.5 years | 3.50% | Fair | Retain | N/A |
| | LNILU2395 | Tapware | \$ 251.00 | 15 | 01-10-2005 | -4.5 years | 96.41% | Good | Retain | Recommend 1/4 turn tapware |
| Jnit Exterior | | | ' | | | | | ' | | ' |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2407 | Clothesline | \$ 514.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | New clothesline |
| | LNILU2408 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Poor | Retain | Bathroom door har to operate - new rollers - B1 and B2 doors also require attention |
| | LNILU2409 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 26.45% | Good | Retain | N/A |
| | LNILU2410 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 72.18% | Good | Retain | Shared between units 33/34 |
| | LNILU2411 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| | LNILU2413 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU2415 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |

| LNILU2416 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|--------|-----------|--------|-----|
| LNILU2417 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 26.24% | Good | Retain | N/A |
| LNILU2418 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2419 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2420 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 4.16% | Good | Retain | N/A |
| LNILU2421 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU4687 | Awnings | \$ 3408.00 | 10 | 22-08-2023 | 8.4 years | 0.00% | Excellent | Retain | N/A |
| LNILU4688 | Fascias | \$ 488.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4689 | Guttering | \$ 488.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

Unit 35-36

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comi |
|---------|--------------|--------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|------|
| | LNILU2422 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 2.62% | Good | Retain | N/A |
| Unit 35 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comi |
| | LNILU2423 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 15.19% | Good | Retain | N/A |
| | LNILU2424 | Lighting | \$ 1966.00 | 15 | 01-02-2011 | 0.9 years | 23.33% | Good | Retain | N/A |
| | LNILU2425 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU2426 | Smoke Alarms | \$ 268.00 | 20 | 01-02-2011 | 5.9 years | 7.89% | Good | Retain | N/A |
| Unit 36 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comr |
| | LNILU2487 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2488 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU2489 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU2490 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 1.32% | Good | Retain | N/A |
| | | | - | - | - | - | | - | - | - |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2448 | Exhaust Fan | \$ 262.00 | 10 | 01-02-2011 | -4.1 years | 33.36% | Good | Retain | N/A |

| | LNILU2449 | Interior Painting | \$ 228.00 | 10 | 01-02-2011 | -4.1 years | 13.16% | Good | Retain | N/A |
|-----|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-----------|
| | LNILU2450 | Shower Screen | \$ 1200.00 | 20 | 12-11-2018 | 13.6 years | 0.00% | Good | Retain | |
| | LNILU2451 | Skylight | \$ 1040.00 | 10 | 01-02-2011 | -4.1 years | 70.00% | Good | Retain | N/A |
| | LNILU2452 | Tapware | \$ 1343.00 | 15 | 01-02-2011 | 0.9 years | 96.24% | Good | Retain | N/A |
| | LNILU2453 | Tiles - Wall | \$ 3384.00 | 20 | 01-02-2011 | 5.9 years | 14.43% | Good | Retain | N/A |
| | LNILU2454 | Tiles - Floor | \$ 4058.00 | 20 | 12-11-2018 | 13.6 years | 0.00% | Good | Retain | New tiles |
| 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2436 | Blind | \$ 342.00 | 10 | 01-02-2011 | -4.1 years | 28.95% | Good | Retain | N/A |
| | LNILU2437 | Carpet | \$ 891.00 | 8 | 01-02-2011 | -6.1 years | 21.89% | Good | Retain | N/A |
| | LNILU2438 | Ceiling Fan | \$ 605.00 | 10 | 01-02-2011 | -4.1 years | 35.04% | Good | Retain | N/A |
| | LNILU2439 | Interior Painting | \$ 726.00 | 10 | 01-02-2011 | -4.1 years | 34.99% | Good | Retain | N/A |
| | LNILU2440 | Wardrobe | \$ 2115.00 | 10 | 01-02-2011 | -4.1 years | 34.99% | Good | Retain | N/A |
| 12 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2441 | Blind | \$ 342.00 | 10 | 01-02-2011 | -4.1 years | 15.79% | Good | Retain | N/A |
| | LNILU2442 | Carpet | \$ 743.00 | 8 | 01-02-2011 | -6.1 years | 21.87% | Good | Retain | N/A |
| | LNILU2443 | Interior Painting | \$ 605.00 | 10 | 01-02-2011 | -4.1 years | 12.26% | Good | Retain | N/A |
| | LNILU2444 | Wardrobe | \$ 2115.00 | 10 | 01-02-2011 | -4.1 years | 12.25% | Good | Retain | N/A |
| | LNILU4457 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2465 | Blind | \$ 400.00 | 10 | 01-02-2011 | -4.1 years | 35.00% | Good | Retain | N/A |
| | | | | | | | | | | |

Remaining Effective Life

18.05% Good

33.29% Good

28.89% Good

6.57% Good

28.95% Good

Asset Condition

Accumulated Repair Cost as % of Acquisition

N/A

N/A

N/A

N/A

N/A

Comments

Retain

Retain

Retain

Plan

Retain

Retain

01-02-2011 -6.1 years

01-02-2011 -4.1 years

01-02-2011 -4.1 years

01-02-2011 -4.1 years

-6.1 years

Installation Date

01-02-2011

8

10

10

8

10

Effective Life (Y)

\$ 640.00

\$ 605.00

\$ 514.00

\$ 354.00

\$ 285.00

Acquisition Cost (\$)

LNILU2466

LNILU2467

LNILU2468

LNILU2469

LNILU2470

Asset Number

Hallway

Carpet

Ceiling Fan

Interior Painting

Asset Name

Interior Painting

Carpet

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2427 | Blind | \$ 285.00 | 10 | 01-02-2011 | -4.1 years | 28.95% | Good | Retain | N/A |
| LNILU2428 | Benchtops | \$ 2414.00 | 20 | 01-02-2011 | 5.9 years | 0.66% | Good | Retain | N/A |
| LNILU2429 | Cooktop | \$ 1394.00 | 12 | 01-02-2011 | -2.1 years | 24.07% | Good | Retain | N/A |
| LNILU2430 | Interior Painting | \$ 434.00 | 10 | 01-02-2011 | -4.1 years | 35.02% | Good | Retain | N/A |
| LNILU2431 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-02-2011 | 5.9 years | 17.50% | Good | Retain | N/A |
| LNILU2432 | Vinyl | \$ 1011.00 | 10 | 01-02-2011 | -4.1 years | 87.54% | Good | Retain | N/A |
| LNILU2433 | Oven | \$ 1451.00 | 12 | 01-02-2011 | -2.1 years | 145.88% | Good | Retain | N/A |
| LNILU2434 | Rangehood | \$ 617.00 | 12 | 01-02-2011 | -2.1 years | 1.09% | Good | Retain | N/A |
| LNILU2435 | Sink & Fittings | \$ 1634.00 | 15 | 01-02-2011 | 0.9 years | 96.27% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------|
| LNILU2445 | Interior Painting | \$ 257.00 | 10 | 01-02-2011 | -4.1 years | 2.63% | Good | Retain | N/A |
| LNILU2446 | Tiles - Wall | \$ 1246.00 | 20 | 01-02-2011 | 5.9 years | 17.50% | Good | Retain | N/A |
| LNILU2447 | Tiles - Floor | \$ 2086.00 | 20 | 01-02-2011 | 5.9 years | 17.50% | Good | Retain | N/A |
| LNILU4458 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4459 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | Mixer upgraded to 1/4 turn |
| LNILU4460 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|------------------------|
| LNILU2460 | Air Conditioner - Split System | \$ 3395.00 | 10 | 12-11-2021 | 6.6 years | 0.00% | Good | Retain | New Living Room A/C |
| LNILU2461 | Blind | \$ 400.00 | 10 | 01-02-2011 | -4.1 years | 0.00% | Good | Retain | N/A |
| LNILU2462 | Carpet | \$ 1371.00 | 8 | 01-02-2011 | -6.1 years | 21.88% | Good | Retain | N/A |
| LNILU2463 | Ceiling Fan | \$ 605.00 | 10 | 01-02-2011 | -4.1 years | 35.04% | Good | Retain | N/A |
| LNILU2464 | Interior Painting | \$ 1097.00 | 10 | 01-02-2011 | -4.1 years | 2.63% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|------------------|
| LNILU2455 | Skylight | \$ 1040.00 | 10 | 01-02-2011 | -4.1 years | 66.50% | Good | Retain | N/A |
| LNILU2456 | Toilet & Cistern | \$ 1383.00 | 20 | 01-02-2011 | 5.9 years | 72.18% | Good | Retain | Requires new lid |
| LNILU2457 | Tiles - Wall | \$ 926.00 | 20 | 01-02-2011 | 5.9 years | 17.49% | Good | Retain | N/A |
| LNILU2458 | Tiles - Floor | \$ 1429.00 | 20 | 01-02-2011 | 5.9 years | 17.49% | Good | Retain | N/A |
| LNILU2459 | Tapware | \$ 251.00 | 15 | 01-02-2011 | 0.9 years | 37.98% | Good | Retain | N/A |
| LNILU4461 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Fair | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|-------------------------------|
| LNILU2471 | Clothesline | \$ 514.00 | 10 | 12-11-2021 | 6.6 years | 0.00% | Good | Retain | New clothesline |
| LNILU2472 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 5.25% | Good | Retain | N/A |
| LNILU2473 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 128.22% | Good | Retain | N/A |
| LNILU2474 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 35 and 36 |
| LNILU2475 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 1.31% | Good | Retain | N/A |
| LNILU2477 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 14.00% | Good | Retain | N/A |
| LNILU2479 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2480 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2481 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.17% | Good | Retain | N/A |
| LNILU2482 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 4.37% | Good | Retain | N/A |
| LNILU2483 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 3.50% | Good | Retain | N/A |
| LNILU2484 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2485 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU2486 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4196 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Poor | Repair | Balcony Awning to be replaced |
| LNILU4690 | Fascias | \$ 1559.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4691 | Guttering | \$ 1559.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

| Bathroom | | | | | | | | | | |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2513 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 28.97% | Good | Retain | N/A |
| | LNILU2514 | Interior Painting | \$ 228.00 | 10 | 01-04-2012 | -3.0 years | 2.63% | Good | Retain | N/A |
| | LNILU2515 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Repair | Mould in screen door |
| | LNILU2516 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU2517 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 8.75% | Good | Retain | N/A |
| | LNILU2518 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| | LNILU2519 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2500 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 33.33% | Good | Retain | N/A |
| | LNILU2501 | Carpet | \$ 891.00 | 8 | 01-04-2012 | -5.0 years | 21.89% | Good | Retain | N/A |
| | LNILU2502 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU2503 | Interior Painting | \$ 726.00 | 10 | 01-04-2012 | -3.0 years | 34.99% | Good | Retain | N/A |
| | LNILU2504 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| Bed 2 | | ' | | | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2505 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 8.77% | Good | Retain | N/A |
| | LNILU2506 | Carpet | \$ 743.00 | 8 | 01-04-2012 | -5.0 years | 7.66% | Good | Retain | N/A |
| | LNILU2507 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 7.01% | Good | Retain | N/A |
| | LNILU2508 | Interior Painting | \$ 605.00 | 10 | 01-04-2012 | -3.0 years | 35.04% | Good | Retain | N/A |
| | LNILU2509 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| Dining | | ' | | | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2530 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU2531 | Carpet | \$ 640.00 | 8 | 01-04-2012 | -5.0 years | 21.88% | Good | Retain | N/A |
| | LNILU2532 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 28.91% | Good | Retain | N/A |
| | LNILU2533 | Interior Painting | \$ 514.00 | 10 | 01-04-2012 | -3.0 years | 33.27% | Good | Retain | N/A |

| A 4 I | Maria India | A 4 N | A : -: 1: C1 (A) | Eff4: 1:6- (A) | In atallatian Data | Danielius Effective Life | A | A + C '+' | DI | <u></u> |
|---------|-------------|---------------------|-----------------------|--------------------|--------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------|
| | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU2 | 2534 | Carpet | \$ 354.00 | 8 | 01-04-2012 | -5.0 years | 21.89% | Good | Retain | N/A |
| LNILU2 | 2535 | Interior Painting | \$ 285.00 | 10 | 01-04-2012 | -3.0 years | 35.09% | Good | Retain | N/A |
| en | | | | | | | | | | |
| Asset | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU24 | 2491 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU2 | 2492 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU2 | 2493 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 8.75% | Good | Retain | N/A |
| LNILU2 | 2494 | Interior Painting | \$ 434.00 | 10 | 01-04-2012 | -3.0 years | 59.27% | Good | Retain | N/A |
| LNILU2 | 2495 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2 | 2496 | Vinyl | \$ 1011.00 | 10 | 01-04-2012 | -3.0 years | 87.54% | Good | Retain | N/A |
| LNILU2 | 2497 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| LNILU2 | 2498 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 1.09% | Good | Retain | N/A |
| LNILU2 | 2499 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| dry | | | ' | | | | | | ' | ' |
| Asset | Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| LNILU2 | 2510 | Interior Painting | \$ 257.00 | 10 | 01-04-2012 | -3.0 years | 11.38% | Good | Retain | N/A |
| LNILU2 | 2511 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU2 | 2512 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Repair | Requires clea and regroutir |
| LNILU4 | 1462 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4 | 1463 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgrad |

Living

Washing Machine

LNILU4464

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2525 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU2526 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU2527 | Carpet | \$ 1371.00 | 8 | 01-04-2012 | -5.0 years | 21.88% | Good | Retain | N/A |

16-11-2022 9.7 years

12

\$ 1371.00

1/4 turn

N/A

Retain

0.00% Good

| LNILU2528 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 15.77% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU2529 | Interior Painting | \$ 1097.00 | 10 | 01-04-2012 | -3.0 years | 86.49% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2520 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 26.25% | Good | Retain | N/A |
| LNILU2521 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU2522 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2523 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU2524 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 8.76% | Good | Retain | N/A |
| LNILU4465 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|------------------------------|
| LNILU2536 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 13.13% | Fair | Retain | Retension clothesline cables |
| LNILU2537 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Fair | Repair | N/A |
| LNILU2538 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 121.27% | Good | Retain | N/A |
| LNILU2539 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 30.62% | Good | Retain | Shared between unit 35/36 |
| LNILU2540 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2542 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| LNILU2544 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 1.75% | Good | Retain | N/A |
| LNILU2545 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 14.44% | Good | Retain | N/A |
| LNILU2546 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU2547 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2548 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Repair | N/A |
| LNILU2549 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2550 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU2551 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4197 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Good | Retain | N/A |

| LNILU4692 | Fascias | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |
|-----------|-----------|------------|----|------------|------------|-------|-----------|--------|-----|
| LNILU4693 | Guttering | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

| Common | | | | | | | | | | |
|---------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2552 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 28.86% | Good | Retain | N/A |
| Init 37 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2553 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2554 | Lighting | \$ 1966.00 | 15 | 01-12-2005 | -4.3 years | 1.75% | Fair | Retain | N/A |
| | LNILU2555 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU2556 | Smoke Alarms | \$ 268.00 | 20 | 01-12-2005 | 0.7 years | 16.66% | Good | Retain | N/A |
| nit 38 | | | | | | | | | | - |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU4855 | Insulation | \$ 3224.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4856 | Lighting | \$ 1966.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4857 | Sarking | \$ 3384.00 | 25 | 09-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4858 | Smoke Alarms | \$ 268.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |

Unit 37

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------------------|
| LNILU2579 | Exhaust Fan | \$ 262.00 | 10 | 01-12-2005 | -9.3 years | 35.11% | Good | Retain | N/A |
| LNILU2580 | Interior Painting | \$ 228.00 | 10 | 01-12-2005 | -9.3 years | 35.09% | Good | Retain | N/A |
| LNILU2581 | Shower Screen | \$ 1200.00 | 20 | 01-12-2005 | 0.7 years | 1.31% | Good | Retain | Noisy door - apply silicon spray |
| LNILU2582 | Skylight | \$ 1040.00 | 10 | 01-12-2005 | -9.3 years | 70.00% | Good | Retain | N/A |
| LNILU2583 | Tapware | \$ 1343.00 | 15 | 01-12-2005 | -4.3 years | 116.65% | Good | Retain | N/A |
| LNILU2584 | Tiles - Wall | \$ 3384.00 | 20 | 01-12-2005 | 0.7 years | 16.62% | Good | Retain | N/A |

| | LNILU2585 | Tiles - Floor | \$ 4058.00 | 20 | 01-12-2005 | 0.7 years | 14.43% | Good | Retain | Requires cleaning and regroutingFlo |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|-------------------------------------|
| | | | | | | | | | | tiles have been regrouted |
| Bed 1 | | • | | • | | | | • | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2566 | Blind | \$ 342.00 | 10 | 01-12-2005 | -9.3 years | 12.28% | Good | Retain | N/A |
| | LNILU2567 | Carpet | \$ 891.00 | 8 | 01-12-2005 | -11.3 years | 21.89% | Good | Retain | N/A |
| | LNILU2568 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2005 | -9.3 years | 2.63% | Good | Retain | N/A |
| | LNILU2569 | Interior Painting | \$ 726.00 | 10 | 01-12-2005 | -9.3 years | 2.62% | Good | Retain | N/A |
| | LNILU2570 | Wardrobe | \$ 2115.00 | 10 | 01-12-2005 | -9.3 years | 16.62% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2571 | Blind | \$ 342.00 | 10 | 01-12-2005 | -9.3 years | 35.09% | Good | Retain | N/A |
| | LNILU2572 | Carpet | \$ 743.00 | 8 | 01-12-2005 | -11.3 years | 8.20% | Good | Retain | N/A |
| | LNILU2573 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2005 | -9.3 years | 35.04% | Good | Retain | N/A |
| | LNILU2574 | Interior Painting | \$ 605.00 | 10 | 01-12-2005 | -9.3 years | 35.04% | Good | Retain | N/A |
| | LNILU2575 | Wardrobe | \$ 2115.00 | 10 | 01-12-2005 | -9.3 years | 34.99% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2596 | Blind | \$ 400.00 | 10 | 01-12-2005 | -9.3 years | 35.00% | Good | Retain | N/A |
| | LNILU2597 | Carpet | \$ 640.00 | 8 | 01-12-2005 | -11.3 years | 21.88% | Good | Retain | N/A |
| | LNILU2598 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2005 | -9.3 years | 16.64% | Good | Retain | N/A |
| | LNILU2599 | Interior Painting | \$ 514.00 | 10 | 01-12-2005 | -9.3 years | 35.02% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2600 | Carpet | \$ 354.00 | 8 | 01-12-2005 | -11.3 years | 21.89% | Good | Retain | N/A |
| | LNILU2601 | Interior Painting | \$ 285.00 | 10 | 01-12-2005 | -9.3 years | 33.33% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2557 | Blind | \$ 285.00 | 10 | 01-12-2005 | -9.3 years | 8.77% | Fair | Retain | Repair blinds around unit |

| LNILU4466 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2578 | Tiles - Floor | \$ 2086.00 | 20 | 01-12-2005 | 0.7 years | 8.31% | Good | Retain | N/A |
| LNILU2577 | Tiles - Wall | \$ 1246.00 | 20 | 01-12-2005 | 0.7 years | 17.50% | Good | Retain | N/A |
| LNILU2576 | Interior Painting | \$ 257.00 | 10 | 01-12-2005 | -9.3 years | 15.76% | Good | Retain | N/A |
| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | |
| LNILU2565 | Sink & Fittings | \$ 1634.00 | 15 | 01-12-2005 | -4.3 years | 116.69% | Good | Retain | N/A |
| LNILU2564 | Rangehood | \$ 617.00 | 12 | 01-12-2005 | -7.3 years | 14.59% | Good | Retain | N/A |
| LNILU2563 | Oven | \$ 1451.00 | 12 | 01-12-2005 | -7.3 years | 145.88% | Good | Retain | N/A |
| LNILU2562 | Vinyl | \$ 1011.00 | 10 | 01-12-2005 | -9.3 years | 87.54% | Good | Retain | N/A |
| LNILU2561 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-12-2005 | 0.7 years | 17.50% | Good | Retain | N/A |
| LNILU2560 | Interior Painting | \$ 434.00 | 10 | 01-12-2005 | -9.3 years | 35.02% | Good | Retain | N/A |
| LNILU2559 | Cooktop | \$ 1394.00 | 12 | 01-12-2005 | -7.3 years | 2.19% | Good | Retain | N/A |
| LNILU2558 | Benchtops | \$ 2414.00 | 20 | 01-12-2005 | 0.7 years | 4.16% | Good | Retain | N/A |

Living

LNILU4467

LNILU4468

Sink & Fittings

Washing

Machine

\$ 1634.00

\$ 1371.00

15

12

16-11-2022 12.7 years

16-11-2022 9.7 years

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2591 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-12-2005 | -9.3 years | 23.62% | Good | Retain | N/A |
| LNILU2592 | Blind | \$ 400.00 | 10 | 01-12-2005 | -9.3 years | 35.00% | Good | Retain | N/A |
| LNILU2593 | Carpet | \$ 1371.00 | 8 | 01-12-2005 | -11.3 years | 21.88% | Good | Retain | N/A |
| LNILU2594 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2005 | -9.3 years | 35.04% | Good | Retain | N/A |
| LNILU2595 | Interior Painting | \$ 1097.00 | 10 | 01-12-2005 | -9.3 years | 35.00% | Good | Retain | N/A |

0.00% Good

0.00% Good

Retain

Retain

N/A

N/A

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2586 | Skylight | \$ 1040.00 | 10 | 01-12-2005 | -9.3 years | 22.75% | Good | Retain | N/A |
| LNILU2587 | Toilet & Cistern | \$ 1383.00 | 20 | 01-12-2005 | 0.7 years | 87.49% | Good | Retain | N/A |
| LNILU2588 | Tiles - Wall | \$ 926.00 | 20 | 01-12-2005 | 0.7 years | 17.49% | Good | Retain | N/A |
| LNILU2589 | Tiles - Floor | \$ 1429.00 | 20 | 01-12-2005 | 0.7 years | 6.12% | Good | Retain | N/A |

| LNILU2590 | Tapware | \$ 251.00 | 15 | 01-12-2005 | -4.3 years | 116.86% | Good | Retain | N/A |
|-----------|-------------|-----------|----|------------|------------|---------|------|--------|-----|
| LNILU4469 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------------------------------------------------|
| LNILU2602 | Clothesline | \$ 514.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | |
| LNILU2603 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | Balcony screen door scrapping; requires adjustment |
| LNILU2604 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 121.27% | Good | Retain | N/A |
| LNILU2605 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 37/38 |
| LNILU2606 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2608 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| LNILU2610 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2611 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU2612 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | Path crack opposite U37 water tank |
| LNILU2613 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 29.16% | Good | Retain | N/A |
| LNILU2614 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2615 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2616 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU2617 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU4198 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Poor | Repair | Bedroom awning has rusted fittingsStill has rusted fittings |
| LNILU4694 | Fascias | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4695 | Guttering | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|----|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| | LNILU2645 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU4839 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4840 | Exhaust Fan | \$ 262.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4841 | Shower Screen | \$ 1200.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4842 | Skylight | \$ 1040.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4843 | Tapware | \$ 1343.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4844 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4845 | Toilet & Cistern | \$ 1383.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| 1 | | | | , | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2634 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 2.62% | Good | Retain | N/A |
| | LNILU4846 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4847 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4848 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4849 | Wardrobe | \$ 2115.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2639 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU4850 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4851 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| ng | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2664 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU4852 | Air Conditioner - Split System | \$ 3395.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| LNILU4853 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| LNILU4854 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |

| Hall | way |
|------|-----|
|------|-----|

| aiiway | | | | | | | | | | |
|--------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2666 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU4859 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| hen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2625 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 12.26% | Excellent | Retain | N/A |
| | LNILU4860 | Cooktop | \$ 1394.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4861 | Oven | \$ 1451.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4862 | Rangehood | \$ 617.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4863 | Dishwasher | \$ 1486.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4864 | Benchtops | \$ 2414.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4865 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4866 | Kitchen Cabinets | \$ 3932.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4867 | Sink & Fittings | \$ 1634.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4868 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| dry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4869 | Interior Painting | \$ 228.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4870 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4871 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4872 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4873 | Sink & Fittings | \$ 1634.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |
| 9 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2660 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 13.13% | Good | Retain | N/A |
| | LNILU4874 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4875 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4876 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|---------------------------------|---------------------------------------------|------------------------|--------|---------------------------------------------|
| LNILU2667 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | New wiring |
| LNILU2668 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2669 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 121.27% | Good | Retain | N/A |
| LNILU2670 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU2671 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 3.50% | Good | Retain | N/A |
| LNILU2673 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2675 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2676 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Repair | Path trip hazard adjacent U38 AC unit |
| LNILU2677 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU2678 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2679 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU2680 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU2681 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.06% | Good | Retain | N/A |
| LNILU4199 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Good | Retain | N/A |
| LNILU4696 | Fascias | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4697 | Guttering | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |

Unit 39-40

| Common | | | | | | | | | | |
|---------|--------------|-----------------------|----------------------------------|--------------------|------------------------------|--------------------------|---------------------------------------------|------------------------|-----------------------|-----------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2682 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 7.00% | Good | Retain | N/A |
| | | | | | | | | | | |
| Jnit 39 | | | | | | | | | | |
| Jnit 39 | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Jnit 39 | Asset Number | Asset Name Insulation | Acquisition Cost (\$) \$ 3224.00 | Effective Life (Y) | Installation Date 01-07-1982 | | | Asset Condition Good | Plan Retain | Comments N/A |

| | | | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | | | Marks on the ce |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------------|
| | LNILU2702 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 18.04% | Good | Retain | N/A |
| | LNILU2701 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Bed 2 | | | | | | | | | | |
| | LNILU2700 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU2699 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU2698 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 7.01% | Good | Retain | N/A |
| | LNILU2697 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU2696 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 12.28% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Bed 1 | | | 1 | | 1 | 1 | | | | 1 1 1 1 1 1 1 1 |
| | LNILU2715 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Repair | Requires clean and regrouting |
| | LNILU2714 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 4.81% | Good | Retain | N/A |
| | LNILU2713 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 8.75% | Good | Retain | N/A |
| | LNILU2712 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| | LNILU2711 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 3.50% | Good | Retain | N/A |
| | LNILU2710 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU2709 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 28.97% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Bathroom | | | , | , | | | | | | |
| | | | | | | | | | | |
| | LNILU2751 | Smoke Alarms | \$ 268.00 | 20 | 01-09-2004 | -0.6 years | 17.54% | Good | Retain | N/A |
| | LNILU2750 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU2749 | Lighting | \$ 1966.00 | 15 | 01-09-2004 | -5.6 years | 23.33% | Good | Retain | N/A |
| | LNILU2748 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Unit 40 | | | 1 | ı | 1 | , | | | | |
| | LNILU2686 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 8.33% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-----|------------------------|---------------------|--------------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|------------------|------------|
| | LNILU2726 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 14.88% | Good | Retain | N/A |
| | LNILU2727 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 20.78% | Good | Retain | N/A |
| | LNILU2728 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2729 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| vay | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2730 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU2731 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| en | | | <u> </u> | , | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2687 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU2688 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| | LNILU2689 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 13.13% | Good | Retain | N/A |
| | LNILU2690 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Good | Retain | N/A |
| | | | | | 01 07 1002 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU2691 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | | | | |
| | LNILU2691 LNILU2692 | | \$ 3932.00 \$ 1011.00 | 20 | 01-07-1982 | -32.7 years | 72.22% | Good | Retain | N/A |
| | | Cabinets | | | | | | Good | Retain Retain | N/A N/A |
| | LNILU2692 | Cabinets Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 72.22% | | | |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------|
| LNILU2706 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU2707 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 9.19% | Good | Retain | N/A |
| LNILU2708 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4474 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4475 | Dryer | \$ 628.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4476 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Fair | Retain | Upgrade to 1/4 turn |
| LNILU4477 | Washing Machine | \$ 685.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| | • | | |
|-----|----|---|---|
| L۱۱ | VI | n | C |
| | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2721 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 149.59% | Good | Retain | N/A |
| LNILU2722 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| LNILU2723 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| LNILU2724 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU2725 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2716 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2717 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU2718 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU2719 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU2720 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 96.41% | Good | Retain | N/A |
| LNILU4478 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------------|
| LNILU2732 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 12.26% | Good | Retain | Has been restrung |
| LNILU2733 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU2734 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 101.14% | Good | Retain | N/A |
| LNILU2735 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 39/40 |
| LNILU2736 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2738 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 24.50% | Good | Retain | N/A |
| LNILU2740 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2741 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU2742 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU2743 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2745 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 2.33% | Good | Retain | N/A |

| LNILU2746 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|-------|------|--------|--------------|
| LNILU2747 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Poor | Repair | Cracked tile |
| LNILU4200 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.51% | Fair | Repair | N/A |
| LNILU4698 | Fascias | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4699 | Guttering | \$ 1432.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4877 | Water Tank | \$ 1063.00 | 25 | 11-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |

Unit 40

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------------------|
| LNILU2775 | Exhaust Fan | \$ 262.00 | 10 | 01-09-2004 | -10.6 years | 35.11% | Good | Retain | N/A |
| LNILU2776 | Interior Painting | \$ 228.00 | 10 | 01-09-2004 | -10.6 years | 15.79% | Good | Retain | N/A |
| LNILU2777 | Shower Screen | \$ 1200.00 | 20 | 01-09-2004 | -0.6 years | 17.50% | Good | Retain | N/A |
| LNILU2778 | Skylight | \$ 1040.00 | 10 | 01-09-2004 | -10.6 years | 5.25% | Good | Retain | N/A |
| LNILU2779 | Tapware | \$ 1343.00 | 15 | 01-09-2004 | -5.6 years | 116.65% | Good | Retain | N/A |
| LNILU2780 | Tiles - Wall | \$ 3384.00 | 20 | 01-09-2004 | -0.6 years | 17.49% | Good | Retain | Requires re- grouting |
| LNILU2781 | Tiles - Floor | \$ 4058.00 | 20 | 01-09-2004 | -0.6 years | 17.50% | Good | Retain | Requires cleaning and regrouting |

Bed 1

| Asse | et Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|-----------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|---------|---------------------|
| LNIL | U2761 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-09-2004 | -10.6 years | 314.93% | Good | Retain | N/A |
| LNIL | U2762 | Blind | \$ 342.00 | 10 | 01-09-2004 | -10.6 years | 35.09% | Good | Retain | N/A |
| LNIL | U2763 | Carpet | \$ 891.00 | 8 | 01-09-2004 | -12.6 years | 1.64% | Good | Retain | N/A |
| LNIL | U2764 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2004 | -10.6 years | 33.29% | Poor | Replace | N/A |
| LNIL | U2765 | Interior Painting | \$ 726.00 | 10 | 01-09-2004 | -10.6 years | 34.99% | Good | Retain | Re-paint B1 ceiling |
| LNIL | U2766 | Wardrobe | \$ 2115.00 | 10 | 01-09-2004 | -10.6 years | 15.74% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2767 | Blind | \$ 342.00 | 10 | 01-09-2004 | -10.6 years | 35.09% | Good | Retain | N/A |
| LNILU2768 | Carpet | \$ 743.00 | 8 | 01-09-2004 | -12.6 years | 10.39% | Good | Retain | N/A |

| | LNILU2769 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2004 | -10.6 years | 15.77% | Good | Retain | N/A |
|----------------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------|
| | LNILU2770 | Interior Painting | \$ 605.00 | 10 | 01-09-2004 | -10.6 years | 35.04% | Good | Retain | N/A |
| | LNILU2771 | Wardrobe | \$ 2115.00 | 10 | 01-09-2004 | -10.6 years | 28.87% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2792 | Blind | \$ 400.00 | 10 | 01-09-2004 | -10.6 years | 2.63% | Good | Retain | N/A |
| | LNILU2793 | Carpet | \$ 640.00 | 8 | 01-09-2004 | -12.6 years | 1.64% | Good | Retain | N/A |
| | LNILU2794 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2004 | -10.6 years | 2.63% | Good | Retain | N/A |
| | LNILU2795 | Interior Painting | \$ 514.00 | 10 | 01-09-2004 | -10.6 years | 35.02% | Good | Retain | N/A |
| lallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2796 | Carpet | \$ 354.00 | 8 | 01-09-2004 | -12.6 years | 20.80% | Good | Retain | N/A |
| | LNILU2797 | Interior Painting | \$ 285.00 | 10 | 01-09-2004 | -10.6 years | 11.40% | Good | Retain | N/A |
| Citchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2752 | Blind | \$ 285.00 | 10 | 01-09-2004 | -10.6 years | 9.65% | Good | Retain | N/A |
| | LNILU2753 | Benchtops | \$ 2414.00 | 20 | 01-09-2004 | -0.6 years | 7.22% | Good | Retain | N/A |
| | LNILU2754 | Cooktop | \$ 1394.00 | 12 | 01-09-2004 | -8.6 years | 29.17% | Good | Retain | N/A |
| | LNILU2755 | Interior Painting | \$ 434.00 | 10 | 01-09-2004 | -10.6 years | 35.02% | Good | Retain | Cracked cornice |
| | LNILU2756 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-09-2004 | -0.6 years | 1.31% | Good | Retain | N/A |
| | LNILU2757 | Vinyl | \$ 1011.00 | 10 | 01-09-2004 | -10.6 years | 87.54% | Fair | Retain | N/A |
| | LNILU2758 | Oven | \$ 1451.00 | 12 | 01-09-2004 | -8.6 years | 145.88% | Good | Retain | N/A |
| | LNILU2759 | Rangehood | \$ 617.00 | 12 | 01-09-2004 | -8.6 years | 6.93% | Good | Retain | N/A |
| | LNILU2760 | Sink & Fittings | \$ 1634.00 | 15 | 01-09-2004 | -5.6 years | 96.27% | Good | Retain | N/A |
| aundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2772 | Interior Painting | \$ 257.00 | 10 | 01-09-2004 | -10.6 years | 35.02% | Good | Retain | N/A |
| | LNILU2773 | Tiles - Wall | \$ 1246.00 | 20 | 01-09-2004 | -0.6 years | 14.43% | Good | Retain | N/A |
| | LNILU2774 | Tiles - Floor | \$ 2086.00 | 20 | 01-09-2004 | -0.6 years | 14.44% | Fair | Retain | N/A |
| | LNILU4479 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | | 7 | | | | | | | | |

| | LNILU4480 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
|--------------|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|---------|----------------|
| | LNILU4481 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| /ing | | | | | | | _ | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2787 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-09-2004 | -10.6 years | 314.93% | Good | Retain | N/A |
| | LNILU2788 | Blind | \$ 400.00 | 10 | 01-09-2004 | -10.6 years | 28.88% | Good | Retain | N/A |
| | LNILU2789 | Carpet | \$ 1371.00 | 8 | 01-09-2004 | -12.6 years | 6.02% | Good | Retain | N/A |
| | LNILU2790 | Ceiling Fan | \$ 605.00 | 10 | 01-09-2004 | -10.6 years | 33.29% | Good | Retain | N/A |
| | LNILU2791 | Interior Painting | \$ 1097.00 | 10 | 01-09-2004 | -10.6 years | 35.00% | Good | Retain | N/A |
| ilet room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2782 | Skylight | \$ 1040.00 | 10 | 01-09-2004 | -10.6 years | 70.00% | Good | Retain | N/A |
| | LNILU2783 | Toilet & Cistern | \$ 1383.00 | 20 | 01-09-2004 | -0.6 years | 87.49% | Good | Retain | N/A |
| | LNILU2784 | Tiles - Wall | \$ 926.00 | 20 | 01-09-2004 | -0.6 years | 14.43% | Good | Retain | N/A |
| | LNILU2785 | Tiles - Floor | \$ 1429.00 | 20 | 01-09-2004 | -0.6 years | 16.62% | Good | Retain | N/A |
| | LNILU2786 | Tapware | \$ 251.00 | 15 | 01-09-2004 | -5.6 years | 111.02% | Good | Retain | N/A |
| | LNILU4482 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| nit Exterior | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2798 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU2799 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| | LNILU2800 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 130.21% | Good | Retain | N/A |
| | LNILU2801 | Electrical | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between |
| | LINILOZOUT | Switchboard | \$ 2023.00 | 20 | 01-07-1302 | -22.7 years | 07.43% | Good | Retairi | 39/40 |

5.69% Good

70.00% Good

23.32% Good

6.56% Good

N/A

N/A

N/A

N/A

Retain

Retain

Retain

Retain

01-07-1982 -32.7 years

01-07-1982 -32.7 years

01-07-1982 -27.7 years

01-07-1982 -22.7 years

10

10

15

20

LNILU2802

LNILU2804

LNILU2806

LNILU2807

Exterior

Painting

Flyscreens

Hot Water

Lattice

Screening

System - Solar

\$ 2149.00

\$ 1920.00

\$ 4516.00

\$ 2206.00

| LNILU2808 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 4.81% | Good | Retain | Pathway cracked |
|-----------|---------------------|------------|----|------------|-------------|--------|------|--------|-------------------------------------------------------------------|
| LNILU2809 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU2811 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU2812 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU2813 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | Tile has visible cracks and also requires cleaning and regrouting |
| LNILU4700 | Awnings | \$ 6886.00 | 10 | 22-08-2023 | 8.4 years | 0.00% | Good | Retain | N/A |
| LNILU4701 | Fascias | \$ 1616.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4702 | Guttering | \$ 1616.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4878 | Water Tank | \$ 1063.00 | 25 | 11-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |

Unit 41-42

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comm |
|---------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|------|
| | LNILU2814 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 9.62% | Good | Retain | N/A |
| Unit 41 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comm |
| | LNILU2815 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2816 | Lighting | \$ 1966.00 | 15 | 01-03-2004 | -6.1 years | 4.67% | Good | Retain | N/A |
| | LNILU2817 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU2818 | Smoke Alarms | \$ 268.00 | 20 | 01-03-2004 | -1.1 years | 16.66% | Good | Retain | N/A |
| Unit 42 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comn |
| | LNILU2879 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2880 | Lighting | \$ 1966.00 | 15 | 01-07-2010 | 0.3 years | 7.58% | Fair | Retain | N/A |
| | LNILU2881 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU2882 | Smoke Alarms | \$ 268.00 | 20 | 01-07-2010 | 5.3 years | 17.54% | Good | Retain | N/A |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| | LNILU2840 | Exhaust Fan | \$ 262.00 | 10 | 01-03-2004 | -11.1 years | 35.11% | Good | Retain | N/A |
| | LNILU2841 | Interior Painting | \$ 228.00 | 10 | 01-03-2004 | -11.1 years | 35.09% | Good | Retain | N/A |
| | LNILU2843 | Skylight | \$ 1040.00 | 10 | 01-03-2004 | -11.1 years | 70.00% | Good | Retain | N/A |
| | LNILU2844 | Tapware | \$ 1343.00 | 15 | 01-03-2004 | -6.1 years | 116.65% | Good | Retain | N/A |
| | LNILU2845 | Tiles - Wall | \$ 3384.00 | 20 | 01-03-2004 | -1.1 years | 17.49% | Good | Retain | N/A |
| | LNILU2846 | Tiles - Floor | \$ 4058.00 | 20 | 01-03-2004 | -1.1 years | 17.50% | Good | Retain | N/A |
| ed 1 | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2829 | Carpet | \$ 891.00 | 8 | 01-03-2004 | -13.1 years | 21.89% | Good | Retain | N/A |
| | LNILU2830 | Ceiling Fan | \$ 605.00 | 10 | 13-11-2023 | 8.6 years | 0.00% | Excellent | Retain | |
| | LNILU2831 | Interior Painting | \$ 726.00 | 10 | 01-03-2004 | -11.1 years | 16.62% | Good | Retain | N/A |
| | LNILU2832 | Wardrobe | \$ 2115.00 | 10 | 01-03-2004 | -11.1 years | 28.87% | Good | Retain | N/A |
| | LNILU4879 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| d 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2834 | Carpet | \$ 743.00 | 8 | 01-03-2004 | -13.1 years | 20.78% | Good | Retain | N/A |
| | LNILU2835 | Interior Painting | \$ 605.00 | 10 | 01-03-2004 | -11.1 years | 35.04% | Good | Retain | N/A |
| | LNILU2836 | Wardrobe | \$ 2115.00 | 10 | 01-03-2004 | -11.1 years | 34.99% | Good | Retain | N/A |
| | LNILU4880 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| ning | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2857 | Blind | \$ 400.00 | 10 | 01-03-2004 | -11.1 years | 35.00% | Good | Retain | N/A |
| | LNILU2858 | Carpet | \$ 640.00 | 8 | 01-03-2004 | -13.1 years | 21.88% | Good | Retain | N/A |
| | LNILU2860 | Interior Painting | \$ 514.00 | 10 | 01-03-2004 | -11.1 years | 28.89% | Good | Retain | N/A |

Hallway

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2861 | Carpet | \$ 354.00 | 8 | 01-03-2004 | -13.1 years | 18.06% | Good | Retain | N/A |
| LNILU2862 | Interior Painting | \$ 285.00 | 10 | 01-03-2004 | -11.1 years | 2.63% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2819 | Blind | \$ 285.00 | 10 | 01-03-2004 | -11.1 years | 33.33% | Good | Retain | N/A |
| LNILU2820 | Benchtops | \$ 2414.00 | 20 | 01-03-2004 | -1.1 years | 8.75% | Good | Retain | N/A |
| LNILU2821 | Cooktop | \$ 1394.00 | 12 | 01-03-2004 | -9.1 years | 29.17% | Good | Retain | N/A |
| LNILU2822 | Interior Painting | \$ 434.00 | 10 | 01-03-2004 | -11.1 years | 35.02% | Good | Retain | N/A |
| LNILU2823 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-03-2004 | -1.1 years | 17.50% | Good | Retain | N/A |
| LNILU2824 | Vinyl | \$ 1011.00 | 10 | 01-03-2004 | -11.1 years | 6.57% | Good | Retain | N/A |
| LNILU2825 | Oven | \$ 1451.00 | 12 | 01-03-2004 | -9.1 years | 145.88% | Good | Retain | N/A |
| LNILU2826 | Rangehood | \$ 617.00 | 12 | 01-03-2004 | -9.1 years | 12.03% | Good | Retain | N/A |
| LNILU2827 | Sink & Fittings | \$ 1634.00 | 15 | 01-03-2004 | -6.1 years | 8.75% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------------------------|
| LNILU2837 | Interior Painting | \$ 257.00 | 10 | 01-03-2004 | -11.1 years | 15.76% | Good | Retain | N/A |
| LNILU2838 | Tiles - Wall | \$ 1246.00 | 20 | 01-03-2004 | -1.1 years | 17.50% | Good | Retain | N/A |
| LNILU2839 | Tiles - Floor | \$ 2086.00 | 20 | 01-03-2004 | -1.1 years | 5.69% | Good | Retain | N/A |
| LNILU4485 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4486 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | Mixer upgraded to 1/4 turn |
| LNILU4487 | Washing Machine | \$ 890.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2854 | Carpet | \$ 1371.00 | 8 | 01-03-2004 | -13.1 years | 21.88% | Good | Retain | N/A |
| LNILU2855 | Ceiling Fan | \$ 605.00 | 10 | 13-11-2023 | 8.6 years | 0.00% | Excellent | Retain | |
| LNILU2856 | Interior Painting | \$ 1097.00 | 10 | 01-03-2004 | -11.1 years | 35.00% | Good | Retain | N/A |
| LNILU4489 | Air Conditioner - Split System | \$ 3395.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4881 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU2847 | Skylight | \$ 1040.00 | 10 | 01-03-2004 | -11.1 years | 70.00% | Good | Retain | N/A |
| LNILU2848 | Toilet & Cistern | \$ 1383.00 | 20 | 01-03-2004 | -1.1 years | 89.66% | Good | Retain | N/A |
| LNILU2849 | Tiles - Wall | \$ 926.00 | 20 | 01-03-2004 | -1.1 years | 14.43% | Good | Retain | N/A |
| LNILU2850 | Tiles - Floor | \$ 1429.00 | 20 | 01-03-2004 | -1.1 years | 1.31% | Good | Retain | N/A |
| LNILU2851 | Tapware | \$ 251.00 | 15 | 01-03-2004 | -6.1 years | 116.86% | Good | Retain | N/A |
| LNILU4488 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|---------------------------------|
| LNILU2863 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 48.64% | Fair | Repair | Has been restrung - still rusty |
| LNILU2864 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2865 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 70.69% | Good | Retain | N/A |
| LNILU2866 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 30.62% | Good | Retain | Shared between unit 41/42 |
| LNILU2867 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2868 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 16.52% | Good | Retain | N/A |
| LNILU2869 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU2870 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU2871 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU2872 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| LNILU2873 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 4.81% | Good | Retain | N/A |
| LNILU2874 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU2875 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU2876 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU2877 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 1.75% | Good | Retain | N/A |
| LNILU2878 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.72% | Good | Retain | N/A |
| LNILU4203 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Fair | Retain | N/A |

| Bathroom | | | | | | | | | | |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|--------------------------------------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2905 | Exhaust Fan | \$ 262.00 | 10 | 01-07-2010 | -4.7 years | 2.63% | Good | Retain | N/A |
| | LNILU2906 | Interior Painting | \$ 228.00 | 10 | 01-07-2010 | -4.7 years | 28.95% | Good | Retain | N/A |
| | LNILU2907 | Shower Screen | \$ 1200.00 | 20 | 01-07-2010 | 5.3 years | 4.81% | Good | Retain | N/A |
| | LNILU2908 | Skylight | \$ 1040.00 | 10 | 01-07-2010 | -4.7 years | 66.50% | Good | Retain | N/A |
| | LNILU2909 | Tapware | \$ 1343.00 | 15 | 01-07-2010 | 0.3 years | 116.65% | Good | Retain | N/A |
| | LNILU2910 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-2010 | 5.3 years | 8.75% | Good | Retain | N/A |
| | LNILU2911 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-2010 | 5.3 years | 17.50% | Good | Retain | Requires cleaning and regroutingHave been cleaned and regrouted |
| Bed 1 | | | | | | | | , | | , |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2892 | Blind | \$ 342.00 | 10 | 01-07-2010 | -4.7 years | 15.79% | Good | Retain | N/A |
| | LNILU2893 | Carpet | \$ 891.00 | 8 | 01-07-2010 | -6.7 years | 1.64% | Good | Retain | N/A |
| | LNILU2894 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 35.04% | Good | Retain | N/A |
| | LNILU2895 | Interior Painting | \$ 726.00 | 10 | 01-07-2010 | -4.7 years | 34.99% | Good | Retain | N/A |
| | LNILU2896 | Wardrobe | \$ 2115.00 | 10 | 01-07-2010 | -4.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4491 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2897 | Blind | \$ 342.00 | 10 | 01-07-2010 | -4.7 years | 35.09% | Good | Retain | N/A |
| | LNILU2898 | Carpet | \$ 743.00 | 8 | 01-07-2010 | -6.7 years | 21.87% | Good | Retain | N/A |
| | LNILU2900 | Interior Painting | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 158.66% | Good | Retain | N/A |
| | LNILU4492 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2922 | Blind | \$ 400.00 | 10 | 01-07-2010 | -4.7 years | 28.88% | Good | Retain | N/A |
| | LNILU2923 | Carpet | \$ 640.00 | 8 | 01-07-2010 | -6.7 years | 21.88% | Good | Retain | N/A |
| | LNILU2924 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 15.77% | Good | Retain | N/A |
| | | | | | | | | | | |

| | LNILU2925 | Interior Painting | \$ 514.00 | 10 | 01-07-2010 | -4.7 years | 33.27% | Good | Retain | N/A |
|---------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------|
| | LNILU4498 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2926 | Carpet | \$ 354.00 | 8 | 01-07-2010 | -6.7 years | 1.64% | Good | Retain | N/A |
| | LNILU2927 | Interior Painting | \$ 285.00 | 10 | 01-07-2010 | -4.7 years | 35.09% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2883 | Blind | \$ 285.00 | 10 | 01-07-2010 | -4.7 years | 35.09% | Good | Retain | N/A |
| | LNILU2884 | Benchtops | \$ 2414.00 | 20 | 01-07-2010 | 5.3 years | 8.75% | Good | Retain | N/A |
| | LNILU2885 | Cooktop | \$ 1394.00 | 12 | 01-07-2010 | -2.7 years | 12.40% | Good | Retain | N/A |
| | LNILU2886 | Interior Painting | \$ 434.00 | 10 | 01-07-2010 | -4.7 years | 28.89% | Good | Retain | N/A |
| | LNILU2887 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-2010 | 5.3 years | 7.87% | Good | Retain | N/A |
| | LNILU2888 | Vinyl | \$ 1011.00 | 10 | 01-07-2010 | -4.7 years | 87.54% | Good | Retain | N/A |
| | LNILU2889 | Oven | \$ 1451.00 | 12 | 01-07-2010 | -2.7 years | 120.35% | Good | Retain | N/A |
| | LNILU2890 | Rangehood | \$ 617.00 | 12 | 01-07-2010 | -2.7 years | 14.59% | Good | Retain | N/A |
| | LNILU2891 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-2010 | 0.3 years | 116.69% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2902 | Interior Painting | \$ 257.00 | 10 | 01-07-2010 | -4.7 years | 35.02% | Good | Retain | N/A |
| | LNILU2903 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-2010 | 5.3 years | 17.50% | Good | Retain | N/A |
| | LNILU2904 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-2010 | 5.3 years | 17.50% | Good | Retain | N/A |
| | LNILU4493 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4494 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | Upgrade to 1/4 turn |
| | LNILU4495 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2917 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-2010 | -4.7 years | 259.82% | Good | Retain | N/A |
| | | | | | | | | | | |

15.75% Good

Retain

N/A

10

01-07-2010 -4.7 years

\$ 400.00

LNILU2918

Blind

| LNILU2919 | Carpet | \$ 1371.00 | 8 | 01-07-2010 | -6.7 years | 20.79% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|------------|--------|------|--------|-----|
| LNILU2920 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2010 | -4.7 years | 35.04% | Good | Retain | N/A |
| LNILU2921 | Interior Painting | \$ 1097.00 | 10 | 01-07-2010 | -4.7 years | 35.00% | Good | Retain | N/A |
| LNILU4497 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU2912 | Skylight | \$ 1040.00 | 10 | 01-07-2010 | -4.7 years | 70.00% | Good | Retain | N/A |
| LNILU2913 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-2010 | 5.3 years | 28.43% | Good | Retain | N/A |
| LNILU2914 | Tiles - Wall | \$ 926.00 | 20 | 01-07-2010 | 5.3 years | 1.31% | Good | Retain | N/A |
| LNILU2915 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-2010 | 5.3 years | 1.75% | Good | Retain | N/A |
| LNILU2916 | Tapware | \$ 251.00 | 15 | 01-07-2010 | 0.3 years | 116.86% | Good | Retain | N/A |
| LNILU4496 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------------|
| LNILU2928 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Fair | Retain | N/A |
| LNILU2929 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 0.87% | Good | Retain | N/A |
| LNILU2930 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 100.24% | Good | Retain | N/A |
| LNILU2931 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 37.18% | Good | Retain | Shared between unit 41/42 |
| LNILU2932 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU2934 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 105.16% | Good | Retain | N/A |
| LNILU2936 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 19.24% | Good | Retain | N/A |
| LNILU2937 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU2938 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Repair | Path crack opposite entry U42 |
| LNILU2939 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 14.58% | Good | Retain | N/A |

| LNILU2941 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 5.25% | Good | Retain | B1 window locking device broken and removed - to be replaced - cannot lock windowRepaired |
|-----------|---------------------|------------|----|------------|-------------|-------|-----------|--------|----------------------------------------------------------------------------------------------------------|
| LNILU2942 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| LNILU2943 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Good | Retain | N/A |
| LNILU4204 | Awnings | \$ 9718.00 | 10 | 13-11-2021 | 6.6 years | 0.00% | Good | Retain | New Awnings |
| LNILU4703 | Fascias | \$ 1468.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Good | Retain | N/A |
| LNILU4704 | Guttering | \$ 1468.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

Unit 43-44

Unit 43

Bathroom

Asset Number

LNILU2971

Asset Name

Exhaust Fan

Acquisition Cost (\$)

\$ 262.00

Effective Life (Y)

10

Installation Date

01-03-2004 -11.1 years

| Common | • | • | | | • | | | • | • | |
|---------|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2944 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Jnit 43 | - | - | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU2945 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU2946 | Lighting | \$ 1966.00 | 15 | 01-03-2004 | -6.1 years | 19.25% | Fair | Retain | N/A |
| | LNILU2947 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 57.73% | Good | Retain | N/A |
| | LNILU2948 | Smoke Alarms | \$ 268.00 | 20 | 01-03-2004 | -1.1 years | 1.32% | Good | Retain | N/A |
| Jnit 44 | | | | , | | | | | · | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3010 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3011 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU3012 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Fair | Retain | N/A |
| | LNILU3013 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 16.66% | Good | Retain | N/A |

Remaining Effective Life

Accumulated Repair Cost as % of Acquisition

Asset Condition

2.63% Good

Plan

Retain

Comments

N/A

| | LINILUZYYZ | Carpet | \$ 354.00 | 8 | 01-03-2004 | -13.1 years | 18.06% | Good | Retain | IN/A |
|-----|------------------------|----------------------------|--------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------|
| | Asset Number LNILU2992 | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments N/A |
| way | • | • | • | | | | | | | |
| | LNILU2991 | Interior Painting | \$ 514.00 | 10 | 01-03-2004 | -11.1 years | 35.02% | Fair | Retain | N/A |
| | LNILU2990 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2004 | -11.1 years | 28.91% | Good | Retain | N/A |
| | LNILU2989 | Carpet | \$ 640.00 | 8 | 01-03-2004 | -13.1 years | 20.78% | Good | Retain | N/A |
| | LNILU2988 | Blind | \$ 400.00 | 10 | 01-03-2004 | -11.1 years | 35.00% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| l | | | | | | | | | | |
| | LNILU2966 | Interior Painting | \$ 605.00 | 10 | 01-03-2004 | -11.1 years | 35.04% | Good | Retain | N/A |
| | LNILU2964 | Carpet | \$ 743.00 | 8 | 01-03-2004 | -13.1 years | 21.87% | Good | Retain | N/A |
| | LNILU2963 | Blind | \$ 342.00 | 10 | 01-03-2004 | -11.1 years | 35.09% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | 1 | | | | , | | | | , |
| | LNILU2962 | Wardrobe | \$ 2115.00 | 10 | 01-03-2004 | -11.1 years | 15.74% | Good | Retain | N/A |
| | LNILU2961 | Interior Painting | \$ 726.00 | 10 | 01-03-2004 | -11.1 years | 33.24% | Fair | Repair | Due for re-pai |
| | LNILU2960 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2004 | -11.1 years | 16.64% | Good | Retain | N/A |
| | LNILU2959 | Carpet | \$ 891.00 | 8 | 01-03-2004 | -13.1 years | 21.89% | Good | Retain | N/A |
| | LNILU2958 | Blind | \$ 342.00 | 10 | 01-03-2004 | -11.1 years | 35.09% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LINILU2977 | Tiles - Floor | \$ 4056.00 | 20 | 01-03-2004 | -1.1 years | 10.02% | raii | Retain | IN/A |
| | LNILU2976 LNILU2977 | Tiles - Wall Tiles - Floor | \$ 3384.00 \$ 4058.00 | 20 | 01-03-2004 01-03-2004 | -1.1 years | 14.43% 16.62% | Good Fair | Retain | N/A N/A |
| | LNILU2975 | Tapware | \$ 1343.00 | 15 | 01-03-2004 | -6.1 years | 96.24% | Good | Retain | Upgrade to 1/4 |
| | LNILU2974 | Skylight | \$ 1040.00 | 10 | 01-03-2004 | -11.1 years | 70.00% | Good | Retain | N/A |
| | LNILU2973 | Shower Screen | \$ 1200.00 | 20 | 01-03-2004 | -1.1 years | 1.31% | Good | Retain | Rust/mould appearing insidescreen |
| | LNILU2972 | Interior Painting | \$ 228.00 | 10 | 01-03-2004 | -11.1 years | 35.09% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|--------------|
| LNILU2949 | Blind | \$ 285.00 | 10 | 01-03-2004 | -11.1 years | 28.95% | Good | Retain | N/A |
| LNILU2950 | Benchtops | \$ 2414.00 | 20 | 01-03-2004 | -1.1 years | 8.75% | Fair | Retain | N/A |
| LNILU2951 | Cooktop | \$ 1394.00 | 12 | 01-03-2004 | -9.1 years | 29.17% | Good | Retain | N/A |
| LNILU2952 | Interior Painting | \$ 434.00 | 10 | 01-03-2004 | -11.1 years | 2.63% | Fair | Retain | N/A |
| LNILU2953 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-03-2004 | -1.1 years | 1.31% | Fair | Retain | N/A |
| LNILU2954 | Vinyl | \$ 1011.00 | 10 | 01-03-2004 | -11.1 years | 41.58% | Fair | Retain | Minor scrato |
| LNILU2955 | Oven | \$ 1451.00 | 12 | 01-03-2004 | -9.1 years | 145.88% | Good | Retain | N/A |
| LNILU2956 | Rangehood | \$ 617.00 | 12 | 01-03-2004 | -9.1 years | 1.09% | Good | Retain | N/A |
| LNILU2957 | Sink & Fittings | \$ 1634.00 | 15 | 01-03-2004 | -6.1 years | 8.75% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------|
| LNILU2968 | Interior Painting | \$ 257.00 | 10 | 01-03-2004 | -11.1 years | 35.02% | Fair | Retain | N/A |
| LNILU2969 | Tiles - Wall | \$ 1246.00 | 20 | 01-03-2004 | -1.1 years | 6.56% | Good | Retain | N/A |
| LNILU2970 | Tiles - Floor | \$ 2086.00 | 20 | 01-03-2004 | -1.1 years | 17.50% | Fair | Retain | N/A |
| LNILU4499 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| LNILU4500 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Fair | Retain | Upgrade to 1/4 turn |
| LNILU4501 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU2983 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-03-2004 | -11.1 years | 314.93% | Good | Retain | N/A |
| LNILU2984 | Blind | \$ 400.00 | 10 | 01-03-2004 | -11.1 years | 35.00% | Good | Retain | N/A |
| LNILU2985 | Carpet | \$ 1371.00 | 8 | 01-03-2004 | -13.1 years | 21.88% | Good | Retain | N/A |
| LNILU2986 | Ceiling Fan | \$ 605.00 | 10 | 01-03-2004 | -11.1 years | 9.64% | Good | Retain | N/A |
| LNILU2987 | Interior Painting | \$ 1097.00 | 10 | 01-03-2004 | -11.1 years | 33.25% | Fair | Retain | N/A |
| LNILU4503 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------------------------------------------------------|
| LNILU2978 | Skylight | \$ 1040.00 | 10 | 01-03-2004 | -11.1 years | 31.50% | Good | Retain | N/A |
| LNILU2979 | Toilet & Cistern | \$ 1383.00 | 20 | 01-03-2004 | -1.1 years | 83.12% | Good | Retain | N/A |
| LNILU2980 | Tiles - Wall | \$ 926.00 | 20 | 01-03-2004 | -1.1 years | 16.62% | Good | Retain | N/A |
| LNILU2981 | Tiles - Floor | \$ 1429.00 | 20 | 01-03-2004 | -1.1 years | 5.69% | Fair | Repair | Requires cleaning and regrouting |
| LNILU2982 | Tapware | \$ 251.00 | 15 | 01-03-2004 | -6.1 years | 116.86% | Fair | Retain | Upgrade to 1/4 turn |
| LNILU4502 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4882 | Interior Painting | \$ 228.00 | 10 | 01-03-2004 | -11.1 years | 0.00% | Fair | Repair | Holes in the toilet wall; requires patch and paint |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------|
| LNILU2994 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 33.27% | Fair | Retain | N/A |
| LNILU2995 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Fair | Repair | Living room door is jamming |
| LNILU2996 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 114.55% | Good | Retain | N/A |
| LNILU2997 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 37.18% | Good | Retain | N/A |
| LNILU2998 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 1.31% | Good | Retain | N/A |
| LNILU3000 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3002 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |
| LNILU3003 | Lattice Screening | \$ 2206.00 | 20 | 13-11-2018 | 13.6 years | 0.00% | Good | Retain | |
| LNILU3004 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | N/A |
| LNILU3005 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3007 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 4.37% | Good | Retain | N/A |
| LNILU3008 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3009 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4205 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 1.03% | Fair | Repair | Repair split awning |

| LNILU4705 | Fascias | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
|-----------|------------|------------|----|------------|------------|-------|-----------|--------|-----|
| LNILU4706 | Guttering | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4883 | Water Tank | \$ 1063.00 | 25 | 10-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |

Unit 44

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------------------------------------------------------------|
| LNILU3035 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| LNILU3036 | Interior Painting | \$ 228.00 | 10 | 01-03-2019 | 3.9 years | 8.77% | Very Poor | Repair | Repair water damaged ceiling has been outstanding for a couple of years |
| LNILU3037 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3038 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 31.50% | Good | Retain | N/A |
| LNILU3039 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 110.82% | Good | Retain | N/A |
| LNILU3040 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3041 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|------------------------------------------------------------------|
| LNILU3023 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| LNILU3024 | Carpet | \$ 891.00 | 8 | 01-03-2019 | 1.9 years | 20.79% | Good | Retain | N/A |
| LNILU3025 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | Fan speed is faulty; change controllerHas been repaired |
| LNILU3026 | Interior Painting | \$ 726.00 | 10 | 01-03-2019 | 3.9 years | 33.24% | Good | Retain | N/A |
| LNILU3027 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| LNILU4504 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3028 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 16.67% | Good | Retain | N/A |
| LNILU3029 | Carpet | \$ 743.00 | 8 | 01-03-2019 | 1.9 years | 21.87% | Good | Retain | N/A |
| LNILU3030 | Interior Painting | \$ 605.00 | 10 | 01-03-2019 | 3.9 years | 12.26% | Good | Retain | N/A |
| LNILU4505 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

| Dining | | | | | | | | | | |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3052 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU3054 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3055 | Interior Painting | \$ 514.00 | 10 | 01-03-2019 | 3.9 years | 35.02% | Good | Retain | N/A |
| | LNILU4509 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4510 | Vinyl | \$ 1011.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3056 | Carpet | \$ 354.00 | 8 | 01-03-2019 | 1.9 years | 21.89% | Good | Retain | N/A |
| | 1811112057 | Intonion Pointino | ¢ 205 00 | 10 | 04 02 0040 | 2.0 | 16.670/ | 6 1 | Dotoin | N/A |
| | LNILU3057 | Interior Painting | \$ 285.00 | 10 | 01-03-2019 | 3.9 years | 16.67% | Good | Retain | IN/A |
| Kitchen | LINILU3057 | interior Painting | \$ 285.00 | 10 | 01-03-2019 | 3.9 years | 16.67% | Good | Retain | IV/A |
| Kitchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| tchen | | | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3014 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU3015 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 2.84% | Good | Retain | N/A |
| LNILU3016 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 24.07% | Good | Retain | N/A |
| LNILU3017 | Interior Painting | \$ 434.00 | 10 | 01-03-2019 | 3.9 years | 11.38% | Good | Retain | N/A |
| LNILU3018 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3019 | Vinyl | \$ 1011.00 | 10 | 01-03-2019 | 3.9 years | 87.54% | Good | Retain | N/A |
| LNILU3020 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| LNILU3021 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 2.92% | Good | Retain | N/A |
| LNILU3022 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3032 | Interior Painting | \$ 257.00 | 10 | 01-03-2019 | 3.9 years | 13.13% | Good | Retain | N/A |
| LNILU3033 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3034 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4506 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4507 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3047 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU3048 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU3049 | Carpet | \$ 1371.00 | 8 | 01-03-2019 | 1.9 years | 21.88% | Good | Retain | N/A |
| LNILU3050 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU3051 | Interior Painting | \$ 1097.00 | 10 | 01-03-2019 | 3.9 years | 35.00% | Good | Retain | N/A |
| LNILU4508 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|---------|----------------------------------------|
| LNILU3058 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 7.00% | Good | Retain | N/A |
| LNILU3059 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | N/A |
| LNILU3060 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 134.19% | Good | Retain | N/A |
| LNILU3061 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared between unit 43/44 |
| LNILU3062 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 1.31% | Good | Retain | N/A |
| LNILU3064 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3066 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3067 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | Lattice post is rusty |
| LNILU3068 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | Pathway/driveway has cracks |
| LNILU3069 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3070 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | Downpipe is not connected to rear pipe |
| LNILU3071 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3072 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3073 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Retain | N/A |
| LNILU4206 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 5.49% | Poor | Replace | Awnings rotting and rusting |

| U | nit | 45-40 | 6 |
|---|-----|-------|---|
| _ | | T 7 | • |

| Common | | | | | | | | | | |
|---------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3074 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Jnit 45 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3075 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3076 | Lighting | \$ 1966.00 | 15 | 01-12-2010 | 0.7 years | 19.25% | Good | Retain | N/A |
| | LNILU3077 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 5.25% | Good | Retain | N/A |
| | LNILU3078 | Smoke Alarms | \$ 268.00 | 20 | 01-12-2010 | 5.7 years | 16.66% | Good | Retain | N/A |
| Jnit 46 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3139 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 12.90% | Good | Retain | N/A |
| | LNILU3140 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 6.42% | Good | Retain | N/A |
| | LNILU3141 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU3142 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

0.00% Excellent

0.00% Good

N/A

N/A

Retain

Retain

26-06-2023 18.3 years

26-06-2023 18.3 years

Unit 45

Bathroom

LNILU4707

LNILU4708

Fascias

Guttering

\$ 1733.00

\$ 1733.00

20

20

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3100 | Exhaust Fan | \$ 262.00 | 10 | 01-12-2010 | -4.3 years | 2.63% | Good | Retain | N/A |
| LNILU3101 | Interior Painting | \$ 228.00 | 10 | 01-12-2010 | -4.3 years | 35.09% | Good | Retain | N/A |
| LNILU3102 | Shower Screen | \$ 1200.00 | 20 | 01-12-2010 | 5.7 years | 4.81% | Fair | Retain | N/A |
| LNILU3103 | Skylight | \$ 1040.00 | 10 | 01-12-2010 | -4.3 years | 19.25% | Good | Retain | N/A |
| LNILU3104 | Tapware | \$ 1343.00 | 15 | 01-12-2010 | 0.7 years | 116.65% | Good | Retain | N/A |
| LNILU3105 | Tiles - Wall | \$ 3384.00 | 20 | 01-12-2010 | 5.7 years | 1.31% | Good | Retain | N/A |
| LNILU3106 | Tiles - Floor | \$ 4058.00 | 20 | 01-12-2010 | 5.7 years | 14.43% | Good | Retain | N/A |

| _ | | |
|----|---|--|
| ĸД | ~ | |
| uc | u | |

| | | , | , | , | | | | | | |
|--------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3088 | Blind | \$ 342.00 | 10 | 01-12-2010 | -4.3 years | 11.40% | Good | Retain | N/A |
| | LNILU3089 | Carpet | \$ 891.00 | 8 | 01-12-2010 | -6.3 years | 21.89% | Good | Retain | N/A |
| | LNILU3090 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2010 | -4.3 years | 35.04% | Good | Retain | N/A |
| | LNILU3091 | Interior Painting | \$ 726.00 | 10 | 01-12-2010 | -4.3 years | 2.62% | Good | Retain | N/A |
| | LNILU3092 | Wardrobe | \$ 2115.00 | 10 | 01-12-2010 | -4.3 years | 34.99% | Good | Retain | N/A |
| | LNILU4511 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3093 | Blind | \$ 342.00 | 10 | 01-12-2010 | -4.3 years | 35.09% | Good | Retain | N/A |
| | LNILU3094 | Carpet | \$ 743.00 | 8 | 01-12-2010 | -6.3 years | 21.87% | Good | Retain | N/A |
| | LNILU3095 | Interior Painting | \$ 605.00 | 10 | 01-12-2010 | -4.3 years | 9.64% | Good | Retain | N/A |
| | LNILU4512 | Curtains | \$ 914.00 | 6 | 16-11-2022 | 3.7 years | 0.00% | Fair | Retain | N/A |
| ining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3117 | Blind | \$ 400.00 | 10 | 01-12-2010 | -4.3 years | 28.88% | Good | Retain | N/A |
| | LNILU3118 | Carpet | \$ 640.00 | 8 | 01-12-2010 | -6.3 years | 18.05% | Good | Retain | N/A |
| | LNILU3119 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2010 | -4.3 years | 28.91% | Good | Retain | N/A |
| | LNILU3120 | Interior Painting | \$ 514.00 | 10 | 01-12-2010 | -4.3 years | 33.27% | Good | Retain | N/A |
| allway | | | | , | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3121 | Carpet | \$ 354.00 | 8 | 01-12-2010 | -6.3 years | 21.89% | Good | Retain | N/A |
| | LNILU3122 | Interior Painting | \$ 285.00 | 10 | 01-12-2010 | -4.3 years | 35.09% | Good | Retain | N/A |
| itchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3079 | Blind | \$ 285.00 | 10 | 01-12-2010 | -4.3 years | 33.33% | Good | Retain | N/A |
| | LNILU3080 | Benchtops | \$ 2414.00 | 20 | 01-12-2010 | 5.7 years | 2.84% | Good | Retain | N/A |
| | LNILU3081 | Cooktop | \$ 1394.00 | 12 | 01-12-2010 | -2.3 years | 29.17% | Good | Retain | N/A |
| | LNILU3082 | Interior Painting | \$ 434.00 | 10 | 01-12-2010 | -4.3 years | | Good | Retain | N/A |

| LNILU3083 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-12-2010 | 5.7 years | 6.12% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|------------|--------|------|--------|-----|
| LNILU3084 | Vinyl | \$ 1011.00 | 10 | 01-12-2010 | -4.3 years | 87.54% | Good | Retain | N/A |
| LNILU3085 | Oven | \$ 1451.00 | 12 | 01-12-2010 | -2.3 years | 62.00% | Good | Retain | N/A |
| LNILU3086 | Rangehood | \$ 617.00 | 12 | 01-12-2010 | -2.3 years | 14.59% | Good | Retain | N/A |
| LNILU3087 | Sink & Fittings | \$ 1634.00 | 15 | 01-12-2010 | 0.7 years | 96.27% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3097 | Interior Painting | \$ 257.00 | 10 | 01-12-2010 | -4.3 years | 2.63% | Good | Retain | N/A |
| LNILU3098 | Tiles - Wall | \$ 1246.00 | 20 | 01-12-2010 | 5.7 years | 17.50% | Good | Retain | N/A |
| LNILU3099 | Tiles - Floor | \$ 2086.00 | 20 | 01-12-2010 | 5.7 years | 7.44% | Good | Retain | N/A |
| LNILU4513 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4514 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4515 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| As | sset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|----|-------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LN | NILU3112 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-12-2010 | -4.3 years | 314.93% | Good | Retain | N/A |
| LN | NILU3113 | Blind | \$ 400.00 | 10 | 01-12-2010 | -4.3 years | 13.13% | Good | Retain | N/A |
| LN | NILU3114 | Carpet | \$ 1371.00 | 8 | 01-12-2010 | -6.3 years | 21.88% | Good | Retain | N/A |
| LN | NILU3115 | Ceiling Fan | \$ 605.00 | 10 | 01-12-2010 | -4.3 years | 28.91% | Good | Retain | N/A |
| LN | NILU3116 | Interior Painting | \$ 1097.00 | 10 | 01-12-2010 | -4.3 years | 12.25% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3107 | Skylight | \$ 1040.00 | 10 | 01-12-2010 | -4.3 years | 22.75% | Fair | Retain | N/A |
| LNILU3108 | Toilet & Cistern | \$ 1383.00 | 20 | 01-12-2010 | 5.7 years | 6.56% | Good | Retain | N/A |
| LNILU3109 | Tiles - Wall | \$ 926.00 | 20 | 01-12-2010 | 5.7 years | 1.31% | Good | Retain | N/A |
| LNILU3110 | Tiles - Floor | \$ 1429.00 | 20 | 01-12-2010 | 5.7 years | 1.31% | Good | Retain | N/A |
| LNILU3111 | Tapware | \$ 251.00 | 15 | 01-12-2010 | 0.7 years | 96.41% | Good | Retain | N/A |
| LNILU4516 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|---------|----------------------------------|
| LNILU3123 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU3124 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 5.69% | Fair | Retain | N/A |
| LNILU3125 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |
| LNILU3126 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between units 45/46 |
| LNILU3127 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 14.43% | Good | Retain | N/A |
| LNILU3129 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3130 | Guttering | \$ 2903.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU3131 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3132 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| LNILU3133 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3134 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 10.43% | Good | Retain | N/A |
| LNILU3135 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3136 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 4.96% | Good | Retain | N/A |
| LNILU3137 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU3138 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | Requires cleaning and regrouting |
| LNILU4207 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.12% | Poor | Replace | Faded and worn |
| LNILU4709 | Fascias | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4710 | Guttering | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |

Unit 46

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU3164 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| LNILU3165 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 14.91% | Good | Retain | N/A |
| LNILU4884 | Shower Screen | \$ 1200.00 | 20 | 15-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| LNILU4885 | Skylight | \$ 1040.00 | 10 | 15-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| LNILU4886 | Tapware | \$ 1343.00 | 15 | 15-01-2024 | 13.8 years | 0.00% | Good | Retain | N/A |

| | LNILU4887 | Tiles - Floor | \$ 4058.00 | 20 | 15-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
|---------|---------------------|------------------------------|------------------------------------|--------------------|---------------------------------|--------------------------------------|----------------------------------------------------|------------------------|-----------------------|------------------------|
| | LNILU4888 | Tiles - Wall | \$ 3384.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| ed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3155 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4889 | Carpet | \$ 891.00 | 8 | 10-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4890 | Ceiling Fan | \$ 605.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4891 | Wardrobe | \$ 2115.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4892 | Blind | \$ 342.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3157 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3159 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 28.91% | Good | Retain | N/A |
| | LNILU4893 | Wardrobe | \$ 2115.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4894 | Carpet | \$ 891.00 | 8 | 10-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |
| ining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3184 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 10.51% | Good | Retain | N/A |
| | LNILU4895 | Vinyl | \$ 1011.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4896 | Ceiling Fan | \$ 605.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4897 | Blind | \$ 342.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| lallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3186 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 28.95% | Good | Retain | N/A |
| | | | | | 10 01 2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| | LNILU4898 | Carpet | \$ 891.00 | 8 | 10-01-2024 | 0.0 years | 0.0070 | 9000 | | |
| (itchen | LNILU4898 | Carpet | \$ 891.00 | 8 | 10-01-2024 | 0.0 years | 0.00% | 0000 | | |
| itchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| itchen | | | | | | | | | | Comments N/A |
| itchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments N/A N/A |
| itchen | Asset Number | Asset Name Interior Painting | Acquisition Cost (\$) \$ 434.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 28.89% | Asset Condition Good | Plan Retain | N/A |

| LNILU4900 | Oven | \$ 1451.00 | 12 | 10-01-2024 | 10.8 years | 0.00% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|------------|-------|------|--------|-----|
| LNILU4901 | Rangehood | \$ 617.00 | 12 | 10-01-2024 | 10.8 years | 0.00% | Good | Retain | N/A |
| LNILU4902 | Dishwasher | \$ 1486.00 | 8 | 10-01-2024 | 6.8 years | 0.00% | Good | Retain | N/A |
| LNILU4903 | Benchtops | \$ 2414.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| LNILU4904 | Blind | \$ 342.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| LNILU4905 | Kitchen Cabinets | \$ 3932.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|--------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3161 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU4522 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4906 | Tiles - Floor | \$ 4058.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| LNILU4907 | Tiles - Wall | \$ 3384.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Good | Retain | N/A |
| LNILU4908 | Blind | \$ 342.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |
| LNILU4909 | Sink & Fittings | \$ 1634.00 | 15 | 10-01-2024 | 13.8 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU3176 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| LNILU3177 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU3179 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| LNILU3180 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU4910 | Vinyl | \$ 1011.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3171 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| LNILU3172 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | N/A |
| LNILU3173 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| LNILU3174 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Good | Retain | N/A |
| LNILU4523 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------------------------------------------|
| LNILU3187 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 13.13% | Good | Retain | N/A |
| LNILU3189 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 134.97% | Good | Retain | N/A |
| LNILU3190 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared between unit 45/46 |
| LNILU3191 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.87% | Good | Retain | N/A |
| LNILU3193 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 76.25% | Good | Retain | N/A |
| LNILU3195 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 19.24% | Good | Retain | N/A |
| LNILU3196 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 14.44% | Good | Retain | N/A |
| LNILU3197 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.54% | Good | Retain | Pathway has cracksCracks in pathway have been rectified. |
| LNILU3198 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 63.32% | Good | Retain | N/A |
| LNILU3200 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3201 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3202 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Repair | Various cracked tiles |
| LNILU4208 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.29% | Good | Retain | N/A |
| LNILU4711 | Fascias | \$ 1713.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4712 | Guttering | \$ 1713.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4911 | Doors | \$ 9215.00 | 30 | 10-01-2024 | 28.8 years | 0.00% | Good | Repair | Door between living room and balcony hard to slide renew casters |
| LNILU4912 | Water Tank | \$ 1063.00 | 25 | 10-01-2024 | 23.8 years | 0.00% | Good | Retain | Shared between unit 45/46 |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Cor |
|----------|------------------------|-----------------------|--------------------------|--------------------|--------------------------|----------------------------|---------------------------------------------|-----------------|------------------|---------------------------------|
| | LNILU3203 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 35.26% | Good | Retain | N/A |
| Unit 47 | | | | | | | | | · | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com |
| | LNILU3204 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3205 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | Light dinin fan p name |
| | LNILU3206 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU3207 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 14.47% | Good | Retain | N/A |
| Unit 48 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com |
| | LNILU3273 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 4.14% | Good | Retain | N/A |
| | LNILU3274 | Lighting | \$ 1966.00 | 15 | 01-11-2004 | -5.4 years | 7.00% | Good | Retain | N/A |
| | LNILU3275 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 5.25% | Good | Retain | N/A |
| | LNILU3276 | Smoke Alarms | \$ 268.00 | 20 | 01-11-2004 | -0.4 years | 16.66% | Good | Retain | N/A |
| | | | | | | | | | | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com |
| | LNILU3235 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| | LNILU3236 | Interior Painting | \$ 228.00 | 10 | 01-03-2019 | 3.9 years | 35.09% | Excellent | Retain | N/A |
| | LNILU3237 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Excellent | Retain | N/A |
| | | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| | LNILU3238 | , , | | | | 27.7 | 32.08% | Excellent | Retain | N/A |
| | LNILU3238 LNILU3239 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | JE.0070 | | | |
| | | | \$ 1343.00 \$ 4058.00 | 15 20 | 01-07-1982 01-07-1982 | -27.7 years -22.7 years | 1.31% | Excellent | Retain | N/A |
| | LNILU3239 | Tapware | | | | | | | Retain Repair | Minc |
| Bed 1 | LNILU3239 LNILU3241 | Tapware Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Excellent | | Minc |
| Bed 1 | LNILU3239 LNILU3241 | Tapware Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 1.31% | Excellent | | N/A Mino requi |

| | LNILU3219 | Carpet | \$ 891.00 | 8 | 01-03-2019 | 1.9 years | 21.89% | Good | Retain | N/A |
|-----|---------------------------------------------------------------------|-----------------------------------------------------------------------------|------------------------------------------------------------------|------------------------------------|--------------------------------------------------------------------|------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------|------------------------------------------------|---------------------------------|
| | LNILU3220 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3221 | Interior Painting | \$ 726.00 | 10 | 01-03-2019 | 3.9 years | 2.62% | Good | Retain | N/A |
| | LNILU3222 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 28.87% | Good | Retain | N/A |
| | LNILU4914 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| 2 | | | | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3224 | Carpet | \$ 743.00 | 8 | 01-03-2019 | 1.9 years | 18.04% | Good | Retain | N/A |
| | LNILU3225 | Interior Painting | \$ 605.00 | 10 | 01-03-2019 | 3.9 years | 35.04% | Good | Retain | N/A |
| | LNILU4915 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| ıg | | ' | , | | | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3253 | Carpet | \$ 640.00 | 8 | 01-03-2019 | 1.9 years | 21.88% | Good | Retain | N/A |
| | LNILU3254 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3255 | Interior Painting | \$ 514.00 | 10 | 01-03-2019 | 3.9 years | 35.02% | Good | Retain | N/A |
| | LNILU4916 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| way | | ' | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3256 | Carpet | \$ 354.00 | 8 | 01-03-2019 | 1.9 years | 20.80% | Good | Retain | N/A |
| | | | 4 225 22 | 10 | | 2.0 | 35.09% | Good | Retain | N/A |
| | LNILU3257 | Interior Painting | \$ 285.00 | 10 | 01-03-2019 | 3.9 years | 55.09% | Good | Retairi | |
| nen | LNILU3257 | Interior Painting | \$ 285.00 | 10 | 01-03-2019 | 3.9 years | 55.03% | Good | Retaili | |
| en | Asset Number | Interior Painting Asset Name | Acquisition Cost (\$) | Effective Life (Y) | 01-03-2019 Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| en | | | | | | - | | | | Comments N/A |
| en | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | |
| en | Asset Number | Asset Name | Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 35.09% | Asset Condition Good | Plan Retain | N/A |
| en | Asset Number LNILU3208 LNILU3209 | Asset Name Blind Benchtops | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 | Effective Life (Y) 10 20 | Installation Date 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years | Accumulated Repair Cost as % of Acquisition 35.09% 2.84% | Asset Condition Good Good | Plan Retain Retain | N/A N/A |
| en | Asset Number LNILU3208 LNILU3209 LNILU3210 | Asset Name Blind Benchtops Cooktop | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 | Effective Life (Y) 10 20 12 | 1nstallation Date 01-07-1982 01-07-1982 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years | Accumulated Repair Cost as % of Acquisition 35.09% 2.84% 27.71% | Asset Condition Good Good Good | Plan Retain Retain Retain | N/A N/A N/A |
| en | Asset Number LNILU3208 LNILU3209 LNILU3210 LNILU3211 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 | Effective Life (Y) 10 20 12 10 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-03-2019 | Remaining Effective Life -32.7 years -22.7 years -30.7 years 3.9 years | Accumulated Repair Cost as % of Acquisition 35.09% 2.84% 27.71% 35.02% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | N/A N/A N/A |
| en | Asset Number LNILU3208 LNILU3209 LNILU3210 LNILU3211 LNILU3212 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | Effective Life (Y) 10 20 12 10 20 | 01-07-1982 01-07-1982 01-07-1982 01-03-2019 01-07-1982 | Remaining Effective Life -32.7 years -22.7 years -30.7 years 3.9 years -22.7 years | Accumulated Repair Cost as % of Acquisition 35.09% 2.84% 27.71% 35.02% 0.00% | Asset Condition Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |

| L | LNILU3216 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 2.92% | Good | Retain | N/A |
|-------------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------|
| aundry | | | | | | | | | | |
| A | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU3227 | Interior Painting | \$ 257.00 | 10 | 01-03-2019 | 3.9 years | 35.02% | Good | Retain | N/A |
| L | LNILU3228 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| L | LNILU3229 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| L | LNILU4528 | Blind | \$ 400.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| L | LNILU4529 | Sink & Fittings | \$ 1634.00 | 15 | 16-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| L | LNILU4530 | Washing Machine | \$ 1371.00 | 12 | 16-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ving | | | | | | | | | | |
| P | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU3247 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| L | LNILU3249 | Carpet | \$ 1371.00 | 8 | 01-03-2019 | 1.9 years | 1.64% | Good | Retain | N/A |
| L | LNILU3250 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| L | LNILU3251 | Interior Painting | \$ 1097.00 | 10 | 01-03-2019 | 3.9 years | 35.00% | Good | Retain | N/A |
| L | LNILU4917 | Shutters | \$ 1063.00 | 10 | 11-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| ilet room | | | | | | | | | | |
| - | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU3230 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| L | LNILU3231 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 28.43% | Good | Retain | N/A |
| L | LNILU3232 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| L | LNILU3234 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 8.76% | Good | Retain | N/A |
| L | LNILU3245 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| L | LNILU4531 | Exhaust Fan | \$ 262.00 | 10 | 16-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| it Exterior | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| L | LNILU3258 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Repair | Needs tensioni |
| L | LNILU3259 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| L | LNILU3260 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |

| LNILU4714 | Guttering | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|----------------------------------------------------------------------|
| LNILU4713 | Fascias | \$ 1671.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4209 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.29% | Good | Repair | N/A |
| LNILU3272 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 2.84% | Fair | Repair | N/A |
| LNILU3271 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 0.22% | Good | Retain | N/A |
| LNILU3270 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 3.79% | Good | Retain | N/A |
| LNILU3269 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Fair | Retain | N/A |
| LNILU3268 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 18.95% | Good | Retain | N/A |
| LNILU3267 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Fair | Repair | Replace entry cracked tile - path crack adjacent water tank |
| LNILU3266 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 36.78% | Good | Retain | N/A |
| LNILU3264 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3262 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU3261 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 28.44% | Good | Retain | Shared between unit 47/48 |

Unit 48

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3298 | Exhaust Fan | \$ 262.00 | 10 | 01-11-2004 | -10.4 years | 35.11% | Good | Retain | N/A |
| LNILU3299 | Interior Painting | \$ 228.00 | 10 | 01-11-2004 | -10.4 years | 16.67% | Good | Retain | N/A |
| LNILU3300 | Shower Screen | \$ 1200.00 | 20 | 01-11-2004 | -0.4 years | 1.31% | Good | Retain | N/A |
| LNILU3301 | Skylight | \$ 1040.00 | 10 | 01-11-2004 | -10.4 years | 70.00% | Good | Retain | N/A |
| LNILU3302 | Tapware | \$ 1343.00 | 15 | 01-11-2004 | -5.4 years | 116.65% | Good | Retain | N/A |
| LNILU3303 | Tiles - Wall | \$ 3384.00 | 20 | 01-11-2004 | -0.4 years | 14.43% | Good | Retain | N/A |
| LNILU3304 | Tiles - Floor | \$ 4058.00 | 20 | 01-11-2004 | -0.4 years | 1.31% | Good | Retain | N/A |

Bed 1

| Asset Numbe | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3286 | Blind | \$ 342.00 | 10 | 01-11-2004 | -10.4 years | 33.33% | Good | Retain | N/A |

| | LNILU3287 | Carpet | \$ 891.00 | 8 | 01-11-2004 | -12.4 years | 21.89% | Good | Retain | N/A |
|---------|-----------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|------------------------------------------|-----------------------------------------------------------------------------|-------------------------------------------------------|
| | LNILU3288 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2004 | -10.4 years | 8.76% | Good | Retain | N/A |
| | LNILU3289 | Interior Painting | \$ 726.00 | 10 | 01-11-2004 | -10.4 years | 16.62% | Good | Retain | N/A |
| | LNILU3290 | Wardrobe | \$ 2115.00 | 10 | 01-11-2004 | -10.4 years | 33.24% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3291 | Blind | \$ 342.00 | 10 | 01-11-2004 | -10.4 years | 35.09% | Good | Retain | N/A |
| | LNILU3292 | Carpet | \$ 743.00 | 8 | 01-11-2004 | -12.4 years | 21.87% | Good | Retain | N/A |
| | LNILU3293 | Interior Painting | \$ 605.00 | 10 | 01-11-2004 | -10.4 years | 35.04% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3315 | Blind | \$ 400.00 | 10 | 01-11-2004 | -10.4 years | 16.63% | Good | Retain | N/A |
| | LNILU3316 | Carpet | \$ 640.00 | 8 | 01-11-2004 | -12.4 years | 1.64% | Good | Retain | N/A |
| | LNILU3317 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2004 | -10.4 years | 33.29% | Good | Retain | N/A |
| | LNILU3318 | Interior Painting | \$ 514.00 | 10 | 01-11-2004 | -10.4 years | 35.02% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number LNILU3319 | Asset Name Carpet | Acquisition Cost (\$) \$ 354.00 | Effective Life (Y) | Installation Date 01-11-2004 | Remaining Effective Life -12.4 years | Accumulated Repair Cost as % of Acquisition 21.89% | Asset Condition Good | Plan Retain | Comments N/A |
| | | | | | | | • | | | |
| Kitchen | LNILU3319 | Carpet | \$ 354.00 | 8 | 01-11-2004 | -12.4 years | 21.89% | Good | Retain | N/A |
| Kitchen | LNILU3319 | Carpet | \$ 354.00 | 8 | 01-11-2004 | -12.4 years | 21.89% | Good | Retain | N/A |
| Kitchen | LNILU3319 LNILU3320 | Carpet Interior Painting | \$ 354.00 \$ 285.00 | 8 10 | 01-11-2004 01-11-2004 | -12.4 years -10.4 years | 21.89% 15.79% | Good | Retain Retain | N/A N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number | Carpet Interior Painting Asset Name | \$ 354.00 \$ 285.00 Acquisition Cost (\$) | 8 10 Effective Life (Y) | 01-11-2004 01-11-2004 Installation Date | -12.4 years -10.4 years Remaining Effective Life | 21.89% 15.79% Accumulated Repair Cost as % of Acquisition | Good Good Asset Condition | Retain Retain Plan | N/A N/A Comments |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 | Carpet Interior Painting Asset Name Blind | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | 01-11-2004 01-11-2004 Installation Date 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years | Accumulated Repair Cost as % of Acquisition 2.63% | Good Good Asset Condition Good | Retain Retain Plan Retain | N/A N/A Comments N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 LNILU3278 | Carpet Interior Painting Asset Name Blind Benchtops | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 | Effective Life (Y) 10 20 | 01-11-2004 01-11-2004 Installation Date 01-11-2004 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years -0.4 years | Accumulated Repair Cost as % of Acquisition 2.63% 0.66% | Good Good Asset Condition Good Good | Retain Retain Plan Retain Retain | N/A N/A Comments N/A N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 LNILU3278 LNILU3279 | Carpet Interior Painting Asset Name Blind Benchtops Cooktop | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 | 8 10 Effective Life (Y) 10 20 12 | 01-11-2004 01-11-2004 Installation Date 01-11-2004 01-11-2004 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years -0.4 years -8.4 years | 21.89% 15.79% Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 9.48% | Good Good Asset Condition Good Good Good | Retain Retain Plan Retain Retain Retain Retain | N/A N/A Comments N/A N/A N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 LNILU3278 LNILU3279 LNILU3280 | Carpet Interior Painting Asset Name Blind Benchtops Cooktop Interior Painting Kitchen | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 | 8 10 Effective Life (Y) 10 20 12 10 | 01-11-2004 01-11-2004 Installation Date 01-11-2004 01-11-2004 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years -0.4 years -8.4 years -10.4 years | 21.89% 15.79% Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 9.48% 35.02% | Good Good Good Good Good Good Good | Retain Retain Plan Retain Retain Retain Retain Retain | N/A N/A Comments N/A N/A N/A N/A N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 LNILU3278 LNILU3279 LNILU3280 LNILU3281 | Carpet Interior Painting Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | 8 10 Effective Life (Y) 10 20 12 10 20 | 01-11-2004 01-11-2004 Installation Date 01-11-2004 01-11-2004 01-11-2004 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years -0.4 years -8.4 years -10.4 years -10.4 years | 21.89% 15.79% Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 9.48% 35.02% 1.31% | Good Good Good Good Good Good Good Good | Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain | N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A |
| Kitchen | LNILU3319 LNILU3320 Asset Number LNILU3277 LNILU3278 LNILU3279 LNILU3280 LNILU3281 LNILU3282 | Carpet Interior Painting Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl | \$ 354.00 \$ 285.00 Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 | 8 10 Effective Life (Y) 10 20 12 10 20 | 01-11-2004 01-11-2004 Installation Date 01-11-2004 01-11-2004 01-11-2004 01-11-2004 01-11-2004 | -12.4 years -10.4 years Remaining Effective Life -10.4 years -0.4 years -8.4 years -10.4 years -10.4 years -10.4 years | 21.89% 15.79% Accumulated Repair Cost as % of Acquisition 2.63% 0.66% 9.48% 35.02% 1.31% | Good Good Good Good Good Good Good Good | Retain Retain Plan Retain Retain Retain Retain Retain Retain Retain Retain | N/A N/A Comments N/A N/A N/A N/A N/A N/A N/A N/A N/A |

| Laundry | , |
|---------|---|
|---------|---|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|--------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3295 | Interior Painting | \$ 257.00 | 10 | 01-11-2004 | -10.4 years | 35.02% | Good | Retain | N/A |
| LNILU3296 | Tiles - Wall | \$ 1246.00 | 20 | 01-11-2004 | -0.4 years | 17.50% | Good | Retain | N/A |
| LNILU3297 | Tiles - Floor | \$ 2086.00 | 20 | 01-11-2004 | -0.4 years | 17.50% | Good | Retain | N/A |
| LNILU4534 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4535 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4536 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3311 | Blind | \$ 400.00 | 10 | 01-11-2004 | -10.4 years | 2.63% | Good | Retain | N/A |
| LNILU3312 | Carpet | \$ 1371.00 | 8 | 01-11-2004 | -12.4 years | 21.88% | Good | Retain | N/A |
| LNILU3313 | Ceiling Fan | \$ 605.00 | 10 | 01-11-2004 | -10.4 years | 0.88% | Good | Retain | N/A |
| LNILU3314 | Interior Painting | \$ 1097.00 | 10 | 01-11-2004 | -10.4 years | 2.63% | Good | Retain | N/A |

Toilet room

| - | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| L | NILU3305 | Skylight | \$ 1040.00 | 10 | 01-11-2004 | -10.4 years | 70.00% | Good | Retain | N/A |
| L | NILU3306 | Toilet & Cistern | \$ 1383.00 | 20 | 01-11-2004 | -0.4 years | 87.49% | Good | Retain | N/A |
| L | NILU3307 | Tiles - Wall | \$ 926.00 | 20 | 01-11-2004 | -0.4 years | 17.49% | Good | Retain | N/A |
| L | NILU3308 | Tiles - Floor | \$ 1429.00 | 20 | 01-11-2004 | -0.4 years | 14.43% | Good | Retain | N/A |
| L | NILU3309 | Tapware | \$ 251.00 | 15 | 01-11-2004 | -5.4 years | 116.86% | Good | Retain | N/A |
| L | NILU4537 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|---------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|---------------------------|
| LNILU3321 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU3322 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3323 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 103.56% | Good | Retain | N/A |
| LNILU3324 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 72.18% | Good | Retain | Shared between unit 47/48 |
| LNILU3325 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 0.44% | Good | Retain | N/A |

| LNILU3327 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 14.00% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|---------------------------------|
| LNILU3329 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3330 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3331 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3332 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 2.62% | Good | Retain | N/A |
| LNILU3333 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3334 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 1.75% | Good | Retain | N/A |
| LNILU3335 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 0.66% | Fair | Repair | Various cracks on balcony tiles |
| LNILU4210 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Good | Retain | N/A |
| LNILU4715 | Fascias | \$ 1733.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4716 | Guttering | \$ 1733.00 | 20 | 26-06-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 49-50

Unit 49

| mmon | | | | | | | | | | |
|--------|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|----------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3336 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| nit 49 | | | | | | | | | · | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3337 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3338 | Lighting | \$ 1966.00 | 15 | 01-06-2016 | 6.2 years | 23.33% | Good | Retain | N/A |
| | LNILU3339 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 22.74% | Good | Retain | N/A |
| | LNILU3340 | Smoke Alarms | \$ 268.00 | 20 | 01-06-2016 | 11.2 years | 0.44% | Good | Retain | N/A |
| nit 50 | | | | | | | | <u>'</u> | <u>'</u> | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3401 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3402 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU3403 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU3404 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

| R | at | h | ro | O | m |
|---|----|---|----|---|---|
| | | | | | |

| athroom | | | | | | | | | | |
|------------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3363 | Exhaust Fan | \$ 262.00 | 10 | 01-06-2016 | 1.2 years | 35.11% | Excellent | Retain | N/A |
| | LNILU3364 | Interior Painting | \$ 228.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Excellent | Retain | N/A |
| | LNILU3365 | Shower Screen | \$ 1200.00 | 20 | 01-06-2016 | 11.2 years | 1.31% | Excellent | Retain | N/A |
| | LNILU3366 | Skylight | \$ 1040.00 | 10 | 01-06-2016 | 1.2 years | 70.00% | Good | Retain | N/A |
| | LNILU3367 | Tapware | \$ 1343.00 | 15 | 01-06-2016 | 6.2 years | 116.65% | Excellent | Retain | N/A |
| | LNILU3368 | Tiles - Wall | \$ 3384.00 | 20 | 01-06-2016 | 11.2 years | 17.49% | Excellent | Retain | N/A |
| | LNILU3369 | Tiles - Floor | \$ 4058.00 | 20 | 12-11-2022 | 17.6 years | 0.00% | Excellent | Retain | |
| l 1 | | | | | , | | | , | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3350 | Blind | \$ 342.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Good | Retain | N/A |
| | LNILU3351 | Carpet | \$ 891.00 | 8 | 01-06-2016 | -0.8 years | 21.89% | Good | Retain | N/A |
| | | | | | | | | | | |

01-06-2016 1.2 years

01-06-2016 1.2 years

01-06-2016 1.2 years

10

10

10

\$ 605.00

\$ 726.00

\$ 2115.00

Bed 2

LNILU3352

LNILU3353

LNILU3354

Ceiling Fan

Wardrobe

Interior Painting

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3355 | Blind | \$ 342.00 | 10 | 01-06-2016 | 1.2 years | 28.95% | Good | Retain | N/A |
| LNILU3356 | Carpet | \$ 743.00 | 8 | 01-06-2016 | -0.8 years | 18.04% | Good | Retain | N/A |
| LNILU3357 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 28.91% | Good | Retain | N/A |
| LNILU3358 | Interior Painting | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 35.04% | Good | Retain | N/A |
| LNILU3359 | Wardrobe | \$ 2115.00 | 10 | 01-06-2016 | 1.2 years | 28.87% | Good | Retain | N/A |

N/A

N/A

N/A

Retain

Retain

Retain

2.63% Good

28.86% Good

34.99% Good

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3380 | Blind | \$ 400.00 | 10 | 01-06-2016 | 1.2 years | 16.63% | Good | Retain | N/A |
| LNILU3381 | Carpet | \$ 640.00 | 8 | 01-06-2016 | -0.8 years | 21.88% | Good | Retain | N/A |
| LNILU3382 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 14.89% | Good | Retain | N/A |
| LNILU3383 | Interior Painting | \$ 514.00 | 10 | 01-06-2016 | 1.2 years | 35.02% | Good | Retain | N/A |

| Hall | way |
|------|-----|
|------|-----|

LNILU3378

LNILU3379

Ceiling Fan

Interior Painting

\$ 605.00

\$ 1097.00

| Hallway | • | | | • | • | | | | | |
|---------|---------------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|-------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3384 | Carpet | \$ 354.00 | 8 | 01-06-2016 | -0.8 years | 10.95% | Good | Retain | N/A |
| | LNILU3385 | Interior Painting | \$ 285.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Good | Retain | N/A |
| itchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3341 | Blind | \$ 285.00 | 10 | 01-06-2016 | 1.2 years | 7.02% | Good | Retain | N/A |
| | LNILU3342 | Benchtops | \$ 2414.00 | 20 | 01-06-2016 | 11.2 years | 4.16% | Excellent | Retain | N/A |
| | LNILU3343 | Cooktop | \$ 1394.00 | 12 | 01-06-2016 | 3.2 years | 29.17% | Good | Retain | N/A |
| | LNILU3344 | Interior Painting | \$ 434.00 | 10 | 01-06-2016 | 1.2 years | 28.89% | Good | Retain | N/A |
| | LNILU3345 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-06-2016 | 11.2 years | 14.44% | Good | Retain | N/A |
| | LNILU3347 | Oven | \$ 1451.00 | 12 | 01-06-2016 | 3.2 years | 3.65% | Good | Retain | N/A |
| | LNILU3348 | Rangehood | \$ 617.00 | 12 | 01-06-2016 | 3.2 years | 0.36% | Good | Retain | N/A |
| | LNILU3349 | Sink & Fittings | \$ 1634.00 | 15 | 01-06-2016 | 6.2 years | 32.09% | Good | Retain | N/A |
| | LNILU4970 | Vinyl | \$ 1011.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Excellent | Retain | Timber look vin |
| | LNILU4971 | Dishwasher | \$ 2685.00 | 8 | 01-07-2024 | 7.3 years | 0.00% | Excellent | Retain | Stainless steel freestanding. |
| undry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3360 | Interior Painting | \$ 257.00 | 10 | 01-06-2016 | 1.2 years | 12.26% | Good | Retain | N/A |
| | LNILU3361 | Tiles - Wall | \$ 1246.00 | 20 | 01-06-2016 | 11.2 years | 1.31% | Good | Retain | N/A |
| | LNILU3362 | Tiles - Floor | \$ 2086.00 | 20 | 12-11-2022 | 17.6 years | 0.00% | Excellent | Retain | |
| | LNILU4541 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4542 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4543 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3376 | Blind | \$ 400.00 | 10 | 01-06-2016 | 1.2 years | 33.25% | Good | Retain | N/A |
| | | | | | | | | | | |

11.39% Good

35.00% Good

Retain

Retain

N/A

N/A

01-06-2016 1.2 years

01-06-2016 1.2 years

10

10

| LNILU4918 | Air Conditioner - Split System | \$ 3395.00 | 10 | 10-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
|-----------|-----------------------------------|------------|----|------------|-----------|-------|-----------|--------|--------------------|
| LNILU4972 | Vinyl | \$ 1011.00 | 10 | 01-07-2024 | 9.3 years | 0.00% | Excellent | Retain | Timber look vinyl. |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3370 | Skylight | \$ 1040.00 | 10 | 01-06-2016 | 1.2 years | 70.00% | Good | Retain | N/A |
| LNILU3372 | Tiles - Wall | \$ 926.00 | 20 | 01-06-2016 | 11.2 years | 17.49% | Good | Retain | N/A |
| LNILU3373 | Tiles - Floor | \$ 1429.00 | 20 | 01-06-2016 | 11.2 years | 17.49% | Good | Retain | N/A |
| LNILU3374 | Tapware | \$ 251.00 | 15 | 01-06-2016 | 6.2 years | 116.86% | Good | Retain | N/A |
| LNILU4544 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4919 | Toilet & Cistern | \$ 1383.00 | 20 | 10-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------|
| LNILU3386 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 14.88% | Good | Retain | N/A |
| LNILU3387 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| LNILU3388 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |
| LNILU3389 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU3390 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 7.44% | Good | Retain | N/A |
| LNILU3392 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3394 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 1.75% | Good | Retain | N/A |
| LNILU3395 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | Pathway has trip hazard |
| LNILU3396 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 18.95% | Good | Retain | N/A |
| LNILU3397 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3398 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3399 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU3400 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU4211 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 1.14% | Good | Retain | N/A |
| LNILU4717 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |

| | LNILU4718 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
|----------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------|
| | | | | | | | | | | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comn |
| | LNILU3426 | Exhaust Fan | \$ 262.00 | 10 | 01-10-2012 | -2.5 years | 8.78% | Good | Retain | N/A |
| | LNILU3427 | Interior Painting | \$ 228.00 | 10 | 01-12-2019 | 4.7 years | 2.63% | Good | Retain | N/A |
| | LNILU3428 | Shower Screen | \$ 1200.00 | 20 | 01-03-2009 | 3.9 years | 5.69% | Good | Retain | N/A |
| | LNILU3429 | Skylight | \$ 1040.00 | 10 | 01-01-1984 | -31.2 years | 66.50% | Good | Retain | N/A |
| | LNILU3430 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 116.65% | Good | Retain | N/A |
| | LNILU3431 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-2010 | 5.3 years | 5.25% | Good | Retain | N/A |
| | LNILU3432 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comn |
| | LNILU3414 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3415 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU3416 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3417 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU3418 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comn |
| | LNILU3419 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3420 | Carpet | \$ 743.00 | 8 | 01-01-1984 | -33.2 years | 20.78% | Good | Retain | N/A |
| | LNILU3421 | Interior Painting | \$ 605.00 | 10 | 01-03-2009 | -6.1 years | 11.39% | Good | Retain | N/A |
| | LNILU3422 | Wardrobe | \$ 2115.00 | 10 | 01-04-2021 | 6.0 years | 0.87% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comn |
| | LNILU3443 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU3444 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| | LNILU3445 | Ceiling Fan | \$ 605.00 | 10 | 01-05-2014 | -0.9 years | 7.01% | Good | Retain | N/A |
| | LNILU3446 | Interior Painting | \$ 514.00 | 10 | 01-01-1989 | -26.2 years | 28.89% | Good | Retain | N/A |

| Ha | llway |
|----|-------|
| | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
|---------------------|----------------------------------------------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------|-------------------------------|------------------------------------------------------|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------------|----------------------------------|----------------------|
| | LNILU3447 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU3448 | Interior Painting | \$ 285.00 | 10 | 01-03-2019 | 3.9 years | 2.63% | Good | Retain | N/A |
| Kitchen | | <u>'</u> | | | | | | | | <u> </u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3405 | Blind | \$ 285.00 | 10 | 01-12-2021 | 6.7 years | 0.88% | Good | Retain | N/A |
| | LNILU3406 | Benchtops | \$ 2414.00 | 20 | 01-02-2003 | -2.1 years | 4.16% | Good | Retain | N/A |
| | LNILU3407 | Cooktop | \$ 1394.00 | 12 | 01-03-2019 | 5.9 years | 2.19% | Good | Retain | N/A |
| | LNILU3408 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU3409 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-03-2019 | 13.9 years | 1.31% | Good | Retain | N/A |
| | LNILU3410 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 87.54% | Good | Retain | N/A |
| | LNILU3412 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 14.59% | Good | Retain | N/A |
| | LNILU3413 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
| | LNILU4719 | Oven | \$ 1494.00 | 12 | 20-07-2023 | 10.3 years | 0.00% | Good | Retain | N/A |
| Laundry | | · | | | | | | | | <u> </u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3423 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU3424 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | | | ' | | | | | | | |
| | LNILU3425 | Tiles - Floor | \$ 2086.00 | 20 | 01-01-1989 | -16.2 years | 14.44% | Good | Retain | N/A |
| Living | LNILU3425 | | | 20 | 01-01-1989 | -16.2 years | | Good | Retain | N/A |
| Living | Asset Number | | | Effective Life (Y) | 01-01-1989 Installation Date | -16.2 years Remaining Effective Life | | Good Asset Condition | Retain | |
| Living | | Tiles - Floor | \$ 2086.00 | | | | 14.44% | | | |
| Living | Asset Number | Asset Name Air Conditioner | \$ 2086.00 Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| Living | Asset Number | Asset Name Air Conditioner - Split System | \$ 2086.00 Acquisition Cost (\$) \$ 3395.00 | Effective Life (Y) | Installation Date 01-02-2008 | Remaining Effective Life -7.1 years | Accumulated Repair Cost as % of Acquisition 110.23% | Asset Condition Good | Plan Retain | Commen N/A |
| Living | Asset Number LNILU3438 LNILU3439 | Asset Name Air Conditioner - Split System Blind | \$ 2086.00 Acquisition Cost (\$) \$ 3395.00 \$ 400.00 | Effective Life (Y) 10 | 1nstallation Date 01-02-2008 01-08-2005 | Remaining Effective Life -7.1 years -9.6 years -34.7 years | Accumulated Repair Cost as % of Acquisition 110.23% 14.88% | Asset Condition Good Good | Plan Retain Retain | Commen N/A N/A |
| Living | Asset Number LNILU3438 LNILU3439 LNILU3440 | Asset Name Air Conditioner - Split System Blind Carpet | \$ 2086.00 Acquisition Cost (\$) \$ 3395.00 \$ 400.00 \$ 1371.00 | Effective Life (Y) 10 10 8 | 01-02-2008 01-08-2005 01-07-1982 | Remaining Effective Life -7.1 years -9.6 years -34.7 years | Accumulated Repair Cost as % of Acquisition 110.23% 14.88% 21.88% | Asset Condition Good Good Good | Plan Retain Retain Retain | N/A N/A N/A |
| Living Toilet room | Asset Number LNILU3438 LNILU3439 LNILU3440 LNILU3441 LNILU3442 | Asset Name Air Conditioner - Split System Blind Carpet Ceiling Fan | \$ 2086.00 Acquisition Cost (\$) \$ 3395.00 \$ 400.00 \$ 1371.00 \$ 605.00 | 10 10 8 10 | 01-02-2008 01-08-2005 01-07-1982 01-07-1982 | Remaining Effective Life -7.1 years -9.6 years -34.7 years -32.7 years | 14.44% Accumulated Repair Cost as % of Acquisition 110.23% 14.88% 21.88% 35.04% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | N/A N/A N/A N/A |
| - | Asset Number LNILU3438 LNILU3439 LNILU3440 LNILU3441 LNILU3442 | Asset Name Air Conditioner - Split System Blind Carpet Ceiling Fan | \$ 2086.00 Acquisition Cost (\$) \$ 3395.00 \$ 400.00 \$ 1371.00 \$ 605.00 | 10 10 8 10 | 01-02-2008 01-08-2005 01-07-1982 01-07-1982 | Remaining Effective Life -7.1 years -9.6 years -34.7 years -32.7 years | 14.44% Accumulated Repair Cost as % of Acquisition 110.23% 14.88% 21.88% 35.04% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | N/A N/A N/A N/A |

| LNILU3434 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
|-----------|------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU3435 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3436 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3437 | Tapware | \$ 251.00 | 15 | 01-03-2019 | 8.9 years | 8.76% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------------------------------------------------------------------------------------------------|
| LNILU3449 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 28.89% | Good | Retain | Clothesline restrung |
| LNILU3450 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| LNILU3451 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 151.19% | Good | Retain | N/A |
| LNILU3452 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared between unit 49/50 |
| LNILU3453 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 16.62% | Good | Retain | N/A |
| LNILU3455 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU3457 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3458 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3459 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3460 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3461 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3462 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| LNILU3463 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 4.16% | Good | Retain | N/A |
| LNILU3464 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4213 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.29% | Good | Repair | Balcony awning has already been placed for orderBalcony awnings replaced B1 and Kitchen to be replaced |
| LNILU4720 | Fascias | \$ 1825.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4721 | Guttering | \$ 1825.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

| UNIL 13465 Root S 2749500 S 0 O 1 0 7 1982 7.3 years S 499% Good Retain N/A | Common | | | • | | | | | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|---------------------------------------------------------------------------------------------|----------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------|------------------------------|------|------|
| National | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com | | |
| Asset Number Asset Name Acquisition Cost (S) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition N/A | | LNILU3465 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A | | |
| LNILU3466 Insulation S 322400 20 01-07-1982 -22.7 years 0.00% Good Retain N/A | Unit 51 | | | | | | | | | | | | |
| LNILU3467 Lighting \$ 1966.00 15 01-07-1992 -277 years 23.33% Good Retain N/A | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com | | |
| UNIU3469 Sarking Saskan | | LNILU3466 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A | | |
| Unit 52 | | LNILU3467 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A | | |
| Note Asset Number Asset Name Acquisition Cost (5) Effective Life (7) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Communication Plan Communication Plan Pl | | LNILU3468 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A | | |
| Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com | | LNILU3469 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A | | |
| LNILU3530 Insulation S 322400 20 01-07-1982 -22.7 years 0.00% Good Retain N/A | Unit 52 | | | | | | | | | | | | |
| Li L | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Com | | |
| LINILU3532 Sarking \$ 3384.00 25 01-07-1982 -17.7 years 22.74% Good Retain N/A | | LNILU3530 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A | | |
| Entiron Saset Number Saset Name \$268.00 20 01-07-1982 -22.7 years 17.54% Good Retain N/A | | LNILU3531 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A | | |
| Asset Number Asset Name Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Communication C | | LNILU3532 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 22.74% | Good | Retain | N/A | | |
| Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com LNILU3491 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 35.11% Good Retain N/A LNILU3492 Interior Painting \$ 228.00 10 01-07-1982 -22.7 years 0.0 years 33.33% Good Retain N/A LNILU3493 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 0.04% Good Retain N/A LNILU3494 Skylight \$ 1040.00 10 01-07-1982 -32.7 years 70.00% Good Retain N/A LNILU3495 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 116.65% Good Retain N/A LNILU3496 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 14.43% Good Retain N/A <td <="" rowspan="4" td=""><td></td><td>LNILU3533</td><td>Smoke Alarms</td><td>\$ 268.00</td><td>20</td><td>01-07-1982</td><td>-22.7 years</td><td>17.54%</td><td>Good</td><td>Retain</td><td>N/A</td></td> | <td></td> <td>LNILU3533</td> <td>Smoke Alarms</td> <td>\$ 268.00</td> <td>20</td> <td>01-07-1982</td> <td>-22.7 years</td> <td>17.54%</td> <td>Good</td> <td>Retain</td> <td>N/A</td> | | LNILU3533 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A | |
| Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com LNILU3491 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 35.11% Good Retain N/A LNILU3492 Interior Painting \$ 228.00 10 01-07-1982 -22.7 years 0.0 years 33.33% Good Retain N/A LNILU3493 Shower Screen \$ 1200.00 20 01-07-1982 -22.7 years 0.04% Good Retain N/A LNILU3494 Skylight \$ 1040.00 10 01-07-1982 -32.7 years 70.00% Good Retain N/A LNILU3495 Tapware \$ 1343.00 15 01-07-1982 -22.7 years 116.65% Good Retain N/A LNILU3496 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 14.43% Good Retain N/A <td <="" rowspan="4" td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td> | | <td></td> | | | | | | | | | | | |
| LNILU3491 Exhaust Fan \$ 262.00 10 01-07-1982 -32.7 years 35.11% Good Retain N/A | | | Bathroom | | | | | | | | | | |
| LNILU3492 Interior Painting \$228.00 10 01-04-2015 0.0 years 33.33% Good Retain N/A | | | | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comi |
| LNILU3493 Shower Screen \$1200.00 20 01-07-1982 -22.7 years 0.44% Good Retain N/A | | | LNILU3491 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | NI/A | |
| LNILU3494 Skylight \$1040.00 10 01-07-1982 -32.7 years 70.00% Good Retain N/A | | | | | | | , | | | | 14/7 | | |
| LNILU3495 Tapware | | LNILU3492 | Interior Painting | \$ 228.00 | 10 | 01-04-2015 | • | | Good | | | | |
| LNILU3496 Tiles - Wall \$ 3384.00 20 01-07-1982 -22.7 years 14.43% Good Retain N/A LNILU3497 Tiles - Floor \$ 4058.00 20 01-07-1982 -22.7 years 4.37% Good Retain N/A Bed 1 Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com LNILU3479 Blind \$ 342.00 10 01-07-1982 -32.7 years 35.09% Good Retain N/A | | | 3 | | | | 0.0 years | 33.33% | | Retain | N/A | | |
| Bed 1 Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date NILU3479 Blind \$342.00 Blind \$342.00 10-07-1982 -32.7 years 4.379 Good Retain N/A Communication Cost (\$) Effective Life (Y) One-of-1982 One-of-19 | | LNILU3493 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | 0.0 years -22.7 years | 33.33% 0.44% | Good | Retain Retain | N/A N/A | | |
| Bed 1 Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com LNILU3479 Blind \$342.00 10 01-07-1982 -32.7 years 35.09% Good Retain N/A | | LNILU3493 LNILU3494 | Shower Screen Skylight | \$ 1200.00 \$ 1040.00 | 20 10 | 01-07-1982 01-07-1982 | 0.0 years -22.7 years -32.7 years | 33.33% 0.44% 70.00% | Good Good | Retain Retain Retain | N/A N/A N/A | | |
| Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition Plan Com LNILU3479 Blind \$342.00 10 01-07-1982 -32.7 years 35.09% Good Retain N/A | | LNILU3493 LNILU3494 LNILU3495 | Shower Screen Skylight Tapware | \$ 1200.00 \$ 1040.00 \$ 1343.00 | 20 10 15 | 01-07-1982 01-07-1982 01-07-1982 | 0.0 years -22.7 years -32.7 years -27.7 years | 33.33% 0.44% 70.00% 116.65% | Good Good | Retain Retain Retain Retain | N/A N/A N/A N/A | | |
| LNILU3479 Blind \$342.00 10 01-07-1982 -32.7 years 35.09% Good Retain N/A | | LNILU3493 LNILU3494 LNILU3495 LNILU3496 | Shower Screen Skylight Tapware Tiles - Wall | \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | 20 10 15 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | 0.0 years -22.7 years -32.7 years -27.7 years -22.7 years | 33.33% 0.44% 70.00% 116.65% 14.43% | Good Good Good | Retain Retain Retain Retain Retain | N/A N/A N/A N/A | | |
| | Bed 1 | LNILU3493 LNILU3494 LNILU3495 LNILU3496 | Shower Screen Skylight Tapware Tiles - Wall | \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 | 20 10 15 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | 0.0 years -22.7 years -32.7 years -27.7 years -22.7 years | 33.33% 0.44% 70.00% 116.65% 14.43% | Good Good Good | Retain Retain Retain Retain Retain | N/A N/A N/A N/A | | |
| LNILU3480 Carpet \$891.00 8 01-04-2015 -2.0 years 21.89% Good Retain N/A | Bed 1 | LNILU3493 LNILU3494 LNILU3495 LNILU3496 LNILU3497 | Shower Screen Skylight Tapware Tiles - Wall Tiles - Floor | \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 \$ 4058.00 | 20 10 15 20 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 | 0.0 years -22.7 years -32.7 years -27.7 years -22.7 years -22.7 years -22.7 years | 33.33% 0.44% 70.00% 116.65% 14.43% 4.37% | Good Good Good Good | Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A | | |
| | Bed 1 | LNILU3493 LNILU3494 LNILU3495 LNILU3496 LNILU3497 Asset Number | Shower Screen Skylight Tapware Tiles - Wall Tiles - Floor Asset Name | \$ 1200.00 \$ 1040.00 \$ 1343.00 \$ 3384.00 \$ 4058.00 Acquisition Cost (\$) | 20 10 15 20 20 | 01-07-1982 01-07-1982 01-07-1982 01-07-1982 01-07-1982 Installation Date | 0.0 years -22.7 years -32.7 years -27.7 years -22.7 years -22.7 years -22.7 years -Example 1.00 Remaining Effective Life | 33.33% 0.44% 70.00% 116.65% 14.43% 4.37% Accumulated Repair Cost as % of Acquisition | Good Good Good Good Asset Condition | Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A Comm | | |

01-07-1982 -32.7 years

N/A

Retain

33.29% Good

10

\$ 605.00

LNILU3481

Ceiling Fan

| | LNILU3482 | Interior Painting | \$ 726.00 | 10 | 01-04-2015 | 0.0 years | 34.99% | Good | Retain | N/A |
|-----|---------------------------------------------------------------|------------------------------------------------------------|-------------------------------------------------------------------|----------------------|--------------------------------------------------------------------|---------------------------------------------------------|---------------------------------------------|------------------------------|--------------------------------------|---------------------------------------------|
| | LNILU3483 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 28.87% | Good | Retain | N/A |
| 12 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3484 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3485 | Carpet | \$ 743.00 | 8 | 01-04-2015 | -2.0 years | 0.55% | Good | Retain | N/A |
| | LNILU3486 | Interior Painting | \$ 605.00 | 10 | 01-04-2015 | 0.0 years | 35.04% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3508 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU3509 | Carpet | \$ 640.00 | 8 | 01-04-2015 | -2.0 years | 18.05% | Good | Retain | N/A |
| | LNILU3510 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3511 | Interior Painting | \$ 514.00 | 10 | 01-04-2015 | 0.0 years | 35.02% | Good | Retain | N/A |
| way | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3512 | Carpet | \$ 354.00 | 8 | 01-04-2015 | -2.0 years | 18.06% | Good | Retain | N/A |
| | LNILU3513 | Interior Painting | \$ 285.00 | 10 | 01-04-2015 | 0.0 years | 35.09% | Good | Retain | N/A |
| hen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | | Replace moul |
| | LNILU3470 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Fair | Repair | |
| | LNILU3470 LNILU3471 | Blind Benchtops | \$ 285.00 \$ 2414.00 | 10 | 01-07-1982 01-07-1982 | -32.7 years -22.7 years | 2.63% 8.75% | Fair Good | Repair Retain | |
| | | | · | | | , | | | · | vertical blinds |
| | LNILU3471 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | vertical blinds |
| | LNILU3471 LNILU3472 | Benchtops Cooktop | \$ 2414.00 \$ 1394.00 | 20 12 | 01-07-1982 01-07-1982 | -22.7 years -30.7 years | 8.75% 0.73% | Good Good | Retain Retain | vertical blinds N/A N/A |
| | LNILU3471 LNILU3472 LNILU3473 | Benchtops Cooktop Interior Painting Kitchen | \$ 2414.00 \$ 1394.00 \$ 434.00 | 20 12 10 | 01-07-1982 01-07-1982 01-04-2015 | -22.7 years -30.7 years 0.0 years | 8.75% 0.73% 35.02% | Good Good | Retain Retain Retain | vertical blinds N/A N/A N/A |
| | LNILU3471 LNILU3472 LNILU3473 LNILU3474 | Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | 20 12 10 20 | 01-07-1982 01-07-1982 01-04-2015 01-07-1982 | -22.7 years -30.7 years 0.0 years -22.7 years | 8.75% 0.73% 35.02% 14.44% | Good Good Good | Retain Retain Retain Retain | vertical blinds N/A N/A N/A N/A N/A |
| | LNILU3471 LNILU3472 LNILU3473 LNILU3474 LNILU3475 | Benchtops Cooktop Interior Painting Kitchen Cabinets Vinyl | \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 \$ 1011.00 | 20 12 10 20 | 01-07-1982 01-07-1982 01-04-2015 01-07-1982 01-04-2015 | -22.7 years -30.7 years 0.0 years -22.7 years 0.0 years | 8.75% 0.73% 35.02% 14.44% 6.57% | Good Good Good Good | Retain Retain Retain Retain Retain | vertical blinds N/A N/A N/A N/A N/A N/A N/A |

| Laundry |
|---------|
|---------|

| aundry | | | | | | | | | | |
|--------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3488 | Interior Painting | \$ 257.00 | 10 | 01-04-2015 | 0.0 years | 35.02% | Good | Retain | N/A |
| | LNILU3489 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU3490 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU4548 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4549 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgraded to 1/4 turn |
| | LNILU4550 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ng | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3503 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 23.62% | Good | Retain | N/A |
| | LNILU3504 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| | | | | | | | | | | |

01-04-2015 -2.0 years

01-07-1982 -32.7 years

01-04-2015 0.0 years

10

10

Toilet room

LNILU3505

LNILU3506

LNILU3507

Carpet

Ceiling Fan

Interior Painting

\$ 1371.00

\$ 605.00

\$ 1097.00

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|------------------|-----------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|--------|-------------------------------------------------|
| LNILU3498 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3499 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 39.37% | Good | Retain | N/A |
| LNILU3500 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU3501 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3502 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | Replace mixer and waste plug and re grout basin |
| LNILU4551 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

18.05% Good

15.77% Good

35.00% Good

Retain

Retain

Retain

N/A

N/A

N/A

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU3514 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 12.26% | Good | Retain | N/A |
| LNILU3515 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 0.29% | Fair | Retain | N/A |
| LNILU3516 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 126.80% | Good | Retain | N/A |

| LNILU3517 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 2.19% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|-----------|--------|-----|
| LNILU3518 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 14.43% | Good | Retain | N/A |
| LNILU3520 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU3522 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3523 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 14.92% | Good | Retain | N/A |
| LNILU3524 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 2.77% | Good | Retain | N/A |
| LNILU3525 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3526 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Fair | Retain | N/A |
| LNILU3527 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3528 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3529 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4214 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 1.03% | Very Poor | Repair | N/A |
| LNILU4722 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4723 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 52

| R | 21 | ·h | ro | _ | m |
|---|----|----|----|---|---|
| _ | 01 | | ıu | u | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-----------------------------------------------------|
| LNILU3555 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNILU3556 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU3557 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3558 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 1.75% | Good | Retain | Flashing appears to have fallen onto skylight |
| LNILU3559 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 116.65% | Good | Retain | N/A |
| LNILU3560 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3561 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 7.44% | Fair | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3543 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |

| | LNILU3544 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| | LNILU3545 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 11.39% | Good | Retain | N/A |
| | LNILU3546 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU3547 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 14.87% | Good | Retain | N/A |
| | LNILU4552 | Curtains | \$ 914.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3548 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3549 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU3550 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 7.01% | Good | Retain | N/A |
| | LNILU4553 | Ceiling Fan | \$ 605.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4554 | Curtains | \$ 914.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ning | | ' | | | | | | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3572 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 3.50% | Good | Retain | N/A |
| | LNILU3573 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| | LNILU3574 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3575 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU4561 | Curtains | \$ 914.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| llway | | | , | | , | | | | | <u> </u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3576 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU3577 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| chen | | ' | , | | , | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3534 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 11.40% | Good | Retain | N/A |
| | LNILU3535 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| | LNILU3536 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 29.17% | Good | Retain | N/A |
| | LNILU3537 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU3538 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

| | LNILU3539 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 87.54% | Good | Retain | N/A |
|---|---------------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|--------------------------|
| | LNILU3540 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 301.11% | Good | Retain | N/A |
| | LNILU3541 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 6.56% | Good | Retain | N/A |
| | LNILU3542 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 40.84% | Good | Retain | N/A |
| у | | | | | | | | | | |
| ' | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3552 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU3553 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU3554 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Fair | Repair | Clean and reg |
| | LNILU4555 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4556 | Dryer | \$ 628.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4557 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | Mixer upgrad 1/4 turn |
| | LNILU4558 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | | | | | | | | | | • |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3567 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 299.19% | Good | Retain | N/A |
| | LNILU3568 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 3.50% | Good | Retain | N/A |
| | LNILU3569 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 18.05% | Good | Retain | N/A |
| | LNILU3570 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 125.95% | Good | Retain | N/A |
| | LNILU3571 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | | | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3562 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 1.75% | Good | Retain | N/A |
| LNILU3563 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 122.20% | Good | Retain | N/A |
| LNILU3564 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 7.44% | Good | Retain | N/A |
| LNILU3565 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3566 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 32.14% | Fair | Retain | N/A |

| LNILU4559 Exhaust Fan \$ 262.00 1 | 0 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
|-----------------------------------|--------------|-----------|-------|------|--------|-----|
|-----------------------------------|--------------|-----------|-------|------|--------|-----|

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------------------------|
| LNILU3578 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU3579 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3580 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 129.81% | Good | Retain | N/A |
| LNILU3581 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 72.18% | Good | Retain | Shared between unit 51/52 |
| LNILU3582 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 14.43% | Good | Retain | N/A |
| LNILU3584 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3586 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3587 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU3588 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3589 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU3590 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3591 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 0.29% | Good | Retain | N/A |
| LNILU3592 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3593 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 2.62% | Good | Retain | N/A |
| LNILU4215 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Poor | Repair | Kitchen awning shredded |
| LNILU4724 | Fascias | \$ 1733.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4725 | Guttering | \$ 1733.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 53-54

| Co | m | m | on |
|----|---|---|----|
| | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3594 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 13.12% | Good | Retain | N/A |

| | | • • | |
|---|---|-----|----------|
| | n | ıt | . |
| · | | ıı | . |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|--------------------------------------------------------------|
| LNILU3595 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU3596 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | Living Room light globe is blownNew lighting installed |
| LNILU3597 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| LNILU3598 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

Unit 54

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3660 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU3661 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| LNILU3662 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| LNILU3663 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |

Unit 53

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------------------------------------|
| LNILU3621 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNILU3622 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 16.67% | Good | Retain | N/A |
| LNILU3623 | Shower Screen | \$ 1200.00 | 20 | 01-07-1982 | -22.7 years | 7.88% | Fair | Repair | Remove mould and rust |
| LNILU3625 | Tapware | \$ 1343.00 | 15 | 01-07-1982 | -27.7 years | 96.24% | Fair | Retain | Sink blocking on numerous occasions |
| LNILU3626 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Fair | Repair | Requires cleaning and regroutingClean and regrout |
| LNILU3627 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 20.79% | Poor | Repair | Clean and regrout |
| LNILU4564 | Skylight | \$ 811.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3609 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| LNILU3610 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| LNILU3611 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 11.37% | Good | Retain | N/A |

| | LNILU3612 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|------------|
| | LNILU4230 | Shutters | \$ 3429.00 | 10 | 28-01-2010 | -5.1 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | · | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3613 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3614 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 10.39% | Good | Retain | N/A |
| | LNILU3615 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 16.64% | Good | Retain | N/A |
| | LNILU3616 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 0.88% | Good | Retain | N/A |
| ning | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3638 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU3639 | Carpet | \$ 640.00 | 8 | 01-07-1982 | -34.7 years | 0.55% | Good | Retain | N/A |
| | LNILU3640 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 11.39% | Good | Retain | N/A |
| | LNILU3641 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| llway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3642 | Carpet | \$ 354.00 | 8 | 01-07-1982 | -34.7 years | 7.12% | Good | Retain | N/A |
| | LNILU3643 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU4568 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| tchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3599 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| | LNILU3600 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| | LNILU3601 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 2.19% | Good | Retain | N/A |
| | LNILU3602 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU3603 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU3604 | Vinyl | \$ 1011.00 | 10 | 01-07-1982 | -32.7 years | 87.54% | Fair | Retain | N/A |
| | LNILU3605 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| | LNILU3606 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 6.93% | Good | Retain | N/A |
| | LNILU3607 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 49.59% | Good | Retain | Renew sink |

| Laundry |
|---------|
|---------|

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------|
| LNILU3618 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU3619 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 14.43% | Good | Retain | N/A |
| LNILU3620 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 14.44% | Fair | Retain | N/A |
| LNILU4562 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | Upgrade to 1/4 turn |
| LNILU4563 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3634 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| LNILU3635 | Carpet | \$ 1371.00 | 8 | 01-07-1982 | -34.7 years | 21.88% | Good | Retain | N/A |
| LNILU3636 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 33.29% | Good | Retain | N/A |
| LNILU3637 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 2.63% | Good | Retain | N/A |
| LNILU4567 | Air Conditioner - Split System | \$ 3395.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU3629 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3630 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 7.87% | Good | Retain | N/A |
| LNILU3631 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Fair | Retain | N/A |
| LNILU3632 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 116.86% | Good | Retain | N/A |
| LNILU4565 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4566 | Skylight | \$ 811.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|---------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|---------------------------|
| LNILU3644 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 10.51% | Good | Retain | N/A |
| LNILU3645 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Fair | Retain | N/A |
| LNILU3646 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 135.94% | Good | Retain | N/A |
| LNILU3647 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared between unit 53/54 |

| LNILU3648 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Fair | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|--------------------------------------|
| LNILU3650 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3652 | Hot Water System - Solar | \$ 4516.00 | 15 | 16-09-2018 | 8.5 years | 0.00% | Good | Retain | N/A |
| LNILU3654 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3655 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Fair | Retain | N/A |
| LNILU3656 | Water Tank | \$ 1063.00 | 25 | 16-09-2016 | 16.5 years | 0.00% | Good | Retain | N/A |
| LNILU3657 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3658 | Balustrade | \$ 1943.00 | 20 | 16-09-2021 | 16.5 years | 0.00% | Good | Retain | N/A |
| LNILU3659 | Balcony Flooring | \$ 3681.00 | 20 | 16-09-2021 | 16.5 years | 0.00% | Good | Retain | Minor tile crack continue to monitor |
| LNILU4216 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 6.29% | Good | Retain | N/A |
| LNILU4726 | Fascias | \$ 1733.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4727 | Guttering | \$ 1733.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 54

| _ | | - 1 | | | | |
|---|---|-----|---|----|--------|---|
| ĸ | 2 | • | h | re | \sim | m |
| | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3686 | Interior Painting | \$ 228.00 | 10 | 01-12-2017 | 2.7 years | 15.79% | Excellent | Retain | N/A |
| LNILU4920 | Exhaust Fan | \$ 262.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4921 | Shower Screen | \$ 1200.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4922 | Skylight | \$ 1040.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4923 | Tapware | \$ 1343.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4924 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4925 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3676 | Interior Painting | \$ 726.00 | 10 | 01-12-2017 | 2.7 years | 28.86% | Excellent | Retain | N/A |
| LNILU4926 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4927 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4928 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4929 | Wardrobe | \$ 2115.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

| Red | 2 |
|-----|---|
| | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------|---------------------------------------------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------------------|--------------------------------------------------------------------|------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------------------------------|--------------------------------------------------|--------------------------|
| | LNILU3680 | Interior Painting | \$ 605.00 | 10 | 01-12-2017 | 2.7 years | 35.04% | Excellent | Retain | N/A |
| | LNILU4930 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4931 | Carpet | \$ 891.00 | 8 | 09-01-2024 | 6.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4932 | Wardrobe | \$ 2115.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| ining | | | · | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3705 | Interior Painting | \$ 514.00 | 10 | 01-12-2017 | 2.7 years | 35.02% | Excellent | Retain | N/A |
| | LNILU4933 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4934 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4935 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| llway | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3707 | Interior Painting | \$ 285.00 | 10 | 01-12-2017 | 2.7 years | 14.91% | Good | Retain | N/A |
| chen | | | | | | | | | | <u> </u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3667 | Interior Painting | \$ 434.00 | 10 | 01-12-2017 | 2.7 years | 35.02% | Excellent | Retain | N/A |
| | LNILU4936 | Benchtops | \$ 2414.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| | | | | | | | | | | |
| | LNILU4937 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4937 LNILU4938 | Blind Cooktop | \$ 342.00 \$ 1394.00 | 10 | 09-01-2024 09-01-2024 | 8.8 years 10.8 years | 0.00% | Excellent Excellent | Retain Retain | N/A N/A |
| | | | | | | | | | | |
| | LNILU4938 | Cooktop Kitchen | \$ 1394.00 | 12 | 09-01-2024 | 10.8 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4938 LNILU4939 | Cooktop Kitchen Cabinets | \$ 1394.00 \$ 3932.00 | 12 20 | 09-01-2024 09-01-2024 | 10.8 years 18.8 years | 0.00% | Excellent Excellent | Retain Retain | N/A N/A |
| | LNILU4938 LNILU4939 LNILU4940 | Cooktop Kitchen Cabinets Oven | \$ 1394.00 \$ 3932.00 \$ 1451.00 | 12 20 12 | 09-01-2024 09-01-2024 09-01-2024 | 10.8 years 18.8 years 10.8 years | 0.00% 0.00% 0.00% | Excellent Excellent Excellent | Retain Retain Retain | N/A N/A N/A |
| | LNILU4938 LNILU4939 LNILU4940 LNILU4941 | Cooktop Kitchen Cabinets Oven Rangehood | \$ 1394.00 \$ 3932.00 \$ 1451.00 \$ 617.00 | 12 20 12 12 | 09-01-2024 09-01-2024 09-01-2024 09-01-2024 | 10.8 years 18.8 years 10.8 years 10.8 years | 0.00% 0.00% 0.00% 0.00% | Excellent Excellent Excellent Excellent | Retain Retain Retain Retain | N/A N/A N/A N/A |
| undry | LNILU4938 LNILU4939 LNILU4940 LNILU4941 LNILU4942 | Cooktop Kitchen Cabinets Oven Rangehood Sink & Fittings | \$ 1394.00 \$ 3932.00 \$ 1451.00 \$ 617.00 \$ 1634.00 | 12 20 12 12 15 | 09-01-2024 09-01-2024 09-01-2024 09-01-2024 | 10.8 years 10.8 years 10.8 years 10.8 years 13.8 years | 0.00% 0.00% 0.00% 0.00% 0.00% | Excellent Excellent Excellent Excellent Excellent | Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| ındry | LNILU4938 LNILU4939 LNILU4940 LNILU4941 LNILU4942 | Cooktop Kitchen Cabinets Oven Rangehood Sink & Fittings | \$ 1394.00 \$ 3932.00 \$ 1451.00 \$ 617.00 \$ 1634.00 | 12 20 12 12 15 | 09-01-2024 09-01-2024 09-01-2024 09-01-2024 | 10.8 years 10.8 years 10.8 years 10.8 years 13.8 years | 0.00% 0.00% 0.00% 0.00% 0.00% | Excellent Excellent Excellent Excellent Excellent | Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| undry | LNILU4938 LNILU4939 LNILU4940 LNILU4941 LNILU4942 LNILU4943 | Cooktop Kitchen Cabinets Oven Rangehood Sink & Fittings Vinyl | \$ 1394.00 \$ 3932.00 \$ 1451.00 \$ 617.00 \$ 1634.00 \$ 1011.00 | 12 20 12 12 15 10 | 09-01-2024 09-01-2024 09-01-2024 09-01-2024 09-01-2024 | 10.8 years 18.8 years 10.8 years 10.8 years 13.8 years 8.8 years | 0.00% 0.00% 0.00% 0.00% 0.00% | Excellent Excellent Excellent Excellent Excellent Excellent Excellent | Retain Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A |

| LNILU4945 | Tiles - Wall | \$ 3384.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
|-----------|-----------------|------------|----|------------|------------|-------|-----------|--------|-----|
| LNILU4946 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4947 | Sink & Fittings | \$ 1634.00 | 15 | 09-01-2024 | 13.8 years | 0.00% | Excellent | Retain | N/A |

Living

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU3701 | Interior Painting | \$ 1097.00 | 10 | 01-12-2017 | 2.7 years | 35.00% | Excellent | Retain | N/A |
| LNILU4948 | Vinyl | \$ 1011.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4949 | Air Conditioner - Split System | \$ 3395.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4950 | Blind | \$ 342.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4951 | Ceiling Fan | \$ 605.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4952 | Curtains | \$ 914.00 | 6 | 09-01-2024 | 4.8 years | 0.00% | Excellent | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3692 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 5.25% | Good | Retain | N/A |
| LNILU4953 | Tiles - Floor | \$ 4058.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4954 | Toilet & Cistern | \$ 1383.00 | 20 | 09-01-2024 | 18.8 years | 0.00% | Excellent | Retain | N/A |
| LNILU4955 | Exhaust Fan | \$ 262.00 | 10 | 09-01-2024 | 8.8 years | 0.00% | Excellent | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|---------------------------|
| LNILU3708 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU3709 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 9.62% | Good | Retain | N/A |
| LNILU3710 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |
| LNILU3711 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 6.56% | Good | Retain | Shared between unit 53/54 |
| LNILU3712 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU3714 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 57.75% | Good | Retain | N/A |
| LNILU3716 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3717 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU3718 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 4.81% | Good | Retain | N/A |

| LNILU3719 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 1.46% | Good | Retain | N/A |
|-----------|---------------------|------------|----|------------|-------------|--------|-----------|--------|-----|
| LNILU3720 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 11.37% | Fair | Retain | N/A |
| LNILU3721 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 3.50% | Good | Retain | N/A |
| LNILU3722 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 7.22% | Good | Retain | N/A |
| LNILU3723 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4217 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.23% | Good | Retain | N/A |
| LNILU4728 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4729 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 55

Unit 55

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3724 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 9.62% | Good | Retain | N/A |
| LNILU3725 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU3726 | Lighting | \$ 1966.00 | 15 | 01-07-2020 | 10.3 years | 0.00% | Good | Retain | |
| LNILU3727 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| LNILU3728 | Smoke Alarms | \$ 268.00 | 20 | 01-07-2020 | 15.3 years | 17.54% | Good | Retain | N/A |

Unit 55

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------------|
| LNILU3750 | Exhaust Fan | \$ 262.00 | 10 | 01-07-2020 | 5.3 years | 2.63% | Good | Retain | N/A |
| LNILU3751 | Interior Painting | \$ 228.00 | 10 | 01-07-2020 | 5.3 years | 28.95% | Good | Retain | N/A |
| LNILU3752 | Shower Screen | \$ 1200.00 | 20 | 01-07-2020 | 15.3 years | 17.50% | Fair | Retain | New silicone required |
| LNILU3754 | Tapware | \$ 1343.00 | 15 | 01-07-2020 | 10.3 years | 116.65% | Good | Retain | N/A |
| LNILU3755 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-2020 | 15.3 years | 17.49% | Good | Repair | N/A |
| LNILU3756 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-2020 | 15.3 years | 17.50% | Fair | Repair | Clean mould from tiles and Regrout |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|------------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3738 | Blind | \$ 342.00 | 10 | 01-07-2020 | 5.3 years | 35.09% | Good | Retain | N/A |

| | LNILU3739 | Carpet | \$ 891.00 | 8 | 01-07-2020 | 3.3 years | 18.06% | Good | Retain | N/A |
|------|---------------------------------------------------------------------|----------------------------------------------------------------------------|------------------------------------------------------------------|------------------------------------|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------|------------------------------------------------|------------------------------|
| | LNILU3740 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2020 | 5.3 years | 35.04% | Good | Retain | N/A |
| | LNILU3741 | Interior Painting | \$ 726.00 | 10 | 01-07-2020 | 5.3 years | 3.50% | Good | Retain | N/A |
| | LNILU3742 | Wardrobe | \$ 2115.00 | 10 | 01-07-2020 | 5.3 years | 2.62% | Good | Retain | N/A |
| 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3743 | Blind | \$ 342.00 | 10 | 01-07-2020 | 5.3 years | 2.63% | Good | Retain | N/A |
| | LNILU3744 | Carpet | \$ 743.00 | 8 | 01-07-2020 | 3.3 years | 21.87% | Good | Retain | N/A |
| | LNILU3745 | Interior Painting | \$ 605.00 | 10 | 01-07-2020 | 5.3 years | 35.04% | Good | Retain | N/A |
| | LNILU3746 | Wardrobe | \$ 2115.00 | 10 | 01-07-2020 | 5.3 years | 34.99% | Good | Retain | N/A |
| ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3767 | Blind | \$ 400.00 | 10 | 01-07-2020 | 5.3 years | 14.88% | Good | Retain | N/A |
| | LNILU3768 | Carpet | \$ 640.00 | 8 | 01-07-2020 | 3.3 years | 8.20% | Good | Retain | N/A |
| | LNILU3769 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2020 | 5.3 years | 35.04% | Good | Retain | N/A |
| | LNILU3770 | Interior Painting | \$ 514.00 | 10 | 01-07-2020 | 5.3 years | 12.26% | Good | Retain | N/A |
| lway | | | , | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3771 | Carpet | \$ 354.00 | 8 | 01-07-2020 | 3.3 years | 9.31% | Good | Retain | N/A |
| | LNILU3772 | | ¢ 205.00 | 10 | | | 25.000/ | C 1 | 5 | N/A |
| | LINILUS//2 | Interior Painting | \$ 285.00 | 10 | 01-07-2020 | 5.3 years | 35.09% | Good | Retain | 14// (|
| hen | LINILUS//2 | Interior Painting | \$ 285.00 | 10 | 01-07-2020 | 5.3 years | 35.09% | Good | Retain | 14// |
| nen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| ien | | | | | | | | | | |
| nen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| nen | Asset Number | Asset Name | Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | Installation Date 01-07-2020 | Remaining Effective Life 5.3 years | Accumulated Repair Cost as % of Acquisition 2.63% | Asset Condition Good | Plan Retain | Comments N/A |
| nen | Asset Number LNILU3729 LNILU3730 | Asset Name Blind Benchtops | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 | Effective Life (Y) 10 20 | Installation Date 01-07-2020 01-07-2020 | Remaining Effective Life 5.3 years 15.3 years | Accumulated Repair Cost as % of Acquisition 2.63% 7.22% | Asset Condition Good Good | Plan Retain Retain | Comments N/A N/A |
| ien | Asset Number LNILU3729 LNILU3730 LNILU3731 | Asset Name Blind Benchtops Cooktop | Acquisition Cost (\$) \$ 285.00 \$ 2414.00 \$ 1394.00 | Effective Life (Y) 10 20 12 | 1nstallation Date 01-07-2020 01-07-2020 01-07-2020 | Remaining Effective Life 5.3 years 15.3 years 7.3 years 5.3 years | Accumulated Repair Cost as % of Acquisition 2.63% 7.22% 29.17% | Asset Condition Good Good Good | Plan Retain Retain Retain | Comments N/A N/A N/A |
| nen | Asset Number LNILU3729 LNILU3730 LNILU3731 LNILU3732 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 | Effective Life (Y) 10 20 12 10 | 1nstallation Date 01-07-2020 01-07-2020 01-07-2020 01-07-2020 | Remaining Effective Life 5.3 years 15.3 years 7.3 years 5.3 years | Accumulated Repair Cost as % of Acquisition 2.63% 7.22% 29.17% 35.02% | Asset Condition Good Good Good Good | Plan Retain Retain Retain Retain | Comments N/A N/A N/A N/A N/A |
| nen | Asset Number LNILU3729 LNILU3730 LNILU3731 LNILU3732 LNILU3733 | Asset Name Blind Benchtops Cooktop Interior Painting Kitchen Cabinets | \$ 285.00 \$ 2414.00 \$ 1394.00 \$ 434.00 \$ 3932.00 | Effective Life (Y) 10 20 12 10 20 | 01-07-2020 01-07-2020 01-07-2020 01-07-2020 01-07-2020 01-07-2020 | Remaining Effective Life 5.3 years 15.3 years 7.3 years 5.3 years 15.3 years 5.3 years | Accumulated Repair Cost as % of Acquisition 2.63% 7.22% 29.17% 35.02% 17.50% | Asset Condition Good Good Good Good Good | Plan Retain Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A N/A |

| | LNILU3737 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-2020 | 10.3 years | 29.17% | Good | Retain | N/A |
|------------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|------------------------------|
| undry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3747 | Interior Painting | \$ 257.00 | 10 | 01-07-2020 | 5.3 years | 7.00% | Good | Retain | N/A |
| | LNILU3748 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-2020 | 15.3 years | 17.50% | Good | Retain | N/A |
| | LNILU3749 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-2020 | 15.3 years | 17.50% | Fair | Repair | Clean and regro |
| | LNILU4578 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | Update to 1/4 tu |
| | LNILU4579 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ring | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3762 | Air Conditioner - Split System | \$ 3395.00 | 10 | 14-11-2021 | 6.7 years | 0.00% | Good | Retain | New A/C |
| | LNILU3763 | Blind | \$ 400.00 | 10 | 01-07-2020 | 5.3 years | 28.88% | Good | Retain | Vertical blind ha come apart |
| | LNILU3764 | Carpet | \$ 1371.00 | 8 | 01-07-2020 | 3.3 years | 20.79% | Good | Retain | N/A |
| | LNILU3765 | Ceiling Fan | \$ 605.00 | 10 | 01-07-2020 | 5.3 years | 35.04% | Good | Retain | N/A |
| | LNILU3766 | Interior Painting | \$ 1097.00 | 10 | 01-07-2020 | 5.3 years | 35.00% | Good | Retain | N/A |
| ilet room | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3757 | Skylight | \$ 1040.00 | 10 | 01-07-2020 | 5.3 years | 70.00% | Good | Retain | N/A |
| | LNILU3758 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-2020 | 15.3 years | 87.49% | Good | Retain | N/A |
| | LNILU3759 | Tiles - Wall | \$ 926.00 | 20 | 01-07-2020 | 15.3 years | 17.49% | Good | Retain | N/A |
| | LNILU3760 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-2020 | 15.3 years | 6.12% | Fair | Repair | N/A |
| | LNILU3761 | Tapware | \$ 251.00 | 15 | 01-07-2020 | 10.3 years | 116.86% | Good | Retain | N/A |
| | LNILU4580 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| it Exterio | , | ' | | | | | | | ' | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3773 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 28.89% | Good | Retain | N/A |
| | LNILU3774 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| | LNILU3775 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |

| LNILU3776 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 53/54 |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|-------------------------------------------------------------------------|
| LNILU3777 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 6.12% | Good | Retain | N/A |
| LNILU3779 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU3781 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 11.08% | Good | Retain | N/A |
| LNILU3782 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU3783 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3784 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 27.70% | Fair | Retain | N/A |
| LNILU3785 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3786 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3787 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 4.16% | Good | Retain | N/A |
| LNILU3788 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 3.06% | Good | Retain | Minor crack near living door entry to continue to be monitored |
| LNILU4218 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 4.12% | Good | Retain | N/A |
| LNILU4730 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| LNILU4731 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |

Unit 56-57

| Commo | n | | | | | | | | | |
|---------|------------------------|------------------------|--------------------------|--------------------|--------------------------|--------------------------|---------------------------------------------|------------------------|------------------|------------|
| ` | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3789 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 10.50% | Good | Retain | N/A |
| Unit 56 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | | | | | | | | | | |
| | LNILU3790 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3790 LNILU3791 | Insulation Lighting | \$ 3224.00 \$ 1966.00 | 20 15 | 01-07-1982 01-06-2016 | -22.7 years 6.2 years | 23.33% | Good | Retain Retain | N/A N/A |
| | | | | | | , | | | | |

| | • • | |
|---|-----|---|
| | nıt | - |
| • | | |

Unit 56

Asset Number

Asset Name

Acquisition Cost (\$) Effective Life (Y)

| | LNILU3854 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
|----------|--------------|-------------------|------------------------------------|--------------------|------------------------------|--------------------------|----------------------------------------------------|----------------------|-----------------------|-----------------|
| | LNILU3855 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU3856 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU3857 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 16.66% | Good | Retain | N/A |
| | | | | | | | | | | |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3815 | Exhaust Fan | \$ 262.00 | 10 | 01-06-2016 | 1.2 years | 35.11% | Good | Retain | N/A |
| | LNILU3816 | Interior Painting | \$ 228.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Good | Retain | N/A |
| | LNILU3817 | Shower Screen | \$ 1200.00 | 20 | 01-06-2016 | 11.2 years | 17.50% | Good | Retain | N/A |
| | LNILU3818 | Skylight | \$ 1040.00 | 10 | 01-06-2016 | 1.2 years | 70.00% | Good | Retain | N/A |
| | LNILU3819 | Tapware | \$ 1343.00 | 15 | 01-06-2016 | 6.2 years | 116.65% | Good | Retain | N/A |
| | LNILU3820 | Tiles - Wall | \$ 3384.00 | 20 | 01-06-2016 | 11.2 years | 16.62% | Good | Retain | N/A |
| | LNILU3821 | Tiles - Floor | \$ 4058.00 | 20 | 01-06-2016 | 11.2 years | 7.87% | Good | Retain | N/A |
| Bed 1 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3803 | Blind | \$ 342.00 | 10 | 01-06-2016 | 1.2 years | 16.67% | Good | Retain | N/A |
| | LNILU3804 | Carpet | \$ 891.00 | 8 | 01-06-2016 | -0.8 years | 7.66% | Good | Retain | N/A |
| | LNILU3805 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 3.50% | Good | Retain | N/A |
| | LNILU3806 | Interior Painting | \$ 726.00 | 10 | 01-06-2016 | 1.2 years | 2.62% | Good | Retain | N/A |
| | LNILU3807 | Wardrobe | \$ 2115.00 | 10 | 01-06-2016 | 1.2 years | 34.99% | Good | Retain | N/A |
| Bed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3808 | Blind | \$ 342.00 | 10 | 01-06-2016 | 1.2 years | 33.33% | Good | Retain | N/A |
| | LNILU3809 | Carpet | \$ 743.00 | 8 | 01-06-2016 | -0.8 years | 18.04% | Good | Retain | N/A |
| | LNILU3810 | Interior Painting | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 33.29% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number | Asset Name | Acquisition Cost (\$) \$ 400.00 | Effective Life (Y) | Installation Date 01-06-2016 | | Accumulated Repair Cost as % of Acquisition 16.63% | Asset Condition Good | Plan Retain | Comments N/A |

Remaining Effective Life

Installation Date

Accumulated Repair Cost as % of Acquisition

Asset Condition

Plan

Comments

| | LNILU3833 | Carpet | \$ 640.00 | 8 | 01-06-2016 | -0.8 years | 20.78% | Good | Retain | N/A |
|---------|--------------|--------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|----------|--------|
| | LNILU3834 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 33.29% | Good | Retain | N/A |
| | LNILU3835 | Interior Painting | \$ 514.00 | 10 | 01-06-2016 | 1.2 years | 10.51% | Good | Retain | N/A |
| Hallway | | ' | ' | | | | | ' | <u>'</u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3836 | Carpet | \$ 354.00 | 8 | 01-06-2016 | -0.8 years | 20.80% | Good | Retain | N/A |
| | LNILU3837 | Interior Painting | \$ 285.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Good | Retain | N/A |
| Kitchen | | | | | | | | · | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3794 | Blind | \$ 285.00 | 10 | 01-06-2016 | 1.2 years | 35.09% | Good | Retain | N/A |
| | LNILU3795 | Benchtops | \$ 2414.00 | 20 | 01-06-2016 | 11.2 years | 8.75% | Good | Retain | N/A |
| | LNILU3796 | Cooktop | \$ 1394.00 | 12 | 01-06-2016 | 3.2 years | 29.17% | Good | Retain | N/A |
| | LNILU3797 | Interior Painting | \$ 434.00 | 10 | 01-06-2016 | 1.2 years | 15.76% | Good | Retain | N/A |
| | LNILU3798 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-06-2016 | 11.2 years | 17.50% | Good | Retain | N/A |
| | LNILU3799 | Vinyl | \$ 1011.00 | 10 | 01-06-2016 | 1.2 years | 87.54% | Good | Retain | N/A |
| | LNILU3800 | Oven | \$ 1451.00 | 12 | 01-06-2016 | 3.2 years | 145.88% | Good | Retain | N/A |
| | LNILU3801 | Rangehood | \$ 617.00 | 12 | 01-06-2016 | 3.2 years | 1.46% | Good | Retain | N/A |
| | LNILU3802 | Sink & Fittings | \$ 1634.00 | 15 | 01-06-2016 | 6.2 years | 8.75% | Good | Retain | N/A |
| Laundry | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3812 | Interior Painting | \$ 257.00 | 10 | 01-06-2016 | 1.2 years | 10.51% | Good | Retain | N/A |
| | LNILU3813 | Tiles - Wall | \$ 1246.00 | 20 | 01-06-2016 | 11.2 years | 5.69% | Good | Retain | N/A |
| | LNILU3814 | Tiles - Floor | \$ 2086.00 | 20 | 01-06-2016 | 11.2 years | 17.50% | Good | Retain | N/A |
| | LNILU4581 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4582 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4583 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| Living | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3827 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-06-2016 | 1.2 years | 314.93% | Good | Retain | N/A |

| LNILU3828 | Blind | \$ 400.00 | 10 | 01-06-2016 | 1.2 years | 15.75% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|------------|--------|------|--------|-------------------------------|
| LNILU3829 | Carpet | \$ 1371.00 | 8 | 01-06-2016 | -0.8 years | 20.79% | Good | Retain | N/A |
| LNILU3830 | Ceiling Fan | \$ 605.00 | 10 | 01-06-2016 | 1.2 years | 42.13% | Good | Retain | Requires new speed controller |
| LNILU3831 | Interior Painting | \$ 1097.00 | 10 | 01-06-2016 | 1.2 years | 35.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3822 | Skylight | \$ 1040.00 | 10 | 01-06-2016 | 1.2 years | 31.50% | Good | Retain | N/A |
| LNILU3823 | Toilet & Cistern | \$ 1383.00 | 20 | 01-06-2016 | 11.2 years | 87.49% | Good | Retain | N/A |
| LNILU3824 | Tiles - Wall | \$ 926.00 | 20 | 01-06-2016 | 11.2 years | 17.49% | Good | Retain | N/A |
| LNILU3825 | Tiles - Floor | \$ 1429.00 | 20 | 01-06-2016 | 11.2 years | 17.49% | Good | Retain | N/A |
| LNILU3826 | Tapware | \$ 251.00 | 15 | 01-06-2016 | 6.2 years | 52.59% | Good | Retain | N/A |
| LNILU4584 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------------------------------------|
| LNILU3838 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| LNILU3839 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3840 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |
| LNILU3841 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between uni 56/57 |
| LNILU3842 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 4.81% | Good | Retain | Soffit has marks; requires re-painting |
| LNILU3844 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 66.50% | Good | Retain | N/A |
| LNILU3846 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3847 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 7.92% | Good | Retain | N/A |
| LNILU3848 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU3849 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 17.49% | Poor | Repair | Porch post has visible rust |
| LNILU3851 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3852 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU3853 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 4.16% | Good | Retain | N/A |

| | LNILU4219 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 2.17% | Good | Retain | N/A |
|-------|--------------------------------------------------|------------------------------------------------------|----------------------------------------------------|----------------------|------------------------------------------------------|-----------------------------------------------|----------------------------------------------------|----------------------|--------------------------------------|-------------------|
| | LNILU4732 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| | LNILU4733 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Good | Retain | N/A |
| | LNILU4956 | Water Tank | \$ 1063.00 | 25 | 08-01-2024 | 23.8 years | 0.00% | Good | Retain | N/A |
| | | | | | | | | | | |
| | | | | | | | | | | |
| hroom | | | | | | | | | | |
| hroom | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| hroom | Asset Number | Asset Name Exhaust Fan | Acquisition Cost (\$) \$ 262.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 35.11% | Asset Condition Good | Plan Retain | Comments N/A |
| hroom | | | | | i e | | | | | |
| nroom | LNILU3879 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| nroom | LNILU3879 LNILU3880 | Exhaust Fan Interior Painting | \$ 262.00 \$ 228.00 | 10 10 | 01-07-1982 01-08-2020 | -32.7 years 5.4 years | 35.11% 33.33% | Good Good | Retain Retain | N/A N/A |
| room | LNILU3879 LNILU3880 LNILU3881 | Exhaust Fan Interior Painting Shower Screen | \$ 262.00 \$ 228.00 \$ 1200.00 | 10 10 20 | 01-07-1982 01-08-2020 01-07-1982 | -32.7 years 5.4 years -22.7 years | 35.11% 33.33% 0.00% | Good Good | Retain Retain Retain | N/A N/A N/A |
| aroom | LNILU3879 LNILU3880 LNILU3881 LNILU3882 | Exhaust Fan Interior Painting Shower Screen Skylight | \$ 262.00 \$ 228.00 \$ 1200.00 \$ 1040.00 | 10 10 20 10 | 01-07-1982 01-08-2020 01-07-1982 01-07-1982 | -32.7 years 5.4 years -22.7 years -32.7 years | 35.11% 33.33% 0.00% 66.50% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A |

Bed 1

Unit 57

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3867 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 10.53% | Good | Retain | N/A |
| LNILU3868 | Carpet | \$ 891.00 | 8 | 01-08-2020 | 3.4 years | 21.89% | Good | Retain | N/A |
| LNILU3869 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 28.91% | Good | Retain | N/A |
| LNILU3870 | Interior Painting | \$ 726.00 | 10 | 01-08-2020 | 5.4 years | 34.99% | Good | Retain | N/A |
| LNILU3871 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |

Bed 2

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3872 | Blind | \$ 342.00 | 10 | 01-07-1982 | -32.7 years | 15.79% | Good | Retain | N/A |
| LNILU3873 | Carpet | \$ 743.00 | 8 | 01-08-2020 | 3.4 years | 21.87% | Good | Retain | N/A |
| LNILU3874 | Interior Painting | \$ 605.00 | 10 | 01-08-2020 | 5.4 years | 33.29% | Good | Retain | N/A |
| LNILU3875 | Wardrobe | \$ 2115.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |

Dining

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU3896 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 33.25% | Good | Retain | N/A |
| LNILU3897 | Carpet | \$ 640.00 | 8 | 01-08-2020 | 3.4 years | 6.56% | Good | Retain | N/A |

| | LNILU3898 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
|------|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|----------|----------|
| | LNILU3899 | Interior Painting | \$ 514.00 | 10 | 01-08-2020 | 5.4 years | 35.02% | Good | Retain | N/A |
| lway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3900 | Carpet | \$ 354.00 | 8 | 01-08-2020 | 3.4 years | 21.89% | Good | Retain | N/A |
| | LNILU3901 | Interior Painting | \$ 285.00 | 10 | 01-08-2020 | 5.4 years | 11.40% | Good | Retain | N/A |
| hen | | | | | | | | | <u> </u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3858 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 15.79% | Good | Retain | N/A |
| | LNILU3859 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| | LNILU3860 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 0.73% | Good | Retain | N/A |
| | LNILU3861 | Interior Painting | \$ 434.00 | 10 | 01-08-2020 | 5.4 years | 11.38% | Good | Retain | N/A |
| | LNILU3862 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU3863 | Vinyl | \$ 1011.00 | 10 | 01-08-2020 | 5.4 years | 8.75% | Good | Retain | N/A |
| | LNILU3864 | Oven | \$ 1451.00 | 12 | 01-07-1982 | -30.7 years | 145.88% | Good | Retain | N/A |
| | LNILU3865 | Rangehood | \$ 617.00 | 12 | 01-07-1982 | -30.7 years | 14.59% | Good | Retain | N/A |
| | LNILU3866 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 110.85% | Good | Retain | N/A |
| ndry | | | | | | | | | <u> </u> | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3876 | Interior Painting | \$ 257.00 | 10 | 01-08-2020 | 5.4 years | 33.27% | Good | Retain | N/A |
| | LNILU3877 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| | LNILU3878 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| | LNILU4585 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4586 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| ıg | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3891 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| | LNILU3892 | Blind | \$ 400.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | N/A |
| | LNILU3893 | Carpet | \$ 1371.00 | 8 | 01-08-2020 | 3.4 years | 21.88% | Good | Retain | N/A |

| LNILU3894 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
|-----------|-------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU3895 | Interior Painting | \$ 1097.00 | 10 | 01-08-2020 | 5.4 years | 16.63% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU3886 | Skylight | \$ 1040.00 | 10 | 01-07-1982 | -32.7 years | 1.75% | Good | Retain | N/A |
| LNILU3887 | Toilet & Cistern | \$ 1383.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | N/A |
| LNILU3888 | Tiles - Wall | \$ 926.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU3889 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU3890 | Tapware | \$ 251.00 | 15 | 01-07-1982 | -27.7 years | 111.02% | Good | Retain | N/A |
| LNILU4587 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|-----------------------------------------------------------------|
| LNILU3902 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Fair | Retain | N/A |
| LNILU3903 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3904 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 75.07% | Good | Retain | N/A |
| LNILU3905 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 26.25% | Good | Retain | Shared between unit 56/57 |
| LNILU3906 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Fair | Retain | N/A |
| LNILU3907 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3908 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 1.75% | Good | Retain | N/A |
| LNILU3909 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU3910 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU3911 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 0.44% | Good | Retain | N/A |
| LNILU3912 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Fair | Retain | Repair cracked entry tiling & path cracks on entry to U57 |
| LNILU3913 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU3914 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 151.93% | Fair | Retain | N/A |
| LNILU3915 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU3916 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |

| | _ | | |
|---|-----|-----|----|
| U | nit | 58- | 59 |
| _ | | | |

LNILU3917

LNILU4220

LNILU3944

LNILU3945

LNILU3946

LNILU3947

LNILU3948

LNILU3949

LNILU3950

Balcony

Flooring

Awnings

Exhaust Fan

Interior Painting

Shower Screen

Skylight

Tapware

Tiles - Wall

Tiles - Floor

\$ 3681.00

\$ 9718.00

\$ 262.00

\$ 228.00

\$ 1200.00

\$ 1040.00

\$ 1343.00

\$ 3384.00

\$ 4058.00

| Common | | | | | | | | | | |
|----------|---------------------|-------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|---------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commer |
| | LNILU3918 | Roof | \$ 27439.00 | 50 | 01-07-1982 | 7.3 years | 34.99% | Good | Retain | N/A |
| Unit 58 | | | | | | | | | | 7 |
| • | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3919 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3920 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU3921 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 66.48% | Good | Retain | N/A |
| | LNILU3922 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| Unit 59 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Commen |
| | LNILU3983 | Insulation | \$ 3224.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| | LNILU3984 | Lighting | \$ 1966.00 | 15 | 01-07-1982 | -27.7 years | 23.33% | Good | Retain | N/A |
| | LNILU3985 | Sarking | \$ 3384.00 | 25 | 01-07-1982 | -17.7 years | 69.98% | Good | Retain | N/A |
| | LNILU3986 | Smoke Alarms | \$ 268.00 | 20 | 01-07-1982 | -22.7 years | 17.54% | Good | Retain | N/A |
| | | | | | | | • | | | · |
| Bathroom | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |

0.66% Good

0.00% Good

35.11% Good

0.88% Good

5.69% Good

70.00% Good

116.65% Good

8.31% Good

1.31% Good

Retain

Retain

Retain

Retain

Retain

Retain

Retain

Retain

Retain

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

01-07-1982 -22.7 years

15-01-2010 -5.2 years

01-07-1982 -32.7 years

01-07-1982 -22.7 years

01-07-1982 -32.7 years

01-07-1982 -27.7 years

01-07-1982 -22.7 years

01-07-1982 -22.7 years

-32.7 years

01-07-1982

20

10

10

10

20

10

15

20

20

| Bed 1 | | | |
|-------|--|--|--|
| | | | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-------|--------------|---------------------|-----------------------|--------------------|-------------------|---------------------------------|---------------------------------------------|------------------------|--------|----------|
| | LNILU3933 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 11.49% | Good | Retain | N/A |
| | LNILU3934 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU3935 | Interior Painting | \$ 726.00 | 10 | 01-07-1982 | -32.7 years | 34.99% | Good | Retain | N/A |
| | LNILU4592 | Blind | \$ 342.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4593 | Wardrobe | \$ 2115.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3938 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU3939 | Interior Painting | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU4594 | Blind | \$ 342.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4595 | Wardrobe | \$ 2115.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| ning | | | · | | | , | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3963 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 12.26% | Good | Retain | N/A |
| | LNILU3964 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 15.76% | Good | Retain | N/A |
| | LNILU4602 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4603 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| llway | | <u>'</u> | · | | | , | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3966 | Interior Painting | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 28.95% | Good | Retain | N/A |
| | LNILU4604 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| chen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU3923 | Blind | \$ 285.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| | LNILU3924 | Benchtops | \$ 2414.00 | 20 | 01-07-1982 | -22.7 years | 2.62% | Good | Retain | N/A |
| | LNILU3925 | Cooktop | \$ 1394.00 | 12 | 01-07-1982 | -30.7 years | 29.17% | Good | Retain | N/A |
| | LNILU3926 | Interior Painting | \$ 434.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | LNILU3927 | Kitchen Cabinets | \$ 3932.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

| | LNILU3931 | Sink & Fittings | \$ 1634.00 | 15 | 01-07-1982 | -27.7 years | 116.69% | Good | Retain | N/A |
|--------|-------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------------------------------------------|----------------------------------------------------------------|-----------------------------------------|
| | LNILU4588 | Dishwasher | \$ 1152.00 | 8 | 17-11-2022 | 5.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4589 | Oven | \$ 958.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4590 | Rangehood | \$ 617.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4591 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| dry | | | | | | | | | | ' |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | LNILU3941 | Interior Painting | \$ 257.00 | 10 | 01-07-1982 | -32.7 years | 28.89% | Good | Retain | N/A |
| | LNILU3942 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 6.12% | Good | Retain | N/A |
| | LNILU3943 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| | LNILU4596 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4597 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4598 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| j | | | | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comment |
| | Asset Number LNILU3956 | Asset Name Air Conditioner - Split System | Acquisition Cost (\$) \$ 3395.00 | Effective Life (Y) | Installation Date 01-07-1982 | Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 314.93% | Asset Condition Good | Plan Retain | Comment N/A |
| | | Air Conditioner | • | | | | • | | | |
| | LNILU3956 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| | LNILU3956 LNILU3959 | Air Conditioner - Split System Ceiling Fan | \$ 3395.00 \$ 605.00 | 10 | 01-07-1982 01-07-1982 | -32.7 years | 314.93% 35.04% | Good | Retain Retain | N/A N/A |
| | LNILU3956 LNILU3959 LNILU3960 | Air Conditioner - Split System Ceiling Fan Interior Painting | \$ 3395.00 \$ 605.00 \$ 1097.00 | 10 10 10 | 01-07-1982 01-07-1982 01-07-1982 | -32.7 years -32.7 years -32.7 years | 314.93% 35.04% 35.00% | Good Good | Retain Retain Retain | N/A N/A N/A |
| : roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 | Air Conditioner - Split System Ceiling Fan Interior Painting Blind | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 | 10 10 10 10 | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 | -32.7 years -32.7 years -32.7 years 7.7 years | 314.93% 35.04% 35.00% 0.00% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A N/A |
| roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 | Air Conditioner - Split System Ceiling Fan Interior Painting Blind | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 | 10 10 10 10 | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 | -32.7 years -32.7 years -32.7 years 7.7 years | 314.93% 35.04% 35.00% 0.00% | Good Good Good | Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 | Air Conditioner - Split System Ceiling Fan Interior Painting Blind Vinyl | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 \$ 1011.00 | 10 10 10 10 10 | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 17-11-2022 | -32.7 years -32.7 years -32.7 years 7.7 years 7.7 years | 314.93% 35.04% 35.00% 0.00% 0.00% | Good Good Good Good | Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A |
| roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 Asset Number | Air Conditioner - Split System Ceiling Fan Interior Painting Blind Vinyl Asset Name | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 \$ 1011.00 Acquisition Cost (\$) | 10 10 10 10 10 Effective Life (Y) | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 17-11-2022 Installation Date | -32.7 years -32.7 years -32.7 years 7.7 years 7.7 years Remaining Effective Life | 314.93% 35.04% 35.00% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition | Good Good Good Good Good Asset Condition | Retain Retain Retain Retain Retain | N/A N/A N/A N/A N/A Comment |
| roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 Asset Number LNILU3951 | Air Conditioner - Split System Ceiling Fan Interior Painting Blind Vinyl Asset Name Skylight | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 \$ 1011.00 Acquisition Cost (\$) \$ 1040.00 | 10 10 10 10 10 10 10 10 | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 17-11-2022 Installation Date 01-07-1982 | -32.7 years -32.7 years -32.7 years 7.7 years 7.7 years Remaining Effective Life -32.7 years | 314.93% 35.04% 35.00% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 70.00% | Good Good Good Good Good Asset Condition Good | Retain Retain Retain Retain Retain Plan Retain | N/A N/A N/A N/A Comments N/A |
| roon | LNILU3956 LNILU3959 LNILU3960 LNILU4600 LNILU4601 Asset Number LNILU3951 LNILU3952 | Air Conditioner - Split System Ceiling Fan Interior Painting Blind Vinyl Asset Name Skylight Toilet & Cistern | \$ 3395.00 \$ 605.00 \$ 1097.00 \$ 400.00 \$ 1011.00 Acquisition Cost (\$) \$ 1040.00 \$ 1383.00 | 10 10 10 10 10 10 10 10 20 | 01-07-1982 01-07-1982 01-07-1982 17-11-2022 17-11-2022 Installation Date 01-07-1982 01-07-1982 | -32.7 years -32.7 years -32.7 years 7.7 years 7.7 years Remaining Effective Life -32.7 years -22.7 years | 314.93% 35.04% 35.00% 0.00% 0.00% Accumulated Repair Cost as % of Acquisition 70.00% 26.25% | Good Good Good Good Good Good Good Good | Retain Retain Retain Retain Retain Retain Retain Retain Retain | N/A |

Unit Exterior

LNILU4599

Exhaust Fan

\$ 262.00

10

Asset Number Asset Name Acquisition Cost (\$) Effective Life (Y) **Installation Date Remaining Effective Life Accumulated Repair Cost as % of Acquisition Asset Condition** Plan Comments LNILU3967 Clothesline \$ 514.00 10 01-07-1982 -32.7 years 35.02% Good Retain N/A

17-11-2022 7.7 years

0.00% Good

Retain

N/A

| LNILU3968 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Fair | Repair | Renew rollers door to B2 |
|-----------|-----------------------------|------------|----|------------|-------------|---------|------|--------|---------------------------|
| LNILU3969 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 76.82% | Good | Retain | N/A |
| LNILU3970 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 87.49% | Good | Retain | Shared between unit 58/59 |
| LNILU3971 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 17.50% | Good | Retain | N/A |
| LNILU3972 | Fascias | \$ 2961.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU3973 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 24.50% | Good | Retain | N/A |
| LNILU3974 | Guttering | \$ 2903.00 | 20 | 01-07-1982 | -22.7 years | 131.24% | Good | Retain | N/A |
| LNILU3975 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 22.16% | Good | Retain | N/A |
| LNILU3976 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 16.62% | Good | Retain | N/A |
| LNILU3977 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 31.05% | Good | Retain | N/A |
| LNILU3978 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 55.40% | Good | Retain | N/A |
| LNILU3979 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU3980 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 4.96% | Good | Retain | N/A |
| LNILU3981 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU3982 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4221 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |

Unit 59

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU4009 | Exhaust Fan | \$ 262.00 | 10 | 01-07-1982 | -32.7 years | 35.11% | Good | Retain | N/A |
| LNILU4010 | Interior Painting | \$ 228.00 | 10 | 01-07-1982 | -32.7 years | 35.09% | Good | Retain | N/A |
| LNILU4011 | Shower Screen | \$ 1200.00 | 20 | 01-01-1984 | -21.2 years | 16.63% | Good | Retain | N/A |
| LNILU4012 | Skylight | \$ 1040.00 | 10 | 01-02-2003 | -12.1 years | 33.25% | Good | Retain | N/A |
| LNILU4013 | Tapware | \$ 1343.00 | 15 | 01-01-1984 | -26.2 years | 110.82% | Good | Retain | N/A |
| LNILU4014 | Tiles - Wall | \$ 3384.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU4015 | Tiles - Floor | \$ 4058.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |

| Bed 1 |
|-------|
|-------|

Cabinets

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------|----------------------------------------------------------|----------------------------------------------------------|---------------------------------------------------------------------------------------------|----------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|------------------------------------------------|--------------------------------------------|-------------------------------------|
| | LNILU3996 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-03-2005 | -10.1 years | 133.85% | Good | Retain | N/A |
| | LNILU3998 | Carpet | \$ 891.00 | 8 | 01-07-1982 | -34.7 years | 21.89% | Good | Retain | N/A |
| | LNILU3999 | Ceiling Fan | \$ 605.00 | 10 | 01-07-1982 | -32.7 years | 35.04% | Good | Retain | N/A |
| | LNILU4000 | Interior Painting | \$ 726.00 | 10 | 01-03-2019 | 3.9 years | 2.62% | Good | Retain | N/A |
| | LNILU4610 | Blind | \$ 342.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4611 | Wardrobe | \$ 2115.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Excellent | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4003 | Carpet | \$ 743.00 | 8 | 01-07-1982 | -34.7 years | 21.87% | Good | Retain | N/A |
| | LNILU4004 | Interior Painting | \$ 605.00 | 10 | 01-03-2005 | -10.1 years | 14.89% | Good | Retain | N/A |
| | LNILU4612 | Blind | \$ 342.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4613 | Wardrobe | \$ 2115.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Excellent | Retain | N/A |
| ining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU4028 | Ceiling Fan | \$ 605.00 | 10 | 01-01-1989 | -26.2 years | 28.91% | Good | Retain | N/A |
| | LNILU4029 | Interior Painting | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 35.02% | Good | Retain | N/A |
| | | | | | 17 11 2022 | 7.7 years | 0.00% | Good | Detain | N/A |
| | LNILU4620 | Blind | \$ 400.00 | 10 | 17-11-2022 | 1.1 years | 0.00% | Good | Retain | , |
| | LNILU4620 LNILU4621 | Blind Vinyl | \$ 400.00 \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| allway | | | | | | | | | | |
| ıllway | | | | | | | | | | |
| ıllway | LNILU4621 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| allway | LNILU4621 Asset Number | Vinyl Asset Name | \$ 1011.00 Acquisition Cost (\$) | Effective Life (Y) | 17-11-2022 Installation Date | 7.7 years Remaining Effective Life | 0.00% Accumulated Repair Cost as % of Acquisition | Good Asset Condition | Retain Plan | N/A Comments |
| • | Asset Number LNILU4031 | Asset Name Interior Painting | \$ 1011.00 Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | 17-11-2022 Installation Date 01-07-1982 | 7.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 35.09% | Asset Condition Good | Plan Retain | N/A Comments N/A |
| • | Asset Number LNILU4031 | Asset Name Interior Painting | \$ 1011.00 Acquisition Cost (\$) \$ 285.00 | Effective Life (Y) | 17-11-2022 Installation Date 01-07-1982 | 7.7 years Remaining Effective Life -32.7 years | Accumulated Repair Cost as % of Acquisition 35.09% | Asset Condition Good | Plan Retain | N/A Comments N/A |
| • | Asset Number LNILU4031 LNILU4622 | Asset Name Interior Painting Vinyl | \$ 1011.00 Acquisition Cost (\$) \$ 285.00 \$ 1011.00 | Effective Life (Y) 10 10 | 17-11-2022 Installation Date 01-07-1982 17-11-2022 | 7.7 years Remaining Effective Life -32.7 years 7.7 years | Accumulated Repair Cost as % of Acquisition 35.09% 0.00% | Asset Condition Good Good | Plan Retain Retain | Comments N/A N/A |
| | Asset Number LNILU4031 LNILU4622 Asset Number | Asset Name Interior Painting Vinyl Asset Name | \$ 1011.00 Acquisition Cost (\$) \$ 285.00 \$ 1011.00 Acquisition Cost (\$) | Effective Life (Y) 10 10 Effective Life (Y) | 17-11-2022 Installation Date 01-07-1982 17-11-2022 Installation Date | 7.7 years Remaining Effective Life -32.7 years 7.7 years Remaining Effective Life | Accumulated Repair Cost as % of Acquisition 35.09% 0.00% Accumulated Repair Cost as % of Acquisition | Asset Condition Good Good Asset Condition | Plan Retain Retain Plan | N/A Comments N/A N/A Comments |
| allway | Asset Number LNILU4031 LNILU4622 Asset Number LNILU3988 | Asset Name Interior Painting Vinyl Asset Name Benchtops | \$ 1011.00 Acquisition Cost (\$) \$ 285.00 \$ 1011.00 Acquisition Cost (\$) \$ 2414.00 | Effective Life (Y) 10 10 Effective Life (Y) 20 | 17-11-2022 Installation Date 01-07-1982 17-11-2022 Installation Date 01-01-1984 | 7.7 years Remaining Effective Life -32.7 years 7.7 years Remaining Effective Life -21.2 years | Accumulated Repair Cost as % of Acquisition 35.09% 0.00% Accumulated Repair Cost as % of Acquisition 8.31% | Asset Condition Good Good Asset Condition Good | Plan Retain Retain Plan Retain Plan Retain | N/A Comments N/A N/A Comments N/A |

| LNILU3995 | Sink & Fittings | \$ 1634.00 | 15 | 01-10-2018 | 8.5 years | 11.67% | Good | Retain | N/A |
|-----------|-----------------|------------|----|------------|-----------|--------|-----------|--------|-----|
| LNILU4605 | Blind | \$ 285.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4606 | Dishwasher | \$ 1152.00 | 8 | 17-11-2022 | 5.7 years | 0.00% | Excellent | Retain | N/A |
| LNILU4607 | Oven | \$ 958.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Excellent | Retain | N/A |
| LNILU4608 | Rangehood | \$ 617.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| LNILU4609 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Laundry

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU4006 | Interior Painting | \$ 257.00 | 10 | 01-01-1989 | -26.2 years | 28.89% | Good | Retain | N/A |
| LNILU4007 | Tiles - Wall | \$ 1246.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4008 | Tiles - Floor | \$ 2086.00 | 20 | 01-07-1982 | -22.7 years | 17.50% | Good | Retain | N/A |
| LNILU4614 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| LNILU4615 | Sink & Fittings | \$ 1634.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Good | Retain | N/A |
| LNILU4616 | Washing Machine | \$ 1371.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |

Living

| Α | sset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|----|-------------|-----------------------------------|-----------------------|--------------------|--------------------------|---------------------------------|----------------------------------------------------|------------------------|--------|----------------------------------------------|
| Lľ | NILU4021 | Air Conditioner - Split System | \$ 3395.00 | 10 | 01-07-1982 | -32.7 years | 314.93% | Good | Retain | N/A |
| Lľ | NILU4024 | Ceiling Fan | \$ 605.00 | 10 | 01-01-1984 | -31.2 years | 33.29% | Good | Retain | N/A |
| Lſ | NILU4025 | Interior Painting | \$ 1097.00 | 10 | 01-07-1982 | -32.7 years | 35.00% | Good | Retain | Patching and painting requiredRoom repainted |
| Lſ | NILU4618 | Blind | \$ 400.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| Lľ | NILU4619 | Vinyl | \$ 1011.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU4016 | Skylight | \$ 1040.00 | 10 | 01-04-2007 | -8.0 years | 26.25% | Good | Retain | N/A |
| LNILU4018 | Tiles - Wall | \$ 926.00 | 20 | 01-01-1989 | -16.2 years | 14.43% | Good | Retain | N/A |
| LNILU4019 | Tiles - Floor | \$ 1429.00 | 20 | 01-07-1982 | -22.7 years | 17.49% | Good | Retain | N/A |
| LNILU4617 | Exhaust Fan | \$ 262.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

Unit Exterior

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU4032 | Clothesline | \$ 514.00 | 10 | 01-07-1982 | -32.7 years | 10.51% | Good | Retain | N/A |
| LNILU4033 | Doors | \$ 9215.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU4034 | Downpipes | \$ 1794.00 | 20 | 01-07-1982 | -22.7 years | 132.93% | Good | Retain | N/A |
| LNILU4035 | Electrical Switchboard | \$ 2023.00 | 20 | 01-07-1982 | -22.7 years | 91.10% | Good | Retain | N/A |
| LNILU4036 | Exterior Painting | \$ 2149.00 | 10 | 01-07-1982 | -32.7 years | 0.00% | Good | Retain | N/A |
| LNILU4038 | Flyscreens | \$ 1920.00 | 10 | 01-07-1982 | -32.7 years | 70.00% | Good | Retain | N/A |
| LNILU4040 | Hot Water System - Solar | \$ 4516.00 | 15 | 01-07-1982 | -27.7 years | 23.32% | Good | Retain | N/A |
| LNILU4041 | Lattice Screening | \$ 2206.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4042 | Path | \$ 1554.00 | 30 | 01-07-1982 | -12.7 years | 5.83% | Good | Retain | N/A |
| LNILU4043 | Porch | \$ 3304.00 | 30 | 01-07-1982 | -12.7 years | 58.31% | Good | Retain | N/A |
| LNILU4044 | Water Tank | \$ 1063.00 | 25 | 01-07-1982 | -17.7 years | 35.00% | Good | Retain | N/A |
| LNILU4045 | Windows | \$ 7980.00 | 30 | 01-07-1982 | -12.7 years | 11.66% | Good | Retain | N/A |
| LNILU4046 | Balustrade | \$ 1943.00 | 20 | 01-07-1982 | -22.7 years | 8.75% | Good | Retain | N/A |
| LNILU4047 | Balcony Flooring | \$ 3681.00 | 20 | 01-07-1982 | -22.7 years | 8.31% | Good | Retain | N/A |
| LNILU4222 | Awnings | \$ 9718.00 | 10 | 15-01-2010 | -5.2 years | 1.03% | Good | Retain | N/A |
| LNILU4734 | Fascias | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |
| LNILU4735 | Guttering | \$ 1671.00 | 20 | 04-07-2023 | 18.3 years | 0.00% | Excellent | Retain | N/A |

Unit G1

| | В | athroom | |
|--|---|---------|--|
|--|---|---------|--|

| Asset Num | ber Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|-----------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0027 | Exhaust Fan | \$ 255.00 | 10 | 01-06-2004 | -10.8 years | 36.08% | Good | Retain | N/A |
| LNILU0028 | Interior Painting | \$ 222.00 | 10 | 01-06-2004 | -10.8 years | 9.01% | Good | Retain | N/A |
| LNILU0029 | Shower Screen | \$ 1165.00 | 20 | 01-06-2004 | -0.8 years | 4.51% | Good | Retain | N/A |
| LNILU0030 | Skylight | \$ 1010.00 | 10 | 01-06-2004 | -10.8 years | 70.28% | Good | Retain | N/A |
| LNILU0031 | Tapware | \$ 1304.00 | 15 | 01-06-2004 | -5.8 years | 117.14% | Good | Retain | N/A |

| | LNILU0032 | Tiles - Wall | \$ 3285.00 | 20 | 01-06-2004 | -0.8 years | 18.02% | Good | Retain | N/A |
|---------|--------------|-------------------|------------------------------------|--------------------|---------------------------------|-----------------------------------------|---------------------------------------------|-------------------|--------|----------|
| | LNILU0033 | Tiles - Floor | \$ 3940.00 | 20 | 01-06-2004 | -0.8 years | 2.25% | Good | Retain | N/A |
| Bed 1 | | | | | | | | | | · |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0015 | Blind | \$ 333.00 | 10 | 01-06-2004 | -10.8 years | 4.50% | Good | Retain | N/A |
| | LNILU0016 | Carpet | \$ 865.00 | 8 | 01-06-2004 | -12.8 years | 3.95% | Good | Retain | N/A |
| | LNILU0017 | Ceiling Fan | \$ 588.00 | 10 | 01-06-2004 | -10.8 years | 43.27% | Good | Retain | N/A |
| | LNILU0018 | Interior Painting | \$ 704.00 | 10 | 01-06-2004 | -10.8 years | 15.33% | Good | Retain | N/A |
| | LNILU0019 | Wardrobe | \$ 2053.00 | 10 | 01-06-2004 | -10.8 years | 36.04% | Good | Retain | N/A |
| ed 2 | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0020 | Blind | \$ 333.00 | 10 | 01-06-2004 | -10.8 years | 14.41% | Good | Retain | N/A |
| | LNILU0021 | Carpet | \$ 721.00 | 8 | 01-06-2004 | -12.8 years | 6.20% | Good | Retain | N/A |
| | LNILU0022 | Interior Painting | \$ 588.00 | 10 | 01-06-2004 | -10.8 years | 36.05% | Good | Retain | N/A |
| | LNILU0023 | Wardrobe | \$ 2053.00 | 10 | 01-06-2004 | -10.8 years | 1.80% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0044 | Blind | \$ 388.00 | 10 | 01-06-2004 | -10.8 years | 36.08% | Good | Retain | N/A |
| | LNILU0045 | Carpet | \$ 621.00 | 8 | 01-06-2004 | -12.8 years | 10.14% | Good | Retain | N/A |
| | LNILU0046 | Ceiling Fan | \$ 588.00 | 10 | 01-06-2004 | -10.8 years | 36.05% | Good | Retain | N/A |
| | LNILU0047 | Interior Painting | \$ 499.00 | 10 | 01-06-2004 | -10.8 years | 36.07% | Good | Retain | N/A |
| Hallway | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0048 | Carpet | \$ 344.00 | 8 | 01-06-2004 | -12.8 years | 22.53% | Good | Retain | N/A |
| | LNILU0049 | Interior Painting | \$ 277.00 | 10 | 01-06-2004 | -10.8 years | 1.81% | Good | Retain | N/A |
| | | | | | | | | | | |
| Citchen | | | | | | D : : = = = = : : : : : : : : : : : : : | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| Citchen | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | 7155CC COMMITTION | | |
| (itchen | Asset Number | Asset Name | Acquisition Cost (\$) \$ 277.00 | Effective Life (Y) | Installation Date 01-06-2004 | -10.8 years | 15.34% | Good | Retain | N/A |
| Kitchen | | | • | | | | · | | | |
| Kitchen | LNILU0006 | Blind | \$ 277.00 | 10 | 01-06-2004 | -10.8 years | 15.34% | Good | Retain | N/A |

| | LNILU0010 | Kitchen Cabinets | \$ 3818.00 | 20 | 01-06-2004 | -0.8 years | 8.11% | Good | Retain | N/A |
|-----|-------------------------------------|----------------------------------------------|---------------------------------------|--------------------|----------------------------------------|--------------------------------------|---------------------------------------------------|----------------------|----------------------------|-------------------|
| | LNILU0011 | Vinyl | \$ 982.00 | 10 | 01-06-2004 | -10.8 years | 38.30% | Good | Retain | N/A |
| | LNILU0012 | Oven | \$ 1409.00 | 12 | 01-06-2004 | -8.8 years | 63.85% | Good | Retain | N/A |
| | LNILU0013 | Rangehood | \$ 599.00 | 12 | 01-06-2004 | -8.8 years | 14.65% | Good | Retain | N/A |
| | LNILU0014 | Sink & Fittings | \$ 1587.00 | 15 | 01-06-2004 | -5.8 years | 6.01% | Good | Retain | N/A |
| dry | | | , | | | | | | | |
| | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | Asset Number LNILU0024 | Asset Name Interior Painting | Acquisition Cost (\$) \$ 249.00 | Effective Life (Y) | Installation Date 01-06-2004 | Remaining Effective Life -10.8 years | Accumulated Repair Cost as % of Acquisition 4.52% | Asset Condition Good | Plan Retain | Comments N/A |
| | | | • | | | | | | | |
| | LNILU0024 | Interior Painting | \$ 249.00 | 10 | 01-06-2004 | -10.8 years | 4.52% | Good | Retain | N/A |
| | LNILU0024 LNILU0025 | Interior Painting Tiles - Wall | \$ 249.00 \$ 1209.00 | 10 20 | 01-06-2004 01-06-2004 | -10.8 years -0.8 years -0.8 years | 4.52% 18.03% | Good Good | Retain Retain | N/A N/A |
| g | LNILU0024 LNILU0025 LNILU0026 | Interior Painting Tiles - Wall Tiles - Floor | \$ 249.00 \$ 1209.00 \$ 2025.00 | 10 20 20 | 01-06-2004 01-06-2004 01-06-2004 | -10.8 years -0.8 years -0.8 years | 4.52% 18.03% 7.66% | Good Good | Retain Retain Retain | N/A N/A N/A |
| } | LNILU0024 LNILU0025 LNILU0026 | Interior Painting Tiles - Wall Tiles - Floor | \$ 249.00 \$ 1209.00 \$ 2025.00 | 10 20 20 | 01-06-2004 01-06-2004 01-06-2004 | -10.8 years -0.8 years -0.8 years | 4.52% 18.03% 7.66% | Good Good | Retain Retain Retain | N/A N/A N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0039 | Air Conditioner - Split System | \$ 3296.00 | 10 | 01-06-2004 | -10.8 years | 316.28% | Good | Retain | N/A |
| LNILU0040 | Blind | \$ 388.00 | 10 | 01-06-2004 | -10.8 years | 0.90% | Good | Retain | N/A |
| LNILU0041 | Carpet | \$ 1332.00 | 8 | 01-06-2004 | -12.8 years | 3.94% | Good | Retain | N/A |
| LNILU0042 | Ceiling Fan | \$ 588.00 | 10 | 01-06-2004 | -10.8 years | 4.51% | Good | Retain | N/A |
| LNILU0043 | Interior Painting | \$ 1065.00 | 10 | 01-06-2004 | -10.8 years | 36.06% | Good | Retain | N/A |

Toilet room

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0034 | Skylight | \$ 1010.00 | 10 | 01-06-2004 | -10.8 years | 32.44% | Good | Retain | N/A |
| LNILU0035 | Toilet & Cistern | \$ 1343.00 | 20 | 01-06-2004 | -0.8 years | 4.50% | Good | Retain | N/A |
| LNILU0036 | Tiles - Wall | \$ 899.00 | 20 | 01-06-2004 | -0.8 years | 17.57% | Good | Retain | N/A |
| LNILU0037 | Tiles - Floor | \$ 1387.00 | 20 | 01-06-2004 | -0.8 years | 18.02% | Good | Retain | N/A |
| LNILU0038 | Tapware | \$ 244.00 | 15 | 01-06-2004 | -5.8 years | 117.21% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0050 | Bargeboards | \$ 1498.00 | 20 | 01-06-2004 | -0.8 years | 9.01% | Good | Retain | N/A |
| LNILU0051 | Clothesline | \$ 499.00 | 10 | 01-07-1982 | -32.7 years | 2.71% | Good | Retain | N/A |
| LNILU0052 | Doors | \$ 8946.00 | 30 | 01-07-1982 | -12.7 years | 5.11% | Good | Retain | N/A |

| LNILU0054 | Electrical Switchboard | \$ 1964.00 | 20 | 01-07-1982 | -22.7 years | 108.15% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|---------|-----------|--------|------------------------------------------------|
| LNILU0055 | Exterior Painting | \$ 2086.00 | 10 | 01-07-1982 | -32.7 years | 8.11% | Fair | Retain | N/A |
| LNILU0056 | Fascias | \$ 2874.00 | 20 | 01-07-1982 | -22.7 years | 33.90% | Good | Retain | N/A |
| LNILU0057 | Flyscreens | \$ 1864.00 | 10 | 01-07-1982 | -32.7 years | 72.10% | Good | Retain | N/A |
| LNILU0058 | Guttering | \$ 2819.00 | 20 | 01-07-1982 | -22.7 years | 51.42% | Fair | Retain | N/A |
| LNILU0059 | Hot Water System - Solar | \$ 4384.00 | 15 | 01-07-1982 | -27.7 years | 23.43% | Good | Retain | N/A |
| LNILU0060 | Lattice Screening | \$ 2142.00 | 20 | 01-07-1982 | -22.7 years | 8.11% | Fair | Retain | N/A |
| LNILU0061 | Path | \$ 1509.00 | 30 | 01-07-1982 | -12.7 years | 0.75% | Fair | Repair | Pathway cracked , poses as a trip hazard |
| LNILU0062 | Porch | \$ 3207.00 | 30 | 01-07-1982 | -12.7 years | 60.08% | Good | Retain | N/A |
| LNILU0063 | Water Tank | \$ 1032.00 | 25 | 01-07-1982 | -17.7 years | 35.15% | Fair | Retain | N/A |
| LNILU0064 | Windows | \$ 7747.00 | 30 | 01-07-1982 | -12.7 years | 12.01% | Good | Retain | N/A |
| LNILU0065 | Balustrade | \$ 1887.00 | 20 | 01-07-1982 | -22.7 years | 3.83% | Good | Retain | N/A |
| LNILU0066 | Balcony Flooring | \$ 3574.00 | 20 | 01-07-1982 | -22.7 years | 2.93% | Good | Retain | N/A |
| LNILU4229 | Awnings | \$ 9435.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Fair | Retain | N/A |
| LNILU4739 | Downpipes | \$ 612.00 | 20 | 22-08-2023 | 18.4 years | 0.00% | Excellent | Retain | N/A |

Unit G1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0001 | Roof | \$ 26640.00 | 50 | 01-07-1982 | 7.3 years | 43.24% | Good | Retain | N/A |
| LNILU0002 | Insulation | \$ 3130.00 | 20 | 01-07-1982 | -22.7 years | 9.83% | Excellent | Retain | N/A |
| LNILU0003 | Lighting | \$ 1909.00 | 15 | 01-06-2004 | -5.8 years | 10.21% | Good | Retain | N/A |
| LNILU0004 | Sarking | \$ 3285.00 | 25 | 01-07-1982 | -17.7 years | 84.07% | Good | Retain | N/A |
| LNILU0005 | Smoke Alarms | \$ 260.00 | 20 | 01-06-2004 | -0.8 years | 7.23% | Good | Retain | N/A |

Unit G2-G3

| (| L | 0 | n | 11 | n | 0 | n | |
|---|---|---|---|----|---|---|---|--|
| | | | | | | | | |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0067 | Roof | \$ 26640.00 | 50 | 01-07-1982 | 7.3 years | 43.24% | Good | Retain | N/A |

| | | • • | | |
|---|---|-----|----|---|
| | n | it | "- | / |
| u | | ıL | | |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---|--------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| L | NILU0068 | Insulation | \$ 3130.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| L | NILU0069 | Lighting | \$ 1909.00 | 15 | 01-10-2005 | -4.5 years | 10.21% | Good | Retain | N/A |
| L | LNILU0070 | Sarking | \$ 3285.00 | 25 | 01-07-1982 | -17.7 years | 3.60% | Good | Retain | N/A |
| L | LNILU0071 | Smoke Alarms | \$ 260.00 | 20 | 01-10-2005 | 0.5 years | 18.08% | Good | Retain | N/A |

Unit G3

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|--------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0134 | Insulation | \$ 3130.00 | 20 | 01-07-1982 | -22.7 years | 0.00% | Good | Retain | N/A |
| LNILU0135 | Lighting | \$ 1909.00 | 15 | 01-11-2006 | -3.4 years | 1.20% | Fair | Retain | N/A |
| LNILU0136 | Sarking | \$ 3285.00 | 25 | 01-07-1982 | -17.7 years | 5.41% | Good | Retain | N/A |
| LNILU0137 | Smoke Alarms | \$ 260.00 | 20 | 01-11-2006 | 1.6 years | 7.68% | Good | Retain | N/A |

Unit G2

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|----------|
| LNILU0094 | Exhaust Fan | \$ 255.00 | 10 | 01-10-2005 | -9.5 years | 6.31% | Good | Retain | N/A |
| LNILU0095 | Interior Painting | \$ 222.00 | 10 | 01-10-2005 | -9.5 years | 1.80% | Good | Retain | N/A |
| LNILU0096 | Shower Screen | \$ 1165.00 | 20 | 01-10-2005 | 0.5 years | 17.58% | Good | Retain | N/A |
| LNILU0097 | Skylight | \$ 1010.00 | 10 | 01-10-2005 | -9.5 years | 32.44% | Good | Retain | N/A |
| LNILU0098 | Tapware | \$ 1304.00 | 15 | 01-10-2005 | -4.5 years | 120.14% | Fair | Retain | N/A |
| LNILU0099 | Tiles - Wall | \$ 3285.00 | 20 | 01-10-2005 | 0.5 years | 0.90% | Good | Retain | N/A |
| LNILU0100 | Tiles - Floor | \$ 3940.00 | 20 | 01-10-2005 | 0.5 years | 17.57% | Fair | Retain | N/A |

Bed 1

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|------------------------|--------|----------|
| LNILU0081 | Air Conditioner - Split System | \$ 3296.00 | 10 | 01-10-2005 | -9.5 years | 137.87% | Good | Retain | N/A |
| LNILU0082 | Blind | \$ 333.00 | 10 | 01-10-2005 | -9.5 years | 10.81% | Good | Retain | N/A |
| LNILU0083 | Carpet | \$ 865.00 | 8 | 01-10-2005 | -11.5 years | 21.98% | Good | Retain | N/A |
| LNILU0084 | Ceiling Fan | \$ 588.00 | 10 | 01-10-2005 | -9.5 years | 35.15% | Good | Retain | N/A |
| LNILU0085 | Interior Painting | \$ 704.00 | 10 | 01-10-2005 | -9.5 years | 43.30% | Fair | Retain | N/A |
| LNILU0086 | Wardrobe | \$ 2053.00 | 10 | 01-10-2005 | -9.5 years | 36.04% | Good | Retain | N/A |

| R | 6 | Ы | 2 |
|---|---|---|---|
| u | c | u | _ |

| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------|---------------------|---------------------|-------------------------|--------------------|-------------------|---------------------------------|----------------------------------------------------|------------------------|------------------|-----------------------------------------------------------------------------------------|
| | LNILU0087 | Blind | \$ 333.00 | 10 | 01-10-2005 | -9.5 years | 36.04% | Good | Retain | N/A |
| | LNILU0088 | Carpet | \$ 721.00 | 8 | 01-10-2005 | -11.5 years | 22.54% | Good | Retain | N/A |
| | LNILU0089 | Interior Painting | \$ 588.00 | 10 | 01-10-2005 | -9.5 years | 35.15% | Good | Retain | N/A |
| | LNILU0090 | Wardrobe | \$ 2053.00 | 10 | 01-10-2005 | -9.5 years | 36.04% | Good | Retain | N/A |
| Dining | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0111 | Blind | \$ 388.00 | 10 | 01-10-2005 | -9.5 years | 36.08% | Good | Retain | N/A |
| | LNILU0112 | Carpet | \$ 621.00 | 8 | 01-10-2005 | -11.5 years | 22.54% | Good | Retain | N/A |
| | LNILU0113 | Ceiling Fan | \$ 588.00 | 10 | 01-10-2005 | -9.5 years | 35.15% | Poor | Repair | Ceiling fan hits ceiling; needs rebalancing or longer hanging post urgently |
| | LNILU0114 | Interior Painting | \$ 499.00 | 10 | 01-10-2005 | -9.5 years | 35.17% | Good | Retain | N/A |
| | LNILU4748 | Curtains | \$ 888.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| Hallway | | | | | | | | | · | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0115 | Carpet | \$ 344.00 | 8 | 01-10-2005 | -11.5 years | 21.97% | Good | Retain | N/A |
| | LNILU0116 | Interior Painting | \$ 277.00 | 10 | 01-10-2005 | -9.5 years | 36.10% | Good | Retain | N/A |
| Kitchen | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0072 | Blind | \$ 277.00 | 10 | 01-10-2005 | -9.5 years | 35.20% | Good | Retain | N/A |
| | LNILU0073 | Benchtops | \$ 2344.00 | 20 | 01-10-2005 | 0.5 years | 1.13% | Good | Retain | N/A |
| | LNILU0074 | Cooktop | \$ 1354.00 | 12 | 01-10-2005 | -7.5 years | 5.26% | Good | Retain | N/A |
| | LNILU0075 | Interior Painting | \$ 421.00 | 10 | 01-10-2005 | -9.5 years | 15.34% | Good | Retain | N/A |
| | | | | | 04 40 2005 | 0.5 years | 18.02% | Fair | Repair | Adjust cabinet |
| | LNILU0076 | Kitchen Cabinets | \$ 3818.00 | 20 | 01-10-2005 | 0.5 years | | | | handle |
| | LNILU0076 | | \$ 3818.00 \$ 982.00 | 20 | 01-10-2005 | -9.5 years | 90.12% | Good | Retain | handle N/A |
| | | Cabinets | | | | | | Good | Retain Retain | |
| | LNILU0077 | Cabinets Vinyl | \$ 982.00 | 10 | 01-10-2005 | -9.5 years | 90.12% | Good | | N/A |

| | LNILU4742 | Curtains | \$ 888.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
|-----------|---------------------|-----------------------------------|-----------------------|--------------------|-------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------------------------------|
| undry | | | | | | | _ | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0091 | Interior Painting | \$ 249.00 | 10 | 01-10-2005 | -9.5 years | 35.24% | Good | Retain | N/A |
| | LNILU0092 | Tiles - Wall | \$ 1209.00 | 20 | 01-10-2005 | 0.5 years | 17.58% | Good | Retain | N/A |
| | LNILU0093 | Tiles - Floor | \$ 2025.00 | 20 | 01-10-2005 | 0.5 years | 18.02% | Fair | Repair | Clean and re gro |
| | LNILU4743 | Blind | \$ 388.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4744 | Sink & Fittings | \$ 1587.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | N/A |
| | LNILU4745 | Washing Machine | \$ 1332.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| /ing | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0106 | Air Conditioner - Split System | \$ 3296.00 | 10 | 01-10-2005 | -9.5 years | 324.39% | Good | Retain | N/A |
| | LNILU0107 | Blind | \$ 388.00 | 10 | 01-10-2005 | -9.5 years | 36.08% | Good | Retain | N/A |
| | LNILU0108 | Carpet | \$ 1332.00 | 8 | 01-10-2005 | -11.5 years | 1.13% | Good | Retain | N/A |
| | LNILU0109 | Ceiling Fan | \$ 588.00 | 10 | 01-10-2005 | -9.5 years | 16.22% | Good | Retain | N/A |
| | LNILU0110 | Interior Painting | \$ 1065.00 | 10 | 01-10-2005 | -9.5 years | 16.23% | Good | Retain | N/A |
| | LNILU4747 | Curtains | \$ 888.00 | 6 | 17-11-2022 | 3.7 years | 0.00% | Good | Retain | N/A |
| ilet room | | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0101 | Skylight | \$ 1010.00 | 10 | 01-10-2005 | -9.5 years | 1.80% | Good | Retain | N/A |
| | LNILU0102 | Toilet & Cistern | \$ 1343.00 | 20 | 01-10-2005 | 0.5 years | 90.10% | Fair | Repair | Toilet mounting cracking |
| | LNILU0103 | Tiles - Wall | \$ 899.00 | 20 | 01-10-2005 | 0.5 years | 7.66% | Fair | Repair | Various drill hol on the wall |
| | LNILU0104 | Tiles - Floor | \$ 1387.00 | 20 | 01-10-2005 | 0.5 years | 2.25% | Good | Retain | N/A |
| | LNILU0105 | Tapware | \$ 244.00 | 15 | 01-10-2005 | -4.5 years | 120.22% | Good | Retain | N/A |
| | LNILU4746 | Exhaust Fan | \$ 255.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| t Exterio | r | | | | | | | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0117 | Bargeboards | \$ 1498.00 | 20 | 01-10-2005 | 0.5 years | 8.79% | Good | Retain | N/A |

| LNILU4227 | Awnings | \$ 9435.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Fair | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|-----|
| LNILU0133 | Balcony Flooring | \$ 3574.00 | 20 | 01-07-1982 | -22.7 years | 6.86% | Good | Retain | N/A |
| LNILU0132 | Balustrade | \$ 1887.00 | 20 | 01-07-1982 | -22.7 years | 9.01% | Good | Retain | N/A |
| LNILU0131 | Windows | \$ 7747.00 | 30 | 01-07-1982 | -12.7 years | 2.10% | Good | Retain | N/A |
| LNILU0130 | Water Tank | \$ 1032.00 | 25 | 01-07-1982 | -17.7 years | 4.51% | Good | Retain | N/A |
| LNILU0129 | Porch | \$ 3207.00 | 30 | 01-07-1982 | -12.7 years | 9.01% | Good | Retain | N/A |
| LNILU0128 | Path | \$ 1509.00 | 30 | 01-07-1982 | -12.7 years | 12.76% | Good | Retain | N/A |
| LNILU0127 | Lattice Screening | \$ 2142.00 | 20 | 01-07-1982 | -22.7 years | 17.57% | Good | Retain | N/A |
| LNILU0126 | Hot Water System - Solar | \$ 4384.00 | 15 | 01-07-1982 | -27.7 years | 23.43% | Good | Retain | N/A |
| LNILU0125 | Guttering | \$ 2819.00 | 20 | 01-07-1982 | -22.7 years | 57.44% | Good | Retain | N/A |
| LNILU0124 | Flyscreens | \$ 1864.00 | 10 | 01-07-1982 | -32.7 years | 23.43% | Good | Retain | N/A |
| LNILU0123 | Fascias | \$ 2874.00 | 20 | 01-07-1982 | -22.7 years | 18.02% | Good | Retain | N/A |
| LNILU0122 | Exterior Painting | \$ 2086.00 | 10 | 01-07-1982 | -32.7 years | 8.11% | Good | Retain | N/A |
| LNILU0121 | Electrical Switchboard | \$ 1964.00 | 20 | 01-07-1982 | -22.7 years | 11.27% | Good | Retain | N/A |
| LNILU0120 | Downpipes | \$ 1742.00 | 20 | 01-07-1982 | -22.7 years | 52.26% | Good | Retain | N/A |
| LNILU0119 | Doors | \$ 8946.00 | 30 | 01-07-1982 | -12.7 years | 11.71% | Good | Retain | N/A |
| LNILU0118 | Clothesline | \$ 499.00 | 10 | 01-07-1982 | -32.7 years | 16.23% | Good | Retain | N/A |

Unit G3

Bathroom

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|--------------------------------------------------------|
| LNILU0159 | Exhaust Fan | \$ 255.00 | 10 | 01-11-2006 | -8.4 years | 35.18% | Good | Retain | N/A |
| LNILU0160 | Interior Painting | \$ 222.00 | 10 | 01-11-2006 | -8.4 years | 36.04% | Good | Retain | N/A |
| LNILU0161 | Shower Screen | \$ 1165.00 | 20 | 01-11-2006 | 1.6 years | 0.45% | Fair | Repair | Excessive Mold and rust on the bottom of shower screen |
| LNILU0162 | Skylight | \$ 1010.00 | 10 | 01-11-2006 | -8.4 years | 3.60% | Fair | Retain | N/A |
| LNILU0163 | Tapware | \$ 1304.00 | 15 | 01-11-2006 | -3.4 years | 54.06% | Fair | Retain | N/A |
| LNILU0164 | Tiles - Wall | \$ 3285.00 | 20 | 01-11-2006 | 1.6 years | 21.63% | Good | Retain | N/A |
| LNILU0165 | Tiles - Floor | \$ 3940.00 | 20 | 01-11-2006 | 1.6 years | 0.90% | Fair | Retain | N/A |

| _ | | |
|----|---|--|
| ĸД | ~ | |
| uc | u | |

| bea i | | | | | | | | | | |
|---------|--------------|-------------------|-----------------------|--------------------|-------------------|--------------------------|---------------------------------------------|-----------------|--------|-------------------------------------------------------|
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0147 | Blind | \$ 333.00 | 10 | 01-11-2006 | -8.4 years | 35.14% | Good | Retain | N/A |
| | LNILU0148 | Carpet | \$ 865.00 | 8 | 01-11-2006 | -10.4 years | 22.54% | Good | Retain | N/A |
| | LNILU0149 | Ceiling Fan | \$ 588.00 | 10 | 01-11-2006 | -8.4 years | 34.25% | Fair | Retain | N/A |
| | LNILU0150 | Interior Painting | \$ 704.00 | 10 | 01-11-2006 | -8.4 years | 16.24% | Good | Retain | N/A |
| | LNILU0151 | Wardrobe | \$ 2053.00 | 10 | 01-11-2006 | -8.4 years | 2.70% | Good | Retain | N/A |
| Bed 2 | | | | | , | | | | | <u>'</u> |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0152 | Blind | \$ 333.00 | 10 | 01-11-2006 | -8.4 years | 36.04% | Good | Retain | N/A |
| | LNILU0153 | Carpet | \$ 721.00 | 8 | 01-11-2006 | -10.4 years | 3.94% | Good | Retain | N/A |
| | LNILU0154 | Interior Painting | \$ 588.00 | 10 | 01-11-2006 | -8.4 years | 15.32% | Good | Retain | N/A |
| Dining | | | ' | | | | <u>'</u> | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0175 | Blind | \$ 388.00 | 10 | 01-11-2006 | -8.4 years | 4.51% | Good | Retain | N/A |
| | LNILU0176 | Carpet | \$ 621.00 | 8 | 01-11-2006 | -10.4 years | 22.54% | Good | Retain | N/A |
| | LNILU0177 | Ceiling Fan | \$ 588.00 | 10 | 01-11-2006 | -8.4 years | 16.22% | Good | Retain | N/A |
| | LNILU0178 | Interior Painting | \$ 499.00 | 10 | 01-11-2006 | -8.4 years | 266.66% | Fair | Repair | Various stains on the wall; requires r painting |
| Hallway | | | ' | | | | ' | | | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0179 | Carpet | \$ 344.00 | 8 | 01-11-2006 | -10.4 years | 7.32% | Good | Retain | N/A |
| | LNILU0180 | Interior Painting | \$ 277.00 | 10 | 01-11-2006 | -8.4 years | 1.81% | Fair | Retain | N/A |
| Kitchen | | | | | | | | | - | |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| | LNILU0138 | Blind | \$ 277.00 | 10 | 01-11-2006 | -8.4 years | 12.64% | Good | Retain | N/A |
| | LNILU0139 | Benchtops | \$ 2344.00 | 20 | 01-11-2006 | 1.6 years | 4.05% | Good | Retain | N/A |
| | LNILU0140 | Cooktop | \$ 1354.00 | 12 | 01-11-2006 | -6.4 years | 12.76% | Good | Retain | N/A |
| | LNILU0141 | Interior Painting | \$ 421.00 | 10 | 01-11-2006 | -8.4 years | 4.51% | Fair | Retain | N/A |
| | | | | | | | | | | |

01-11-2006 1.6 years

7.66% Good

Retain

N/A

\$ 3818.00

20

Kitchen Cabinets

LNILU0142

| | LNILU0167 | Toilet & Cistern | \$ 1343.00 | 20 | 01-11-2006 | 1.6 years | 87.84% | Good | Retain | N/A |
|---------|------------------------|-----------------------------------|-----------------------------------|--------------------|------------------------------|-------------------------------------|-----------------------------------------------------|------------------------|-----------------------|------------------|
| | Asset Number LNILU0166 | Asset Name Skylight | Acquisition Cost (\$) \$ 1010.00 | Effective Life (Y) | Installation Date 01-11-2006 | Remaining Effective Life -8.4 years | Accumulated Repair Cost as % of Acquisition 28.83% | Asset Condition Good | Plan Retain | Comments N/A |
| et room | | | | | | | | | | |
| | LNILU0174 | Interior Painting | \$ 1065.00 | 10 | 01-11-2006 | -8.4 years | 12.62% | Fair | Retain | N/A |
| | LNILU0173 | Carpet | \$ 1332.00 | 8 | 01-11-2006 | -10.4 years | 3.94% | Good | Retain | N/A |
| | LNILU0172 | Blind | \$ 388.00 | 10 | 01-11-2006 | -8.4 years | 36.08% | Good | Retain | N/A |
| | LNILU0171 | Air Conditioner - Split System | \$ 3296.00 | 10 | 01-11-2006 | -8.4 years | 324.39% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| g | | | | | | | | | | |
| | LNILU4751 | Washing Machine | \$ 1332.00 | 12 | 17-11-2022 | 9.7 years | 0.00% | Good | Retain | N/A |
| | LNILU4750 | Sink & Fittings | \$ 1587.00 | 15 | 17-11-2022 | 12.7 years | 0.00% | Fair | Retain | N/A |
| | LNILU4749 | Blind | \$ 388.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |
| | LNILU0158 | Tiles - Floor | \$ 2025.00 | 20 | 01-11-2006 | 1.6 years | 12.00% | Fair | Repair | Clean and re g |
| | LNILU0157 | Tiles - Wall | \$ 1209.00 | 20 | 01-11-2006 | 1.6 years | 17.58% | Good | Retain | N/A |
| | LNILU0156 | Interior Painting | \$ 249.00 | 10 | 01-11-2006 | -8.4 years | 36.14% | Good | Retain | N/A |
| | Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
| dry | | ' | | | | | | | | ' |
| | LNILU4741 | Rangehood | \$ 1354.00 | 12 | 20-07-2023 | 10.3 years | 0.00% | Excellent | Retain | N/A |
| | LNILU4740 | Oven | \$ 1354.00 | 12 | 20-07-2023 | 10.3 years | 0.00% | Excellent | Retain | N/A |
| | LNILU0146 | Sink & Fittings | \$ 1587.00 | 15 | 01-11-2006 | -3.4 years | 120.14% | Good | Retain | cracking visible |
| | LNILU0143 | Vinyl | \$ 982.00 | 10 | 01-11-2006 | -8.4 years | 4.51% | Fair | Repair | Various stains |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0166 | Skylight | \$ 1010.00 | 10 | 01-11-2006 | -8.4 years | 28.83% | Good | Retain | N/A |
| LNILU0167 | Toilet & Cistern | \$ 1343.00 | 20 | 01-11-2006 | 1.6 years | 87.84% | Good | Retain | N/A |
| LNILU0168 | Tiles - Wall | \$ 899.00 | 20 | 01-11-2006 | 1.6 years | 17.57% | Good | Retain | N/A |
| LNILU0169 | Tiles - Floor | \$ 1387.00 | 20 | 01-11-2006 | 1.6 years | 21.63% | Fair | Retain | N/A |
| LNILU0170 | Tapware | \$ 244.00 | 15 | 01-11-2006 | -3.4 years | 117.21% | Fair | Retain | N/A |
| LNILU4752 | Exhaust Fan | \$ 255.00 | 10 | 17-11-2022 | 7.7 years | 0.00% | Good | Retain | N/A |

| Asset Number | Asset Name | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | Remaining Effective Life | Accumulated Repair Cost as % of Acquisition | Asset Condition | Plan | Comments |
|---------------------|-------------------|-----------------------|--------------------|--------------------------|--------------------------|----------------------------------------------------|------------------------|--------|----------|
| LNILU0181 | Bargeboards | \$ 1498.00 | 20 | 01-11-2006 | 1.6 years | 9.01% | Good | Retain | N/A |

| LNILU0182 | Clothesline | \$ 499.00 | 10 | 01-07-1982 | -32.7 years | 16.23% | Good | Retain | N/A |
|-----------|-----------------------------|------------|----|------------|-------------|--------|------|--------|--------------------------|
| LNILU0183 | Doors | \$ 8946.00 | 30 | 01-07-1982 | -12.7 years | 1.80% | Good | Retain | N/A |
| LNILU0184 | Downpipes | \$ 1742.00 | 20 | 01-07-1982 | -22.7 years | 26.75% | Good | Retain | N/A |
| LNILU0185 | Electrical Switchboard | \$ 1964.00 | 20 | 01-07-1982 | -22.7 years | 4.51% | Good | Retain | N/A |
| LNILU0186 | Exterior Painting | \$ 2086.00 | 10 | 01-07-1982 | -32.7 years | 17.12% | Good | Retain | N/A |
| LNILU0187 | Fascias | \$ 2874.00 | 20 | 01-07-1982 | -22.7 years | 18.02% | Good | Retain | N/A |
| LNILU0188 | Flyscreens | \$ 1864.00 | 10 | 01-07-1982 | -32.7 years | 9.01% | Good | Retain | N/A |
| LNILU0189 | Guttering | \$ 2819.00 | 20 | 01-07-1982 | -22.7 years | 40.55% | Good | Retain | N/A |
| LNILU0190 | Hot Water System - Solar | \$ 4384.00 | 15 | 01-07-1982 | -27.7 years | 24.03% | Good | Retain | N/A |
| LNILU0191 | Lattice Screening | \$ 2142.00 | 20 | 01-07-1982 | -22.7 years | 17.57% | Good | Retain | N/A |
| LNILU0192 | Path | \$ 1509.00 | 30 | 01-07-1982 | -12.7 years | 0.15% | Good | Retain | N/A |
| LNILU0193 | Porch | \$ 3207.00 | 30 | 01-07-1982 | -12.7 years | 27.03% | Good | Retain | N/A |
| LNILU0194 | Water Tank | \$ 1032.00 | 25 | 01-07-1982 | -17.7 years | 36.05% | Good | Retain | N/A |
| LNILU0195 | Windows | \$ 7747.00 | 30 | 01-07-1982 | -12.7 years | 3.90% | Fair | Repair | Repair rubber seal B1 |
| LNILU0196 | Balustrade | \$ 1887.00 | 20 | 01-07-1982 | -22.7 years | 1.13% | Good | Retain | N/A |
| LNILU0197 | Balcony Flooring | \$ 3574.00 | 20 | 01-07-1982 | -22.7 years | 3.83% | Good | Retain | N/A |
| LNILU4228 | Awnings | \$ 9435.00 | 10 | 15-01-2010 | -5.2 years | 0.00% | Good | Retain | N/A |