

Asset Register - Narrabri - AJ000

Common

Carports

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0945    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0946    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0947    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0948    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0949    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0950    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0951    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0952    | Carport    | Good            |              |       |           | 4480                  | 30                 | 01/01/1984        | 100              |             |

Grounds

| Asset Number | Asset Name                | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|---------------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0953    | Distribution Board        | Good            |              |       |           | 1344                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0954    | Drainage                  | Good            |              |       |           | 224000                | 50                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0955    | Fencing                   | Good            |              |       |           | 5600                  | 20                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0956    | Gas Meter                 | Good            |              |       |           | 224                   | 15                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0957    | Kerb & Gutter             | Good            |              |       |           | 85120                 | 50                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0958    | Letterboxes               | Good            |              |       |           | 672                   | 30                 | 01/01/1984        | 100              |             |
| NRILU0959    | Lighting Bollards         | Good            |              |       |           | 1120                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0960    | Power Supply              | Good            |              |       |           | 1344                  | 40                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0961    | Roads                     | Good            |              |       |           | 280000                | 25                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0962    | Sewer                     | Good            |              |       |           | 280000                | 80                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0963    | Signage                   | Good            |              |       |           | 11200                 | 7                  | 01/01/1984        | 25               | Aged Care   |
| NRILU0964    | Telephone/Com ms services | Good            |              |       |           | 5600                  | 40                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0965    | Water Mains               | Good            |              |       |           | 2240                  | 80                 | 01/01/1984        | 25               | Aged Care   |
| NRILU0966    | Patio                     | Good            |              |       |           | 2004                  | 30                 | 01/01/1984        | 100              |             |

Unit 1-4

|           |            |      |  |  |  |       |    |            |    |           |
|-----------|------------|------|--|--|--|-------|----|------------|----|-----------|
| NRILU0967 | Hydrants   | Good |  |  |  | 16800 | 30 | 01/01/1984 | 25 | Aged Care |
| NRILU1053 | FIP System | Good |  |  |  | 56000 | 15 | 01/01/1984 |    |           |

Common

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0001    | Roof       | Good            |              |       |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 1

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model       | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|-------------|----------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0002    | Hot Water System - Electric | Good            | Aqua Max     | EM50S36-HWA | 4180041-001290 | 2408                  | 12                 | 01/12/2003        | 100              |             |
| NRILU0003    | Insulation                  | Fair            |              |             |                | 3584                  | 20                 | 01/12/2003        | 100              |             |
| NRILU0004    | Lighting                    | Fair            |              |             |                | 1926                  | 15                 | 01/12/2003        | 100              |             |
| NRILU0005    | Sarking                     | Poor            |              |             |                | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0006    | Smoke Alarms                | Good            |              |             |                | 263                   | 20                 | 01/12/2003        | 100              |             |
| NRILU0007    | Electrical Switchboard      | Good            | Nfederal     |             |                | 1982                  | 20                 | 01/12/2003        | 100              |             |

Unit 2

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No   | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|-------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0048    | Hot Water System - Electric | Good            | Dux Proflo   | 50V1-24C | 29514444983 | 2408                  | 12                 | 01/11/2004        | 100              |             |
| NRILU0049    | Insulation                  | Good            |              |          |             | 3584                  | 20                 | 01/11/2004        | 100              |             |
| NRILU0050    | Lighting                    | Good            |              |          |             | 1926                  | 15                 | 01/11/2004        | 100              |             |
| NRILU0051    | Sarking                     | Good            |              |          |             | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0052    | Smoke Alarms                | Good            |              |          |             | 263                   | 20                 | 01/11/2004        | 100              |             |
| NRILU0053    | Electrical Switchboard      | Good            |              |          |             | 1982                  | 20                 | 01/11/2004        | 100              |             |
| NRILU1054    | Hot Water System - Electric | Good            | Rheem        | 191050V7 | V110370623  | 2408                  | 12                 | 09/01/2024        |                  |             |

Unit 3

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No  | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0094    | Hot Water System - Electric | Good            | Dux Proflo   | 50V1-36C | 2792555689 | 2408                  | 12                 | 01/11/2005        | 100              |             |
| NRILU0095    | Insulation                  | Good            |              |          |            | 3584                  | 20                 | 01/11/2005        | 100              |             |
| NRILU0096    | Lighting                    | Good            |              |          |            | 1926                  | 15                 | 01/11/2005        | 100              |             |
| NRILU0097    | Sarking                     | Good            |              |          |            | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0098    | Smoke Alarms                | Good            |              |          |            | 263                   | 20                 | 01/11/2005        | 100              |             |

Unit 4

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0140    | Hot Water System - Electric | Good            | Dux Proflo   | 50V1-48C | 206116294 | 2408                  | 12                 | 01/07/2004        | 100              |             |
| NRILU0141    | Insulation                  | Good            |              |          |           | 3584                  | 20                 | 01/07/2004        | 100              |             |
| NRILU0142    | Lighting                    | Good            |              |          |           | 1926                  | 15                 | 01/07/2004        | 100              |             |
| NRILU0143    | Sarking                     | Good            |              |          |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0144    | Smoke Alarms                | Good            |              |          |           | 263                   | 20                 | 01/07/2004        | 100              |             |
| NRILU0145    | Electrical Switchboard      | Good            |              |          |           | 1982                  | 20                 | 01/07/2004        | 100              |             |

Unit 1

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0022    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/12/2003        | 100              |             |
| NRILU0023    | Interior Painting | Poor            |              |       |           | 2464                  | 10                 | 01/12/2003        | 100              |             |
| NRILU0024    | Tapware           | Fair            |              |       |           | 1316                  | 15                 | 01/12/2003        | 100              |             |
| NRILU0025    | Shower Screen     | Fair            |              |       |           | 2576                  | 20                 | 01/12/2003        | 100              |             |
| NRILU0026    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/12/2003        | 100              |             |
| NRILU0027    | Tiles - Wall      | Fair            |              |       |           | 3763                  | 20                 | 01/12/2003        | 100              |             |
| NRILU0028    | Toilet & Cistern  | Fair            |              |       |           | 2027                  | 20                 | 01/12/2003        | 100              |             |
| NRILU0968    | Sink & Fittings   | Poor            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

| Bed 1   |              |                                |                 |              |           |           |                       |                    |                   |                  |             |
|---------|--------------|--------------------------------|-----------------|--------------|-----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|         | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model     | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0017    | Blind                          | Good            |              |           |           | 504                   | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0018    | Carpet                         | Fair            |              |           |           | 2800                  | 8                  | 01/12/2003        | 100              |             |
|         | NRILU0019    | Ceiling Fan                    | Good            |              |           |           | 593                   | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0020    | Interior Painting              | Fair            |              |           |           | 2464                  | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0021    | Wardrobe                       | Good            |              |           |           | 3192                  | 10                 | 01/12/2003        | 100              |             |
| Dining  |              |                                |                 |              |           |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model     | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0034    | Carpet                         | Fair            |              |           |           | 2800                  | 8                  | 01/12/2003        | 100              |             |
|         | NRILU0035    | Interior Painting              | Poor            |              |           |           | 2464                  | 10                 | 01/12/2003        | 100              |             |
| Kitchen |              |                                |                 |              |           |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model     | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0008    | Blind                          | Good            |              |           |           | 504                   | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0009    | Benchtops                      | Good            |              |           |           | 2363                  | 20                 | 01/12/2003        | 100              |             |
|         | NRILU0011    | Interior Painting              | Fair            |              |           |           | 2464                  | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0012    | Kitchen Cabinets               | Good            |              |           |           | 3852                  | 20                 | 01/12/2003        | 100              |             |
|         | NRILU0013    | Oven                           | Fair            | Chef         |           |           | 1422                  | 12                 | 01/12/2003        | 100              |             |
|         | NRILU0014    | Rangehood                      | Good            | Westinghouse |           |           | 604                   | 12                 | 01/12/2003        | 100              |             |
|         | NRILU0015    | Sink & Fittings                | Fair            |              |           |           | 2016                  | 15                 | 01/12/2003        | 100              |             |
|         | NRILU0016    | Vinyl Flooring                 | Good            |              |           |           | 4009                  | 10                 | 01/12/2003        | 100              |             |
| Living  |              |                                |                 |              |           |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model     | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0029    | Blind                          | Good            |              |           |           | 504                   | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0030    | Air Conditioner - Split System | Good            | Daikin       | FTX60JVMA | E009704   | 2016                  | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0031    | Carpet                         | Fair            |              |           |           | 2800                  | 8                  | 01/12/2003        | 100              |             |
|         | NRILU0032    | Ceiling Fan                    | Good            |              |           |           | 593                   | 10                 | 01/12/2003        | 100              |             |
|         | NRILU0033    | Interior Painting              | Poor            |              |           |           | 2464                  | 10                 | 01/12/2003        | 100              |             |

| Unit Exterior |                   |                 |              |       |           |                       |                    |                   |                  |             |
|---------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Asset Number  | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0036     | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0037     | Doors             | Very Poor       |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0038     | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0039     | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0040     | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0041     | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0042     | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0043     | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0044     | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0045     | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0046     | Water Meter       | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0047     | Windows           | Poor            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |
| Unit 2        |                   |                 |              |       |           |                       |                    |                   |                  |             |
| Bathroom      |                   |                 |              |       |           |                       |                    |                   |                  |             |
| Asset Number  | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0068     | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/11/2004        | 100              |             |
| NRILU0069     | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2004        | 100              |             |
| NRILU0070     | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/11/2004        | 100              |             |
| NRILU0072     | Tiles - Floor     | Fair            |              |       |           | 5880                  | 20                 | 01/11/2004        | 100              |             |
| NRILU0073     | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/11/2004        | 100              |             |
| NRILU0074     | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/11/2004        | 100              |             |
| NRILU0969     | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |
| NRILU1026     | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 01/11/2004        |                  |             |
| Bed 1         |                   |                 |              |       |           |                       |                    |                   |                  |             |
| Asset Number  | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0063     | Blind             | Good            |              |       |           | 504                   | 10                 | 01/11/2004        | 100              |             |
| NRILU0064     | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/11/2004        | 100              |             |
| NRILU0065     | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/11/2004        | 100              |             |

|               |              |                                |                 |              |            |           |                       |                    |                   |                  |             |
|---------------|--------------|--------------------------------|-----------------|--------------|------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Dining        | NRILU0066    | Interior Painting              | Good            |              |            |           | 2464                  | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0067    | Wardrobe                       | Good            |              |            |           | 3192                  | 10                 | 01/11/2004        | 100              |             |
|               |              |                                |                 |              |            |           |                       |                    |                   |                  |             |
| Kitchen       | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model      | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0080    | Carpet                         | Good            |              |            |           | 2800                  | 8                  | 01/11/2004        | 100              |             |
|               | NRILU0081    | Interior Painting              | Good            |              |            |           | 2464                  | 10                 | 01/11/2004        | 100              |             |
| Living        | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model      | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0054    | Blind                          | Good            |              |            |           | 504                   | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0055    | Benchtops                      | Good            |              |            |           | 2363                  | 20                 | 01/11/2004        | 100              |             |
|               | NRILU0057    | Interior Painting              | Good            |              |            |           | 2464                  | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0058    | Kitchen Cabinets               | Good            |              |            |           | 3852                  | 20                 | 01/11/2004        | 100              |             |
|               | NRILU0059    | Stove                          | Good            | Chef         |            |           | 1680                  | 12                 | 01/11/2004        | 100              |             |
|               | NRILU0060    | Rangehood                      | Good            | Westinghouse |            |           | 604                   | 12                 | 01/11/2004        | 100              |             |
|               | NRILU0061    | Sink & Fittings                | Good            |              |            |           | 2016                  | 15                 | 01/11/2004        | 100              |             |
|               | NRILU0062    | Vinyl                          | Good            |              |            |           | 3360                  | 10                 | 01/11/2004        | 100              |             |
| Unit Exterior | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model      | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0075    | Air Conditioner - Split System | Good            | Daikin       | FTXS50LVMA | E004050   | 2016                  | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0076    | Blind                          | Good            |              |            |           | 504                   | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0077    | Carpet                         | Good            |              |            |           | 2800                  | 8                  | 01/11/2004        | 100              |             |
|               | NRILU0078    | Ceiling Fan                    | Good            |              |            |           | 593                   | 10                 | 01/11/2004        | 100              |             |
|               | NRILU0079    | Interior Painting              | Good            |              |            |           | 2464                  | 10                 | 01/11/2004        | 100              |             |
| Unit Exterior | Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model      | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0082    | Clothesline                    | Good            |              |            |           | 728                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0083    | Doors                          | Good            |              |            |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0084    | Downpipes                      | Good            |              |            |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0085    | Exterior Painting              | Good            |              |            |           | 6160                  | 10                 | 01/01/1984        | 100              |             |

|           |             |      |  |  |  |      |    |            |     |  |
|-----------|-------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0086 | Fascias     | Good |  |  |  | 5140 | 20 | 01/01/1984 | 100 |  |
| NRILU0087 | Flyscreens  | Good |  |  |  | 2240 | 10 | 01/01/1984 | 100 |  |
| NRILU0088 | Guttering   | Good |  |  |  | 2844 | 20 | 01/01/1984 | 100 |  |
| NRILU0089 | Path        | Good |  |  |  | 3763 | 30 | 01/01/1984 | 100 |  |
| NRILU0090 | Porch       | Good |  |  |  | 2979 | 30 | 01/01/1984 | 100 |  |
| NRILU0092 | Water Meter | Good |  |  |  | 1120 | 20 | 01/01/1984 | 100 |  |
| NRILU0093 | Windows     | Good |  |  |  | 3360 | 30 | 01/01/1984 | 100 |  |

Unit 3

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0113    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/11/2005        | 100              |             |
| NRILU0114    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2005        | 100              |             |
| NRILU0115    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/11/2005        | 100              |             |
| NRILU0117    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/11/2005        | 100              |             |
| NRILU0118    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/11/2005        | 100              |             |
| NRILU0119    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/11/2005        | 100              |             |
| NRILU0970    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0108    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/11/2005        | 100              |             |
| NRILU0109    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/11/2005        | 100              |             |
| NRILU0110    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/11/2005        | 100              |             |
| NRILU0111    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2005        | 100              |             |
| NRILU0112    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/11/2005        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0125    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/11/2005        | 100              |             |
| NRILU0126    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2005        | 100              |             |

Kitchen

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0099    | Blind      | Good            |              |       |           | 504                   | 10                 | 01/11/2005        | 100              |             |

|           |                   |      |      |  |  |      |    |            |     |  |
|-----------|-------------------|------|------|--|--|------|----|------------|-----|--|
| NRILU0100 | Benchtops         | Good |      |  |  | 2363 | 20 | 01/11/2005 | 100 |  |
| NRILU0102 | Interior Painting | Good |      |  |  | 2464 | 10 | 01/11/2005 | 100 |  |
| NRILU0103 | Kitchen Cabinets  | Good |      |  |  | 3852 | 20 | 01/11/2005 | 100 |  |
| NRILU0104 | Oven              | Good | Chef |  |  | 1422 | 12 | 01/11/2005 | 100 |  |
| NRILU0105 | Rangehood         | Good |      |  |  | 604  | 12 | 01/11/2005 | 100 |  |
| NRILU0106 | Sink & Fittings   | Good |      |  |  | 2016 | 15 | 01/11/2005 | 100 |  |
| NRILU0107 | Vinyl Flooring    | Good |      |  |  | 4009 | 10 | 01/11/2005 | 100 |  |

Living

| Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0120    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/11/2005        | 100              |             |
| NRILU0121    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL60VGD | 7002711T  | 2016                  | 10                 | 01/11/2005        | 100              |             |
| NRILU0122    | Carpet                         | Good            |                     |             |           | 2800                  | 8                  | 01/11/2005        | 100              |             |
| NRILU0123    | Ceiling Fan                    | Good            |                     |             |           | 593                   | 10                 | 01/11/2005        | 100              |             |
| NRILU0124    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/11/2005        | 100              |             |

Unit Exterior

| Asset Number | Asset Name             | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0127    | Clothesline            | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0128    | Doors                  | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0129    | Downpipes              | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0130    | Electrical Switchboard | Good            |              |       |           | 1982                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0131    | Exterior Painting      | Fair            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0132    | Fascias                | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0133    | Flyscreens             | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0134    | Guttering              | Fair            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0135    | Path                   | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0136    | Porch                  | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0137    | Handrails              | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0138    | Water Meter            | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0139    | Windows                | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 4

| Bathroom  |                 |                   |                 |              |       |           |                       |                    |                   |                  |             |
|-----------|-----------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|           | Asset Number    | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|           | NRILU0160       | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0161       | Interior Painting | Fair            |              |       |           | 2464                  | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0162       | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/07/2004        | 100              |             |
|           | NRILU0164       | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/07/2004        | 100              |             |
|           | NRILU0165       | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/07/2004        | 100              |             |
|           | NRILU0166       | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/07/2004        | 100              |             |
|           | NRILU0971       | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |
| Bed 1     |                 |                   |                 |              |       |           |                       |                    |                   |                  |             |
|           | Asset Number    | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|           | NRILU0155       | Blind             | Good            |              |       |           | 504                   | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0156       | Carpet            | Fair            |              |       |           | 2800                  | 8                  | 01/07/2004        | 100              |             |
|           | NRILU0157       | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0158       | Interior Painting | Fair            |              |       |           | 2464                  | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0159       | Wardrobe          | Fair            |              |       |           | 3192                  | 10                 | 01/07/2004        | 100              |             |
| Dining    |                 |                   |                 |              |       |           |                       |                    |                   |                  |             |
|           | Asset Number    | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|           | NRILU0172       | Carpet            | Fair            |              |       |           | 2800                  | 8                  | 01/07/2004        | 100              |             |
|           | NRILU0173       | Interior Painting | Fair            |              |       |           | 2464                  | 10                 | 01/07/2004        | 100              |             |
| Kitchen   |                 |                   |                 |              |       |           |                       |                    |                   |                  |             |
|           | Asset Number    | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|           | NRILU0146       | Blind             | Good            |              |       |           | 504                   | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0147       | Benchtops         | Good            |              |       |           | 2363                  | 20                 | 01/07/2004        | 100              |             |
|           | NRILU0149       | Interior Painting | Very Poor       |              |       |           | 2464                  | 10                 | 01/07/2004        | 100              |             |
|           | NRILU0150       | Kitchen Cabinets  | Fair            |              |       |           | 3852                  | 20                 | 01/07/2004        | 100              |             |
|           | NRILU0151       | Oven              | Good            | Chef         |       |           | 1422                  | 12                 | 01/07/2004        | 100              |             |
|           | NRILU0152       | Rangehood         | Good            | Westinghouse |       |           | 604                   | 12                 | 01/07/2004        | 100              |             |
| NRILU0153 | Sink & Fittings | Good              |                 |              |       | 2016      | 15                    | 01/07/2004         | 100               |                  |             |

|               |              |                                   |                 |                     |             |           |                       |                    |                   |                  |             |
|---------------|--------------|-----------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Living        | NRILU0154    | Vinyl Flooring                    | Good            |                     |             |           | 4009                  | 10                 | 01/07/2004        | 100              |             |
|               | Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0167    | Blind                             | Good            |                     |             |           | 504                   | 10                 | 01/07/2004        | 100              |             |
|               | NRILU0168    | Air Conditioner<br>- Split System | Good            | Mitsubishi Electric | MSZ-GL60VGD | 7002695T  | 2016                  | 10                 | 01/07/2004        | 100              |             |
|               | NRILU0169    | Carpet                            | Fair            |                     |             |           | 2800                  | 8                  | 01/07/2004        | 100              |             |
|               | NRILU0170    | Ceiling Fan                       | Good            |                     |             |           | 593                   | 10                 | 01/07/2004        | 100              |             |
|               | NRILU0171    | Interior Painting                 | Very Poor       |                     |             |           | 2464                  | 10                 | 01/07/2004        | 100              |             |
| Unit Exterior |              |                                   |                 |                     |             |           |                       |                    |                   |                  |             |
| Unit 5-8      | Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0174    | Clothesline                       | Good            |                     |             |           | 728                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0175    | Doors                             | Good            |                     |             |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0176    | Downpipes                         | Good            |                     |             |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0177    | Exterior<br>Painting              | Good            |                     |             |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0178    | Fascias                           | Good            |                     |             |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0179    | Flyscreens                        | Good            |                     |             |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0180    | Guttering                         | Good            |                     |             |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0181    | Path                              | Good            |                     |             |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0182    | Porch                             | Good            |                     |             |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0183    | Handrails                         | Good            |                     |             |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0184    | Water Meter                       | Good            |                     |             |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0185    | Windows                           | Fair            |                     |             |           | 3360                  | 30                 | 01/01/1984        | 100              |             |
| Common        |              |                                   |                 |                     |             |           |                       |                    |                   |                  |             |
| Unit 5        | Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0186    | Roof                              | Good            |                     |             |           | 22400                 | 50                 | 01/01/1984        | 100              |             |
| Unit 5        | Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0188    | Insulation                        | Good            |                     |             |           | 3584                  | 20                 | 01/01/1984        | 100              |             |

|           |                             |      |          |          |            |      |    |            |     |  |
|-----------|-----------------------------|------|----------|----------|------------|------|----|------------|-----|--|
| NRILU0189 | Lighting                    | Good |          |          |            | 1926 | 15 | 01/01/1984 | 100 |  |
| NRILU0190 | Sarking                     | Good |          |          |            | 4099 | 25 | 01/01/1984 | 100 |  |
| NRILU0191 | Smoke Alarms                | Good |          |          |            | 263  | 20 | 01/01/1984 | 100 |  |
| NRILU0192 | Electrical Switchboard      | Good | Nfederal |          |            | 1982 | 20 | 01/01/1984 | 100 |  |
| NRILU0980 | Hot Water System - Electric | Good | Rheem    | 191050v7 | V110329185 | 2408 | 12 | 08/11/2022 | 100 |  |

Unit 6

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No  | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0236    | Insulation                  | Good            |              |          |            | 3584                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0237    | Lighting                    | Good            |              |          |            | 1926                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0238    | Sarking                     | Good            |              |          |            | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0239    | Smoke Alarms                | Good            |              |          |            | 263                   | 20                 | 01/01/1984        | 100              |             |
| NRILU0240    | Electrical Switchboard      | Good            | Nfederal     |          |            | 1982                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0986    | Hot Water System - Electric | Good            | Rheem        | 191050v7 | V110345653 | 2408                  | 12                 | 08/11/2022        | 100              |             |

Unit 7

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No  | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0284    | Insulation                  | Good            |              |          |            | 3584                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0285    | Lighting                    | Good            |              |          |            | 1926                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0286    | Sarking                     | Good            |              |          |            | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0287    | Smoke Alarms                | Good            |              |          |            | 263                   | 20                 | 01/01/1984        | 100              |             |
| NRILU0288    | Electrical Switchboard      | Good            | Nfederal     |          |            | 1982                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0988    | Hot Water System - Electric | Good            | Rheem        | 191050V7 | V110370614 | 2408                  | 12                 | 08/11/2022        | 100              |             |

Unit 8

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model   | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|---------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0331    | Hot Water System - Electric | Fair            | Aqua Max     | EM50S36 |           | 2408                  | 12                 | 08/05/2024        | 100              |             |

|           |                        |      |          |  |  |      |    |            |     |  |
|-----------|------------------------|------|----------|--|--|------|----|------------|-----|--|
| NRILU0332 | Insulation             | Poor |          |  |  | 3584 | 20 | 01/01/1984 | 100 |  |
| NRILU0333 | Lighting               | Good |          |  |  | 1926 | 15 | 01/01/1984 | 100 |  |
| NRILU0334 | Sarking                | Poor |          |  |  | 4099 | 25 | 01/01/1984 | 100 |  |
| NRILU0335 | Smoke Alarms           | Good |          |  |  | 263  | 20 | 01/01/1984 | 100 |  |
| NRILU0336 | Electrical Switchboard | Good | Nfederal |  |  | 1982 | 20 | 01/01/1984 | 100 |  |

Unit 5

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0208    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0209    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0210    | Tapware           | Excellent       |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0211    | Shower Screen     | Excellent       |              |       |           | 2576                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0212    | Tiles - Floor     | Excellent       |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0213    | Tiles - Wall      | Excellent       |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0214    | Toilet & Cistern  | Excellent       |              |       |           | 2027                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0972    | Sink & Fittings   | Excellent       |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0202    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/01/1984        | 100              |             |
| NRILU0205    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0206    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0207    | Wardrobe          | Excellent       |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0973    | Blind             | Good            |              |       |           | 504                   | 10                 | 08/11/2022        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0222    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0974    | Vinyl             | Excellent       |              |       |           | 3360                  | 10                 | 08/11/2022        | 100              |             |

Kitchen

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0193    | Blind      | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |

|           |                   |      |              |          |          |      |    |            |     |  |
|-----------|-------------------|------|--------------|----------|----------|------|----|------------|-----|--|
| NRILU0194 | Benchtops         | Good |              |          |          | 2363 | 20 | 01/01/1984 | 100 |  |
| NRILU0196 | Interior Painting | Good |              |          |          | 2464 | 10 | 01/01/1984 | 100 |  |
| NRILU0197 | Kitchen Cabinets  | Good |              |          |          | 3852 | 20 | 01/01/1984 | 100 |  |
| NRILU0199 | Rangehood         | Good | Westinghouse |          |          | 604  | 12 | 01/01/1984 | 100 |  |
| NRILU0200 | Sink & Fittings   | Good |              |          |          | 2016 | 15 | 01/01/1984 | 100 |  |
| NRILU0201 | Vinyl             | Good |              |          |          | 3360 | 10 | 01/01/1984 | 100 |  |
| NRILU0975 | Cooktop           | Good | Westinghouse |          |          | 1366 | 12 | 08/11/2022 | 100 |  |
| NRILU0976 | Dishwasher        | Good |              |          |          | 2240 | 8  | 08/11/2022 | 100 |  |
| NRILU0977 | Oven              | Good | Westinghouse | WVE616SC | 21991989 | 1422 | 12 | 08/11/2022 | 100 |  |

Living

| Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0215    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0216    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL60VGD | 7002707T  | 2016                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0218    | Ceiling Fan                    | Good            |                     |             |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0220    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0978    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 08/11/2022        | 100              |             |
| NRILU0979    | Vinyl                          | Good            |                     |             |           | 3360                  | 10                 | 08/11/2022        | 100              |             |

Unit Exterior

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0223    | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0224    | Doors             | Excellent       |              |       |           | 2240                  | 30                 | 08/10/2022        | 100              |             |
| NRILU0225    | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0226    | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0227    | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0228    | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0229    | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0230    | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0231    | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0232    | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |

|           |             |      |  |  |  |      |    |            |     |  |
|-----------|-------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0233 | Water Meter | Good |  |  |  | 1120 | 20 | 01/01/1984 | 100 |  |
| NRILU0234 | Windows     | Good |  |  |  | 3360 | 30 | 01/01/1984 | 100 |  |

Unit 6

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0256    | Exhaust Fan       | Excellent       |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0257    | Interior Painting | Excellent       |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0258    | Tapware           | Excellent       |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0259    | Shower Screen     | Excellent       |              |       |           | 2576                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0260    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0261    | Tiles - Wall      | Excellent       |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0262    | Toilet & Cistern  | Excellent       |              |       |           | 2027                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0982    | Sink & Fittings   | Excellent       |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0250    | Carpet            | Excellent       |              |       |           | 2800                  | 8                  | 01/01/1984        | 100              |             |
| NRILU0251    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0253    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0254    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0255    | Wardrobe          | Excellent       |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0270    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0984    | Blind             | Good            |              |       |           | 504                   | 10                 | 08/11/2022        | 100              |             |
| NRILU1027    | Vinyl             | Good            |              |       |           | 3360                  | 10                 | 08/01/2024        |                  |             |

Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0241    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0242    | Benchtops         | Good            |              |       |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0244    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |

|           |                  |      |              |          |          |      |    |            |     |  |
|-----------|------------------|------|--------------|----------|----------|------|----|------------|-----|--|
| NRILU0245 | Kitchen Cabinets | Good |              |          |          | 3852 | 20 | 01/01/1984 | 100 |  |
| NRILU0247 | Rangehood        | Good | Westinghouse |          |          | 604  | 12 | 01/01/1984 | 100 |  |
| NRILU0248 | Sink & Fittings  | Good |              |          |          | 2016 | 15 | 01/01/1984 | 100 |  |
| NRILU0249 | Vinyl            | Good |              |          |          | 3360 | 10 | 01/01/1984 | 100 |  |
| NRILU1028 | Oven             | Good | Westinghouse | WVE616SC | 32190586 | 1422 | 12 | 08/01/2024 |     |  |
| NRILU1029 | Cooktop          | Good |              |          |          | 1366 | 12 | 08/11/2022 |     |  |
| NRILU1030 | Dishwasher       | Good |              |          |          | 2240 | 8  | 08/11/2022 |     |  |

Living

| Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0263    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0264    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL60VGD | 7002706   | 2016                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0266    | Ceiling Fan                    | Good            |                     |             |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0268    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU1031    | Vinyl                          | Good            |                     |             |           | 3360                  | 10                 | 08/01/2024        |                  |             |

Unit Exterior

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0271    | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0272    | Doors             | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0273    | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0274    | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0275    | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0276    | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0277    | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0278    | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0279    | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0280    | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0281    | Water Meter       | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0282    | Windows           | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 7

| Bathroom |              |                   |                 |              |       |           |                       |                    |                   |                  |             |
|----------|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|          | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|          | NRILU0304    | Exhaust Fan       | Excellent       |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
|          | NRILU0305    | Interior Painting | Excellent       |              |       |           | 2464                  | 10                 | 01/10/2024        | 100              |             |
|          | NRILU0306    | Tapware           | Excellent       |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
|          | NRILU0307    | Shower Screen     | Excellent       |              |       |           | 2576                  | 20                 | 01/10/2024        | 100              |             |
|          | NRILU0308    | Tiles - Floor     | Excellent       |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
|          | NRILU0309    | Tiles - Wall      | Excellent       |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |
|          | NRILU0310    | Toilet & Cistern  | Excellent       |              |       |           | 2027                  | 20                 | 01/01/1984        | 100              |             |
|          | NRILU0987    | Sink & Fittings   | Excellent       |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |
| Bed 1    |              |                   |                 |              |       |           |                       |                    |                   |                  |             |
|          | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|          | NRILU0298    | Carpet            | Excellent       |              |       |           | 2800                  | 8                  | 01/09/2015        | 100              |             |
|          | NRILU0299    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|          | NRILU0300    | Curtain           | Good            |              |       |           | 1792                  | 6                  | 01/01/1984        | 100              |             |
|          | NRILU0301    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/01/1984        | 100              |             |
|          | NRILU0302    | Interior Painting | Excellent       |              |       |           | 2464                  | 10                 | 01/10/2024        | 100              |             |
|          | NRILU0303    | Wardrobe          | Excellent       |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |
| Dining   |              |                   |                 |              |       |           |                       |                    |                   |                  |             |
|          | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|          | NRILU0317    | Carpet            | Excellent       |              |       |           | 2800                  | 8                  | 01/09/2015        | 100              |             |
|          | NRILU0318    | Interior Painting | Excellent       |              |       |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
| Kitchen  |              |                   |                 |              |       |           |                       |                    |                   |                  |             |
|          | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|          | NRILU0289    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|          | NRILU0290    | Benchtops         | Excellent       |              |       |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
|          | NRILU0292    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|          | NRILU0293    | Kitchen Cabinets  | Excellent       |              |       |           | 3852                  | 20                 | 01/01/1984        | 100              |             |
|          | NRILU0294    | Oven              | Excellent       | Chef         |       |           | 1422                  | 12                 | 01/01/1984        | 100              |             |
|          | NRILU0295    | Rangehood         | Excellent       | Westinghouse |       |           | 604                   | 12                 | 01/01/1984        | 100              |             |

|           |                 |           |  |  |  |      |    |            |     |  |
|-----------|-----------------|-----------|--|--|--|------|----|------------|-----|--|
| NRILU0296 | Sink & Fittings | Excellent |  |  |  | 2016 | 15 | 01/01/1984 | 100 |  |
| NRILU0297 | Vinyl Flooring  | Good      |  |  |  | 4009 | 10 | 01/09/2015 | 100 |  |

Living

| Asset Number | Asset Name                     | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0311    | Blind                          | Good            |              |       | 387703706 | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0312    | Air Conditioner - Split System | Good            |              |       |           | 2016                  | 10                 | 30/06/2022        |                  |             |
| NRILU0313    | Carpet                         | Excellent       |              |       |           | 2800                  | 8                  | 01/09/2015        | 100              |             |
| NRILU0314    | Ceiling Fan                    | Good            |              |       |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0315    | Curtain                        | Good            |              |       |           | 1792                  | 6                  | 01/01/1984        | 100              |             |
| NRILU0316    | Interior Painting              | Good            |              |       |           | 2464                  | 10                 | 01/09/2015        | 100              |             |

Unit Exterior

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0319    | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0320    | Doors             | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0321    | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0322    | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0323    | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0324    | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0325    | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0326    | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0327    | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0328    | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0329    | Water Meter       | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0330    | Windows           | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 8

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0352    | Exhaust Fan       | Excellent       |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0353    | Interior Painting | Excellent       |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0354    | Tapware           | Excellent       |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |

|           |                  |           |  |  |  |      |    |            |     |  |
|-----------|------------------|-----------|--|--|--|------|----|------------|-----|--|
| NRILU0355 | Shower Screen    | Excellent |  |  |  | 2576 | 20 | 01/01/1984 | 100 |  |
| NRILU0356 | Tiles - Floor    | Excellent |  |  |  | 5880 | 20 | 01/01/1984 | 100 |  |
| NRILU0357 | Tiles - Wall     | Excellent |  |  |  | 3763 | 20 | 01/01/1984 | 100 |  |
| NRILU0358 | Toilet & Cistern | Excellent |  |  |  | 2027 | 20 | 01/01/1984 | 100 |  |
| NRILU0989 | Sink & Fittings  | Excellent |  |  |  | 2016 | 15 | 08/11/2022 | 100 |  |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0346    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/01/1984        | 100              |             |
| NRILU0347    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0348    | Curtain           | Good            |              |       |           | 1792                  | 6                  | 01/01/1984        | 100              |             |
| NRILU0349    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0350    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0351    | Wardrobe          | Excellent       |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0364    | Vinyl Flooring    | Excellent       |              |       |           | 4009                  | 10                 | 08/10/2024        | 100              |             |
| NRILU0365    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |

Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model   | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|---------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0337    | Blind             | Good            |              |         |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0338    | Benchtops         | Excellent       |              |         |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0340    | Interior Painting | Good            |              |         |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0341    | Kitchen Cabinets  | Excellent       |              |         |           | 3852                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0342    | Oven              | Excellent       | Simpson      | 61D890R |           | 1422                  | 12                 | 01/01/1984        | 100              |             |
| NRILU0343    | Rangehood         | Excellent       | Robinhood    |         |           | 604                   | 12                 | 01/01/1984        | 100              |             |
| NRILU0344    | Sink & Fittings   | Excellent       |              |         |           | 2016                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0345    | Vinyl Flooring    | Good            |              |         |           | 4009                  | 10                 | 01/01/1984        | 100              |             |

Living

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0359    | Blind      | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |

|           |                                   |           |                     |                 |          |      |    |            |     |           |
|-----------|-----------------------------------|-----------|---------------------|-----------------|----------|------|----|------------|-----|-----------|
| NRILU0360 | Air Conditioner<br>- Split System | Good      | Mitsubishi Electric | MSZ-<br>GL60VGD | 7003360T | 2016 | 10 | 01/01/1984 | 100 |           |
| NRILU0361 | Vinyl Flooring                    | Excellent |                     |                 |          | 4009 | 10 | 08/08/2024 | 100 |           |
| NRILU0362 | Ceiling Fan                       | Good      |                     |                 |          | 593  | 10 | 01/01/1984 | 100 |           |
| NRILU0363 | Interior Painting                 | Good      |                     |                 |          | 2464 | 10 | 01/01/1984 | 100 | Aged Care |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0366    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              | Aged Care   |
| NRILU0367    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              | Aged Care   |
| NRILU0368    | Downpipes            | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              | Aged Care   |
| NRILU0369    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              | Aged Care   |
| NRILU0370    | Fascias              | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              | Aged Care   |
| NRILU0371    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0372    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0373    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0374    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0375    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0376    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0377    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 11-12

Common

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0378    | Roof       | Good            |              |       |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 11

| Asset Number | Asset Name                        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0379    | Hot Water<br>System -<br>Electric | Good            | Dux Proflo   |       |           | 2408                  | 12                 | 01/01/1984        | 100              |             |
| NRILU0380    | Insulation                        | Good            |              |       |           | 3584                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0381    | Lighting                          | Good            |              |       |           | 1926                  | 15                 | 01/01/1984        | 100              |             |

|           |                        |      |         |  |  |      |    |            |     |  |
|-----------|------------------------|------|---------|--|--|------|----|------------|-----|--|
| NRILU0382 | Sarking                | Good |         |  |  | 4099 | 25 | 01/01/1984 | 100 |  |
| NRILU0384 | Smoke Alarms           | Good |         |  |  | 263  | 20 | 01/01/1984 | 100 |  |
| NRILU0385 | Electrical Switchboard | Good | Clipsal |  |  | 1982 | 20 | 01/01/1984 | 100 |  |

Unit 12

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model        | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|--------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0439    | Hot Water System - Electric | Good            | Rinnai       | EHFA250S36 H | 5014351   | 2408                  | 12                 | 01/01/1984        | 100              |             |
| NRILU0440    | Insulation                  | Good            |              |              |           | 3584                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0441    | Lighting                    | Good            |              |              |           | 1926                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0442    | Sarking                     | Good            |              |              |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0444    | Smoke Alarms                | Good            |              |              |           | 263                   | 20                 | 01/01/1984        | 100              |             |
| NRILU0445    | Electrical Switchboard      | Good            | Clipsal      |              |           | 1982                  | 20                 | 01/01/1984        | 100              |             |

Unit 11

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0411    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0412    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0413    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0414    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0415    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0416    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0417    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/01/1984        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0396    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0397    | Vinyl Flooring    | Excellent       |              |       |           | 4009                  | 10                 | 08/10/2024        | 100              |             |
| NRILU0399    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0400    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

| Bed 2   |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|---------|--------------|-------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0401    | Carpet            | Good            |              |          |           | 2800                  | 8                  | 01/01/1984        | 100              |             |
|         | NRILU0402    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|         | NRILU0404    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU0405    | Wardrobe          | Good            |              |          |           | 3192                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU1032    | Ceiling Fan       | Good            |              |          |           | 593                   | 10                 | 08/11/2022        |                  |             |
| Dining  |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0424    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU1033    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 09/01/2024        |                  |             |
| Hallway |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0426    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU1034    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 09/01/2024        |                  |             |
| Kitchen |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0386    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|         | NRILU0387    | Benchtops         | Good            |              |          |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
|         | NRILU0390    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU0391    | Kitchen Cabinets  | Good            |              |          |           | 3852                  | 20                 | 01/01/1984        | 100              |             |
|         | NRILU0393    | Rangehood         | Good            | Robinhood    |          |           | 604                   | 12                 | 01/01/1984        | 100              |             |
|         | NRILU0394    | Sink & Fittings   | Good            |              |          |           | 2016                  | 15                 | 01/01/1984        | 100              |             |
|         | NRILU0395    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 01/01/1984        | 100              |             |
|         | NRILU1035    | Oven              | Good            | Westinghouse | WVE616SC | 32190594  | 1422                  | 12                 | 09/01/2024        |                  |             |
|         | NRILU1036    | Dishwasher        | Good            |              |          |           | 2240                  | 8                  | 08/11/2022        |                  |             |
|         | NRILU1037    | Cooktop           | Good            |              |          |           | 1366                  | 12                 | 08/11/2022        |                  |             |
| Laundry |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0406    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/01/1984        | 100              |             |

|           |                 |           |  |  |  |      |    |            |     |  |
|-----------|-----------------|-----------|--|--|--|------|----|------------|-----|--|
| NRILU0407 | Tiles - Floor   | Good      |  |  |  | 5880 | 20 | 01/01/1984 | 100 |  |
| NRILU0408 | Tiles - Wall    | Good      |  |  |  | 3763 | 20 | 01/01/1984 | 100 |  |
| NRILU0992 | Sink & Fittings | Excellent |  |  |  | 2016 | 15 | 01/10/2024 | 100 |  |

Living

| Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model           | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------------|-----------------|---------------------|-----------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0418    | Blind                             | Good            |                     |                 |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0419    | Air Conditioner<br>- Split System | Good            | Mitsubishi Electric | MSZ-<br>GL71VGD | 7011190T  | 2016                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0422    | Interior Painting                 | Good            |                     |                 |           | 2464                  | 10                 | 01/01/1984        | 100              |             |
| NRILU1038    | Vinyl                             | Good            |                     |                 |           | 3360                  | 10                 | 09/01/2024        |                  |             |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0427    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0428    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0429    | Downpipes            | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0430    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0431    | Fascias              | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0432    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0433    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0434    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0435    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0436    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0437    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0438    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 12

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0469    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0470    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |
| NRILU0471    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0472    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/01/1984        | 100              |             |

|           |                  |      |  |  |  |      |    |            |     |  |
|-----------|------------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0473 | Tiles - Floor    | Fair |  |  |  | 5880 | 20 | 01/01/1984 | 100 |  |
| NRILU0474 | Tiles - Wall     | Good |  |  |  | 3763 | 20 | 01/01/1984 | 100 |  |
| NRILU0475 | Toilet & Cistern | Good |  |  |  | 2027 | 20 | 01/01/1984 | 100 |  |
| NRILU0993 | Vanity           | Good |  |  |  | 1232 | 20 | 08/11/2022 | 100 |  |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0456    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0457    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2013        | 100              |             |
| NRILU0459    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |
| NRILU0460    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0461    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2013        | 100              |             |
| NRILU0462    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0464    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |
| NRILU0465    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0481    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2013        | 100              |             |
| NRILU0482    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |

Hallway

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0483    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2013        | 100              |             |
| NRILU0484    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |

Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0446    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0447    | Benchtops         | Good            |              |       |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0450    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |
| NRILU0451    | Kitchen Cabinets  | Good            |              |       |           | 3852                  | 20                 | 01/01/1984        | 100              |             |

|           |                 |      |              |          |          |      |    |            |     |  |
|-----------|-----------------|------|--------------|----------|----------|------|----|------------|-----|--|
| NRILU0452 | Stove           | Good | Westinghouse | WLE525WA | 34300731 | 1680 | 12 | 01/01/1984 | 100 |  |
| NRILU0453 | Rangehood       | Good | Westinghouse |          |          | 604  | 12 | 01/01/1984 | 100 |  |
| NRILU0454 | Sink & Fittings | Good |              |          |          | 2016 | 15 | 01/01/1984 | 100 |  |
| NRILU0455 | Vinyl           | Good |              |          |          | 3360 | 10 | 01/09/2013 | 100 |  |
| NRILU1039 | Exhaust fan     | Good |              |          |          | 257  | 10 | 01/09/2013 |     |  |

Laundry

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0466    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2013        | 100              |             |
| NRILU0467    | Tiles - Floor     | Fair            |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0468    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |

Living

| Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model           | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------------|-----------------|---------------------|-----------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0476    | Blind                             | Good            |                     |                 |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0477    | Air Conditioner<br>- Split System | Good            | Mitsubishi Electric | MSZ-<br>GL71VGD | 7011184   | 2016                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0478    | Carpet                            | Good            |                     |                 |           | 2800                  | 8                  | 01/09/2013        | 100              |             |
| NRILU0480    | Interior Painting                 | Fair            |                     |                 |           | 2464                  | 10                 | 01/09/2013        | 100              |             |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0485    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0486    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0487    | Downpipes            | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0488    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0489    | Fascias              | Fair            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0490    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0491    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0492    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0493    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0494    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0495    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0496    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 13-14

Common

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0497    | Roof       | Good            |              |       |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 13

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0499    | Insulation                  | Good            |              |          |           | 3584                  | 20                 | 01/08/2019        | 100              |             |
| NRILU0500    | Lighting                    | Good            |              |          |           | 1926                  | 15                 | 01/08/2019        | 100              |             |
| NRILU0501    | Sarking                     | Good            |              |          |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0502    | Smoke Alarms                | Good            |              |          |           | 263                   | 20                 | 01/08/2019        | 100              |             |
| NRILU0503    | Electrical Switchboard      | Good            | Clipsal      |          |           | 1982                  | 20                 | 01/08/2019        | 100              |             |
| NRILU1040    | Hot Water System - Electric | Good            | Aqua Max     | 991250R7 | 7168832   | 2408                  | 12                 | 09/01/2024        |                  |             |

Unit 14

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0551    | Hot Water System - Electric | Good            | Aqua Max     | E250S36-HWA |           | 2408                  | 12                 | 01/01/1984        | 100              |             |
| NRILU0552    | Insulation                  | Good            |              |             |           | 3584                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0553    | Lighting                    | Good            |              |             |           | 1926                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0554    | Sarking                     | Good            |              |             |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0555    | Smoke Alarms                | Good            |              |             |           | 263                   | 20                 | 01/01/1984        | 100              |             |
| NRILU0556    | Electrical Switchboard      | Good            | Clipsal      |             |           | 1982                  | 20                 | 01/01/1984        | 100              |             |

Unit 13

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0525    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/08/2019        | 100              |             |
| NRILU0526    | Interior Painting | Fair            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |
| NRILU0527    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/08/2019        | 100              |             |

|           |                  |      |  |  |  |      |    |            |     |  |
|-----------|------------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0528 | Shower Screen    | Good |  |  |  | 2576 | 20 | 01/08/2019 | 100 |  |
| NRILU0529 | Tiles - Floor    | Fair |  |  |  | 5880 | 20 | 01/08/2019 | 100 |  |
| NRILU0530 | Tiles - Wall     | Good |  |  |  | 3763 | 20 | 01/08/2019 | 100 |  |
| NRILU0531 | Toilet & Cistern | Good |  |  |  | 2027 | 20 | 01/08/2019 | 100 |  |
| NRILU0994 | Vanity           | Good |  |  |  | 1232 | 20 | 08/11/2022 | 100 |  |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0513    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/08/2019        | 100              |             |
| NRILU0514    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/08/2019        | 100              |             |
| NRILU0515    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |
| NRILU0516    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/08/2019        | 100              |             |

Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0517    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/08/2019        | 100              |             |
| NRILU0518    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/08/2019        | 100              |             |
| NRILU0519    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |
| NRILU0520    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/08/2019        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0535    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/08/2019        | 100              |             |
| NRILU0536    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |

Hallway

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0537    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/08/2019        | 100              |             |
| NRILU0538    | Interior Painting | Fair            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |

Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0504    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/08/2019        | 100              |             |
| NRILU0505    | Benchtops         | Good            |              |       |           | 2363                  | 20                 | 01/08/2019        | 100              |             |
| NRILU0506    | Cooktop           | Good            | Euro Kera    |       |           | 1366                  | 12                 | 01/08/2019        | 100              |             |
| NRILU0507    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |

|           |                  |      |              |            |             |      |    |            |     |  |
|-----------|------------------|------|--------------|------------|-------------|------|----|------------|-----|--|
| NRILU0508 | Kitchen Cabinets | Good |              |            |             | 3852 | 20 | 01/08/2019 | 100 |  |
| NRILU0509 | Oven             | Good | Platinum     | AUPL-F65SS | 09221-00163 | 1422 | 12 | 01/08/2019 | 100 |  |
| NRILU0510 | Rangehood        | Good | Westinghouse |            |             | 604  | 12 | 01/08/2019 | 100 |  |
| NRILU0511 | Sink & Fittings  | Good |              |            |             | 2016 | 15 | 01/08/2019 | 100 |  |
| NRILU0512 | Vinyl            | Good |              |            |             | 3360 | 10 | 01/08/2019 | 100 |  |

**Laundry**

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0522    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/08/2019        | 100              |             |
| NRILU0523    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/08/2019        | 100              |             |
| NRILU0995    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

**Living**

| Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model        | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|---------------------|--------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0521    | Blind                          | Good            |                     |              |           | 504                   | 10                 | 01/08/2019        | 100              |             |
| NRILU0532    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ7011164 T |           | 2016                  | 10                 | 01/08/2019        | 100              |             |
| NRILU0533    | Carpet                         | Good            |                     |              |           | 2800                  | 8                  | 01/08/2019        | 100              |             |
| NRILU0534    | Interior Painting              | Good            |                     |              |           | 2464                  | 10                 | 01/08/2019        | 100              |             |

**Unit Exterior**

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0539    | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0540    | Doors             | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0541    | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0542    | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0543    | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0544    | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0545    | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0546    | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0547    | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0548    | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0549    | Water Meter       | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |

|           |         |      |  |  |  |      |    |            |     |  |
|-----------|---------|------|--|--|--|------|----|------------|-----|--|
| NRILU0550 | Windows | Good |  |  |  | 3360 | 30 | 01/01/1984 | 100 |  |
|-----------|---------|------|--|--|--|------|----|------------|-----|--|

## Unit 14

## Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0577    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0578    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2016        | 100              |             |
| NRILU0579    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/01/1984        | 100              |             |
| NRILU0580    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0581    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0582    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0583    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0996    | Vanity            | Good            |              |       |           | 1232                  | 20                 | 08/11/2022        | 100              |             |

### Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0566    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0567    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2016        | 100              |             |
| NRILU0568    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2016        | 100              |             |

## Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0570    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2016        | 100              |             |
| NRILU0571    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0572    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2016        | 100              |             |
| NRILU0573    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/01/1984        | 100              |             |

## Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0588    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2016        | 100              |             |
| NRILU0589    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2016        | 100              |             |

## Hallway

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0590    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2016        | 100              |             |
| NRILU0591    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2016        | 100              |             |

| Kitchen       |              |                                |                 |                     |             |           |                       |                    |                   |                  |             |
|---------------|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0557    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0558    | Benchtops                      | Good            |                     |             |           | 2363                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0560    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/09/2016        | 100              |             |
|               | NRILU0561    | Kitchen Cabinets               | Good            |                     |             |           | 3852                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0562    | Stove                          | Good            | Chef                | CFE535WB    | 82500688  | 1680                  | 12                 | 01/01/1984        | 100              |             |
|               | NRILU0563    | Rangehood                      | Good            | Westinghouse        |             |           | 604                   | 12                 | 01/01/1984        | 100              |             |
|               | NRILU0564    | Sink & Fittings                | Good            |                     |             |           | 2016                  | 15                 | 01/01/1984        | 100              |             |
|               | NRILU0565    | Vinyl                          | Good            |                     |             |           | 3360                  | 10                 | 01/09/2016        | 100              |             |
|               | NRILU0997    | Exhaust Fan                    | Good            |                     |             |           | 257                   | 10                 | 08/11/2022        | 100              |             |
| Laundry       |              |                                |                 |                     |             |           |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0574    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/09/2016        | 100              |             |
|               | NRILU0575    | Tiles - Floor                  | Good            |                     |             |           | 5880                  | 20                 | 01/01/1984        | 100              |             |
| Living        |              |                                |                 |                     |             |           |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0584    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0585    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL71VGD | 7011181T  | 2016                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0586    | Carpet                         | Good            |                     |             |           | 2800                  | 8                  | 01/09/2016        | 100              |             |
|               | NRILU0587    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/09/2016        | 100              |             |
| Unit Exterior |              |                                |                 |                     |             |           |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0592    | Clothesline                    | Good            |                     |             |           | 728                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0593    | Doors                          | Good            |                     |             |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0594    | Downpipes                      | Good            |                     |             |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0595    | Exterior Painting              | Good            |                     |             |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0596    | Fascias                        | Good            |                     |             |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0597    | Flyscreens                     | Good            |                     |             |           | 2240                  | 10                 | 01/01/1984        | 100              |             |

|           |             |      |  |  |  |      |    |            |     |  |
|-----------|-------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0598 | Guttering   | Good |  |  |  | 2844 | 20 | 01/01/1984 | 100 |  |
| NRILU0599 | Path        | Good |  |  |  | 3763 | 30 | 01/01/1984 | 100 |  |
| NRILU0600 | Porch       | Good |  |  |  | 2979 | 30 | 01/01/1984 | 100 |  |
| NRILU0601 | Handrails   | Good |  |  |  | 1232 | 20 | 01/01/1984 | 100 |  |
| NRILU0602 | Water Meter | Good |  |  |  | 1120 | 20 | 01/01/1984 | 100 |  |
| NRILU0603 | Windows     | Good |  |  |  | 3360 | 30 | 01/01/1984 | 100 |  |

Unit 15-16

Common

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0604    | Roof       | Good            |              |       |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 15

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model       | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|-------------|----------------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0605    | Hot Water System - Electric | Good            | Aqua Max     | E250S36-HWA | 4050041-002943 | 2408                  | 12                 | 01/03/2005        | 100              |             |
| NRILU0606    | Insulation                  | Good            |              |             |                | 3584                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0607    | Lighting                    | Good            |              |             |                | 1926                  | 15                 | 01/03/2005        | 100              |             |
| NRILU0608    | Sarking                     | Good            |              |             |                | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0609    | Smoke Alarms                | Good            |              |             |                | 263                   | 20                 | 01/03/2005        | 100              |             |
| NRILU0611    | Electrical Switchboard      | Good            | Clipsal      |             |                | 1982                  | 20                 | 01/03/2005        | 100              |             |

Unit 16

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model        | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|--------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0662    | Hot Water System - Electric | Good            | Rinnai       | EHFA250S36 H | 5244636   | 2408                  | 12                 | 01/09/2015        | 100              |             |
| NRILU0663    | Insulation                  | Good            |              |              |           | 3584                  | 20                 | 01/09/2015        | 100              |             |
| NRILU0664    | Lighting                    | Good            |              |              |           | 1926                  | 15                 | 01/09/2015        | 100              |             |
| NRILU0665    | Sarking                     | Good            |              |              |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0667    | Smoke Alarms                | Good            |              |              |           | 263                   | 20                 | 01/09/2015        | 100              |             |
| NRILU0668    | Electrical Switchboard      | Good            | Clipsal      |              |           | 1982                  | 20                 | 01/09/2015        | 100              |             |

Unit 15

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0635    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/03/2005        | 100              |             |
| NRILU0636    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0637    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/03/2005        | 100              |             |
| NRILU0638    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0639    | Tiles - Floor     | Fair            |              |       |           | 5880                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0640    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0641    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/03/2005        | 100              |             |
| NRILU1000    | Vanity            | Good            |              |       |           | 1232                  | 20                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0621    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/03/2005        | 100              |             |
| NRILU0622    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/03/2005        | 100              |             |
| NRILU0623    | Curtain           | Good            |              |       |           | 1792                  | 6                  | 01/03/2005        | 100              |             |
| NRILU0624    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0625    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/03/2005        | 100              |             |

Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0626    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/03/2005        | 100              |             |
| NRILU0627    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/03/2005        | 100              |             |
| NRILU0628    | Curtain           | Good            |              |       |           | 1792                  | 6                  | 01/03/2005        | 100              |             |
| NRILU0629    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0630    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/03/2005        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0646    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/03/2005        | 100              |             |
| NRILU0647    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |

## Hallway

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0648    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/03/2005        | 100              |             |
| NRILU0649    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |

## Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0612    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/03/2005        | 100              |             |
| NRILU0613    | Benchtops         | Good            |              |       |           | 2363                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0614    | Curtain           | Good            |              |       |           | 1792                  | 6                  | 01/03/2005        | 100              |             |
| NRILU0615    | Stove             | Fair            | Chef         |       |           | 1680                  | 12                 | 01/03/2005        | 100              |             |
| NRILU0616    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0617    | Kitchen Cabinets  | Good            |              |       |           | 3852                  | 20                 | 01/03/2005        | 100              |             |
| NRILU0619    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 01/03/2005        | 100              |             |
| NRILU0620    | Vinyl             | Good            |              |       |           | 3360                  | 10                 | 01/03/2005        | 100              |             |
| NRILU1001    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 08/11/2022        | 100              |             |
| NRILU1025    | Rangehood         | Good            |              |       |           | 604                   | 12                 | 04/08/2023        | 100              |             |

## Laundry

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0632    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0633    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/03/2005        | 100              |             |
| NRILU1002    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

## Living

| Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0642    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL71VGD | 7011166T  | 2016                  | 10                 | 01/03/2005        | 100              |             |
| NRILU0643    | Carpet                         | Good            |                     |             |           | 2800                  | 8                  | 01/03/2005        | 100              |             |
| NRILU0644    | Curtain                        | Good            |                     |             |           | 1792                  | 6                  | 01/03/2005        | 100              |             |
| NRILU0645    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/03/2005        | 100              |             |
| NRILU1041    | Blind                          | Good            |                     |             |           | 504                   | 10                 | 01/03/2005        |                  |             |

| Unit Exterior |                   |                 |              |       |           |                       |                    |                   |                  |             |
|---------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Asset Number  | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0650     | Clothesline       | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0651     | Doors             | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0652     | Downpipes         | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0653     | Exterior Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0654     | Fascias           | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0655     | Flyscreens        | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0656     | Guttering         | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0657     | Path              | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0658     | Porch             | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0659     | Handrails         | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0660     | Water Meter       | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0661     | Windows           | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 16

| Bathroom     |                   |                 |              |       |           |                       |                    |                   |                  |             |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0690    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/09/2015        | 100              |             |
| NRILU0691    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
| NRILU0692    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/09/2015        | 100              |             |
| NRILU0693    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/09/2015        | 100              |             |
| NRILU0694    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/09/2015        | 100              |             |
| NRILU0695    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/09/2015        | 100              |             |
| NRILU0696    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/09/2015        | 100              |             |

| Bed 1        |                   |                 |              |       |           |                       |                    |                   |                  |             |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
| NRILU0678    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/09/2015        | 100              |             |
| NRILU0679    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/09/2015        | 100              |             |
| NRILU0680    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
| NRILU0681    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/09/2015        | 100              |             |

| Bed 2   | NRILU1042    | Ceiling Fan       | Good            |              |          |           | 593                   | 10                 | 01/09/2015        |                  |             |
|---------|--------------|-------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|         |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
| Bed 2   | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0682    | Carpet            | Good            |              |          |           | 2800                  | 8                  | 01/09/2015        | 100              |             |
|         | NRILU0683    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/09/2015        | 100              |             |
|         | NRILU0684    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU0685    | Wardrobe          | Good            |              |          |           | 3192                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU1043    | Ceiling Fan       | Good            |              |          |           | 593                   | 10                 | 01/09/2015        |                  |             |
| Dining  | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0701    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU1044    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 09/01/2024        |                  |             |
| Hallway | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0703    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU1045    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 09/01/2024        |                  |             |
| Kitchen | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0669    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/09/2015        | 100              |             |
|         | NRILU0670    | Benchtops         | Good            |              |          |           | 2363                  | 20                 | 01/09/2015        | 100              |             |
|         | NRILU0672    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU0673    | Kitchen Cabinets  | Good            |              |          |           | 3852                  | 20                 | 01/09/2015        | 100              |             |
|         | NRILU0675    | Rangehood         | Good            | Westinghouse |          |           | 604                   | 12                 | 01/09/2015        | 100              |             |
|         | NRILU0676    | Sink & Fittings   | Good            |              |          |           | 2016                  | 15                 | 01/09/2015        | 100              |             |
|         | NRILU0677    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 01/09/2015        | 100              |             |
|         | NRILU1046    | Cooktop           | Good            | Westinghouse |          |           | 1366                  | 12                 | 09/01/2024        |                  |             |
|         | NRILU1047    | Oven              | Good            | Westinghouse | WVE616SC | 21090228  | 1422                  | 12                 | 09/01/2024        |                  |             |
|         | NRILU1048    | Exhaust Fan       | Good            |              |          |           | 257                   | 10                 | 01/09/2015        |                  |             |

| Laundry       | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|---------------|--------------|--------------------------------|-----------------|---------------------|-------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
|               | NRILU0687    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|               | NRILU0688    | Tiles - Floor                  | Good            |                     |             |           | 5880                  | 20                 | 01/09/2015        | 100              |             |
|               | NRILU0689    | Tiles - Wall                   | Good            |                     |             |           | 3763                  | 20                 | 01/09/2015        | 100              |             |
| Living        | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0697    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL71VGD | 7011168T  | 2016                  | 10                 | 01/09/2015        | 100              |             |
|               | NRILU0699    | Interior Painting              | Good            |                     |             |           | 2464                  | 10                 | 01/09/2015        | 100              |             |
|               | NRILU1049    | Vinyl                          | Good            |                     |             |           | 3360                  | 10                 | 09/01/2024        |                  |             |
|               | NRILU1050    | Ceiling Fan                    | Good            |                     |             |           | 593                   | 10                 | 01/09/2015        |                  |             |
| Unit Exterior | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0704    | Clothesline                    | Good            |                     |             |           | 728                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0705    | Doors                          | Good            |                     |             |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0706    | Downpipes                      | Good            |                     |             |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0707    | Exterior Painting              | Good            |                     |             |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0708    | Fascias                        | Good            |                     |             |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0709    | Flyscreens                     | Good            |                     |             |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0710    | Guttering                      | Good            |                     |             |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0711    | Path                           | Good            |                     |             |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0712    | Porch                          | Good            |                     |             |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
|               | NRILU0713    | Handrails                      | Good            |                     |             |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0714    | Water Meter                    | Good            |                     |             |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
|               | NRILU0715    | Windows                        | Good            |                     |             |           | 3360                  | 30                 | 01/01/1984        | 100              |             |
| Unit 17-18    |              |                                |                 |                     |             |           |                       |                    |                   |                  |             |
| Common        | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0716    | Roof                           | Good            |                     |             |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 17

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model   | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|---------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0717    | Hot Water System - Electric | Good            | Aqua Max     | E250S48 | 4878      | 2408                  | 12                 | 01/09/2017        | 100              |             |
| NRILU0718    | Insulation                  | Good            |              |         |           | 3584                  | 20                 | 01/09/2017        | 100              |             |
| NRILU0719    | Lighting                    | Good            |              |         |           | 1926                  | 15                 | 01/09/2017        | 100              |             |
| NRILU0720    | Sarking                     | Good            |              |         |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0721    | Smoke Alarms                | Good            |              |         |           | 263                   | 20                 | 01/09/2017        | 100              |             |
| NRILU0722    | Electrical Switchboard      | Good            | Clipsal      |         |           | 1982                  | 20                 | 01/09/2017        | 100              |             |

Unit 18

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0778    | Hot Water System - Electric | Good            | Vulcan       |       |           | 2408                  | 12                 | 01/02/2005        | 100              |             |
| NRILU0779    | Insulation                  | Good            |              |       |           | 3584                  | 20                 | 01/02/2005        | 100              |             |
| NRILU0780    | Lighting                    | Good            |              |       |           | 1926                  | 15                 | 01/02/2005        | 100              |             |
| NRILU0781    | Sarking                     | Good            |              |       |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0782    | Smoke Alarms                | Good            |              |       |           | 263                   | 20                 | 01/02/2005        | 100              |             |
| NRILU0783    | Electrical Switchboard      | Good            | Clipsal      |       |           | 1982                  | 20                 | 01/02/2005        | 100              |             |

Unit 17

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0750    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/09/2017        | 100              |             |
| NRILU0751    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2017        | 100              |             |
| NRILU0752    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/09/2017        | 100              |             |
| NRILU0753    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/09/2017        | 100              |             |
| NRILU0754    | Tiles - Floor     | Excellent       |              |       |           | 5880                  | 20                 | 27/10/2022        | 100              |             |
| NRILU0755    | Tiles - Wall      | Excellent       |              |       |           | 3763                  | 20                 | 27/10/2022        | 100              |             |
| NRILU0756    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/09/2017        | 100              |             |
| NRILU1003    | Vanity            | Good            |              |       |           | 1232                  | 20                 | 08/11/2022        | 100              |             |

|         |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|---------|--------------|-------------------|-----------------|--------------|------------|----------------|-----------------------|--------------------|-------------------|------------------|-------------|
| Bed 1   |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model      | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0733    | Blind             | Good            |              |            |                | 504                   | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0734    | Carpet            | Good            |              |            |                | 2800                  | 8                  | 01/09/2017        | 100              |             |
|         | NRILU0736    | Ceiling Fan       | Good            |              |            |                | 593                   | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0737    | Interior Painting | Good            |              |            |                | 2464                  | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0738    | Wardrobe          | Good            |              |            |                | 3192                  | 10                 | 01/09/2017        | 100              |             |
| Bed 2   |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model      | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0739    | Carpet            | Good            |              |            |                | 2800                  | 8                  | 01/09/2017        | 100              |             |
|         | NRILU0740    | Blind             | Good            |              |            |                | 504                   | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0742    | Ceiling Fan       | Good            |              |            |                | 593                   | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0743    | Interior Painting | Good            |              |            |                | 2464                  | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0744    | Wardrobe          | Good            |              |            |                | 3192                  | 10                 | 01/09/2017        | 100              |             |
| Dining  |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model      | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0762    | Carpet            | Good            |              |            |                | 2800                  | 8                  | 01/09/2017        | 100              |             |
|         | NRILU0763    | Interior Painting | Good            |              |            |                | 2464                  | 10                 | 01/09/2017        | 100              |             |
| Hallway |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model      | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0764    | Vinyl Flooring    | Excellent       |              |            |                | 4009                  | 10                 | 08/10/2024        | 100              |             |
|         | NRILU0765    | Interior Painting | Good            |              |            |                | 2464                  | 10                 | 01/09/2017        | 100              |             |
| Kitchen |              |                   |                 |              |            |                |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model      | Serial No      | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0723    | Blind             | Good            |              |            |                | 504                   | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0724    | Benchtops         | Good            |              |            |                | 2363                  | 20                 | 01/09/2017        | 100              |             |
|         | NRILU0726    | Cooktop           | Good            | Schott Ceran |            |                | 1366                  | 12                 | 01/09/2017        | 100              |             |
|         | NRILU0727    | Interior Painting | Good            |              |            |                | 2464                  | 10                 | 01/09/2017        | 100              |             |
|         | NRILU0728    | Kitchen Cabinets  | Good            |              |            |                | 3852                  | 20                 | 01/09/2017        | 100              |             |
|         | NRILU0729    | Oven              | Good            | Platinum     | AUPL-F65SS | MD-07202-00025 | 1422                  | 12                 | 01/09/2017        | 100              |             |

|           |                 |      |  |  |  |      |    |            |     |  |
|-----------|-----------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0730 | Rangehood       | Good |  |  |  | 604  | 12 | 01/09/2017 | 100 |  |
| NRILU0731 | Sink & Fittings | Good |  |  |  | 2016 | 15 | 01/09/2017 | 100 |  |
| NRILU0732 | Vinyl           | Good |  |  |  | 3360 | 10 | 01/09/2017 | 100 |  |

Laundry

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0746    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2017        | 100              |             |
| NRILU0747    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/09/2017        | 100              |             |
| NRILU0748    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/09/2017        | 100              |             |
| NRILU1004    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Living

| Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model           | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------------|-----------------|---------------------|-----------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0745    | Blind                             | Good            |                     |                 |           | 504                   | 10                 | 01/09/2017        | 100              |             |
| NRILU0757    | Air Conditioner<br>- Split System | Good            | Mitsubishi Electric | MSZ-<br>GL71VGD | 7011172T  | 2016                  | 10                 | 01/09/2017        | 100              |             |
| NRILU0759    | Ceiling Fan                       | Good            |                     |                 |           | 593                   | 10                 | 01/09/2017        | 100              |             |
| NRILU0761    | Interior Painting                 | Good            |                     |                 |           | 2464                  | 10                 | 01/09/2017        | 100              |             |
| NRILU1055    | Vinyl                             | Excellent       |                     |                 |           | 3360                  | 10                 | 01/07/2024        | 100              |             |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0766    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0767    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0768    | Downpipes            | Fair            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0769    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0770    | Fascias              | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0771    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0772    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0773    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0774    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0775    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0776    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0777    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 18

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0805    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/02/2005        | 100              |             |
| NRILU0806    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/02/2005        | 100              |             |
| NRILU0807    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/02/2005        | 100              |             |
| NRILU0808    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/02/2005        | 100              |             |
| NRILU0809    | Tiles - Floor     | Fair            |              |       |           | 5880                  | 20                 | 01/02/2005        | 100              |             |
| NRILU0810    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/02/2005        | 100              |             |
| NRILU0811    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/02/2005        | 100              |             |
| NRILU1005    | Vanity            | Good            |              |       |           | 1232                  | 20                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0793    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/02/2005        | 100              |             |
| NRILU0794    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/02/2005        | 100              |             |
| NRILU0795    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 01/02/2005        | 100              |             |
| NRILU0796    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/02/2005        | 100              |             |
| NRILU0797    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/02/2005        | 100              |             |

Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0798    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/02/2005        | 100              |             |
| NRILU0799    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/02/2005        | 100              |             |
| NRILU0800    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/02/2005        | 100              |             |
| NRILU0801    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/02/2005        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0817    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/02/2005        | 100              |             |
| NRILU0818    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/02/2005        | 100              |             |

Hallway

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0819    | Carpet     | Good            |              |       |           | 2800                  | 8                  | 01/02/2005        | 100              |             |

| Kitchen       | NRILU0820    | Interior Painting              | Good            |                     |             |               | 2464                  | 10                 | 01/02/2005        | 100              |             |
|---------------|--------------|--------------------------------|-----------------|---------------------|-------------|---------------|-----------------------|--------------------|-------------------|------------------|-------------|
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No     | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0784    | Blind                          | Good            |                     |             |               | 504                   | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0785    | Benchtops                      | Good            |                     |             |               | 2363                  | 20                 | 01/02/2005        | 100              |             |
|               | NRILU0786    | Cooktop                        | Good            |                     |             |               | 1366                  | 12                 | 01/02/2005        | 100              |             |
|               | NRILU0787    | Interior Painting              | Good            |                     |             |               | 2464                  | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0788    | Kitchen Cabinets               | Good            |                     |             |               | 3852                  | 20                 | 01/02/2005        | 100              |             |
|               | NRILU0789    | Oven                           | Good            | Platinum            | AUPL-F65SS  | MD-07916-0020 | 1422                  | 12                 | 01/02/2005        | 100              |             |
|               | NRILU0790    | Rangehood                      | Good            | Westinghouse        |             |               | 604                   | 12                 | 01/02/2005        | 100              |             |
|               | NRILU0791    | Sink & Fittings                | Good            |                     |             |               | 2016                  | 15                 | 01/02/2005        | 100              |             |
|               | NRILU0792    | Vinyl                          | Good            |                     |             |               | 3360                  | 10                 | 01/02/2005        | 100              |             |
|               | NRILU1006    | Exhaust Fan                    | Good            |                     |             |               | 257                   | 10                 | 08/11/2022        | 100              |             |
| Laundry       |              |                                |                 |                     |             |               |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No     | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0802    | Interior Painting              | Good            |                     |             |               | 2464                  | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0803    | Tiles - Floor                  | Good            |                     |             |               | 5880                  | 20                 | 01/02/2005        | 100              |             |
|               | NRILU0804    | Tiles - Wall                   | Good            |                     |             |               | 3763                  | 20                 | 01/02/2005        | 100              |             |
|               | NRILU1007    | Sink & Fittings                | Good            |                     |             |               | 2016                  | 15                 | 08/11/2022        | 100              |             |
| Living        |              |                                |                 |                     |             |               |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No     | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0812    | Blind                          | Good            |                     |             |               | 504                   | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0813    | Air Conditioner - Split System | Good            | Mitsubishi Electric | MSZ-GL71VGD | 7011173T      | 2016                  | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0814    | Carpet                         | Good            |                     |             |               | 2800                  | 8                  | 01/07/2020        | 100              |             |
|               | NRILU0815    | Ceiling Fan                    | Good            |                     |             |               | 593                   | 10                 | 01/02/2005        | 100              |             |
|               | NRILU0816    | Interior Painting              | Good            |                     |             |               | 2464                  | 10                 | 01/02/2005        | 100              |             |
| Unit Exterior |              |                                |                 |                     |             |               |                       |                    |                   |                  |             |
|               | Asset Number | Asset Name                     | Asset Condition | Manufacturer        | Model       | Serial No     | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|               | NRILU0821    | Clothesline                    | Good            |                     |             |               | 728                   | 10                 | 01/01/1984        | 100              |             |
|               | NRILU0822    | Doors                          | Good            |                     |             |               | 2240                  | 30                 | 01/01/1984        | 100              |             |

|           |                   |      |  |  |  |      |    |            |     |  |
|-----------|-------------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0823 | Downpipes         | Good |  |  |  | 1758 | 20 | 01/01/1984 | 100 |  |
| NRILU0824 | Exterior Painting | Good |  |  |  | 6160 | 10 | 01/01/1984 | 100 |  |
| NRILU0825 | Fascias           | Good |  |  |  | 5140 | 20 | 01/01/1984 | 100 |  |
| NRILU0826 | Flyscreens        | Good |  |  |  | 2240 | 10 | 01/01/1984 | 100 |  |
| NRILU0827 | Guttering         | Good |  |  |  | 2844 | 20 | 01/01/1984 | 100 |  |
| NRILU0828 | Path              | Good |  |  |  | 3763 | 30 | 01/01/1984 | 100 |  |
| NRILU0829 | Porch             | Good |  |  |  | 2979 | 30 | 01/01/1984 | 100 |  |
| NRILU0830 | Handrails         | Good |  |  |  | 1232 | 20 | 01/01/1984 | 100 |  |
| NRILU0831 | Water Meter       | Good |  |  |  | 1120 | 20 | 01/01/1984 | 100 |  |
| NRILU0832 | Windows           | Good |  |  |  | 3360 | 30 | 01/01/1984 | 100 |  |

Unit 19-20

Common

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0833    | Roof       | Good            |              |       |           | 22400                 | 50                 | 01/01/1984        | 100              |             |

Unit 19

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model        | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|--------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0835    | Insulation                  | Good            |              |              |           | 3584                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0836    | Lighting                    | Good            |              |              |           | 1926                  | 15                 | 01/11/2017        | 100              |             |
| NRILU0837    | Sarking                     | Good            |              |              |           | 4099                  | 25                 | 01/01/1984        | 100              |             |
| NRILU0838    | Smoke Alarms                | Good            |              |              |           | 263                   | 20                 | 01/11/2017        | 100              |             |
| NRILU0839    | Electrical Switchboard      | Good            | Clipsal      |              |           | 1982                  | 20                 | 01/11/2017        | 100              |             |
| NRILU1018    | Hot Water System - Electric | Good            | Rinnai       | EHFA250S24 H | 5283333   | 2408                  | 12                 | 08/11/2022        | 100              |             |

Unit 20

| Asset Number | Asset Name                  | Asset Condition | Manufacturer | Model        | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------|-----------------|--------------|--------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0887    | Hot Water System - Electric | Good            | Rinnai       | EHFA250S36 H | 5222173   | 2408                  | 12                 | 01/09/2021        | 100              |             |
| NRILU0888    | Insulation                  | Good            |              |              |           | 3584                  | 20                 | 01/09/2021        | 100              |             |

|           |                        |      |  |  |  |      |    |            |     |  |
|-----------|------------------------|------|--|--|--|------|----|------------|-----|--|
| NRILU0889 | Lighting               | Good |  |  |  | 1926 | 15 | 01/09/2021 | 100 |  |
| NRILU0890 | Sarking                | Good |  |  |  | 4099 | 25 | 01/01/1984 | 100 |  |
| NRILU0892 | Smoke Alarms           | Good |  |  |  | 263  | 20 | 01/09/2021 | 100 |  |
| NRILU0935 | Electrical Switchboard | Good |  |  |  | 1982 | 20 | 01/01/1984 | 100 |  |

Unit 19

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0860    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/11/2017        | 100              |             |
| NRILU0861    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU0862    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/11/2017        | 100              |             |
| NRILU0863    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0864    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0865    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0866    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/11/2017        | 100              |             |
| NRILU1008    | Vanity            | Good            |              |       |           | 1232                  | 20                 | 08/11/2022        | 100              |             |

Bed 1

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0849    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/11/2017        | 100              |             |
| NRILU0850    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/11/2017        | 100              |             |
| NRILU0851    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU0852    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/11/2017        | 100              |             |
| NRILU1009    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 08/11/2022        | 100              |             |

Bed 2

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0853    | Carpet            | Good            |              |       |           | 2800                  | 8                  | 01/11/2017        | 100              |             |
| NRILU0854    | Blind             | Good            |              |       |           | 504                   | 10                 | 01/11/2017        | 100              |             |
| NRILU0855    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU0856    | Wardrobe          | Good            |              |       |           | 3192                  | 10                 | 01/11/2017        | 100              |             |
| NRILU1010    | Ceiling Fan       | Good            |              |       |           | 593                   | 10                 | 08/11/2022        | 100              |             |

Dining

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0872    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU1011    | Vinyl             | Good            |              |       |           | 3360                  | 10                 | 08/11/2022        | 100              |             |

Hallway

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0874    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU1012    | Vinyl             | Good            |              |       |           | 3360                  | 10                 | 08/11/2022        | 100              |             |

Kitchen

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0840    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/11/2017        | 100              |             |
| NRILU0841    | Benchtops         | Good            |              |          |           | 2363                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0842    | Cooktop           | Good            |              |          |           | 1366                  | 12                 | 01/11/2017        | 100              |             |
| NRILU0843    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU0844    | Kitchen Cabinets  | Good            |              |          |           | 3852                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0846    | Rangehood         | Good            | Westinghouse |          |           | 604                   | 12                 | 01/11/2017        | 100              |             |
| NRILU0847    | Sink & Fittings   | Good            |              |          |           | 2016                  | 15                 | 01/11/2017        | 100              |             |
| NRILU0848    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 01/11/2017        | 100              |             |
| NRILU1013    | Dishwasher        | Good            | Platinum     |          |           | 2240                  | 8                  | 08/11/2022        | 100              |             |
| NRILU1014    | Exhaust Fan       | Good            |              |          |           | 257                   | 10                 | 08/11/2022        | 100              |             |
| NRILU1051    | Oven              | Good            | Westinghouse | WVE616SC |           | 1422                  | 12                 | 09/01/2024        |                  |             |

Laundry

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0857    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/11/2017        | 100              |             |
| NRILU0858    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/11/2017        | 100              |             |
| NRILU0859    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/11/2017        | 100              |             |
| NRILU1015    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Living

| Asset Number | Asset Name | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0867    | Blind      | Good            |              |       |           | 504                   | 10                 | 01/11/2017        | 100              |             |

|           |                                   |      |                     |                 |          |      |    |            |     |  |
|-----------|-----------------------------------|------|---------------------|-----------------|----------|------|----|------------|-----|--|
| NRILU0868 | Air Conditioner<br>- Split System | Good | Mitsubishi Electric | MSZ-<br>GL71VGD | 7011169T | 2016 | 10 | 01/11/2017 | 100 |  |
| NRILU0870 | Interior Painting                 | Good |                     |                 |          | 2464 | 10 | 01/11/2017 | 100 |  |
| NRILU1016 | Ceiling Fan                       | Good |                     |                 |          | 593  | 10 | 08/11/2022 | 100 |  |
| NRILU1017 | Vinyl                             | Good |                     |                 |          | 3360 | 10 | 08/11/2022 | 100 |  |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0875    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0876    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0877    | Downpipes            | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0878    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0879    | Fascias              | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0880    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0881    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0882    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0883    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0884    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0885    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0886    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |

Unit 20

Bathroom

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0916    | Exhaust Fan       | Good            |              |       |           | 257                   | 10                 | 01/09/2021        | 100              |             |
| NRILU0917    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
| NRILU0918    | Tapware           | Good            |              |       |           | 1316                  | 15                 | 01/09/2021        | 100              |             |
| NRILU0919    | Shower Screen     | Good            |              |       |           | 2576                  | 20                 | 01/09/2021        | 100              |             |
| NRILU0920    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/09/2021        | 100              |             |
| NRILU0921    | Tiles - Wall      | Good            |              |       |           | 3763                  | 20                 | 01/09/2021        | 100              |             |
| NRILU0922    | Toilet & Cistern  | Good            |              |       |           | 2027                  | 20                 | 01/09/2021        | 100              |             |

|         |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|---------|--------------|-------------------|-----------------|--------------|----------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| Bed 1   |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0903    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0904    | Carpet            | Good            |              |          |           | 2800                  | 8                  | 01/09/2021        | 100              |             |
|         | NRILU0906    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0907    | Wardrobe          | Good            |              |          |           | 3192                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU1052    | Ceiling Fan       | Good            |              |          |           | 593                   | 10                 | 01/09/2021        |                  |             |
| Bed 2   |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0908    | Carpet            | Good            |              |          |           | 2800                  | 8                  | 01/09/2021        | 100              |             |
|         | NRILU0909    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0911    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0912    | Wardrobe          | Good            |              |          |           | 3192                  | 10                 | 01/09/2021        | 100              |             |
| Dining  |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0929    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU1019    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 08/11/2022        | 100              |             |
| Hallway |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0931    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU1020    | Vinyl             | Good            |              |          |           | 3360                  | 10                 | 08/11/2022        | 100              |             |
| Kitchen |              |                   |                 |              |          |           |                       |                    |                   |                  |             |
|         | Asset Number | Asset Name        | Asset Condition | Manufacturer | Model    | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|         | NRILU0893    | Blind             | Good            |              |          |           | 504                   | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0894    | Benchtops         | Good            |              |          |           | 2363                  | 20                 | 01/09/2021        | 100              |             |
|         | NRILU0896    | Cooktop           | Good            | Westinghouse |          |           | 1366                  | 12                 | 01/09/2021        | 100              |             |
|         | NRILU0897    | Interior Painting | Good            |              |          |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
|         | NRILU0898    | Kitchen Cabinets  | Fair            |              |          |           | 3852                  | 20                 | 01/09/2021        | 100              |             |
|         | NRILU0899    | Oven              | Good            | Westinghouse | WLE525WA | 34300594  | 1422                  | 12                 | 01/09/2021        | 100              |             |
|         | NRILU0900    | Rangehood         | Good            | Westinghouse |          |           | 604                   | 12                 | 01/09/2021        | 100              |             |

|           |                 |      |          |  |  |      |    |            |     |  |
|-----------|-----------------|------|----------|--|--|------|----|------------|-----|--|
| NRILU0901 | Sink & Fittings | Good |          |  |  | 2016 | 15 | 01/09/2021 | 100 |  |
| NRILU0902 | Vinyl           | Good |          |  |  | 3360 | 10 | 01/09/2021 | 100 |  |
| NRILU1021 | Dishwasher      | Good | Platinum |  |  | 2240 | 8  | 08/11/2022 | 100 |  |
| NRILU1022 | Exhaust Fan     | Good |          |  |  | 257  | 10 | 08/11/2022 | 100 |  |

Laundry

| Asset Number | Asset Name        | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0913    | Interior Painting | Good            |              |       |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
| NRILU0914    | Tiles - Floor     | Good            |              |       |           | 5880                  | 20                 | 01/09/2021        | 100              |             |
| NRILU1023    | Sink & Fittings   | Good            |              |       |           | 2016                  | 15                 | 08/11/2022        | 100              |             |

Living

| Asset Number | Asset Name                        | Asset Condition | Manufacturer        | Model           | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|-----------------------------------|-----------------|---------------------|-----------------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0923    | Blind                             | Good            |                     |                 |           | 504                   | 10                 | 01/09/2021        | 100              |             |
| NRILU0924    | Air Conditioner<br>- Split System | Good            | Mitsubishi Electric | MSZ-<br>GL71VGD | 7011200T  | 2016                  | 10                 | 01/09/2021        | 100              |             |
| NRILU0927    | Interior Painting                 | Good            |                     |                 |           | 2464                  | 10                 | 01/09/2021        | 100              |             |
| NRILU1024    | Vinyl                             | Good            |                     |                 |           | 3360                  | 10                 | 08/11/2022        | 100              |             |

Unit Exterior

| Asset Number | Asset Name           | Asset Condition | Manufacturer | Model | Serial No | Acquisition Cost (\$) | Effective Life (Y) | Installation Date | RV Component (%) | Shared With |
|--------------|----------------------|-----------------|--------------|-------|-----------|-----------------------|--------------------|-------------------|------------------|-------------|
| NRILU0932    | Clothesline          | Good            |              |       |           | 728                   | 10                 | 01/01/1984        | 100              |             |
| NRILU0933    | Doors                | Good            |              |       |           | 2240                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0934    | Downpipes            | Good            |              |       |           | 1758                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0936    | Exterior<br>Painting | Good            |              |       |           | 6160                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0937    | Fascias              | Good            |              |       |           | 5140                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0938    | Flyscreens           | Good            |              |       |           | 2240                  | 10                 | 01/01/1984        | 100              |             |
| NRILU0939    | Guttering            | Good            |              |       |           | 2844                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0940    | Path                 | Good            |              |       |           | 3763                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0941    | Porch                | Good            |              |       |           | 2979                  | 30                 | 01/01/1984        | 100              |             |
| NRILU0942    | Handrails            | Good            |              |       |           | 1232                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0943    | Water Meter          | Good            |              |       |           | 1120                  | 20                 | 01/01/1984        | 100              |             |
| NRILU0944    | Windows              | Good            |              |       |           | 3360                  | 30                 | 01/01/1984        | 100              |             |