

Assets Register - Yamba

Common

Garages 1-4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0899	Roof	Good				9600		50/01/10/1983	100	

Garages 5-8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0904	Roof	Fair				9600		50/01/10/1983	100	

Garages 9-11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0909	Roof	Good				7200		50/01/10/1983	100	

Garages 12-14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0913	Roof	Good				7200		50/01/10/1983	100	

Grounds

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0917	Distribution Board	Fair				10760		20/01/10/1983	100	
YAILU0918	Drainage	Good				0		50/01/10/1983	100	
YAILU0920	Gas Meter	Good				0		15/01/10/1983	100	
YAILU0921	Lattice Screening	Fair				2600		20/01/10/1983	100	
YAILU0922	Kerb & Gutter	Good				15770		50/01/10/1983	100	
YAILU0923	Letterboxes	Fair				3000		30/01/10/1983	100	
YAILU0924	Lighting Bollards	Fair				22000		15/01/10/1983	100	
YAILU0925	Power Supply	Good				0		40/01/10/1983	100	
YAILU0926	Retaining Walls	Fair				35200		20/01/10/1983	100	
YAILU0928	Sewer	Good				116000		80/01/10/1983	100	
YAILU0929	Signage	Poor				2000		7/01/10/1983	100	
YAILU0930	Street Lighting	Good				2440		15/01/10/1983	100	
YAILU0931	Telephone/Comms services	Good				0		40/01/10/1983	100	
YAILU0932	Water Mains	Good				0		80/01/10/1983	100	
YAILU0933	Hydrants	Good				0		30/01/10/1983	100	
YAILU0934	Roads	Good				114000		25/01/10/1983	100	
YAILU1039	Fencing	Excellent				79877		20/14/09/2023	100	

Garages 1-4

Garage 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0900	Electric Roller Door	Fair				2200		10/01/10/1983	100	

Garage 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0901	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 3

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0902	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0903	Electric Roller Door	Fair				2200		10/01/10/1983	100	

Garages 5-8

Garage 5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0905	Electric Roller Door	Fair				2200		10/01/10/1983	100	

Garage 6

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0906	Electric Roller Door	Fair				2200		10/01/10/1983	100	

Garage 7

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0907	Electric Roller Door	Fair				2200		10/01/10/1983	100	

Garage 8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

YAILU0908	Electric Roller Door	Fair					2200		10/01/10/1983	100	
-----------	----------------------	------	--	--	--	--	------	--	---------------	-----	--

Garages 9-11

Garage 9

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0910	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 10

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0911	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0912	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garages 12-14

Garage 12

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0914	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0915	Electric Roller Door	Good				2200		10/01/10/1983	100	

Garage 14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0916	Electric Roller Door	Good				1300		10/20/10/2022		

Unit 1

Unit 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0001	Roof	Good				7800		50/01/03/2019	100	
YAILU0002	Hot Water System - Electric	Good	Dux Proflo			2150		12/01/07/2010	100	
YAILU0003	Insulation	Good				2710		20/01/09/2006	100	
YAILU0004	Lighting	Fair				1720		15/01/03/2019	100	
YAILU0005	Sarking	Good				3580		25/01/09/2004	100	
YAILU0006	Smoke Alarms	Good				235		20/01/07/2010	100	

Unit 2

Unit 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0056	Roof	Good				7800		50/01/01/1989	100	
YAILU0057	Hot Water System - Electric	Good	Rheem	101090	48363	2150		12/01/07/1982	100	
YAILU0058	Insulation	Good				2875		20/01/07/2010	100	
YAILU0059	Lighting	Good				1420		15/01/04/2004	100	
YAILU0060	Sarking	Good				3530		25/01/01/1989	100	
YAILU0061	Smoke Alarms	Good				235		20/01/07/1982	100	

Unit 3-4

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0103	Roof	Good				7800		50/01/10/1983	100	

Unit 3

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0104	Hot Water System - Electric	Good	Rheem	191M5005/P	5072671	2150		12/01/09/2009	100	
YAILU0105	Insulation	Good				2875		20/01/09/2009	100	
YAILU0106	Lighting	Good				1420		15/01/09/2009	100	
YAILU0107	Sarking	Good				3530		25/01/09/2009	100	
YAILU0108	Smoke Alarms	Good				235		20/01/09/2009	100	

Unit 4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0153	Hot Water System - Electric	Fair	Rheem			2150		12/01/01/2022	100	
YAILU0154	Insulation	Good				2875		20/01/12/2017	100	

YAILU0155	Lighting	Good					1420		15/01/09/2004	100	
YAILU0156	Sarking	Good					3530		25/01/10/1983	100	
YAILU0157	Smoke Alarms	Good					235		20/01/12/2021	100	

Unit 5

Unit 5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0203	Roof	Good				7800		50/01/10/1983	100	
YAILU0204	Hot Water System - Electric	Good	Rheem	111080	859339	2150		12/01/10/1983	100	
YAILU0205	Insulation	Good				2710		20/01/10/1983	100	
YAILU0206	Lighting	Fair				1720		15/01/10/1983	100	
YAILU0207	Sarking	Good				3580		25/01/10/1983	100	
YAILU0208	Smoke Alarms	Good				235		20/01/10/1983	100	
YAILU0209	Skylight	Fair				710		10/01/10/1983	100	

Unit 6

Unit 6

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0262	Roof	Good				7800		50/01/10/1983	100	
YAILU0263	Hot Water System - Electric	Good	Dux Proflo	50V136G	50901107920	2150		12/01/01/1984	100	
YAILU0264	Insulation	Good				2875		20/01/07/1982	100	
YAILU0265	Lighting	Fair				1420		15/01/10/2012	100	
YAILU0266	Sarking	Good				3530		25/01/10/1983	100	
YAILU0267	Smoke Alarms	Good				235		20/01/07/2011	100	

Unit 7

Unit 7

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0312	Roof	Good				7800		50/01/10/1983	100	
YAILU0313	Hot Water System - Electric	Good	Vulcan			2150		12/01/10/2015	100	
YAILU0314	Insulation	Good				2710		20/01/10/2015	100	
YAILU0315	Lighting	Good				1720		15/01/10/2015	100	
YAILU0316	Sarking	Good				3580		25/01/10/1983	100	
YAILU0317	Smoke Alarms	Good				235		20/01/10/2015	100	
YAILU0318	Skylight	Fair				710		10/01/10/2015	100	

Unit 8

Unit 8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0372	Roof	Good				7800		50/01/10/1983	100	Aged Care
YAILU0373	Hot Water System - Electric	Good				2150		12/01/10/1983	100	Aged Care
YAILU0374	Insulation	Good				2710		20/01/10/1983	100	
YAILU0375	Lighting	Good				1720		15/01/10/1983	100	
YAILU0376	Sarking	Good				3580		25/01/10/1983	100	
YAILU0377	Smoke Alarms	Good				235		20/01/10/1983	100	

Unit 9

Unit 9

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0430	Roof	Good				7800		50/01/10/1983	100	
YAILU0431	Hot Water System - Electric	Good	Vulcan	66108007	3048735	2150		12/01/10/1983	100	
YAILU0432	Insulation	Good				2710		20/01/10/1983	100	
YAILU0433	Lighting	Good				1720		15/01/10/1983	100	
YAILU0434	Sarking	Good				3580		25/01/10/1983	100	
YAILU0435	Smoke Alarms	Good				235		20/01/10/1983	100	
YAILU0436	Skylight	Fair				710		10/01/10/1983	100	

## Unit 10

## Unit 10

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0490	Roof	Good				7800	50	01/10/1983	100	
YAILU0491	Hot Water System - Electric	Good	Rheem			2150	12	01/01/1989	100	
YAILU0492	Insulation	Good				2710	20	01/03/2019	100	
YAILU0493	Lighting	Good				1720	15	01/03/2019	100	
YAILU0494	Sarking	Good				3580	25	01/10/1983	100	
YAILU0495	Smoke Alarms	Good				235	20	01/07/1982	100	
YAILU0496	Skylight	Good				710	10	01/07/1982	100	

## Unit 11

## Unit 11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0550	Roof	Good				7800	50	01/10/1983	100	
YAILU0551	Hot Water System - Electric	Good	Vulcan	66108007	2371082	2150	12	01/01/1989	100	
YAILU0552	Insulation	Good				2710	20	01/11/2005	100	
YAILU0553	Lighting	Good				1720	15	01/01/1989	100	
YAILU0554	Sarking	Good				3580	25	01/10/1983	100	
YAILU0555	Smoke Alarms	Good				235	20	01/03/2019	100	
YAILU0556	Skylight	Fair				710	10	01/01/1989	100	

## Unit 12-13

## Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0608	Roof	Good				7800	50	01/10/1983	100	

## Unit 12

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0609	Hot Water System - Electric	Good				2150	12	01/03/2019	100	
YAILU0610	Insulation	Good				2710	20	01/03/2019	100	
YAILU0611	Lighting	Good				1720	15	01/03/2019	100	
YAILU0612	Sarking	Good				3580	25	01/10/1983	100	
YAILU0613	Smoke Alarms	Good				235	20	01/03/2019	100	

## Unit 13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0667	Hot Water System - Electric	Good	Rheem	111080	1010702	2150	12	01/03/2019	100	
YAILU0668	Insulation	Good				2710	20	01/03/2019	100	
YAILU0669	Lighting	Good				1720	15	01/01/1989	100	
YAILU0670	Sarking	Good				3580	25	01/10/1983	100	
YAILU0671	Smoke Alarms	Good				235	20	01/01/1989	100	
YAILU0672	Skylight	Fair				710	10	01/03/2019	100	

## Unit 14

## Unit 14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0723	Roof	Good				7800	50	01/10/1983	100	
YAILU0724	Hot Water System - Electric	Good	Rheem	491080R7	06782483	2150	12	23/11/2022	100	
YAILU0725	Insulation	Good				2710	20	01/03/2019	100	
YAILU0726	Lighting	Good				1720	15	01/03/2019	100	
YAILU0727	Sarking	Good				3580	25	01/10/1983	100	
YAILU0728	Smoke Alarms	Good				235	20	01/01/1984	100	
YAILU0729	Skylight	Good				710	10	01/03/2019	100	
YAILU1023	Hot Water System - Electric	Good	Rheem	491080R7	06782483	2150	12	23/11/2022	100	

## Unit 15

## Unit 15

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0781	Roof	Good				7800		50/01/10/1983	100	
YAILU0782	Hot Water System - Electric	Good	Rheem	111080	1268001	2150		12/01/03/2019	100	
YAILU0783	Insulation	Good				2710		20/01/07/1982	100	
YAILU0784	Lighting	Good				1720		15/01/08/2005	100	
YAILU0785	Sarking	Good				3580		25/01/10/1983	100	
YAILU0786	Smoke Alarms	Good				235		20/01/01/1989	100	
YAILU0787	Skylight	Fair				1420		10/01/07/1982	100	

## Unit 16

## Unit 16

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0839	Roof	Good				8658		50/01/10/1983	100	
YAILU0840	Hot Water System - Electric	Good	Dux Proflo	80F136G	60905107990	2386		12/01/01/1989	100	
YAILU0841	Insulation	Good				3008		20/01/07/1982	100	
YAILU0842	Lighting	Good				1909		15/01/07/1982	100	
YAILU0843	Sarking	Good				3973		25/01/10/1983	100	
YAILU0844	Smoke Alarms	Good				260		20/01/11/2004	100	
YAILU0845	Skylight	Good				788		10/01/04/2015	100	

## Unit 16

## Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0869	Exhaust Fan	Good				255		10/01/03/2019	100	
YAILU0870	Interior Painting	Excellent				222		10/01/03/2019	100	
YAILU0871	Tapware	Good				1304		15/01/03/2019	100	
YAILU0872	Shower Screen	Good				1165		20/01/07/1982	100	
YAILU0873	Tiles - Floor	Good				3940		20/01/07/2003	100	
YAILU0874	Tiles - Wall	Good				3285		20/01/06/2016	100	

## Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0857	Carpet	Good				965		8/01/07/1982	100	
YAILU0858	Ceiling Fan	Good				588		10/01/01/1989	100	
YAILU0859	Interior Painting	Good				832		10/01/07/1982	100	
YAILU0860	Wardrobe	Good				2053		10/01/01/1989	100	

## Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0861	Carpet	Good				666		8/01/01/1989	100	
YAILU0862	Ceiling Fan	Good				588		10/01/01/1989	100	
YAILU0863	Interior Painting	Good				532		10/01/12/2018	100	
YAILU0864	Blind	Good				333		10/01/03/2004	100	

## Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0882	Carpet	Good				832		8/01/03/2019	100	
YAILU0883	Interior Painting	Good				710		10/01/03/2004	100	

## Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0884	Carpet	Good				277		8/01/03/2019	100	
YAILU0885	Interior Painting	Excellent				233		10/01/01/1989	100	

## Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0847	Curtain	Good				444		6/01/01/1989	100	
YAILU0848	Benchtops	Good				2342		20/01/03/2019	100	
YAILU0849	Cooktop	Good	Chef			1354		12/01/07/1982	100	
YAILU0850	Interior Painting	Good				388		10/01/01/1989	100	
YAILU0851	Kitchen Cabinets	Good				3818		20/01/03/2019	100	
YAILU0852	Electric Elevated Oven	Good	Chef	EECL010W	12300121	1409		12/01/07/1982	100	

YAILU0853	Exhaust Fan	Good				255	10/01/1989	100	
YAILU0854	Sink & Fittings	Good				1587	15/01/07/1982	100	
YAILU0855	Vinyl Flooring	Good				777	10/01/12/2018	100	
YAILU1034	Blind	Good				277	10/23/11/2022	100	

**Laundry**

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0846	Blind	Good				277	10/01/07/1982	100		
YAILU0865	Curtain	Good				444	6/01/11/2004	100		
YAILU0866	Interior Painting	Excellent				222	10/01/12/2010	100		
YAILU0867	Tiles - Floor	Good				2025	20/01/01/1989	100		
YAILU0868	Tiles - Wall	Good				1209	20/01/01/1989	100		
YAILU1032	Sink & Fittings	Good				1587	15/23/11/2022	100		
YAILU1033	Vinyl Flooring	Good				777	10/23/11/2022	100		

**Living**

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0877	Blind	Good				388	10/01/03/2019	100		
YAILU0878	Air Conditioner - Split System	Poor	Daikin			3296	10/01/03/2019	100		
YAILU0879	Carpet	Good				865	8/01/03/2004	100		
YAILU0880	Ceiling Fan	Good				588	10/01/07/1982	100		
YAILU0881	Interior Painting	Good				710	10/01/03/2019	100		

**Toilet Room**

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0875	Tiles - Floor	Good				3940	20/01/01/1984	100		
YAILU0876	Toilet & Cistern	Good				1343	20/01/03/2019	100		
YAILU1031	Tapware	Good				1304	15/23/11/2022	100		

**Unit Exterior**

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
YAILU0886	Clothesline	Good				499	10/01/10/1983	100		
YAILU0887	Courtyard	Good				2197	30/01/10/1983	100		
YAILU0888	Doors	Good				6560	30/01/10/1983	100		
YAILU0889	Downpipes	Good				1742	20/01/10/1983	100		
YAILU0890	Electrical Switchboard	Good				1964	20/01/10/1983	100		
YAILU0891	Exterior Painting	Good				2086	10/01/10/1983	100		
YAILU0892	Fascias	Good				2874	20/01/10/1983	100		
YAILU0893	Flyscreens	Good				1864	10/01/10/1983	100		
YAILU0894	Lattice Screening	Fair				3163	20/01/10/1983	100		
YAILU0895	Guttering	Good				2819	20/01/10/1983	100		
YAILU0896	Path	Fair				2197	30/01/10/1983	100		
YAILU0897	Porch	Good				2197	30/01/10/1983	100		
YAILU0898	Water Meter	Good				388	20/01/10/1983	100		
YAILU1035	Awning	Good				325	10/23/11/2022	100		