

3Yr Maintenance & Repair Schedule - Narrabri ILU

Common

Carpports

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0945	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0945	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0945	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0946	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0946	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0946	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0947	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0947	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0947	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0948	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0948	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0948	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0949	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0949	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0949	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0950	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0950	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0950	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0951	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0951	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0951	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0952	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0952	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0952	Carport	5328	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Grounds

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2024
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2025
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2026
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0953	Distribution Board	11943	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0954	Drainage	0	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0954	Drainage	0	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0954	Drainage	0	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0955	Fencing	92268	01/01/2004	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0955	Fencing	92268	01/01/2004	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0955	Fencing	92268	01/01/2004	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2024
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2025
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr General External ILU Insepction	Yearly	\$10.00	19/07/2026
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0956	Gas Meter	0	01/01/1999	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0957	Kerb & Gutter	26995	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0957	Kerb & Gutter	26995	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0957	Kerb & Gutter	26995	01/01/2034	25	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0958	Letterboxes	4440	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0958	Letterboxes	4440	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0958	Letterboxes	4440	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2024
NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2025
NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2026
NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0959	Lighting Bollards		12321	01/01/1999		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0960	Power Supply		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0960	Power Supply		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0960	Power Supply		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0961	Roads		259740	01/01/2009		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0961	Roads		259740	01/01/2009		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0961	Roads		259740	01/01/2009		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0962	Sewer		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0962	Sewer		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0962	Sewer		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0963	Signage		4440	01/01/1991		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0963	Signage		4440	01/01/1991		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0963	Signage		4440	01/01/1991		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2024
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2025
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2026
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0964	Telephone/Comms services		0	01/01/2024		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2024
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2025
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr General External ILU Insepction	Yearly		\$10.00	19/07/2026
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0965	Water Mains		0	01/01/2064		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0966	Patio		4662	01/01/2014		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0966	Patio		4662	01/01/2014		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0966	Patio		4662	01/01/2014		100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - Annual Hydrant Inspection - Service	Yearly		\$480.00	19/07/2024
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - Annual Hydrant Inspection - Service	Yearly		\$480.00	19/07/2025
NRILU0967	Hydrants		333	01/01/2014		25	Narrabri - Annual Hydrant Inspection - Service	Yearly		\$480.00	19/07/2026
NRILU1053	FIP System		0	01/01/1999			Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1053	FIP System		0	01/01/1999			Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1053	FIP System		0	01/01/1999			Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit 1-4

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0001	Roof	34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0001	Roof	34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0001	Roof	34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
--------------	------------	-----------------------	-------------------------------	------------------	---------------	--------------------	------------------------	----------

NRILU0002	Hot Water System - Electric		2150	01/12/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0002	Hot Water System - Electric		2150	01/12/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0002	Hot Water System - Electric		2150	01/12/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0003	Insulation		2875	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0003	Insulation		2875	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0003	Insulation		2875	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0004	Lighting		1420	01/12/2018	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0004	Lighting		1420	01/12/2018	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0004	Lighting		1420	01/12/2018	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0005	Sarking		3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0005	Sarking		3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0005	Sarking		3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2024
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2025
NRILU0006	Smoke Alarms		235	01/12/2023	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2026
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2024
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2025
NRILU0007	Electrical Switchboard		1770	01/12/2023	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2026

Unit 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date	
NRILU0048	Hot Water System - Electric		2150	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0048	Hot Water System - Electric		2150	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0048	Hot Water System - Electric		2150	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0049	Insulation		3191	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0049	Insulation		3191	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0049	Insulation		3191	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0050	Lighting		1576	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0050	Lighting		1576	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0050	Lighting		1576	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0051	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0051	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0051	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0052	Smoke Alarms		260	01/11/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0053	Electrical Switchboard		1964	01/11/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026
NRILU1054	Hot Water System - Electric		2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1054	Hot Water System - Electric		2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1054	Hot Water System - Electric		2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 3

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date	
NRILU0094	Hot Water System - Electric		2150	01/11/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0094	Hot Water System - Electric	2150	01/11/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0094	Hot Water System - Electric	2150	01/11/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0095	Insulation	2875	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0095	Insulation	2875	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0095	Insulation	2875	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0096	Lighting	1420	01/11/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0096	Lighting	1420	01/11/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0096	Lighting	1420	01/11/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0097	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0097	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0097	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0098	Smoke Alarms	235	01/11/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026

Unit 4

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0140	Hot Water System - Electric	2150	01/07/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0140	Hot Water System - Electric	2150	01/07/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0140	Hot Water System - Electric	2150	01/07/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0141	Insulation	2875	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0141	Insulation	2875	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0141	Insulation	2875	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0142	Lighting	1420	01/07/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0142	Lighting	1420	01/07/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0142	Lighting	1420	01/07/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0143	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0143	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0143	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0144	Smoke Alarms	235	01/07/2024	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0145	Electrical Switchboard	1770	01/07/2024	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 2

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0068	Exhaust Fan	255	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0068	Exhaust Fan	255	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0068	Exhaust Fan	255	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0069	Interior Painting	355	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0069	Interior Painting	355	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0069	Interior Painting	355	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0070	Tapware	1304	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0070	Tapware	1304	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0070	Tapware	1304	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0072	Tiles - Floor	3940	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0072	Tiles - Floor	3940	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0072	Tiles - Floor	3940	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0073	Tiles - Wall		3285	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0073	Tiles - Wall		3285	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0073	Tiles - Wall		3285	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0074	Toilet & Cistern		1343	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0074	Toilet & Cistern		1343	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0074	Toilet & Cistern		1343	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0969	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0969	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0969	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1026	Sink & Fittings		1587	01/11/2019		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1026	Sink & Fittings		1587	01/11/2019		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1026	Sink & Fittings		1587	01/11/2019		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0063	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0063	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0063	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0064	Carpet	721	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0064	Carpet	721	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0064	Carpet	721	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0065	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0065	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0065	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0066	Interior Painting	621	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0066	Interior Painting	621	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0066	Interior Painting	621	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0067	Wardrobe	2053	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0067	Wardrobe	2053	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0067	Wardrobe	2053	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0080	Carpet	865	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0080	Carpet	865	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0080	Carpet	865	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0081	Interior Painting	743	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0081	Interior Painting	743	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0081	Interior Painting	743	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0054	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0054	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0054	Blind	333	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0055	Benchtops	2344	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0055	Benchtops	2344	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0055	Benchtops	2344	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0057	Interior Painting	477	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0057	Interior Painting	477	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0057	Interior Painting	477	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0058	Kitchen Cabinets	3818	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0058	Kitchen Cabinets	3818	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0058	Kitchen Cabinets	3818	01/11/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0059	Stove	1409	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0059	Stove	1409	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0059	Stove	1409	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0060	Rangehood	599	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0060	Rangehood	599	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0060	Rangehood	599	01/11/2016	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0061	Sink & Fittings	1587	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0061	Sink & Fittings	1587	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0061	Sink & Fittings	1587	01/11/2019	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0062	Vinyl		777	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0062	Vinyl		777	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0062	Vinyl		777	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0075	Air Conditioner - Split System	3296	01/11/2014	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0076	Blind	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0076	Blind	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0076	Blind	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0077	Carpet	765	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0077	Carpet	765	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0077	Carpet	765	01/11/2012	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0078	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0078	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0078	Ceiling Fan	588	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0079	Interior Painting	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0079	Interior Painting	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0079	Interior Painting	666	01/11/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0082	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0082	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0082	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0083	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0083	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0083	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0084	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0084	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0084	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0085	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0085	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0085	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0086	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0086	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0086	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0087	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0087	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0087	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0088	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0089	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0089	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0089	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0090	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0090	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0090	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0092	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0092	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0092	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0093	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0093	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0093	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit 5-8

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0186	Roof		34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0186	Roof		34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0186	Roof		34632	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026

Unit 5

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0188	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0188	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0188	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0189	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0189	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0189	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0190	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0190	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0190	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2024
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2025
NRILU0191	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2026
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00 19/07/2024
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00 19/07/2025
NRILU0192	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00 19/07/2026
NRILU0980	Hot Water System - Electric		2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0980	Hot Water System - Electric		2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0980	Hot Water System - Electric		2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026

Unit 6

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0236	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0236	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0236	Insulation		3191	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0237	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0237	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0237	Lighting		1576	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0238	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0238	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0238	Sarking		3918	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2024
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2025
NRILU0239	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00 19/09/2026
NRILU0240	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2024
NRILU0240	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2025
NRILU0240	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14 19/07/2026
NRILU0240	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00 19/07/2024

NRILU0240	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0240	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026
NRILU0986	Hot Water System - Electric	2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0986	Hot Water System - Electric	2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0986	Hot Water System - Electric	2386	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 7

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0284	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0284	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0284	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0285	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0285	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0285	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0286	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0286	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0286	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0287	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0288	Electrical Switchboard	1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026
NRILU0988	Hot Water System - Electric	2150	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0988	Hot Water System - Electric	2150	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0988	Hot Water System - Electric	2150	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 8

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0331	Hot Water System - Electric	2150	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0331	Hot Water System - Electric	2150	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0331	Hot Water System - Electric	2150	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0332	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0332	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0332	Insulation	2875	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0333	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0333	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0333	Lighting	1420	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0334	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0334	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0334	Sarking	3530	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0335	Smoke Alarms	235	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0336	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0336	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0336	Electrical Switchboard	1770	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0336	Electrical Switchboard	1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024

NRILU0336	Electrical Switchboard		1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0336	Electrical Switchboard		1770	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 5

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0208	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0208	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0208	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0209	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0209	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0209	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0210	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0210	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0210	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0211	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0211	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0211	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0212	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0212	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0212	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0213	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0213	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0213	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0214	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0214	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0214	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0972	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0972	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0972	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0202	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0202	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0202	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0205	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0205	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0205	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0206	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0206	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0206	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0207	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0207	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0207	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0973	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0973	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0973	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0222	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0222	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0222	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0974	Vinyl	832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0974	Vinyl	832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0974	Vinyl	832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0193	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0193	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0193	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0194	Benchtops		2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0194	Benchtops		2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0194	Benchtops		2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0196	Interior Painting		477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0196	Interior Painting		477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0196	Interior Painting		477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0197	Kitchen Cabinets		3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0197	Kitchen Cabinets		3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0197	Kitchen Cabinets		3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0199	Rangehood		599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0199	Rangehood		599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0199	Rangehood		599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0200	Sink & Fittings		1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0200	Sink & Fittings		1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0200	Sink & Fittings		1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0201	Vinyl		777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0201	Vinyl		777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0201	Vinyl		777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0975	Cooktop		1354	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0975	Cooktop		1354	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0975	Cooktop		1354	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0976	Dishwasher		1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0976	Dishwasher		1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0976	Dishwasher		1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0977	Oven		1409	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0977	Oven		1409	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0977	Oven		1409	08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0215	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0215	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0215	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0216	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0218	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0218	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0218	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0220	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0220	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0220	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0978	Blind	666	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0978	Blind	666	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0978	Blind	666	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0979	Vinyl	865	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0979	Vinyl	865	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0979	Vinyl	865	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0223	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0223	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0223	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0224	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0224	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0224	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0225	Downpipes		1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0225	Downpipes		1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0225	Downpipes		1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0226	Exterior Painting		1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0226	Exterior Painting		1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0226	Exterior Painting		1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0227	Fascias		2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0227	Fascias		2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0227	Fascias		2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0228	Flyscreens		1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0228	Flyscreens		1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0228	Flyscreens		1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	\$220.00	19/07/2024
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	\$220.00	19/07/2025
NRILU0229	Guttering		2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	\$220.00	19/07/2026
NRILU0230	Path		2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0230	Path		2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0230	Path		2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0231	Porch		1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0231	Porch		1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0231	Porch		1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0232	Handrails		1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0232	Handrails		1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0232	Handrails		1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0233	Water Meter		388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0233	Water Meter		388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0233	Water Meter		388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0234	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0234	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0234	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit 6

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0256	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0256	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0256	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0257	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0257	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0257	Interior Painting	355	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0258	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0258	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0258	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0259	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0259	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0259	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0260	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0260	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0260	Tiles - Floor	3940	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0261	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0261	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0261	Tiles - Wall	3285	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0262	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0262	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0262	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0982	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0982	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0982	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0250	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0250	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0250	Carpet	721	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0251	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0251	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0251	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0253	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0253	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0253	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0254	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0254	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0254	Interior Painting	621	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0255	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0255	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0255	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0270	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0270	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0270	Interior Painting	743	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0984	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0984	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0984	Blind	333	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1027	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1027	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1027	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0241	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0241	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0241	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0242	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0242	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0242	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0244	Interior Painting	477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0244	Interior Painting	477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0244	Interior Painting	477	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0245	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0245	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0245	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0247	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0247	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0247	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0248	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0248	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0248	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0249	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0249	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0249	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1028	Oven	1409	08/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1028	Oven	1409	08/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1028	Oven	1409	08/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1029	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1029	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1029	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1030	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1030	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1030	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0263	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0263	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0263	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0264	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0266	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0266	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0266	Ceiling Fan	588	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0268	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0268	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0268	Interior Painting	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1031	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1031	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1031	Vinyl	777	08/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0271	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0271	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0271	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0272	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0272	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0272	Doors	3141	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0273	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0273	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0273	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0274	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0274	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0274	Exterior Painting	1465	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0275	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0275	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0275	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0276	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0276	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0276	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0277	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0278	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0278	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0278	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0279	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0279	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0279	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0280	Handrails	1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0280	Handrails	1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0280	Handrails	1998	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0281	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0281	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0281	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0282	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0282	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0282	Windows		5505	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit 11-12

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date	
NRILU0378	Roof		19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0378	Roof		19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0378	Roof		19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 11

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date	
NRILU0379	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0379	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0379	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0380	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0380	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0380	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0381	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0381	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0381	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0382	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0382	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0382	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0384	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0385	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 12

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date	
NRILU0439	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0439	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0439	Hot Water System - Electric		2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0440	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0440	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0440	Insulation		3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0441	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0441	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0441	Lighting		1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0442	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0442	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0442	Sarking		3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0444	Smoke Alarms		260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2024
NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2025
NRILU0445	Electrical Switchboard		1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2026

Unit 11

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0411	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0411	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0411	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0412	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0412	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0412	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0413	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0413	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0413	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0414	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0414	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0414	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0415	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0415	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0415	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0416	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0416	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0416	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0417	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0417	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0417	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0396	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0396	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0396	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0397	Carpet	965	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0397	Carpet	965	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0397	Carpet	965	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0399	Interior Painting	832	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0399	Interior Painting	832	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0399	Interior Painting	832	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0400	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0400	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0400	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0401	Carpet	666	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0401	Carpet	666	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0401	Carpet	666	01/01/1992	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0402	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0402	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0402	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0404	Interior Painting	532	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0404	Interior Painting	532	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0404	Interior Painting	532	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0405	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0405	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0405	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1032	Ceiling Fan	588	08/11/2032		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1032	Ceiling Fan	588	08/11/2032		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU1032	Ceiling Fan		588	08/11/2032		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
-----------	-------------	--	-----	------------	--	-------------------------------	--------	--	--------	------------

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0424	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0424	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0424	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1033	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1033	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1033	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0426	Interior Painting	133	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0426	Interior Painting	133	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0426	Interior Painting	133	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1034	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1034	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1034	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0386	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0386	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0386	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0387	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0387	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0387	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0390	Interior Painting	388	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0390	Interior Painting	388	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0390	Interior Painting	388	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0391	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0391	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0391	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0393	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0393	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0393	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0394	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0394	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0394	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0395	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0395	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0395	Vinyl	777	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1035	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1035	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1035	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1036	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1036	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1036	Dishwasher	1110	08/11/2030		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1037	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1037	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1037	Cooktop	1354	08/11/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0406	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0406	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0406	Interior Painting	222	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0407	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0407	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0407	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0408	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0408	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0408	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0992	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0992	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0992	Sink & Fittings		1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0418	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0418	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0418	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0419	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0422	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0422	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0422	Interior Painting	710	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1038	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1038	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1038	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0427	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0427	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0427	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0428	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0428	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0428	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0429	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0429	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0429	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0430	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0430	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0430	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0431	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0431	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0431	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0432	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0432	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0432	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0433	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0434	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0434	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0434	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0435	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0435	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0435	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0436	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0436	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0436	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0437	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0437	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0437	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

NRILU0438	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0438	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0438	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 12

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0469	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0469	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0469	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0470	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0470	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0470	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0471	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0471	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0471	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0472	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0472	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0472	Shower Screen	1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0473	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0473	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0473	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0474	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0474	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0474	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0475	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0475	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0475	Toilet & Cistern	1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0993	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0993	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0993	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0456	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0456	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0456	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0457	Carpet	965	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0457	Carpet	965	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0457	Carpet	965	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0459	Interior Painting	832	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0459	Interior Painting	832	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0459	Interior Painting	832	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0460	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0460	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0460	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0461	Carpet	666	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0461	Carpet	666	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0461	Carpet	666	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0462	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0462	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0462	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0464	Interior Painting	532	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0464	Interior Painting	532	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0464	Interior Painting	532	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0465	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0465	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0465	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
--------------	------------	-----------------------	-------------------------------	------------------	---------------	--------------------	------------------------	----------

NRILU0481	Carpet		832	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0481	Carpet		832	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0481	Carpet		832	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0482	Interior Painting		710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0482	Interior Painting		710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0482	Interior Painting		710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0483	Carpet	166	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0483	Carpet	166	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0483	Carpet	166	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0484	Interior Painting	133	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0484	Interior Painting	133	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0484	Interior Painting	133	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0446	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0446	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0446	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0447	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0447	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0447	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0450	Interior Painting	388	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0450	Interior Painting	388	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0450	Interior Painting	388	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0451	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0451	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0451	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0452	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0452	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0452	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0453	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0453	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0453	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0454	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0454	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0454	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0455	Vinyl	777	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0455	Vinyl	777	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0455	Vinyl	777	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1039	Exhaust fan	255	01/09/2023		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1039	Exhaust fan	255	01/09/2023		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1039	Exhaust fan	255	01/09/2023		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0466	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0466	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0466	Interior Painting	222	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0467	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0467	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0467	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0468	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0468	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0468	Tiles - Wall	1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0476	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0476	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0476	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0477	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0478	Carpet	865	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0478	Carpet	865	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0478	Carpet	865	01/09/2021	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0480	Interior Painting	710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0480	Interior Painting	710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0480	Interior Painting	710	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0485	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0485	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0485	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0486	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0486	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0486	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0487	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0487	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0487	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0488	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0488	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0488	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0489	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0489	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0489	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0490	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0490	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0490	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0491	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0492	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0492	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0492	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0493	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0493	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0493	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0494	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0494	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0494	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0495	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0495	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0495	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0496	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0496	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0496	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 13-14

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0497	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0497	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0497	Roof		19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
-----------	------	--	-------	------------	-----	-------------------------------	--------	--	--------	------------

Unit 13

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0499	Insulation	3008	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0499	Insulation	3008	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0499	Insulation	3008	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0500	Lighting	1909	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0500	Lighting	1909	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0500	Lighting	1909	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0501	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0501	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0501	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0502	Smoke Alarms	260	01/08/2039	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0503	Electrical Switchboard	1964	01/08/2039	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026
NRILU1040	Hot Water System - Electric	2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1040	Hot Water System - Electric	2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1040	Hot Water System - Electric	2386	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 14

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0551	Hot Water System - Electric	2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0551	Hot Water System - Electric	2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0551	Hot Water System - Electric	2386	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0552	Insulation	3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0552	Insulation	3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0552	Insulation	3008	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0553	Lighting	1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0553	Lighting	1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0553	Lighting	1909	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0554	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0554	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0554	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0555	Smoke Alarms	260	01/01/2004	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0556	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 13

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
--------------	------------	-----------------------	-------------------------------	------------------	---------------	--------------------	------------------------	----------

NRILU0525	Exhaust Fan		255	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0525	Exhaust Fan		255	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0525	Exhaust Fan		255	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0526	Interior Painting		222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0526	Interior Painting		222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0526	Interior Painting		222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0527	Tapware		1304	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0527	Tapware		1304	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0527	Tapware		1304	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0528	Shower Screen		1165	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0528	Shower Screen		1165	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0528	Shower Screen		1165	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0529	Tiles - Floor		1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0529	Tiles - Floor		1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0529	Tiles - Floor		1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0530	Tiles - Wall		1642	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0530	Tiles - Wall		1642	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0530	Tiles - Wall		1642	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0531	Toilet & Cistern		1343	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0531	Toilet & Cistern		1343	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0531	Toilet & Cistern		1343	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0994	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0994	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0994	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0513	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0513	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0513	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0514	Carpet	965	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0514	Carpet	965	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0514	Carpet	965	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0515	Interior Painting	832	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0515	Interior Painting	832	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0515	Interior Painting	832	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0516	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0516	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0516	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0517	Carpet	666	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0517	Carpet	666	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0517	Carpet	666	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0518	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0518	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0518	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0519	Interior Painting	532	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0519	Interior Painting	532	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0519	Interior Painting	532	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0520	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0520	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0520	Wardrobe	2053	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0535	Carpet	832	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0535	Carpet	832	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0535	Carpet	832	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0536	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0536	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0536	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0537	Carpet	166	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0537	Carpet	166	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0537	Carpet	166	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0538	Interior Painting	133	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0538	Interior Painting	133	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0538	Interior Painting	133	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0504	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0504	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0504	Blind	333	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0505	Benchtops	2344	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0505	Benchtops	2344	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0505	Benchtops	2344	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0506	Cooktop	1354	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0506	Cooktop	1354	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0506	Cooktop	1354	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0507	Interior Painting	388	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0507	Interior Painting	388	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0507	Interior Painting	388	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0508	Kitchen Cabinets	3818	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0508	Kitchen Cabinets	3818	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0508	Kitchen Cabinets	3818	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0509	Oven	1409	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0509	Oven	1409	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0509	Oven	1409	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0510	Rangehood	599	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0510	Rangehood	599	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0510	Rangehood	599	01/08/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0511	Sink & Fittings	1587	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0511	Sink & Fittings	1587	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0511	Sink & Fittings	1587	01/08/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0512	Vinyl	777	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0512	Vinyl	777	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0512	Vinyl	777	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0522	Interior Painting	222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0522	Interior Painting	222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0522	Interior Painting	222	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0523	Tiles - Floor	1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0523	Tiles - Floor	1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0523	Tiles - Floor	1970	01/08/2039	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0995	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0995	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0995	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0521	Blind	666	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0521	Blind	666	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0521	Blind	666	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026

NRILU0532	Air Conditioner - Split System	3296	01/08/2029	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0533	Carpet	865	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0533	Carpet	865	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0533	Carpet	865	01/08/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0534	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0534	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0534	Interior Painting	710	01/08/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0539	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0539	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0539	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0540	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0540	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0540	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0541	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0541	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0541	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0542	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0542	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0542	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0543	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0543	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0543	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0544	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0544	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0544	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0545	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0546	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0546	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0546	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0547	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0547	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0547	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0548	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0548	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0548	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0549	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0549	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0549	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0550	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0550	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0550	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 14

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0577	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0577	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0577	Exhaust Fan	255	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0578	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0578	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0578	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0579	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0579	Tapware	1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0579	Tapware		1304	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0580	Shower Screen		1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0580	Shower Screen		1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0580	Shower Screen		1165	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0581	Tiles - Floor		1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0581	Tiles - Floor		1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0581	Tiles - Floor		1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0582	Tiles - Wall		1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0582	Tiles - Wall		1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0582	Tiles - Wall		1642	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0583	Toilet & Cistern		1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0583	Toilet & Cistern		1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0583	Toilet & Cistern		1343	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0996	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0996	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0996	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0566	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0566	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0566	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0567	Carpet	965	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0567	Carpet	965	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0567	Carpet	965	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0568	Interior Painting	832	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0568	Interior Painting	832	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0568	Interior Painting	832	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0569	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0569	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0569	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0570	Carpet	666	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0570	Carpet	666	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0570	Carpet	666	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0571	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0571	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0571	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0572	Interior Painting	532	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0572	Interior Painting	532	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0572	Interior Painting	532	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0573	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0573	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0573	Wardrobe	2053	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0588	Carpet	832	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0588	Carpet	832	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0588	Carpet	832	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0589	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0589	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0589	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0590	Carpet	166	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0590	Carpet	166	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0590	Carpet	166	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0591	Interior Painting	133	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0591	Interior Painting	133	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0591	Interior Painting	133	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0557	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0557	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0557	Blind	333	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0558	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0558	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0558	Benchtops	2344	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0560	Interior Painting	388	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0560	Interior Painting	388	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0560	Interior Painting	388	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0561	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0561	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0561	Kitchen Cabinets	3818	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0562	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0562	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0562	Stove	1409	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0563	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0563	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0563	Rangehood	599	01/01/1996	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0564	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0564	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0564	Sink & Fittings	1587	01/01/1999	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0565	Vinyl	777	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0565	Vinyl	777	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0565	Vinyl	777	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0997	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0997	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0997	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0574	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0574	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0574	Interior Painting	222	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0575	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0575	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0575	Tiles - Floor	1970	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0584	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0584	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0584	Blind	666	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0585	Air Conditioner - Split System	3296	01/01/1994	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0586	Carpet	865	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0586	Carpet	865	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0586	Carpet	865	01/09/2024	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0587	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0587	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0587	Interior Painting	710	01/09/2026	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0592	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0592	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0592	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0593	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0593	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0593	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0594	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0594	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0594	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0595	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0595	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0595	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0596	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0596	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0596	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0597	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0597	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0597	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0598	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0599	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0599	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0599	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0600	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0600	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0600	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0601	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0601	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0601	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0602	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0602	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0602	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0603	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0603	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0603	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 15-16

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0604	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0604	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0604	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 15

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0605	Hot Water System - Electric	2386	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0605	Hot Water System - Electric	2386	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0605	Hot Water System - Electric	2386	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0606	Insulation	3008	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0606	Insulation	3008	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0606	Insulation	3008	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0607	Lighting	1909	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0607	Lighting	1909	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0607	Lighting	1909	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0608	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0608	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0608	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0609	Smoke Alarms	260	01/03/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0611	Electrical Switchboard	1964	01/03/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 16

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0662	Hot Water System - Electric	2386	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0662	Hot Water System - Electric	2386	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0662	Hot Water System - Electric	2386	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0663	Insulation	3008	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0663	Insulation	3008	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0663	Insulation	3008	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0664	Lighting	1909	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0664	Lighting	1909	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0664	Lighting	1909	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0665	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0665	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0665	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0667	Smoke Alarms	260	01/09/2035	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0668	Electrical Switchboard	1964	01/09/2035	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 15

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0635	Exhaust Fan	255	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0635	Exhaust Fan	255	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0635	Exhaust Fan	255	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0636	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0636	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0636	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0637	Tapware	1304	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0637	Tapware	1304	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0637	Tapware	1304	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0638	Shower Screen	1165	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0638	Shower Screen	1165	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0638	Shower Screen	1165	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0639	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0639	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0639	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0640	Tiles - Wall	1642	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0640	Tiles - Wall	1642	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0640	Tiles - Wall		1642	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0641	Toilet & Cistern		1343	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0641	Toilet & Cistern		1343	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0641	Toilet & Cistern		1343	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1000	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1000	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1000	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0621	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0621	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0621	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0622	Carpet	965	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0622	Carpet	965	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0622	Carpet	965	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0623	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0623	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0623	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0624	Interior Painting	832	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0624	Interior Painting	832	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0624	Interior Painting	832	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0625	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0625	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0625	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0626	Carpet	666	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0626	Carpet	666	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0626	Carpet	666	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0627	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0627	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0627	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0628	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0628	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0628	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0629	Interior Painting	532	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0629	Interior Painting	532	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0629	Interior Painting	532	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0630	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0630	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0630	Wardrobe	2053	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0646	Carpet	832	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0646	Carpet	832	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0646	Carpet	832	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0647	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0647	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0647	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0648	Carpet	166	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0648	Carpet	166	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0648	Carpet	166	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0649	Interior Painting	133	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0649	Interior Painting	133	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0649	Interior Painting	133	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0612	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0612	Blind		333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0612	Blind		333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0613	Benchtops		2344	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0613	Benchtops		2344	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0613	Benchtops		2344	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0614	Curtain		444	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0614	Curtain		444	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0614	Curtain		444	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0615	Stove		1354	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0615	Stove		1354	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0615	Stove		1354	01/03/2017	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0616	Interior Painting		388	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0616	Interior Painting		388	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0616	Interior Painting		388	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0617	Kitchen Cabinets		3818	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0617	Kitchen Cabinets		3818	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0617	Kitchen Cabinets		3818	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0619	Sink & Fittings		1587	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0619	Sink & Fittings		1587	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0619	Sink & Fittings		1587	01/03/2020	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0620	Vinyl		777	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0620	Vinyl		777	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0620	Vinyl		777	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1001	Exhaust Fan		255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1001	Exhaust Fan		255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1001	Exhaust Fan		255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1025	Rangehood		599	04/08/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1025	Rangehood		599	04/08/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1025	Rangehood		599	04/08/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0632	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0632	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0632	Interior Painting	222	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0633	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0633	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0633	Tiles - Floor	1970	01/03/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1002	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1002	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1002	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0642	Air Conditioner - Split System	3296	01/03/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0643	Carpet	865	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0643	Carpet	865	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0643	Carpet	865	01/03/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0644	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0644	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0644	Curtain	1776	01/03/2011	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0645	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0645	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0645	Interior Painting	710	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1041	Blind	333	01/03/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU1041	Blind		333	01/03/2015		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1041	Blind		333	01/03/2015		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0650	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0650	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0650	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0651	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0651	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0651	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0652	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0652	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0652	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0653	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0653	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0653	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0654	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0654	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0654	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0655	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0655	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0655	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0656	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0657	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0657	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0657	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0658	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0658	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0658	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0659	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0659	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0659	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0660	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0660	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0660	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0661	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0661	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0661	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 16

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0690	Exhaust Fan	255	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0690	Exhaust Fan	255	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0690	Exhaust Fan	255	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0691	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0691	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0691	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0692	Tapware	1304	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0692	Tapware	1304	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0692	Tapware	1304	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0693	Shower Screen	1165	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0693	Shower Screen	1165	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0693	Shower Screen	1165	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0694	Tiles - Floor	1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0694	Tiles - Floor	1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0694	Tiles - Floor		1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0695	Tiles - Wall		1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0695	Tiles - Wall		1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0695	Tiles - Wall		1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0696	Toilet & Cistern		1343	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0696	Toilet & Cistern		1343	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0696	Toilet & Cistern		1343	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0678	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0678	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0678	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0679	Carpet	965	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0679	Carpet	965	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0679	Carpet	965	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0680	Interior Painting	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0680	Interior Painting	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0680	Interior Painting	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0681	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0681	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0681	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1042	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1042	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1042	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0682	Carpet	666	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0682	Carpet	666	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0682	Carpet	666	01/09/2023	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0683	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0683	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0683	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0684	Interior Painting	532	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0684	Interior Painting	532	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0684	Interior Painting	532	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0685	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0685	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0685	Wardrobe	2053	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1043	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1043	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1043	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0701	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0701	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0701	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1044	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1044	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1044	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0703	Interior Painting	133	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0703	Interior Painting	133	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0703	Interior Painting	133	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1045	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1045	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1045	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0669	Blind	333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0669	Blind		333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0669	Blind		333	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0670	Benchtops		2344	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0670	Benchtops		2344	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0670	Benchtops		2344	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0672	Interior Painting		388	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0672	Interior Painting		388	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0672	Interior Painting		388	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0673	Kitchen Cabinets		3818	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0673	Kitchen Cabinets		3818	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0673	Kitchen Cabinets		3818	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0675	Rangehood		599	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0675	Rangehood		599	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0675	Rangehood		599	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0676	Sink & Fittings		1587	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0676	Sink & Fittings		1587	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0676	Sink & Fittings		1587	01/09/2030	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0677	Vinyl		777	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0677	Vinyl		777	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0677	Vinyl		777	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1046	Cooktop		1354	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1046	Cooktop		1354	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1046	Cooktop		1354	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1047	Oven		1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1047	Oven		1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1047	Oven		1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1048	Exhaust Fan		255	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1048	Exhaust Fan		255	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1048	Exhaust Fan		255	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0687	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0687	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0687	Interior Painting	222	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0688	Tiles - Floor	1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0688	Tiles - Floor	1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0688	Tiles - Floor	1970	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0689	Tiles - Wall	1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0689	Tiles - Wall	1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0689	Tiles - Wall	1642	01/09/2035	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0697	Air Conditioner - Split System	3296	01/09/2025	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0699	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0699	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0699	Interior Painting	710	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1049	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1049	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1049	Vinyl	777	09/01/2034		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1050	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1050	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1050	Ceiling Fan	588	01/09/2025		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0704	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0704	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0704	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0705	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0705	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0705	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0706	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0706	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0706	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0707	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0707	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0707	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0708	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0708	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0708	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0709	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0709	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0709	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0710	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0711	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0711	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0711	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0712	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0712	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0712	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0713	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0713	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0713	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0714	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0714	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0714	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0715	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0715	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0715	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 17-18

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0716	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0716	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0716	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 17

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0717	Hot Water System - Electric	2386	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0717	Hot Water System - Electric	2386	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0717	Hot Water System - Electric	2386	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0718	Insulation	3008	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0718	Insulation	3008	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0718	Insulation	3008	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0719	Lighting	1909	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0719	Lighting	1909	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0719	Lighting	1909	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0720	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0720	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0720	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0721	Smoke Alarms	260	01/09/2037	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0722	Electrical Switchboard	1964	01/09/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 18

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0778	Hot Water System - Electric	2386	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0778	Hot Water System - Electric	2386	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0778	Hot Water System - Electric	2386	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0779	Insulation	3008	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0779	Insulation	3008	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0779	Insulation	3008	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0780	Lighting	1909	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0780	Lighting	1909	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0780	Lighting	1909	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0781	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0781	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0781	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0782	Smoke Alarms	260	01/02/2025	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0783	Electrical Switchboard	1964	01/02/2025	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 17

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0750	Exhaust Fan	255	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0750	Exhaust Fan	255	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0750	Exhaust Fan	255	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0751	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0751	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0751	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0752	Tapware	1304	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0752	Tapware	1304	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0752	Tapware	1304	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0753	Shower Screen	1165	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0753	Shower Screen	1165	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0753	Shower Screen	1165	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0754	Tiles - Floor	1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0754	Tiles - Floor	1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0754	Tiles - Floor		1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0755	Tiles - Wall		1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0755	Tiles - Wall		1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0755	Tiles - Wall		1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0756	Toilet & Cistern		1343	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0756	Toilet & Cistern		1343	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0756	Toilet & Cistern		1343	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1003	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1003	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1003	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0733	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0733	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0733	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0734	Carpet	965	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0734	Carpet	965	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0734	Carpet	965	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0736	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0736	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0736	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0737	Interior Painting	832	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0737	Interior Painting	832	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0737	Interior Painting	832	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0738	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0738	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0738	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0739	Carpet	666	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0739	Carpet	666	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0739	Carpet	666	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0740	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0740	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0740	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0742	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0742	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0742	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0743	Interior Painting	532	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0743	Interior Painting	532	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0743	Interior Painting	532	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0744	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0744	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0744	Wardrobe	2053	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0762	Carpet	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0762	Carpet	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0762	Carpet	832	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0763	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0763	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0763	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0764	Carpet	166	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0764	Carpet	166	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0764	Carpet	166	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0765	Interior Painting	133	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0765	Interior Painting	133	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0765	Interior Painting	133	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0723	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0723	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0723	Blind	333	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0724	Benchtops	2344	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0724	Benchtops	2344	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0724	Benchtops	2344	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0726	Cooktop	1354	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0726	Cooktop	1354	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0726	Cooktop	1354	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0727	Interior Painting	388	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0727	Interior Painting	388	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0727	Interior Painting	388	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0728	Kitchen Cabinets	3818	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0728	Kitchen Cabinets	3818	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0728	Kitchen Cabinets	3818	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0729	Oven	1409	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0729	Oven	1409	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0729	Oven	1409	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0730	Rangehood	599	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0730	Rangehood	599	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0730	Rangehood	599	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0731	Sink & Fittings	1587	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0731	Sink & Fittings	1587	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0731	Sink & Fittings	1587	01/09/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0732	Vinyl	777	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0732	Vinyl	777	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0732	Vinyl	777	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0746	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0746	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0746	Interior Painting	222	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0747	Tiles - Floor	1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0747	Tiles - Floor	1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0747	Tiles - Floor	1970	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0748	Tiles - Wall	1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0748	Tiles - Wall	1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0748	Tiles - Wall	1642	01/09/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1004	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1004	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1004	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0745	Blind	666	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0745	Blind	666	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0745	Blind	666	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0757	Air Conditioner - Split System	3296	01/09/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0758	Carpet	865	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0758	Carpet	865	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0758	Carpet	865	01/09/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0759	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0759	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0759	Ceiling Fan	588	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0761	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0761	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0761	Interior Painting	710	01/09/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0766	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0766	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0766	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0767	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0767	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0767	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0768	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0768	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0768	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0769	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0769	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0769	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0770	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0770	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0770	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0771	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0771	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0771	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0772	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0773	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0773	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0773	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0774	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0774	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0774	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0775	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0775	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0775	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0776	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0776	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0776	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0777	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0777	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0777	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 18

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0805	Exhaust Fan	255	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0805	Exhaust Fan	255	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0805	Exhaust Fan	255	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0806	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0806	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0806	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0807	Tapware	1304	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0807	Tapware	1304	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0807	Tapware	1304	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0808	Shower Screen	1165	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0808	Shower Screen	1165	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0808	Shower Screen		1165	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0809	Tiles - Floor		1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0809	Tiles - Floor		1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0809	Tiles - Floor		1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0810	Tiles - Wall		1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0810	Tiles - Wall		1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0810	Tiles - Wall		1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0811	Toilet & Cistern		1343	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0811	Toilet & Cistern		1343	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0811	Toilet & Cistern		1343	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1005	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1005	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1005	Vanity		1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0793	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0793	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0793	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0794	Carpet	965	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0794	Carpet	965	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0794	Carpet	965	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0795	Ceiling Fan	588	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0795	Ceiling Fan	588	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0795	Ceiling Fan	588	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0796	Interior Painting	832	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0796	Interior Painting	832	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0796	Interior Painting	832	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0797	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0797	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0797	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0798	Carpet	666	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0798	Carpet	666	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0798	Carpet	666	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0799	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0799	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0799	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0800	Interior Painting	532	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0800	Interior Painting	532	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0800	Interior Painting	532	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0801	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0801	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0801	Wardrobe	2053	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0817	Carpet	832	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0817	Carpet	832	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0817	Carpet	832	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0818	Interior Painting	710	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0818	Interior Painting	710	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0818	Interior Painting	710	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0819	Carpet	166	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0819	Carpet	166	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0819	Carpet	166	01/02/2013	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0820	Interior Painting	133	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0820	Interior Painting	133	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0820	Interior Painting	133	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0784	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0784	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0784	Blind	333	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0785	Benchtops	2344	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0785	Benchtops	2344	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0785	Benchtops	2344	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0786	Cooktop	1354	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0786	Cooktop	1354	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0786	Cooktop	1354	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0787	Interior Painting	388	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0787	Interior Painting	388	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0787	Interior Painting	388	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0788	Kitchen Cabinets	3818	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0788	Kitchen Cabinets	3818	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0788	Kitchen Cabinets	3818	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0789	Oven	1409	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0789	Oven	1409	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0789	Oven	1409	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0790	Rangehood	599	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0790	Rangehood	599	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0790	Rangehood	599	01/02/2017	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0791	Sink & Fittings	1587	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0791	Sink & Fittings	1587	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0791	Sink & Fittings	1587	01/02/2020	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0792	Vinyl	777	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0792	Vinyl	777	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0792	Vinyl	777	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1006	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1006	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1006	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0802	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0802	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0802	Interior Painting	222	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0803	Tiles - Floor	1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0803	Tiles - Floor	1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0803	Tiles - Floor	1970	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0804	Tiles - Wall	1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0804	Tiles - Wall	1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0804	Tiles - Wall	1642	01/02/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1007	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1007	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1007	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0812	Blind	666	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0812	Blind	666	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0812	Blind	666	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0813	Air Conditioner - Split System	3296	01/02/2015	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0814	Carpet	865	01/07/2028	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024

NRILU0814	Carpet		865 01/07/2028	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2025
NRILU0814	Carpet		865 01/07/2028	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2026
NRILU0815	Ceiling Fan		588 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2024
NRILU0815	Ceiling Fan		588 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2025
NRILU0815	Ceiling Fan		588 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2026
NRILU0816	Interior Painting		710 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2024
NRILU0816	Interior Painting		710 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2025
NRILU0816	Interior Painting		710 01/02/2015	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14 19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0821	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0821	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0821	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0822	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0822	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0822	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0823	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0823	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0823	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0824	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0824	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0824	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0825	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0825	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0825	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0826	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0826	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0826	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0827	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0828	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0828	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0828	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0829	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0829	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0829	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0830	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0830	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0830	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0831	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0831	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0831	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0832	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0832	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0832	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 19-20

Common

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0833	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0833	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0833	Roof	19980	01/01/2034	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit 19

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0835	Insulation	3008	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0835	Insulation	3008	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0835	Insulation		3008 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0836	Lighting		1909 01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0836	Lighting		1909 01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0836	Lighting		1909 01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0837	Sarking		3973 01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0837	Sarking		3973 01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0837	Sarking		3973 01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2024
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2025
NRILU0838	Smoke Alarms		260 01/11/2037	100	Narrabri - Smoke Alarm Testing	Yearly		\$10.00	19/09/2026
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2024
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2025
NRILU0839	Electrical Switchboard		1964 01/11/2037	100	Narrabri - RCD Push Button/Trip Test	Yearly		\$120.00	19/07/2026
NRILU1018	Hot Water System - Electric		2386 08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1018	Hot Water System - Electric		2386 08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1018	Hot Water System - Electric		2386 08/11/2034	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit 20

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0887	Hot Water System - Electric	2386	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0887	Hot Water System - Electric	2386	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0887	Hot Water System - Electric	2386	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0888	Insulation	3008	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0888	Insulation	3008	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0888	Insulation	3008	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0889	Lighting	1909	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0889	Lighting	1909	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0889	Lighting	1909	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0890	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0890	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0890	Sarking	3973	01/01/2009	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2024
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2025
NRILU0892	Smoke Alarms	260	01/09/2041	100	Narrabri - Smoke Alarm Testing	Yearly	\$10.00	19/09/2026
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2024
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2025
NRILU0935	Electrical Switchboard	1964	01/01/2004	100	Narrabri - RCD Push Button/Trip Test	Yearly	\$120.00	19/07/2026

Unit 19

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0860	Exhaust Fan	255	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0860	Exhaust Fan	255	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0860	Exhaust Fan	255	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0861	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0861	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0861	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0862	Tapware	1304	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0862	Tapware	1304	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0862	Tapware	1304	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0863	Shower Screen	1165	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0863	Shower Screen	1165	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0863	Shower Screen	1165	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0864	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0864	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0864	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0865	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0865	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0865	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0866	Toilet & Cistern	1343	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0866	Toilet & Cistern	1343	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0866	Toilet & Cistern	1343	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1008	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1008	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1008	Vanity	1776	08/11/2042	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0849	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0849	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0849	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0850	Carpet	965	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0850	Carpet	965	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0850	Carpet	965	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0851	Interior Painting	832	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0851	Interior Painting	832	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0851	Interior Painting	832	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0852	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0852	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0852	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1009	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1009	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1009	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0853	Carpet	666	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0853	Carpet	666	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0853	Carpet	666	01/11/2025	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0854	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0854	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0854	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0855	Interior Painting	532	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0855	Interior Painting	532	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0855	Interior Painting	532	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0856	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0856	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0856	Wardrobe	2053	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1010	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1010	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1010	Ceiling Fan	588	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0872	Interior Painting	710	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0872	Interior Painting	710	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0872	Interior Painting	710	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1011	Vinyl	832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1011	Vinyl	832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU1011	Vinyl		832	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
-----------	-------	--	-----	------------	-----	-------------------------------	--------	--------	------------

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0874	Interior Painting	133	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0874	Interior Painting	133	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0874	Interior Painting	133	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1012	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1012	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1012	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0840	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0840	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0840	Blind	333	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0841	Benchtops	2344	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0841	Benchtops	2344	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0841	Benchtops	2344	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0842	Cooktop	1354	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0842	Cooktop	1354	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0842	Cooktop	1354	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0843	Interior Painting	388	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0843	Interior Painting	388	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0843	Interior Painting	388	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0844	Kitchen Cabinets	3818	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0844	Kitchen Cabinets	3818	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0844	Kitchen Cabinets	3818	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0846	Rangehood	599	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0846	Rangehood	599	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0846	Rangehood	599	01/11/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0847	Sink & Fittings	1587	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0847	Sink & Fittings	1587	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0847	Sink & Fittings	1587	01/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0848	Vinyl	777	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0848	Vinyl	777	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0848	Vinyl	777	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1013	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1013	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1013	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1014	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1014	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1014	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1051	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1051	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1051	Oven	1409	09/01/2036		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0857	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0857	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0857	Interior Painting	222	01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0858	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0858	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0858	Tiles - Floor	1970	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0859	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0859	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0859	Tiles - Wall	1642	01/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1015	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1015	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1015	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
--------------	------------	-----------------------	-------------------------------	------------------	---------------	--------------------	------------------------	----------

NRILU0867	Blind		666 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0867	Blind		666 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0867	Blind		666 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2024
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2025
NRILU0868	Air Conditioner - Split System		3296 01/11/2027	100	Narrabri - Air Conditioner Filter Clean	Yearly	\$50.00	19/07/2026
NRILU0870	Interior Painting		710 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0870	Interior Painting		710 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0870	Interior Painting		710 01/11/2027	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1016	Ceiling Fan		588 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1016	Ceiling Fan		588 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1016	Ceiling Fan		588 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1017	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1017	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1017	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0875	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0875	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0875	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0876	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0876	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0876	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0877	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0877	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0877	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0878	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0878	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0878	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0879	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0879	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0879	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0880	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0880	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0880	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0881	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0882	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0882	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0882	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0883	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0883	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0883	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0884	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0884	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0884	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0885	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0885	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0885	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0886	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0886	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

Unit 20

NRILU0886	Windows		6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
-----------	---------	--	------	------------	-----	-------------------------------	--------	--	--------	------------

Bathroom

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0916	Exhaust Fan	255	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0916	Exhaust Fan	255	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0916	Exhaust Fan	255	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0917	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0917	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0917	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0918	Tapware	1304	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0918	Tapware	1304	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0918	Tapware	1304	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0919	Shower Screen	1165	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0919	Shower Screen	1165	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0919	Shower Screen	1165	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0920	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0920	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0920	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0921	Tiles - Wall	1642	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0921	Tiles - Wall	1642	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0921	Tiles - Wall	1642	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0922	Toilet & Cistern	1343	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0922	Toilet & Cistern	1343	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0922	Toilet & Cistern	1343	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 1

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0903	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0903	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0903	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0904	Carpet	965	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0904	Carpet	965	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0904	Carpet	965	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0906	Interior Painting	832	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0906	Interior Painting	832	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0906	Interior Painting	832	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0907	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0907	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0907	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1052	Ceiling Fan	588	01/09/2031		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1052	Ceiling Fan	588	01/09/2031		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1052	Ceiling Fan	588	01/09/2031		Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Bed 2

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0908	Carpet	666	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0908	Carpet	666	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0908	Carpet	666	01/09/2029	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0909	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0909	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0909	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0911	Interior Painting	532	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0911	Interior Painting	532	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0911	Interior Painting	532	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0912	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0912	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0912	Wardrobe	2053	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Dining

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0929	Interior Painting	710	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0929	Interior Painting	710	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025

NRILU0929	Interior Painting		710 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1019	Vinyl		832 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1019	Vinyl		832 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1019	Vinyl		832 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Hallway

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0931	Interior Painting	133	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0931	Interior Painting	133	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0931	Interior Painting	133	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1020	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1020	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1020	Vinyl	166	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Kitchen

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0893	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0893	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0893	Blind	333	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0894	Benchtops	2344	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0894	Benchtops	2344	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0894	Benchtops	2344	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0896	Cooktop	1354	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0896	Cooktop	1354	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0896	Cooktop	1354	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0897	Interior Painting	388	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0897	Interior Painting	388	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0897	Interior Painting	388	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0898	Kitchen Cabinets	3818	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0898	Kitchen Cabinets	3818	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0898	Kitchen Cabinets	3818	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0899	Oven	1409	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0899	Oven	1409	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0899	Oven	1409	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0900	Rangehood	599	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0900	Rangehood	599	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0900	Rangehood	599	01/09/2033	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0901	Sink & Fittings	1587	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0901	Sink & Fittings	1587	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0901	Sink & Fittings	1587	01/09/2036	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0902	Vinyl	777	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0902	Vinyl	777	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0902	Vinyl	777	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1021	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1021	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1021	Dishwasher	1110	08/11/2030	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1022	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1022	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1022	Exhaust Fan	255	08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Laundry

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0913	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0913	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0913	Interior Painting	222	01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0914	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0914	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0914	Tiles - Floor	1970	01/09/2041	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU1023	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU1023	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU1023	Sink & Fittings	1587	08/11/2037	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026

Living

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
--------------	------------	-----------------------	-------------------------------	------------------	---------------	--------------------	------------------------	----------

NRILU0923	Blind		666 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0923	Blind		666 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0923	Blind		666 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - Air Conditioner Filter Clean	Yearly		\$50.00	19/07/2024
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - Air Conditioner Filter Clean	Yearly		\$50.00	19/07/2025
NRILU0924	Air Conditioner - Split System		3296 01/09/2031	100	Narrabri - Air Conditioner Filter Clean	Yearly		\$50.00	19/07/2026
NRILU0927	Interior Painting		710 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU0927	Interior Painting		710 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU0927	Interior Painting		710 01/09/2031	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026
NRILU1024	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2024
NRILU1024	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2025
NRILU1024	Vinyl		865 08/11/2032	100	Narrabri - 1yr ILU Inspection	Yearly		\$2.14	19/07/2026

Unit Exterior

Asset Number	Asset Name	Acquisition Cost (\$)	Estimated Date of Replacement	RV Component (%)	Job Plan Name	Period + Frequency	Estimated Cost per Job	Due Date
NRILU0932	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0932	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0932	Clothesline	499	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0933	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0933	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0933	Doors	6005	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0934	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0934	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0934	Downpipes	1742	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0936	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0936	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0936	Exterior Painting	2086	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0937	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0937	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0937	Fascias	2874	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0938	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0938	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0938	Flyscreens	1864	01/01/1994	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2024
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2025
NRILU0939	Guttering	2819	01/01/2004	100	Narrabri - Gutter Cleaning Service	Yearly	\$220.00	19/07/2026
NRILU0940	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0940	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0940	Path	2197	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0941	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0941	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0941	Porch	1021	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0942	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0942	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0942	Handrails	610	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0943	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0943	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0943	Water Meter	388	01/01/2004	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026
NRILU0944	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2024
NRILU0944	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2025
NRILU0944	Windows	6682	01/01/2014	100	Narrabri - 1yr ILU Inspection	Yearly	\$2.14	19/07/2026