

Assets Register - Redhead ILU

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU2000	Fascia & Barges	Good				22644		20/01/09/2013	100	
REILU2015	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2016	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Common

Garages 1-2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1870	Roof	Good				5328		50/01/01/1991	100	
REILU2012	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Garages 3-5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1873	Roof	Good				7992		50/01/01/1991	100	
REILU2001	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Garages 6-8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1877	Roof	Good				7992		50/01/01/1991	100	
REILU2002	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2101	Roof	Good				5328		50/01/01/1991		

Garages 9-11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1881	Roof	Fair				7992		50/01/01/1991	100	

Garages 12-13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1885	Roof	Good				5328		50/01/01/1991	100	

Garages 14-15

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1888	Roof	Good				5328		50/01/01/1991	100	
REILU2013	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Garages 16-17

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1891	Roof	Good				5328		50/01/01/1991	100	

Garages 18-19

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1894	Roof	Good				5328		50/01/01/1991	100	
REILU2014	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Garages 20-21

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1897	Roof	Good				5328		50/01/01/1991	100	

Garages 22-24

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1900	Roof	Good				7992		50/01/01/1991	100	

Grounds

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1904	Distribution Board	Good				11943		20/01/01/1991	100	
REILU1905	Drainage	Good				1587		50/01/01/1991	15	Aged Care
REILU1906	Fencing	Good				22200		20/01/01/1991	15	Aged Care
REILU1907	Gas Meter	Good				1587		15/01/01/1991	15	Aged Care
REILU1908	Kerb & Gutter	Good				69597		50/01/01/1991	15	Aged Care
REILU1909	Letterboxes	Good				8325		30/01/01/1991	100	

REILU1910	Lighting Bollards	Fair					18481	15	01/01/1991	100	
REILU1911	Power Supply	Good					1587	40	01/01/1991	15	Aged Care
REILU1912	Retaining wall	Poor					11655	20	01/01/1991	15	Aged Care
REILU1913	Roads	Good					284049	25	01/01/1991	15	Aged Care
REILU1914	Sewer	Good					1587	80	01/01/1991	15	Aged Care
REILU1915	Signage	Good					5550	7	01/01/1991	15	Aged Care
REILU1916	Street Lighting	Good					13542	15	01/01/1991	15	Aged Care
REILU1917	Telephone / Comms Services	Good					1587	40	01/01/1991	15	Aged Care
REILU1918	Water Mains	Good					1587	80	01/01/1991	15	Aged Care
REILU1919	Hydrants	Good					1587	30	01/01/1991	15	Aged Care
REILU1923	Irrigation System	Good					27750	20	01/01/1989		

Garages 1-2

Garage 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1871	Roller Door	Good				2442		10/01/01/1991	100	

Garage 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1872	Roller Door	Good				2442		10/01/01/1991	100	

Garages 3-5

Garage 3

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1874	Roller Door	Good				2442		10/01/01/1991	100	

Garage 4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1875	Roller Door	Good				2442		10/01/01/1991	100	

Garage 5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1876	Roller Door	Good	Merlin	Mr650EVO		2442		10/01/01/1991	100	

Garages 6-8

Garage 6

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1878	Roller Door	Good				2442		10/01/01/1991	100	

Garage 7

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1879	Roller Door	Good				2442		10/01/01/1991	100	

Garage 8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1880	Roller Door	Good	Merlin	MR655MYO	336	2442		10/01/01/1991	100	

Garages 9-11

Garage 9

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1882	Roller Door	Good				2442		10/01/01/1991	100	

Garage 10

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1883	Roller Door	Good				2442		10/01/01/1991	100	

Garage 11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1884	Roller Door	Good				2442		10/01/01/1991	100	

Garages 12-13

Garage 12

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1886	Roller Door	Good				2442		10/01/01/1991	100	

Garage 13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1887	Roller Door	Fair				2442		10/01/01/1991	100	

Garages 14-15

Garage 14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1889	Roller Door	Good				2442		10/01/01/1991	100	

Garage 15

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1890	Roller Door	Good				2442		10/01/01/1991	100	

Garages 16-17

Garage 16

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1892	Roller Door	Good				2442		10/01/01/1991	100	

Garage 17

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1893	Roller Door	Fair				2442		10/01/01/1991	100	

Garages 18-19

Garage 18

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1895	Roller Door	Good				2442		10/01/01/1991	100	

Garage 19

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1896	Roller Door	Good				2442		10/01/01/1991	100	

Garages 20-21

Garage 20

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1898	Roller Door	Good				2442		10/01/01/1991	100	

Garage 21

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1899	Roller Door	Good				2442		10/01/01/1991	100	

Garages 22-24

Garage 22

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1901	Roller Door	Good				2442		10/01/01/1991	100	

Garage 23

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1902	Roller Door	Good				2442		10/01/01/1991	100	

Garage 24

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1903	Roller Door	Good				2442		10/01/01/1991	100	

Unit 1-2

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0001	Roof	Good				27972		50/01/01/1991	100	

Unit 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0002	Insulation	Good				3191		20/01/10/2015	100	
REILU0003	Lighting	Good				1909		15/01/10/2015	100	
REILU0004	Sarking	Good				4140		25/01/01/1991	100	
REILU0005	Smoke Alarms	Good				260		20/01/10/2015	100	
REILU0034	Hot Water System - Electric	Good	Vulcan	66125007	2477339	2386		12/01/10/2015		
REILU0052	Skylight	Good				788		10/01/10/2015	100	

Unit 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0067	Insulation	Good				3191		20/01/08/2004	100	
REILU0068	Lighting	Good				1909		15/01/08/2004	100	
REILU0069	Sarking	Good				4140		25/01/01/1991	100	
REILU0070	Smoke Alarms	Good				260		20/01/08/2004	100	
REILU0096	Hot Water System - Electric	Good	Vulcan	66125007	2477338	2386		12/23/10/2023		
REILU0114	Skylight	Good				788		10/01/08/2004	100	

Unit 1

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0028	Exhaust Fan	Good				255		10/01/10/2015	100	

REILU0041	Interior Painting	Good					177	10/01/2015	100	
REILU0050	Shower Screen	Good					1165	20/01/2015	100	
REILU0053	Tapware	Good					1304	15/01/2015	100	
REILU0056	Tiles - Floor	Fair					3940	20/01/2015	100	
REILU0058	Tiles - Wall	Good					3285	20/01/2015	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0010	Blind	Good					666	10/01/2015	100	
REILU0013	Carpet	Good					1054	8/01/2015	100	
REILU0017	Ceiling Fan	Good					588	10/01/2015	100	
REILU0037	Interior Painting	Good					921	10/01/2015	100	
REILU0064	Wardrobe	Good					2053	10/01/2015	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0009	Blind	Good					333	10/01/2015	100	
REILU0012	Carpet	Good					688	8/01/2015	100	
REILU0016	Ceiling Fan	Good					588	10/01/2015	100	
REILU0036	Interior Painting	Good					599	10/01/2015	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0015	Carpet	Good					688	8/01/2015	100	
REILU0039	Interior Painting	Good					599	10/01/2015	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0040	Interior Painting	Good					355	10/01/2015	100	
REILU0062	Vinyl	Poor					932	10/01/2015	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0007	Benchtops	Good					2344	20/01/2015	100	
REILU0020	Cooktop	Good	Westinghouse				1354	12/01/2015	100	
REILU0035	Interior Painting	Good					499	10/01/2015	100	
REILU0043	Kitchen Cabinets	Good					3818	20/01/2015	100	
REILU0044	Electric Elevated Oven	Good	Westinghouse	WDE147WA-L	60780006		1409	12/01/2015	100	
REILU0048	Rangehood	Good	Westinghouse				599	12/01/2015	100	
REILU0051	Sink & Fittings	Good					1587	15/01/2015	100	
REILU0061	Vinyl	Fair					777	10/01/2015	100	
REILU2020	Blind	Good					1110	10/13/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0042	Interior Painting	Good					177	10/01/2015	100	
REILU0057	Tiles - Floor	Good					2025	20/01/2015	100	
REILU0059	Tiles - Wall	Good					1209	20/01/2015	100	
REILU1924	Exhaust Fan	Good					255	10/03/11/2022	100	
REILU2021	Sink & Fittings	Good					1587	15/03/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0006	Air Conditioner - Split System	Good	Carrier	42P250HX	3304Y40300		3296	10/01/2015	100	
REILU0011	Blind	Good					777	10/01/2015	100	
REILU0014	Carpet	Good					954	8/01/2015	100	
REILU0018	Ceiling Fan	Good					588	10/01/2015	100	
REILU0024	Curains	Good					1776	6/01/2015	100	
REILU0038	Interior Painting	Good					832	10/01/2015	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0054	Tiles - Floor	Good					1387	20/01/2015	100	
REILU0060	Toilet & Cistern	Good					1343	20/01/2015	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0019	Clothesline	Fair					499	10/01/1991	100	

REILU0021	Courtyard	Good				2908		30/01/1991	100	
REILU0025	Doors	Good				8946		30/01/1991	100	
REILU0026	Downpipes	Good				1742		20/01/1991	100	
REILU0027	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU0029	Exterior Painting	Good				2086		10/01/1991	100	
REILU0030	Fascia & Barges	Fair				2874		20/01/1991	100	
REILU0031	Fencing	Fair				7725		20/01/1991	100	
REILU0032	Flyscreens	Good				1864		10/01/1991	100	
REILU0033	Guttering	Good				2819		20/01/1991	100	
REILU0045	Path	Good				2197		30/01/1991	100	
REILU0046	Patio	Good				1642		30/01/1991	100	
REILU0047	Porch	Good				2908		30/01/1991	100	
REILU0065	Water Meter	Good				388		20/01/1991	100	
REILU0066	Windows	Good				7747		30/01/1991	100	
REILU2019	Hot Water System - Electric	Excellent				2017		12/07/12/2023		

Unit 2

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0090	Exhaust Fan	Good				255		10/01/08/2004	100	
REILU0103	Interior Painting	Fair				177		10/01/08/2004	100	
REILU0112	Shower Screen	Good				1165		20/01/08/2004	100	
REILU0115	Tapware	Good				1304		15/01/08/2004	100	
REILU0118	Tiles - Floor	Fair				3940		20/01/08/2004	100	
REILU0121	Tiles - Wall	Good				3285		20/01/08/2004	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0073	Blind	Good				333		10/01/08/2004	100	
REILU0076	Carpet	Fair				1054		8/01/08/2004	100	
REILU0080	Ceiling Fan	Fair				588		10/01/08/2004	100	
REILU0099	Interior Painting	Fair				921		10/01/08/2004	100	
REILU0127	Wardrobe	Good				2053		10/01/08/2004	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0072	Blind	Good				333		10/01/08/2004	100	
REILU0075	Carpet	Fair				688		8/01/08/2004	100	
REILU0079	Ceiling Fan	Good				588		10/01/08/2004	100	
REILU0098	Interior Painting	Fair				599		10/01/08/2004	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0078	Carpet	Fair				688		8/01/08/2004	100	
REILU0101	Interior Painting	Good				599		10/01/08/2004	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0102	Interior Painting	Fair				355		10/01/08/2004	100	
REILU0117	Vinyl	Good				932		10/01/08/2004	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0071	Benchtops	Good				2344		20/01/08/2004	100	
REILU0083	Cooktop	Fair	Westinghouse			1354		12/01/08/2004	100	
REILU0097	Interior Painting	Good				499		10/01/08/2004	100	
REILU0105	Kitchen Cabinets	Good				3818		20/01/08/2004	100	
REILU0106	Electric Elevated Oven	Fair	Westinghouse			1409		12/01/08/2004	100	
REILU0110	Rangehood	Fair	Westinghouse			599		12/01/08/2004	100	
REILU0113	Sink & Fittings	Good				1587		15/01/08/2004	100	
REILU0124	Vinyl	Good				777		10/01/08/2004	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0104	Interior Painting	Fair				177		10/01/08/2004	100	

REILU0120	Tiles - Floor	Fair				2025		20/01/08/2004	100	
REILU0122	Tiles - Wall	Good				1209		20/01/08/2004	100	
REILU1925	Exhaust Fan	Fair				255		10/03/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0074	Blind	Good				388		10/01/08/2004	100	
REILU0077	Carpet	Fair				954		8/01/08/2004	100	
REILU0100	Interior Painting	Good				832		10/01/08/2004	100	
REILU1991	Ceiling Fan	Good				640		10/16/07/2023	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0116	Tiles - Floor	Fair				1387		20/01/08/2004	100	
REILU0123	Toilet & Cistern	Good				1343		20/01/08/2004	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0084	Courtyard	Good				2908		30/01/01/1991	100	
REILU0088	Doors	Good				8946		30/01/01/1991	100	
REILU0089	Downpipes	Good				1742		20/01/01/1991	100	
REILU0091	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU0092	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0093	Fencing	Good				7725		20/01/01/1991	100	
REILU0094	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0095	Guttering	Good				2819		20/01/01/1991	100	
REILU0107	Path	Good				2197		30/01/01/1991	100	
REILU0108	Patio	Good				1642		30/01/01/1991	100	
REILU0109	Porch	Good				2908		30/01/01/1991	100	
REILU0128	Water Meter	Good				388		20/01/01/1991	100	
REILU0129	Windows	Good				7747		30/01/01/1991	100	
REILU1992	Clothesline	Good				1097		10/02/08/2023	100	

Unit 3-4

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0252	Roof	Good				27972		50/01/01/1991	100	

Unit 3

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0253	Insulation	Fair				3191		20/01/01/1991	100	
REILU0254	Lighting	Good				1909		15/01/01/1991	100	
REILU0255	Sarking	Good				4140		25/01/01/1991	100	
REILU0256	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU0284	Hot Water System - Electric	Good	Thermann	250THM136	17031620012H	2386		12/01/01/1991	100	
REILU0302	Skylight	Good				788		10/01/01/1991	100	

Unit 4

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0316	Insulation	Good				3191		20/01/01/1991	100	
REILU0317	Lighting	Good				1909		15/01/01/1991	100	
REILU0318	Sarking	Good				4140		25/01/01/1991	100	
REILU0319	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU0344	Hot Water System - Electric	Excellent	Thermann	250THMB136	22021720334H	2386		12/01/01/1991	100	
REILU0362	Skylight	Good				788		10/01/01/1991	100	

Unit 3

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0278	Exhaust Fan	Good				255		10/01/01/1991	100	
REILU0291	Interior Painting	Good				177		10/01/01/1991	100	
REILU0299	Shower Screen	Fair				1165		20/01/01/1991	100	
REILU0303	Tapware	Good				1304		15/01/01/1991	100	
REILU0306	Tiles - Floor	Good				3940		20/01/01/1991	100	
REILU0308	Tiles - Wall	Good				3285		20/01/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0261	Blind	Good				666		10/01/1991	100	
REILU0264	Carpet	Good				1054		8/01/1991	100	
REILU0267	Ceiling Fan	Good				588		10/01/1991	100	
REILU0287	Interior Painting	Good				921		10/01/1991	100	
REILU0313	Wardrobe	Good				2053		10/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0260	Blind	Good				333		10/01/1991	100	
REILU0263	Carpet	Good				688		8/01/1991	100	
REILU0286	Interior Painting	Good				599		10/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0289	Interior Painting	Good				599		10/01/1991	100	
REILU2022	Vinyl	Good				777		10/13/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0290	Interior Painting	Good				355		10/01/1991	100	
REILU0312	Vinyl	Good				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0258	Benchtops	Good				2344		20/01/1991	100	
REILU0259	Blind	Good				333		10/01/1991	100	
REILU0270	Cooktop	Good	Fisher & Paykel			1354		12/01/1991	100	
REILU0272	Curtains	Good				444		6/01/1991	100	
REILU0285	Interior Painting	Good				499		10/01/1991	100	
REILU0293	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU0301	Sink & Fittings	Good				1587		15/01/1991	100	
REILU0311	Vinyl	Good				777		10/01/1991	100	
REILU2023	Rangehood	Good	Fisher & Paykel			599		12/13/2023		
REILU2024	Oven	Good	Fisher & Paykel			1409		12/13/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0292	Interior Painting	Good				177		10/01/1991	100	
REILU0307	Tiles - Floor	Good				2025		20/01/1991	100	
REILU0309	Tiles - Wall	Good				1209		20/01/1991	100	
REILU1926	Exhaust Fan	Good				255		10/03/11/2022	100	
REILU2025	Sink & Fittings	Good				1587		15/03/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0257	Air Conditioner - Split System	Good	Mitsubishi Electric	MSZ-GL60VGD	7002871T	3296		10/01/1991	100	
REILU0262	Blind	Good				777		10/01/1991	100	
REILU0268	Ceiling Fan	Good				588		10/01/1991	100	
REILU0275	Curtains	Good				888		6/01/1991	100	
REILU0288	Interior Painting	Good				832		10/01/1991	100	
REILU2026	Vinyl	Good				777		10/13/2023		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0304	Tiles - Floor	Good				1387		20/01/1991	100	
REILU0310	Toilet & Cistern	Good				1343		20/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0269	Clothesline	Good				499		10/10/11/2023		
REILU0271	Courtyard	Good				2908		30/01/1991	100	
REILU0276	Doors	Good				8946		30/01/1991	100	
REILU0277	Downpipes	Good				1742		20/01/1991	100	
REILU0279	Exterior Painting	Good				2086		10/01/1991	100	
REILU0280	Fascia & Barges	Good				2874		20/01/1991	100	

REILU0281	Fencing	Good				7725		20/01/1991	100	
REILU0282	Flyscreens	Good				1864		10/01/1991	100	
REILU0283	Guttering	Good				2819		20/01/1991	100	
REILU0295	Path	Good				2197		30/01/1991	100	
REILU0296	Patio	Good				1642		30/01/1991	100	
REILU0297	Porch	Good				2908		30/01/1991	100	
REILU0314	Water Meter	Good				388		20/01/1991	100	
REILU0315	Windows	Good				7747		30/01/1991	100	

Unit 4

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0338	Exhaust Fan	Good				255		10/01/1991	100	
REILU0351	Interior Painting	Good				177		10/01/1991	100	
REILU0359	Shower Screen	Good				1165		20/01/1991	100	
REILU0363	Tapware	Good				1304		15/01/1991	100	Aged Care
REILU0366	Tiles - Floor	Good				3940		20/01/1991	100	Aged Care
REILU0368	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0323	Blind	Good				666		10/01/1991	100	
REILU0326	Carpet	Good				1054		8/01/1991	100	
REILU0330	Ceiling Fan	Good				588		10/01/1991	100	
REILU0347	Interior Painting	Good				921		10/01/1991	100	
REILU0373	Wardrobe	Good				2053		10/01/1991	100	Aged Care

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0322	Blind	Good				666		10/01/1991	100	
REILU0325	Carpet	Good				688		8/01/1991	100	
REILU0329	Ceiling Fan	Good				588		10/01/1991	100	
REILU0346	Interior Painting	Good				599		10/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0349	Interior Painting	Good				599		10/01/1991	100	
REILU2027	Vinyl	Good				777		10/13/12/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0350	Interior Painting	Good				355		10/01/1991	100	
REILU0372	Vinyl	Good				932		10/01/1991	100	Aged Care

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0321	Benchtops	Good				2344		20/01/1991	100	
REILU0333	Cooktop	Good	Fisher & Paykel			1354		12/01/1991	100	
REILU0345	Interior Painting	Good				499		10/01/1991	100	
REILU0353	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU0361	Sink & Fittings	Good				1587		15/01/1991	100	
REILU0371	Vinyl	Good				777		10/01/1991	100	Aged Care
REILU2028	Rangehood	Good	Fisher & Paykel			599		12/13/12/2023		
REILU2029	Oven	Good	Fisher & Paykel			1409		12/13/12/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0352	Interior Painting	Good				177		10/01/1991	100	
REILU0367	Tiles - Floor	Good				2025		20/01/1991	100	
REILU0369	Tiles - Wall	Good				1209		20/01/1991	100	Aged Care
REILU2030	Sink & Fittings	Good				1587		15/01/1991		
REILU2031	Exhaust Fan	Fair				255		10/01/1991		
REILU2032	Downlight	Poor				1587		15/01/1991		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0320	Air Conditioner - Split System	Good	Daikin	FTXS60FVMA	E020075	3296		10/01/1991	100	

REILU0324	Blind	Good				777		10/01/1991	100	
REILU0331	Ceiling Fan	Good				588		10/01/1991	100	
REILU0348	Interior Painting	Good				832		10/01/1991	100	
REILU2033	Vinyl	Good				777		10/13/12/2023		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0364	Tiles - Floor	Good				1387		20/01/1991	100	
REILU0370	Toilet & Cistern	Good				1343		20/01/1991	100	Aged Care

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0332	Clothesline	Fair				499		10/01/1991	100	
REILU0334	Courtyard	Good				2908		30/01/1991	100	
REILU0335	Doors	Good				8946		30/01/1991	100	
REILU0336	Downpipes	Fair				1742		20/01/1991	100	
REILU0337	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU0339	Exterior Painting	Good				2086		10/01/1991	100	
REILU0340	Fascia & Barges	Good				2874		20/01/1991	100	
REILU0341	Fencing	Fair				7725		20/01/1991	100	
REILU0342	Flyscreens	Good				1864		10/01/1991	100	
REILU0343	Guttering	Good				2819		20/01/1991	100	
REILU0355	Path	Good				2197		30/01/1991	100	
REILU0356	Patio	Good				1642		30/01/1991	100	
REILU0357	Porch	Fair				2908		30/01/1991	100	
REILU0374	Water Meter	Good				388		20/01/1991	100	
REILU0375	Windows	Good				7747		30/01/1991	100	

Unit 5-6

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0130	Roof	Good				27972		50/01/1991	100	

Unit 5

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0131	Insulation	Good				3191		20/01/11/2021	100	
REILU0132	Lighting	Good				1909		15/01/11/2021	100	
REILU0133	Sarking	Good				4140		25/01/01/1991	100	
REILU0134	Smoke Alarms	Good				260		20/01/11/2021	100	
REILU0160	Hot Water System - Electric	Good	Everhot	291250R7	5427171	2386		12/01/11/2021	100	
REILU0178	Skylight	Good				788		10/01/11/2021	100	

Unit 6

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0192	Insulation	Good				3191		20/01/11/2021	100	
REILU0193	Lighting	Good				1909		15/01/11/2021	100	
REILU0194	Sarking	Good				4140		25/01/01/1991	100	
REILU0195	Smoke Alarms	Good				260		20/01/11/2021	100	
REILU0220	Hot Water System - Electric	Good	Forte			2386		12/01/11/2021	100	
REILU0238	Skylight	Good				788		10/01/11/2021	100	

Unit 5

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0154	Exhaust Fan	Good				255		10/01/11/2021	100	
REILU0167	Interior Painting	Good				177		10/01/11/2021	100	
REILU0175	Shower Screen	Good				1165		20/01/11/2021	100	
REILU0176	Shower Screen	Good				1165		20/01/11/2021	100	
REILU0179	Tapware	Good				1304		15/01/11/2021	100	
REILU0182	Tiles - Floor	Good				3940		20/01/11/2021	100	
REILU0184	Tiles - Wall	Good				3285		20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

REILU0139	Blind	Good				666		10/01/11/2021	100	
REILU0142	Carpet	Good				1054		8/01/11/2021	100	
REILU0146	Ceiling Fan	Fair				588		10/01/11/2021	100	
REILU0163	Interior Painting	Good				921		10/01/11/2021	100	
REILU0189	Wardrobe	Good				2053		10/01/11/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0138	Blind	Good				333		10/01/11/2021	100	
REILU0141	Carpet	Good				688		8/01/11/2021	100	
REILU0145	Ceiling Fan	Fair				588		10/01/11/2021	100	
REILU0162	Interior Painting	Good				599		10/01/11/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0144	Vinyl	Good				688		10/06/09/2022	100	
REILU0165	Interior Painting	Good				599		10/01/11/2021	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0166	Interior Painting	Good				355		10/01/11/2021	100	
REILU0181	Vinyl	Good				932		10/01/11/2021	100	
REILU0188	Vinyl	Fair				932		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0136	Benchtops	Good				2344		20/01/11/2021	100	
REILU0137	Blind	Good				333		10/01/11/2021	100	
REILU0149	Cooktop	Good	Fisher & Paykel			1354		12/01/11/2021	100	
REILU0161	Interior Painting	Good				499		10/01/11/2021	100	
REILU0169	Kitchen Cabinets	Good				3818		20/01/11/2021	100	
REILU0170	Electric Elevated Oven	Good	Fisher & Paykel		71580041	1409		12/01/11/2021	100	
REILU0174	Rangehood	Good	Fisher & Paykel			599		12/01/11/2021	100	
REILU0177	Sink & Fittings	Good				1587		15/01/11/2021	100	
REILU0187	Vinyl	Fair				777		10/01/11/2021	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0168	Interior Painting	Good				177		10/01/11/2021	100	
REILU0183	Tiles - Floor	Good				2025		20/01/11/2021	100	
REILU0185	Tiles - Wall	Good				1209		20/01/11/2021	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0135	Air Conditioner - Split System	Good	Daikin	FTXD60BVM48	4900337	3296		10/01/11/2021	100	
REILU0140	Blind	Good				777		10/01/11/2021	100	
REILU0143	Vinyl	Good				954		10/06/09/2022	100	
REILU0147	Ceiling Fan	Fair				588		10/01/11/2021	100	
REILU0164	Interior Painting	Good				832		10/01/11/2021	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0180	Tiles - Floor	Good				1387		20/01/11/2021	100	
REILU0186	Toilet & Cistern	Good				1343		20/01/11/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0148	Clothesline	Good				499		10/01/01/1991	100	
REILU0150	Courtyard	Good				2908		30/01/01/1991	100	
REILU0151	Doors	Good				8946		30/01/01/1991	100	
REILU0152	Downpipes	Good				1742		20/01/01/1991	100	
REILU0153	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	
REILU0155	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU0156	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0157	Fencing	Fair				7725		20/01/01/1991	100	
REILU0158	Flyscreens	Good				1864		10/01/01/1991	100	

REILU0159	Guttering	Good					2819	20/01/1991	100	
REILU0171	Path	Good					2197	30/01/1991	100	
REILU0172	Patio	Poor					1642	30/01/1991	100	
REILU0173	Porch	Good					2908	30/01/1991	100	
REILU0190	Water Meter	Good					388	20/01/1991	100	
REILU0191	Windows	Good					7747	30/01/1991	100	

Unit 6

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0214	Exhaust Fan	Good				255		10/01/11/2021	100	
REILU0227	Interior Painting	Good				177		10/01/11/2021	100	
REILU0236	Shower Screen	Good				1165		20/01/11/2021	100	
REILU0239	Tapware	Good				1304		15/01/11/2021	100	
REILU0242	Tiles - Floor	Good				3940		20/01/11/2021	100	
REILU0244	Tiles - Wall	Good				3285		20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0200	Blind	Good				666		10/01/11/2021	100	
REILU0203	Carpet	Good				1054		8/01/11/2021	100	
REILU0207	Ceiling Fan	Excellent				588		10/01/11/2021	100	
REILU0223	Interior Painting	Good				921		10/01/11/2021	100	
REILU0249	Wardrobe	Good				2053		10/01/11/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0199	Blind	Good				333		10/01/11/2021	100	
REILU0202	Carpet	Good				688		8/01/11/2021	100	
REILU0206	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU0222	Interior Painting	Good				599		10/01/11/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0205	Vinyl	Good				688		8/01/11/2021	100	
REILU0225	Interior Painting	Good				599		10/01/11/2021	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0226	Interior Painting	Good				355		10/01/11/2021	100	
REILU0248	Vinyl	Good				932		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0197	Benchtops	Excellent				2344		20/01/11/2021	100	
REILU0198	Blind	Good				333		10/01/11/2021	100	
REILU0221	Interior Painting	Good				499		10/01/11/2021	100	
REILU0229	Kitchen Cabinets	Excellent				3818		20/01/11/2021	100	
REILU0237	Sink & Fittings	Good				1587		15/01/11/2021	100	
REILU0247	Vinyl	Excellent				777		10/01/11/2021	100	
REILU1927	Cooktop	Excellent	Fisher & Paykel			1354		12/03/11/2022	100	
REILU1928	Dishwasher	Excellent	Fisher & Paykel	DW60FC1X1	FAM180239	1164		8/03/11/2022	100	
REILU1929	Oven	Good	Fisher & Paykel			1409		12/03/11/2022	100	
REILU1930	Rangehood	Good	Fisher & Paykel			599		12/03/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0228	Interior Painting	Good				177		10/01/11/2021	100	
REILU0243	Tiles - Floor	Good				2025		20/01/11/2021	100	
REILU0245	Tiles - Wall	Good				1209		20/01/11/2021	100	
REILU2034	Sink & Fittings	Good				1587		15/01/11/2021		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0196	Air Conditioner - Split System	Excellent	Daikin	FTXS46KVMA	E004828	3296		10/01/11/2021	100	
REILU0201	Blind	Good				777		10/01/11/2021	100	
REILU0204	Vinyl	Good				954		8/01/11/2021	100	

REILU0208	Ceiling Fan	Excellent				588		10/01/11/2021	100	
REILU0224	Interior Painting	Good				832		10/01/11/2021	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0240	Tiles - Floor	Good				1387		20/01/11/2021	100	
REILU0246	Toilet & Cistern	Good				1343		20/01/11/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0209	Clothesline	Good				499		10/01/01/1991	100	
REILU0211	Courtyard	Good				2908		30/01/01/1991	100	
REILU0212	Doors	Good				8946		30/01/01/1991	100	
REILU0213	Downpipes	Good				1742		20/01/01/1991	100	
REILU0215	Exterior Painting	Fair				2086		10/01/01/1991	100	
REILU0216	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0217	Fencing	Good				7725		20/01/01/1991	100	
REILU0218	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0219	Guttering	Good				2819		20/01/01/1991	100	
REILU0231	Path	Good				2197		30/01/01/1991	100	
REILU0232	Patio	Good				1642		30/01/01/1991	100	
REILU0233	Porch	Good				2908		30/01/01/1991	100	
REILU0250	Water Meter	Good				388		20/01/01/1991	100	
REILU0251	Windows	Good				7747		30/01/01/1991	100	
REILU2003	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Unit 7-8

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0376	Roof	Good				27972		50/01/01/1991	100	

Unit 7

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0377	Insulation	Good				3191		20/01/01/2021	100	
REILU0378	Lighting	Good				1909		15/01/01/2021	100	
REILU0379	Sarking	Good				4140		25/01/01/1991	100	
REILU0380	Smoke Alarms	Good				260		20/01/01/2021	100	
REILU0405	Hot Water System - Electric	Good	Thermann	250THM136		2386		12/30/08/2023		
REILU0423	Skylight	Good				788		10/01/01/2021	100	

Unit 8

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0437	Insulation	Good				3191		20/01/03/2012	100	
REILU0438	Lighting	Good				1909		15/01/03/2012	100	
REILU0439	Sarking	Good				4140		25/01/01/1991	100	
REILU0440	Smoke Alarms	Good				260		20/01/03/2012	100	
REILU0469	Hot Water System - Electric	Good	Thermann	250THM136	17101620121H	2386		12/01/03/2012	100	
REILU0487	Skylight	Good				788		10/01/03/2012	100	

Unit 7

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0399	Exhaust Fan	Good				255		10/13/11/2023		
REILU0412	Interior Painting	Good				177		10/01/01/2021	100	
REILU0421	Shower Screen	Good				1165		20/01/01/2021	100	
REILU0424	Tapware	Good				1304		15/01/01/2021	100	
REILU0427	Tiles - Floor	Fair				3940		20/01/01/2021	100	
REILU0429	Tiles - Wall	Good				3285		20/01/01/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0385	Blind	Good				666		10/01/01/2021	100	
REILU0388	Carpet	Good				1054		8/01/01/2021	100	
REILU0392	Ceiling Fan	Good				588		10/01/01/2021	100	

REILU0408	Interior Painting	Good					921	10/01/01/2021	100	
REILU0434	Wardrobe	Good					2053	10/01/01/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0384	Blind	Good				333		10/01/01/2021	100	
REILU0387	Carpet	Good				688		8/01/01/2021	100	
REILU0391	Ceiling Fan	Good				588		10/01/01/2021	100	
REILU0407	Interior Painting	Good				599		10/01/01/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0390	Carpet	Good				688		8/01/01/2021	100	
REILU0410	Interior Painting	Good				599		10/01/01/2021	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0411	Interior Painting	Good				355		10/01/01/2021	100	
REILU0426	Vinyl	Fair				932		10/01/01/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0382	Benchtops	Good				2344		20/01/01/2021	100	
REILU0383	Blind	Good				333		10/01/01/2021	100	
REILU0395	Cooktop	Good	Westinghouse			1354		12/01/01/2021	100	
REILU0406	Interior Painting	Good				499		10/01/01/2021	100	
REILU0414	Kitchen Cabinets	Good				3818		20/01/01/2021	100	
REILU0419	Rangehood	Good	Westinghouse			599		12/01/01/2021	100	
REILU0422	Sink & Fittings	Good				1587		15/01/01/2021	100	
REILU0432	Vinyl	Good				777		10/01/01/2021	100	
REILU0435	Electric Elevated Oven	Good	Westinghouse	WDE147WA-L	10580052	388		20/01/01/1991	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0413	Interior Painting	Good				177		10/01/01/2021	100	
REILU0428	Tiles - Floor	Good				2025		20/01/01/2021	100	
REILU0430	Tiles - Wall	Good				1209		20/01/01/2021	100	
REILU1931	Exhaust Fan	Good				255		10/03/11/2022	100	
REILU2035	Sink & Fittings	Good				1587		15/03/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0381	Air Conditioner - Split System	Good	Daikin	FTXM60QVMA	E015732	3296		10/01/01/2021	100	
REILU0386	Blind	Good				777		10/01/01/2021	100	
REILU0389	Carpet	Good				954		8/01/01/2021	100	
REILU0393	Ceiling Fan	Good				588		10/01/01/2021	100	
REILU0409	Interior Painting	Good				832		10/01/01/2021	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0425	Tiles - Floor	Good				1387		20/01/01/2021	100	
REILU0431	Toilet & Cistern	Good				1343		20/01/01/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0394	Clothesline	Good				499		10/01/01/1991	100	
REILU0396	Courtyard	Good				2908		30/01/01/1991	100	
REILU0397	Doors	Fair				8946		30/01/01/1991	100	
REILU0398	Downpipes	Good				1742		20/01/01/1991	100	
REILU0400	Exterior Painting	Fair				2086		10/01/01/1991	100	
REILU0401	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0402	Fencing	Good				7725		20/01/01/1991	100	
REILU0403	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0404	Guttering	Good				2819		20/01/01/1991	100	
REILU0416	Path	Good				2197		30/01/01/1991	100	
REILU0417	Patio	Good				1642		30/01/01/1991	100	
REILU0418	Porch	Good				2908		30/01/01/1991	100	

REILU0436	Windows	Good				7747		30/01/1991	100	
REILU2006	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Unit 8

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0463	Exhaust Fan	Fair				255		10/01/03/2012	100	
REILU0476	Interior Painting	Good				177		10/01/03/2012	100	
REILU0485	Shower Screen	Fair				1165		20/01/03/2012	100	
REILU0488	Tapware	Good				1304		15/01/03/2012	100	
REILU0490	Tiles - Floor	Good				3940		20/01/03/2012	100	
REILU0492	Tiles - Wall	Good				3285		20/01/03/2012	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0445	Blind	Good				666		10/01/03/2012	100	
REILU0448	Carpet	Fair				1054		8/01/03/2012	100	
REILU0452	Ceiling Fan	Fair				588		10/01/03/2012	100	
REILU0472	Interior Painting	Good				921		10/01/03/2012	100	
REILU0498	Wardrobe	Good				2053		10/01/03/2012	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0444	Blind	Poor				333		10/01/03/2012	100	
REILU0447	Carpet	Fair				688		8/01/03/2012	100	
REILU0451	Ceiling Fan	Good				588		10/01/03/2012	100	
REILU0471	Interior Painting	Good				599		10/01/03/2012	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0450	Carpet	Poor				688		8/01/03/2012	100	
REILU0474	Interior Painting	Good				599		10/01/03/2012	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0475	Interior Painting	Good				355		10/01/03/2012	100	
REILU2036	Carpet	Good				1054		8/01/03/2012		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0442	Benchtops	Good				2344		20/01/03/2012	100	
REILU0443	Blind	Good				333		10/01/03/2012	100	
REILU0455	Cooktop	Fair	Westinghouse			1354		12/01/03/2012	100	
REILU0458	Curtains	Good				444		6/01/03/2012	100	
REILU0470	Interior Painting	Good				499		10/01/03/2012	100	
REILU0478	Kitchen Cabinets	Good				3818		20/01/03/2012	100	
REILU0479	Electric Elevated Oven	Fair	Westinghouse	PEK1350W-R	20880006	1409		12/01/03/2012	100	
REILU0483	Rangehood	Good	Westinghouse			599		12/01/03/2012	100	
REILU0486	Sink & Fittings	Good				1587		15/01/03/2012	100	
REILU0495	Vinyl	Fair				777		10/01/03/2012	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0477	Interior Painting	Good				177		10/01/03/2012	100	
REILU0491	Tiles - Floor	Good				2025		20/01/03/2012	100	
REILU0493	Tiles - Wall	Good				1209		20/01/03/2012	100	
REILU1932	Exhaust Fan	Good				255		10/03/11/2022	100	
REILU2037	Sink & Fittings	Good				1587		15/03/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0441	Air Conditioner - Split System	Good	Daikin	FVXS60HVMA	C000594	3296		10/01/03/2012	100	
REILU0446	Blind	Good				388		10/01/03/2012	100	
REILU0449	Carpet	Fair				954		8/01/03/2012	100	
REILU0453	Ceiling Fan	Good				588		10/01/03/2012	100	
REILU0459	Curtains	Good				1776		6/01/03/2012	100	

REILU0473	Interior Painting	Good					832	10/01/03/2012	100	
-----------	-------------------	------	--	--	--	--	-----	---------------	-----	--

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0489	Tiles - Floor	Good				1387		20/01/03/2012	100	
REILU0494	Toilet & Cistern	Good				1343		20/01/03/2012	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0454	Clothesline	Good				499		10/01/01/1991	100	
REILU0456	Courtyard	Fair				2908		30/01/01/1991	100	
REILU0460	Doors	Good				8946		30/01/01/1991	100	
REILU0461	Downpipes	Good				1742		20/01/01/1991	100	
REILU0462	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	
REILU0464	Exterior Painting	Fair				2086		10/01/01/1991	100	
REILU0465	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0466	Fencing	Good				7725		20/01/01/1991	100	
REILU0467	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0468	Guttering	Good				2819		20/01/01/1991	100	
REILU0480	Path	Good				2197		30/01/01/1991	100	
REILU0481	Patio	Good				1642		30/01/01/1991	100	
REILU0482	Porch	Good				2908		30/01/01/1991	100	
REILU0499	Water Meter	Good				388		20/01/01/1991	100	
REILU0500	Windows	Good				7747		30/01/01/1991	100	

Unit 9-10

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0501	Roof	Good				27972		50/01/01/1991	100	

Unit 9

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0502	Insulation	Good				3191		20/01/12/2018	100	
REILU0503	Lighting	Good				1909		15/01/12/2018	100	
REILU0504	Sarking	Good				4140		25/01/01/1991	100	
REILU0505	Smoke Alarms	Good				260		20/01/12/2018	100	
REILU0530	Hot Water System - Electric	Fair	Vulcan			2386		12/01/12/2018	100	
REILU0548	Skylight	Good				788		10/01/12/2018	100	

Unit 10

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0562	Insulation	Fair				3191		20/01/12/2004	100	
REILU0563	Lighting	Good				1909		15/01/12/2004	100	
REILU0564	Sarking	Good				4140		25/01/01/1991	100	
REILU0565	Smoke Alarms	Good				260		20/01/12/2004	100	
REILU0589	Hot Water System - Electric	Good	Vulcan	66125007	6499071	2386		12/01/12/2004	100	
REILU0607	Skylight	Good				788		10/01/12/2004	100	

Unit 9

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0524	Exhaust Fan	Good				255		10/01/12/2018	100	
REILU0537	Interior Painting	Good				177		10/01/12/2018	100	
REILU0545	Shower Screen	Good				1165		20/01/12/2018	100	
REILU0549	Tapware	Good				1304		15/01/12/2018	100	
REILU0552	Tiles - Floor	Good				3940		20/01/12/2018	100	
REILU0554	Tiles - Wall	Good				3285		20/01/12/2018	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0513	Carpet	Good				1054		8/01/12/2018	100	
REILU0516	Ceiling Fan	Good				588		10/01/12/2018	100	
REILU0533	Interior Painting	Good				921		10/01/12/2018	100	
REILU0559	Wardrobe	Good				2053		10/01/12/2018	100	

REILU2038	Blind	Good					1110		10/01/2018		
-----------	-------	------	--	--	--	--	------	--	------------	--	--

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0512	Carpet	Good				688		8/01/2018	100	
REILU0532	Interior Painting	Good				599		10/01/2018	100	
REILU2039	Ceiling fan	Good				588		10/01/2018		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0515	Vinyl	Excellent				688		8/01/2018	100	
REILU0535	Interior Painting	Good				599		10/01/2018	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0536	Interior Painting	Good				355		10/01/2018	100	
REILU0551	Vinyl	Good				932		10/01/2018	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0507	Benchtops	Excellent				2344		20/01/2018	100	
REILU0531	Interior Painting	Good				499		10/01/2018	100	
REILU0539	Kitchen Cabinets	Excellent				3818		20/01/2018	100	
REILU0547	Sink & Fittings	Excellent				1587		15/01/2018	100	
REILU0557	Vinyl	Excellent				777		10/01/2018	100	
REILU1933	Cooktop	Good	Fisher & Paykel			1354		12/03/11/2022	100	
REILU1934	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAN6U0028	1164		8/03/11/2022	100	
REILU1935	Oven	Good	Fisher & Paykel			1409		12/03/11/2022	100	
REILU1936	Rangehood	Good	Fisher & Paykel			599		12/03/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0538	Interior Painting	Good				177		10/01/2018	100	
REILU0553	Tiles - Floor	Good				2025		20/01/2018	100	
REILU0555	Tiles - Wall	Good				1209		20/01/2018	100	
REILU1937	Exhaust Fan	Good				255		10/03/11/2022	100	
REILU1938	Sink & Fittings	Good				1587		15/03/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0514	Vinyl	Excellent				954		8/01/2018	100	
REILU0517	Ceiling Fan	Good				588		10/01/2018	100	
REILU0534	Interior Painting	Good				832		10/01/2018	100	
REILU1939	Air Conditioner - Split System	Excellent	Actron Air			3296		10/03/11/2022	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0550	Tiles - Floor	Good				1387		20/01/2018	100	
REILU0556	Toilet & Cistern	Good				1343		20/01/2018	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0518	Clothesline	Good				499		10/01/01/1991	100	
REILU0520	Courtyard	Good				2908		30/01/01/1991	100	
REILU0521	Doors	Good				8946		30/01/01/1991	100	
REILU0522	Downpipes	Good				1742		20/01/01/1991	100	
REILU0523	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	
REILU0525	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU0526	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0527	Fencing	Good				7725		20/01/01/1991	100	
REILU0528	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0529	Guttering	Good				2819		20/01/01/1991	100	
REILU0541	Path	Good				2197		30/01/01/1991	100	
REILU0542	Patio	Good				1642		30/01/01/1991	100	
REILU0543	Porch	Good				2908		30/01/01/1991	100	
REILU0560	Water Meter	Good				388		20/01/01/1991	100	
REILU0561	Windows	Good				7747		30/01/01/1991	100	

Unit 10

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0583	Exhaust Fan	Good				255		10/01/12/2004	100	
REILU0596	Interior Painting	Good				177		10/01/12/2004	100	
REILU0605	Shower Screen	Good				1165		20/01/12/2004	100	
REILU0608	Tapware	Good				1304		15/01/12/2004	100	
REILU0611	Tiles - Floor	Good				3940		20/01/12/2004	100	
REILU0613	Tiles - Wall	Good				3285		20/01/12/2004	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0570	Blind	Good				1110		10/01/09/2015	100	
REILU0573	Carpet	Good				1054		8/01/12/2004	100	
REILU0576	Ceiling Fan	Good				588		10/01/12/2004	100	
REILU0592	Interior Painting	Good				921		10/01/12/2004	100	
REILU0619	Wardrobe	Good				2053		10/01/12/2004	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0569	Blind	Good				1110		10/01/09/2015	100	
REILU0572	Carpet	Good				688		8/01/12/2004	100	
REILU0591	Interior Painting	Good				599		10/01/12/2004	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0575	Carpet	Good				688		8/01/12/2004	100	
REILU0594	Interior Painting	Good				599		10/01/12/2004	100	
REILU1920	Shutter	Good				1110		10/01/09/2015		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0595	Interior Painting	Good				355		10/01/12/2004	100	
REILU0617	Vinyl	Good				932		10/01/12/2004	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0567	Benchtops	Good				2344		20/01/12/2004	100	
REILU0568	Blind	Good				333		10/01/09/2015	100	
REILU0579	Cooktop	Good	Westinghouse			1354		12/01/12/2004	100	
REILU0590	Interior Painting	Good				499		10/01/12/2004	100	
REILU0598	Kitchen Cabinets	Good				3818		20/01/12/2004	100	
REILU0599	Electric Elevated Oven	Good	Westinghouse	WDE147WA-R	88002	1409		12/01/12/2004	100	
REILU0603	Rangehood	Good	Westinghouse			599		12/01/12/2004	100	
REILU0606	Sink & Fittings	Good				1587		15/01/12/2004	100	
REILU0616	Vinyl	Good				777		10/01/12/2004	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0597	Interior Painting	Good				177		10/01/12/2004	100	
REILU0612	Tiles - Floor	Good				2025		20/01/12/2004	100	
REILU0614	Tiles - Wall	Good				1209		20/01/12/2004	100	
REILU2040	Sink & Fittings	Good				1587		15/01/12/2004		
REILU2041	Exhaust Fan	Good				255		10/01/12/2004		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0566	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	SRK60ZJX-S1	312900506RE	3296		10/01/12/2004	100	
REILU0571	Blind	Good				777		10/01/12/2004	100	
REILU0574	Carpet	Good				954		8/01/12/2004	100	
REILU0577	Ceiling Fan	Good				588		10/01/12/2004	100	
REILU0593	Interior Painting	Good				832		10/01/12/2004	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0609	Tiles - Floor	Good				1387		20/01/12/2004	100	
REILU0615	Toilet & Cistern	Good				1343		20/01/12/2004	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0578	Clothesline	Good				499		10/01/01/1991	100	
REILU0580	Courtyard	Good				2908		30/01/01/1991	100	
REILU0581	Doors	Good				8946		30/01/01/1991	100	
REILU0582	Downpipes	Good				1742		20/01/01/1991	100	
REILU0584	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU0585	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0586	Fencing	Fair				7725		20/01/01/1991	100	
REILU0587	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0588	Guttering	Good				2819		20/01/01/1991	100	
REILU0600	Path	Good				2197		30/01/01/1991	100	
REILU0601	Patio	Good				1642		30/01/01/1991	100	
REILU0602	Porch	Good				2908		30/01/01/1991	100	
REILU0620	Water Meter	Good				388		20/01/01/1991	100	
REILU0621	Windows	Good				7747		30/01/01/1991	100	
REILU2004	Electrical	Good				1964		20/01/09/2013	100	
	Switchboard									
REILU2042	Retaining wall	Fair				1587		20/01/09/2013		

Unit 11-12

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0622	Roof	Good				27972		50/01/01/1991	100	

Unit 11

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0623	Insulation	Good				3191		20/01/07/2018	100	
REILU0624	Lighting	Good				1909		15/01/07/2018	100	
REILU0625	Sarking	Good				4140		25/01/01/1991	100	
REILU0626	Smoke Alarms	Good				260		20/01/07/2018	100	
REILU0651	Hot Water System - Electric	Fair	Dux Proflo			2386		12/01/07/2018	100	
REILU0669	Skylight	Good				788		10/01/07/2018	100	

Unit 12

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0683	Insulation	Fair				3191		20/01/11/2021	100	
REILU0684	Lighting	Good				1909		15/01/11/2021	100	
REILU0685	Sarking	Good				4140		25/01/01/1991	100	
REILU0686	Smoke Alarms	Good				260		20/01/11/2021	100	
REILU0713	Hot Water System - Electric	Fair	Thermann	250THM136	17102420198H	2386		12/01/11/2021	100	
REILU0731	Skylight	Good				788		10/01/11/2021	100	

Unit 11

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0658	Interior Painting	Good				177		10/01/07/2018	100	
REILU0667	Shower Screen	Good				1165		20/01/07/2018	100	
REILU0670	Tapware	Good				1304		15/01/07/2018	100	
REILU0673	Tiles - Floor	Good				3940		20/01/07/2018	100	
REILU0675	Tiles - Wall	Good				3285		20/01/07/2018	100	
REILU1940	Exhaust Fan	Good				255		10/03/11/2022	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0631	Blind	Good				666		10/01/07/2018	100	
REILU0634	Carpet	Good				1054		8/01/07/2018	100	
REILU0638	Ceiling Fan	Good				588		10/01/07/2018	100	
REILU0654	Interior Painting	Good				921		10/01/07/2018	100	
REILU0680	Wardrobe	Good				2053		10/01/07/2018	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0630	Blind	Good				333		10/01/07/2018	100	

REILU0633	Carpet	Good				688	8/01/07/2018	100	
REILU0637	Ceiling Fan	Good				588	10/01/07/2018	100	
REILU0653	Interior Painting	Good				599	10/01/07/2018	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0636	Vinyl	Good				688	8/01/07/2018	100		
REILU0656	Interior Painting	Good				599	10/01/07/2018	100		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0657	Interior Painting	Good				355	10/01/07/2018	100		
REILU0679	Vinyl	Good				932	10/01/07/2018	100		

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0628	Benchtops	Good				2344	20/01/07/2018	100		
REILU0629	Blind	Good				333	10/01/07/2018	100		
REILU0641	Cooktop	Good	Fisher & Paykel			1354	12/01/07/2018	100		
REILU0652	Interior Painting	Good				499	10/01/07/2018	100		
REILU0660	Kitchen Cabinets	Good				3818	20/01/07/2018	100		
REILU0661	Oven	Good	Fisher & Paykel			1409	12/01/07/2018	100		
REILU0665	Rangehood	Good	Fisher & Paykel			599	12/01/07/2018	100		
REILU0668	Sink & Fittings	Good				1587	15/01/07/2018	100		
REILU0678	Vinyl	Good				777	10/01/07/2018	100		
REILU1941	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAM7C0180	1164	8/03/11/2022	100		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0659	Interior Painting	Good				177	10/01/07/2018	100		
REILU0674	Tiles - Floor	Good				2025	20/01/07/2018	100		
REILU0676	Tiles - Wall	Good				1209	20/01/07/2018	100		
REILU1942	Exhaust Fan	Good	Trader			255	10/03/11/2022	100		
REILU1943	Sink & Fittings	Good				1587	15/03/11/2022	100		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0627	Air Conditioner - Split System	Good	mitsubishi	DXK18ZMA-S		3296	10/01/07/2018	100		
REILU0632	Blind	Good				777	10/01/07/2018	100		
REILU0635	Vinyl	Good				954	8/01/07/2018	100		
REILU0639	Ceiling Fan	Good				588	10/01/07/2018	100		
REILU0655	Interior Painting	Good				832	10/01/07/2018	100		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0671	Tiles - Floor	Good				1387	20/01/07/2018	100		
REILU0677	Toilet & Cistern	Good				1343	20/01/07/2018	100		
REILU2043	Exhaust Fan	Good				255	10/01/07/2018	100		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0640	Clothesline	Good				499	10/01/01/1991	100		
REILU0642	Courtyard	Good				2908	30/01/01/1991	100		
REILU0643	Doors	Good				8946	30/01/01/1991	100		
REILU0644	Downpipes	Good				1742	20/01/01/1991	100		
REILU0646	Exterior Painting	Good				2086	10/01/01/1991	100		
REILU0647	Fascia & Barges	Good				2874	20/01/01/1991	100		
REILU0648	Fencing	Good				7725	20/01/01/1991	100		
REILU0649	Flyscreens	Good				1864	10/01/01/1991	100		
REILU0650	Guttering	Good				2819	20/01/01/1991	100		
REILU0662	Path	Good				2197	30/01/01/1991	100		
REILU0663	Patio	Good				1642	30/01/01/1991	100		
REILU0664	Porch	Good				2908	30/01/01/1991	100		
REILU0681	Water Meter	Good				388	20/01/01/1991	100		
REILU0682	Windows	Good				7747	30/01/01/1991	100		
REILU2005	Electrical Switchboard	Good				1964	20/01/09/2013	100		

Unit 12

REILU2044	Drain	Poor					1587		50/01/09/2013		
-----------	-------	------	--	--	--	--	------	--	---------------	--	--

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0707	Exhaust Fan	Good				255		10/01/11/2021	100	
REILU0720	Interior Painting	Good				177		10/01/11/2021	100	
REILU0729	Shower Screen	Fair				1165		20/01/11/2021	100	
REILU0732	Tapware	Good				1304		15/01/11/2021	100	
REILU0735	Tiles - Floor	Good				3940		20/01/11/2021	100	
REILU0737	Tiles - Wall	Good				3285		20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0691	Blind	Good				666		10/01/11/2021	100	
REILU0694	Carpet	Good				1054		8/01/11/2021	100	
REILU0698	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU0703	Curtains	Good				888		6/01/11/2021	100	
REILU0716	Interior Painting	Good				921		10/01/11/2021	100	
REILU0742	Wardrobe	Good				2053		10/01/11/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0690	Blind	Good				333		10/01/11/2021	100	
REILU0693	Carpet	Good				688		8/01/11/2021	100	
REILU0697	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU0715	Interior Painting	Good				599		10/01/11/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0718	Interior Painting	Good				599		10/01/11/2021	100	
REILU2045	Vinyl	Good				777		10/17/12/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0719	Interior Painting	Good				355		10/01/11/2021	100	
REILU0734	Vinyl	Good				932		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0688	Benchtops	Good				2344		20/01/11/2021	100	
REILU0689	Blind	Good				333		10/01/11/2021	100	
REILU0714	Interior Painting	Good				499		10/01/11/2021	100	
REILU0722	Kitchen Cabinets	Good				3818		20/01/11/2021	100	
REILU0730	Sink & Fittings	Good				1587		15/01/11/2021	100	
REILU0740	Vinyl	Good				777		10/01/11/2021	100	
REILU2046	Cooktop	Good	Fisher & Paykel			1354		12/17/12/2023		
REILU2047	Oven	Good	Fisher & Paykel			1409		12/17/12/2023		
REILU2048	Rangehood	Good	Fisher & Paykel			599		12/17/12/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0721	Interior Painting	Good				177		10/01/11/2021	100	
REILU0736	Tiles - Floor	Good				2025		20/01/11/2021	100	
REILU0738	Tiles - Wall	Good				1209		20/01/11/2021	100	
REILU2049	Exhaust Fan	Good				255		10/01/11/2021		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0687	Air Conditioner - Split System	Good	Daikin	FTXS60FVMA	E002325	3296		10/01/11/2021	100	
REILU0692	Blind	Good				777		10/01/11/2021	100	
REILU0699	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU0717	Interior Painting	Good				832		10/01/11/2021	100	
REILU2050	Vinyl	Good				777		10/17/12/2023		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0733	Tiles - Floor	Good				1387		20/01/11/2021	100	

REILU0739	Toilet & Cistern	Good					1343	20/01/11/2021	100	
-----------	------------------	------	--	--	--	--	------	---------------	-----	--

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0700	Clothesline	Good				499		10/01/01/1991	100	
REILU0702	Courtyard	Good				2908		30/01/01/1991	100	
REILU0704	Doors	Good				8946		30/01/01/1991	100	
REILU0705	Downpipes	Good				1742		20/01/01/1991	100	
REILU0706	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	
REILU0708	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU0709	Fascia & Barges	Fair				2874		20/01/01/1991	100	
REILU0710	Fencing	Fair				7725		20/01/01/1991	100	
REILU0711	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0712	Guttering	Good				2819		20/01/01/1991	100	
REILU0724	Path	Good				2197		30/01/01/1991	100	
REILU0725	Patio	Good				1642		30/01/01/1991	100	
REILU0726	Porch	Good				2908		30/01/01/1991	100	
REILU0743	Water Meter	Good				388		20/01/01/1991	100	
REILU0744	Windows	Good				7747		30/01/01/1991	100	

Unit 13-14

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0745	Roof	Good				27972		50/01/01/1991	100	

Unit 13

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0746	Insulation	Good				3191		20/01/12/2007	100	
REILU0748	Sarking	Good				4140		25/01/01/1991	100	
REILU0749	Smoke Alarms	Good				260		20/01/12/2007	100	
REILU0774	Hot Water System - Electric	Good	Rinnai	EHFA250S36	5218052	2386		12/01/12/2007	100	
REILU0792	Skylight	Good				788		10/01/12/2007	100	
REILU1978	Lighting	Excellent				355		15/18/08/2023	100	

Unit 14

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0807	Insulation	Good				3191		20/01/01/1991	100	
REILU0808	Lighting	Good				1909		15/01/01/1991	100	
REILU0809	Sarking	Good				4140		25/01/01/1991	100	
REILU0810	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU0835	Hot Water System - Electric	Good	Dux Proflo	250T136	18121320039H	2386		12/01/01/1991	100	
REILU0853	Skylight	Good				788		10/01/01/1991	100	

Unit 13

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0768	Exhaust Fan	Good				255		10/01/12/2007	100	
REILU0781	Interior Painting	Fair				177		10/01/12/2007	100	
REILU0789	Shower Screen	Good				1165		20/01/12/2007	100	
REILU0790	Shower Screen	Good				1165		20/01/12/2007	100	
REILU0793	Tapware	Good				1304		15/01/12/2007	100	
REILU0796	Tiles - Floor	Fair				3940		20/01/12/2007	100	
REILU0798	Tiles - Wall	Good				3285		20/01/12/2007	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0754	Blind	Fair				666		10/01/12/2007	100	
REILU0757	Carpet	Poor				1054		8/01/12/2007	100	
REILU0777	Interior Painting	Fair				921		10/01/12/2007	100	
REILU0804	Wardrobe	Good				2053		10/01/12/2007	100	
REILU1976	Ceiling Fan	Excellent				510		10/18/08/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

REILU0753	Blind	Fair					333	10/01/2007	100	
REILU0756	Carpet	Poor					688	8/01/2007	100	
REILU0776	Interior Painting	Fair					599	10/01/2007	100	
REILU0803	Wardrobe	Good					2053	10/01/2007	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0759	Carpet	Poor					688	8/01/2007	100	
REILU0779	Interior Painting	Fair					599	10/01/2007	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0780	Interior Painting	Fair					355	10/01/2007	100	
REILU0795	Vinyl	Poor					932	10/01/2007	100	
REILU0802	Vinyl	Good					932	10/01/2007	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0751	Benchtops	Good					2344	20/01/2007	100	
REILU0752	Blind	Fair					333	10/01/2007	100	
REILU0763	Cooktop	Good	Westinghouse				1354	12/01/2007	100	
REILU0775	Interior Painting	Fair					499	10/01/2007	100	
REILU0783	Kitchen Cabinets	Good					3818	20/01/2007	100	
REILU0784	Electric Elevated Oven	Good	Westinghouse	WDE147WA-L	71580040		1409	12/01/2007	100	
REILU0788	Rangehood	Good	Westinghouse				599	12/01/2007	100	
REILU0791	Sink & Fittings	Good					1587	15/01/2007	100	
REILU0801	Vinyl	Fair					777	10/01/2007	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0782	Interior Painting	Fair					177	10/01/2007	100	
REILU0797	Tiles - Floor	Fair					2025	20/01/2007	100	
REILU0799	Tiles - Wall	Good					1209	20/01/2007	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0750	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	DXK18ZMA-S	535500262BE		3296	10/01/2007	100	
REILU0755	Blind	Fair					777	10/01/2007	100	
REILU0758	Carpet	Poor					954	8/01/2007	100	
REILU0778	Interior Painting	Fair					832	10/01/2007	100	
REILU1977	Ceiling Fan	Excellent					510	10/18/2023	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0794	Tiles - Floor	Fair					1387	20/01/2007	100	
REILU0800	Toilet & Cistern	Good					1343	20/01/2007	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0762	Clothesline	Good					499	10/01/01/1991	100	
REILU0764	Courtyard	Good					2908	30/01/01/1991	100	
REILU0765	Doors	Good					8946	30/01/01/1991	100	
REILU0766	Downpipes	Good					1742	20/01/01/1991	100	
REILU0767	Electrical Switchboard	Good	B&R				1964	20/01/01/1991	100	
REILU0769	Exterior Painting	Good					2086	10/01/01/1991	100	
REILU0770	Fascia & Barges	Good					2874	20/01/01/1991	100	
REILU0771	Fencing	Fair					7725	20/01/01/1991	100	
REILU0772	Flyscreens	Good					1864	10/01/01/1991	100	
REILU0773	Guttering	Good					2819	20/01/01/1991	100	
REILU0785	Path	Good					2197	30/01/01/1991	100	
REILU0786	Patio	Good					1642	30/01/01/1991	100	
REILU0787	Porch	Good					2908	30/01/01/1991	100	
REILU0805	Water Meter	Good					388	20/01/01/1991	100	
REILU0806	Windows	Good					7747	30/01/01/1991	100	

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0829	Exhaust Fan	Good				255		10/01/1991	100	
REILU0842	Interior Painting	Fair				177		10/01/1991	100	
REILU0850	Shower Screen	Fair				1165		20/01/1991	100	
REILU0854	Tapware	Good				1304		15/01/1991	100	
REILU0857	Tiles - Floor	Fair				3940		20/01/1991	100	
REILU0859	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0818	Carpet	Good				1054		8/01/1991	100	
REILU0838	Interior Painting	Fair				921		10/01/1991	100	
REILU0865	Wardrobe	Good				2053		10/01/1991	100	
REILU1980	Ceiling Fan	Good				782		10/11/08/2023	100	
REILU2052	Blind	Good				1110		10/14/12/2023		

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0817	Carpet	Good				688		8/01/1991	100	
REILU0837	Interior Painting	Fair				599		10/01/1991	100	
REILU0864	Wardrobe	Good				2053		10/01/1991	100	
REILU1979	Ceiling Fan	Good				782		10/11/08/2023	100	
REILU2053	Blind	Good				1110		10/14/12/2023		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0820	Carpet	Good				688		8/01/1991	100	
REILU0840	Interior Painting	Good				599		10/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0841	Interior Painting	Fair				355		10/01/1991	100	
REILU0856	Vinyl	Good				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0812	Benchtops	Good				2344		20/01/1991	100	
REILU0825	Cooktop	Good	Westinghouse			1354		12/01/1991	100	
REILU0836	Interior Painting	Fair				499		10/01/1991	100	
REILU0844	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU0845	Electric Elevated Oven	Good	Westinghouse	WDE147WA-R	10380051	1409		12/01/1991	100	
REILU0849	Rangehood	Fair	Simpson			599		12/01/1991	100	
REILU0852	Sink & Fittings	Good				1587		15/01/1991	100	
REILU0862	Vinyl	Good				777		10/01/1991	100	
REILU2054	Blind	Good				1110		10/14/12/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0843	Interior Painting	Fair				177		10/01/1991	100	
REILU0858	Tiles - Floor	Good				2025		20/01/1991	100	
REILU0860	Tiles - Wall	Good				1209		20/01/1991	100	
REILU2055	Sink & Fittings	Good				1587		15/01/1991		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0811	Air Conditioner - Split System	Good	DAIKIN	FVXS60LVMA	C006243	3296		10/08/06/2022	100	
REILU0816	Blind	Good				777		10/01/1991	100	
REILU0819	Carpet	Good				954		8/01/1991	100	
REILU0839	Interior Painting	Good				832		10/01/1991	100	
REILU1981	Ceiling Fan	Good				255		10/18/08/2023	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0855	Tiles - Floor	Good				1387		20/01/1991	100	
REILU0861	Toilet & Cistern	Good				1343		20/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0826	Courtyard	Good				2908		30/01/1991	100	
REILU0827	Doors	Good				8946		30/01/1991	100	
REILU0828	Downpipes	Good				1742		20/01/1991	100	
REILU0830	Exterior Painting	Good				2086		10/01/1991	100	
REILU0831	Fascia & Barges	Good				2874		20/01/1991	100	
REILU0832	Fencing	Fair				7725		20/01/1991	100	
REILU0833	Flyscreens	Good				1864		10/01/1991	100	
REILU0834	Guttering	Good				2819		20/01/1991	100	
REILU0846	Path	Good				2197		30/01/1991	100	
REILU0847	Patio	Good				1642		30/01/1991	100	
REILU0848	Porch	Good				2908		30/01/1991	100	
REILU0866	Water Meter	Good				388		20/01/1991	100	
REILU0867	Windows	Good				7747		30/01/1991	100	
REILU1982	Clothesline	Excellent				1213		10/02/08/2023	100	
REILU2007	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Unit 15-16

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0868	Roof	Good				27972		50/01/1991	100	

Unit 15

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0869	Insulation	Fair				3191		20/01/1991	100	
REILU0870	Lighting	Good				1909		15/01/1991	100	
REILU0871	Sarking	Good				4140		25/01/1991	100	
REILU0872	Smoke Alarms	Good				260		20/01/1991	100	
REILU0894	Hot Water System - Electric	Good	Vulcan	66125008	5207374	2386		12/01/1991	100	
REILU0912	Skylight	Good				788		10/01/1991	100	

Unit 16

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0926	Insulation	Good				3191		20/01/11/2021	100	
REILU0927	Lighting	Good				1909		15/01/11/2021	100	
REILU0928	Sarking	Good				4140		25/01/1991	100	
REILU0929	Smoke Alarms	Good				260		20/01/11/2021	100	
REILU0959	Hot Water System - Electric	Good	Thermann	250THM136	19021320168H	2386		12/01/11/2021	100	
REILU0977	Skylight	Good				788		10/01/11/2021	100	

Unit 15

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0888	Exhaust Fan	Good				255		10/01/1991	100	
REILU0910	Shower Screen	Good				1165		20/01/1991	100	
REILU0913	Tapware	Good				1304		15/01/1991	100	
REILU0916	Tiles - Floor	Good				3940		20/01/1991	100	
REILU0918	Tiles - Wall	Good				3285		20/01/1991	100	
REILU1989	Interior Painting	Good				1070		10/10/05/2023	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0876	Blind	Good				666		10/01/1991	100	
REILU0879	Carpet	Fair				1054		8/01/1991	100	
REILU0923	Wardrobe	Good				2053		10/01/1991	100	
REILU1985	Interior Painting	Good				1070		10/10/05/2023	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0875	Blind	Good				333		10/01/1991	100	
REILU0878	Carpet	Good				688		8/01/1991	100	
REILU1984	Interior Painting	Good				1070		10/10/05/2023	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0881	Carpet	Fair				688		8/01/01/1991	100	
REILU1987	Interior Painting	Good				1070		10/10/05/2023	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0915	Vinyl	Good				932		10/01/01/1991	100	
REILU1988	Interior Painting	Good				1070		10/10/05/2023	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0873	Benchtops	Fair				2344		20/01/01/1991	100	
REILU0874	Blind	Good				333		10/01/01/1991	100	
REILU0884	Cooktop	Good	Westinghouse			1354		12/01/01/1991	100	
REILU0903	Kitchen Cabinets	Good				3818		20/01/01/1991	100	
REILU0904	Electric Elevated Oven	Good	Westinghouse	WDE143WC-L	12880017	1409		12/01/01/1991	100	
REILU0908	Rangehood	Good	Westinghouse			599		12/01/01/1991	100	
REILU0911	Sink & Fittings	Good				1587		15/01/01/1991	100	
REILU0921	Vinyl	Fair				777		10/01/01/1991	100	
REILU1983	Interior Painting	Good				1070		10/10/05/2023	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0917	Tiles - Floor	Good				2025		20/01/01/1991	100	
REILU0919	Tiles - Wall	Good				1209		20/01/01/1991	100	
REILU1944	Exhaust Fan	Good				255		10/03/11/2022	100	
REILU1990	Interior Painting	Good				1070		10/10/05/2023	100	
REILU2056	Sink & Fittings	Good				1587		15/03/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0877	Blind	Good				777		10/01/01/1991	100	
REILU0880	Carpet	Fair				954		8/01/01/1991	100	
REILU0882	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1986	Interior Painting	Good				1070		10/10/05/2023	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0914	Tiles - Floor	Good				1387		20/01/01/1991	100	
REILU0920	Toilet & Cistern	Good				1343		20/01/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0883	Clothesline	Good				499		10/01/01/1991	100	
REILU0885	Courtyard	Good				2908		30/01/01/1991	100	
REILU0886	Doors	Good				8946		30/01/01/1991	100	
REILU0887	Downpipes	Good				1742		20/01/01/1991	100	
REILU0889	Exterior Painting	Fair				2086		10/01/01/1991	100	
REILU0890	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU0891	Fencing	Fair				7725		20/01/01/1991	100	
REILU0892	Flyscreens	Good				1864		10/01/01/1991	100	
REILU0893	Guttering	Good				2819		20/01/01/1991	100	
REILU0905	Path	Good				2197		30/01/01/1991	100	
REILU0906	Patio	Good				1642		30/01/01/1991	100	
REILU0907	Porch	Good				2908		30/01/01/1991	100	
REILU0924	Water Meter	Good				388		20/01/01/1991	100	
REILU0925	Windows	Good				7747		30/01/01/1991	100	
REILU1996	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2057	Vent pipe	Fair				1587		15/01/09/2013		
REILU2058	Drain	Poor				1587		50/01/09/2013		

Unit 16

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0953	Exhaust Fan	Good				255		10/01/11/2021	100	
REILU0966	Interior Painting	Good				177		10/01/11/2021	100	

REILU0974	Shower Screen	Good					1165	20/01/11/2021	100	
REILU0978	Tapware	Good					1304	15/01/11/2021	100	
REILU0981	Tiles - Floor	Good					3940	20/01/11/2021	100	
REILU0983	Tiles - Wall	Good					3285	20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0934	Blind	Good				666	10/01/11/2021	10/01/11/2021	100	
REILU0937	Carpet	Good				1054	8/01/11/2021	8/01/11/2021	100	
REILU0941	Ceiling Fan	Good				588	10/01/11/2021	10/01/11/2021	100	
REILU0962	Interior Painting	Good				921	10/01/11/2021	10/01/11/2021	100	
REILU0989	Wardrobe	Good				2053	10/01/11/2021	10/01/11/2021	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0933	Blind	Good				333	10/01/11/2021	10/01/11/2021	100	
REILU0936	Carpet	Good				688	8/01/11/2021	8/01/11/2021	100	
REILU0940	Ceiling Fan	Good				588	10/01/11/2021	10/01/11/2021	100	
REILU0961	Interior Painting	Good				599	10/01/11/2021	10/01/11/2021	100	
REILU0988	Wardrobe	Good				2053	10/01/11/2021	10/01/11/2021	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0939	Vinyl	Good				688	8/01/11/2021	8/01/11/2021	100	
REILU0964	Interior Painting	Good				599	10/01/11/2021	10/01/11/2021	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0965	Interior Painting	Good				355	10/01/11/2021	10/01/11/2021	100	
REILU0980	Vinyl	Good				932	10/01/11/2021	10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0931	Benchtops	Good				2344	20/01/11/2021	20/01/11/2021	100	
REILU0932	Blind	Good				333	10/01/11/2021	10/01/11/2021	100	
REILU0960	Interior Painting	Good				499	10/01/11/2021	10/01/11/2021	100	
REILU0968	Kitchen Cabinets	Good				3818	20/01/11/2021	20/01/11/2021	100	
REILU0969	Oven	Good	Fisher & Paykel	PEK1350W-R	14680012	1409	12/01/11/2021	12/01/11/2021	100	
REILU0973	Rangehood	Good	Fisher & Paykel			599	12/01/11/2021	12/01/11/2021	100	
REILU0976	Sink & Fittings	Good				1587	15/01/11/2021	15/01/11/2021	100	
REILU0986	Vinyl	Good				777	10/01/11/2021	10/01/11/2021	100	
REILU1945	Cooktop	Good	Fisher & Paykel			1354	12/04/11/2022	12/04/11/2022	100	
REILU1946	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAM830925	1164	8/04/11/2022	8/04/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0967	Interior Painting	Good				177	10/01/11/2021	10/01/11/2021	100	
REILU0982	Tiles - Floor	Good				2025	20/01/11/2021	20/01/11/2021	100	
REILU0984	Tiles - Wall	Good				1209	20/01/11/2021	20/01/11/2021	100	
REILU1947	Exhaust Fan	Good				255	10/04/11/2022	10/04/11/2022	100	
REILU1948	Sink & Fittings	Good				1587	15/04/11/2022	15/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0930	Air Conditioner - Split System	Good	Daikin			3296	10/01/11/2021	10/01/11/2021	100	
REILU0935	Blind	Good				777	10/01/11/2021	10/01/11/2021	100	
REILU0938	Vinyl	Good				954	8/01/11/2021	8/01/11/2021	100	
REILU0942	Ceiling Fan	Good				588	10/01/11/2021	10/01/11/2021	100	
REILU0963	Interior Painting	Good				832	10/01/11/2021	10/01/11/2021	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0979	Tiles - Floor	Good				1387	20/01/11/2021	20/01/11/2021	100	
REILU0985	Toilet & Cistern	Good				1343	20/01/11/2021	20/01/11/2021	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0943	Clothesline	Good				499	10/01/01/1991	10/01/01/1991	100	

REILU0945	Courtyard	Good					2908	30/01/1991	100	
REILU0950	Doors	Good					8946	30/01/1991	100	
REILU0951	Downpipes	Good					1742	20/01/1991	100	
REILU0952	Electrical Switchboard	Good	B&R				1964	20/01/1991	100	
REILU0954	Exterior Painting	Good					2086	10/01/1991	100	
REILU0955	Fascia & Barges	Good					2874	20/01/1991	100	
REILU0956	Fencing	Fair					7725	20/01/1991	100	
REILU0957	Flyscreens	Good					1864	10/01/1991	100	
REILU0958	Guttering	Good					2819	20/01/1991	100	
REILU0970	Path	Good					2197	30/01/1991	100	
REILU0971	Patio	Good					1642	30/01/1991	100	
REILU0972	Porch	Good					2908	30/01/1991	100	
REILU0990	Water Meter	Good					388	20/01/1991	100	
REILU0991	Windows	Good					7747	30/01/1991	100	
REILU2059	Vent pipe	Fair					1587	15/01/1991		

Unit 17-18

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0996	Roof	Good				27972		50/01/1991	100	

Unit 17

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU0997	Insulation	Good				3191		20/01/05/2004	100	
REILU0998	Lighting	Good				1909		15/01/05/2004	100	
REILU0999	Sarking	Good				4140		25/01/01/1991	100	
REILU1000	Smoke Alarms	Good				260		20/01/05/2004	100	
REILU1024	Hot Water System - Electric	Good	Vulcan	66125008	2557805	2386		12/01/05/2004	100	
REILU1042	Skylight	Good				788		10/01/05/2004	100	

Unit 18

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1056	Insulation	Good				3191		20/01/01/1991	100	
REILU1057	Lighting	Good				1909		15/01/01/1991	100	
REILU1058	Sarking	Good				4140		25/01/01/1991	100	
REILU1059	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU1087	Hot Water System - Electric	Good	Vulcan			2386		12/01/01/1991	100	
REILU1105	Skylight	Good				788		10/01/01/1991	100	

Unit 17

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1018	Exhaust Fan	Good	IXL & Airflow			255		10/01/05/2004	100	
REILU1031	Interior Painting	Good				177		10/01/05/2004	100	
REILU1039	Shower Screen	Good				1165		20/01/05/2004	100	
REILU1043	Tapware	Good				1304		15/01/05/2004	100	
REILU1046	Tiles - Floor	Good				3940		20/01/05/2004	100	
REILU1048	Tiles - Wall	Good				3285		20/01/05/2004	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1004	Blind	Good				666		10/01/05/2004	100	
REILU1007	Carpet	Good				1054		8/01/05/2004	100	
REILU1010	Ceiling Fan	Good				588		10/01/05/2004	100	
REILU1027	Interior Painting	Good				921		10/01/05/2004	100	
REILU1053	Wardrobe	Good				2053		10/01/05/2004	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1003	Blind	Good				333		10/01/05/2004	100	
REILU1006	Carpet	Good				688		8/01/05/2004	100	
REILU1026	Interior Painting	Good				599		10/01/05/2004	100	
REILU1949	Ceiling Fan	Good				588		10/04/11/2022	100	

REILU2060	Doors	Fair					8946		30/01/05/2004		
-----------	-------	------	--	--	--	--	------	--	---------------	--	--

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1029	Interior Painting	Good				599		10/01/05/2004	100	
REILU2017	Vinyl	Good				688		10/04/11/2022	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1030	Interior Painting	Good				355		10/01/05/2004	100	
REILU1045	Vinyl	Good				932		10/01/05/2004	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1001	Benchtops	Good				2344		20/01/05/2004	100	
REILU1002	Blind	Good				333		10/01/05/2004	100	
REILU1025	Interior Painting	Good				499		10/01/05/2004	100	
REILU1033	Kitchen Cabinets	Good				3818		20/01/05/2004	100	
REILU1038	Rangehood	Good	Fisher & Paykel			599		12/01/05/2004	100	
REILU1041	Sink & Fittings	Good				1587		15/01/05/2004	100	
REILU1051	Vinyl	Good				777		10/01/05/2004	100	
REILU1950	Cooktop	Good	Fisher & Paykel			1354		12/04/11/2022	100	
REILU1951	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAN3P0276	1164		8/04/11/2022	100	
REILU1952	Oven	Good	Fisher & Paykel			1409		12/04/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1032	Interior Painting	Good				177		10/01/05/2004	100	
REILU1047	Tiles - Floor	Good				2025		20/01/05/2004	100	
REILU1049	Tiles - Wall	Good				1209		20/01/05/2004	100	
REILU1953	Exhaust Fan	Good	IXL & Airflow			255		10/04/11/2022	100	
REILU1954	Sink & Fittings	Good				1587		15/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1005	Blind	Good				777		10/01/05/2004	100	
REILU1011	Ceiling Fan	Good				588		10/01/05/2004	100	
REILU1028	Interior Painting	Good				832		10/01/05/2004	100	
REILU1955	Air Conditioner - Split System	Good	Daikin	FTXS60LVMA	E074232	3296		10/04/11/2022	100	
REILU2018	Vinyl	Good				954		10/04/11/2022	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1044	Tiles - Floor	Good				1387		20/01/05/2004	100	
REILU1050	Toilet & Cistern	Good				1343		20/01/05/2004	100	
REILU1956	Interior Painting	Good				499		10/04/11/2022	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1012	Clothesline	Good				499		10/25/08/2022		
REILU1014	Courtyard	Good				2908		30/01/01/1991	100	
REILU1015	Doors	Good				8946		30/01/01/1991	100	
REILU1016	Downpipes	Good				1742		20/01/01/1991	100	
REILU1017	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	
REILU1019	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1020	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1021	Fencing	Fair				7725		20/01/01/1991	100	
REILU1022	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1023	Guttering	Good				2819		20/01/01/1991	100	
REILU1035	Path	Good				2197		30/01/01/1991	100	
REILU1036	Patio	Good				1642		30/01/01/1991	100	
REILU1037	Porch	Good				2908		30/01/01/1991	100	
REILU1054	Water Meter	Good				388		20/01/01/1991	100	
REILU1055	Windows	Good				7747		30/01/01/1991	100	

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1081	Exhaust Fan	Good				255		10/01/1991	100	
REILU1094	Interior Painting	Good				177		10/01/1991	100	
REILU1102	Shower Screen	Good				1165		20/01/1991	100	
REILU1106	Tapware	Good				1304		15/01/1991	100	
REILU1109	Tiles - Floor	Good				3940		20/01/1991	100	
REILU1111	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1064	Blind	Good				333		10/01/1991	100	
REILU1067	Carpet	Good				1054		8/01/1991	100	
REILU1071	Ceiling Fan	Good				588		10/01/1991	100	
REILU1078	Curtains	Good				1776		6/01/1991	100	
REILU1090	Interior Painting	Good				921		10/01/1991	100	
REILU1116	Wardrobe	Good				2053		10/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1063	Blind	Good				333		10/01/1991	100	
REILU1066	Carpet	Good				688		8/01/1991	100	
REILU1070	Ceiling Fan	Good				588		10/01/1991	100	
REILU1077	Curtains	Good				888		6/01/1991	100	
REILU1089	Interior Painting	Good				599		10/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1069	Carpet	Good				688		8/01/1991	100	
REILU1092	Interior Painting	Good				599		10/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1093	Interior Painting	Good				355		10/01/1991	100	
REILU1115	Vinyl	Good				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1061	Benchtops	Good				2344		20/01/1991	100	
REILU1062	Blind	Good				333		10/01/1991	100	
REILU1074	Cooktop	Good	Westinghouse			1354		12/01/1991	100	
REILU1076	Curtains	Good				444		6/01/1991	100	
REILU1088	Interior Painting	Good				499		10/01/1991	100	
REILU1096	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU1097	Electric Elevated Oven	Good	Westinghouse			1409		12/01/1991	100	
REILU1101	Rangehood	Good	Westinghouse			599		12/01/1991	100	
REILU1104	Sink & Fittings	Good				1587		15/01/1991	100	
REILU1114	Vinyl	Good				777		10/01/1991	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1095	Interior Painting	Good				177		10/01/1991	100	
REILU1110	Tiles - Floor	Good				2025		20/01/1991	100	
REILU1112	Tiles - Wall	Good				1209		20/01/1991	100	
REILU2061	Sink & Fittings	Good				1587		15/01/1991		
REILU2062	Exhaust Fan	Good				255		10/01/1991		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1060	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	SRK71ZMA-S	438103310BE	3296		10/01/1991	100	
REILU1065	Blind	Good				388		10/01/1991	100	
REILU1068	Carpet	Good				954		8/01/1991	100	
REILU1072	Ceiling Fan	Good				588		10/01/1991	100	
REILU1091	Interior Painting	Good				832		10/01/1991	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1107	Tiles - Floor	Good				1387		20/01/1991	100	

REILU1113	Toilet & Cistern	Good					1343	20/01/1991	100	
-----------	------------------	------	--	--	--	--	------	------------	-----	--

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1073	Clothesline	Good				499		10/01/1991	100	
REILU1075	Courtyard	Good				2908		30/01/1991	100	
REILU1079	Doors	Good				8946		30/01/1991	100	
REILU1080	Downpipes	Good				1742		20/01/1991	100	
REILU1082	Exterior Painting	Fair				2086		10/01/1991	100	
REILU1083	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1084	Fencing	Good				7725		20/01/1991	100	
REILU1085	Flyscreens	Good				1864		10/01/1991	100	
REILU1086	Guttering	Good				2819		20/01/1991	100	
REILU1098	Path	Good				2197		30/01/1991	100	
REILU1099	Patio	Fair				1642		30/01/1991	100	
REILU1100	Porch	Good				2908		30/01/1991	100	
REILU1117	Water Meter	Good				388		20/01/1991	100	
REILU1118	Windows	Good				7747		30/01/1991	100	
REILU1957	Blind	Good				555		10/04/11/2022	100	
REILU1997	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2063	Vent pipe	Poor				1587		15/01/09/2013		

Unit 19-20

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1122	Roof	Good				27972		50/01/1991	100	

Unit 19

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1123	Insulation	Good				3191		20/01/07/2003	100	
REILU1124	Lighting	Good				1909		15/01/07/2003	100	
REILU1125	Sarking	Good				4140		25/01/01/1991	100	
REILU1126	Smoke Alarms	Good				260		20/01/07/2003	100	
REILU1151	Hot Water System - Electric	Good	Everhot	291250R7	5645931	2386		12/01/07/2003	100	
REILU1169	Skylight	Good				788		10/01/07/2003	100	

Unit 20

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1183	Insulation	Good				3191		20/01/03/2019	100	
REILU1184	Lighting	Good				1909		15/01/03/2019	100	
REILU1185	Sarking	Good				4140		25/01/01/1991	100	
REILU1186	Smoke Alarms	Good				260		20/01/03/2019	100	
REILU1213	Hot Water System - Electric	Good	Thermann	250THM136	18050820102H	2386		12/01/03/2019	100	
REILU1231	Skylight	Good				788		10/01/03/2019	100	

Unit 19

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1145	Exhaust Fan	Good				255		10/01/07/2003	100	
REILU1158	Interior Painting	Fair				177		10/01/07/2003	100	
REILU1167	Shower Screen	Fair				1165		20/01/07/2003	100	
REILU1170	Tapware	Good				1304		15/01/07/2003	100	
REILU1173	Tiles - Floor	Good				3940		20/01/07/2003	100	
REILU1175	Tiles - Wall	Good				3285		20/01/07/2003	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1121	Curtains	Good				1776		6/01/07/2003	100	
REILU1128	Air Conditioner - Split System	Good	Daikin	FTX20KVMA	E002552	3296		10/01/07/2003	100	
REILU1131	Blind	Good				666		10/01/07/2003	100	
REILU1134	Carpet	Poor				1054		8/01/07/2003	100	
REILU1138	Ceiling Fan	Good				588		10/01/07/2003	100	

REILU1154	Interior Painting	Good					921	10/01/07/2003	100	
REILU1180	Wardrobe	Good					2053	10/01/07/2003	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1133	Carpet	Fair				688		8/01/07/2003	100	
REILU1137	Ceiling Fan	Good				588		10/01/07/2003	100	
REILU1153	Interior Painting	Good				599		10/01/07/2003	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1136	Carpet	Poor				688		8/01/07/2003	100	
REILU1156	Interior Painting	Good				599		10/01/07/2003	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1157	Interior Painting	Good				355		10/01/07/2003	100	
REILU1179	Vinyl	Poor				932		10/01/07/2003	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1129	Benchtops	Good				2344		20/01/07/2003	100	
REILU1130	Blind	Good				333		10/01/07/2003	100	
REILU1141	Cooktop	Good	Westinghouse			1354		12/01/07/2003	100	
REILU1152	Interior Painting	Good				499		10/01/07/2003	100	
REILU1160	Kitchen Cabinets	Good				3818		20/01/07/2003	100	
REILU1161	Electric Elevated Oven	Good	Westinghouse	PEK1350W-L*40	90380073	1409		12/01/07/2003	100	
REILU1165	Rangehood	Good	Simpson			599		12/01/07/2003	100	
REILU1168	Sink & Fittings	Good				1587		15/01/07/2003	100	
REILU1178	Vinyl	Good				777		10/01/07/2003	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1159	Interior Painting	Good				177		10/01/07/2003	100	
REILU1174	Tiles - Floor	Good				2025		20/01/07/2003	100	
REILU1176	Tiles - Wall	Good				1209		20/01/07/2003	100	
REILU1958	Exhaust Fan	Good				255		10/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1127	Air Conditioner - Split System	Good	Daikin	FTXS60GVMA	E008134	3296		10/01/07/2003	100	
REILU1132	Blind	Good				777		10/01/07/2003	100	
REILU1135	Carpet	Poor				954		8/01/07/2003	100	
REILU1139	Ceiling Fan	Good				588		10/01/07/2003	100	
REILU1155	Interior Painting	Fair				832		10/01/07/2003	100	
REILU2064	Tiles - Entry Landing	Poor				1587		20/01/07/2003		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1119	Curtains	Good				333		6/01/07/2003	100	
REILU1171	Tiles - Floor	Good				1387		20/01/07/2003	100	
REILU1177	Toilet & Cistern	Good				1343		20/01/07/2003	100	
REILU2065	Interior Painting	Fair				177		10/01/07/2003		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1142	Courtyard	Good				2908		30/01/01/1991	100	
REILU1143	Doors	Good				8946		30/01/01/1991	100	
REILU1144	Downpipes	Good				1742		20/01/01/1991	100	
REILU1146	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1147	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1148	Fencing	Fair				7725		20/01/01/1991	100	
REILU1149	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1150	Guttering	Good				2819		20/01/01/1991	100	
REILU1162	Path	Good				2197		30/01/01/1991	100	
REILU1163	Patio	Good				1642		30/01/01/1991	100	
REILU1164	Porch	Good				2908		30/01/01/1991	100	

REILU1181	Water Meter	Good				388		20/01/01/1991	100	
REILU1182	Windows	Good				7747		30/01/01/1991	100	
REILU1959	Blind	Good				555		10/04/11/2022	100	
REILU2008	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2066	Clothesline	Good				499		10/14/12/2023		

Unit 20

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1207	Exhaust Fan	Good				255		10/01/03/2019	100	
REILU1220	Interior Painting	Good				177		10/01/03/2019	100	
REILU1229	Shower Screen	Good				1165		20/01/03/2019	100	
REILU1232	Tapware	Good				1304		15/01/03/2019	100	
REILU1235	Tiles - Floor	Good				3940		20/01/03/2019	100	
REILU1237	Tiles - Wall	Good				3285		20/01/03/2019	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1195	Carpet	Good				1054		8/01/03/2019	100	
REILU1199	Ceiling Fan	Good				588		10/01/03/2019	100	
REILU1216	Interior Painting	Good				921		10/01/03/2019	100	
REILU1243	Wardrobe	Good				2053		10/01/03/2019	100	
REILU2067	Blind	Good				1110		10/14/12/2023		
REILU2068	Air Conditioner - Split System	Good	Daikin			3296		10/01/03/2019		

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1194	Carpet	Good				688		8/01/03/2019	100	
REILU1198	Ceiling Fan	Good				588		10/01/03/2019	100	
REILU1215	Interior Painting	Good				599		10/01/03/2019	100	
REILU1242	Wardrobe	Good				2053		10/01/03/2019	100	
REILU2069	Blind	Good				1110		10/14/12/2023		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1218	Interior Painting	Good				599		10/01/03/2019	100	
REILU2070	Vinyl	Good				777		10/14/12/2023		

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1219	Interior Painting	Good				355		10/01/03/2019	100	
REILU1241	Vinyl	Good				932		10/01/03/2019	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1189	Benchtops	Good				2344		20/01/03/2019	100	
REILU1202	Cooktop	Good	Fisher & Paykel			1354		12/01/03/2019	100	
REILU1214	Interior Painting	Good				499		10/01/03/2019	100	
REILU1222	Kitchen Cabinets	Good				3818		20/01/03/2019	100	
REILU1230	Sink & Fittings	Good				1587		15/01/03/2019	100	
REILU1240	Vinyl	Good				777		10/01/03/2019	100	
REILU2071	Blind	Good				1110		8/14/12/2023		
REILU2072	Rangehood	Good	Fisher & Paykel			599		12/14/12/2023		
REILU2073	Oven	Good	Fisher & Paykel			1409		12/14/12/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1221	Interior Painting	Good				177		10/01/03/2019	100	
REILU1236	Tiles - Floor	Good				2025		20/01/03/2019	100	
REILU1238	Tiles - Wall	Good				1209		20/01/03/2019	100	
REILU2074	Sink & Fittings	Good				1587		15/01/03/2019		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1188	Air Conditioner - Split System	Good	Daikin	FTXS25LVMA	E022949	3296		10/01/03/2019	100	
REILU1193	Blind	Good				777		10/01/03/2019	100	

REILU1200	Ceiling Fan	Good					588	10/01/03/2019	100	
REILU1217	Interior Painting	Good					832	10/01/03/2019	100	
REILU2075	Vinyl	Good					777	10/14/12/2023		

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1233	Tiles - Floor	Good					1387	20/01/03/2019	100	
REILU1239	Toilet & Cistern	Good					1343	20/01/03/2019	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1203	Courtyard	Good					2908	30/01/01/1991	100	
REILU1204	Doors	Good					8946	30/01/01/1991	100	
REILU1205	Downpipes	Good					1742	20/01/01/1991	100	
REILU1206	Electrical Switchboard	Good	B&R				1964	20/01/01/1991	100	
REILU1208	Exterior Painting	Good					2086	10/01/01/1991	100	
REILU1209	Fascia & Barges	Good					2874	20/01/01/1991	100	
REILU1210	Fencing	Poor					7725	20/01/01/1991	100	
REILU1211	Flyscreens	Good					1864	10/01/01/1991	100	
REILU1212	Guttering	Good					2819	20/01/01/1991	100	
REILU1224	Path	Good					2197	30/01/01/1991	100	
REILU1225	Patio	Good					1642	30/01/01/1991	100	
REILU1226	Porch	Good					2908	30/01/01/1991	100	
REILU1244	Water Meter	Good					388	20/01/01/1991	100	
REILU1245	Windows	Good					7747	30/01/01/1991	100	
REILU1960	Blind	Good					555	10/04/11/2022	100	
REILU2076	Clothesline	Good					499	10/14/12/2023		
REILU2077	Drain	Poor					1587	50/01/01/1991		

Unit 21-22

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1246	Roof	Good					27972	50/01/01/1991	100	

Unit 21

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1247	Insulation	Good					3191	20/01/11/2021	100	
REILU1248	Lighting	Good					1909	15/01/11/2021	100	
REILU1249	Sarking	Good					4140	25/01/01/1991	100	
REILU1250	Smoke Alarms	Good					260	20/01/11/2021	100	
REILU1275	Hot Water System - Gas	Good	Eternity	Eternity 20V	66029813		2386	12/01/11/2021	100	
REILU1293	Skylight	Good					788	10/01/11/2021	100	

Unit 22

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1308	Insulation	Good					3191	20/01/10/2019	100	
REILU1309	Lighting	Good					1909	15/01/10/2019	100	
REILU1310	Sarking	Good					4140	25/01/01/1991	100	
REILU1311	Smoke Alarms	Good					260	20/01/10/2019	100	
REILU1336	Hot Water System - Gas	Good	Rheem	876T26NF-A	H14-0221900939		2386	12/01/10/2019	100	
REILU1354	Skylight	Good					788	10/01/10/2019	100	

Unit 21

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1269	Exhaust Fan	Good					255	10/01/11/2021	100	
REILU1282	Interior Painting	Good					177	10/01/11/2021	100	
REILU1291	Shower Screen	Good					1165	20/01/11/2021	100	
REILU1294	Tapware	Good					1304	15/01/11/2021	100	
REILU1297	Tiles - Floor	Good					3940	20/01/11/2021	100	
REILU1299	Tiles - Wall	Good					3285	20/01/11/2021	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

REILU1255	Blind	Good				666		10/01/11/2021	100	
REILU1262	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU1278	Interior Painting	Good				921		10/01/11/2021	100	
REILU1305	Wardrobe	Good				2053		10/01/11/2021	100	
REILU1921	Curtains	Good				222		6/01/09/2015		
REILU1961	Carpet	Good				599		8/04/11/2022	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1254	Blind	Good				333		10/01/11/2021	100	
REILU1261	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU1277	Interior Painting	Good				599		10/01/11/2021	100	
REILU1962	Carpet	Good				599		8/04/11/2022	100	
REILU1963	Wardrobe	Good				2053		10/04/11/2022	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1260	Vinyl	Good				688		10/01/09/2015		
REILU1280	Interior Painting	Good				599		10/01/11/2021	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1281	Interior Painting	Good				355		10/01/11/2021	100	
REILU1296	Vinyl	Good				932		10/01/11/2021	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1252	Benchtops	Good				2344		20/01/11/2021	100	
REILU1253	Blind	Good				333		10/01/11/2021	100	
REILU1276	Interior Painting	Good				499		10/01/11/2021	100	
REILU1284	Kitchen Cabinets	Good				3818		20/01/11/2021	100	
REILU1285	Oven	Good	Fisher & Paykel	PEK1350W-L	42280081	1409		12/01/11/2021	100	
REILU1289	Rangehood	Good	Fisher & Paykel			599		12/01/11/2021	100	
REILU1292	Sink & Fittings	Good				1587		15/01/11/2021	100	
REILU1302	Vinyl	Good				777		10/01/11/2021	100	
REILU1964	Cooktop	Good	Fisher & Paykel			1354		12/04/11/2022	100	
REILU1965	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAM7K0614	3818		8/04/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1283	Interior Painting	Good				177		10/01/11/2021	100	
REILU1298	Tiles - Floor	Good				2025		20/01/11/2021	100	
REILU1300	Tiles - Wall	Good				1209		20/01/11/2021	100	
REILU1966	Exhaust Fan	Good				255		10/04/11/2022	100	
REILU1967	Sink & Fittings	Good				1587		15/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1251	Air Conditioner - Split System	Good	Hitachi	RAS-50YHA3	1383609045	3296		10/01/11/2021	100	
REILU1256	Blind	Good				777		10/01/11/2021	100	
REILU1259	Vinyl	Good				954		10/01/09/2015	100	
REILU1263	Ceiling Fan	Good				588		10/01/11/2021	100	
REILU1279	Interior Painting	Good				832		10/01/11/2021	100	
REILU1968	Curtains	Good				777		6/04/11/2022	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1295	Tiles - Floor	Good				1387		20/01/11/2021	100	
REILU1301	Toilet & Cistern	Good				1343		20/01/11/2021	100	
REILU2078	Interior Painting	Good				177		10/01/11/2021		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1264	Clothesline	Good				499		10/01/01/1991	100	
REILU1266	Courtyard	Good				2908		30/01/01/1991	100	
REILU1267	Doors	Good				8946		30/01/01/1991	100	
REILU1268	Downpipes	Good				1742		20/01/01/1991	100	

REILU1270	Exterior Painting	Good					2086	10/01/1991	100	
REILU1271	Fascia & Barges	Good					2874	20/01/1991	100	
REILU1272	Fencing	Poor					7725	20/01/1991	100	
REILU1273	Flyscreens	Good					1864	10/01/1991	100	
REILU1274	Guttering	Good					2819	20/01/1991	100	
REILU1286	Path	Good					2197	30/01/1991	100	
REILU1287	Patio	Good					1642	30/01/1991	100	
REILU1288	Porch	Good					2908	30/01/1991	100	
REILU1306	Water Meter	Good					388	20/01/1991	100	
REILU1307	Windows	Good					7747	30/01/1991	100	
REILU2011	Electrical	Good					1964	20/01/09/2013	100	
	Switchboard									

Unit 22

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1330	Exhaust Fan	Good				255		10/01/10/2019	100	
REILU1343	Interior Painting	Good				177		10/01/10/2019	100	
REILU1351	Shower Screen	Good				1165		20/01/10/2019	100	
REILU1355	Tapware	Good				1304		15/01/10/2019	100	
REILU1358	Tiles - Floor	Good				3940		20/01/10/2019	100	
REILU1360	Tiles - Wall	Good				3285		20/01/10/2019	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1316	Blind	Good				666		10/01/10/2019	100	
REILU1319	Carpet	Good				1054		8/01/10/2019	100	
REILU1322	Ceiling Fan	Good				588		10/01/10/2019	100	
REILU1339	Interior Painting	Fair				921		10/01/10/2019	100	
REILU1366	Wardrobe	Good				2053		10/01/10/2019	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1315	Blind	Good				333		10/01/10/2019	100	
REILU1318	Carpet	Good				688		8/01/10/2019	100	
REILU1338	Interior Painting	Good				599		10/01/10/2019	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1321	Carpet	Good				688		8/01/10/2019	100	
REILU1341	Interior Painting	Good				599		10/01/10/2019	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1342	Interior Painting	Good				355		10/01/10/2019	100	
REILU1364	Vinyl	Good				932		10/01/10/2019	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1313	Benchtops	Good				2344		20/01/10/2019	100	
REILU1314	Blind	Good				333		10/01/10/2019	100	
REILU1325	Cooktop	Good	Electrolux			1354		12/01/10/2019	100	
REILU1337	Interior Painting	Good				499		10/01/10/2019	100	
REILU1345	Kitchen Cabinets	Good				3818		20/01/10/2019	100	
REILU1346	Electric Elevated Oven	Good	Chef	EEC1230-R*20	44600094	1409		12/01/10/2019	100	
REILU1350	Rangehood	Good	Westinghouse			599		12/01/10/2019	100	
REILU1353	Sink & Fittings	Good				1587		15/01/10/2019	100	
REILU1363	Vinyl	Good				777		10/01/10/2019	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1344	Interior Painting	Good				177		10/01/10/2019	100	
REILU1359	Tiles - Floor	Good				2025		20/01/10/2019	100	
REILU1361	Tiles - Wall	Good				1209		20/01/10/2019	100	
REILU2079	Sink & Fittings	Good				1587		15/01/10/2019	100	
REILU2080	Exhaust Fan	Good				255		10/01/10/2019	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1312	Air Conditioner - Split System	Good	Fujitsu	ASTG18KMCA	E027676	3296		10/01/2019	100	
REILU1317	Blind	Good				777		10/01/2019	100	
REILU1320	Carpet	Good				954		8/01/2019	100	
REILU1323	Ceiling Fan	Good				588		10/01/2019	100	
REILU1340	Interior Painting	Good				832		10/01/2019	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1356	Tiles - Floor	Good				1387		20/01/2019	100	
REILU1362	Toilet & Cistern	Good				1343		20/01/2019	100	
REILU2081	Interior Painting	Poor				177		10/01/2019		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1324	Clothesline	Fair				499		10/01/1991	100	
REILU1326	Courtyard	Good				2908		30/01/1991	100	
REILU1327	Doors	Good				8946		30/01/1991	100	
REILU1328	Downpipes	Good				1742		20/01/1991	100	
REILU1329	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU1331	Exterior Painting	Good				2086		10/01/1991	100	
REILU1332	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1333	Fencing	Good				7725		20/01/1991	100	
REILU1334	Flyscreens	Good				1864		10/01/1991	100	
REILU1335	Guttering	Good				2819		20/01/1991	100	
REILU1347	Path	Good				2197		30/01/1991	100	
REILU1348	Patio	Fair				1642		30/01/1991	100	
REILU1349	Porch	Good				2908		30/01/1991	100	
REILU1367	Water Meter	Good				388		20/01/1991	100	
REILU1368	Windows	Fair				7747		30/01/1991	100	
REILU2082	Drain	Poor				1587		50/01/1991		

Unit 23-24

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1369	Roof	Good				27972		50/01/1991	100	

Unit 23

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1370	Insulation	Good				3191		20/01/1991	100	
REILU1371	Lighting	Good				1909		15/01/1991	100	
REILU1372	Sarking	Good				4140		25/01/1991	100	
REILU1373	Smoke Alarms	Good				260		20/01/1991	100	
REILU1399	Hot Water System - Gas	Good	Thermann	GMK10409	2019.03-6525197	2386		12/01/1991	100	
REILU1417	Skylight	Good				788		10/01/1991	100	

Unit 24

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1431	Insulation	Good				3191		20/01/2010	100	
REILU1432	Lighting	Good				1909		15/01/2010	100	
REILU1433	Sarking	Good				4140		25/01/1991	100	
REILU1434	Smoke Alarms	Good				260		20/01/2010	100	
REILU1486	Skylight	Good				788		10/01/2010	100	
REILU2085	Hot Water System - Gas	Good	Rheem			2386		12/15/2024		

Unit 23

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1393	Exhaust Fan	Good				255		10/01/1991	100	
REILU1406	Interior Painting	Good				177		10/01/2020	100	
REILU1415	Shower Screen	Good				1165		20/01/1991	100	
REILU1418	Tapware	Good				1304		15/01/1991	100	

REILU1421	Tiles - Floor	Good				3940		20/01/01/1991	100	
REILU1423	Tiles - Wall	Good				3285		20/01/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1378	Blind	Good				666		10/01/01/1991	100	
REILU1381	Carpet	Good				1054		8/01/07/2020	100	
REILU1385	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1402	Interior Painting	Good				921		10/01/07/2020	100	
REILU1428	Wardrobe	Good				2053		10/01/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1377	Blind	Good				333		10/01/01/1991	100	
REILU1380	Carpet	Fair				688		8/01/07/2020	100	
REILU1384	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1401	Interior Painting	Good				599		10/01/07/2020	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1383	Carpet	Good				688		8/01/07/2020	100	
REILU1404	Interior Painting	Fair				599		10/01/07/2020	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1405	Interior Painting	Fair				355		10/01/07/2020	100	
REILU1427	Vinyl	Fair				932		10/01/07/2020	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1375	Benchtops	Good				2344		20/01/01/1991	100	
REILU1376	Blind	Good				333		10/01/01/1991	100	
REILU1388	Cooktop	Good	Westinghouse			1354		12/01/01/1991	100	
REILU1400	Interior Painting	Fair				499		10/01/07/2020	100	
REILU1408	Kitchen Cabinets	Good				3818		20/01/01/1991	100	
REILU1409	Oven	Good	Westinghouse	WDE147WA-L	580022	1409		12/01/01/1991	100	
REILU1413	Rangehood	Good	Westinghouse			599		12/01/01/1991	100	
REILU1416	Sink & Fittings	Good				1587		15/01/01/1991	100	
REILU1426	Vinyl	Fair				777		10/01/07/2020	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1407	Interior Painting	Good				177		10/01/07/2020	100	
REILU1422	Tiles - Floor	Good				2025		20/01/01/1991	100	
REILU1424	Tiles - Wall	Good				1209		20/01/01/1991	100	
REILU2083	Sink & Fittings	Good				1587		15/01/07/2020	100	
REILU2084	Exhaust Fan	Good				255		10/01/01/1991	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1374	Air Conditioner - Split System	Good	Daikin	FTXD60BVMMA8	4902183	3296		10/01/01/1991	100	
REILU1379	Blind	Good				777		10/01/01/1991	100	
REILU1382	Carpet	Good				954		8/01/07/2020	100	
REILU1386	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1403	Interior Painting	Good				832		10/01/07/2020	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1419	Tiles - Floor	Good				1387		20/01/01/1991	100	
REILU1425	Toilet & Cistern	Good				1343		20/01/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1387	Clothesline	Good				499		10/01/01/1991	100	
REILU1389	Courtyard	Good				2908		30/01/01/1991	100	
REILU1390	Doors	Good				8946		30/01/01/1991	100	
REILU1391	Downpipes	Good				1742		20/01/01/1991	100	
REILU1392	Electrical Switchboard	Good	B&R			1964		20/01/01/1991	100	

Unit 24

REILU1394	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1395	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1396	Fencing	Good				7725		20/01/01/1991	100	
REILU1397	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1398	Guttering	Good				2819		20/01/01/1991	100	
REILU1410	Path	Good				2197		30/01/01/1991	100	
REILU1411	Patio	Good				1642		30/01/01/1991	100	
REILU1412	Porch	Good				2908		30/01/01/1991	100	
REILU1429	Water Meter	Good				388		20/01/01/1991	100	
REILU1430	Windows	Good				7747		30/01/01/1991	100	
REILU1969	Blind	Good				555		10/04/11/2022	100	

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1462	Exhaust Fan	Good				255		10/01/07/2010	100	
REILU1475	Interior Painting	Good				177		10/01/07/2010	100	
REILU1483	Shower Screen	Fair				1165		20/01/07/2010	100	
REILU1487	Tapware	Good				1304		15/01/07/2010	100	
REILU1490	Tiles - Floor	Good				3940		20/01/07/2010	100	
REILU1492	Tiles - Wall	Good				3285		20/01/07/2010	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1439	Blind	Good				666		10/01/07/2010	100	
REILU1442	Carpet	Good				1054		8/01/07/2010	100	
REILU1446	Ceiling Fan	Good				588		10/01/07/2010	100	
REILU1457	Curtains	Good				1776		6/01/07/2010	100	
REILU1471	Interior Painting	Good				921		10/01/07/2010	100	
REILU1498	Wardrobe	Good				2053		10/01/07/2010	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1438	Blind	Good				333		10/01/07/2010	100	
REILU1441	Carpet	Good				688		8/01/07/2010	100	
REILU1445	Ceiling Fan	Good				588		10/01/07/2010	100	
REILU1455	Curtains	Good				888		6/01/07/2010	100	
REILU1470	Interior Painting	Good				599		10/01/07/2010	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1444	Vinyl	Good				688		8/01/07/2010	100	
REILU1473	Interior Painting	Good				599		10/01/07/2010	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1474	Interior Painting	Good				355		10/01/07/2010	100	
REILU1489	Vinyl	Good				932		10/01/07/2010	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1436	Benchtops	Good				2344		20/01/07/2010	100	
REILU1437	Blind	Good				333		10/01/07/2010	100	
REILU1449	Cooktop	Good	Westinghouse			1354		12/01/07/2010	100	
REILU1453	Curtains	Good				444		6/01/07/2010	100	
REILU1469	Interior Painting	Good				499		10/01/07/2010	100	
REILU1477	Kitchen Cabinets	Good				3818		20/01/07/2010	100	
REILU1478	Electric Elevated Oven	Good	Westinghouse	PEK1350W-R*53	1780059	1409		12/01/07/2010	100	
REILU1482	Rangehood	Good	Westinghouse			599		12/01/07/2010	100	
REILU1485	Sink & Fittings	Good				1587		15/01/07/2010	100	
REILU1495	Vinyl	Good				777		10/01/07/2010	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1476	Interior Painting	Good				177		10/01/07/2010	100	
REILU1491	Tiles - Floor	Good				2025		20/01/07/2010	100	

REILU1493	Tiles - Wall	Good					1209	20/01/07/2010	100	
REILU1922	Exhaust Fan	Good					277	10/01/09/2015		
REILU2086	Sliding door	Fair					1587	30/01/07/2010		
REILU2087	Sink & Fittings	Good					1587	15/01/09/2015		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1435	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	SRK50ZMA-S	640104493BE	3296		10/01/07/2010	100	
REILU1440	Blind	Good				777		10/01/07/2010	100	
REILU1443	Vinyl	Good				954		8/01/07/2010	100	
REILU1447	Ceiling Fan	Good				588		10/01/07/2010	100	
REILU1458	Curtains	Good				888		6/01/07/2010	100	
REILU1472	Interior Painting	Good				832		10/01/07/2010	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1488	Tiles - Floor	Good				1387		20/01/07/2010	100	
REILU1494	Toilet & Cistern	Good				1343		20/01/07/2010	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1448	Clothesline	Good				499		10/01/01/1991	100	
REILU1450	Courtyard	Good				2908		30/01/01/1991	100	
REILU1460	Doors	Good				8946		30/01/01/1991	100	
REILU1461	Downpipes	Good				1742		20/01/01/1991	100	
REILU1463	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1464	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1465	Fencing	Good				7725		20/01/01/1991	100	
REILU1466	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1467	Guttering	Good				2819		20/01/01/1991	100	
REILU1479	Path	Good				2197		30/01/01/1991	100	
REILU1480	Patio	Good				1642		30/01/01/1991	100	
REILU1481	Porch	Good				2908		30/01/01/1991	100	
REILU1499	Water Meter	Good				388		20/01/01/1991	100	
REILU1500	Windows	Good				7747		30/01/01/1991	100	
REILU1998	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Unit 25-26

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1501	Roof	Good				27972		50/01/01/1991	100	

Unit 25

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1502	Insulation	Fair				3191		20/01/01/1991	100	
REILU1503	Lighting	Good				1909		15/01/01/1991	100	
REILU1504	Sarking	Good				4140		25/01/01/1991	100	
REILU1505	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU1530	Hot Water System - Gas	Good	Thermann	GMK10409	2019.03-6525449	2386		12/01/01/1991	100	
REILU1548	Skylight	Good				788		10/01/01/1991	100	

Unit 26

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1562	Insulation	Good				3191		20/01/01/1991	100	
REILU1563	Lighting	Good				1909		15/01/01/1991	100	
REILU1564	Sarking	Good				4140		25/01/01/1991	100	
REILU1565	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU1594	Hot Water System - Gas	Good	Thermann	GSCS20021	2016.02-6504197	2386		12/01/01/1991	100	
REILU1612	Skylight	Good				788		10/01/01/1991	100	

Unit 25

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
--------------	------------	-----------------	--------------	-------	-----------	-----------------------	--------------------	-------------------	------------------	-------------

REILU1524	Exhaust Fan	Good				255		10/01/1991	100	
REILU1537	Interior Painting	Good				177		10/01/1991	100	
REILU1545	Shower Screen	Good				1165		20/01/1991	100	
REILU1549	Tapware	Good				1304		15/01/1991	100	
REILU1552	Tiles - Floor	Good				3940		20/01/1991	100	
REILU1554	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1506	Air Conditioner - Split System	Good	Fujitsu	ASTG09LVCC	E093441	3296		10/01/1991	100	
REILU1510	Blind	Good				666		10/01/1991	100	
REILU1513	Carpet	Good				1054		8/01/1991	100	
REILU1516	Ceiling Fan	Good				588		10/01/1991	100	
REILU1533	Interior Painting	Good				921		10/01/1991	100	
REILU1559	Wardrobe	Good				2053		10/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1509	Blind	Good				666		10/01/1991	100	
REILU1512	Carpet	Good				688		8/01/1991	100	
REILU1532	Interior Painting	Good				599		10/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1515	Carpet	Good				688		8/01/1991	100	
REILU1535	Interior Painting	Good				599		10/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1536	Interior Painting	Good				355		10/01/1991	100	
REILU1551	Vinyl	Good				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1507	Benchtops	Good				2344		20/01/1991	100	
REILU1508	Blind	Good				333		10/01/1991	100	
REILU1531	Interior Painting	Good				499		10/01/1991	100	
REILU1539	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU1544	Rangehood	Good	Westinghouse			599		12/01/1991	100	
REILU1547	Sink & Fittings	Good				1587		15/01/1991	100	
REILU1557	Vinyl	Good				777		10/01/1991	100	
REILU1994	Electric Elevated Oven	Good	Westinghouse	WDE132WC-L		1811		12/16/07/2023	100	
REILU2088	Cooktop	Good	Westinghouse			1354		12/16/07/2023		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1538	Interior Painting	Good				177		10/01/1991	100	
REILU1553	Tiles - Floor	Good				2025		20/01/1991	100	
REILU1555	Tiles - Wall	Good				1209		20/01/1991	100	
REILU2089	Sink & Fittings	Good				1587		15/01/1991		
REILU2090	Exhaust Fan	Good				255		10/01/1991		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1511	Blind	Good				777		10/01/1991	100	
REILU1514	Carpet	Good				954		8/01/1991	100	
REILU1517	Ceiling Fan	Good				588		10/01/1991	100	
REILU1534	Interior Painting	Good				832		10/01/1991	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1550	Tiles - Floor	Good				1387		20/01/1991	100	
REILU1556	Toilet & Cistern	Good				1343		20/01/1991	100	
REILU2091	Interior Painting	Good				177		10/01/1991		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1518	Clothesline	Good				499		10/01/1991	100	

REILU1520	Courtyard	Good				2908		30/01/1991	100	
REILU1521	Doors	Good				8946		30/01/1991	100	
REILU1522	Downpipes	Good				1742		20/01/1991	100	
REILU1523	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU1525	Exterior Painting	Good				2086		10/01/1991	100	
REILU1526	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1527	Fencing	Good				7725		20/01/1991	100	
REILU1528	Flyscreens	Good				1864		10/01/1991	100	
REILU1529	Guttering	Good				2819		20/01/1991	100	
REILU1541	Path	Good				2197		30/01/1991	100	
REILU1542	Patio	Fair				1642		30/01/1991	100	
REILU1543	Porch	Good				2908		30/01/1991	100	
REILU1560	Water Meter	Good				388		20/01/1991	100	
REILU1561	Windows	Good				7747		30/01/1991	100	

Unit 26

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1588	Exhaust Fan	Good				255		10/01/1991	100	
REILU1601	Interior Painting	Good				177		10/01/1991	100	
REILU1610	Shower Screen	Good				1165		20/01/1991	100	
REILU1613	Tapware	Good				1304		15/01/1991	100	
REILU1616	Tiles - Floor	Good				3940		20/01/1991	100	
REILU1618	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1570	Blind	Good				666		10/01/1991	100	
REILU1574	Carpet	Good				1054		8/01/1991	100	
REILU1578	Ceiling Fan	Good				588		10/01/1991	100	
REILU1584	Curains	Good				1776		6/01/1991	100	
REILU1597	Interior Painting	Good				921		10/01/1991	100	
REILU1624	Wardrobe	Good				2053		10/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1569	Blind	Good				333		10/01/1991	100	
REILU1573	Carpet	Good				688		8/01/1991	100	
REILU1577	Ceiling Fan	Good				588		10/01/1991	100	
REILU1583	Curains	Good				1776		6/01/1991	100	
REILU1596	Interior Painting	Good				599		10/01/1991	100	
REILU1623	Wardrobe	Good				2053		10/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1576	Carpet	Good				688		8/01/1991	100	
REILU1599	Interior Painting	Good				599		10/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1600	Interior Painting	Good				355		10/01/1991	100	
REILU1622	Vinyl	Good				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1567	Benchtops	Good				2344		20/01/1991	100	
REILU1568	Blind	Good				333		10/01/1991	100	
REILU1581	Cooktop	Good	Westinghouse			1354		12/01/1991	100	
REILU1595	Interior Painting	Good				499		10/01/1991	100	
REILU1603	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU1604	Electric Elevated Oven	Good	Westinghouse	PEK1370W-R	43280060	1409		12/01/1991	100	
REILU1608	Rangehood	Good	Westinghouse			599		12/01/1991	100	
REILU1611	Sink & Fittings	Good				1587		15/01/1991	100	
REILU1621	Vinyl	Good				777		10/01/1991	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1602	Interior Painting	Good				177		10/01/1991	100	
REILU1617	Tiles - Floor	Good				2025		20/01/1991	100	
REILU1619	Tiles - Wall	Good				1209		20/01/1991	100	
REILU1970	Exhaust Fan	Good				255		10/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1566	Air Conditioner - Split System	Good	Actron Air	WRE-071AS	847363020206	3296		10/01/1991	100	
REILU1572	Blind	Good				388		10/01/1991	100	
REILU1575	Carpet	Good				954		8/01/1991	100	
REILU1579	Ceiling Fan	Good				588		10/01/1991	100	
REILU1585	Curtains	Good				1776		6/01/1991	100	
REILU1598	Interior Painting	Good				832		10/01/1991	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1571	Blind	Good				277		10/01/1991	100	
REILU1614	Tiles - Floor	Good				1387		20/01/1991	100	
REILU1620	Toilet & Cistern	Good				1343		20/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1580	Clothesline	Good	Daytek			499		10/01/1991	100	
REILU1582	Courtyard	Good				2908		30/01/1991	100	
REILU1586	Doors	Good				8946		30/01/1991	100	
REILU1587	Downpipes	Good				1742		20/01/1991	100	
REILU1589	Exterior Painting	Good				2086		10/01/1991	100	
REILU1590	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1591	Fencing	Good				7725		20/01/1991	100	
REILU1592	Flyscreens	Good				1864		10/01/1991	100	
REILU1593	Guttering	Good				2819		20/01/1991	100	
REILU1605	Path	Good				2197		30/01/1991	100	
REILU1606	Patio	Good				1642		30/01/1991	100	
REILU1607	Porch	Good				2908		30/01/1991	100	
REILU1625	Water Meter	Good				388		20/01/1991	100	
REILU1626	Windows	Good				7747		30/01/1991	100	
REILU1999	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2092	Drain	Poor				1587		50/01/1991		

Unit 27-28

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1627	Roof	Good				27972		50/01/1991	100	

Unit 27

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1628	Insulation	Good				3191		20/01/1991	100	
REILU1629	Lighting	Good				1909		15/01/1991	100	
REILU1630	Sarking	Good				4140		25/01/1991	100	
REILU1631	Smoke Alarms	Good				260		20/01/1991	100	
REILU1657	Hot Water System - Gas	Good	Eternity	Eternity T20	66032342	2386		12/01/1991	100	
REILU1675	Skylight	Good				788		10/01/1991	100	

Unit 27

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1651	Exhaust Fan	Good				255		10/01/1991	100	
REILU1664	Interior Painting	Good				177		10/01/1991	100	
REILU1673	Shower Screen	Good				1165		20/01/1991	100	
REILU1676	Tapware	Good				1304		15/01/1991	100	
REILU1679	Tiles - Floor	Good				3940		20/01/1991	100	
REILU1681	Tiles - Wall	Good				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1636	Blind	Good				666		10/01/1991	100	
REILU1639	Carpet	Good				1054		8/01/1991	100	
REILU1643	Ceiling Fan	Good				588		10/01/1991	100	
REILU1660	Interior Painting	Good				921		10/01/1991	100	
REILU1686	Wardrobe	Good				2053		10/01/1991	100	
REILU2093	Curtains	Good				888		6/01/1991		

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1635	Blind	Good				333		10/01/1991	100	
REILU1638	Carpet	Good				688		8/01/1991	100	
REILU1642	Ceiling Fan	Good				588		10/01/1991	100	
REILU1659	Interior Painting	Fair				599		10/01/1991	100	
REILU2094	Curtains	Good				888		6/01/1991		

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1641	Carpet	Good				688		8/01/1991	100	
REILU1662	Interior Painting	Good				599		10/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1663	Interior Painting	Good				355		10/01/1991	100	
REILU1685	Vinyl	Poor				932		10/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1633	Benchtops	Good				2344		20/01/1991	100	
REILU1634	Blind	Good				333		10/01/1991	100	
REILU1646	Cooktop	Good	Chef			1354		12/01/1991	100	
REILU1658	Interior Painting	Good				499		10/01/1991	100	
REILU1666	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU1667	Electric Elevated Oven	Good	Chef	EESFDLW	2560081	1409		12/01/1991	100	
REILU1671	Rangehood	Good	Westinghouse			599		12/01/1991	100	
REILU1674	Sink & Fittings	Good				1587		15/01/1991	100	
REILU1684	Vinyl	Good				777		10/01/1991	100	
REILU2095	Curtains	Good				888		6/01/1991		

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1665	Interior Painting	Fair				177		10/01/1991	100	
REILU1680	Tiles - Floor	Good				2025		20/01/1991	100	
REILU1682	Tiles - Wall	Good				1209		20/01/1991	100	
REILU1971	Exhaust Fan	Good				255		10/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1632	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	DXK18ZSA-W	841004032BE	3296		10/01/1991	100	
REILU1637	Blind	Good				777		10/01/1991	100	
REILU1640	Carpet	Good				954		8/01/1991	100	
REILU1644	Ceiling Fan	Good				588		10/01/1991	100	
REILU1661	Interior Painting	Good				832		10/01/1991	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1677	Tiles - Floor	Good				1387		20/01/1991	100	
REILU1683	Toilet & Cistern	Good				1343		20/01/1991	100	
REILU2096	Curtains	Good				888		6/01/1991		

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1645	Clothesline	Good				499		10/01/1991	100	
REILU1647	Courtyard	Good				2908		30/01/1991	100	
REILU1648	Doors	Good				8946		30/01/1991	100	
REILU1649	Downpipes	Good				1742		20/01/1991	100	

Unit 28

REILU1650	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU1652	Exterior Painting	Good				2086		10/01/1991	100	
REILU1653	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1654	Fencing	Good				7725		20/01/1991	100	
REILU1655	Flyscreens	Good				1864		10/01/1991	100	
REILU1656	Guttering	Good				2819		20/01/1991	100	
REILU1668	Path	Good				2197		30/01/1991	100	
REILU1669	Patio	Good				1642		30/01/1991	100	
REILU1670	Porch	Good				2908		30/01/1991	100	
REILU1687	Water Meter	Fair				388		20/01/1991	100	
REILU1688	Windows	Good				7747		30/01/1991	100	

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1711	Exhaust Fan	Good				255		10/01/1991	100	
REILU1724	Interior Painting	Good				177		10/01/09/2019	100	
REILU1733	Shower Screen	Good				1165		20/01/01/1991	100	
REILU1736	Tapware	Good				1304		15/01/01/1991	100	
REILU1739	Tiles - Floor	Good				3940		20/01/01/1991	100	
REILU1741	Tiles - Wall	Good				3285		20/01/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1697	Blind	Good				666		10/01/01/1991	100	
REILU1700	Carpet	Good				1054		8/01/09/2019	100	
REILU1704	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1720	Interior Painting	Good				921		10/01/09/2019	100	
REILU1747	Wardrobe	Good				2053		10/01/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1696	Blind	Good				333		10/01/01/1991	100	
REILU1699	Carpet	Good				688		8/01/09/2019	100	
REILU1703	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1719	Interior Painting	Good				599		10/01/09/2019	100	
REILU1746	Wardrobe	Good				2053		10/01/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1702	Vinyl	Good				688		8/01/09/2019	100	
REILU1722	Interior Painting	Good				599		10/01/09/2019	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1723	Interior Painting	Good				355		10/01/09/2019	100	
REILU1738	Vinyl	Good				932		10/01/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1694	Benchtops	Good				2344		20/01/01/1991	100	
REILU1695	Blind	Good				333		10/01/01/1991	100	
REILU1707	Cooktop	Good	Fisher & Paykel		MFV200425	1354		12/19/06/2023		
REILU1718	Interior Painting	Good				499		10/01/09/2019	100	
REILU1726	Kitchen Cabinets	Good				3818		20/01/01/1991	100	
REILU1727	Oven	Good	Fisher & Paykel	PEK1370W-R	43280011	1409		12/01/01/1991	100	
REILU1731	Rangehood	Good	Fisher & Paykel			599		12/01/01/1991	100	
REILU1734	Sink & Fittings	Good				1587		15/01/01/1991	100	
REILU1744	Vinyl	Good				777		10/01/09/2019	100	
REILU1972	Dishwasher	Good	Fisher & Paykel	DW60FC1X1	FAM7K0284	1164		8/04/11/2022	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1725	Interior Painting	Good				177		10/01/09/2019	100	
REILU1740	Tiles - Floor	Good				2025		20/01/01/1991	100	
REILU1742	Tiles - Wall	Good				1209		20/01/01/1991	100	

REILU1973	Exhaust Fan	Good				255		10/04/11/2022	100	
REILU2097	Sink & Fittings	Good				1587		15/04/11/2022		

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1693	Air Conditioner - Split System	Good	Daikin	FTXS71LVMA	E037842	3296		10/01/01/1991	100	
REILU1698	Blind	Good				777		10/01/01/1991	100	
REILU1701	Vinyl	Good				954		8/01/09/2019	100	
REILU1705	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1721	Interior Painting	Good				832		10/01/09/2019	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1737	Tiles - Floor	Good				1387		20/01/01/1991	100	
REILU1743	Toilet & Cistern	Good				1343		20/01/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1706	Clothesline	Good				499		10/01/01/1991	100	
REILU1708	Courtyard	Good				2908		30/01/01/1991	100	
REILU1709	Doors	Good				8946		30/01/01/1991	100	
REILU1710	Downpipes	Good				1742		20/01/01/1991	100	
REILU1712	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1713	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1714	Fencing	Good				7725		20/01/01/1991	100	
REILU1715	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1716	Guttering	Good				2819		20/01/01/1991	100	
REILU1728	Path	Good				2197		30/01/01/1991	100	
REILU1729	Patio	Good				1642		30/01/01/1991	100	
REILU1730	Porch	Good				2908		30/01/01/1991	100	
REILU1748	Water Meter	Good				388		20/01/01/1991	100	
REILU1749	Windows	Good				7747		30/01/01/1991	100	
REILU2009	Electrical Switchboard	Good				1964		20/01/09/2013	100	

Unit 28

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1689	Insulation	Fair				3191		20/01/01/1991	100	
REILU1690	Lighting	Good				1909		15/01/01/1991	100	
REILU1691	Sarking	Good				4140		25/01/01/1991	100	
REILU1692	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU1735	Skylight	Good				788		10/01/01/1991	100	
REILU1974	Hot Water System - Gas	Good	Rheem	874T26NF-A	H14-0521900172	2386		12/04/11/2022	100	

Unit 29-30

Common

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1750	Roof	Good				27972		50/01/01/1991	100	

Unit 29

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1751	Insulation	Good				3191		20/01/01/1991	100	
REILU1752	Lighting	Good				1909		15/01/01/1991	100	
REILU1753	Sarking	Good				4140		25/01/01/1991	100	
REILU1754	Smoke Alarms	Good				260		20/01/01/1991	100	
REILU1779	Hot Water System - Gas	Good	ETERNITY	ETERNITY T26	54019994	2386		12/01/01/1991	100	
REILU1797	Skylight	Good				788		10/01/01/1991	100	

Unit 30

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1811	Insulation	Good				3191		20/01/01/1991	100	
REILU1812	Lighting	Good				1909		15/01/01/1991	100	
REILU1813	Sarking	Good				4140		25/01/01/1991	100	
REILU1814	Smoke Alarms	Good				260		20/01/01/1991	100	

Unit 29

REILU1837	Hot Water System - Gas	Good	RHEEM	876T26NF-A		2386		12/01/01/1991	100	
REILU1855	Skylight	Good				788		10/01/01/1991	100	

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1773	Exhaust Fan	Good				255		10/01/01/1991	100	
REILU1786	Interior Painting	Good				177		10/01/01/1991	100	
REILU1795	Shower Screen	Good				1165		20/01/01/1991	100	
REILU1798	Tapware	Good				1304		15/01/01/1991	100	
REILU1801	Tiles - Floor	Good				3940		20/01/01/1991	100	
REILU1803	Tiles - Wall	Good				3285		20/01/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1758	Blind	Good				666		10/01/01/1991	100	
REILU1761	Carpet	Good				1054		8/01/01/1991	100	
REILU1765	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1782	Interior Painting	Good				921		10/01/01/1991	100	
REILU1808	Wardrobe	Good				2053		10/01/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1757	Blind	Good				333		10/01/01/1991	100	
REILU1760	Carpet	Good				688		8/01/01/1991	100	
REILU1764	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1781	Interior Painting	Good				599		10/01/01/1991	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1763	Carpet	Good				688		8/01/01/1991	100	
REILU1784	Interior Painting	Good				599		10/01/01/1991	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1785	Interior Painting	Good				355		10/01/01/1991	100	
REILU1807	Vinyl	Fair				932		10/01/01/1991	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1755	Benchtops	Good				2344		20/01/01/1991	100	
REILU1756	Blind	Good				333		10/01/01/1991	100	
REILU1768	Cooktop	Good	Westinghouse			1354		12/01/01/1991	100	
REILU1780	Interior Painting	Good				499		10/01/01/1991	100	
REILU1788	Kitchen Cabinets	Good				3818		20/01/01/1991	100	
REILU1789	Electric Elevated Oven	Good	Westinghouse	WDE147WA-L	83480043	1409		12/01/01/1991	100	
REILU1793	Rangehood	Good	Westinghouse			599		12/01/01/1991	100	
REILU1796	Sink & Fittings	Good				1587		15/01/01/1991	100	
REILU1806	Vinyl	Good				777		10/01/01/1991	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1787	Interior Painting	Good				177		10/01/01/1991	100	
REILU1802	Tiles - Floor	Good				2025		20/01/01/1991	100	
REILU1804	Tiles - Wall	Good				1209		20/01/01/1991	100	
REILU2098	Sink & Fittings	Good				1587		15/01/01/1991	100	
REILU2099	Exhaust Fan	Good				255		10/01/01/1991	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1759	Blind	Good				777		10/01/01/1991	100	
REILU1762	Carpet	Good				954		8/01/01/1991	100	
REILU1766	Ceiling Fan	Good				588		10/01/01/1991	100	
REILU1783	Interior Painting	Good				832		10/01/01/1991	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1799	Tiles - Floor	Good				1387		20/01/01/1991	100	

REILU1805	Toilet & Cistern	Good					1343		20/01/1991	100	
-----------	------------------	------	--	--	--	--	------	--	------------	-----	--

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1769	Courtyard	Fair				2908		30/01/1991	100	
REILU1770	Doors	Good				8946		30/01/1991	100	
REILU1771	Downpipes	Good				1742		20/01/1991	100	
REILU1772	Electrical Switchboard	Good	B&R			1964		20/01/1991	100	
REILU1774	Exterior Painting	Good				2086		10/01/1991	100	
REILU1775	Fascia & Barges	Good				2874		20/01/1991	100	
REILU1776	Fencing	Good				7725		20/01/1991	100	
REILU1777	Flyscreens	Good				1864		10/01/1991	100	
REILU1778	Guttering	Good				2819		20/01/1991	100	
REILU1790	Path	Good				2197		30/01/1991	100	
REILU1791	Patio	Good				1642		30/01/1991	100	
REILU1792	Porch	Good				2908		30/01/1991	100	
REILU1809	Water Meter	Good				388		20/01/1991	100	
REILU1810	Windows	Good				7747		30/01/1991	100	
REILU1995	Clothesline	Good				1563		10/02/2023	100	

Unit 30

Bathroom

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1831	Exhaust Fan	Good				255		10/01/1991	100	
REILU1844	Interior Painting	Good				177		10/01/2019	100	
REILU1853	Shower Screen	Good				1165		20/01/1991	100	
REILU1856	Tapware	Good				1304		15/01/1991	100	
REILU1859	Tiles - Floor	Fair				3940		20/01/1991	100	
REILU1861	Tiles - Wall	Fair				3285		20/01/1991	100	

Bed 1

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1819	Blind	Good				666		10/01/1991	100	
REILU1822	Carpet	Good				1054		8/01/2019	100	
REILU1825	Ceiling Fan	Good				588		10/01/1991	100	
REILU1840	Interior Painting	Good				921		10/01/2019	100	
REILU1867	Wardrobe	Good				2053		10/01/1991	100	

Bed 2

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1818	Blind	Good				333		10/01/1991	100	
REILU1821	Carpet	Good				688		8/01/2019	100	
REILU1839	Interior Painting	Good				599		10/01/2019	100	

Dining

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1824	Carpet	Good				688		8/01/2019	100	
REILU1842	Interior Painting	Good				599		10/01/2019	100	

Hallway

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1843	Interior Painting	Good				355		10/01/2019	100	
REILU1865	Vinyl	Good				932		10/01/2019	100	

Kitchen

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1816	Benchtops	Good				2344		20/01/1991	100	
REILU1817	Blind	Good				333		10/01/1991	100	
REILU1827	Cooktop	Good	Westinghouse			1354		12/01/1991	100	
REILU1838	Interior Painting	Good				499		10/01/2019	100	
REILU1846	Kitchen Cabinets	Good				3818		20/01/1991	100	
REILU1847	Electric Elevated Oven	Good	Westinghouse	PEK1350W-R	41680005	1409		12/01/1991	100	
REILU1851	Rangehood	Good	Westinghouse			599		12/01/1991	100	
REILU1854	Sink & Fittings	Good				1587		15/01/1991	100	
REILU1864	Vinyl	Good				777		10/01/2019	100	

Laundry

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1845	Interior Painting	Good				177		10/01/04/2019	100	
REILU1860	Tiles - Floor	Fair				2025		20/01/01/1991	100	
REILU1862	Tiles - Wall	Fair				1209		20/01/01/1991	100	
REILU1975	Exhaust Fan	Good				255		10/04/11/2022	100	

Living

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1815	Air Conditioner - Split System	Good	Mitsubishi Heavy Industries	SRF50ZJX-S1	313201138RE	3296		10/01/01/1991	100	
REILU1820	Blind	Good				777		10/01/01/1991	100	
REILU1823	Carpet	Good				954		8/01/04/2019	100	
REILU1841	Interior Painting	Good				832		10/01/04/2019	100	

Toilet Room

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1857	Tiles - Floor	Fair				1387		20/01/01/1991	100	
REILU1863	Toilet & Cistern	Good				1343		20/01/01/1991	100	

Unit Exterior

Asset Number	Asset Name	Asset Condition	Manufacturer	Model	Serial No	Acquisition Cost (\$)	Effective Life (Y)	Installation Date	RV Component (%)	Shared With
REILU1826	Clothesline	Good				499		10/01/01/1991	100	
REILU1828	Courtyard	Good				2908		30/01/01/1991	100	
REILU1829	Doors	Good				8946		30/01/01/1991	100	
REILU1830	Downpipes	Good				1742		20/01/01/1991	100	
REILU1832	Exterior Painting	Good				2086		10/01/01/1991	100	
REILU1833	Fascia & Barges	Good				2874		20/01/01/1991	100	
REILU1834	Fencing	Good				7725		20/01/01/1991	100	
REILU1835	Flyscreens	Good				1864		10/01/01/1991	100	
REILU1836	Guttering	Good				2819		20/01/01/1991	100	
REILU1848	Path	Good				2197		30/01/01/1991	100	
REILU1849	Patio	Good				1642		30/01/01/1991	100	
REILU1850	Porch	Good				2908		30/01/01/1991	100	
REILU1868	Water Meter	Good				388		20/01/01/1991	100	
REILU1869	Windows	Good				7747		30/01/01/1991	100	
REILU2010	Electrical Switchboard	Good				1964		20/01/09/2013	100	
REILU2100	Flyscreens	Fair				1864		10/01/01/1991		